BASICS DATA

ID Number: 1044	I-0022	Year	Built: 1907	Data	Source: Permit		
Number Extended	Street			Quad T	ype of Address		
701	14th Street			SE C	urrent		
Name(s)			Туре	of Name			
Rowhouse, 701 14th	Street, S.E.		Comi	mon			
TaxCode1 TaxCode	2 TaxCode3	Type	Expla	ain			
1044/0022		Square	•				
STATUS/PURPOS	E/USE DATA						
Resource Type: Bui	lding		St	atus Currei	nt: Extant		
	toric		Qı	uality:			
Purpose: Rov	whouse		Co	ondition:	Good		
Frantise // les		C++	0	Ctan	Carran	Franksia	
Function/Use Residential (Single-I	Eamily)	Start 1907	Source Permit	Stop	Source	Explain Historic/Current	_
Residential (Single-	allilly)	1907	1 Cillin			Tilstoric/Current	
CONSTRUCTION	DATA						
Construction Event		art	Source	Stop	Source	Cost Source	
Addition		1928	Sanborn Ma		000.00	0001 000100	
Orig Construction		07	Permit	•		1500 Permit	
Construction Event		Associa	tion		Associated Na	ame	
Orig Construction		Archite			Beers, A. H.		_
Orig Construction		Builder			Wardman, Ha	arry	
Orig Construction		Owner			Wardman, Ha		
Construction Notes:							
One of eight rowhou	uses constructe	ed from	the same perr	nit (#2691)	.		
PEOPLE/EVENTS	DATA						
Racial Segregation S	tatus:						
0 0							
SETTING/SHAPE/	SIZE DATA						
Surroundings:	Urban			Cross Refe	erence Notes:		
Streetscape:	Intact						
Relate to Othr Bldgs:	`	-					
Relate to Street:	Face on Setba						
Massing:	Row Building	/Front P	orch				
Footprint:	L-Shaped						
Number Stories:	2						
Bays Wide:	3						
Height:			Outbuild	ling Type	(Contributing Status	
Width:	19						
Depth/Length: SqFt:	30						
Volume:							
Lot Width							
Lot Depth/Length:			Outbuild	ling Notes:			
Lot SqFt:							
			1				1
Acreage:							

ID Number: 1044-0022

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

February 2008: Constructed in 1907 by Harry Wardman, this two-story, three-bay Colonial Revival-style rowhouse is the end unit and one of eight similar rowhouses constructed from the same permit (#2691). The dwelling is constructed of brick and is set on a solid concrete foundation; both are faced with Flemish-bond brick. A sloping roof caps the dwelling and is enhanced along the façade (east elevation) and north (side) elevation by a projecting molded cornice with dentil and egg-and-dart molding. An exterior-side chimney rises from the north (side) elevation and is clad with German vinyl siding. The southernmost bay of the first story holds a single-leaf door and a stained-glass rectangular transom. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows and have concrete sills and concrete jack arches with keystones. A one-story, one-bay porch shelters the primary entrance and central bay and is set on a brick pier foundation that has been infilled with lattice. The roof of the porch has overhanging eaves and scrolled modillions and is supported by Tuscan wood columns set on brick posts. A balustrade of honey-comb brick encircles the porch, which is accessed by brick steps in the southern end bay. The north (side) elevation has fenestration that is consistent with the façade.

A two-story, full-width addition is located on the rear (west) elevation of the main block and is noted on the 1928 Sanborn map. The wood-frame addition, clad with asbestos shingles, is set on a raised brick foundation and is capped by a shed roof. The north elevation is fenestrated with triple 6/1, double-hung, wood-sash windows and have wood surrounds. The foundation of the north elevation was originally pierced by a vehicular opening, but is now infilled with brick. A single-leaf paneled door with lights and an octagonal-shaped nine-light vinyl window fenestrate the foundation. The rear elevation of the addition was not surveyed by volunteer surveyor.

Site Notes

February 2008: This two-story rowhouse is located on the southwest corner of G Street, S.E. and 14th Street, S.E. and is located approximately ten feet from the concrete sidewalk. The south (side) elevation of the dwelling is adjacent to 703 14th Street, S.E. The small front and side yards are landscaped with mature trees and shrubs, as well as foundation plantings and is encircled by metal chain-link fencing. A low, stone retaining wall bounds the eastern and northern edges of the property. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component	Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Flemish Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Side Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Main Door	Rectangular	Single		
Notable Interior Plan	n(s)		Notable Interior Feature(s)	

ID Number: 1044-0022 Page 2

Capitol Hill Southeast Phase I (2009/2010)

Neighborhood: Capitol Hill

Subdivision: Ward/ANC: Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G

St\Database\Pictures\Square 1044\

File: **701_14STSE (2).JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\

File: 701_14STSE .JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\

File: 701_14STSE.JPG

Date:: Photog:

Code:: R: Fr:







PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:					
PERMIT DATA	l				
Permit Issue Date	e Number	Туре	Remarks		
03/07/1907	2691	Build			
Permit Notes:					
BIBLIOGRAPH	IIC DATA				
SIGNIFICANCE	E DATA				
Study Unit					
Code C	Criteria			_	

ID_Number: 1044-0022 Page 4

ID Number: 1044-0023

ID Number: 1044	-0023	Year Built:	1907	Data S	ource: Per	mit		
Number Extended	Street			Quad Ty	pe of Address			
703	14th Street			SE Cu	irrent			
Name(s)			Type of	Name				
Rowhouse, 703 14th	Street, S.E.		Commo	on		<u> </u>		
TaxCode1 TaxCode	2 TaxCode3	Туре	Explair	1				
1044/0023		Square/Lot	Currer			_		
STATUS/PURPOS	E/USE DATA							
Resource Type: Bui	_			us Current	: Extant			
o .	toric		Qua	-	01			
Purpose: Rov	vhouse		Con	dition:	Good			
Function/Use		Start S	Source	Stop	Source	e Expl	lain	
Residential (Single-I	Family)	1907 F	Permit			Hist	oric/Current	
CONSTRUCTION								
Construction Event	Sta 19			Stop	Source		ost Source 500 Permit	
Orig Construction	19		IIIL				oo remiii	
Construction Event		Association			Associated			
Orig Construction Orig Construction		Architect Builder			Beers, A.			
Orig Construction		Owner			Wardman Wardman			
_		•				, ,		
Construction Notes: One of eight rowhou	iene conetruct	ad from the sa	mo normi	+ (#2601)				
One of eight fowhor	ises constructi	eu iroin tile se	ine permi	t (#2031).				
PEOPLE/EVENTS	DATA							
Racial Segregation St	tatus:							
SETTING/SHAPE/	SIZE DATA							
Surroundings:	Urban		С	ross Refer	ence Notes:			
Streetscape:	Intact							
Relate to Othr Bldgs:								
Relate to Street:	Face on Setba							
Massing: Footprint:	Row Building	/Front Porch						
	L-Shaped							
Number Stories:	2							
Bays Wide:	3		Outhuildia	a T. ma		Contrib	uting Status	
Height: Width:	40		Outbuildin	g rype		Contrib	uting Status	
Depth/Length:	19 30							
SqFt:	00							
Volume:								
Lot Width								
Lot Depth/Length:			Outbuildin	a Notes:				
				<u> </u>				
Lot SqFt:				<u> </u>				
Lot SqFt: Acreage:				<u> </u>				

Architectural Style(s)					
Colonial Revival			<u> </u>		
Exterior & Architectural	Notes:				
of eight similar rowho a solid concrete foun- along the façade (eas bay of the first story h openings on the faça with keystones. A one foundation that has b supported by Tuscan	ouses constructed fro dation; both are faced t elevation) by a proje nolds a single-leaf woo de hold 1/1, double-hu e-story, one-bay porch een infilled with lattic wood columns. A me	ry Wardman, this two- m the same permit (#2 d with Flemish-bond b ecting molded cornice od-frame glass door a ung, wood-sash windon a shelters the primary e. The roof of the poro tal balustrade encircle a was not surveyed or	2691). The dwelling is or rick. A sloping roof ca with dentil and egg-ar nd a one-light rectang was and have concrete entrance and central be th has overhanging ea the porch, which is	constructed of b ps the dwelling d-dart molding. ular wood trans sills and concr ay and is set on ves and scrolled accessed by wo	rick and is set of and is enhanced. The southernm om. All window ete jack arches a brick pier d modillions and od steps in the
Site Notes:					
feet from the concrete	e sidewalk. The dwelli I shrubs and is lined a	located on the west s ing is adjacent to 701 a along its eastern edge	and 705 14th Street, S.	E. The grassy fr	ont yard is plant
	Featu	ıre			
EXTERIOR MATER Roof Component	IALS DATA Material	Color	Treatment	Source	
EXTERIOR MATER Roof Component Sloped	Material Not Visible	Color	Not Visible		
EXTERIOR MATER Roof Component	IALS DATA Material			Source	
EXTERIOR MATER Roof Component Sloped Wall Component	Material Not Visible Material	Color	Not Visible Treatment		
EXTERIOR MATER Roof Component Sloped Wall Component Facade	Material Not Visible Material Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation	Material Not Visible Material Brick Material Concrete	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Material Not Visible Material Brick Material Concrete Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick	Color	Not Visible Treatment	Source	Material
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond	Source	Material Wood
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/IN Window Location Facade	Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond Light	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/IN Window Location	Material Not Visible Material Brick Material Concrete Brick	Color Color Feature Type Dbl-Hung	Not Visible Treatment Flemish Bond Ligh 1/1	Source	Wood

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC:

Zoning: Designation Event(s)

Contributing:

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\

File: 703_14STSE .JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photographer Caption		Date	Frame(s)	Roll	Photo Code
----------------------	--	------	----------	------	------------

MISCELLANEOUS NOTES DATA

notes:						

PERMIT DATA

Permit Issue Date	Number Type	Remarks	

03/07/1907 2691 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1044-0023 Page 3

ID Number: 1044-0024

ID Number: 1044	l-0024	Year Built	1907	Data So	ource: Permit		
Number Extended	Street			Quad Typ	e of Address		
705	14th Street			SE Cu	rrent		
Name(s)			Type	of Name			
Rowhouse, 705 14th	Street, S.E.		Comn	non			
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	ain			
1044/0024		Square/Lot	Curre	ent			
STATUS/PURPOS							
Resource Type: Buil	lding toric			atus Current:	Extant		
9	vhouse			nality:	Good		
Function/Use Residential (Single-I	Eamily)		Source Permit	Stop	Source	Explain Historic/Current	
Residential (Single-	raillily)	1907	remm			HIStoric/Current	
CONSTRUCTION	DATA						
Construction Event		art Soi	ırce	Stop	Source	Cost Source	
Orig Construction	19	007 Pe	mit	•		1500 Permit	
Construction Event		Association			Associated Na	me	
Orig Construction		Architect			Beers, A. H.		
Orig Construction		Builder			Wardman, Ha	rry	
Orig Construction		Owner			Wardman, Ha	rry	
Construction Notes: One of eight rowhou	ıses construct	ed from the s	same pern	nit (#2691).			
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Refere	ence Notes:		
Streetscape:	Intact		Г]
Relate to Othr Bldgs:							
Relate to Street:	Face on Setb	ack Line					
Massing:	Row Building	/Flat Front					
Footprint:	L-Shaped						
Number Stories:	2						
Bays Wide:	3						
Height:			Outbuild	ing Type	C	Contributing Status	-
Width:	19 30						
Depth/Length: SqFt:	30						
Volume:							
Lot Width							
Lot Depth/Length:			Outbuild	ing Notes:			_
Lot SqFt:							
Acreage:							
Has Driveway:							

Architectural Style(s)			_		
Colonial Revival					
Exterior & Architectura					
of eight similar rowh a solid concrete four along the façade (ea: bay of the first story shelters the primary entrance and is set on removed from the face	tructed in 1907 by Harlouses constructed frondation; both are faced at elevation) by a projetholds a single-leaf worden at brick pier foundationade. All window open ck arches with keyston	m the same permit (# I with Flemish-bond becting molded cornice od-frame glass door a breed by scrolled brack ion. Metal balusters e ings on the façade ho	2691). The dwelling is prick. A sloping roof of with dentil and egg- and a stained-glass ro kets. A metal deck pr incircle the deck. The old 1/1, double-hung	s constructed of caps the dwelling and-dart molding ectangular wood ovides access to original one-stors ash windows ar	brick and is set on g and is enhanced g. The southernmon transom. A hood the primary ry porch has been and have concrete
Site Notes:					
feet from the concre with mature trees an	two-story rowhouse is te sidewalk. The dwelli d shrubs, as well as fo ls at the concrete side RES DATA	ing is adjacent to 703 oundation plantings. <i>I</i>	and 707 14th Street, A concrete walkway le	S.E. The front ya	rd is landscaped
		ıre			
·	Featu				
EXTERIOR MATER Roof Component Sloped	Material Not Visible	Color	Treatment Not Visible	Source	
EXTERIOR MATER Roof Component Sloped Wall Component	Material Not Visible Material	Color	Not Visible Treatment	Source Source	
EXTERIOR MATER Roof Component Sloped	Material Not Visible		Not Visible		
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component	Material Material Material Material Bluestone Material		Not Visible Treatment		
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation	Material Not Visible Material Bluestone Material Concrete	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component	Material Material Material Material Bluestone Material	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Material Not Visible Material Bluestone Material Concrete	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Material Not Visible Material Bluestone Material Concrete Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Bluestone Material Concrete Brick	Color	Not Visible Treatment Flemish Bond	Source	Material
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Bluestone Material Concrete Brick	Color Feature	Not Visible Treatment Flemish Bond	Source	Material Unknown
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/IN	Material Not Visible Material Bluestone Material Concrete Brick	Color Feature	Not Visible Treatment Flemish Bond	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/IN Window Location Facade	Material Not Visible Material Bluestone Material Concrete Brick ITERIOR DATA Aperture Shape Rectangular	Color Feature Type Dbl-Hung	Not Visible Treatment Flemish Bond	Source Source	Unknown

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC:

Designation Event(s)

Contributing:

Zoning:

Survey(s)	Level(s) of Investigation
-----------	---------------------------

Capitol Hill Southeast Phase I (2009/2010)

Permit Research Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\

File: 705_14STSE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

|--|

MISCELLANEOUS NOTES DATA

Notes:					

PERMIT DATA

Permit Issue Date	Number Type	Remarks	
03/07/1907	2691 Build		

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1044-0024 Page 3

ID Number: 1044-0025

ID Number: 1044	-0025	Year Built:	1907	Data So	ource: Permit		
Number Extended	Street			Quad Typ	e of Address		
707	14th Street			SE Cui	rrent		
Name(s)			Туре	of Name			
Rowhouse, 707 14th	Street, S.E.		Comr	non			
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	ain			
1044/0025		Square/Lot	Curr	ent			
STATUS/PURPOS	E/USE DATA						
Resource Type: Bui	_			atus Current:	Extant		
9	toric vhouse			nality: Indition:	Good		
ruipose. Rov	viiouse		CC	manion.	Good		
Function/Use			Source	Stop	Source	Explain	
Residential (Single-I	Family)	1907 I	Permit			Historic/Current	
CONSTRUCTION	ΠΑΤΑ						
Construction Event		art Sou	rce	Stop	Source	Cost Source	
Orig Construction		07 Per		Отор	Course	1500 Permit	
Construction Event		Association			Associated Na	me	
Orig Construction		Architect			Beers, A. H.		
Orig Construction		Builder			Wardman, Ha	rry	
Orig Construction		Owner			Wardman, Ha	rry	
Construction Notes: One of eight rowhou	ises construct	ed from the s	ame pern	nit (#2691).			
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Refere	ence Notes:		
Streetscape:	Intact		ſ]
Relate to Othr Bldgs:	Row (1 of 8)						
Relate to Street:	Face on Setb						
Massing:		/Front Porch					
Footprint:	L-Shaped						
Number Stories:	2						
Bays Wide:	3		0 41 111				
Height: Width:	40		Outbuild	ing Type	C	Contributing Status	=
Depth/Length:	19 30						
SqFt:	00						
Volume:							
Lot Width							
Lot Depth/Length:			Outbuild	ing Notes:			٦
Lot SqFt:							
Acreage:							
Has Driveway:							

Architectural Style(s)			<u></u>		
Colonial Revival					
Exterior & Architectur	al Notes:				
of eight similar rowl a solid concrete fou along the façade (ea bay of the first story door and transom a hung, vinyl-sash wii shelters the primary lattice. The roof of the posts. Square wood	structed in 1907 by Har nouses constructed frondation; both are faced st elevation) by a project holds a single-leaf parter set within a square-endows and have concretentrance and central be porch has overhang balusters encircle the ation was not surveyed.	m the same permit (#2 d with Flemish-bond b ecting molded cornice neled wood door with edged wood surround ete sills and concrete pay and is set on a brid ing eaves and scrolled porch, which is acces	2691). The dwelling is a rick. A sloping roof ca with dentil and egg-ar one-light and a one-lig. All window openings jack arches with keystok pier foundation that d modillions and is sused by poured concre	constructed of I ps the dwelling nd-dart molding th rectangular on the façade I ones. A one-sto has been infille pported by pane te steps in the s	orick and is set on and is enhanced . The southernmost wood transom. The hold 1/1, double- iry, one-bay porch ed with wood eled square wood
ite Notes:					
feet from the concre landscaped with ma	two-story rowhouse is te sidewalk. The dwelli ture shrubs and founda a. An alley is located we	ing is adjacent to 705 a ation plantings. A wall	and 709 14th Street, S.	E. The small fro	ont yard is
NOTABLE FEATU	RES DATA				
NOTABLE FEATU Component	RES DATA Featu	ıre			
Component EXTERIOR MATEI Roof Component	Featu RIALS DATA Material	ure Color	Treatment	Source	
Component EXTERIOR MATEI	Featu	Color	Treatment Not Visible	Source	
EXTERIOR MATEI Roof Component Sloped Wall Component	Featu RIALS DATA Material Not Visible Material		Not Visible Treatment	Source Source	
EXTERIOR MATEI Roof Component Sloped	Featu RIALS DATA Material Not Visible	Color	Not Visible		
EXTERIOR MATEI Roof Component Sloped Wall Component Facade Structure Component	Feature RIALS DATA Material Not Visible Material Brick Material	Color	Not Visible Treatment		
EXTERIOR MATEI Roof Component Sloped Wall Component Facade Structure Component Foundation	Feature RIALS DATA Material Not Visible Material Brick Material Concrete	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Feature RIALS DATA Material Not Visible Material Brick Material	Color	Not Visible Treatment	Source	
EXTERIOR MATEI Roof Component Sloped Wall Component Facade Structure Component Foundation	Feature RIALS DATA Material Not Visible Material Brick Material Concrete	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Feature RIALS DATA Material Not Visible Material Brick Material Concrete	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Feature RIALS DATA Material Not Visible Material Brick Material Concrete	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Material Material Material Brick Material Concrete Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATEI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Material Material Brick Material Concrete Brick	Color	Not Visible Treatment	Source	Material
EXTERIOR MATEI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Material Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond	Source	Material Vinyl
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond Light	Source	

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Interior Notes:

Ward/ANC: Zoning:

Contributing:

Designation Event(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

File:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1044\
707_14STSE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

03/07/1907 2691 Build

Permit Notes:

L		

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1044-0025 Page 3

ID Number: 1044-0026

ID Number: 1044	-0026	Year Built:	1907	Data Sour	ce: Permit		
Number Extended	Street			Quad Type	of Address		
709	14th Street			SE Curre	nt		
Name(s)			Type of	Name			
Rowhouse, 709 14th	Street, S.E.		Commo				
TaxCode1 TaxCode	2 TaxCode3	Туре	Explain				
1044/0026	2 1000000	Square/Lot	Curren				
		•					
STATUS/PURPOS	E/USE DATA						
Resource Type: Bui	lding		Statu	us Current: Ex	xtant		
Desig. Status: Hist	oric		Qual	ity:			
Purpose: Rov	vhouse		Cond	dition: G	ood		
Function/Use		Start S	Source	Stop	Source	Explain	
Residential (Single-I	amily)	1907 F	Permit			Historic/Current	
CONSTRUCTION I	DATA						
Construction Event	Sta	art Soul	rce :	Stop S	Source	Cost Source	
Orig Construction	19	07 Perr	nit			1500 Permit	
Construction Event		Association			Associated Na	ıme	
Orig Construction		Architect			Beers, A. H.		
Orig Construction		Builder			Wardman, Ha	rry	
Orig Construction		Owner			Wardman, Ha	rry	
Construction Notes:							
One of eight rowhou	ses constructe	ed from the sa	ame permit	(#2691).			
PEOPLE/EVENTS	ΠΔΤΔ						
Racial Segregation St	alus.						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		Cı	oss Referenc	e Notes:		
Streetscape:	Intact						
Relate to Othr Bldgs:							
Relate to Street:	Face on Setba						
Massing: Footprint:	Row Building	/Front Porch					
Number Stories:	2						
Bays Wide:	3		المائد المائد	T		Danatulla valina ni Odadova	
Height: Width:	10		Outbuilding	д гуре		Contributing Status	
Depth/Length:	19 30						
SqFt:	00						
Volume:							
Lot Width							
Lot Depth/Length:			Outbuilding	g Notes:			
Lot SqFt:			1				
A							
Acreage:							

Architectural Style(s)					
Colonial Revival					
Exterior & Architectural	Notes:				
of eight similar rowho a solid concrete foun- dwelling and is enhar southernmost bay of transom. All window concrete jack arches on a brick pier founda eaves and scrolled m porch, which is acces	ouses constructed fro dation. The façade (eanced along the façade the first story holds a openings on the façade with keystones. A one ation that has been in odillions and is suppositions and is suppositions.	ry Wardman, this two- om the same permit (#2 ast elevation) is faced by a projecting molde single-leaf paneled do de hold 1/1, double-hu e-story, two-bay porch filled with decorative o orted by metal filigree ete steps in the souther.	691). The dwelling is with Flemish-bond brid cornice with dentil por with lights and a ong, vinyl-sash window shelters the primary econcrete blocks. The reposts set on brick pos	constructed of to ck. A sloping ro and egg-and-da ne-light rectang as and have con entrance and ce oof of the porch sts. Metal balus	orick and is set on to caps the rt molding. The jular wood crete sills and ntral bay and is se has overhanging ters encircle the
Site Notes:					
feet from the concrete mature shrubs and fo	e sidewalk. The dwelli undation plantings. A	located on the west sing is adjacent to 707 at a concrete walkway, with ocated west of the dwo	and 711 14th Street, S th metal hand rails, le	E. The grassy fi	ont yard features
NOTABLE FEATUR	ES DATA				
NOTABLE FEATUR Component	ES DATA Featu	ure			
_	Featu	ure Color	Treatment	Source	
Component EXTERIOR MATER	Featu		Treatment Not Visible	Source	
Component EXTERIOR MATER Roof Component	Featu IALS DATA Material			Source Source	
EXTERIOR MATER Roof Component Sloped	Featu IALS DATA Material Not Visible	Color	Not Visible		
EXTERIOR MATER Roof Component Sloped Wall Component	Featu IALS DATA Material Not Visible Material	Color	Not Visible Treatment		
EXTERIOR MATER Roof Component Sloped Wall Component Facade	Featu IALS DATA Material Not Visible Material Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Feature Featur	Color	Not Visible Treatment	Source	Material
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond	Source	Material Vinyl
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond Ligi 1/1	Source	

Neighborhood: Capitol Hill Historic District(s)

Subdivision:

Interior Notes:

Ward/ANC: Zoning:

Contributing:

Designation Event(s)

Survey(s) Level(s) of Investigation	
-------------------------------------	--

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\

File: 709_14STSE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

MISCELLANEOUS NOTES DATA

Notes:			

PERMIT DATA

Permit Issue Date	Number Type	Remarks	

03/07/1907 2691 Build

Permit Notes:

BIBLIOGRAPHIC DATA SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1044-0026 Page 3

ID Number: 1044-0027

ID Number: 1044	l-0027	Year Built	1907	Data So	ource: Permit		
Number Extended	Street			Quad Typ	e of Address		
711	14th Street			SE Cu	rrent		
Name(s)			Type	of Name			
Rowhouse, 711 14th	Street, S.E.		Comn	non			
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	ain			
1044/0027		Square/Lot	Curre	ent			
STATUS/PURPOS							
Resource Type: Buil	lding toric			atus Current:	Extant		
9	vhouse			nality: Indition:	Good		
Function/Use Residential (Single-I	Eamily)		Source Permit	Stop	Source	Explain Historic/Current	
Residential (Single-I	raillily)	1907	remm			HIStoric/Current	
CONSTRUCTION	DATA						
Construction Event		art Sou	ırce	Stop	Source	Cost Source	
Orig Construction	19	007 Pei	mit	•		1500 Permit	
Construction Event		Association			Associated Na	me	
Orig Construction		Architect			Beers, A. H.		
Orig Construction		Builder			Wardman, Ha	rry	
Orig Construction		Owner			Wardman, Ha	rry	
Construction Notes: One of eight rowhou	ıses construct	ed from the s	same pern	nit (#2691).			
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Refere	ence Notes:		
Streetscape:	Intact		Г]
Relate to Othr Bldgs:							
Relate to Street:	Face on Setb	ack Line					
Massing:	Row Building	/Flat Front					
Footprint:	L-Shaped						
Number Stories:	2						
Bays Wide:	3						
Height:			Outbuild	ing Type	C	Contributing Status	=
Width:	19 30						
Depth/Length: SqFt:	30						
Volume:							
Lot Width							
Lot Depth/Length:			Outbuild	ing Notes:			
Lot SqFt:				-			
Acreage:							
Has Driveway:							

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

February 2008: Constructed in 1907 by Harry Wardman, this two-story, three-bay Colonial Revival-style rowhouse is one of eight similar rowhouses constructed from the same permit (#2691). The dwelling is constructed of brick and is set on a solid concrete foundation. The façade (east elevation) is faced with Flemish-bond brick that has been painted. A sloping roof caps the dwelling and is enhanced along the façade by a projecting molded cornice with dentil and egg-and-dart molding. The southernmost bay of the first story holds a single-leaf wood-frame glass door and a leaded-glass rectangular wood transom. Brick steps with metal hand rails provide access to the door. All window openings on the façade hold 1/1, double-hung, wood-sash windows and have concrete sills and concrete jack arches with keystones. The foundation is fenestrated with a single-leaf door and a 1/1, double-hung, wood-sash window. The original one-story porch has been removed from the façade. The rear (west) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

February 2008: This two-story rowhouse is located on the west side of 14th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 709 and 713 14th Street, S.E. The small front yard is planted with mature trees and shrubs and is bounded along its eastern edge by a low, stone retaining wall. A concrete walkway leads from the primary entrance and ends at the sidewalk.

١	N	i		٦	Ē,	Δ	B	ł	1	F	ı	F	F	Δ	d	П	П	R	•	E	ς	: 1	n	Δ	П	Г,	Δ	
п	N	ľ	u		1	н) [_1	_	- 1	г	_	~	M		u	п	N	_	0		ப	-	N١		-	ı

Component	Feature	

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Flemish Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			
Materials Notes:				

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
Basemt Windows	Rectangular	Dbl-Hung	1/1	Wood	-
Facade	Rectangular	Dbl-Hung	1/1	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single		Wood/Glass	-
Main Door	Rectangular	Single	Full Glass	Wood	
Notable Interior Plan	(s)		Notable Interior Feature(s)		

Interior Notes:

ID Number: 1044-0027 Page 2

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning:

ng: Designation Event(s)

Contribu	uting:				3	,						
Survey(s)				Level(s) of Investiga	Level(s) of Investigation						
Capitol	Hill Southeast F	Phase I (2	2009/2010)		Permit Research Volunteer Reconna	Permit Research Volunteer Reconnaissance Survey						
РНОТО	OS - DIGITIZED)										
Caption Path:	: C:\Users\CHRS Databases\SE St\Database\Pi	Phase I -	D to G									
File:	711_14STSE.J		quale 10441									
Date::		notog:										
Code::		3	R:	Fr:	4							
PHOTO	OS - B/W OR N	ON-DIG	ITIZED Frame(s)	Date	Photographer	Caption						
	LLANEOUS N	OTES D			· ·	·						
Notes:												
PERMI	IT DATA											
Permit I	ssue Date	N	lumber Type		Remarks							
03/07/19	907		2691 Build									
Permit N	Notes:											
BIBLIC	OGRAPHIC DA	TA										
SIGNIF	FICANCE DATA	A										
Study U	Init											
Code	Criteria											

DATA PROCESSING EVENTS DATA

ID_Number: 1044-0027 Page 3

ID Number: 1044-0028

ID Number: 1044	l-0028	Year Built:	1907	Data So	ource: Permit		
Number Extended	Street			Quad Typ	e of Address		
713	14th Street			SE Cu	rrent		
Name(s)			Туре	of Name			
Rowhouse, 713 14th	Street, S.E.		Comr	non			
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	ain			
1044/0028		Square/Lot	Curr	ent			
STATUS/PURPOS							
Resource Type: Buil	_			atus Current:	Extant		
9	toric vhouse			uality: ondition:	Fair		
, aipooo.	viiouse		00	mandon.	ı alı		
Function/Use	= U. A		Source	Stop	Source	Explain	
Residential (Single-I	-amily)	1907 I	Permit			Historic/Current	
CONSTRUCTION	DATA						
Construction Event		art Sou	rce	Stop	Source	Cost Source	
Orig Construction	19	07 Per	mit	· ·		1500 Permit	
Construction Event		Association			Associated Na	ame	
Orig Construction		Architect			Beers, A. H.		
Orig Construction		Builder			Wardman, Ha	nrry	
Orig Construction		Owner			Wardman, Ha	nrry	
Construction Notes:							
One of eight rowhou	ises construct	ed from the s	ame pern	nit (#2691).			
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Refere	ence Notes:		
Streetscape:	Intact		[]
Relate to Othr Bldgs:							
Relate to Street:	Face on Setb						
Massing:		/Front Porch					
Footprint:	Rectangular						
Number Stories:	2						
Bays Wide:	3						
Height:			Outbuild	ing Type	(Contributing Status	-
Width: Depth/Length:	19 30						
SqFt:	30						
Volume:							
Lot Width							
Lot Depth/Length:			Outbuild	ing Notes:			7
Lot SqFt:							
Acreage:							
Has Driveway:							

Architectural Style(s)					
Colonial Revival			<u> </u>		
Exterior & Architectural I	Notes:				
February 2008: Construction of eight similar rowhout a solid concrete found sloping roof caps the codart molding. The sout rectangular wood transconcrete sills and concentral bay and is set coverhanging eaves and simulate a balustrade allevation was not surv	uses constructed fro ation. The façade (eadwelling and is enhal hernmost bay of the som. All window opeorete jack arches with a brick pier found a scrolled modillions and encircle the porce	om the same permit (#2 ast elevation) is faced nced along the façade first story holds a sin enings on the façade h th keystones. A one-ste lation that has been in a and is supported by ch, which is accessed	(691). The dwelling is with Flemish-bond brown by a projecting mold gle-leaf wood-frame cold 1/1, double-hung, bry, two-bay porch shilled with wood lattic Tuscan wood column by wood steps in the	constructed of ick that has bee ed cornice with glass door and a vinyl-sash wing elters the prima e. The roof of the s. Horizontal wo	brick and is set on an painted. A dentil and egg-and none-light dows and have ary entrance and ne porch has nod boards
Site Notes:					
February 2008: This tw feet from the concrete with mature shrubs an the primary entrance a	sidewalk. The dwelli d is bounded along i	ing is adjacent to 711 a its eastern edge by a l	and 715 14th Street, S	.E. The small fro	ont yard is planted
NOTABLE FEATURE					
NOTABLE FEATURE Component	S DATA Featu	ıre			
Component	Featu	ıre			
_	Featu	ure Color	Treatment	Source	
Component EXTERIOR MATERIA	Featu		Treatment Not Visible	Source	
EXTERIOR MATERIA Roof Component	Featu ALS DATA Material			Source Source	
EXTERIOR MATERIA Roof Component Sloped	Featu ALS DATA Material Not Visible	Color	Not Visible		
EXTERIOR MATERIA Roof Component Sloped Wall Component	Featu ALS DATA Material Not Visible Material	Color	Not Visible Treatment		
EXTERIOR MATERIA Roof Component Sloped Wall Component Facade	Featu ALS DATA Material Not Visible Material Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATERIA Roof Component Sloped Wall Component Facade Structure Component	Featu ALS DATA Material Not Visible Material Brick Material	Color	Not Visible Treatment	Source	
EXTERIOR MATERIA Roof Component Sloped Wall Component Facade Structure Component Foundation	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATERIA Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATERIA Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATERIA Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Material Not Visible Material Brick Material Concrete Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATERIA Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick	Color	Not Visible Treatment Flemish Bond	Source	Material
EXTERIOR MATERIA Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond	Source	Material Vinyl
EXTERIOR MATERIA Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/INT Window Location Facade	Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond Lig	Source	

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC:

Interior Notes:

Designation Event(s)

Zoning: Contributing:

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\

File: 713_14STSE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Caption	
---------	--

MISCELLANEOUS NOTES DATA

Notes:			

PERMIT DATA

Permit Issue Date	Number Type	Remarks	

03/07/1907 2691 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1044-0028 Page 3

ID Number: 1044-0003

ID Number: 1044	-0003	Year Built:	1907	Data So	ource: Permit		
Number Extended	Street			Quad Typ	e of Address		
715	14th Street			SE Cui	rrent		
Name(s)			Туре	of Name			
Rowhouse, 715 14th	Street, S.E.		Comn	non			
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	ain			
1044/0003		Square/Lot	Curre	ent			
STATUS/PURPOS							
Resource Type: Buil	_			atus Current:	Extant		
9	toric vhouse			nality: Indition:	Fair		
, aipooo.	viiouse		00	manion.	ı alı		
Function/Use	!I-A		Source	Stop	Source	Explain	
Residential (Single-I	-amily)	1907 F	Permit			Historic/Current	
CONSTRUCTION	DATA						
Construction Event	Sta	art Sou	rce	Stop	Source	Cost Source	
Orig Construction	19	07 Peri	nit	· ·		1500 Permit	
Construction Event		Association			Associated Na	ame	
Orig Construction		Architect			Beers, A. H.		
Orig Construction		Builder			Wardman, Ha	arry	
Orig Construction		Owner			Wardman, Ha	arry	
Construction Notes:							
One of eight rowhou	ises constructe	ed from the sa	ame pern	nit (#2691).			
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Refere	ance Notes:		
Streetscape:	Intact		Г	01033 1101011	THE NOTES.]
Relate to Othr Bldgs:		f 8)					
Relate to Street:	Face on Setba						
Massing:	Row Building	Front Porch					
Footprint:	Rectangular						
Number Stories:	2						
Bays Wide:	3		L				
Height:			Outbuild	ing Type	(Contributing Status	-
Width:	19						
Depth/Length: SqFt:	30						
Volume:							
Lot Width							
Lot Depth/Length:			Outbuild	ing Notes:			_
Lot SqFt:							
Acreage:							
Has Driveway:							

STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Colonial Revival			<u> </u>		
Exterior & Architectura	I Notes:				
of eight similar rowhon a solid concrete foun dwelling and is enhaum and-dart molding. The transom. All window concrete jack arches on a brick pier found Tuscan wood column	tructed in 1907 by Harrouses constructed from dation. The façade (eanced along the façade e southernmost bay of openings on the façade with keystones. A one ation. The roof of the pas. Metal balusters enciside) and rear (west) el	m the same permit (#2 st elevation) is faced and south (side) eleva f the first story holds a le hold 1/1, double-hu lestory, two-bay porch porch has overhanging sircle the porch, which	2691). The dwelling is with Flemish-bond by a projecting a single-leaf door and ng, wood-sash windo shelters the primary g eaves and scrolled n is accessed by pour	constructed of cick. A sloping remolded cornice I a one-light recovers and have contrance and commodillions and red concrete ste	brick and is set on oof caps the with dentil and egg- tangular wood oncrete sills and entral bay and is set is supported by ps in the southern
Site Notes:					
Avenue, S.E. and is s dwelling is adjacent t	wo-story rowhouse is et back approximately to 713 14th Street, S.E. talkway leads from the RES DATA	ten feet from the con The small front yard,	crete sidewalks. The which faces 14th Str	north (side) elev eet, S.E., is land	vation of the Iscaped with mature
Component	Featu	re			
Roof Component Sloped	Material Not Visible	Color	Treatment Not Visible	Source	
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Flemish Bond		
Structure Component	Material	Feature		Source	
Foundation Walls	Concrete Brick				
Materials Notes:					
WINDOW/DOOR/IN	TERIOR DATA				
Window Location	Aperture Shape	Туре	Lig	ıhts	Material
Facade	Rectangular	Dbl-Hung	1/1		Wood
Door Location	Aperture Shape	Туре	Pa	mels	Material
Main Door	Rectangular	Single			Unknown
Notable Interior Plan(s)		Notable Interior F	eature(s)	
Interior Notes:					

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC:

Zoning: Designation Event(s)

Contributing:

Capitol Hill Southeast Phase I (2009/2010) Permit Research	
Volunteer Reconnaissance Survey	
Volunteer Reconnaissance Survey	

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\

File: 715_14STSE.JPG

Date:: Photog:

Fr: Code:: R:



PHOTOS - B/W OR NON-DIGITIZED

|--|

MISCELLANEOUS NOTES DATA

notes:						

PERMIT DATA

Permit Issue Date	Number Type	Remarks	
03/07/1907	2691 Ruild		

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1044-0003 Page 3

ID Number: 1044-0801

ID Number: 1044	-0801	Year Built:	1907	Data So	ource: Permit		
Number Extended	Street			Quad Typ	oe of Address		
1343	G Street			SE Cu	rrent		
Name(s)			Type o	of Name			
Single Dwelling, 134	3 G Street, S.E	i.	Comn	non			
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	iin			
1044/0801		Square/Lot	Curre	ent			
STATUS/PURPOS							
Resource Type: Buil	_			atus Current:	Extant		
9	toric sidential			ndition:	Poor		
naipooo. Nes	naciitiai		00	ridition.	1 001		
Function/Use			Source	Stop	Source	Explain	
Residential (Single-F	-amily)	1907	Permit			Historic/Current	
CONSTRUCTION I	DATA						
Construction Event		art Sou	ırce	Stop	Source	Cost Source	
Orig Construction	19	07 Per	mit	· ·		1500 Permit	
Construction Event		Association			Associated Na	ıme	
Orig Construction		Architect			Beers, A. H.	· · ·	
Orig Construction		Builder			Wardman, Ha	irry	
Orig Construction		Owner			Wardman, Ha	irry	
Construction Notes:							
PEOPLE/EVENTS	ΠΑΤΑ						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Refere	ence Notes:		
Streetscape:	Intact		Г				
Relate to Othr Bldgs:							
Relate to Street:	Face on Setb						
Massing: Footprint:	Row Building Rectangular	/Front Porch					
	_						
Number Stories: Bays Wide:	2 2						
Height:	2		Outbuild	ing Type	(Contributing Status	
Width:	30			9 .) [-		g	-
Depth/Length:	20						
SqFt:							
Volume:							
Lot Width Lot Depth/Length:			Outhuild	ing Notes:			
Lot SqFt:			Catbana	9 140103.			
Acreage:							
Has Driveway:							

Architectural Style(s) Colonial Revival Exterior & Architectural Notes: February 2008: Constructed in 1907 by Harry Wardman, this two-story, four-bay Colonial Revival-style dwelling is si in style as 1345-1351 6 Street, S.E. The dwelling is constructed of brick and is set on a solid concrete foundation; bare faced with Flemish-bond brick. A sloping roof caps the dwelling and is enhanced along the façade (north elevat by a projecting molded metal cornice with brackets featuring anthemion molding. A single-leaf door with a one-ligh rectangular wood transom and concrete lintel pierces the façade. The two easternmost window bays of the first sto the single and paired window openings of the second story are infilled with plywood. The westernmost bay of the fistory retains a 1/1, double-hung, metal-sash window. All window openings have concrete six, concrete jack archet keystones, and inoperable louvered shutters. A one-story, three-bay porch shelters the primary entrance and easter flanking window opening and is set on a brick pier foundation that has been infilled with wood lattice. The roof of the porch has overhanging eaves with modillions and is supported by Corinthian cast iron columns. The porch, which encircled by hairpin and picket metal balusters, is accessed via poured concrete steps with cast iron hand rails in the central bay. The west (side) and rear (south) elevations were not surveyed or photographed by the volunteer survey. Site Notes: February 2008: This two-story dwelling is located on the south side of G Street, S.E. and is set back approximately feet from the concrete sidewalk. The east (side) elevation of the dwelling is adjacent to 1345 G Street, S.E. The gras front yard features minimal shrubbery. Hairpin and picket metal fencing encircle the property and is set above a low stone retaining wall. An alley is located south of the dwelling. **NOTABLE FEATURES DATA** Roof Component Material Color Treatment Source Flemish Bond Structure Component Material Feature Source Flemish Bond Stru	ooth tion) it ory and irst s with rn he is the /or.
Exterior & Architectural Notes: February 2008: Constructed in 1907 by Harry Wardman, this two-story, four-bay Colonial Revival-style dwelling is si in style as 1345-1351 G Street, S.E. The dwelling is constructed of brick and is set on a solid concrete foundation; be are faced with Flemish-bond brick. A sloping roof caps the dwelling and is enhanced along the façade (north elevat by a projecting molded metal cornice with brackets featuring anthemion molding. A single-leaf door with a one-ligh rectangular wood transom and concrete lintel pierces the façade. The two easternmost window bays of the first sto the single and paired window openings of the second story are infilled with plywood. The westernmost bay of the fistory retains a 1/1, double-hung, metal-sash window. All window openings have concrete silks, concrete jack arche keystones, and inoperable louvered shutters. A one-story, three-bay porch shelters the primary entrance and easter flanking window opening and is set on a brick pier foundation that has been infilled with wood lattice. The roof of the porch has overhanging eaves with modillions and is supported by Corinthian cast iron columns. The porch, which encircled by hairpin and picket metal balusters, is accessed via poured concrete steps with cast iron hand rails in the central bay. The west (side) and rear (south) elevations were not surveyed or photographed by the volunteer survey. Site Notes: February 2008: This two-story dwelling is located on the south side of G Street, S.E. and is set back approximately if feet from the concrete sidewalk. The east (side) elevation of the dwelling is adjacent to 1345 G Street, S.E. The gras front yard features minimal shrubbery. Hairpin and picket metal fencing encircle the property and is set above a low stone retaining wall. An alley is located south of the dwelling. NOTABLE FEATURES DATA Component Material Color Treatment Source Facade Brick Flemish Bond Structure Component Material Feature Source	ooth tion) it ory and irst s with rn he is the /or.
February 2008: Constructed in 1907 by Harry Wardman, this two-story, four-bay Colonial Revival-style dwelling is si in style as 1345-1351 G Street, S.E. The dwelling is constructed of brick and is set on a solid concrete foundation; is are faced with Flemish-bond brick. A sloping roof caps the dwelling and is enhanced along the façade (north elevat by a projecting molded metal cornice with brackets featuring anthemion molding. A single-leaf door with a one-ligh rectangular wood transom and concrete lintel pierces the façade. The two easternmost window bays of the first sto the single and paired window openings of the second story are infilled with plywood. The westernmost bay of the fistory retains a 1/1, double-hung, metal-sash window. All window openings have concrete sills, concrete jack archer keystones, and inoperable louvered shutters. A one-story, three-bay porch shelters the primary entrance and easter flanking window opening and is set on a brick pier foundation that has been infilled with wood lattice. The roof of the porch has overhanging eaves with modillions and is supported by Corinthian cast iron columns. The porch, which encircled by hairpin and picket metal balusters, is accessed via poured concrete steps with cast iron hand rails in tentral bay. The west (side) and rear (south) elevations were not surveyed or photographed by the volunteer survey. Site Notes: February 2008: This two-story dwelling is located on the south side of G Street, S.E. and is set back approximately feet from the concrete sidewalk. The east (side) elevation of the dwelling is adjacent to 1345 G Street, S.E. The gras front yard features minimal shrubbery. Hairpin and picket metal fencing encircle the property and is set above a low stone retaining wall. An alley is located south of the dwelling. NOTABLE FEATURES DATA Component Material Color Treatment Source Feacade Brick Flemish Bond Structure Component Material Feature Source	ooth tion) it ory and irst s with rn he is the /or.
in style as 1345-1351 G Street, S.E. The dwelling is constructed of brick and is set on a solid concrete foundation; to are faced with Flemish-bond brick. A sloping roof caps the dwelling and is enhanced along the façade (north elevate by a projecting molded metal cornice with brackets featuring anthemion molding. A single-leaf door with a one-ligh rectangular wood transom and concrete lintel pierces the façade. The two easternmost window bays of the first sto the single and paired window openings of the second story are infilled with plywood. The westernmost bay of the first story retains a 1/1, double-hung, metal-sash window. All window openings have concrete sills, concrete jack archet keystones, and inoperable louvered shutters. A one-story, three-bay porch shelters the primary entrance and easter flanking window opening and is set on a brick pier foundation that has been infilled with wood lattice. The roof of the porch has overhanging eaves with modillions and is supported by Corinthian cast iron columns. The porch, which encircled by hairpin and picket metal balusters, is accessed via poured concrete steps with cast iron hand rails in tentral bay. The west (side) and rear (south) elevations were not surveyed or photographed by the volunteer survey. Site Notes: February 2008: This two-story dwelling is located on the south side of G Street, S.E. and is set back approximately feet from the concrete sidewalk. The east (side) elevation of the dwelling is adjacent to 1345 G Street, S.E. The gras front yard features minimal shrubbery. Hairpin and picket metal fencing encircle the property and is set above a low stone retaining wall. An alley is located south of the dwelling. **NOTABLE FEATURES DATA** **EXTERIOR MATERIALS DATA** **EXTERIOR MATERIALS DATA** **Component** **Material** **Color** **Treatment** **Source** **Flemish Bond** **Source** **Flemish Bond** **Source** **Flemidation** **Color Treatment** **Source** **Flemidation** **Flemidation** **Flemidation** **Flemidation** **Flemid	ooth tion) it ory and irst s with rn he is the /or.
February 2008: This two-story dwelling is located on the south side of G Street, S.E. and is set back approximately feet from the concrete sidewalk. The east (side) elevation of the dwelling is adjacent to 1345 G Street, S.E. The gras front yard features minimal shrubbery. Hairpin and picket metal fencing encircle the property and is set above a low stone retaining wall. An alley is located south of the dwelling. NOTABLE FEATURES DATA Component Feature EXTERIOR MATERIALS DATA Roof Component Material Color Treatment Source Sloped Not Visible Not Visible Wall Component Material Color Treatment Source Facade Brick Flemish Bond Structure Component Material Feature Source Foundation Concrete	sy
EXTERIOR MATERIALS DATA Roof Component Material Color Treatment Source Sloped Not Visible Not Visible Wall Component Material Color Treatment Source Facade Brick Flemish Bond Structure Component Material Feature Source Foundation Concrete	
EXTERIOR MATERIALS DATA Roof Component Material Color Treatment Source Sloped Not Visible Not Visible Wall Component Material Color Treatment Source Facade Brick Flemish Bond Structure Component Material Feature Source Foundation Concrete	
Structure Component Material Feature Source Foundation Concrete	
Foundation Concrete	
Materials Notes:	
WINDOW/DOOR/INTERIOR DATA	
Window Location Aperture Shape Type Lights Material	
Facade Rectangular Dbl-Hung 1/1 Metal	
Facade Rectangular Dbl-Hung None Metal	
Door Location Aperture Shape Type Pamels Material	
Main Door Rectangular Single Unknow	n
Notable Interior Plan(s) Notable Interior Feature(s)	

Neighborhood: Capitol Hill

Subdivision: Ward/ANC:

Zoning:	:			Designation Event(s)		
Contrib	outing:					
Survey	(s)			Level(s) of Investigat	ion	
Capito	l Hill Southeast Phas	e I (2009/2010)		Permit Research		
				Volunteer Reconnai	issance Survey	
РНОТ	OS - DIGITIZED					
Caption	n:					
Path: File:	C:\Users\CHRS\Doo Databases\SE Phas St\Database\Picture 1343_GSTSE.JPG	se I - D to G				
Date::	Photog	:				
Code::		R: Fr:				
Photo (OS - B/W OR NON- Code Roll ELLANEOUS NOTE	Frame(s)	Date	Photographer	Caption	
Notes:						
PERM	IT DATA					
Permit	Issue Date	Number Type		Remarks		
03/09/1	907	2726 Build				
Permit	Notes:					
BIBLIC	OGRAPHIC DATA					
SIGNII	FICANCE DATA					
Study L	Jnit					
Code	Criteria					

DATA PROCESSING EVENTS DATA

ID Number: 1044-0018

ID Number: 1044	l-0018	Year Built:	1907	Data So	ource: Permit		
Number Extended	Street			Quad Typ	e of Address		
1345	G Street			SE Cu	rrent		
Name(s)			Type	of Name			
Rowhouse, 1345 G S	Street, S.E.		Comr	non			
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	ain			
1044/0018		Square/Lot	Curr	ent			
STATUS/PURPOS							
Resource Type: Buil	_			atus Current:	Extant		
9	toric vhouse			uality: ondition:	Good		
, aipooo.	viiouse		00	manion.	Coou		
Function/Use			Source	Stop	Source	Explain	
Residential (Single-I	Family)	1907	Permit			Historic/Current	
CONSTRUCTION	DATA						
Construction Event		art Sou	ırce	Stop	Source	Cost Source	
Orig Construction	19	007 Per	mit	<u> </u>		1500 Permit	
Construction Event		Association			Associated Na	me	
Orig Construction		Architect			Beers, A. H.	<u> </u>	
Orig Construction		Builder			Wardman, Ha	rry	
Orig Construction		Owner			Wardman, Ha	rry	
Construction Notes: One of four rowhous	ses constructe	d from the sa	ıme perm	it (#2692).			
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Refere	ence Notes:		
Streetscape:	Intact		ſ	O1033 INCICIO	chec Notes.]
Relate to Othr Bldgs:							
Relate to Street:	Face on Setb	ack Line					
Massing:	Row Building	/Front Porch					
Footprint:	Rectangular						
Number Stories:	2						
Bays Wide:	3		Ŀ				,
Height:			Outbuild	ing Type	C	Contributing Status	_
Width:	20						
Depth/Length:	30						
SqFt: Volume:							
Lot Width							
Lot Depth/Length:			Outbuild	ing Notes:			
Lot SqFt:				-			
Acreage:							
Has Driveway:							

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Interior Notes:

Ward/ANC: Zoning:

Contributing:

Designation Event(s)

	J					
Survey	(s)			Level(s) of Investigati	on	
	I Hill Southeast Phas	se I (2009/2010)		Permit Research Volunteer Reconnai		
РНОТ	OS - DIGITIZED					
Caption	1:					
Path: File:	C:\Users\CHRS\Do Databases\SE Pha St\Database\Pictui 1345_GSTSE.JPG	se I - D to G				
Date::	Photo	g:	Alle Man A	I KAN		
Code::		R: Fr:	-			
Photo (OS - B/W OR NON Code Roll ELLANEOUS NOTE	Frame(s)	Date	Photographer	Caption	
Notes:	ELLANEOUS NOTE	ES DATA				
PERM	IT DATA					
Permit 03/07/1	Issue Date	Number Type 2692 Build		Remarks		
Permit						
BIBLIC	OGRAPHIC DATA					
SIGNII	FICANCE DATA					
Study L						
			"			

DATA PROCESSING EVENTS DATA

Criteria

Code

ID_Number: 1044-0018 Page 3

ID Number: 1044-0019

ID Number: 1044	-0019	Year Built:	1907	Data So	ource: Permit		
Number Extended	Street			Quad Typ	e of Address		
1347	G Street			SE Cu	rrent		
Name(s)			Type	of Name			
Rowhouse, 1347 G S	Street, S.E.		Comr	non	<u> </u>		
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	ain			
1044/0019		Square/Lot	Curr	ent			
STATUS/PURPOS							
Resource Type: Buil	_			atus Current:	Extant		
9	toric vhouse			uality: ondition:	Good		
, aipooo.	viiouse		00	manion.	300 4		
Function/Use	= !!. A		Source	Stop	Source	Explain	
Residential (Single-I	-amily)	1907	Permit			Historic/Current	
CONSTRUCTION	DATA						
Construction Event		art Sou	irce	Stop	Source	Cost Source	
Orig Construction	19	007 Per	mit	<u> </u>		1500 Permit	
Construction Event		Association			Associated Na	ıme	
Orig Construction		Architect			Beers, A. H.		
Orig Construction		Builder			Wardman, Ha	rry	
Orig Construction		Owner			Wardman, Ha	rry	
Construction Notes: One of four rowhous	ses constructe	d from the sa	me perm	it (#2692).			
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Refere	ance Notes:		
Streetscape:	Intact		ſ	CIOSS INCICIO	ence notes.		1
Relate to Othr Bldgs:							
Relate to Street:	Face on Setb	ack Line					
Massing:	Row Building	/Front Porch					
Footprint:	Rectangular						
Number Stories:	2						
Bays Wide:	3		_				
Height:			Outbuild	ing Type	C	Contributing Status	-
Width:	20						
Depth/Length: SqFt:	30						
Volume:							
Lot Width							
Lot Depth/Length:			Outbuild	ing Notes:			_
Lot SqFt:							
Acreage:							
Has Driveway:							

Architectural Style(s)					
Colonial Revival					
Exterior & Architectura	al Notes:				
of four similar rowho solid concrete found roof caps the dwellir anthemion molding. transom. All window concrete jack arches one-story, two-bay p the porch has overha wood balusters enci	puses constructed from ation that has been pa ag and is enhanced alo The easternmost bay of openings on the façad with keystones. The worch shelters the prima anging eaves and mod	n the same permit (#2) orged. The façade (nore) org the façade by a proposed the first story holds de hold 1/1, double-hundersternmost bay of the ary entrance and cent illions and is supported accessed by poured	story, three-bay Colonia 692). The dwelling is conth elevation) is faced wind ojecting molded metal control a single-leaf door and a ing, vinyl-sash windows e foundation holds a single lay and is set on a be ed by Tuscan wood colusticoncrete steps in the e rveyor.	nstructed of bri th Flemish-bon ornice with bra a one-light recta and have cond ngle-leaf multi-l rick pier found umns set on bri	ick and is set on a and brick. A sloping ackets featuring angular wood crete sills and ight wood door. A ation. The roof of ick posts. Square
Site Notes:			•		
sidewalk approximat along its northern ed	ely ten feet. The dwelli Ige by a low, stone reta	ing is adjacent to 1345	side of G Street, S.E. an and 1349 G Street, S.E located south of the dv	. The small fror	
NOTABLE FEATUR	RES DATA				
Component	Featu	ire			
EXTERIOR MATER	RIALS DATA				
EXTERIOR MATER Roof Component Sloped	Material Not Visible	Color	Treatment Not Visible	Source	
Roof Component Sloped	Material	Color		Source Source	
Roof Component Sloped Wall Component	Material Not Visible		Not Visible		
Roof Component	Material Not Visible Material		Not Visible Treatment		
Roof Component Sloped Wall Component Facade Structure Component Foundation	Material Not Visible Material Brick Material Concrete	Color	Not Visible Treatment	Source	
Roof Component Sloped Wall Component Facade Structure Component	Material Not Visible Material Brick Material	Color	Not Visible Treatment	Source	
Roof Component Sloped Wall Component Facade Structure Component Foundation	Material Not Visible Material Brick Material Concrete	Color	Not Visible Treatment	Source	
Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Material Not Visible Material Brick Material Concrete Brick	Color	Not Visible Treatment	Source	
Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick	Color	Not Visible Treatment	Source	Material
Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/IN	Material Not Visible Material Brick Material Concrete Brick	Color Feature	Not Visible Treatment Flemish Bond	Source	Material Vinyl
Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick	Color Feature	Not Visible Treatment Flemish Bond	Source	
Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/IN Window Location Facade	Material Not Visible Material Brick Material Concrete Brick ITERIOR DATA Aperture Shape Rectangular	Color Feature Type Dbl-Hung	Not Visible Treatment Flemish Bond Light:	Source	Vinyl
Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/IN Window Location Facade Door Location	Material Not Visible Material Brick Material Concrete Brick ITERIOR DATA Aperture Shape Rectangular Aperture Shape	Color Feature Type Dbl-Hung Type	Not Visible Treatment Flemish Bond Light:	Source	Vinyl Material

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC:

Zoning: Designation Event(s)

Contributing:

	J					
Survey	(s)			Level(s) of Investigat	ion	
	Hill Southeast Pha	se I (2009/2010)		Permit Research Volunteer Reconnai		
РНОТ	OS - DIGITIZED					
Caption	1:					
Path: File:	C:\Users\CHRS\D Databases\SE Ph St\Database\Pictu 1347_GSTSE.JPG	ase I - D to G ires\Square 1044\				
Date::	Photo	og:				
Code::		R: Fr:				
PHOTO	OS - B/W OR NON Code Roll	I-DIGITIZED Frame(s)	Date	Photographer	Caption	
MISCE	ELLANEOUS NOT	ES DATA				
Notes:						
PERM	IT DATA					
Permit	Issue Date	Number Type		Remarks		
03/07/1	907	2692 Build				
Permit	Notes:					
BIBLIC	OGRAPHIC DATA					
SIGNII	FICANCE DATA					
Study L	Jnit					

DATA PROCESSING EVENTS DATA

Criteria

Code

ID Number: 1044-0020

ID Number: 1044	-0020	Year Buil	t: 1907	Dat	a Source:	Permit		
Number Extended	Street			Quad	Type of Add	dress		
1349	G Street			SE	Current			
Name(s)			Туре	of Name				
Rowhouse, 1349 G S	Street, S.E.		Curre	nt				
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	ain				
1044/0020		Square/Lot						
STATUS/PURPOS	E/USE DATA	1						
Resource Type: Bui	lding		Sta	atus Curr	ent: Extant			
9	toric		Qι	uality:				
Purpose: Rov	vhouse		Co	ndition:	Good			
Function/Use		Start	Source	Stop	,	Source	Explain	
Residential (Single-I	amily)	1907	Permit				Historic/Current	
CONSTRUCTION I	DATA							
Construction Event	S	tart So	urce	Stop	Source)	Cost Source	
Orig Construction	19	907 Pe	rmit				1500 Permit	
Construction Event		Association			Asso	ciated Na	me	
Orig Construction		Architect			Beer	s, A. H.		
Orig Construction		Builder				dman, Ha	-	
Orig Construction		Owner			War	dman, Ha	rry	
Construction Notes:								
One of four rowhous	ses constructe	ed from the s	ame perm	it (#2692	2).			
PEOPLE/EVENTS	DATA							
Racial Segregation St	tatus:							
SETTING/SHAPE/S	RIZE DATA							
Surroundings:	Urban		г	Cross Re	eference No	es:		
Streetscape: Relate to Othr Bldgs:	Intact							
Relate to Street:	Face on Sett	ack Line						
Massing:	Row Building		h					
Footprint:	Rectangular							
Number Stories:								
Bays Wide:	2		L					
Height:			Outbuild	ing Type		C	Contributing Status	
Width:	20							
Depth/Length:	30							
SqFt: Volume:								
Lot Width								
Lot Depth/Length:			Outbuild	ing Notes	s:			
Lot SqFt:								
Acreage:								
Has Driveway:								

Colonial Revival Exterior & Architectura	l Notes:					
February 2008: Const of four similar rowho solid concrete found: along the façade (nor easternmost bay of the transom. All window concrete jack arches on a brick pier found wood columns set or	tructed in 1907 by Harn uses constructed fron ation; both are faced v th elevation) by a proj the first story holds a s openings on the façac with keystones. A one ation. The roof of the p a stone piers. Square v end bay. The rear (sou	n the same permit (#2 with Flemish-bond bri jecting molded metal ingle-leaf paneled wo de hold 1/1, double-hu pestory, two-bay porch porch has overhangin wood balusters encirc	692). The dwelling is on ck. A sloping roof cap cornice with brackets and door with lights and ung, vinyl-sash window a shelters the primary ag eaves and modillion cle the porch, which is	constructed of beather the dwelling and featuring anther and a one-light rews and have contrance and centrance and sand is supports accessed by possible.	rick and is set on a and is enhanced mion molding. The ctangular wood nerete sills and entral bay and is set reed by Tuscan pured concrete	
Site Notes:						
feet from the concret planted with mature t	wo-story rowhouse is e sidewalk. The dwelli rees and shrubs, as w An alley is located at t	ng is adjacent to 1351 vell as foundation plan	1 and 1347 G Street, S ntings and is bounded	.E. The landscap	ped front yard is	
Component	Featu	ire				
Component EXTERIOR MATER Roof Component	Featu	Color	Treatment Not Visible	Source		
EXTERIOR MATER Roof Component Sloped	Featu IALS DATA Material			Source Source		
EXTERIOR MATER Roof Component Sloped Wall Component	Featu IALS DATA Material Not Visible	Color	Not Visible			
EXTERIOR MATER Roof Component Sloped Wall Component Facade	Featu IALS DATA Material Not Visible Material	Color	Not Visible Treatment			
Component EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Featu IALS DATA Material Not Visible Material Brick	Color	Not Visible Treatment	Source		
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Featu IALS DATA Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond	Source		
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Feature Featur	Color Color Feature	Not Visible Treatment Flemish Bond	Source		
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: One of four rowhouse	Featu IALS DATA Material Not Visible Material Brick Material Concrete Brick Brick	Color Color Feature	Not Visible Treatment Flemish Bond	Source		
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: One of four rowhouse	Featu IALS DATA Material Not Visible Material Brick Material Concrete Brick Brick	Color Color Feature	Not Visible Treatment Flemish Bond 2).	Source	Material	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: One of four rowhouse WINDOW/DOOR/IN	Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond 2).	Source	Material Vinyl	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Feature Featur	Color Color Feature ne same permit (#2692	Not Visible Treatment Flemish Bond 2). Lig	Source		

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC:

Interior Notes:

Zoning: Designation Event(s)

Contributing:

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\

File: 1349_GSTSE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

03/07/1907 2692 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1044-0020 Page 3

ID Number: 1044-0021

	021	Year Built:	1907	Data So	ource: Permit		
Number Extended	Street			Quad Typ	e of Address		
1351	G Street			SE Cui			
Name(s)			Type of	Name			
Rowhouse, 1351 G Str	eet, S.E.		Commo				
TayCodo1 TayCodo2	ToyCodo2 Ty		Cyploin				
TaxCode1 TaxCode2 1044/0021	,	uare/Lot	Explain Curren				
1044/0021	94	dai o, Lot	Guiren	•			
STATUS/PURPOSE/	USE DATA						
Resource Type: Buildi	ng		Statu	s Current:	Extant		
Desig. Status: Histor	ric		Quali				
Purpose: Rowh	ouse		Cond	lition:	Good		
Function/Use	St	art So	ource	Stop	Source	Explain	
Residential (Single-Fa			ermit			Historic/Current	
CONSTRUCTION DA	ATA						
Construction Event	Start	Sourc	ce S	Stop	Source	Cost Source	
Orig Construction	1907	Perm	nit	-		1500 Permit	
Construction Event	As	sociation			Associated Na	ame	
Orig Construction		chitect			Beers, A. H.		
Orig Construction		ilder			Wardman, Ha	arry	
Orig Construction	Ov	ner			Wardman, Ha		
Construction Notes:							
One of four rowhouse	s constructed fr	om the san	ne permit ((#2692).			
			•	,			
PEOPLE/EVENTS D	ATA						
Daniel Commonstion Ctat							
Racial Segregation Stat	us:						
Racial Segregation Stat	us:						
SETTING/SHAPE/SI							
SETTING/SHAPE/SI			Cr	oss Refere	ence Notes:		
SETTING/SHAPE/SIZ Surroundings: U Streetscape: II	ZE DATA Irban ntact		Cr	oss Refere	ence Notes:		7
SETTING/SHAPE/SIZ Surroundings: L Streetscape: In Relate to Othr Bldgs: F	ZE DATA Irban ntact Row End (1 of 4)		Cr	oss Refere	ence Notes:		
SETTING/SHAPE/SIZ Surroundings: U Streetscape: II Relate to Othr Bldgs: R Relate to Street: F	ZE DATA Irban ntact Row End (1 of 4) face on Setback		Cr	oss Refere	ence Notes:		
SETTING/SHAPE/SIZ Surroundings: U Streetscape: II Relate to Othr Bldgs: F Relate to Street: F Massing: F	ZE DATA Irban ntact Row End (1 of 4) face on Setback Row Building/Fro		Cr	oss Refere	ence Notes:		
SETTING/SHAPE/SIZ Surroundings: U Streetscape: II Relate to Othr Bldgs: F Relate to Street: F Massing: F	ZE DATA Irban ntact Row End (1 of 4) face on Setback		Cr	oss Refere	ence Notes:		
SETTING/SHAPE/SIZ Surroundings: U Streetscape: II Relate to Othr Bldgs: F Relate to Street: F Massing: F Tootprint: F Number Stories:	ZE DATA Irban ntact Row End (1 of 4) face on Setback Row Building/Fro		Cr	oss Refere	ence Notes:		
SETTING/SHAPE/SIZ Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide:	ZE DATA Irban ntact Row End (1 of 4) Face on Setback Row Building/From	ont Porch					
SETTING/SHAPE/SIZ Surroundings: UStreetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height:	ZE DATA Irban ntact Row End (1 of 4) face on Setback Row Building/Fro tectangular 2 3	ont Porch	Cr			Contributing Status	
SETTING/SHAPE/SIZ Surroundings: UStreetscape: IRelate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width:	ZE DATA Irban Intact Row End (1 of 4) Face on Setback Row Building/Fro Rectangular 2 3	ont Porch				Contributing Status	
SETTING/SHAPE/SIZ Surroundings: UStreetscape: In Relate to Othr Bldgs: Relate to Street: FMassing: FOOTPRINT: FOOTPRINT: FOUR BLDGS: Bays Wide: Height: Width: Depth/Length:	ZE DATA Irban ntact Row End (1 of 4) face on Setback Row Building/Fro tectangular 2 3	ont Porch				Contributing Status	
SETTING/SHAPE/SIZ Surroundings: L. Streetscape: In Relate to Othr Bldgs: R. Relate to Street: F. Massing: F. Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt:	ZE DATA Irban Intact Row End (1 of 4) Face on Setback Row Building/Fro Rectangular 2 3	ont Porch				Contributing Status	
SETTING/SHAPE/SIZ Surroundings: L. Streetscape: In Relate to Othr Bldgs: F. Relate to Street: F. Massing: F. Otoprint: F. Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume:	ZE DATA Irban Intact Row End (1 of 4) Face on Setback Row Building/Fro Rectangular 2 3	ont Porch				Contributing Status	
SETTING/SHAPE/SIZ Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width	ZE DATA Irban Intact Row End (1 of 4) Face on Setback Row Building/Fro Rectangular 2 3	ont Porch		з Туре		Contributing Status	
SETTING/SHAPE/SIZ Surroundings: L. Streetscape: In Relate to Othr Bldgs: F. Relate to Street: F. Massing: F. Otoprint: F. Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume:	ZE DATA Irban Intact Row End (1 of 4) Face on Setback Row Building/Fro Rectangular 2 3	ont Porch	Outbuilding	з Туре		Contributing Status	
SETTING/SHAPE/SIZ Surroundings: L. Streetscape: III Relate to Othr Bldgs: F. Relate to Street: F. Massing: F. Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length:	ZE DATA Irban Intact Row End (1 of 4) Face on Setback Row Building/Fro Rectangular 2 3	ont Porch	Outbuilding	з Туре		Contributing Status	

STYLE/EXTERIOR DATA Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

February 2008: Constructed in 1907 by Harry Wardman, this two-story, three-bay Colonial Revival-style rowhouse is one of four similar rowhouses constructed from the same permit (#2692). The dwelling is constructed of brick and is set on a solid concrete foundation; both are faced with Flemish-bond brick. A sloping roof caps the dwelling and is enhanced along the façade (north elevation) by a projecting molded metal cornice with brackets featuring anthemion molding. The easternmost bay of the first story holds a single-leaf door and a one-light rectangular wood transom. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows and have concrete sills. The first story openings have concrete lintels and the second story openings have concrete jack arches with keystones. A one-story, two-bay porch shelters the primary entrance and central bay and is set on a solid stone foundation. The roof of the porch has overhanging eaves and modillions and is supported by Tuscan wood columns set on stone piers. A stone balustrade encircles the porch, which is accessed by poured concrete steps in the eastern end bay. The rear (south) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

February 2008: This two-story rowhouse is located on the south side of G Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The west (side) elevation of the dwelling is adjacent to 1349 G Street, S.E. and a concrete alley runs parallel to the east (side) elevation of the dwelling. The small front yard is landscaped with mature trees and shrubs and is bounded along its northern edge by a low, stone retaining wall. An alley is located south of the dwelling.

NOTABLE FEATURES DATA

Component	Feature	
-----------	---------	--

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Flemish Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

One of four rowhouses constructed from the same permit (#2692).

WINDOW/DOOR/INTERIOR DATA

Aperture Shape	Type	Lights	Material	
Rectangular	Dbl-Hung	1/1	Vinyl	
Aperture Shape	Туре	Pamels	Material	
Rectangular	Single		Unknown	
n(s)		Notable Interior Feature(s)		
	Rectangular Aperture Shape Rectangular	Rectangular Dbl-Hung Aperture Shape Type Rectangular Single	Rectangular Dbl-Hung 1/1 Aperture Shape Type Pamels Rectangular Single	Rectangular Dbl-Hung 1/1 Vinyl Aperture Shape Type Pamels Material Rectangular Single Unknown

Interio	r N	lotes	S

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)
Subdivision:

Ward/ANC:
Zoning: Designation Event(s)

Contrib	-		
Survey	(s)	Level(s) of Investigation	
Capito	Hill Southeast Phase I (2009/2010)	Permit Research Volunteer Reconnaissance Survey	
PHOT	OS - DIGITIZED		
Caption	C:\Users\CHRS\Documents\CHRS		
File:	Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\ 1351 GSTSE.JPG		
Date::	Photog:		
Code::	R:	Fr:	

Photo Code Frame(s) Date Caption **MISCELLANEOUS NOTES DATA** Notes: **PERMIT DATA** Remarks Permit Issue Date Number Type 03/07/1907 2692 Build Permit Notes: **BIBLIOGRAPHIC DATA** SIGNIFICANCE DATA Study Unit Code Criteria

ID Number: 1044-0802a

ID Number: 1044-0802a Page 1

BASICS DATA

ID Number: 1044-0802a Year Built: 1907 Data Source: Permit

Number Extended Street Quad Type of Address

1330 Pennsylvania Avenue SE Current

Name(s) Type of Name

Single Dwelling, 1330 Pennsylvania Avenue, S.E. Common
La Lomita Mexican Restaurant Current

TaxCode1 TaxCode2 TaxCode3 Type Explain

1044/0802a Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1907 Permit Original

Restaurant/Dwelling Current

CONSTRUCTION DATA

Construction Event Start Source Cost Source Stop Source **Orig Construction** 1907 **Permit** 1500 Permit Construction Event Association Associated Name **Orig Construction Architect** Beers, A. H. **Orig Construction** Builder Wardman, Harry **Orig Construction** Owner Wardman, Harry

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings:	Urban	Cross Ref	erence Notes:		
Streetscape:	Intact]
Relate to Othr Bldgs:	Semi-Attached				
Relate to Street:	Face on Line				
Massing:	Vertical Block				
Footprint:	Polygonal				
Number Stories:	2				
Bays Wide:	3				J
Height:		Outbuilding Type	Co	ontributing Status	
Width:	20				=
Depth/Length:	34				
SqFt:					
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes	•		٦
Lot SqFt:					
Acreage:					
Has Driveway:					
					_
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
, , ,			_		
Colonial Revival					
Exterior & Architecture	al Notes:				
anthemion molding. north corner of the f southwest elevation have concrete sills a of the southwest ele vinyl-sash windows, of a 1/1, double-hun volunteer surveyor. Site Notes:	The first story of the faceade and is faced with accord story win and concrete jack archevation. A canopy shelt, which have a concrete g, vinyl-sash window.	açade is pierced by a or h Permastone. A one-si dow openings of the fa es with keystones. Dou ers the doors. The sec e sill and concrete jack The northeast (side) ele	ne-light fixed wood woory pent roof spans to gade contain 1/1, doe ble-leaf paneled door ond story is fenestrate arch with a keystone wation was not surve	nice with brackets featuring indow. A bay projects from the façade and wraps around ble-hung, vinyl-sash wind swith lights pierce the first with paired 1/1, double-backet and the factor of the facto	n the and to the dows and st story chung, onsists
•	, ,	ation of the dwelling is	•		y ironts
NOTABLE FEATU	RES DATA Featu	иге			
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		-
•		Calan		Course	
Wall Component	Material	Color	Treatment	Source	
Facade (Lower)	Permastone		Veneer		
Facade (Upper)	Brick		Flemish Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				
Materials Notes:					
materiale (Votes.					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
1 Flr Windows	Rectangular	Fixed	1	Wood	
2 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Double	Paneled	Unknown	
Notable Interior Plan	n(s)	1	Notable Interior Feature(s)		

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision: Ward/ANC: Zoning: Contributing:

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Historic District(s)

Designation Event(s)

Level(s) of Investigation **Permit Research**

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

C:\Users\CHRS\Documents\CHRS Path:

Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\

File: 1330_PA AVESE.JPG

Date:: Photog: Code::

R: Fr:



Caption:

C:\Users\CHRS\Documents\CHRS Path: Databases\SE Phase I - D to G

St\Database\Pictures\Square 1044\

File: 1330_PA.AVESE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

ID_Number: 1044-0802a Page 3

MISCELLA	NEOUS NOTES DAT	ГА				
Notes:						
PERMIT DA	ATA					
Permit Issue	Date Nun	nber T	уре	Remarks		
03/09/1907	2	2725 B	uild			
Permit Notes	::					
BIBLIOGR	APHIC DATA					
SIGNIFICA	NCE DATA					
Study Unit						
Code	Criteria					

ID_Number: 1044-0802a Page 4

ID Number: 1044-0802b

ID Number: 1044-0802b Page 1

BASICS DATA

Data Source: ID Number: 1044-0802b Year Built: 1907 Permit Number Extended Street Quad Type of Address 1332 Pennsylvania Avenue SE Current Name(s) Type of Name Rowhouse, 1332 Pennsylvania Avenue, S.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain 1044/0802b Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Fair

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1907 Permit Original

Restaurant/Dwelling Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source 1500 Permit **Orig Construction** 1907 **Permit** Construction Event Association **Associated Name Orig Construction Architect** Beers, A. H. **Orig Construction** Builder Wardman, Harry **Orig Construction** Owner Wardman, Harry Construction Notes:

One of twelve rowhouses constructed from the same permit (#2690).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings:	Urban	Cross Refere	ence Notes:		
Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Intact Row (1 of 12) Face on Line Row Building/Flat Front Rectangular				
Number Stories: Bays Wide:	2 3				
Height:		Outbuilding Type	Con	tributing Status	
Width: Depth/Length:	20 30				
SqFt:	30				
Volume:					
Lot Width Lot Depth/Length:		Outbuilding Notes:			
Lot SqFt:					
Acreage:					
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Colonial Revival (Alt	ered)				
Exterior & Architectura	al Notes:				
featuring anthemion concrete steps with windows (possibly disecond story window arches with keyston concrete steps acceone-story porch has the volunteer survey Site Notes: February 2008: This approximately ten fe	two-story rowhouse is loca	n bay of the first story cess to the door. All ght wood transoms. I e-hung, wood-sash wed by a single-leaf paining along the found cade. The rear (northe lated on the northeast alk. The dwelling is a	holds a single-leaf first story window of Rowlock brick sills findows and have con neled wood door in ation has been infilled east) elevation was re- side of Pennsylvani djacent to 1330 and	paneled wood door. Pou penings hold six-light wo inish the window openin oncrete sills and concrete the northwestern bay. Po ed with plywood. The orig not surveyed or photogra a Avenue, S.E. and is set 1334 Pennsylvania Aven	red pod gs. The piack pured ginal phed by
NOTABLE FEATU	is paved with concrete. The	e rear of the property	opens onto G Stree	τ, δ.Ε.	
Component	Feature				
-					
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade (Lower) Facade (Upper)	Permastone Brick		Veneer Flemish Bond		
,		Feature	. ioiiiidii bollu	Source	
Structure Component Foundation	Concrete	i caluic		Jource	
Walls	Brick				
Materials Notes:					
	ouses constructed from the	same permit (#2690).			

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
1 Flr Windows	Rectangular	Unknown	6	Wood	
2 Flr Windows	Rectangular	Dbl-Hung	9/9	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single	Paneled	Wood	
Main Door	Rectangular	Single	Paneled	Wood	
Notable Interior Plan	n(s)	ı	Notable Interior Feature(s)		

Interior Notes:

וח	A NI/C	IIDVEV	/DESIGN	IATION	DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation
Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\

File: 1332_PA AVESE.JPG
Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks
03/07/1907 2690 Build

ID_Number: 1044-0802b Page 3

Permit Not	tes:			
BIBLIOG	RAPHIC DATA			
SIGNIFIC	CANCE DATA			
Study Unit				
Code	Criteria			

ID_Number: 1044-0802b Page 4

ID Number: 1044-0014

ID Number: 1044	-0014	Year Built	1907	Data	a Source:	Permit		
Number Extended	Street			Quad	Type of Add	ress		
1334	Pennsylvania	Avenue		SE	Current			
Name(s)			Type	of Name				
Rowhouse, 1334 Per	nnsylvania Aver	nue, S.E.	Comr					
			Ele					
TaxCode1 TaxCode 1044/0014		Type Square/Lot	Expla Curre					
1044/0014		Square/Lot	Curr	CIIL				
STATUS/PURPOS	F/USF DATA							
Resource Type: Buil			Str	atus Curr	ent: Extant			
	oric			alus Curr Jality:	ent. Extant			
_	vhouse			ndition:	Good			
. d.pood.	Mouse			manion.	Ooou			
Function/Use		Start	Source	Stop	S	ource	Explain	
Residential (Single-F	Family)	1907	Permit				Historic/Current	
CONSTRUCTION I	DATA							
Construction Event	Sta	rt Soi	urce	Stop	Source		Cost Source	
Orig Construction	190	7 Pe	rmit				1500 Permit	
Construction Event		Association			Assoc	ciated Nar	me	
Orig Construction		Architect			Beers	s, A. H.		
Orig Construction		Builder			Ward	man, Har	rry	
Orig Construction		Owner			Ward	man, Har	rry	
Construction Notes:								
One of twelve rowho	uses construct	ed from the	same per	rmit (#26	90).			
			·		·			
PEOPLE/EVENTS	DATA							
Racial Segregation St	atus:							
radiai edgi egalidir et	ato.							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban			Cross Re	eference Note	es:		
Streetscape:	Intact		ſ					7
Relate to Othr Bldgs:								
Relate to Street:	Face on Setba	ck Line						
Massing:	Row Building/	Front Porch	1					
Footprint:	Rectangular							
Number Stories:	2							
Bays Wide:	3		L					_
Height:			Outbuild	ing Type		С	ontributing Status	
Width:	20							_
Depth/Length:	30							
SqFt:								
Volume:								
Lot Width			_					
Lot Depth/Length:			Outbuild	ing Notes	S:			٦
Lot SqFt:								
Acreage:								
Has Driveway:								

STYLE/EXTERIOR					
Architectural Style(s)					
Colonial Revival					
Exterior & Architectura					
of twelve similar row a solid concrete four dwelling and is enha The northwestern ba openings on the faça with keystones. A on foundation. The roof balusters encircle the	houses constructed from the factor. The factor (so need along the factor of the first story hold the hold 1/1, double-hold the factor, two-bay porch of the porch has over e porch, which is acce	ry Wardman, this two- rom the same permit (# buthwest elevation) is by a projecting moldeds a single-leaf door along, wood-sash windon a shelters the primary of hanging eaves and is sessed by wood steps in ed by the volunteer su	#2690). The dwelling faced with Flemish-bed metal cornice with and a one-light rectangus and have concretentrance and central supported by Tuscangus the northwestern er	is constructed of cond brick. A slop brackets with an gular wood transo te sills and concre bay and is set on wood columns. S	brick and is set on ing roof caps the themion molding. om. All window ete jack arches a brick pier Square wood
Site Notes:					
approximately ten fe	et from the concrete si	located on the northe idewalk. The dwelling couthwestern edge by	is adjacent to 1332 a	nd 1336 Pennsylv	ania Avenue, S.E.
NOTABLE FEATUR	RES DATA				
Component	Featu	ıre			
EXTERIOR MATER		Color	Treatment	Source	
EXTERIOR MATER Roof Component Sloped	IIALS DATA		Treatment Not Visible	Source	
EXTERIOR MATER Roof Component Sloped	NATA Material			Source Source	
EXTERIOR MATER Roof Component	Material Not Visible	Color	Not Visible		
EXTERIOR MATER Roof Component Sloped Wall Component	Material Mot Visible Material	Color	Not Visible Treatment		
EXTERIOR MATER Roof Component Sloped Wall Component Facade	Material Mot Visible Material Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation	Material Not Visible Material Brick Material Concrete	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Material Not Visible Material Brick Material Concrete Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick	Color	Not Visible Treatment Flemish Bond	Source	Material
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/IN Window Location	Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond	Source	Material Wood
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/IN Window Location Facade	Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick	Color Color Feature Type Dbl-Hung	Not Visible Treatment Flemish Bond Lig 1/2	Source Source	Wood

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

ID_Number: 1044-0014 Page 2

Survey(s)	Level(s) of Investigation
-----------	---------------------------

Permit Research Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G

St\Database\Pictures\Square 1044\

File: 1334_PA AVESE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

|--|

MISCELLANEOUS NOTES DATA

Notes:		

PERMIT DATA

Permit issue Date	Number Type	Remarks	
03/07/1907	2600 Build		

2000 Buil

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1044-0014 Page 3

ID Number: 1044-0013

ID Number: 1044	-0013	Year Built:	1907	Data	Source:	Permit		
Number Extended	Street			Quad T	ype of Add	ress		
1336	Pennsylvania	Avenue			Current			
Name(s)			Type of	Name				
Rowhouse, 1336 Per	nnsylvania Aver	nue, S.E.	Commo					
TaxCode1 TaxCode	2 TaxCode3	Туре	Explain					
1044/0013		Square/Lot	Curren					
STATUS/PURPOS								
Resource Type: Buil	ding oric				nt: Extant			
_	vhouse		Qual Conc	ity. dition:	Fair			
Function/Use	:I. A		Source	Stop	S	ource	Explain	
Residential (Single-F	·amiiy)	1907 F	Permit				Historic/Current	
CONSTRUCTION I	ΔΤΔ							
Construction Event	Sta	rt Sou	rce S	Stop	Source		Cost Source	
Orig Construction	190	7 Peri		•			1500 Permit	
Construction Event		Association			Assoc	ciated Na	me	
Orig Construction		Architect			Beers	s, A. H.		
Orig Construction		Builder			Ward	man, Hai	rry	
Orig Construction		Owner			Ward	man, Haı	rry	
Construction Notes:								
One of twelve rowho	uses construct	ed from the	same perm	it (#269	0).			
PEOPLE/EVENTS	ΠΔΤΔ							
Racial Segregation St								
racial ocgregation of	atus.							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban		Cr	oss Ref	erence Note	es:		
Streetscape:	Intact							
Relate to Othr Bldgs:								
Relate to Street:	Face on Setba							
Massing:	Row Building/	Front Porch						
Footprint:	Rectangular							
Number Stories:	2							
Bays Wide:	3							
Height:			Outbuilding	g Type		С	Contributing Status	-
Width:	20							
Depth/Length:	30							
SqFt:								
Volume: Lot Width								
Lot Depth/Length:			Outbuilding	n Notae:				
Lot SqFt:			- atbulluli (9 140163.]
Acreage:								
Has Driveway:								
								J.

STYLE/EXTERIOR Architectural Style(s)					
Colonial Revival			_		
Exterior & Architectura	l Notos:				
February 2008: Const of twelve similar rowl a solid concrete found welling and is enhaumolding. The northway wood transom. All with and concrete jack arctis set on a brick pier supported by Tuscan northwestern end bay Site Notes: February 2008: This tapproximately ten fee The small front yard is	tructed in 1907 by Har houses constructed findation. The façade (some dealing the façade estern bay of the first ndow openings on the ches with keystones. A foundation that is infination wood columns. Squay. The rear (northeast) wo-story rowhouse is et from the concrete sis landscaped with marked the structure of the structure	rry Wardman, this two- rom the same permit (# outhwest elevation) is a by a projecting molde story holds a single-le e façade hold 1/1, dou A one-story, two-bay pe Illed with wood lattice. are wood balusters end elevation was not sur s located on the northe idewalk. The dwelling ature trees and is bour the primary entrance a	#2690). The dwelling is faced with Flemish-bot metal cornice with I af wood-frame glass oble-hung, wood-sash worch shelters the prim The roof of the porch circle the porch, which veyed or photographe ast side of Pennsylvanis adjacent to 1334 anded along its southwood	s constructed of ond brick. A slop or ackets featuring door and a one-windows and ha ary entrance an has overhanging is accessed by the volunter of the color of	brick and is set oping roof caps the ng anthemion light rectangular live concrete sills discentral bay and is a wood steps in the eer surveyor. and is set back vania Avenue, S.E. a low, stone
NOTABLE FEATUR	RES DATA				
NOTABLE FEATUR Component	PES DATA Featu	ure			
Component EXTERIOR MATER Roof Component	Featu IALS DATA Material	ure Color	Treatment	Source	
EXTERIOR MATER Roof Component Sloped	Featu IALS DATA Material Not Visible	Color	Not Visible		
EXTERIOR MATER Roof Component Sloped Wall Component	Featu IALS DATA Material Not Visible Material		Not Visible Treatment	Source Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade	Featu IALS DATA Material Not Visible Material Brick	Color	Not Visible	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component	Feature Featur	Color	Not Visible Treatment		
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Feature Featur	Color	Not Visible Treatment	Source	Material
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Feature Featur	Color Color Feature	Not Visible Treatment Flemish Bond	Source	Material Wood
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick TERIOR DATA Aperture Shape	Color Color Feature	Not Visible Treatment Flemish Bond Light	Source	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Historic District(s)

Subdivision: Ward/ANC:

Designation Event(s)

Zoning: Contributing:

Survey(s)	Level(s) of Investigation
-----------	---------------------------

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\

File: 1336_PA AVESE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

03/07/1907 2690 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1044-0013 Page 3

ID Number: 1044-0012

ID Number: 1044	-0012	Year Built:	1907	Data	a Source: P	ermit		
Number Extended	Street			Quad	Type of Addres	S		
1338	Pennsylvania	Avenue			Current			
Name(s)			Type of	f Name				
Rowhouse, 1338 Per	nnsylvania Avei	nue, S.E.	Commo	on				
TaxCode1 TaxCode	2 TaxCode3	Туре	Explair	n				
1044/0012		Square/Lot	Currer					
STATUS/PURPOS	E/USE DATA							
Resource Type: Bui	lding		Stat	us Curre	ent: Extant			
	toric		Qua	ality:				
Purpose: Rov	vhouse		Con	dition:	Good			
Function/Use		Start S	Source	Stop	Sou	roo	Explain	
Residential (Single-I	Family)		Permit	Зюр	300	ice	Historic/Current	
g.c .	y,							
CONSTRUCTION I	DATA							
Construction Event	Sta	rt Sou	rce	Stop	Source		Cost Source	
Orig Construction	190	7 Peri					1500 Permit	
Construction Event		Association			Associat	ed Nan	ma	
Orig Construction		Architect			Beers, A			
Orig Construction		Builder			Wardma		ry	
Orig Construction		Owner			Wardma		-	
Construction Notes:								
One of twelve rowho	ouses construct	ed from the	same pern	nit (#26	90).			
					<u> </u>			_
PEOPLE/EVENTS	DATA							
Racial Segregation St	tatus:							
SETTING/SHAPE/	SIZE DATA							
Surroundings:	Urban		С	ross Re	ference Notes:			
Streetscape:	Intact							
Relate to Othr Bldgs:	Row (1 of 12)							
Relate to Street:	Face on Setba							
Massing:	Row Building/	Front Porch						
Footprint:	Rectangular							
Number Stories:	2							
Bays Wide:	3							
Height:			Outbuildin	ng Type		C	ontributing Status	
Width:	20							
Depth/Length: SqFt:	30							
Volume:								
Lot Width								
Lot Depth/Length:			Outbuildin	ng Notes	:			
Lot SqFt:				<u> </u>				
Acreage:								
Has Driveway:								

WINDOW/DOOR/II Window Location Facade Door Location Main Door Notable Interior Plan(Aperture Shape Rectangular Aperture Shape Rectangular	Type Dbl-Hung Type Single	Ligh 1/1 Pam Notable Interior Fea	nels	Material Wood Material Unknown
Window Location Facade Door Location	Aperture Shape Rectangular Aperture Shape	Dbl-Hung Type	1/1		Wood Material
Window Location Facade	Aperture Shape Rectangular	Dbl-Hung	1/1		Wood
Window Location	Aperture Shape			ts	
		Type	1 *1.	to.	Motorial
Materials Notes:					
Walls	Brick				
Structure Component Foundation	Material Concrete	Feature		Source	
		Factors		Ca	
Wall Component Facade	Material Brick	Color	Treatment Flemish Bond	Source	
Sloped	Not Visible	0-1		0	
Roof Component	Material Not Visible	Color	Treatment Not Visible	Source	
EXTERIOR MATER	RIALS DATA				
Component	Featu	re			
NOTABLE FEATU	RES DATA				
approximately ten fe The grassy front yar	et from the concrete si d is landscaped with m An alley is located nor	dewalk. The dwelling ature trees and shrub	is adjacent to 1336 and s, and is bounded alor	d 1340 Pennsylva	ania Avenue, S.E.
Site Notes: February 2008: This	two-story rowhouse is	located on the northe	east side of Pennsylvan	ia Avenue, S.E.	and is set back
	ortheast) elevation was	not surveyed or prior	Saprica by the volun	toor ourveyor.	
a solid concrete fou dwelling and is enha molding. The northy window openings of arches with keyston pier foundation that Tuscan wood colum	whouses constructed from the fraction. The façade (so the façade vestern bay of the first so the façade hold 1/1, does. A one-story, two-bais infilled with wood larges.	buthwest elevation) is by a projecting molde story holds a single-le ouble-hung, wood-say y porch shelters the pttice. The roof of the ptters encircle the porc	faced with Flemish-bo ed metal cornice with be eaf door and a one-ligh sh windows and have o orimary entrance and co porch has overhanging h, which is accessed b	nd brick. A sloping ackets featuring trectangular wo concrete sills an entral bay and is eaves and is supy wood steps in	ing roof caps the g anthemion od transom. All d concrete jack s set on a brick apported by
February 2008: Cons	structed in 1907 by Hari				
Exterior & Architectur	al Notes:				
oololliai kovivai			_		
Architectural Style(s) Colonial Revival					

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC:

Zoning: Designation Event(s)

Contributing:

Survey(s)	Level(s) of Investigation
Capitol Hill Southeast Phase I (2009/2010)	Permit Research
	Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\

File: 1338_PAAVESE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

03/07/1907 2690 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1044-0012 Page 3

ID Number: 1044-0011

ID Number: 1044	-0011	Year Built:	1907	Data So	ource: Permit		
Number Extended	Street			Quad Typ	e of Address		
1340	Pennsylvania A	venue		SE Cu	rrent		
Name(s)			Туре	of Name			
Rowhouse, 1340 Per	nnsylvania Avenu	e, S.E.	Comn	non			
TaxCode1 TaxCode	2 TaxCode3 T	/ре	Expla	in			
1044/0011	S	quare/Lot	Curre	ent			
STATUS/PURPOS							
Resource Type: Buil Desig. Status: Hist	lding toric			atus Current: ality:	Extant		
_	vhouse			anty. ndition:	Good		
		_					
Function/Use Residential (Single-F			Source Permit	Stop	Source	Explain Historic/Current	
Nesidential (Single-I	anny) is	,0,	Cillin			mstoric/current	
CONSTRUCTION I	DATA						
Construction Event	Start	Soul	rce	Stop	Source	Cost Source	
Orig Construction	1907	Perr	nit	·		1500 Permit	
Construction Event	А	ssociation			Associated Na	me	
Orig Construction	Α	chitect			Beers, A. H.		
Orig Construction	В	uilder			Wardman, Ha	rry	
Orig Construction	0	wner			Wardman, Ha	rry	
Construction Notes: One of twelve rowho	ouses constructe	d from the	same per	mit (#2690).			
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		(Cross Refere	ence Notes:		
Streetscape:	Intact						
Relate to Othr Bldgs:	` '						
Relate to Street: Massing:	Face on Setbac Row Building/F						
Footprint:	Rectangular	OIIL FOICII					
Number Stories:							
Bays Wide:	2 3		L				
Height:	ŭ		Outbuildi	ng Type	C	Contributing Status	
Width:	20			3 71		<u> </u>	-
Depth/Length:	30						
SqFt:							
Volume:							
Lot Width			O. 45 - 31 11	mm Nates			
Lot Depth/Length: Lot SqFt:			Outbuildi	ng Notes:]
Acreage:							
Has Driveway:							
ao Diivovay.]

STYLE/EXTERIOR I Architectural Style(s)					
Colonial Revival			_		
Exterior & Architectural	Notes:				
February 2008: Const of twelve similar rowh a solid concrete found dwelling and is enharmolding. The northwestransom. All window whave concrete sills are and central bay and is overhanging eaves are accessed by wood step the volunteer surveysite Notes: February 2008: This trapproximately ten fee	ructed in 1907 by Har nouses constructed frouses constructed frouses constructed frouses. The façade (so need along the façade estern bay of the first openings on the façade do concrete jack arches set on a brick pier for dis supported by Tueps in the northweste eyor.	ry Wardman, this two- rom the same permit (a) buthwest elevation) is by a projecting molde story holds a single-le de hold 1/1, double-hu es with keystones. A o bundation that is infille scan wood columns. S rn end bay. The rear (r	#2690). The dwelling is faced with Flemish-board metal cornice with leaf door with lights and ne-story, two-bay porced with wood lattice. To Square wood balusters northeast) elevation wast side of Pennsylval is adjacent to 1338 an	s constructed of ond brick. A slo brackets featurid a one-light reason with false 9/9 ch shelters the he roof of the pas not surveyed as not surveyed hia Avenue, S.Ed 1342 Pennsyl	f brick and is set or ping roof caps the ng anthemion ctangular wood vinyl muntins and primary entrance orch has orch, which is I or photographed
NOTABI F FFATUR	ES DATA				
_	ES DATA Featu	ıre			
NOTABLE FEATUR Component EXTERIOR MATERI Roof Component	Featu	ure Color	Treatment	Source	
Component EXTERIOR MATERI	Featu		Treatment Not Visible	Source	
Component EXTERIOR MATERI Roof Component	Featu ALS DATA Material			Source Source	
Component EXTERIOR MATERI Roof Component Sloped	Featu ALS DATA Material Not Visible	Color	Not Visible		
EXTERIOR MATERI Roof Component Sloped Wall Component	Featu ALS DATA Material Not Visible Material	Color	Not Visible Treatment		
EXTERIOR MATERI Roof Component Sloped Wall Component Facade	Featu ALS DATA Material Not Visible Material Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component	Featu ALS DATA Material Not Visible Material Brick Material	Color	Not Visible Treatment	Source	
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Material Not Visible Material Brick Material Concrete Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick	Color	Not Visible Treatment	Source	Material
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond	Source	Material Vinyl
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond Light	Source	

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC:

Interior Notes:

Zoning: Contributing: Designation Event(s)

Survey(s)	Level(s) of Investigation
-----------	---------------------------

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\

1340_PAAVESE.JPG File:

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Frame(s) Date Photographer Roll Caption

MISCELLANEOUS NOTES DATA

Notes:			

PERMIT DATA

Permit Issue Date Number Type Remarks

03/07/1907 2690 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1044-0011 Page 3

ID Number: 1044-0010

ID Number: 1044	-0010	Year Built:	1907	Data	Source:	Permit		
Number Extended	Street			Quad T	ype of Addr	ess		
1342	Pennsylvania A	Avenue			urrent			
Name(s)			Type of	Name				
Rowhouse, 1342 Per	nnsylvania Aveni	ıe, S.E.	Commo					
TaxCode1 TaxCode	2 TaxCode3 T	ype	Explain	1				
1044/0010		quare/Lot	Curren					
STATUS/PURPOS	E/USE DATA							
Resource Type: Buil	lding		Statu	us Currer	nt: Extant			
Desig. Status: Hist	toric		Qual	lity:				
Purpose: Rov	vhouse		Cond	dition:	Fair			
Function/Use	ç	Start S	ource	Stop	Sc	ource	Explain	
Residential (Single-F			ermit	Стор		74.00	Historic/Current	
` •	•							
CONSTRUCTION I	DATA							
Construction Event	Start	Sour	ce S	Stop	Source		Cost Source	
Orig Construction	1907	Perm	nit	-			1500 Permit	
Construction Event	А	ssociation			Assoc	ated Nar	me	
Orig Construction		rchitect			Beers			
Orig Construction	В	uilder				nan, Har	ry	
Orig Construction	O	wner			Wardr	nan, Har	ry	
Construction Notes:								
One of twelve rowho	uses constructe	d from the s	ame perm	nit (#2690	0).			
PEOPLE/EVENTS	DATA							
Racial Segregation St	atus:							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban		Cr	ross Refe	erence Note	s:		
Streetscape:	Intact							
Relate to Othr Bldgs:								
Relate to Street: Massing:	Face on Setbac Row Building/F							
Footprint:	Rectangular	IOIIL FOICII						
Number Stories:	2							
Bays Wide: Height:	3		Outbuilding	a Type		C	ontributing Status	
Width:	20	-	Carbanani	giypo			Online Citates	
Depth/Length:	30							
SqFt:								
Volume:								
Lot Width								
Lot Depth/Length:		Г	Outbuilding	g Notes:				
Lot SqFt:								
Acreage:								
Has Driveway:								

Architectural Style(s)					
Colonial Revival					
Exterior & Architectural	Notes:				
of twelve similar rowh a solid concrete found sloping roof caps the featuring anthemion r rectangular wood trar concrete sills and cor first story are sheltere is set on a brick pier f supported by square	nouses constructed from the façade (so dwelling and is enha molding. The northwen som. All window open crete jack arches with by metal awnings. Foundation that is infibrick posts. Metal bal	ry Wardman, this two- rom the same permit (# buthwest elevation) is need along the façade estern bay of the first senings on the façade he he keystones. The seco A one-story, two-bay pelled with a metal grille. Justers encircle the pole of elevation was not sur	£2690). The dwelling is faced with Flemish-bo by a projecting molde tory holds a single-lead old 1/1, double-hung, and story windows and orch shelters the prim The roof of the porch, which is accessed.	constructed of and brick that had define the cornice of wood door an vinyl-sash wind I the southeaste ary entrance an has overhangi d by poured cor	f brick and is set on as been painted. A set with brackets in a one-light lows and have ern window of the not central bay and ng eaves and is no rete steps in the
approximately ten fee	t from the concrete si	located on the northe idewalk. The dwelling southwestern edge by	is adjacent to 1340 and	d 1344 Pennsylv	vania Avenue, S.E.
NOTABLE FEATUR Component	ES DATA Featu	ıre			
_	Featu	ure Color	Treatment	Source	
Component EXTERIOR MATERI	Featu		Treatment Not Visible	Source	
Component EXTERIOR MATERI Roof Component	Featu ALS DATA Material			Source Source	
Component EXTERIOR MATERI Roof Component Sloped	Featu ALS DATA Material Not Visible	Color	Not Visible		
EXTERIOR MATERI Roof Component Sloped Wall Component	Featu ALS DATA Material Not Visible Material	Color	Not Visible Treatment		
EXTERIOR MATERI Roof Component Sloped Wall Component Facade	Featu ALS DATA Material Not Visible Material Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component	ALS DATA Material Not Visible Material Brick Material	Color	Not Visible Treatment	Source	
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	ALS DATA Material Not Visible Material Brick Material Concrete Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	ALS DATA Material Not Visible Material Brick Material Concrete Brick	Color	Not Visible Treatment	Source	Material
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	ALS DATA Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond	Source	Material Vinyl
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/INT Window Location Facade	ALS DATA Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond Ligh	Source	

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC:

Interior Notes:

Zoning: Designation Event(s)

Contributing:

ID_Number: 1044-0010 Page 2

Survey(s)	Level(s) of Investigation
-----------	---------------------------

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\

1342_PA AVESE.JPG File:

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Frame(s) Date Photographer Roll Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

03/07/1907 2690 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1044-0010 Page 3

ID Number: 1044-0009

ID Number: 1044	-0009	Year Buil	t: 1907	Data	a Source:	Permit		
Number Extended	Street			Quad	Type of Add	ress		
1344	Pennsylvania	Avenue		SE	Current			
Name(s)			Туре	of Name				
Rowhouse, 1344 Per	nnsylvania Ave	nue, S.E.	Curre	nt				
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	ain				
1044/0009		Square/Lot						
STATUS/PURPOS	E/USE DATA							
Resource Type: Buil	lding		Sta	atus Curr	ent: Extant			
•	toric			ıality:				
Purpose: Row	vhouse		Co	ndition:	Fair			
Function/Use		Start	Source	Stop	S	ource	Explain	
Residential (Single-F	amily)	1907	Permit				Historic/Current	
CONSTRUCTION I	DATA							
Construction Event	Sta	art Sc	urce	Stop	Source		Cost Source	
Orig Construction	190	07 Pe	rmit				1500 Permit	
Construction Event		Association			Asso	ciated Na	me	
Orig Construction		Architect				s, A. H.		
Orig Construction		Builder				man, Haı	-	
Orig Construction		Owner			ward	man, Hai	rry	
Construction Notes:								
One of twelve rowho	uses construc	ted from the	e same per	rmit (#26	90).			
PEOPLE/EVENTS	DATA							
Racial Segregation St	atus:							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban			Cross Bo	eference Note	20.		
Streetscape:	Intact		ſ	C1055 IVE	eleterice Note	 		٦
Relate to Othr Bldgs:								
Relate to Street:	Face on Setba	ack Line						
Massing:	Row Building	Front Porc	h					
Footprint:	Rectangular							
Number Stories:	2							
Bays Wide:	3		L					_
Height:			Outbuild	ing Type		С	Contributing Status	_
Width:	20							
Depth/Length: SqFt:	30							
Volume:								
Lot Width								
Lot Depth/Length:			Outbuild	ing Notes	3:			
Lot SqFt:					-			
Acreage:								
Has Driveway:								

STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Colonial Revival					
Exterior & Architectura	al Notes:				
of twelve similar row a solid concrete four dwelling and is enha molding. The northw transom. All window concrete jack arches on a brick pier found Metal balusters encir	rhouses constructed findation. The façade (so inced along the façade restern bay of the first openings on the façade with keystones. A one lation. The roof of the role the porch, which i	ry Wardman, this two- rom the same permit (a outhwest elevation) is by a projecting molder story holds a single-led de hold 1/1, double-hu e-story, two-bay porch porch has overhangin s accessed by wood s ed by the volunteer su	#2690). The dwelling in faced with Flemish-bed metal cornice with eaf paneled door and ang, wood-sash windows shelters the primary greaves and is supposteps in the northwest	s constructed of ond brick. A slop brackets featuring one-light rectains and have corentrance and ceitted by Tuscan w	brick and is set on bing roof caps the ng anthemion ngular wood ncrete sills and ntral bay and is set wood columns.
Site Notes:					
approximately ten fe	et from the concrete s d is bounded along its	located on the northe idewalk. The dwelling southwestern edge by	is adjacent to 1342 ar	nd 1346 Pennsylv	vania Avenue, S.E.
NOTABLE FEATUR	RES DATA				
Component	Feat	ıre			
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Flemish Bond		
Structure Component	Material	Feature		Source	
Foundation Walls	Concrete Brick				
Materials Notes:					
L					
WINDOW/DOOR/IN	ITERIOR DATA				
Window Location	Aperture Shape	Туре	Lig	hts	Material
Facade	Rectangular	Dbl-Hung	1/1		Wood
Door Location	Aperture Shape	Туре	Pa	mels	Material
Main Door	Rectangular	Single	Pa	neled	Unknown
Notable Interior Plan(s	3)		Notable Interior Fe	eature(s)	
Interior Notes:					

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning:

Designation Event(s)

Contributing:

Survey(s)	Level(s) of Investigation

Permit Research Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\

File: 1344_PA AVESE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

03/07/1907 2690 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1044-0009 Page 3

ID Number: 1044-0008

ID Number: 1044	-0008	Year Built:	1907	Data	Source:	Permit		
Number Extended	Street			Quad T	ype of Addr	ess		
1346	Pennsylvania /	Avenue			urrent			
Name(s)			Type of I	Name				
Rowhouse, 1346 Per	nnsylvania Aveni	ue, S.E.	Commo					
TaxCode1 TaxCode 1044/0008		ype quare/Lot	Explain Current					
		40.00/ _01						
STATUS/PURPOS	E/USE DATA							
Resource Type: Buil			Statu	ıs Currer	nt: Extant			
	oric		Quali	ity:				
Purpose: Rov	vhouse		Cond	dition:	Fair			
Function/Use	5	Start So	ource	Stop	Sc	ource	Explain	
Residential (Single-F			ermit	O.Op		, u. 00	Historic/Current	
CONSTRUCTION I	DATA							
Construction Event	Start	Source	ce S	Stop	Source		Cost Source	
Orig Construction	1907	Perm	nit				1500 Permit	
Construction Event	А	ssociation			Assoc	iated Nar	me	
Orig Construction		rchitect			Beers	, A. H.		
Orig Construction	В	uilder				man, Har		
Orig Construction	C	wner			Wardr	nan, Har	rry	
Construction Notes:								
One of twelve rowho	uses constructe	d from the s	ame perm	it (#2690	0).			
PEOPLE/EVENTS	DATA							
Racial Segregation St								
racial ocgregation of	atus.							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban		Cr	oss Refe	erence Note	s:		
Streetscape:	Intact							1
Relate to Othr Bldgs:								
Relate to Street:	Face on Setbac							1
Massing: Footprint:	Row Building/F Rectangular	ront Porch						1
								1
Number Stories: Bays Wide:	2 3							
Height:	3		Outbuilding	a Type		C	ontributing Status	
Width:	20	=		5 - 7 -				
Depth/Length:	30							
SqFt:								
Volume:								
Lot Width								
Lot Depth/Length:		Г	Outbuilding	g Notes:				
Lot SqFt: Acreage:								
Has Driveway:		L						

Architectural Style(s)					
Colonial Revival					
Exterior & Architectur	al Notes:				
of twelve similar rovals solid concrete fou sloping roof caps the featuring anthemion and a one-light rectawindows and have coprimary entrance and supported by met	structed in 1907 by Har whouses constructed from the façade (some description of the factor of the f	rom the same permit (a outhwest elevation) is inced along the façade estern bay of the first s . All window openings erete jack arches with le ton a brick pier found balusters encircle the	#2690). The dwelling faced with Flemish-k by a projecting mole tory holds a single-le on the façade hold 1 teystones. A one-storation. The roof of the porch, which is access.	is constructed of pond brick that he ded metal cornice af paneled wood /1, double-hung, ry, two-bay porche porch has over essed by steps in	f brick and is set or as been painted. A e with brackets d door with lights vinyl-sash n shelters the hanging eaves and
Site Notes:					
approximately ten fe	two-story rowhouse is set from the concrete si ortheast of the dwelling	idewalk. The dwelling			
·	Featu	ure			
EXTERIOR MATE		Color	Treatment	Source	
EXTERIOR MATEI Roof Component Sloped	RIALS DATA		Treatment Not Visible	Source	
EXTERIOR MATEI Roof Component Sloped	RIALS DATA Material			Source Source	
EXTERIOR MATEI	RIALS DATA Material Not Visible	Color	Not Visible		
EXTERIOR MATEI Roof Component Sloped Wall Component	Material Not Visible Material Brick	Color	Not Visible Treatment		
EXTERIOR MATEI Roof Component Sloped Wall Component Facade Structure Component Foundation	Material Not Visible Material Brick Material Concrete	Color	Not Visible Treatment	Source	
EXTERIOR MATEI Roof Component Sloped Wall Component Facade Structure Component	Material Mot Visible Material Brick Material	Color	Not Visible Treatment	Source	
EXTERIOR MATEI Roof Component Sloped Wall Component Facade Structure Component Foundation	Material Not Visible Material Brick Material Concrete	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Material Not Visible Material Brick Material Concrete	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Material Not Visible Material Brick Material Concrete	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Material Not Visible Material Brick Material Concrete Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATEI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick	Color	Not Visible Treatment Flemish Bond	Source	Material
EXTERIOR MATEI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond	Source	Material Vinyl
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/II Window Location	Material Not Visible Material Brick Material Concrete Brick Mterial	Color Color Feature	Not Visible Treatment Flemish Bond	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/II Window Location Facade	Material Not Visible Material Brick Material Concrete Brick MTERIOR DATA Aperture Shape Rectangular	Color Color Feature Type Dbl-Hung	Not Visible Treatment Flemish Bond Light 1/	Source Source	Vinyl

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill
Subdivision: Historic District(s)

Ward/ANC:
Zoning: Designation Event(s)

Contributing:

Interior Notes:

Level(s) of Investigation

Permit Research Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1044\

File: 1346_PA AVESE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

03/07/1907 2690 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1044-0008 Page 3

ID Number: 1044-0007

ID Number: 1044	-0007	Year Built:	1907	Data So	ource: Permit		
Number Extended	Street			Quad Typ	e of Address		
1348	Pennsylvania /	Avenue		SE Cui	rrent		
Name(s)			Type o	of Name			
Rowhouse, 1348 Per	nnsylvania Aven	ıe, S.E.	Comm	non			
TaxCode1 TaxCode	2 TaxCode3 T	уре	Expla	in			
1044/0007	S	quare/Lot	Curre	ent			
STATUS/PURPOS							
Resource Type: Buil	_			tus Current:	Extant		
9	toric vhouse			ality: ndition:	Good		
, aipooo.	viiouse		00	nation.	Coou		
Function/Use			Source	Stop	Source	Explain	
Residential (Single-I	-amily) 1	907 F	ermit			Historic/Current	
CONSTRUCTION	DATA						
Construction Event	Start	Sou	rce	Stop	Source	Cost Source	
Orig Construction	1907	Perr	nit	•		1500 Permit	
Construction Event	А	ssociation			Associated Na	me	
Orig Construction	Α	rchitect			Beers, A. H.		
Orig Construction	В	uilder			Wardman, Ha	rry	
Orig Construction	C	wner			Wardman, Ha	rry	
Construction Notes:							
One of twelve rowho	ouses constructe	d from the	same per	mit (#2690).			
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Refere	ance Notes:		
Streetscape:	Intact		,	JIUSS IXEIEIR	ence Notes.		1
Relate to Othr Bldgs:							
Relate to Street:	Face on Setbac	k Line					
Massing:	Row Building/F	ront Porch					
Footprint:	Rectangular						
Number Stories:	2						
Bays Wide:	3		_				1
Height:			Outbuildi	ng Type	C	Contributing Status	_
Width:	20						
Depth/Length:	30						
SqFt: Volume:							
Lot Width							
Lot Depth/Length:			Outbuildi	ng Notes:			
Lot SqFt:							
Acreage:							
Has Driveway:							

Architectural Style(s)					
Colonial Revival			<u></u>		
Exterior & Architectur	al Notes:				
of twelve similar row a solid concrete fou dwelling and is enh molding. The northw wood transom. All w and concrete jack a is set on a solid fou supported by squar accessed by poured	structed in 1907 by Har whouses constructed f ndation. The façade (s anced along the façade vestern bay of the first window openings on the rches with keystones. A ndation faced with stree be brick posts. A solid be concrete steps with be stographed by the volu	rom the same permit (southwest elevation) is a by a projecting molde story holds a single-leve façade hold 1/1, dou A one-story, one-bay petcher-bond brick. The prick balustrade with purick wing walls in the	#2690). The dwelling is faced with Flemish-book metal cornice with eaf paneled door with ble-hung, vinyl-sash vorch shelters the prim roof of the porch has erforated columns of	s constructed of ond brick. A slop brackets featurin lights and a one vindows and have ary entrance an overhanging ea orick encircles t	i brick and is set on bing roof caps the ng anthemion -light rectangular we concrete sills d central bay and wes and is he porch, which is
Site Notes:					
approximately ten fo	two-story rowhouse is set from the concrete s is bounded along its s	idewalk. The dwelling	is adjacent to 1346 an	d 1350 Pennsylv	vania Avenue, S.E.
NOTABLE FEATU	RES DATA				
_	RES DATA Feati	ure			
NOTABLE FEATU Component EXTERIOR MATE Roof Component Sloped	Featı	ure	Treatment Not Visible	Source	
EXTERIOR MATE Roof Component	Featu RIALS DATA Material			Source	
EXTERIOR MATE Roof Component Sloped	Feati RIALS DATA Material Not Visible	Color	Not Visible		
EXTERIOR MATE Roof Component Sloped Wall Component	Feature RIALS DATA Material Not Visible Material Brick	Color	Not Visible Treatment		
EXTERIOR MATE Roof Component Sloped Wall Component Facade	Feature RIALS DATA Material Not Visible Material Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATE Roof Component Sloped Wall Component Facade Structure Component	RIALS DATA Material Not Visible Material Brick Material	Color	Not Visible Treatment	Source	
EXTERIOR MATE Roof Component Sloped Wall Component Facade Structure Component Foundation	Feature RIALS DATA Material Not Visible Material Brick Material Concrete	Color	Not Visible Treatment	Source	
EXTERIOR MATE Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Feature RIALS DATA Material Not Visible Material Brick Material Concrete	Color	Not Visible Treatment	Source	
EXTERIOR MATE Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	RIALS DATA Material Not Visible Material Brick Material Concrete Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATE Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	RIALS DATA Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond	Source	Material
EXTERIOR MATE Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	RIALS DATA Material Not Visible Material Brick Material Concrete Brick	Color	Not Visible Treatment	Source	Material Vinyl
EXTERIOR MATE Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	RIALS DATA Material Not Visible Material Brick Material Concrete Brick	Color Color Feature	Not Visible Treatment Flemish Bond Lig	Source	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Historic District(s)

Subdivision: Ward/ANC:

Designation Event(s)

Zoning: Contributing:

Survey(s)	Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G

St\Database\Pictures\Square 1044\

File: 1348_PA AVESE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

03/07/1907 2690 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1044-0007 Page 3

Resource All Data Report

ID Number: 1044-0006

ID_Number: 1044-0006 Page 1

BASICS DATA

ID Numbe	r: 1044-	0006	Year Built:	1907	Da	ta Source:	Permit
Number	Extended	Street			Qua	d Type of Ad	ldress
1350a	-1350b	Pennsylvani	a Avenue		SE	Current	
1350		Pennsylvani	a Avenue		SE	Original	
Name(s)				Type of	Name)	
Rowhous	e, 1350 Pen	nsylvania Av	enue, S.E.	Commo	n		
TaxCode1	TaxCode2	2 TaxCode3	Туре	Explain			
1044/0006	3		Square/Lot	Curren	t		

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: **Historic** Quality: Purpose: **Rowhouse** Condition:

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1907 Permit Original

Retail (Beauty Salon) Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1907	Permit			1500 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Arch	itect		Beers, A. H	l
Orig Construction	Build	ler		Wardman,	Harry
Orig Construction	Own	er		Wardman,	Harry
Construction Notes:					
One of twelve rowhouses	constructed fr	om the same	permit (#269	00).	

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings:	Urban	Cross Ref	erence Notes:		
Streetscape:	Intact				1
Relate to Othr Bldgs:	Row (1 of 12)				
Relate to Street:	Face on Setback Line				
Massing:	Row Bldg Flat-Fronted				
Footprint:	Rectangular				
Number Stories:	2 plus basement				
Bays Wide:	3				
Height:		Outbuilding Type	Cor	ntributing Status	_
Width:	20				
Depth/Length:	30				
SqFt:					
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes:			1
Lot SqFt:					
Acreage:					
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s) Colonial Revival			-		
	-I Ni-t				
Exterior & Architectura	al Notes: structed in 1907 by Harry W				
single-leaf paneled	s with keystones. The first door with lights and a 1/1, o çade. The rear (northeast)	double-hung, vinyl-s	sash window. The ori	ginal one-story porch has	been
Site Notes:					
approximately ten fe	two-story rowhouse is loc set from the concrete sidew t the rear of the property.				
NOTABLE FEATU	RES DATA				
Component	Feature				
Component	1 Gataro				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		=
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Flemish Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA

	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single	Paneled	Unkown w/Lights
Main Door	Rectangular	Single		Unknown
Notable Interior Plan	n(s)		Notable Interior Feature(s)	
Interior Notes:				
PLAN/SURVEY/D	ESIGNATION DATA			
Neighborhood: (Subdivision: Ward/ANC:	Capitol Hill		Historic District(s)	
Zoning: Contributing:			Designation Event(s)	
Survey(s)			Level(s) of Investigation	
Capitol Hill Southe	ast Phase I (2009/2010)		Permit Research	
			Volunteer Reconnaissance S	Survey
PHOTOS - DIGITI	ZED			
Caption:	CHRS\Documents\CHRS S\SE Phase I - D to G			
Databases St\Databas	se\Pictures\Square 1044\ \VESE.JPG Photog: R:	Fr:		
Databases St\Databas File: 1350_PA A Date:: Code::	se\Pictures\Square 1044\ \VESE.JPG Photog:	Fr:		
Databases St\Databas File: 1350_PA A Date:: Code::	se\Pictures\Square 1044\ \VESE.JPG Photog: R:	Fr: Date		ption
Databases St\Database File: 1350_PA A Date:: Code:: PHOTOS - B/W O	se\Pictures\Square 1044\ AVESE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)			ption
Databases St\Database File: 1350_PA A Date:: Code:: PHOTOS - B/W O Photo Code MISCELLANEOU	se\Pictures\Square 1044\ AVESE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)			ption
Databases St\Database File: 1350_PA A Date:: Code:: PHOTOS - B/W O Photo Code	se\Pictures\Square 1044\ AVESE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)			ption
Databases St\Database File: 1350_PA A Date:: Code:: PHOTOS - B/W O Photo Code MISCELLANEOU	se\Pictures\Square 1044\ AVESE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)			ption
Databases St\Databases St\Databases File: 1350_PA A Date:: Code:: PHOTOS - B/W O Photo Code MISCELLANEOU Notes: PERMIT DATA Permit Issue Date	Photog: R: RNON-DIGITIZED Roll Frame(s) S NOTES DATA Number Type	Date		ption
Databases St\Databases St\Databases File: 1350_PA A Date:: Code:: PHOTOS - B/W O Photo Code MISCELLANEOU Notes: PERMIT DATA	se\Pictures\Square 1044\ AVESE.JPG Photog: R: PR NON-DIGITIZED Roll Frame(s) S NOTES DATA	Date	Photographer Ca	ption
Databases St\Databases St\Databases File: 1350_PA A Date:: Code:: PHOTOS - B/W O Photo Code MISCELLANEOU Notes: PERMIT DATA Permit Issue Date	Photog: R: RNON-DIGITIZED Roll Frame(s) S NOTES DATA Number Type	Date	Photographer Ca	ption

BIBLIOGRAPHIC DATA

SIGNIFIC	CANCE DATA			
Study Unit		<u> </u>		
Code	Criteria			
DATA DE	DOCESSING EVENTS DATA			

ID_Number: 1044-0006 Page 4

Resource All Data Report

ID Number: 1044-0005

ID Number: 1044-0005 Page 1

BASICS DATA

Data Source: ID Number: Year Built: 1907 1044-0005 Permit Number Extended Street Quad Type of Address 1352 Pennsylvania Avenue SE Current Name(s) Type of Name Rowhouse, 1352 Pennsylvania Avenue, S.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain 1044/0005 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1907 Permit Original

Residential/Store Site Visit Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source 1500 Permit **Orig Construction** 1907 **Permit** Construction Event Association **Associated Name Orig Construction Architect** Beers, A. H. **Orig Construction** Builder Wardman, Harry **Orig Construction** Owner Wardman, Harry Construction Notes:

One of twelve rowhouses constructed from the same permit (#2690).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings:	Urban	Cross Refe	rence Notes:		
Streetscape:	Intact]
Relate to Othr Bldgs:	Row (1 of 12)				
Relate to Street:	Face on Setback Line				
Massing:	Row Bldg Flat-Fronted				
Footprint:	Rectangular				
Number Stories:	2 plus basement				
Bays Wide:	3				1
Height:		Outbuilding Type	Con	tributing Status	
Width:	20				=
Depth/Length:	30				
SqFt:					
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes:			7
Lot SqFt:					
Acreage:					
Has Driveway:					
					,
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Colonial Revival					
	al Natas.				
Exterior & Architectur	ar Notes. structed in 1907 by Harry W	Jandonan thia too ata	thuse her Coloui	al Davissal atola nacolacoa	- !
window openings or arches with keyston sided, rectangular b paired one-light fixe	angular wood transom. Poun the façade hold 1/1, doubles. The foundation is piero ay projects from the found d wood windows. The orig	ole-hung, vinyl-sash ved by a single-leaf pa ation and is capped l inal one-story porch	vindows and have co aneled wood door wi by a flat roof. The wo has been removed fr	oncrete sills and concrete th lights. Additionally, a to od-frame bay is fenestrate	e jack three-
,	n was not surveyed or phot	tographed by the voil	unteer surveyor.		
Site Notes:					
approximately ten fe	two-story rowhouse is loc- eet from the concrete sidew t the rear of the property.				
NOTABLE FEATU	RES DATA				
Component	Feature				
EXTERIOR MATER	DIALS DATA				
EXTERIOR MATER	-				
Roof Component	Material	Color	Treatment	Source	-
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Flemish Bond		_
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				
Materials Notes:					

Window Location	Aperture Shape	Type	Lights	Material
Bay Windows	Rectangular	Fixed	1	Wood
acade	Rectangular	Dbl-Hung	1/1	Vinyl
oor Location	Aportura Chana	Tuno	Pamels	Material
	Aperture Shape	Type		Wood/Glass
Basement Main Door	Rectangular Rectangular	Single Single	Paneled Paneled	Wood/Glass Wood/Glass
nain booi	Rectaligular	Siligle	Faileleu	WOOU/Glass
Notable Interior Plan	(s)		Notable Interior Feature(s)	
nterior Notes:				
PLAN/SURVEY/DI	ESIGNATION DATA			
Neighborhood: C	apitol Hill		Historic District(s)	
Subdivision:				
Vard/ANC:				
Zoning:			Designation Event(s)	
Contributing:				
Survey(s)			Level(s) of Investigation	
	ast Phase I (2009/2010)		Permit Research	
apitoi riii Soutilea	15t Filase I (2009/2010)		Volunteer Reconnaissance Sur	vev
				•
PHOTOS - DIGITIZ	ZED			
Caption:				
		I		
Path: C:\Users\C Databases\ St\Databas	HRS\Documents\CHRS \SE Phase I - D to G e\Pictures\Square 1044\			
Path: C:\Users\C Databases\ St\Databas	SE Phase I - D to G e\Pictures\Square 1044\ VESE.JPG			
Path: C:\Users\C Databases\ St\Databas File: 1352_PA A'	SE Phase I - D to G e\Pictures\Square 1044\ VESE.JPG Photog:			
Path: C:\Users\C Databases\ St\Databas File: 1352_PA A'	SE Phase I - D to G e\Pictures\Square 1044\ VESE.JPG	Fr:		
Path: C:\Users\C Databases\ St\Databas File: 1352_PA A' Date::	SE Phase I - D to G e\Pictures\Square 1044\ VESE.JPG Photog: R:	Fr:		
Path: C:\Users\C Databases\ St\Databas File: 1352_PA A' Date:: Code::	SE Phase I - D to G e\Pictures\Square 1044\ VESE.JPG Photog:	Fr: Date	Photographer Capti	on
Path: C:\Users\C Databases\ St\Databas File: 1352_PA A' Date::	SE Phase I - D to G e\Pictures\Square 1044\ VESE.JPG Photog: R:		Photographer Capti	ion
Path: C:\Users\C Databases\ St\Databas St\Databas 1352_PA A' Date:: Code:: PHOTOS - B/W OI Photo Code	SE Phase I - D to G e\Pictures\Square 1044\ VESE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer Capti	on
Path: C:\Users\C Databases\St\Databases\Tile: 1352_PA A' Date:: Code:: PHOTOS - B/W OI Photo Code	SE Phase I - D to G e\Pictures\Square 1044\ VESE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer Capti	ion
Path: C:\Users\C Databases\ St\Databas File: 1352_PA A' Date:: Code:: PHOTOS - B/W OI	SE Phase I - D to G e\Pictures\Square 1044\ VESE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer Capti	on
Path: C:\Users\C Databases\St\Databases\Tile: 1352_PA A' Date:: Code:: PHOTOS - B/W OI Photo Code	SE Phase I - D to G e\Pictures\Square 1044\ VESE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer Capti	ion
Path: C:\Users\C Databases\St\Databases\St\Databases\Code:: 1352_PA A' Date:: Code:: PHOTOS - B/W OR Photo Code	SE Phase I - D to G e\Pictures\Square 1044\ VESE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer Capti	on
Path: C:\Users\C Databases\St\Databases\Tile: 1352_PA A' Date:: Code:: PHOTOS - B/W OI Photo Code	SE Phase I - D to G e\Pictures\Square 1044\ VESE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer Capti	ion
Path: C:\Users\C Databases\St\Databases\St\Databases\Sile: 1352_PA A' Date:: Code:: PHOTOS - B/W OR Photo Code MISCELLANEOUS Rotes:	RE Phase I - D to G e\Pictures\Square 1044\ VESE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)			ion

BIBLIOG	RAPHIC DATA		
SIGNIFIC	CANCE DATA		
Study Unit			
Code	Criteria		
DATA PF	ROCESSING EVENTS DATA		

ID_Number: 1044-0005 Page 4

Resource All Data Report

ID Number: 1044-0004

ID_Number: 1044-0004 Page 1

BASICS DATA

ID Number: Year Built: 1907 Data Source: 1044-0004 **Permit** Quad Type of Address Number Extended Street 1354 Pennsylvania Avenue SE Current Name(s) Type of Name Rowhouse, 1354 Pennsylvania Avenue, S.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain 1044/0004 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Boarded up

Function/Use Start Source Stop Source Explain 1907 Residential (Single-Family) Permit Original Residential/Offices Sanborn M Historic Vacant Site Visit Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1907	Permit			1500 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Archi	tect		Beers, A. H	l
Orig Construction	Build	er		Wardman,	Harry
Orig Construction	Owne	er		Wardman,	Harry
Construction Notes:					
One of twelve rowhouses co	onstructed fr	om the same	permit (#269	0).	

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

• .					
Streetscape:	Intact				
Relate to Othr Bldgs:	Row End (1 of 12)				
Relate to Street:	Face on Setback Line				
Massing:	Row Bldg Flat-Fronted				
Footprint:	Rectangular				
Number Stories:	2 plus basement				
Bays Wide:	3				
Height:		Outbuilding Type	Co	ntributing Status	
Width:	20				
Depth/Length:	30				
SqFt:					
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes			_
Lot SqFt:					
Acreage:					
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)			_		
Colonial Revival					
Exterior & Architectura	al Notes:				
of twelve similar row a solid concrete four sloping roof caps the featuring anthemion awning, which is acc	structed in 1907 by Harry W houses constructed from ndation. The façade (south e dwelling and is enhanced molding. The northwester cessed by poured concrete have concrete sills and con	the same permit (#: west elevation) is f d along the façade l n bay of the first st e steps. All window	2690). The dwelling is aced with Flemish-bo by a projecting moldo ory is blocked by ply openings on the faça	s constructed of brick and and brick that has been p and metal cornice with bra wood. A metal awning sh ade hold 1/1, double-hung	ainted. A ckets elters this g, vinyl-
of twelve similar row a solid concrete four sloping roof caps the featuring anthemion awning, which is accessab windows and hoeen blocked by ply (northeast) elevation.	whouses constructed from ndation. The façade (south e dwelling and is enhanced molding. The northwester cessed by poured concrete lave concrete sills and con wood. The original one-sto is were not surveyed or ph	the same permit (#. west elevation) is food along the façade n bay of the first sto e steps. All window crete jack arches w ry porch has been otographed by the	2690). The dwelling is aced with Flemish-boy a projecting molder ory is blocked by ply openings on the façaith keystones. The faremoved from the factorium t	s constructed of brick and brick that has been peed metal cornice with brawood. A metal awning shade hold 1/1, double-hung enestration of the foundate ade. The southeast (side	ainted. A ckets elters this g, vinyl- ion has) and rear
of twelve similar row a solid concrete four sloping roof caps the featuring anthemion awning, which is accessab windows and house blocked by ply (northeast) elevation. Site Notes: February 2008: This approximately ten fe	whouses constructed from ndation. The façade (south e dwelling and is enhanced molding. The northwester cessed by poured concrete ave concrete sills and con wood. The original one-sto	the same permit (#. west elevation) is for along the façade in bay of the first stresses. All window crete jack arches work porch has been otographed by the ated on the northwest.	2690). The dwelling is aced with Flemish-body a projecting molder ory is blocked by ply openings on the factifith keystones. The factorist from th	s constructed of brick and brick that has been part of metal cornice with brawood. A metal awning shade hold 1/1, double-hung enestration of the foundation and the southeast (side the southeast (side the southeast).	ainted. A ckets elters this g, vinyl- ion has) and rear
of twelve similar row a solid concrete four sloping roof caps the featuring anthemion awning, which is accessab windows and house blocked by ply (northeast) elevation. Site Notes: February 2008: This approximately ten fe	whouses constructed from ndation. The façade (south e dwelling and is enhanced molding. The northwester cessed by poured concrete lave concrete sills and conwood. The original one-stops were not surveyed or photosteries in the concrete sidewer, S.E. An alley is located in the concrete sidewer.	the same permit (#. west elevation) is for along the façade in bay of the first stresses. All window crete jack arches work porch has been otographed by the ated on the northwest.	2690). The dwelling is aced with Flemish-body a projecting molder ory is blocked by ply openings on the factifith keystones. The factorist from th	s constructed of brick and brick that has been part of metal cornice with brawood. A metal awning shade hold 1/1, double-hung enestration of the foundation and the southeast (side the southeast (side the southeast).	ainted. A ckets elters this g, vinyl- ion has) and rear
of twelve similar row a solid concrete four sloping roof caps the featuring anthemion awning, which is accessab windows and house blocked by ply (northeast) elevation. Site Notes: February 2008: This approximately ten fe Pennsylvania Avenu	whouses constructed from ndation. The façade (south e dwelling and is enhanced molding. The northwester cessed by poured concrete lave concrete sills and conwood. The original one-stops were not surveyed or photosteries in the concrete sidewer, S.E. An alley is located in the concrete sidewer.	the same permit (#. west elevation) is for along the façade in bay of the first stresses. All window crete jack arches work porch has been otographed by the ated on the northwest.	2690). The dwelling is aced with Flemish-body a projecting molder ory is blocked by ply openings on the factifith keystones. The factorist from th	s constructed of brick and brick that has been part of metal cornice with brawood. A metal awning shade hold 1/1, double-hung enestration of the foundation and the southeast (side the southeast (side the southeast).	ainted. A ckets elters this g, vinyl- ion has) and rear
of twelve similar row a solid concrete four sloping roof caps the featuring anthemion awning, which is accessab windows and house blocked by ply (northeast) elevation. Site Notes: February 2008: This approximately ten fe Pennsylvania Avenu	whouses constructed from notation. The façade (south e dwelling and is enhanced molding. The northwester cessed by poured concrete lave concrete sills and conwood. The original one-stops were not surveyed or photostory rowhouse is located from the concrete sidewer, S.E. An alley is located responsible.	the same permit (#. west elevation) is for along the façade in bay of the first stresses. All window crete jack arches work porch has been otographed by the ated on the northwest.	2690). The dwelling is aced with Flemish-body a projecting molder ory is blocked by ply openings on the factifith keystones. The factorist from th	s constructed of brick and brick that has been part of metal cornice with brawood. A metal awning shade hold 1/1, double-hung enestration of the foundation and the southeast (side the southeast (side the southeast).	ainted. A ckets elters this g, vinyl- ion has) and rear
of twelve similar row a solid concrete four sloping roof caps the featuring anthemion awning, which is accessab windows and house blocked by ply (northeast) elevation. Site Notes: February 2008: This approximately ten fe Pennsylvania Avenu	whouses constructed from notation. The façade (south e dwelling and is enhanced molding. The northwester cessed by poured concrete lave concrete sills and conwood. The original one-stop were not surveyed or photomorphic two-story rowhouse is located from the concrete sidewing e, S.E. An alley is located from the concrete sidewing the surveyed or photomorphic two-story rowhouse is located from the concrete sidewing the surveyed or photomorphic from	the same permit (#. west elevation) is for along the façade in bay of the first stresses. All window crete jack arches work porch has been otographed by the ated on the northwest.	2690). The dwelling is aced with Flemish-body a projecting molder ory is blocked by ply openings on the factifith keystones. The factorist from th	s constructed of brick and brick that has been part of metal cornice with brawood. A metal awning shade hold 1/1, double-hung enestration of the foundation and the southeast (side the southeast (side the southeast).	ainted. A ckets elters this g, vinyl- ion has) and rear
of twelve similar row a solid concrete four sloping roof caps the featuring anthemion awning, which is accessab windows and house blocked by ply (northeast) elevation. Site Notes: February 2008: This approximately ten fe Pennsylvania Avenu. NOTABLE FEATULE Component	whouses constructed from notation. The façade (south e dwelling and is enhanced molding. The northwester cessed by poured concrete lave concrete sills and conwood. The original one-stop were not surveyed or photomorphic two-story rowhouse is located from the concrete sidewing e, S.E. An alley is located from the concrete sidewing the surveyed or photomorphic two-story rowhouse is located from the concrete sidewing the surveyed or photomorphic from	the same permit (#. west elevation) is for along the façade in bay of the first stresses. All window crete jack arches work porch has been otographed by the ated on the northwest.	2690). The dwelling is aced with Flemish-body a projecting molder ory is blocked by ply openings on the factifith keystones. The factorist from th	s constructed of brick and brick that has been part of metal cornice with brawood. A metal awning shade hold 1/1, double-hung enestration of the foundation and the southeast (side the southeast (side the southeast).	ainted. A ckets elters this g, vinyl- ion has) and rear
of twelve similar row a solid concrete four sloping roof caps the featuring anthemion awning, which is accessab windows and house blocked by ply (northeast) elevation. Site Notes: February 2008: This approximately ten fe Pennsylvania Avenu. NOTABLE FEATUR Component	whouses constructed from notation. The façade (south e dwelling and is enhanced molding. The northwester cessed by poured concrete lave concrete sills and conwood. The original one-stops were not surveyed or photosteristics were not surveyed or photosteristics. An alley is located respectively. An alley is located respectively. Feature	the same permit (#. west elevation) is fid along the façade in bay of the first stresteps. All window crete jack arches wary porch has been otographed by the ated on the northead valk. The northwest northeast of the pro-	2690). The dwelling is aced with Flemish-boy a projecting moldory is blocked by ply openings on the façavith keystones. The faremoved from the fact volunteer surveyor. The st side of Pennsylva (side) elevation of the perty.	s constructed of brick and brick that has been ped metal cornice with brawood. A metal awning shade hold 1/1, double-hung enestration of the foundate ade. The southeast (side hia Avenue, S.E. and is see dwelling is adjacent to	ainted. A ckets elters this g, vinyl- ion has) and rear
of twelve similar row a solid concrete four sloping roof caps the featuring anthemion awning, which is accessab windows and heen blocked by ply (northeast) elevation Site Notes: February 2008: This approximately ten fe Pennsylvania Avenu NOTABLE FEATULE Component EXTERIOR MATER	whouses constructed from notation. The façade (south e dwelling and is enhanced molding. The northwester cessed by poured concrete lave concrete sills and conwood. The original one-stops were not surveyed or photosteristics and converted in the concrete sidew e, S.E. An alley is located in the concrete sidew e, S.E. An alley is located in the concrete sidew e, S.E. An alley is located in the concrete sidew e, S.E. An alley is located in the concrete sidew e, S.E. An alley is located in the concrete sidew. RIALS DATA Material	the same permit (#. west elevation) is fi d along the façade i n bay of the first stresteps. All window crete jack arches w ry porch has been otographed by the ated on the northea ralk. The northwest northeast of the pro	2690). The dwelling is aced with Flemish-boy a projecting moldory is blocked by ply openings on the façarith keystones. The fremoved from the fact volunteer surveyor. Set side of Pennsylva (side) elevation of the perty.	s constructed of brick and brick that has been ped metal cornice with brawood. A metal awning shade hold 1/1, double-hung enestration of the foundate ade. The southeast (side hia Avenue, S.E. and is see dwelling is adjacent to	ainted. A ckets elters this g, vinyl- ion has) and rear
of twelve similar row a solid concrete four sloping roof caps the featuring anthemion awning, which is accessab windows and heen blocked by ply (northeast) elevation Site Notes: February 2008: This approximately ten fe Pennsylvania Avenu NOTABLE FEATUL Component EXTERIOR MATER Roof Component Sloped	whouses constructed from notation. The façade (south e dwelling and is enhanced molding. The northwester cessed by poured concrete lave concrete sills and conwood. The original one-stops were not surveyed or photosteristics and converted in the concrete sidew of t	the same permit (#. west elevation) is fid along the façade in bay of the first stresteps. All window crete jack arches wary porch has been otographed by the ated on the northead valk. The northwest northeast of the pro-	2690). The dwelling is aced with Flemish-boy a projecting moldory is blocked by ply openings on the façavith keystones. The feremoved from the fact volunteer surveyor. It side of Pennsylva (side) elevation of the perty. Treatment Not Visible	s constructed of brick and brick that has been ped metal cornice with brawood. A metal awning shade hold 1/1, double-hung enestration of the foundate ade. The southeast (side hia Avenue, S.E. and is see dwelling is adjacent to	ainted. A ckets elters this g, vinyl- ion has) and rear
of twelve similar row a solid concrete four sloping roof caps the featuring anthemion awning, which is accessab windows and heen blocked by ply (northeast) elevation Site Notes: February 2008: This approximately ten fe Pennsylvania Avenu NOTABLE FEATUL Component EXTERIOR MATER Roof Component Sloped Wall Component Facade	whouses constructed from notation. The façade (south e dwelling and is enhanced molding. The northwester cessed by poured concrete lave concrete sills and conwood. The original one-stops were not surveyed or photosterial in the concrete sidew e, S.E. An alley is located in the concrete sidew e,	the same permit (#. west elevation) is fid along the façade in bay of the first stresteps. All window crete jack arches wiry porch has been otographed by the ated on the northeat ated on the northwest northeast of the pro	2690). The dwelling is aced with Flemish-body a projecting moldory is blocked by ply openings on the façavith keystones. The feremoved from the fact volunteer surveyor. Set side of Pennsylva (side) elevation of the perty. Treatment Not Visible Treatment	s constructed of brick and brick that has been ped metal cornice with brawood. A metal awning shade hold 1/1, double-hung mestration of the foundate ade. The southeast (side hia Avenue, S.E. and is see dwelling is adjacent to	ainted. A ckets elters this g, vinyl- ion has) and rear
of twelve similar row a solid concrete four sloping roof caps the featuring anthemion awning, which is acc sash windows and heen blocked by ply (northeast) elevation Site Notes: February 2008: This approximately ten fe Pennsylvania Avenu NOTABLE FEATUL Component EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component	whouses constructed from notation. The façade (south e dwelling and is enhanced molding. The northwester cessed by poured concrete lave concrete sills and conwood. The original one-sto is were not surveyed or photostory rowhouse is located from the concrete sidewer, S.E. An alley is located from the concrete sidewer, S.E. An all	the same permit (#. west elevation) is fi d along the façade i n bay of the first stresteps. All window crete jack arches w ry porch has been otographed by the ated on the northea ralk. The northwest northeast of the pro	2690). The dwelling is aced with Flemish-body a projecting moldory is blocked by ply openings on the façavith keystones. The feremoved from the fact volunteer surveyor. Set side of Pennsylva (side) elevation of the perty. Treatment Not Visible Treatment	s constructed of brick and brick that has been ped metal cornice with brawood. A metal awning shade hold 1/1, double-hung enestration of the foundate ade. The southeast (side hia Avenue, S.E. and is see dwelling is adjacent to	ainted. A ckets elters this g, vinyl- ion has) and rear
of twelve similar row a solid concrete four sloping roof caps the featuring anthemion awning, which is acc sash windows and heen blocked by ply (northeast) elevation Site Notes: February 2008: This approximately ten fe Pennsylvania Avenu NOTABLE FEATUL Component EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation	whouses constructed from notation. The façade (south e dwelling and is enhanced molding. The northwester cessed by poured concrete lave concrete sills and conwood. The original one-stop wood. The original one-stop were not surveyed or photosterial surveyed or photosteria	the same permit (#. west elevation) is fid along the façade in bay of the first stresteps. All window crete jack arches wiry porch has been otographed by the ated on the northeat ated on the northwest northeast of the pro	2690). The dwelling is aced with Flemish-body a projecting moldory is blocked by ply openings on the façavith keystones. The feremoved from the fact volunteer surveyor. Set side of Pennsylva (side) elevation of the perty. Treatment Not Visible Treatment	s constructed of brick and brick that has been ped metal cornice with brawood. A metal awning shade hold 1/1, double-hung mestration of the foundate ade. The southeast (side hia Avenue, S.E. and is see dwelling is adjacent to	ainted. A ckets elters this g, vinyl- ion has) and rear
of twelve similar row a solid concrete four sloping roof caps the featuring anthemion awning, which is accessab windows and heen blocked by plyy (northeast) elevation Site Notes: February 2008: This approximately ten fe Pennsylvania Avenu NOTABLE FEATULE Component EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	whouses constructed from notation. The façade (south e dwelling and is enhanced molding. The northwester cessed by poured concrete lave concrete sills and conwood. The original one-sto is were not surveyed or photostory rowhouse is located from the concrete sidewer, S.E. An alley is located from the concrete sidewer, S.E. An all	the same permit (#. west elevation) is fid along the façade in bay of the first stresteps. All window crete jack arches wiry porch has been otographed by the ated on the northeat ated on the northwest northeast of the pro	2690). The dwelling is aced with Flemish-body a projecting moldory is blocked by ply openings on the façavith keystones. The feremoved from the fact volunteer surveyor. Set side of Pennsylva (side) elevation of the perty. Treatment Not Visible Treatment	s constructed of brick and brick that has been ped metal cornice with brawood. A metal awning shade hold 1/1, double-hung mestration of the foundate ade. The southeast (side hia Avenue, S.E. and is see dwelling is adjacent to	ainted. A ckets elters this g, vinyl- ion has) and rear
of twelve similar row a solid concrete four sloping roof caps the featuring anthemion awning, which is acc sash windows and heen blocked by ply (northeast) elevation Site Notes: February 2008: This approximately ten fe Pennsylvania Avenu NOTABLE FEATUL Component EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation	whouses constructed from notation. The façade (south e dwelling and is enhanced molding. The northwester cessed by poured concrete lave concrete sills and conwood. The original one-stop wood. The original one-stop were not surveyed or photosterial surveyed or photosteria	the same permit (#. west elevation) is fid along the façade in bay of the first stresteps. All window crete jack arches wiry porch has been otographed by the ated on the northeat ated on the northwest northeast of the pro	2690). The dwelling is aced with Flemish-body a projecting moldory is blocked by ply openings on the façavith keystones. The feremoved from the fact volunteer surveyor. Set side of Pennsylva (side) elevation of the perty. Treatment Not Visible Treatment	s constructed of brick and brick that has been ped metal cornice with brawood. A metal awning shade hold 1/1, double-hung mestration of the foundate ade. The southeast (side hia Avenue, S.E. and is see dwelling is adjacent to	ainted. A ckets elters this g, vinyl- ion has) and rear

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material
acade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single		Boarded Up
Main Door	Rectangular	Single		Boarded Up
Notable Interior Plan	u(s)		Notable Interior Feature(s)	
Interior Notes:				
PLAN/SURVEY/D	ESIGNATION DATA			
Neighborhood: (Subdivision:	Capitol Hill		Historic District(s)	
Ward/ANC: Zoning:			Designation Event(s)	
Contributing: Survey(s)			Level(s) of Investigation	
Capitol Hill Southe	ast Phase I (2009/2010)		Permit Research	
			Volunteer Reconnaissance Survey	1
PHOTOS - DIGITI	ZED			
Caption:	<u>LLU</u>		62	
Databases St\Databas	CHRS\Documents\CHRS \SE Phase I - D to G se\Pictures\Square 1044\ \VESE.JPG			
Date::	Photog: R:	Fr:		
Date:: Code::		Fr:		
Date:: Code:: PHOTOS - B/W O	R:	Fr: Date	Photographer Caption	
Date:: Code:: PHOTOS - B/W O	R: PR NON-DIGITIZED		Photographer Caption	
Date:: Code:: PHOTOS - B/W O Photo Code	R: PR NON-DIGITIZED Roll Frame(s)		Photographer Caption	
Date:: Code::	R: PR NON-DIGITIZED Roll Frame(s)		Photographer Caption	
Date:: Code:: PHOTOS - B/W O Photo Code MISCELLANEOU	R: PR NON-DIGITIZED Roll Frame(s)		Photographer Caption	
Date:: Code:: PHOTOS - B/W O Photo Code MISCELLANEOU	R: PR NON-DIGITIZED Roll Frame(s)		Photographer Caption	
Date:: Code:: PHOTOS - B/W O Photo Code MISCELLANEOU Notes: PERMIT DATA	R: PR NON-DIGITIZED Roll Frame(s)		Photographer Caption Remarks	
Date:: Code:: PHOTOS - B/W O Photo Code MISCELLANEOU Notes:	R: PR NON-DIGITIZED Roll Frame(s) S NOTES DATA			
PHOTOS - B/W O Photo Code MISCELLANEOU Notes: PERMIT DATA Permit Issue Date	R: PR NON-DIGITIZED Roll Frame(s) S NOTES DATA Number Type			

SIGNIFIC	CANCE DATA			
Study Unit		<u> </u>		
Code	Criteria			
DATA DE	DOCESSING EVENTS DATA			

ID_Number: 1044-0004 Page 4

ID_Number: 1044-0004 Page 5