ID Number: 1078-0028

BASICS DATA

ID Number:	1078-0	0028	Year Built:	1912	Da	ta Source:	Permit
Number Exte	ended	Street			Qua	d Type of Add	dress
1533		Pennsylvani	a Avenue		SE	Current	
Name(s)				Type of	Name)	
Rowhouse, 15	33 Peni	nsylvania Ave	enue, S.E.	Commo	n		<u> </u>
Century 21				Current			
TaxCode1 Ta	xCode2	TaxCode3	Туре	Explain			
1078/0028			Square/Lot	Curren	t		

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: **Historic** Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1912 Permit Original

Professional & office Current

Residential (Multi-Family) Historic

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Rear Addition	pre 1928	Site Visit/Maps			
Orig Construction	1912	Permit			2500 Permit
Construction Event	Associa	ation		Associated	Name
Orig Construction	Archite	ect		Boss, Willi	am A.
Orig Construction	Builde	r		Boss, Willi	am A.
Orig Construction	Owner			Boss, Willi	am A.
Construction Notes:					
One of three rowhouses	constructed from	the same per	mit (#6196).	

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

ID_Number: 1078-0028 Page 1

Surroundings:	Urban	C	Cross Refere	nce Notes:		
Streetscape:	Intact					
Relate to Othr Bldgs:	Row End (1 of 3)					
Relate to Street:	Face on Setback Line					
Massing:	Row Building/Flat Front					
Footprint:	Rectangular					
Number Stories:	2 plus basement					
Bays Wide:	3					
Height:		Outbuildir	ng Type	Contri	buting Status	
Width:	16					
Depth/Length:	32					
SqFt:						
Volume: Lot Width						
Lot Depth/Length:		Outbuildir	na Notes:			
Lot SqFt:		Outbuildii	ig Notes.			
Acreage:						
Has Driveway:						
rido Diivoway.						
STYLE/EXTERIOR	DΔTΔ					
Architectural Style(s)	DAIN					
Italianate						
Exterior & Architectura	al Notes:					
with dentil molding. cap. The northweste transom. A concrete façade. Metal steps including the founda (side) elevation of th A two-story, full-wide Sanborn map. Possi a shed roof. Visible to of one-light fixed wo Site Notes: September 2008: Thi approximately ten fe	d. A sloping roof caps the cap An exterior-rear brick chiming and bay of the first story hold lintel highlights the opening with metal balusters provide ation, hold 1/1, double-hung the dwelling is not fenestrate the addition is located on the bly an enclosed sleeping perfenestration consists of single dwindows.	ney rises f ds a single gg. The orig e access to l, metal-sa d. e rear (sou orch, the w ggle, paired	from the sound from the sound from the door of the doo	ath corner of the dwe ded door with lights ar ory, full-width porch opening. All window of and have concrete s vation of the dwelling addition is clad with 6/6, double-hung, wo t side of Pennsylvani ion is adjacent to 153	elling and has a corbeled a one-light rectangular has been removed from openings on the façade sills and lintels. The source of	d brick ar wood the atheast 28 ped by a band et back
NOTABLE FEATUR	DEC DATA					
NOTABLE FEATU						
Component	Feature					
EXTERIOR MATER	RIALS DATA					
Roof Component	Material	Colo	or	Treatment	Source	
Sloped	Not Visible			Not Visible		
Wall Component	Material	Colo	or	Treatment	Source	
Facade	Brick			Flemish Bond		
Structure Component	Material	Featu	ıre		Source	
Foundation	Concrete					

Brick

Walls

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Metal
Door Location	Aperture Shape	Туре	Pamels	Material
Main Door	Rectangular	Single	Paneled	Unkown w/Lights

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision:
Ward/ANC:
Zoning:
Contributing:

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Level(s) of Investigation

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G

St\Database\Pictures\Square 1078\

File: 1533_PA_AVSE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1078\

File: 1533_PA_AVSE-E_side.JPG

Date:: Photog:

Code:: R: Fr:





ID_Number: 1078-0028 Page 3

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1078\

File: 1533_PA_AVSE-rear.JPG

Date:: Photog:

Code:: R: Fr:



Photo Code	Roll	Frame(s)	Date	Photographer	Caption	
MISCELLANEOU	S NOTES	DATA				
Notes:						
PERMIT DATA						
Permit Issue Date		Number Type		Remarks		
06/26/1912		6196 Build				
Permit Notes:						
BIBLIOGRAPHIC	DATA					
SIGNIFICANCE D	ATA					
Study Unit						
Code Crite	eria					

DATA PROCESSING EVENTS DATA

ID Number: 1078-0027

BASICS DATA

ID Number: 1078	3-0027	Year Bu	ilt: 1912	Data	Source: Pern	nit	
Number Extended	Street			Quad -	Type of Address		
1531	Pennsylvania	a Avenue		SE (Current		
Name(s)			Туре	e of Name			
Rowhouse, 1531 Per	nnsylvania Ave	nue, S.E.	Con	nmon		=	
TaxCode1 TaxCode	2 TaxCode3	Type	Exp	olain			
1078/0027		Square/Lo		rent			
STATUS/PURPOS	E/USE DATA						
Resource Type: Buil	lding		S	Status Curre	nt: Extant		
· ·	toric			Quality:			
Purpose: Rov	vhouse		C	Condition:	Good		
Function/Use		Start	Source	Stop	Source	Explain	
Residential (Single-I	Family)	1912	Permit			Historic/Current	
CONSTRUCTION I	DATA						
Construction Event	Sta	art S	Source	Stop	Source	Cost Source	
Orig Construction	19	12 F	ermit			2500 Permit	
Construction Event		Associatio	n		Associated	Name	
Orig Construction		Architect			Boss, Willi	am A.	
Orig Construction		Builder			Boss, Willi		
Orig Construction		Owner			Boss, Willi	am A.	
Construction Notes:							
One of three rowhou	uses construct	ed from the	e same per	rmit (#6196).		
DEODI E/EVENTS	DATA						
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Ref	erence Notes:		
Streetscape:	Intact			01000 1101			
Relate to Othr Bldgs:							
Relate to Street:	Face on Setb	ack Line					
Massing:	Row Building	/Flat Front					
Footprint:	Rectangular						
Number Stories:	2 plus ba	sement					
Bays Wide:	3						
Height:			Outbuil	lding Type		Contributing Status	
Width:	16						
Depth/Length:	32						
SqFt: Volume:							
Lot Width							
Lot Depth/Length:			Outbuil	Iding Notes:			
Lot SqFt:				<u> </u>			
Acreage:							
Has Driveway:							

STYLE/EXTERIOR DATA Architectural Style(s)

Exterior & Architectural Notes:

September 2008: Constructed in 1912 by William A. Boss, this two-story, three-bay Italianate -style single-family rowhouse is one of three similar rowhouses constructed from the same permit (#6196). The dwelling is constructed of brick and is set on a solid, raised concrete foundation; the façade (northeast elevation) is faced with Flemish-bond brick that has been painted. A sloping roof caps the dwelling and is fronted along the façade by a projecting molded cornice with dentil molding. An exterior-rear brick chimney rises from the south corner of the dwelling and has a corbeled brick cap. The northwestern bay of the first story holds a single-leaf paneled wood door and a one-light rectangular wood transom. A concrete lintel highlights the opening. The original one-story, full-width porch has been removed from the façade. Metal steps with metal balusters, set on a brick foundation, provide access to the door opening. All window openings on the façade, including the foundation, hold 6/9, double-hung, wood-sash windows and have concrete sills. The first and second story openings have concrete lintels.

The second story of the rear (southwest) elevation is fenestrated with paired 6/9, double-hung, wood-sash windows, which feature a two-course, rowlock brick segmental arch.

Site Notes:

September 2008: This two-story dwelling is located on the southwest side of Pennsylvania Avenue, S.E. and is set back approximately ten feet from the sidewalk. The dwelling is adjacent to 1529 and 1533 Pennsylvania Avenue, S.E. The small front yard is landscaped with mature shrubs and foundation plantings.

NOTABLE FEATURES DATA Component Feature EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Flemish Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA Window Location Aperture Shape Type Lights Material Facade Rectangular Dbl-Hung 6/9 Wood

Door LocationAperture ShapeTypePamelsMaterialMain DoorRectangularSinglePaneledWood

Notable Interior Plan(s)

Notable Interior Feature(s)

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning:

Interior Notes:

Designation Event(s)

ID_Number: 1078-0027 Page 2

Contrib	uting:							
Survey((s)					Level(s) of Investiga	ation	
Capitol	Capitol Hill Southeast Phase I (2009/2010)					Permit Research		
					Volunteer Reconna	aissance Survey		
DUOT	00 DIGITIZ	ED						
PHOTO	OS - DIGITIZ	EU						
Caption	n:							
Path: File:	Databases\	SE Phase NPictures	s\Square 1078\					
Date::		Photog:	_	_				
Code::			R:	Fr:				
Photo 0	OS - B/W OR	Roll	Frame(s)		Date	Photographer	Caption	
MISCE	ELLANEOUS	NOTES	DATA					
Notes:								
PERM	IT DATA							
Permit	Issue Date		Number Type			Remarks		
06/26/1			6196 Build					
Permit	Notes:							
BIBLIC	OGRAPHIC I	DATA						
SIGNII	FICANCE DA	ATA						
Study L	Jnit				<u> </u>			
Code	Criter	ia						

DATA PROCESSING EVENTS DATA

ID Number: 1078-0026

ID_Number: 1078-0026 Page 1

BASICS DATA

ID Number: 1078-0026 Year Built: 1912 Data Source: Permit Number Extended Street Quad Type of Address 1529 Pennsylvania Avenue SE Current Name(s) Type of Name Rowhouse, 1529 Pennsylvania Avenue, S.E. Common **INOsolut Computer** Current TaxCode1 TaxCode2 TaxCode3 Type Explain 1078/0026 Current Square/Lot

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1912 Permit Original

Office/Residential Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source		
Orig Construction	1912	Permit			2500 Permit		
Construction Event	Association		Associated Name				
Orig Construction	Arch	Architect		Boss, William A.			
Orig Construction	Build	der		Boss, Willia	am A.		
Orig Construction	Own	er		Boss, Willia	am A.		
Construction Notes:							
One of three rowhouses	constructed fro	m the same ne	ermit (#6196	1.			

PEOPLE/EVENTS DATA

Racial Segregation Status:

_						
Streetscape:	Intact					
Relate to Othr Bldgs:	Row (1 of 3)					
Relate to Street:	Face on Setback Line					
Massing:	Row Building/Flat Front					
Footprint:	Rectangular					
Number Stories:	2 plus basement					
Bays Wide:	3					
Height:		Outbuilding Type	Cor	ntributing Status		
Width:	16					
Depth/Length:	32					
SqFt:						
Volume: Lot Width						
Lot Width Lot Depth/Length:		Outbuilding Notes:				
Lot SqFt:		Catbanang 140too.				
Acreage:						
Has Driveway:						
i ias Diiveway.						
STYLE/EXTERIOR	ΠΔΤΔ					
Architectural Style(s)						
Italianate						
unut	al Niataa.					
E (' 0						
September 2008: Co rowhouse is one of to brick and is set on a that has been painte with dentil molding.	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the	onstructed from the s ndation; the façade (dwelling and is fron ne first story holds a	same permit (#6196). northeast elevation) ted along the façade single-leaf paneled v	The dwelling is const is faced with Flemish- by a projecting molde wood door and a one-	ructed of -bond brick ed cornice light	
September 2008: Co rowhouse is one of the brick and is set on a that has been painte with dentil molding. The transport of the faction of the	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel hig cade. Metal steps with met façade are fenestrated with ash windows. All windows	enstructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening al balusters provide (6/6, double-hung, we have concrete sills)	same permit (#6196). northeast elevation) ted along the façade single-leaf paneled v . The original one-st access to the door of rood-sash windows. The first and second	The dwelling is const is faced with Flemish by a projecting molde wood door and a one-lory, full-width porch hopening. The foundation The first story openings have	ructed of -bond brick ed cornice light nas been on and gs hold 1/1,	
September 2008: Co rowhouse is one of the brick and is set on a sthat has been painte with dentil molding. The transpular wood	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel hig cade. Metal steps with metagade are fenestrated with	enstructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening al balusters provide (6/6, double-hung, we have concrete sills)	same permit (#6196). northeast elevation) ted along the façade single-leaf paneled v . The original one-st access to the door of rood-sash windows. The first and second	The dwelling is const is faced with Flemish by a projecting molde wood door and a one-lory, full-width porch hopening. The foundation The first story openings have	ructed of -bond brick ed cornice light nas been on and gs hold 1/1,	
September 2008: Co rowhouse is one of the brick and is set on a second story of the sec	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel higade. Metal steps with met façade are fenestrated with each windows. All windows athwest) elevation was not	enstructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening al balusters provide (6/6, double-hung, we have concrete sills surveyed or photogi	same permit (#6196). northeast elevation) ted along the façade single-leaf paneled v . The original one-st access to the door of cood-sash windows. The first and second	The dwelling is const is faced with Flemish by a projecting molde wood door and a one-lory, full-width porch hopening. The foundation The first story opening have beer surveyor.	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, e concrete	
September 2008: Co rowhouse is one of the brick and is set on a second story of the sec	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel higade. Metal steps with metagade are fenestrated with the ash windows. All windows athwest) elevation was not its two-story dwelling is locally similar to whose the steps.	enstructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening al balusters provide (a 6/6, double-hung, we have concrete sills surveyed or photogonated on the southweated on the southweated the factor of the southweated on the south	same permit (#6196). northeast elevation) ted along the façade single-leaf paneled v . The original one-st access to the door of cood-sash windows. The first and second aphed by the volunte	The dwelling is const is faced with Flemish by a projecting molde wood door and a one-lory, full-width porch hopening. The foundation The first story openings have beer surveyor.	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, concrete	
September 2008: Co rowhouse is one of the brick and is set on a sthat has been painted with dentil molding. The rectangular wood transported from the fasecond story of the stouble-hung, vinyl-slintels. The rear (sout Site Notes:	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel higade. Metal steps with met façade are fenestrated with each windows. All windows athwest) elevation was not	enstructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening al balusters provide (a 6/6, double-hung, we have concrete sills surveyed or photogonated on the southweated on the southweated the factor of the southweated on the south	same permit (#6196). northeast elevation) ted along the façade single-leaf paneled v . The original one-st access to the door of cood-sash windows. The first and second aphed by the volunte	The dwelling is const is faced with Flemish by a projecting molde wood door and a one-lory, full-width porch hopening. The foundation The first story openings have beer surveyor.	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, concrete	
September 2008: Co rowhouse is one of the brick and is set on a that has been painted with dentil molding. The rectangular wood transported from the fasecond story of the fadouble-hung, vinyl-slintels. The rear (sout Site Notes: September 2008: The proving the face of	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel hig cade. Metal steps with met façade are fenestrated with each windows. All windows athwest) elevation was not die two-story dwelling is locet from the sidewalk. The	enstructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening al balusters provide (a 6/6, double-hung, we have concrete sills surveyed or photogonated on the southweated on the southweated the factor of the southweated on the south	same permit (#6196). northeast elevation) ted along the façade single-leaf paneled v . The original one-st access to the door of cood-sash windows. The first and second aphed by the volunte	The dwelling is const is faced with Flemish by a projecting molde wood door and a one-lory, full-width porch hopening. The foundation The first story openings have beer surveyor.	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, concrete	
September 2008: Co rowhouse is one of the brick and is set on a strat has been painted with dentil molding. The rectangular wood transported from the fasecond story of the fase	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel hig cade. Metal steps with met façade are fenestrated with ash windows. All windows athwest) elevation was not is two-story dwelling is located from the sidewalk. The	enstructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening al balusters provide (a 6/6, double-hung, we have concrete sills surveyed or photogonated on the southweated on the southweated the factor of the southweated on the south	same permit (#6196). northeast elevation) ted along the façade single-leaf paneled v . The original one-st access to the door of cood-sash windows. The first and second aphed by the volunte	The dwelling is const is faced with Flemish by a projecting molde wood door and a one-lory, full-width porch hopening. The foundation The first story openings have beer surveyor.	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, concrete	
September 2008: Co rowhouse is one of the brick and is set on a strat has been painted with dentil molding. The rectangular wood transported from the fasecond story of the fase	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel hig cade. Metal steps with met façade are fenestrated with each windows. All windows athwest) elevation was not die two-story dwelling is locet from the sidewalk. The	enstructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening al balusters provide (a 6/6, double-hung, we have concrete sills surveyed or photogonated on the southweated on the southweated the factor of the southweated on the south	same permit (#6196). northeast elevation) ted along the façade single-leaf paneled v . The original one-st access to the door of cood-sash windows. The first and second aphed by the volunte	The dwelling is const is faced with Flemish by a projecting molde wood door and a one-lory, full-width porch hopening. The foundation The first story openings have beer surveyor.	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, concrete	
September 2008: Co rowhouse is one of the brick and is set on a strat has been painted with dentil molding. The rectangular wood transported from the fasecond story of the fase	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel hig cade. Metal steps with met façade are fenestrated with ash windows. All windows athwest) elevation was not is two-story dwelling is located from the sidewalk. The	enstructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening al balusters provide (a 6/6, double-hung, we have concrete sills surveyed or photogonated on the southweated on the southweated the factor of the southweated on the south	same permit (#6196). northeast elevation) ted along the façade single-leaf paneled v . The original one-st access to the door of cood-sash windows. The first and second aphed by the volunte	The dwelling is const is faced with Flemish by a projecting molde wood door and a one-lory, full-width porch hopening. The foundation The first story openings have beer surveyor.	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, concrete	
September 2008: Co rowhouse is one of the brick and is set on a strat has been painted with dentil molding. The rectangular wood transported from the fasecond story of the fase	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel hig cade. Metal steps with metacade are fenestrated with each windows. All windows athwest) elevation was not set from the sidewalk. The RES DATA	enstructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening al balusters provide (a 6/6, double-hung, we have concrete sills surveyed or photogonated on the southweated on the southweated the factor of the southweated on the south	same permit (#6196). northeast elevation) ted along the façade single-leaf paneled v . The original one-st access to the door of cood-sash windows. The first and second aphed by the volunte	The dwelling is const is faced with Flemish by a projecting molde wood door and a one-lory, full-width porch hopening. The foundation The first story openings have beer surveyor.	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, concrete	
September 2008: Co rowhouse is one of a brick and is set on a strat has been painted with dentil molding. The rectangular wood trace removed from the fasecond story of the adouble-hung, vinyl-slintels. The rear (sout Site Notes: September 2008: The approximately five for the fase of the fase of the second story of the fase of t	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel hig cade. Metal steps with met façade are fenestrated with each windows. All windows athwest) elevation was not set from the sidewalk. The RES DATA	enstructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening al balusters provide to 6/6, double-hung, we have concrete sills surveyed or photograted on the southweld dwelling is adjacent	same permit (#6196). northeast elevation) ted along the façade single-leaf paneled v . The original one-st access to the door o cood-sash windows. The first and second aphed by the volunte est side of Pennsylva to 1527 and 1531 Per	The dwelling is const is faced with Flemish-by a projecting molde wood door and a one-ory, full-width porch hopening. The foundation The first story opening story openings have been surveyor. Inia Avenue, S.E. and innsylvania Avenue, S.	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, concrete	
September 2008: Co rowhouse is one of the brick and is set on a strat has been painted with dentil molding. The rectangular wood transported from the fasecond story of the fase	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel his cade. Metal steps with met façade are fenestrated with each windows. All windows athwest) elevation was not set from the sidewalk. The RES DATA RIALS DATA Material	enstructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening al balusters provide (a 6/6, double-hung, we have concrete sills surveyed or photogonated on the southweated on the southweated the factor of the southweated on the south	same permit (#6196). northeast elevation) ted along the façade single-leaf paneled v . The original one-st access to the door o rood-sash windows. The first and second aphed by the volunte est side of Pennsylva to 1527 and 1531 Pe	The dwelling is const is faced with Flemish by a projecting molde wood door and a one-lory, full-width porch hopening. The foundation The first story openings have beer surveyor.	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, concrete	
September 2008: Co rowhouse is one of a brick and is set on a that has been painted with dentil molding. The rectangular wood trace removed from the fasecond story of the adouble-hung, vinyl-slintels. The rear (sout Site Notes: September 2008: The approximately five for the fase of Component EXTERIOR MATERIAL Roof Component Sloped	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel hig cade. Metal steps with metacade are fenestrated with each windows. All windows athwest) elevation was not sis two-story dwelling is located from the sidewalk. The RES DATA RIALS DATA Material Not Visible	constructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening al balusters provide to 6/6, double-hung, we have concrete sills surveyed or photograted on the southwedwelling is adjacent	same permit (#6196). northeast elevation) ted along the façade single-leaf paneled v . The original one-st access to the door of cood-sash windows. The first and second aphed by the volunte est side of Pennsylva to 1527 and 1531 Per Treatment Not Visible	The dwelling is const is faced with Flemish-by a projecting molde wood door and a one-ory, full-width porch hopening. The foundation The first story opening distory openings have ever surveyor. Inia Avenue, S.E. and innsylvania Avenue, S.	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, concrete	
September 2008: Co rowhouse is one of a brick and is set on a sthat has been painted with dentil molding. The rectangular wood trace and second story of the adouble-hung, vinyl-slintels. The rear (sout Site Notes: September 2008: The approximately five for the five forms and the five forms are also be a second story of the five forms. September 2008: The proximately five forms are also be a second story of the five forms	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel hig cade. Metal steps with met façade are fenestrated with each windows. All windows athwest) elevation was not set from the sidewalk. The RES DATA RIALS DATA Material Not Visible Material	enstructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening al balusters provide to 6/6, double-hung, we have concrete sills surveyed or photograted on the southweld dwelling is adjacent	reatment Same permit (#6196). In ortheast elevation) ted along the façade single-leaf paneled with the original one-structure access to the door crood-sash windows. The first and second aphed by the volunter to 1527 and 1531 Permits and and 1531 Permit	The dwelling is const is faced with Flemish-by a projecting molde wood door and a one-ory, full-width porch hopening. The foundation The first story opening story openings have been surveyor. Inia Avenue, S.E. and innsylvania Avenue, S.	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, concrete	
September 2008: Co rowhouse is one of a brick and is set on a sthat has been painted with dentil molding. The rectangular wood trace are with dentil molding. The rectangular wood trace are with the fassecond story of the adouble-hung, vinyl-slintels. The rear (sout the second story of the adouble-hung, vinyl-slintels. The rear (sout the second story of the adouble-hung, vinyl-slintels. The rear (sout the second story of the adouble-hung, vinyl-slintels. The rear (sout the second story of the second st	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel hig cade. Metal steps with metacade are fenestrated with each windows. All windows athwest) elevation was not sis two-story dwelling is located from the sidewalk. The RES DATA RIALS DATA Material Not Visible	constructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening al balusters provide to 6/6, double-hung, we have concrete sills surveyed or photograted on the southwedwelling is adjacent	same permit (#6196). northeast elevation) ted along the façade single-leaf paneled v . The original one-st access to the door of cood-sash windows. The first and second aphed by the volunte est side of Pennsylva to 1527 and 1531 Per Treatment Not Visible	The dwelling is const is faced with Flemish-by a projecting molde wood door and a one-ory, full-width porch hopening. The foundation The first story opening distory openings have ever surveyor. Inia Avenue, S.E. and innsylvania Avenue, S.	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, concrete	
September 2008: Co rowhouse is one of a brick and is set on a sthat has been painted with dentil molding. The rectangular wood trace removed from the fasecond story of the adouble-hung, vinyl-slintels. The rear (south september 2008: The approximately five formulated the second story of the adouble-hung, vinyl-slintels. The rear (south september 2008: The approximately five formulated the second story of the second story o	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel hig cade. Metal steps with met façade are fenestrated with each windows. All windows athwest) elevation was not set from the sidewalk. The RES DATA RIALS DATA Material Not Visible Material	constructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening al balusters provide to 6/6, double-hung, we have concrete sills surveyed or photograted on the southwedwelling is adjacent	reatment Same permit (#6196). In ortheast elevation) ted along the façade single-leaf paneled with the original one-structure access to the door crood-sash windows. The first and second aphed by the volunter to 1527 and 1531 Permits and and 1531 Permit	The dwelling is const is faced with Flemish-by a projecting molde wood door and a one-ory, full-width porch hopening. The foundation The first story opening distory openings have ever surveyor. Inia Avenue, S.E. and innsylvania Avenue, S.	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, concrete	
September 2008: Co rowhouse is one of it brick and is set on a that has been painte with dentil molding. rectangular wood tra removed from the fa second story of the it double-hung, vinyl-s lintels. The rear (sou Site Notes: September 2008: Th approximately five for NOTABLE FEATUR Component EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel hig cade. Metal steps with met façade are fenestrated with each windows. All windows athwest) elevation was not sis two-story dwelling is located from the sidewalk. The RES DATA RIALS DATA Material Not Visible Material Brick	constructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening all balusters provide (6/6, double-hung, we have concrete sills, surveyed or photograted on the southweld dwelling is adjacent Color	reatment Same permit (#6196). In ortheast elevation) ted along the façade single-leaf paneled with the original one-structure access to the door crood-sash windows. The first and second aphed by the volunter to 1527 and 1531 Permits and and 1531 Permit	The dwelling is const is faced with Flemish-by a projecting molde wood door and a one-ory, full-width porch hypening. The foundation The first story opening have been surveyor. Inia Avenue, S.E. and innsylvania Avenue, S. Source	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, concrete	
rowhouse is one of the brick and is set on a that has been painted with dentil molding. rectangular wood transport the fasecond story of the fasecond story of the fouble-hung, vinyl-slintels. The rear (souther the bottom of the set	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel hig cade. Metal steps with met façade are fenestrated with each windows. All windows athwest) elevation was not districted to the side with the side walk. The seature RIALS DATA Material Not Visible Material Brick Material	constructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening all balusters provide (6/6, double-hung, we have concrete sills, surveyed or photograted on the southweld dwelling is adjacent Color	reatment Same permit (#6196). In ortheast elevation) ted along the façade single-leaf paneled with the original one-structure access to the door crood-sash windows. The first and second aphed by the volunter to 1527 and 1531 Permits and and 1531 Permit	The dwelling is const is faced with Flemish-by a projecting molde wood door and a one-ory, full-width porch hypening. The foundation The first story opening have been surveyor. Inia Avenue, S.E. and innsylvania Avenue, S. Source	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, concrete	
September 2008: Co rowhouse is one of the brick and is set on a that has been painted with dentil molding. The rectangular wood transport of the fasecond story of the fasecond	nstructed in 1912 by Willia three similar rowhouses co solid, raised concrete four d. A sloping roof caps the The northwestern bay of the ansom. A concrete lintel hig cade. Metal steps with met façade are fenestrated with each windows. All windows atthwest) elevation was not set from the sidewalk. The RES DATA RIALS DATA Material Not Visible Material Brick Material Concrete	constructed from the sendation; the façade (dwelling and is from the first story holds a ghlights the opening all balusters provide (6/6, double-hung, we have concrete sills, surveyed or photograted on the southweld dwelling is adjacent Color	reatment Same permit (#6196). In ortheast elevation) ted along the façade single-leaf paneled with the original one-structure access to the door crood-sash windows. The first and second aphed by the volunter to 1527 and 1531 Permits and and 1531 Permit	The dwelling is const is faced with Flemish-by a projecting molde wood door and a one-ory, full-width porch hypening. The foundation The first story opening have been surveyor. Inia Avenue, S.E. and innsylvania Avenue, S. Source	ructed of -bond brick ed cornice light nas been on and gs hold 1/1, concrete	

Window Location	Aperture Shape	Туре	Lights	Material			
1 FIr Windows	Rectangular	Dbl-Hung	1/1	Vinyl			
2 Flr Windows	Rectangular	Dbl-Hung	6/6	Wood			
Basemt Windows	Rectangular	Dbl-Hung	6/6	Wood			
Door Location	Aperture Shape	Туре	Pamels	Material			
Main Door	Rectangular	Single	Paneled	Wood			
Notable Interior Plan(s)		Notable Interior Feature(s)			
Interior Notes:							
PLAN/SURVEY/DE	ESIGNATION DATA						
Neighborhood: C	apitol Hill		Historic District(s)				
Subdivision:	ириот тип		Thotorio District(0)				
Ward/ANC:							
Zoning:			Designation Event(s)				
Contributing:							
Survey(s)			Level(s) of Investigation				
	st Phase I (2009/2010)		Permit Research				
	(Volunteer Reconnaissance Survey				
PHOTOS - DIGITIZ	ZED						
Path: C:\Users\C	HRS\Documents\CHRS SE Phase I - D to G						
Databases\ St\Databas	e\Pictures\Square 1078\						
Databases\ St\Database	e\Pictures\Square 1078\						
Databases\ St\Database File: 1529_PA_A Date::	e\Pictures\Square 1078\						
Databases\ St\Database File: 1529_PA_A Date::	e\Pictures\Square 1078\ VSE.JPG	Fr:					
Databases\ St\Database File: 1529_PA_A Date:: Code::	e\Pictures\Square 1078\ VSE.JPG Photog: R:	Fr:					
Databases\ St\Databas	e\Pictures\Square 1078\ VSE.JPG Photog: R:	Fr: Date	Photographer	Caption			
Databases\ St\Databases\ Tile: 1529_PA_A Date:: Code:: PHOTOS - B/W OF Photo Code	e\Pictures\Square 1078\ VSE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption			
Databases\ St\Databases\ Tile: 1529_PA_A Date:: Code:: PHOTOS - B/W OF Photo Code	e\Pictures\Square 1078\ VSE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption			
Databases\ St\Databases\ Tile: 1529_PA_A Date:: Code:: PHOTOS - B/W OF	e\Pictures\Square 1078\ VSE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption			
Databases\ St\Databases\ St\Databases\ Interpretation 1529_PA_A Date:: Code:: PHOTOS - B/W OF Photo Code MISCELLANEOUS	e\Pictures\Square 1078\ VSE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption			
Databases\ St\Databases\ 1529_PA_A Date:: Code:: PHOTOS - B/W OF Photo Code MISCELLANEOUS Notes:	e\Pictures\Square 1078\ VSE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption			
Databases\ St\Databases\ Tile: 1529_PA_A Date:: Code:: PHOTOS - B/W OF Photo Code MISCELLANEOUS	e\Pictures\Square 1078\ VSE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption			
Databases\ St\Databases\ St\Databases\ Tile: 1529_PA_A Date:: Code:: PHOTOS - B/W OF Photo Code MISCELLANEOUS Notes: PERMIT DATA	elPictures\Square 1078\ VSE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s) S NOTES DATA	Date		Caption			

BIBLIOG	RAPHIC DATA			
SIGNIFIC	CANCE DATA			
Study Unit				
Code	Criteria			
DATA PF	ROCESSING EVENTS DATA			

ID_Number: 1078-0026 Page 4

ID Number: 1078-0025

ID_Number: 1078-0025 Page 1

BASICS DATA

ID Number: 1078-0025 Year Built: 1912 Data Source: **Permit** Quad Type of Address Number Extended Street 1527 **NW** Current Pennsylvania Avenue Name(s) Type of Name Rowhouse, 1527 Pennsylvania Avenue, S.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain 1078/0025 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1912 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1912	Permit			2000 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Arch	itect		Talbott, W.	R.
Orig Construction	Build	ler		Boss, Willi	am A.
Orig Construction	Own	er		Boss, Willi	am A.
Construction Notes:					
One of three rowhouses c	onstructed fro	m the same po	ermit (#4471).	

PEOPLE/EVENTS DATA

Racial Segregation Status:

have concrete sills. surveyed or photograms Site Notes: September 2008: The approximately five for the sills.	The first and second story caphed by the volunteer sursists two-story rowhouse is located from the sidewalk. The conditional caped with foundation caped c	veyor. cated on the southw	•	•	set back
have concrete sills. surveyed or photogr Site Notes: September 2008: Th approximately five fe small front yard is la NOTABLE FEATUR Component EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation	The first and second story caphed by the volunteer sure caphed with foundation. RES DATA Feature RIALS DATA Material Not Visible Material Brick Material Concrete	cated on the southw dwelling is adjacent to plantings. Color	Treatment Not Visible Treatment	Source Source	set back
have concrete sills. surveyed or photogr Site Notes: September 2008: Th approximately five fe small front yard is la NOTABLE FEATUR Component EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component	The first and second story caphed by the volunteer sursiphed by the volunte	cated on the southw dwelling is adjacent to plantings. Color	Treatment Not Visible Treatment	Source Source	set back
have concrete sills. surveyed or photogr Site Notes: September 2008: Th approximately five fe small front yard is la NOTABLE FEATU Component EXTERIOR MATER Roof Component Sloped Wall Component Facade	The first and second story caphed by the volunteer sursists two-story rowhouse is located from the sidewalk. The conditional caped with foundation caped c	cated on the southw dwelling is adjacent to plantings. Color	Treatment Not Visible Treatment	Source Source	set back
have concrete sills. surveyed or photogr Site Notes: September 2008: Th approximately five fe small front yard is la NOTABLE FEATU Component EXTERIOR MATER Roof Component Sloped Wall Component	The first and second story caphed by the volunteer sursists two-story rowhouse is located from the sidewalk. The conditional story with the first part of th	cated on the southw dwelling is adjacent t plantings.	Treatment Not Visible Treatment	Source	set back
have concrete sills. surveyed or photogr Site Notes: September 2008: Th approximately five fe small front yard is la NOTABLE FEATU Component EXTERIOR MATER Roof Component Sloped Wall Component	The first and second story caphed by the volunteer sursists two-story rowhouse is located from the sidewalk. The conditional story with the first part of th	cated on the southw dwelling is adjacent t plantings.	Treatment Not Visible Treatment	Source	set back
have concrete sills. surveyed or photogr Site Notes: September 2008: Th approximately five for small front yard is la NOTABLE FEATU Component EXTERIOR MATER Roof Component Sloped	The first and second story caphed by the volunteer sure is two-story rowhouse is located from the sidewalk. The condscaped with foundation RES DATA Feature RIALS DATA Material Not Visible	cated on the southw dwelling is adjacent t plantings.	Treatment Not Visible	Source	set back
have concrete sills. surveyed or photogree Site Notes: September 2008: The approximately five from the small front yard is language. NOTABLE FEATURE Component EXTERIOR MATERIES.	The first and second story caphed by the volunteer sure is two-story rowhouse is located from the sidewalk. The condscaped with foundation RES DATA Feature RIALS DATA Material	veyor. cated on the southw dwelling is adjacent t plantings.	o 1525 and 1529 Pe	nnsylvania Avenue, S.E. T	set back
have concrete sills. surveyed or photogree Site Notes: September 2008: The approximately five from the small front yard is language. NOTABLE FEATURE. Component	The first and second story caphed by the volunteer sure is two-story rowhouse is located from the sidewalk. The condscaped with foundation RES DATA Feature	veyor. cated on the southw dwelling is adjacent t plantings.	o 1525 and 1529 Pe	nnsylvania Avenue, S.E. T	set back
have concrete sills. surveyed or photogr Site Notes: September 2008: Th approximately five for small front yard is lated to the surveyed or photography of the surveyed of the	The first and second story caphed by the volunteer sure is two-story rowhouse is locate from the sidewalk. The condscaped with foundation RES DATA	veyor. cated on the southw	•	•	set back
have concrete sills. surveyed or photogree Site Notes: September 2008: The approximately five feather small front yard is later than the small front yard is	The first and second story caphed by the volunteer sure is two-story rowhouse is located from the sidewalk. The candscaped with foundation RES DATA	veyor. cated on the southw	•	•	set back
have concrete sills. surveyed or photogr Site Notes: September 2008: Th approximately five for small front yard is la	The first and second story aphed by the volunteer sur is two-story rowhouse is located from the sidewalk. The candscaped with foundation	veyor. cated on the southw	•	•	set back
have concrete sills. surveyed or photograms Site Notes: September 2008: The approximately five for the sills.	The first and second story caphed by the volunteer sur is two-story rowhouse is located from the sidewalk. The capet from the sidewalk.	veyor. cated on the southw	•	•	set back
have concrete sills. surveyed or photogr Site Notes: September 2008: Th	The first and second story caphed by the volunteer sur is two-story rowhouse is lo	veyor.	•	•	set back
have concrete sills. surveyed or photogr	The first and second story	. •			
have concrete sills.	The first and second story	. •			5 1161
rowhouse is one of the brick and is set on a that has been painte with dentil molding. transom. A concrete façade. Metal steps pierced by a single-l	nstructed in 1912 by Willian three similar rowhouses co solid, raised concrete four d. A sloping roof caps the of the northwestern bay of the lintel highlights the opening with metal balusters provide eaf paneled door with light sash windows. The first steep the sash windows.	nstructed from the s ndation; the façade (r dwelling and is fronto the first story holds a tag. The original one-se e access to the door s. The foundation an ory openings hold 6/5	ame permit (#4471). northeast elevation) ed along the façade single-leaf door and story, full-width pord opening. The north d second story of th odouble-hung, woo	The dwelling is construct is faced with Flemish-bor by a projecting molded control a one-light rectangular with has been removed from western bay of the foundate façade are fenestrated to d-sash windows. All windows.	nd brick conice cood n the ation is with 6/6, lows
Exterior & Architectura					
Italianate					
Architectural Style(s)					
STYLE/EXTERIOR	DATA				
Has Driveway:					
Acreage:					
Lot SqFt:		Satisfaining Notes.			
Lot Width Lot Depth/Length:		Outbuilding Notes:			
Volume:					
Depth/Length: SqFt:	32				
Width:	16				
Height:		Outbuilding Type	Cor	tributing Status	-
Bays Wide:	3]
Number Stories:	2 plus basement				
	Rectangular				
Footprint:	Row Building/Flat Front				
Massing:	Face on Setback Line				
Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Row (1 of 3) Face on Setback Line				
Relate to Street: Massing:	` '				

Window Location	Aperture Shape	Type	Lights	Material	
1 Fir Windows	Rectangular	Dbl-Hung	6/9	Wood	
2 Flr Windows	Rectangular	Dbl-Hung	6/6	Wood	
Basemt Windows	Rectangular	Dbl-Hung	6/6	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single		Unknown	
Notable Interior Plan	(s)		Notable Interior Feature(s)		
Interior Notes:					
PLAN/SURVEY/D	ESIGNATION DATA				
Neighborhood: C Subdivision: Ward/ANC:	capitol Hill		Historic District(s)		
vvard/ANC. Zoning:			Designation Event(s)		
Contributing:					
Survey(s)			Level(s) of Investigation		
Capitol Hill Southea	ast Phase I (2009/2010)		Permit Research		
			Volunteer Reconnaissand	ce Survey	
PHOTOS - DIGITIZ	ZED				
Caption:		()	NVIC		
Databases\	:HRS\Documents\CHRS \SE Phase I - D to G				
Databases\ St\Databas	\SE Phase I - D to G se\Pictures\Square 1078\				
Databases\ St\Databases File: 1527_PA_A Date::	\SE Phase I - D to G se\Pictures\Square 1078\	Fr:			
Databases' St\Databas File: 1527_PA_A Date:: Code::	ASE Phase I - D to G selPictures\Square 1078\ AVSE.JPG Photog: R:	Fr:			
Databases' St\Databas File: 1527_PA_A Date:: Code::	ASE Phase I - D to G selPictures\Square 1078\ AVSE.JPG Photog:	Fr:	Photographer	Caption	
Databases' St\Databas File: 1527_PA_A Date:: Code:: PHOTOS - B/W O	ASE Phase I - D to G selPictures\Square 1078\ AVSE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption	
Databases' St\Databas File: 1527_PA_A Date:: Code:: PHOTOS - B/W O	ASE Phase I - D to G selPictures\Square 1078\ AVSE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption	
Databases' St\Databases File: 1527_PA_A Date:: Code:: PHOTOS - B/W OF Photo Code MISCELLANEOUS	ASE Phase I - D to G selPictures\Square 1078\ AVSE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption	
Databases' St\Databas File: 1527_PA_A Date:: Code:: PHOTOS - B/W OF Photo Code MISCELLANEOUS	ASE Phase I - D to G selPictures\Square 1078\ AVSE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption	
Databases' St\Databases' St\Databases' File: 1527_PA_A Date:: Code:: PHOTOS - B/W Ol Photo Code MISCELLANEOUS Notes:	ASE Phase I - D to G selPictures\Square 1078\ AVSE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption	
Databases' St\Databas File: 1527_PA_A Date:: Code:: PHOTOS - B/W O	ASE Phase I - D to G selPictures\Square 1078\ AVSE.JPG Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption	

BIBLIOG	GRAPHIC DATA			
SIGNIFIC	CANCE DATA			
Study Unit	t			
Code	Criteria			
DATA PF	ROCESSING EVENTS DATA			

ID Number: 1078-0024

BASICS DATA

ID Number: 1078-0024 Year Built: 1912 Data Source: Permit Number Extended Street Quad Type of Address 1525 SE Current Pennsylvania Avenue Name(s) Type of Name Rowhouse, 1525 Pennsylvania Avenue, S.E. Common **Liquidity Jones Tattoo** Current **Holistic Wellness Center** Current TaxCode1 TaxCode2 TaxCode3 Type Explain 1078/0024 Current Square/Lot

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1912 Permit Original

Professional Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1912	Permit			2000 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Arch	itect		Talbott, W.	R.
Orig Construction	Build	ler		Boss, Willia	am A.
Orig Construction	Own	er		Boss, Willia	am A.
Construction Notes:					

One of three rowhouses constructed from the same permit (#4471).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

ID_Number: 1078-0024 Page 1

Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick	Color Color Feature	Treatment Not Visible Treatment Flemish Bond	Source Source	-
Roof Component Sloped Wall Component Facade Structure Component Foundation	Material Not Visible Material Brick Material Concrete	Color	Not Visible Treatment	Source	-
Roof Component Sloped Wall Component Facade Structure Component	Material Not Visible Material Brick Material	Color	Not Visible Treatment	Source	-
Roof Component Sloped Wall Component Facade	Material Not Visible Material Brick	Color	Not Visible Treatment	Source	-
Roof Component Sloped Wall Component	Material Not Visible Material		Not Visible Treatment		-
Roof Component Sloped Wall Component	Material Not Visible Material		Not Visible Treatment		-
Roof Component Sloped	Material Not Visible		Not Visible		
Roof Component	Material	Color		Source	-
				_	
Component	Feature				
NOTABLE FEATU	-				
-		entrances.			
September 2008: Th approximately five fo small front yard is la	is two-story rowhouse is lo eet from the sidewalk. The o indscaped with mature shru e basement and first story	dwelling is adjacent ubs and is bounded	to 1523 and 1527 Pe	nnsylvania Avenue, S.E.	The
Site Notes:					
rowhouse is one of brick and is set on a that has been painte with dentil molding. concrete lintel. The concrete lintel highl steps with metal bal the façade hold 1/1,	al Notes: nstructed in 1912 by Willian three similar rowhouses co solid, raised concrete four d. A sloping roof caps the anorthwestern bay of the firstights the opening. The origusters provide access to the double-hung, vinyl-sash will photographed by the volund three similars.	nstructed from the s ndation; the façade (dwelling and is front by a single-leaf door at story holds a singl inal one-story, full-w e door opening. All ndows and have co	ame permit (#4471). northeast elevation) ed along the façade with lights and a sli e-leaf wood-frame g idth porch has been window openings or	The dwelling is construct is faced with Flemish-bor by a projecting molded coding one-light window will lass door and a blind transemoved from the façader the first and second stores.	nd brick ornice th a asom. A a. Metal ries of
Italianate					
Architectural Style(s)					
STYLE/EXTERIOR	DATA				
Has Driveway:					
Acreage:					
Lot Depth/Length: Lot SqFt:		Outbuilding Notes:]
Lot Width					
SqFt: Volume:	32				
Width: Depth/Length:	16 32				
Height:		Outbuilding Type	Cor	ntributing Status	_
Bays Wide:	3				J
Number Stories:	2 plus basement				
Footprint:	Row Building/Flat Front Rectangular				
Massing:	Face on Setback Line				
Relate to Street:	` '				
Relate to Othr Bldgs: Relate to Street:	Row (1 of 3)				
<u> </u>	Intact		rence Notes:		

Window Location	Aperture Shape	Туре	Lights		Material
Basemt Windows	Rectangular	Unknown	1-light		Unknown
Facade	Rectangular	Dbl-Hung	1/1		Vinyl
Door Location	Aperture Shape	Туре	Pamels		Material
Basement	Rectangular	Single			Unkown w/Lights
Main Door	Rectangular	Single	Full Glas	s	Wood/Glass
Notable Interior Plan	(s)		Notable Interior Feature(s	s)	
Interior Notes:					_
PLAN/SURVEY/D	ESIGNATION DATA				
Neighborhood: C Subdivision: Ward/ANC:	apitol Hill		Historic District(s)		
Zoning: Contributing:			Designation Event(s)		
Survey(s)			Level(s) of Investigation		
	ast Phase I (2009/2010)		Permit Research		
			Volunteer Reconnaissa	nce Survey	
PHOTOS - DIGITI	ZED				
Caption:					
Databases ¹	HRS\Documents\CHRS \SE Phase I - D to G \e\Pictures\Square 1078\ \VSE.JPG				
Date::	Photog:	Fr:			
PHOTOS - B/W O	R NON-DIGITIZED				
Photo Code	Roll Frame(s)	Date	Photographer	Caption	
MISCELLANEOUS	S NOTES DATA				
PERMIT DATA					
Permit Issue Date	Number Type		Remarks		
04/06/1912	4471 Build				
Permit Notes:					

BIBLIOG	GRAPHIC DATA			
SIGNIFIC	CANCE DATA			
Study Unit	t			
Code	Criteria			
DATA PF	ROCESSING EVENTS DATA			

ID_Number: 1078-0024 Page 4

ID Number: 1078-0023

ID_Number: 1078-0023 Page 1

BASICS DATA

ID Number: 1078-0023 Year Built: 1912 Data Source: Permit Quad Type of Address Number Extended Street 1523 Current Pennsylvania Avenue Name(s) Type of Name Rowhouse, 1523 Pennsylvania Avenue, S.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain 1078/0023 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1912 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1912	Permit			2000 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Archi	itect		Talbott, W.	R.
Orig Construction	Build	ler		Boss, Willi	am A.
Orig Construction	Owne	er		Boss, Willi	am A.
Construction Notes:					
One of three rowhouses	constructed fro	m the same pe	ermit (#4471).	

PEOPLE/EVENTS DATA

Racial Segregation Status:

Ctus stansana	Urban	01033 110	rerence Notes:		
Streetscape: Relate to Othr Bldgs:	Intact				
Relate to Street:	Row (1 of 3) Face on Setback Line				
Massing:	Row Building/Flat Front				
Footprint:	Rectangular				
Number Stories:	2 plus basement				
Bays Wide:	3				
Height:		Outbuilding Type	Со	ntributing Status	<u> </u>
Width:	16				
Depth/Length:	32				
SqFt: Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes	::		
Lot SqFt:					
Acreage:					
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)	DATA				
Italianate			_		
	INI A				
Exterior & Architectura		m A Bass this tw	a atami three bay Itali	anata atula aingla family	,
	nstructed in 1912 by Willia hree similar rowhouses co				
	solid, raised concrete four		. ,	•	
that has been painte	d. A sloping roof caps the	dwelling and is fro	nted along the facade	by a projecting molded	cornice
1.1 1 .11 1 11					
•	The foundation is pierced	by a single-leaf do	or and 1/1, double-hur	ng, vinyl-sash windows.	The
northwestern bay of	The foundation is pierced the first story holds a sing	by a single-leaf do le-leaf door with li	or and 1/1, double-hur ghts and a one-light re	ng, vinyl-sash windows. ectangular wood transor	The n. A
northwestern bay of concrete lintel highli metal balusters, set	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation	by a single-leaf do le-leaf door with li inal one-story por , provide access t	or and 1/1, double-hur ghts and a one-light re ch has been removed o the door opening. Al	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s I window openings on t	The n. A teps with he first
northwestern bay of concrete lintel highli metal balusters, set and second stories of	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, doub	by a single-leaf do le-leaf door with li inal one-story por , provide access t ble-hung, vinyl-sas	or and 1/1, double-hur ghts and a one-light re ch has been removed o the door opening. Al h windows and have o	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s I window openings on t	The n. A teps with he first
northwestern bay of concrete lintel highli metal balusters, set and second stories of (southwest) elevation	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation	by a single-leaf do le-leaf door with li inal one-story por , provide access t ble-hung, vinyl-sas	or and 1/1, double-hur ghts and a one-light re ch has been removed o the door opening. Al h windows and have o	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s I window openings on t	The n. A teps with he first
northwestern bay of concrete lintel highli metal balusters, set and second stories (southwest) elevation. Site Notes:	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, douk n was not surveyed or pho-	by a single-leaf do le-leaf door with li inal one-story port, provide access to le-hung, vinyl-sastographed by the v	or and 1/1, double-hur ghts and a one-light re ch has been removed o the door opening. Al h windows and have o colunteer surveyor.	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s Il window openings on t concrete sills and lintels	The n. A teps with he first . The rear
northwestern bay of concrete lintel highli metal balusters, set and second stories (southwest) elevation. Site Notes: September 2008: This approximately five fee	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, douk n was not surveyed or phoses two-story rowhouse is located from the concrete sidew	by a single-leaf do le-leaf door with li inal one-story port, provide access to le-hung, vinyl-sastographed by the valled on the south valle. The dwelling	or and 1/1, double-hur ghts and a one-light re ch has been removed to the door opening. Al h windows and have o colunteer surveyor.	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s Il window openings on to concrete sills and lintels vania Avenue, S.E. and i	The n. A teps with he first . The rear
northwestern bay of concrete lintel highli metal balusters, set and second stories (southwest) elevation. Site Notes: September 2008: This approximately five fee	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, doukn was not surveyed or phosis two-story rowhouse is lo	by a single-leaf do le-leaf door with li inal one-story port, provide access to le-hung, vinyl-sastographed by the valled on the south valle. The dwelling	or and 1/1, double-hur ghts and a one-light re ch has been removed to the door opening. Al h windows and have o colunteer surveyor.	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s Il window openings on to concrete sills and lintels vania Avenue, S.E. and i	The n. A teps with he first . The rear
northwestern bay of concrete lintel highli metal balusters, set and second stories (southwest) elevation. Site Notes: September 2008: This approximately five fee	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, doubn was not surveyed or phosis two-story rowhouse is locet from the concrete sidew is landscaped with mature	by a single-leaf do le-leaf door with li inal one-story port, provide access to le-hung, vinyl-sastographed by the valled on the south valle. The dwelling	or and 1/1, double-hur ghts and a one-light re ch has been removed to the door opening. Al h windows and have o colunteer surveyor.	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s Il window openings on to concrete sills and lintels vania Avenue, S.E. and i	The n. A teps with he first . The rear
northwestern bay of concrete lintel highli metal balusters, set and second stories of (southwest) elevation. Site Notes: September 2008: This approximately five for the small front yard.	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, doubn was not surveyed or phosis two-story rowhouse is locet from the concrete sidew is landscaped with mature	by a single-leaf do le-leaf door with li inal one-story port, provide access to le-hung, vinyl-sastographed by the valled on the south valle. The dwelling	or and 1/1, double-hur ghts and a one-light re ch has been removed to the door opening. Al h windows and have o colunteer surveyor.	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s Il window openings on to concrete sills and lintels vania Avenue, S.E. and i	The n. A teps with he first . The rear
northwestern bay of concrete lintel highlimetal balusters, set and second stories of (southwest) elevation. Site Notes: September 2008: This approximately five for the small front yard.	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, douk n was not surveyed or phosis two-story rowhouse is loset from the concrete sidew is landscaped with mature	by a single-leaf do le-leaf door with li inal one-story port, provide access to le-hung, vinyl-sastographed by the valled on the south valle. The dwelling	or and 1/1, double-hur ghts and a one-light re ch has been removed to the door opening. Al h windows and have o colunteer surveyor.	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s Il window openings on to concrete sills and lintels vania Avenue, S.E. and i	The n. A teps with he first . The rear
northwestern bay of concrete lintel highlimetal balusters, set and second stories of (southwest) elevation. Site Notes: September 2008: This approximately five for the small front yard.	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, douk n was not surveyed or phosis two-story rowhouse is loset from the concrete sidew is landscaped with mature RES DATA	by a single-leaf do le-leaf door with li inal one-story port, provide access to le-hung, vinyl-sastographed by the valled on the south valle. The dwelling	or and 1/1, double-hur ghts and a one-light re ch has been removed to the door opening. Al h windows and have o colunteer surveyor.	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s Il window openings on to concrete sills and lintels vania Avenue, S.E. and i	The n. A teps with he first . The rear
northwestern bay of concrete lintel highlimetal balusters, set and second stories of (southwest) elevation. Site Notes: September 2008: This approximately five for the small front yard. NOTABLE FEATURE. Component	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, douk n was not surveyed or phosis two-story rowhouse is loset from the concrete sidew is landscaped with mature RES DATA	by a single-leaf do le-leaf door with li inal one-story port, provide access to le-hung, vinyl-sastographed by the valled on the south valle. The dwelling	or and 1/1, double-hur ghts and a one-light re ch has been removed to the door opening. Al h windows and have o colunteer surveyor.	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s Il window openings on to concrete sills and lintels vania Avenue, S.E. and i	The n. A teps with he first . The rear
northwestern bay of concrete lintel highlimetal balusters, set and second stories of (southwest) elevation. Site Notes: September 2008: This approximately five for the small front yard. NOTABLE FEATURE.	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, douk n was not surveyed or phoris two-story rowhouse is loset from the concrete sidew is landscaped with mature RES DATA Feature	by a single-leaf do le-leaf door with li inal one-story pore, provide access to le-hung, vinyl-sastographed by the vicated on the south valk. The dwelling shrubs and found	or and 1/1, double-hur ghts and a one-light re ch has been removed to the door opening. Al h windows and have o colunteer surveyor. nwest side of Pennsylv is adjacent to 1521 an lation plantings.	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s I window openings on to concrete sills and lintels vania Avenue, S.E. and i d 1525 Pennsylvania Ave	The n. A teps with he first . The rear
northwestern bay of concrete lintel highlimetal balusters, set and second stories of (southwest) elevation. Site Notes: September 2008: This approximately five for the small front yard. NOTABLE FEATURE. Component. EXTERIOR MATERIES. Roof Component. Sloped.	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, douk n was not surveyed or phoris two-story rowhouse is loset from the concrete sidew is landscaped with mature RES DATA RIALS DATA Material Not Visible	by a single-leaf do le-leaf door with li inal one-story pore, , provide access to le-hung, vinyl-sast tographed by the vicated on the south ralk. The dwelling shrubs and founce	or and 1/1, double-hur ghts and a one-light re ch has been removed to the door opening. Al h windows and have o volunteer surveyor. nwest side of Pennsylv is adjacent to 1521 an lation plantings. Treatment Not Visible	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s Il window openings on to concrete sills and lintels vania Avenue, S.E. and i d 1525 Pennsylvania Ave Source	The n. A teps with he first . The rear
northwestern bay of concrete lintel highlimetal balusters, set and second stories of (southwest) elevation. Site Notes: September 2008: This approximately five for the small front yard. NOTABLE FEATURE. Component. EXTERIOR MATER. Roof Component. Sloped. Wall Component.	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, douk n was not surveyed or phores to the factory rowhouse is loset from the concrete sidew is landscaped with mature RES DATA RIALS DATA Material Not Visible Material	by a single-leaf do le-leaf door with li inal one-story pore, provide access to le-hung, vinyl-sastographed by the vicated on the south valk. The dwelling shrubs and found	or and 1/1, double-hur ghts and a one-light re ch has been removed to the door opening. Al th windows and have o rolunteer surveyor. Inwest side of Pennsylv is adjacent to 1521 an lation plantings. Treatment Not Visible Treatment	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s I window openings on to concrete sills and lintels vania Avenue, S.E. and i d 1525 Pennsylvania Ave	The n. A teps with he first . The rear
northwestern bay of concrete lintel highlimetal balusters, set and second stories of (southwest) elevation. Site Notes: September 2008: This approximately five for the small front yard. NOTABLE FEATURE. Component. EXTERIOR MATERIES. Roof Component. Sloped.	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, douk n was not surveyed or phoris two-story rowhouse is loset from the concrete sidew is landscaped with mature RES DATA RIALS DATA Material Not Visible	by a single-leaf do le-leaf door with li inal one-story pore, , provide access to le-hung, vinyl-sast tographed by the vicated on the south ralk. The dwelling shrubs and founce	or and 1/1, double-hur ghts and a one-light re ch has been removed to the door opening. Al h windows and have o volunteer surveyor. nwest side of Pennsylv is adjacent to 1521 an lation plantings. Treatment Not Visible	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s Il window openings on to concrete sills and lintels vania Avenue, S.E. and i d 1525 Pennsylvania Ave Source	The n. A teps with he first . The rear
northwestern bay of concrete lintel highlimetal balusters, set and second stories of (southwest) elevation. Site Notes: September 2008: This approximately five for the small front yard. NOTABLE FEATURE. Component. EXTERIOR MATER. Roof Component. Sloped. Wall Component. Facade.	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, dout n was not surveyed or photes two-story rowhouse is locet from the concrete sidew is landscaped with mature RES DATA RIALS DATA Material Not Visible Material Brick Material	by a single-leaf do le-leaf door with li inal one-story pore, , provide access to le-hung, vinyl-sast tographed by the vicated on the south ralk. The dwelling shrubs and founce	or and 1/1, double-hur ghts and a one-light re ch has been removed to the door opening. Al th windows and have o rolunteer surveyor. Inwest side of Pennsylv is adjacent to 1521 an lation plantings. Treatment Not Visible Treatment	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s Il window openings on to concrete sills and lintels vania Avenue, S.E. and i d 1525 Pennsylvania Ave Source	The n. A teps with he first . The rear
northwestern bay of concrete lintel highlimetal balusters, set and second stories of (southwest) elevation. Site Notes: September 2008: This approximately five for The small front yard. NOTABLE FEATURE. Component. EXTERIOR MATER. Roof Component. Sloped. Wall Component. Facade. Structure Component.	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, doubt n was not surveyed or photes two-story rowhouse is located from the concrete sidew is landscaped with mature. RES DATA Feature RIALS DATA Material Not Visible Material Brick Material Concrete	by a single-leaf do le-leaf door with li inal one-story pore, , provide access to le-hung, vinyl-sast tographed by the vicated on the south valk. The dwelling shrubs and found Color	or and 1/1, double-hur ghts and a one-light re ch has been removed to the door opening. Al th windows and have o rolunteer surveyor. Inwest side of Pennsylv is adjacent to 1521 an lation plantings. Treatment Not Visible Treatment	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s Il window openings on to concrete sills and lintels vania Avenue, S.E. and i d 1525 Pennsylvania Ave Source	The n. A teps with he first . The rear
northwestern bay of concrete lintel highlimetal balusters, set and second stories of (southwest) elevation. Site Notes: September 2008: This approximately five for the small front yard. NOTABLE FEATURE. Component. EXTERIOR MATER. Roof Component. Sloped. Wall Component. Facade.	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, dout n was not surveyed or photes two-story rowhouse is locet from the concrete sidew is landscaped with mature RES DATA RIALS DATA Material Not Visible Material Brick Material	by a single-leaf do le-leaf door with li inal one-story pore, , provide access to le-hung, vinyl-sast tographed by the vicated on the south valk. The dwelling shrubs and found Color	or and 1/1, double-hur ghts and a one-light re ch has been removed to the door opening. Al th windows and have o rolunteer surveyor. Inwest side of Pennsylv is adjacent to 1521 an lation plantings. Treatment Not Visible Treatment	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s Il window openings on to concrete sills and lintels vania Avenue, S.E. and i d 1525 Pennsylvania Ave Source	The n. A teps with he first . The rear
northwestern bay of concrete lintel highlimetal balusters, set and second stories of (southwest) elevation. Site Notes: September 2008: This approximately five for The small front yard. NOTABLE FEATURE. Component. EXTERIOR MATER. Roof Component. Sloped. Wall Component. Facade. Structure Component.	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, doubt n was not surveyed or photes two-story rowhouse is located from the concrete sidew is landscaped with mature. RES DATA Feature RIALS DATA Material Not Visible Material Brick Material Concrete	by a single-leaf do le-leaf door with li inal one-story pore, , provide access to le-hung, vinyl-sast tographed by the vicated on the south valk. The dwelling shrubs and found Color	or and 1/1, double-hur ghts and a one-light re ch has been removed to the door opening. Al th windows and have o rolunteer surveyor. Inwest side of Pennsylv is adjacent to 1521 an lation plantings. Treatment Not Visible Treatment	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s Il window openings on to concrete sills and lintels vania Avenue, S.E. and i d 1525 Pennsylvania Ave Source	The n. A teps with he first . The rear
northwestern bay of concrete lintel highlimetal balusters, set and second stories of (southwest) elevation. Site Notes: September 2008: This approximately five for the small front yard. NOTABLE FEATURE. Component. EXTERIOR MATER. Roof Component. Sloped. Wall Component. Facade. Structure Component. Foundation. Walls.	The foundation is pierced the first story holds a sing ights the opening. The orig on a solid brick foundation of the façade hold 1/1, doubt n was not surveyed or photes two-story rowhouse is located from the concrete sidew is landscaped with mature. RES DATA Feature RIALS DATA Material Not Visible Material Brick Material Concrete	by a single-leaf do le-leaf door with li inal one-story pore, , provide access to le-hung, vinyl-sast tographed by the vicated on the south valk. The dwelling shrubs and found Color	or and 1/1, double-hur ghts and a one-light re ch has been removed to the door opening. Al th windows and have o rolunteer surveyor. Inwest side of Pennsylv is adjacent to 1521 an lation plantings. Treatment Not Visible Treatment	ng, vinyl-sash windows. ectangular wood transor from the façade. Metal s Il window openings on to concrete sills and lintels vania Avenue, S.E. and i d 1525 Pennsylvania Ave Source	The n. A teps with he first . The rear

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material
Basemt Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
	_	_		•
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single		Unknown
Main Door	Rectangular	Single		Unkown w/Lights
Notable Interior Plan(s)		Notable Interior Feature	(s)
nterior Notes:				
PLAN/SURVEY/DE	ESIGNATION DATA			
Neighborhood: Ca	apitol Hill		Historic District(s)	
Subdivision:	•			
Ward/ANC:				
Zoning:			Designation Event(s)	
Contributing:			· ·	
Survey(s)			Level(s) of Investigation	
Capitol Hill Southea	st Phase I (2009/2010)		Permit Research	
			Volunteer Reconnaiss	ance Survey
Caption:				
Databases\	HRS\Documents\CHRS SE Phase I - D to G e\Pictures\Square 1078\			
St\Database			The second secon	
St\Database File: 1523_PA_A	_			
File: 1523_PA_A	_			
File: 1523_PA_A Date::	VSE.JPG	Fr:		
File: 1523_PA_A Date:: Code::	VSE.JPG Photog: R:	Fr:		
File: 1523_PA_A Date:: Code:: PHOTOS - B/W OF	Photog: R: R NON-DIGITIZED		Photographer	Continu
File: 1523_PA_A Date:: Code::	VSE.JPG Photog: R:	Fr:	Photographer	Caption
File: 1523_PA_A Date:: Code:: PHOTOS - B/W OF Photo Code	Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption
File: 1523_PA_A Date:: Code:: PHOTOS - B/W OF Photo Code	Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption
PHOTOS - B/W OF Photo Code MISCELLANEOUS	Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption
File: 1523_PA_A Date:: Code:: PHOTOS - B/W OF	Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption
Tile: 1523_PA_A Date:: Code:: PHOTOS - B/W OF Photo Code MISCELLANEOUS	Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption
PHOTOS - B/W OF Photo Code MISCELLANEOUS	Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption
PHOTOS - B/W OF Photo Code MISCELLANEOUS Notes:	Photog: R: R NON-DIGITIZED Roll Frame(s)		Photographer	Caption
File: 1523_PA_A Date:: Code:: PHOTOS - B/W OF Photo Code MISCELLANEOUS Notes: PERMIT DATA Permit Issue Date	Photog: R: R NON-DIGITIZED Roll Frame(s) S NOTES DATA			Caption
PHOTOS - B/W OF Photo Code MISCELLANEOUS	Photog: R: R NON-DIGITIZED Roll Frame(s) S NOTES DATA Number Type			Caption

BIBLIOG	GRAPHIC DATA			
SIGNIFIC	CANCE DATA			
Study Unit	t			
Code	Criteria			
DATA PF	ROCESSING EVENTS DATA			

ID Number: 1078-0033

ID_Number: 1078-0033 Page 1

BASICS DATA

ID Number: 1078-0033 Year Built: 1912 Data Source: Permit

Number Extended Street Quad Type of Address

1521 Pennsylvania Avenue SE Current

Name(s) Type of Name

Single Dwelling, 1521 Pennsylvania Avenue, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1078/0033 Square/Lot Permit

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1912 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

 Construction Event
 Start
 Source
 Stop
 Source
 Cost Source

 Orig Construction
 1912
 Permit
 2000 Permit

 Construction Event
 Association
 Associated Name

 Orig Construction
 Architect
 Masson, S.E.

 Orig Construction
 Builder
 Masson, S.E.

 Orig Construction
 Owner
 Brawner, John W.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

Surroundings:	Urban	Cross Ref	erence Notes:		
Streetscape:	Intact				
Relate to Othr Bldgs:	Attached				
Relate to Street:	Face on Setback Line				
Massing:	Vertical Box/flat front				
Footprint:	Rectangular				
Number Stories:	2 plus basement				
Bays Wide:	2 pius basement				
Height:	3	Outbuilding Type	Cor	ntributing Status	
Width:	20	Outbuilding Type	001	ithoding Status	
Depth/Length:	20 32				
SqFt:	J2				
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes:			
Lot SqFt:					
Acreage:					
_					
Has Driveway:					
OTVI E/EVTERIOR	D.174				
STYLE/EXTERIOR	DATA				
Architectural Style(s)			_		
Colonial Revival					
Exterior & Architectura	al Notes:				
mansard roof and ha light wood window (wood-sash windows wood door, which is highlights the openi- metal balusters, set and second stories of	ornice with scrolled modillings a raking wood cornice we possibly fixed). The foundate, which have rowlock brick flanked by sidelights and the original one-story, from a solid brick foundation of the façade hold 1/1, doubtels. The rear (southwest) of the factor (southwest) or the rear (southwe	ith fleur-de-lis mole tion is pierced by a sills. The northwe opped by a one-lig full-width porch ha , provide access to le-hung, vinyl-sasl	ding in the tympanum a single-leaf paneled wastern bay of the first shift rectangular wood the been removed from the door opening. All windows with false	. The dormer is pierced by wood door and 6/6, double story holds a single-leaf paransom. A concrete lintel the façade. Metal steps w I window openings on the 9/9 vinyl muntins and have	va one- e-hung, aneled ith first
Site Notes:					
September 2008: The approximately five for The small grassy from	is two-story dwelling is loca set from the concrete sidew nt yard is landscaped with An alley is located southw	alk. The dwelling i mature shrubs. A s	s adjacent to 1519 and short, brick walkway le	d 1523 Pennsylvania Aven	ue, S.E.
NOTABLE FEATU	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Mansard (False)	Slate		Shingled		
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Flemish Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				

Materials Notes:					
WINDOW/DOOR/I	NTERIOR DATA				
Window Location	Aperture Shape	Туре	Lights	Mater	ial
Basemt Windows Dormer	Rectangular Rectangular	Dbl-Hung Unknown	6/6 1-light	Wood Wood	
Facade	Rectangular	Dbl-Hung	1-ngnt 1/1	Vinyl	1
Door Location	Aperture Shape	Туре	Pamels	Mater	ial
Basement	Rectangular	Single	Paneled	Wood	
Main Door	Rectangular	Single	Paneled	Wood	1
Notable Interior Plan	(s)		Notable Interior Feature(s	s)	
Interior Notes:					
intenor Notes.					
PLAN/SURVEY/DI	ESIGNATION DATA				
	apitol Hill		Historic District(s)		
Subdivision: Ward/ANC:					
Zoning:			Designation Event(s)		
Contributing:					
Survey(s)			Level(s) of Investigation		
Capitol Hill Southea	st Phase I (2009/2010)		Permit Research Volunteer Reconnaissa	nce Survey	
			Volunteer Neconnaissa	nee ourvey	
PHOTOS - DIGITIZ	ZED				
Caption:					
			mi.		
	HRS\Documents\CHRS SE Phase I - D to G				
St\Databas	e\Pictures\Square 1078\				
File: 1521_PA_A					
Date:: Code::	Photog: R:	Fr:			
PHOTOS - B/W OI	R NON-DIGITIZED				
Photo Code	Roll Frame(s)	Date	Photographer	Caption	
MISCELLANEOUS	S NOTES DATA				
Notes:					
L					_

ID_Number: 1078-0033 Page 3

Permit Issue Date	Number	Type	Remarks	
11/16/1912	2560	Build		
Permit Notes:				
BIBLIOGRAPHIC DA	TA			
SIGNIFICANCE DATA	4			
Study Unit			_	
Code Criteria				
DATA PROCESSING	EVENTS DAT	A		

ID Number: 1078-0038

BASICS DATA

ID Number: 1078-0038 Year Built: 1913 Data Source: **Permit** Quad Type of Address Number Extended Street 1519 Current Pennsylvania Avenue Name(s) Type of Name Rowhouse, 1519 Pennsylvania Avenue, S.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain 1078/0038 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1913 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1913	Permit			1600 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Archi	itect		Masson, S.	E.
Orig Construction	Build	ler		Boss, Willi	am A.
Orig Construction	Owne	er		Boss, Willi	am A.
Construction Notes:					
One of five rowhouses co	nstructed from	the same per	mit (#3839).		

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

ID_Number: 1078-0038 Page 1

Relate to Othr Bldgs:	Row (1 of 5)					
Relate to Street:	Front Yard w/ Setback					
Massing:	Row Building/Flat Front					
Footprint:	Rectangular					
Number Stories:	2 plus basement					
Bays Wide:	3					
Height:		Outbuilding Type	Co	ntributing Status		
Width:	17					
Depth/Length:	32					
SqFt:						
Volume:						
Lot Width						
Lot Depth/Length:		Outbuilding Notes:				
Lot SqFt:						
Acreage:						
Has Driveway:						
STYLE/EXTERIOR	DATA					
Architectural Style(s)						
Italianate						
Exterior & Architectura	l Notes:					
		m A Bass this two sta	orv. three-bay Itali	anate-style single-family	,	
September 2008: Cor	istructed in 1913 by Williar	II A. DOSS. THIS TWO-STO				
•	nstructed in 1913 by Williar ive similar rowhouses cons	•	e permit (#3839).		ted of	
rowhouse is one of fi brick and is set on a	ive similar rowhouses cons solid, raised concrete foun	structed from the same adation; the façade (no	rtheast elevation	The dwelling is construct) is faced with five-cours	e,	
rowhouse is one of fi brick and is set on a American-bond brick	ive similar rowhouses cons solid, raised concrete foun that has been painted. A s	structed from the same ndation; the façade (no sloping roof caps the d	rtheast elevation	The dwelling is construc is faced with five-cours inted along the façade by	e, y a	
rowhouse is one of fi brick and is set on a American-bond brick projecting molded co	ive similar rowhouses consolid, raised concrete fount that has been painted. A sonice with dentil molding.	structed from the same adation; the façade (no sloping roof caps the d The foundation is pier	ortheast elevation welling and is fro ced by a single-le	The dwelling is construc) is faced with five-cours onted along the façade by eaf door and 6/6, double-	e, y a hung,	
rowhouse is one of fi brick and is set on a American-bond brick projecting molded co wood-sash windows.	ive similar rowhouses consolid, raised concrete fount that has been painted. A sornice with dentil molding. The northwestern bay of the sornice with dentil molding.	structed from the same dation; the façade (no sloping roof caps the d The foundation is pier the first story holds a s	ortheast elevation lwelling and is fro ced by a single-le single-leaf panele	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, double- d wood door and a blind	e, y a hung, transom.	
rowhouse is one of fi brick and is set on a American-bond brick projecting molded co wood-sash windows. A concrete lintel high	ive similar rowhouses consolid, raised concrete fount that has been painted. A sonice with dentil molding.	structed from the same dation; the façade (no sloping roof caps the d The foundation is pier the first story holds a s iginal one-story, full-w	ortheast elevation lwelling and is fro ced by a single-le single-leaf panele idth porch has be	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blinden removed from the face	e, y a hung, transom. çade.	
rowhouse is one of fi brick and is set on a American-bond brick projecting molded co wood-sash windows. A concrete lintel high Metal steps with met openings on the first	ive similar rowhouses consolid, raised concrete fount that has been painted. A sornice with dentil molding. The northwestern bay of the lights the opening. The oral balusters, set on a solid and second stories of the	structed from the same dation; the façade (no sloping roof caps the d The foundation is pier the first story holds a s iginal one-story, full-w brick foundation, prov façade hold 6/9, double	ortheast elevation lwelling and is from the ling and is from the ling and is from the ling and l	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blind are removed from the face door opening. All windows and have co	y a hung, transom. çade.	
rowhouse is one of fi brick and is set on a American-bond brick projecting molded co wood-sash windows. A concrete lintel high Metal steps with met openings on the first	ive similar rowhouses consolid, raised concrete fount that has been painted. A sornice with dentil molding. The northwestern bay of talights the opening. The oral balusters, set on a solid	structed from the same dation; the façade (no sloping roof caps the d The foundation is pier the first story holds a s iginal one-story, full-w brick foundation, prov façade hold 6/9, double	ortheast elevation lwelling and is from the ling and is from the ling and is from the ling and l	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blind are removed from the face door opening. All windows and have co	y a hung, transom. çade.	
rowhouse is one of fi brick and is set on a American-bond brick projecting molded co wood-sash windows. A concrete lintel high Metal steps with met openings on the first	ive similar rowhouses consolid, raised concrete fount that has been painted. A sornice with dentil molding. The northwestern bay of the lights the opening. The oral balusters, set on a solid and second stories of the	structed from the same dation; the façade (no sloping roof caps the d The foundation is pier the first story holds a s iginal one-story, full-w brick foundation, prov façade hold 6/9, double	ortheast elevation lwelling and is from the ling and is from the ling and is from the ling and l	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blind are removed from the face door opening. All windows and have co	y a hung, transom. çade.	
rowhouse is one of fi brick and is set on a American-bond brick projecting molded co wood-sash windows. A concrete lintel high Metal steps with met openings on the first sills and lintels. The Site Notes: September 2008: This	ive similar rowhouses consolid, raised concrete found that has been painted. A sometime with dentil molding. The northwestern bay of the lights the opening. The oral balusters, set on a solid and second stories of the rear (southwest) elevation is two-story rowhouse is located.	structed from the same dation; the façade (no sloping roof caps the d The foundation is pier the first story holds a s iginal one-story, full-w brick foundation, prov façade hold 6/9, double was not surveyed or p	ortheast elevation lwelling and is from the ling and is from the ling and is from the level by the ling and the line and t	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blind the removed from the fact door opening. All windows and have come volunteer surveyor.	y a hung, transom. çade. ow oncrete	
rowhouse is one of fi brick and is set on a American-bond brick projecting molded co wood-sash windows. A concrete lintel high Metal steps with met openings on the first sills and lintels. The Site Notes: September 2008: This approximately five fe	ive similar rowhouses consolid, raised concrete found that has been painted. A sometime with dentil molding. The northwestern bay of the lights the opening. The oral balusters, set on a solid and second stories of the rear (southwest) elevation as two-story rowhouse is lose to from the concrete sidew	structed from the same dation; the façade (no sloping roof caps the d The foundation is pier the first story holds a s iginal one-story, full-w brick foundation, prov façade hold 6/9, double was not surveyed or p cated on the southwes ralk. The dwelling is ac	ortheast elevation lwelling and is from the ling and is from the ling and is from the level by the ling and the line and t	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blind the removed from the fact door opening. All windows and have contained the volunteer surveyor. I wania Avenue, S.E. and in the door opening the volunteer surveyor.	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	
rowhouse is one of fi brick and is set on a American-bond brick projecting molded co wood-sash windows. A concrete lintel high Metal steps with met openings on the first sills and lintels. The Site Notes: September 2008: This approximately five fe The grassy front yard	ive similar rowhouses consolid, raised concrete found that has been painted. A sometime with dentil molding. The northwestern bay of the lights the opening. The oral balusters, set on a solid and second stories of the rear (southwest) elevation is two-story rowhouse is located.	structed from the same dation; the façade (no sloping roof caps the dation is pier the first story holds a siginal one-story, full-w brick foundation, proving façade hold 6/9, double was not surveyed or procated on the southwestalk. The dwelling is accommand.	ortheast elevation lwelling and is from the ling and is from the ling and is from the level by the ling and the line and t	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blind the removed from the fact door opening. All windows and have contained the volunteer surveyor. I wania Avenue, S.E. and in the door opening the volunteer surveyor.	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	
rowhouse is one of fi brick and is set on a American-bond brick projecting molded co wood-sash windows. A concrete lintel high Metal steps with met openings on the first sills and lintels. The Site Notes: September 2008: This approximately five fe The grassy front yard	ive similar rowhouses consolid, raised concrete found that has been painted. A some with dentil molding. The northwestern bay of the lights the opening. The oral balusters, set on a solid and second stories of the rear (southwest) elevation as two-story rowhouse is located from the concrete sidew is landscaped with a few	structed from the same dation; the façade (no sloping roof caps the dation is pier the first story holds a siginal one-story, full-w brick foundation, proving façade hold 6/9, double was not surveyed or procated on the southwestalk. The dwelling is accommand.	ortheast elevation lwelling and is from the ling and is from the ling and is from the level by the ling and the line and t	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blind the removed from the fact door opening. All windows and have contained the volunteer surveyor. I wania Avenue, S.E. and in the door opening the volunteer surveyor.	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	
rowhouse is one of fi brick and is set on a American-bond brick projecting molded co wood-sash windows. A concrete lintel high Metal steps with met openings on the first sills and lintels. The Site Notes: September 2008: This approximately five fe The grassy front yard	ive similar rowhouses consolid, raised concrete found that has been painted. A sornice with dentil molding. The northwestern bay of the thights the opening. The oral balusters, set on a solid and second stories of the rear (southwest) elevation as two-story rowhouse is love the from the concrete sidew is landscaped with a few y is located southwest of the solid southwest of the solid sol	structed from the same dation; the façade (no sloping roof caps the dation is pier the first story holds a siginal one-story, full-w brick foundation, proving façade hold 6/9, double was not surveyed or procated on the southwestalk. The dwelling is accommand.	ortheast elevation lwelling and is from the ling and is from the ling and is from the level by the ling and the line and t	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blind the removed from the fact door opening. All windows and have contained the volunteer surveyor. I wania Avenue, S.E. and in the door opening the volunteer surveyor.	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	
rowhouse is one of fibrick and is set on a American-bond brick projecting molded cowood-sash windows. A concrete lintel high Metal steps with met openings on the first sills and lintels. The Site Notes: September 2008: This approximately five fe The grassy front yard the sidewalk. An allegent and intelled the sidewalk. An allegent process of the sidewalk.	ive similar rowhouses consolid, raised concrete found that has been painted. A somice with dentil molding. The northwestern bay of tablights the opening. The oral balusters, set on a solid and second stories of the rear (southwest) elevation as two-story rowhouse is lovet from the concrete sidew it is landscaped with a few y is located southwest of the RES DATA	structed from the same dation; the façade (no sloping roof caps the dation is pier the first story holds a siginal one-story, full-w brick foundation, proving façade hold 6/9, double was not surveyed or procated on the southwestalk. The dwelling is accommand.	ortheast elevation lwelling and is from the ling and is from the ling and is from the level by the ling and the line and t	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blind the removed from the fact door opening. All windows and have contained the volunteer surveyor. I wania Avenue, S.E. and in the door opening the volunteer surveyor.	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	
rowhouse is one of fibrick and is set on a American-bond brick projecting molded cowood-sash windows. A concrete lintel high Metal steps with met openings on the first sills and lintels. The Site Notes: September 2008: This approximately five fe The grassy front yard the sidewalk. An allegation and since the sidewalk. An allegation is set on a set of the sidewalk.	ive similar rowhouses consolid, raised concrete found that has been painted. A sornice with dentil molding. The northwestern bay of the thights the opening. The oral balusters, set on a solid and second stories of the rear (southwest) elevation as two-story rowhouse is love the from the concrete sidew is landscaped with a few y is located southwest of the solid southwest of the solid sol	structed from the same dation; the façade (no sloping roof caps the dation is pier the first story holds a siginal one-story, full-w brick foundation, proving façade hold 6/9, double was not surveyed or procated on the southwestalk. The dwelling is accommand to the southwestalk.	ortheast elevation lwelling and is from the ling and is from the ling and is from the level by the ling and the line and t	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blind the removed from the fact door opening. All windows and have contained the volunteer surveyor. I wania Avenue, S.E. and in the door opening the volunteer surveyor.	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	
rowhouse is one of fibrick and is set on a American-bond brick projecting molded cowood-sash windows. A concrete lintel high Metal steps with met openings on the first sills and lintels. The Site Notes: September 2008: This approximately five fe The grassy front yard the sidewalk. An allegent and intelled the sidewalk. An allegent process of the sidewalk.	ive similar rowhouses consolid, raised concrete found that has been painted. A somice with dentil molding. The northwestern bay of tablights the opening. The oral balusters, set on a solid and second stories of the rear (southwest) elevation as two-story rowhouse is lovet from the concrete sidew it is landscaped with a few y is located southwest of the RES DATA	structed from the same dation; the façade (no sloping roof caps the dation is pier the first story holds a siginal one-story, full-w brick foundation, proving façade hold 6/9, double was not surveyed or procated on the southwestalk. The dwelling is accommand to the southwestalk.	ortheast elevation lwelling and is from the ling and is from the ling and is from the level by the ling and the line and t	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blind the removed from the fact door opening. All windows and have contained the volunteer surveyor. I wania Avenue, S.E. and in the door opening the volunteer surveyor.	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	
rowhouse is one of fibrick and is set on a American-bond brick projecting molded cowood-sash windows. A concrete lintel high Metal steps with met openings on the first sills and lintels. The Site Notes: September 2008: This approximately five fe The grassy front yard the sidewalk. An allegation of the proposed of the sidewalk of th	ive similar rowhouses consolid, raised concrete four that has been painted. A sornice with dentil molding. The northwestern bay of talights the opening. The oral balusters, set on a solid and second stories of the rear (southwest) elevation as two-story rowhouse is lovet from the concrete sidew is landscaped with a few y is located southwest of the RES DATA	structed from the same dation; the façade (no sloping roof caps the dation is pier the first story holds a siginal one-story, full-w brick foundation, proving façade hold 6/9, double was not surveyed or procated on the southwestalk. The dwelling is accommand to the southwestalk.	ortheast elevation lwelling and is from the ling and is from the ling and is from the level by the ling and the line and t	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blind the removed from the fact door opening. All windows and have contained the volunteer surveyor. I wania Avenue, S.E. and in the door opening the volunteer surveyor.	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	
rowhouse is one of fibrick and is set on a American-bond brick projecting molded cowood-sash windows. A concrete lintel high Metal steps with met openings on the first sills and lintels. The Site Notes: September 2008: This approximately five fe The grassy front yard the sidewalk. An allegent and intelled the sidewalk. An allegent process of the sidewalk.	ive similar rowhouses consolid, raised concrete four that has been painted. A sornice with dentil molding. The northwestern bay of talights the opening. The oral balusters, set on a solid and second stories of the rear (southwest) elevation as two-story rowhouse is lovet from the concrete sidew is landscaped with a few y is located southwest of the RES DATA	structed from the same dation; the façade (no sloping roof caps the dation is pier the first story holds a siginal one-story, full-w brick foundation, proving façade hold 6/9, double was not surveyed or procated on the southwestalk. The dwelling is accommand to the southwestalk.	ortheast elevation lwelling and is from the ling and is from the ling and is from the level by the ling and the line and t	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blind the removed from the fact door opening. All windows and have contained the volunteer surveyor. I wania Avenue, S.E. and in the door opening the volunteer surveyor.	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	
rowhouse is one of fibrick and is set on a American-bond brick projecting molded cowood-sash windows. A concrete lintel high Metal steps with met openings on the first sills and lintels. The Site Notes: September 2008: This approximately five fe The grassy front yard the sidewalk. An allegation of the proposed of the sidewalk of th	ive similar rowhouses consolid, raised concrete four that has been painted. A sornice with dentil molding. The northwestern bay of talights the opening. The oral balusters, set on a solid and second stories of the rear (southwest) elevation as two-story rowhouse is lovet from the concrete sidew is landscaped with a few y is located southwest of the RES DATA	structed from the same dation; the façade (no sloping roof caps the dation is pier the first story holds a siginal one-story, full-w brick foundation, proving façade hold 6/9, double was not surveyed or procated on the southwestalk. The dwelling is accommand to the southwestalk.	ortheast elevation lwelling and is from the ling and is from the ling and is from the level by the ling and the line and t	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blind the removed from the fact door opening. All windows and have contained the volunteer surveyor. I wania Avenue, S.E. and in the door opening the volunteer surveyor.	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	
rowhouse is one of fibrick and is set on a American-bond brick projecting molded cowood-sash windows. A concrete lintel high Metal steps with met openings on the first sills and lintels. The Site Notes: September 2008: This approximately five fee The grassy front yard the sidewalk. An allegate NOTABLE FEATURE Component	ive similar rowhouses consolid, raised concrete four that has been painted. A sornice with dentil molding. The northwestern bay of tablights the opening. The oral balusters, set on a solid and second stories of the rear (southwest) elevation as two-story rowhouse is lovet from the concrete sidew is landscaped with a few y is located southwest of the RES DATA	structed from the same dation; the façade (no sloping roof caps the dation is pier the first story holds a siginal one-story, full-webrick foundation, proving a surveyed or proceed on the southwest ralk. The dwelling is act mature shrubs. A brick he dwelling.	ortheast elevation lwelling and is from the ling and is from the least panele idth porch has beyide access to the le-hung, wood-sathotographed by the ligate of Pennsyl ligacent to 1517 and walkway leads for the least side of Pennsyl ligacent to 1517 and walkway leads for light panels in ligate in light panels in ligh	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blind sen removed from the face door opening. All windows and have control to the volunteer surveyor. I wania Avenue, S.E. and it is described a door opening and have control to the volunteer surveyor.	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	
rowhouse is one of fibrick and is set on a American-bond brick projecting molded cowood-sash windows. A concrete lintel high Metal steps with metopenings on the first sills and lintels. The Site Notes: September 2008: This approximately five fee The grassy front yard the sidewalk. An allegate NOTABLE FEATURE Component EXTERIOR MATER Roof Component Sloped	ive similar rowhouses consolid, raised concrete found that has been painted. A sornice with dentil molding. The northwestern bay of the fights the opening. The orial balusters, set on a solid and second stories of the rear (southwest) elevation is two-story rowhouse is located from the concrete sidew is landscaped with a few y is located southwest of the RES DATA Material Not Visible	structed from the same dation; the façade (no sloping roof caps the dation is pier the first story holds a siginal one-story, full-webrick foundation, proving façade hold 6/9, double was not surveyed or procated on the southwest ralk. The dwelling is act mature shrubs. A brick he dwelling.	ortheast elevation lwelling and is from the ling and is from the ling and is from the level of the ling and is from the level of the ling and the line and the ling and the line and the line and the ling and the line and the li	The dwelling is construct is faced with five-cours is faced with five-cours inted along the façade by ital door and 6/6, double- d wood door and a blind iten removed from the face door opening. All windows windows and have con the volunteer surveyor. I wania Avenue, S.E. and it d 1521 Pennsylvania Averom the primary stairs and something of the primary stairs and its source	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	
rowhouse is one of fibrick and is set on a American-bond brick projecting molded cowood-sash windows. A concrete lintel high Metal steps with met openings on the first sills and lintels. The Site Notes: September 2008: This approximately five fee The grassy front yard the sidewalk. An allest NOTABLE FEATURE Component EXTERIOR MATER Roof Component Sloped Wall Component	ive similar rowhouses consolid, raised concrete found that has been painted. A sornice with dentil molding. The northwestern bay of the solid that has been painted. A sornice with dentil molding. The northwestern bay of the solid that has been painted. The oral balusters, set on a solid and second stories of the rear (southwest) elevation as two-story rowhouse is loved its landscaped with a few by its located southwest of the second southwest of the solid landscaped with a few by its located southwest of the second southwest of the second solid landscaped with a few by its located southwest of the second solid landscaped with a few by its located southwest of the second solid landscaped with a few by its located southwest of the second solid landscaped with a few by its located southwest of the second solid landscaped with a few by its located southwest of the second solid landscaped with a few by its located solid	structed from the same dation; the façade (no sloping roof caps the dation is pier the first story holds a siginal one-story, full-webrick foundation, proving a surveyed or proceed on the southwest ralk. The dwelling is act mature shrubs. A brick he dwelling.	ortheast elevation lwelling and is from the ling and is from the ling and is from the level by a single-leaf panele idth porch has be levide access to the level by the level	The dwelling is construct is faced with five-cours inted along the façade by af door and 6/6, doubled wood door and a blind sen removed from the face door opening. All windows and have control to the volunteer surveyor. I wania Avenue, S.E. and it is different along the primary stairs and the primary stairs and the control to the primary stairs and the primary sta	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	
rowhouse is one of fibrick and is set on a American-bond brick projecting molded cowood-sash windows. A concrete lintel high Metal steps with metopenings on the first sills and lintels. The Site Notes: September 2008: This approximately five fee The grassy front yard the sidewalk. An allegate NOTABLE FEATURE Component EXTERIOR MATER Roof Component Sloped	ive similar rowhouses consolid, raised concrete found that has been painted. A sornice with dentil molding. The northwestern bay of the fights the opening. The orial balusters, set on a solid and second stories of the rear (southwest) elevation is two-story rowhouse is located from the concrete sidew is landscaped with a few y is located southwest of the RES DATA Material Not Visible	structed from the same dation; the façade (no sloping roof caps the dation is pier the first story holds a siginal one-story, full-webrick foundation, proving façade hold 6/9, double was not surveyed or procated on the southwest ralk. The dwelling is act mature shrubs. A brick he dwelling.	ortheast elevation lwelling and is from the ling and is from the ling and is from the level of the ling and is from the level of the ling and the line and the ling and the line and the line and the ling and the line and the li	The dwelling is construct is faced with five-cours is faced with five-cours inted along the façade by ital door and 6/6, double- d wood door and a blind iten removed from the face door opening. All windows windows and have con the volunteer surveyor. I wania Avenue, S.E. and it d 1521 Pennsylvania Averom the primary stairs and something of the primary stairs and its source	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	
rowhouse is one of fibrick and is set on a American-bond brick projecting molded cowood-sash windows. A concrete lintel high Metal steps with met openings on the first sills and lintels. The Site Notes: September 2008: This approximately five fee The grassy front yard the sidewalk. An allest NOTABLE FEATURE Component EXTERIOR MATER Roof Component Sloped Wall Component	ive similar rowhouses consolid, raised concrete found that has been painted. A sornice with dentil molding. The northwestern bay of the solid that has been painted. A sornice with dentil molding. The northwestern bay of the solid that has been painted. The oral balusters, set on a solid and second stories of the rear (southwest) elevation as two-story rowhouse is loved its landscaped with a few by its located southwest of the second southwest of the solid landscaped with a few by its located southwest of the second southwest of the second solid landscaped with a few by its located southwest of the second solid landscaped with a few by its located southwest of the second solid landscaped with a few by its located southwest of the second solid landscaped with a few by its located southwest of the second solid landscaped with a few by its located southwest of the second solid landscaped with a few by its located solid	structed from the same dation; the façade (no sloping roof caps the dation is pier the first story holds a siginal one-story, full-webrick foundation, proving façade hold 6/9, double was not surveyed or procated on the southwest ralk. The dwelling is act mature shrubs. A brick he dwelling.	ortheast elevation lwelling and is from the ling and is from the ling and is from the level by a single-leaf panele idth porch has be levide access to the level by the level	The dwelling is construct is faced with five-cours is faced with five-cours inted along the façade by ital door and 6/6, double- d wood door and a blind iten removed from the face door opening. All windows windows and have con the volunteer surveyor. I wania Avenue, S.E. and it d 1521 Pennsylvania Averom the primary stairs and something of the primary stairs and its source	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	
rowhouse is one of fibrick and is set on a American-bond brick projecting molded cowood-sash windows. A concrete lintel high Metal steps with metopenings on the first sills and lintels. The Site Notes: September 2008: This approximately five fee The grassy front yard the sidewalk. An allegate NOTABLE FEATURE Component EXTERIOR MATER Roof Component Sloped Wall Component	ive similar rowhouses consolid, raised concrete found that has been painted. A sornice with dentil molding. The northwestern bay of the fights the opening. The orial balusters, set on a solid and second stories of the rear (southwest) elevation is two-story rowhouse is located from the concrete sidew is landscaped with a few yis located southwest of the rear (southwest). Feature IALS DATA Material Not Visible Material Brick	structed from the same dation; the façade (no sloping roof caps the dation is pier the first story holds a siginal one-story, full-webrick foundation, proving façade hold 6/9, double was not surveyed or proceed on the southwest ralk. The dwelling is act mature shrubs. A brick he dwelling. Color	ortheast elevation lwelling and is from the ling and is from the ling and is from the level by a single-leaf panele idth porch has be levide access to the level by the level	The dwelling is construct is faced with five-cours is faced with five-cours inted along the façade by ital door and 6/6, double- d wood door and a blind iten removed from the face door opening. All windows and have con he volunteer surveyor. I vania Avenue, S.E. and it id 1521 Pennsylvania Averom the primary stairs and Source Source	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	
rowhouse is one of fibrick and is set on a American-bond brick projecting molded cowood-sash windows. A concrete lintel high Metal steps with metopenings on the first sills and lintels. The Site Notes: September 2008: This approximately five fe The grassy front yard the sidewalk. An alley NOTABLE FEATURE Component EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component	ive similar rowhouses consolid, raised concrete found that has been painted. A sornice with dentil molding. The northwestern bay of the lights the opening. The oral balusters, set on a solid and second stories of the rear (southwest) elevation is two-story rowhouse is located from the concrete sidew is landscaped with a few by is located southwest of the rear (southwest) elevation. RES DATA Material Not Visible Material Brick Material Brick Material	structed from the same dation; the façade (no sloping roof caps the dation is pier the first story holds a siginal one-story, full-webrick foundation, proving façade hold 6/9, double was not surveyed or proceed on the southwest ralk. The dwelling is act mature shrubs. A brick he dwelling. Color	ortheast elevation lwelling and is from the ling and is from the ling and is from the level by a single-leaf panele idth porch has be levide access to the level by the level	The dwelling is construct is faced with five-cours is faced with five-cours inted along the façade by ital door and 6/6, double- d wood door and a blind iten removed from the face door opening. All windows and have con he volunteer surveyor. I vania Avenue, S.E. and it id 1521 Pennsylvania Averom the primary stairs and Source Source	se, y a hung, transom. çade. ow oncrete s set back enue, S.E.	

Window Location	Aperture Shape	Туре	Lights	Materia	I
Basemt Windows	Rectangular	Dbl-Hung	6/6	Wood	·
Facade	Rectangular	Dbl-Hung	6/9	Wood	
Door Location	Aperture Shape	Туре	Pamels	Materia	I
Basement	Rectangular	Single		Unkno	wn
Main Door	Rectangular	Single	Paneled	Wood	
Notable Interior Plan	(s)		Notable Interior Feature(s))	
Interior Notes:					
PLAN/SURVEY/D	ESIGNATION DATA				
Neighborhood: C Subdivision:	apitol Hill		Historic District(s)		
Ward/ANC:					
Zoning:			Designation Event(s)		
Contributing:					
Survey(s)			Level(s) of Investigation		
Capitol Hill Southea	ast Phase I (2009/2010)		Permit Research		
			Volunteer Reconnaissan	ice Survey	
PHOTOS - DIGITIZ	ZED				
Caption:					
Databases' St\Databas	HRS\Documents\CHRS \SE Phase I - D to G se\Pictures\Square 1078\				
File: 1519_PA_ A Date::	Photog:				
Code::	R:	Fr:			
PHOTOS - PAN O	R NON-DIGITIZED				
Photo Code	Roll Frame(s)	Date	Photographer	Caption	
	110110(5)	Date	Ποιοβιαρίιοι	Сарион	
MISCELLANEOUS	S NOTES DATA				
Notes:					
PERMIT DATA					
Permit Issue Date	Number Type		Remarks		
02/20/1913	3839 Build	I			
02/20/1913 Permit Notes:					

BIBLIOG	GRAPHIC DATA			
SIGNIFIC	CANCE DATA			
Study Unit	t			
Code	Criteria			
DATA PF	ROCESSING EVENTS DATA			

ID_Number: 1078-0038 Page 4

ID Number: 1078-0037

ID_Number: 1078-0037 Page 1

BASICS DATA

ID Number: 1078-0037 Year Built: 1913 Data Source: Permit Quad Type of Address Number Extended Street 1517 Pennsylvania Avenue Current Name(s) Type of Name Rowhouse, 1517 Pennsylvania Avenue, S.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain 1078/0037 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Fair

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1913 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source	
Orig Construction	1913	Permit			1600 Permit	
Construction Event	Asso	ciation		Associated	Name	
Orig Construction	Archi	tect		Masson, S.	E.	
Orig Construction	Build	er		Boss, Willia	am A.	
Orig Construction	Owne	er		Boss, Willia	am A.	
Construction Notes:						
One of five rowhouses con	structed from	the same per	mit (#3839).			

PEOPLE/EVENTS DATA

Racial Segregation Status:

Surroundings: Streetscape:	Urban Intact	Cross Refe	rence Notes:		
Relate to Othr Bldgs:	Row (1 of 5)				
Relate to Street:	Front Yard w/ Setback				
Massing:	Row Building/Flat Front				
Footprint:	Rectangular				
Number Stories:	2 plus basement				
Bays Wide:	3	0 4 4 5 7			
Height:	4-	Outbuilding Type	Co	ontributing Status	
Width: Depth/Length:	17 32				
SqFt:	32				
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes:			
Lot SqFt:					
Acreage:					
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Italianate					
Exterior & Architectura	al Notes				
American-bond bricl projecting molded convood-sash windows rectangular wood transpersion wood from the factorian wood from the	solid, raised concrete fount that has been painted. A sornice with dentil molding. The northwestern bay of tansom. A concrete lintel hig çade. Metal steps with metal openings on the first and sills and lintels. The rear (so is two-story rowhouse is located for the concrete sidewals landscaped with mature.	loping roof caps the The foundation is pi he first story holds a hlights the opening al balusters, set on a second stories of the uthwest) elevation was cated on the southwalk. The dwelling is	dwelling and is from the control of	onted along the façade by a part door and 6/6, double-hu d wood door and a one-lightory, full-width porch has bution, provide access to the ouble-hung, wood-sash with photographed by the volutivania Avenue, S.E. and is and 1521 Pennsylvania Avenue.	ing, nt peen door ndows nteer set back ue, S.E.
dwelling.	is landscaped with mature	snrubs and foundat	ion piantings. An ai	liey is located southwest of	tne
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		American Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Basemt Windows	Rectangular	Dbl-Hung	6/6	Wood
Facade	Rectangular	Dbl-Hung	6/9	Wood
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single		Unknown
Main Door	Rectangular	Single	Paneled	Wood
Notable Interior Plan(s)			Notable Interior Feature(s)	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill
Subdivision:
Ward/ANC:
Zoning: Designation Event(s)

Contributing:

Survey(s) Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010) Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1078\

File: **1517_PA_AVSE.JPG**Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks
02/20/1913 3839 Build

12/20/1913 3039 Build

Permit Notes:

BIBLIOG	GRAPHIC DATA			
SIGNIFIC	CANCE DATA			
Study Unit	t			
Code	Criteria			

ID Number: 1078-0036

BASICS DATA

ID Number: 1078-0036 Year Built: 1913 Data Source: **Permit** Quad Type of Address Number Extended Street 1515 Current Pennsylvania Avenue Name(s) Type of Name Rowhouse, 1515 Pennsylvania Avenue, S.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain 1078/0036 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1913 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1913	Permit			1600 Permit
Construction Event	Association		Associated Name		
Orig Construction	Arch	Architect		Masson, S.E.	
Orig Construction	Builder		Boss, William A.		
Orig Construction	Owner		Boss, William A.		
Construction Notes:					
One of five rowhouses co	nstructed from	the same per	mit (#3839).		

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

ID_Number: 1078-0036 Page 1

Surroundings:	Urban	Cross Refe	rence Notes:		
Streetscape:	Intact				
Relate to Othr Bldgs: Relate to Street:	Row (1 of 3) Front Yard w/ Setback				
Massing:	Row Building/Flat Front				
Footprint:	Rectangular				
Number Stories:	2 plus basement				
Bays Wide:	3				
Height:	•	Outbuilding Type	Co	ontributing Status	
Width:	17				
Depth/Length:	32				
SqFt:					
Volume:					
Lot Width Lot Depth/Length:		Outbuilding Notes:			
Lot SqFt:		Outbuilding Notes.			
Acreage:					
Has Driveway:					
riao Biivoliay.					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Italianate					
Exterior & Architectura	al Notes:				
rowhouse is one of the brick and is set on a set		structed from the sa dation; the façade (loping roof caps the The foundation is p rowlock brick sills. ular wood transom. om the façade. Meta All window opening e concrete sills and veyor.	me permit (#3839). northeast elevation dwelling and is from the defect of the northwestern because the first and lintels. The rear (so the first and lintels. The rear (so the first side of Pennsyladjacent to 1513 ar	The dwelling is constructed is faced with five-course, onted along the façade by a part paneled wood door and pay of the first story holds a ghlights the opening. The consistency is second stories of the façad outhwest) elevation was not evania Avenue, S.E. and is second 1517 Pennsylvania Avenue.	6/6, single- priginal ck e hold set back ue, S.E.
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Flemish Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				
Materials Notes:					
					7

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
Basemt Windows	Rectangular	Dbl-Hung	6/6	Wood	
Facade	Rectangular	Dbl-Hung	6/9	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single	Paneled	Wood	
Main Door	Rectangular	Single	Paneled	Wood	
Notable Interior Plan(s)			Notable Interior Feature(s)		

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1078\

File: **1515_PA_AVSE.JPG**Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

02/20/1913 3839 Build

Permit Notes:

BIBLIOG	RAPHIC DATA			
SIGNIFIC	CANCE DATA			
Study Unit	t .			
Code	Criteria			
DATA PF	ROCESSING EVENTS DATA			

ID_Number: 1078-0036 Page 4

ID Number: 1078-0035

ID_Number: 1078-0035 Page 1

BASICS DATA

ID Number: 1078-0035 Year Built: 1913 Data Source: **Permit** Quad Type of Address Number Extended Street 1513 Current Pennsylvania Avenue Name(s) Type of Name Rowhouse, 1513 Pennsylvania Avenue, S.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain 1078/0035 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1913 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1913	Permit			1600 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Archi	itect		Masson, S	E.
Orig Construction	Build	ler		Boss, Willi	am A.
Orig Construction	Owne	er		Boss, Willi	am A.
Construction Notes:					
One of five rowhouses con	nstructed from	the same per	mit (#3839).		

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings:	Urban	Cross Refe	rence Notes:		
Streetscape: Relate to Othr Bldgs:	Intact				
Relate to Street:	Front Yard w/ Setback				
Massing:	Row Building/Flat Front				
Footprint:	Rectangular				
Number Stories:	2 plus basement				
Bays Wide:	3				
Height:		Outbuilding Type	C	ontributing Status	
Width:	17				
Depth/Length:	32				
SqFt: Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes:			
Lot SqFt:					
Acreage:					
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Italianate					
Exterior & Architectura	al Notes:				
projecting molded of wood-sash windows rectangular wood tra removed from the fa opening. All window	ornice with dentil molding. The northwestern bay of tansom. A concrete lintel hig çade. Metal steps with metal openings on the first and	The foundation is p the first story holds ghlights the opening al balusters, set on a second stories of the	ierced by a single-l a single-leaf panele I. The original one-s a solid brick founda e façade hold 6/9, d	onted along the façade by a eaf door and 6/6, double-hu ed wood door and a one-ligh story, full-width porch has b ation, provide access to the double-hung, wood-sash wir r photographed by the volu	een door ndows
Site Notes:					
approximately five fe	eet from the concrete sidew	alk. The dwelling is	adjacent to 1511 a	rivania Avenue, S.E. and is s nd 1515 Pennsylvania Avenu alley is located southwest o	ue, S.E.
NOTABLE FEATUR	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		American Bond		
Structure Component	NA=(!-1	Feature			
Foundation	Material	i cataro		Source	
Foundation	Concrete	reature		Source	
Walls		roduro		Source	
	Concrete	reature		Source	

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
Basemt Windows	Rectangular	Dbl-Hung	6/6	Wood	
Facade	Rectangular	Dbl-Hung	6/9	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single		Unknown	
Main Door	Rectangular	Single	Paneled	Wood	
Notable Interior Plan(s)			Notable Interior Feature(s)		

Interior Notes:

DI	A NI/QI	IDVEV	DEGICE	MATION	DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s) Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010) Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1078\

File: **1513_PA_AVSE.JPG**Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Notes:

Permit Issue Date Number Type Remarks
02/20/1913 3839 Build

Friday, August 30, 2013

BIBLIOG	RAPHIC DATA			
SIGNIFIC	CANCE DATA			
Study Unit	t .			
Code	Criteria			
DATA PF	ROCESSING EVENTS DATA			

ID Number: 1078-0034

ID_Number: 1078-0034 Page 1

BASICS DATA

ID Number: 1078-0034 Year Built: 1913 Data Source: Permit Quad Type of Address Number Extended Street 1511 Current Pennsylvania Avenue Name(s) Type of Name Rowhouse, 1511 Pennsylvania Avenue, S.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain 1078/0034 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1913 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1913	Permit			1600 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Archi	tect		Masson, S.	E.
Orig Construction	Build	er		Boss, Willia	am A.
Orig Construction	Own	er		Boss, Willia	am A.
Construction Notes:					
One of five rowhouses con	structed from	the same per	mit (#3839).		

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings:	Urban	Cross Refe	rence Notes:		
Streetscape:	Intact				
Relate to Othr Bldgs:	Row (1 of 5)				
Relate to Street:	Face on Setback Line				
Massing:	Row Building/Front Porch				
Footprint:	Rectangular				
Number Stories:	2 plus basement				
Bays Wide:	3				
Height:	J	Outbuilding Type	C	ontributing Status	
Width:	47	Outbuilding Type		ontributing Otatus	
Depth/Length:	17 32				
SqFt:	32				
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes:			
Lot SqFt:		Outbuilding Notes.			
Acreage:					
_					
Has Driveway:					
07/4 = (7)/7=5105					
Architectural Style(a)	DATA				
Architectural Style(s)					
Italianate					
Exterior & Architectura	al Notes:				
projecting molded or double-hung, vinyl-s one-light rectangula removed from the fa opening. All window	k that has been painted. A slornice with dentil molding. The ash windows. The northwes r wood transom. A concrete çade. Metal steps with meta openings on the first and sills and lintels. The rear (sou	The foundation is p stern bay of the firs lintel highlights the I balusters, set on a econd stories of the	ierced by a single-l t story holds a sing e opening. The orig a solid brick founda e façade hold 1/1, d	eaf paneled wood door and gle-leaf paneled wood door a ginal one-story porch has be ation, provide access to the double-hung, vinyl-sash win	1/1, and a een door dows
Site Notes:					
approximately five fe	is two-story rowhouse is loc eet from the concrete sidewa is landscaped with mature s	alk. The dwelling is	adjacent to 1509 a	nd 1513 Pennsylvania Aven	ue, S.E.
NOTABLE FEATUR	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		American Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				_
Walls					
	Brick				
Materials Notes:	Brick				

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
Basemt Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Facade	Rectangular	Dbl-Hung	1/1	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single	Paneled	Wood	
Main Door	Rectangular	Single	Paneled	Wood	
Notable Interior Plan(s)			Notable Interior Feature(s)		

Interior Notes:

DI	A NI/QI	IDVEV	DEGICE	MATION	DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation
Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1078\

File: **1511_PA_AVSE.JPG**Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks
02/20/1913 3839 Build

12/20/1913 3039 Build

Permit Notes:

ID_Number: 1078-0034 Page 3

BIBLIOG	RAPHIC DATA			
SIGNIFIC	CANCE DATA			
Study Unit	t .			
Code	Criteria			
DATA PF	ROCESSING EVENTS DATA			

ID_Number: 1078-0034 Page 4

ID Number: 1078-0804

BASICS DATA

ID Number: 1078-0804 Year Built: 1909 Data Source: Permit Number Extended Street Quad Type of Address 1509 Current Pennsylvania Avenue Type of Name Name(s) Rowhouse, 1509 Pennsylvania Avenue, S.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain 1078/0804 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Fair

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1909 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1909	Permit			1500 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Arch	itect		Beers, A. H	
Orig Construction	Build	der		Hight, C.B.	
Orig Construction	Own	er		Hight, C.B.	

Construction Notes:

Originally one of four rowhouses constructed from the same permit (#3025). 1503 Pennsylvania Avenue, S.E. has been replaced by a 1948 building.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

ID_Number: 1078-0804 Page 1

		Cross Refe			
Streetscape:	Intact				
Relate to Othr Bldgs:	Row (1 of 3)				
Relate to Street:	Face on Setback Line				
Massing:	Row Building/Flat Front				
Footprint:	Rectangular				
Number Stories:	2 plus basement				
Bays Wide:	3				
Height:	•	Outbuilding Type	Co	ntributing Status	
Width:	20	Outballaing Type		Titibuting Otatus	
Depth/Length:	20 28				
SqFt:	20				
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes:			
Lot SqFt:		Outbuilding Notes.			
Acreage:					
_					
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)	DATA				
Italianate					
Exterior & Architectura	Il Notes:				
		Unit di la torra atama	41	style single-family rowhou	
foundation consists paneled wood door a with metal balusters façade. All window o	nd a one-light rectangular provide access to the prim penings on the first and se	sash windows. The wood transom. A co ary entrance. The o econd stories hold 6	southeastern bay of oncrete jack arch hig riginal one-story por /9, double-hung, wo	tional renestration of the first story holds a sing hillights the opening. Metal ch has been removed from od-sash windows and have tographed by the volunteer	steps the
Site Notes:					
	s two-story rowhouse is lo	cated on the southw	est side of Pennsylv	vania Avenue, S.E. and is s	et back
approximately five fe foundation plantings	et from the concrete sidew and is bounded by a mille	alk. The small front d point metal fence.	yard is landscaped	with mature shrubs and	
NOTABLE FEATUR	RES DATA				
Component					
	Feature				
EXTERIOR MATER	Feature				
EXTERIOR MATER	Feature	Color	Treatment	Source	
	Feature	Color	Treatment Not Visible	Source	
Roof Component	Feature IALS DATA Material	Color		Source Source	
Roof Component Sloped	Feature IALS DATA Material Not Visible		Not Visible		
Roof Component Sloped Wall Component	IALS DATA Material Not Visible Material		Not Visible Treatment		
Roof Component Sloped Wall Component Facade	Feature IALS DATA Material Not Visible Material Brick	Color	Not Visible Treatment	Source	
Roof Component Sloped Wall Component Facade Structure Component	IALS DATA Material Not Visible Material Brick Material	Color	Not Visible Treatment	Source	
Roof Component Sloped Wall Component Facade Structure Component Foundation	Feature IALS DATA Material Not Visible Material Brick Material Concrete	Color	Not Visible Treatment	Source	

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
Basemt Windows	Rectangular	Dbl-Hung	6/6	Wood	
Facade	Rectangular	Dbl-Hung	6/6 Double	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single	Paneled	Wood	
Main Door	Rectangular	Single	Paneled	Wood	
Notable Interior Plan((s)		Notable Interior Feature(s)		

Interior Notes:

DI	A NI/	CHID	/EV/F	PECICN	ATION	I DATA
гь	.MIN/s	JUN	V I I / L		AIIOI	4 DAIA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Permit Research

Capitol Hill Southeast Phase I (2009/2010)

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1078\

File: **1509_PA_AVSE.JPG**Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks
02/18/1909 3025 Build

Permit Notes:

BIBLIOG	RAPHIC DATA			
SIGNIFIC	CANCE DATA			
Study Unit	t .			
Code	Criteria			
DATA PF	ROCESSING EVENTS DATA			

ID_Number: 1078-0804 Page 4

ID Number: 1078-0021

BASICS DATA

ID Number: 1078-0021 Year Built: 1909 Data Source: Permit Number Extended Street Quad Type of Address 1507 Current Pennsylvania Avenue Type of Name Name(s) Rowhouse, 1507 Pennsylvania Avenue, S.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain 1078/0021 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1909 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1909	Permit			1500 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Arch	itect		Beers, A. H	l.
Orig Construction	Build	ler		Hight, C.B.	i
Orig Construction	Own	er		Hight, C.B.	
Construction Notes:					

Originally one of four rowhouses constructed from the same permit (#3025). 1503 Pennsylvania Avenue, S.E. has been replaced by a 1948 building.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

ID_Number: 1078-0021 Page 1

Surroundings: Streetscape:	Urban Intact	Cross Refere	ence Notes:]
	Row (1 of 3)				
Relate to Street:	Face on Setback Line				
Massing:	Row Building/Front Porch				
Footprint:	Rectangular				
Number Stories:	2 plus basement				
Bays Wide:	3	Outle did no Tomo	0 1 -	the of any Otation	
Height: Width:	20	Outbuilding Type	Contr	ibuting Status	
Depth/Length:	20 28				
SqFt:	20				
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes:			1
Lot SqFt:					
Acreage:					
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Italianate					
Exterior & Architectura	al Notes: s two-story rowhouse is loc				
The small front yard steps provide access	et from the concrete sidewa is landscaped with mature s to the primary entrance of	plantings and is bou			
Site Notes:					
one of originally four Pennsylvania Avenu- on a solid concrete f dwelling and is front foundation is pierced the first story holds a highlights the openii concrete sills and jac brick pier foundation porch and is suppor- accessed by poured	nstructed in 1909 by C.B. His similar rowhouses construe, S.E. was replaced by an a coundation; the façade (northed along the façade by a product by a single-leaf paneled word as single-leaf paneled words. All window openings on that has been infilled with ted by brick posts set on the concrete steps with brick with photographed by the voluntary.	acted from the same apartment/store in 19 heast elevation) is clojecting molded corroad door and is topp door and a one-light the façade hold 1/1, bay porch shelters the concrete blocks. A he brick piers. Square ving walls in the sout	permit (#3025). The d 48. The dwelling is co ad with aluminum sic nice with modillions. I bed by a concrete jack rectangular wood tra double-hung, vinyl-s he primary entrance a alf-hipped roof with o wood balusters enci	welling addressed as 15 constructed of brick and ding. A sloping roof cap The northwestern bay ok arch. The southeastern som. A concrete jack a ash windows and have and central bay and is so overhanging eaves shell rcle the porch, which is	is set s the f the n bay of arch et on a ters the
NOTABLE FEATUR	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Aluminum		Siding (Aluminum)		
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
Facade	Rectangular	Dbl-Hung	1/1	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single	Paneled	Wood	
Main Door	Rectangular	Single	Paneled	Wood	
Notable Interior Plar	n(s)		Notable Interior Feature(s)		

Interior Notes:

DI.	A NI/QII	DVEV	DESIG	NI A TIC	ם ואכ	$\Lambda T \Lambda$

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Level(s) of Investigation

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1078\

File: **1507_PA_AVSE.JPG**Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks
02/18/1909 3025 Build

Permit Notes:

BIBLIOG	BRAPHIC DATA			
SIGNIFIC	CANCE DATA			
Study Unit	t			
Code	Criteria			
DATA PF	ROCESSING EVENTS DATA			

ID_Number: 1078-0021 Page 4

ID Number: 1078-0020

BASICS DATA

ID Number: 1078	3-0020	Year B	uilt: 1909	Data	Source: F	Permit		
Number Extended	Street			Quad T	ype of Addre	SS		
1505	Pennsylvan	ia Avenue			Current			
Name(s)			Type	of Name				
Rowhouse, 1505 Per	nnsylvania Av	enue, S.E.	Com					
			- Frank	a in				
TaxCode1 TaxCode 1078/0020	2 TaxCode3	Type Square/L	ot Curr					
1070/0020		Oqualc/L	ot oun	CIT				
STATUS/PURPOS	E/USE DATA	\						
Resource Type: Bui		<u> </u>	St	atus Curre	nt: Extant			
	toric			uality:	=xtant			
Purpose: Rov	vhouse		Co	ondition:	Good			
Function/Use		Start	Source	Stop	Sou	urce	Explain	
Residential (Single-I	Family)	1909	Permit	Stop	300	JIC C	Historic/Current	
Residential (Single)	unny,	1505	Cillin				motorio/ our cit	
CONSTRUCTION	DATA							
Construction Event		tart S	Source	Stop	Source		Cost Source	
Orig Construction			Permit				1500 Permit	
Construction Event		Association	nn .		Associa	ated Na	me	
Orig Construction		Architect			Beers,			
Orig Construction		Builder			Hight,			
Orig Construction		Owner			Hight,	C.B.		
Construction Notes:								
			d from the s	ame perm	it (#3025). 15	503 Pen	nnsylvania Avenue, S.E. has	
been replaced by a 1	1948 building.							
DEODI E/EVENTO	DATA							
PEOPLE/EVENTS								
Racial Segregation St	tatus:							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban			Cross Ref	erence Notes	:		
Streetscape:	Intact							
Relate to Othr Bldgs:	,							
Relate to Street:	Face on Sett							
Massing:	Row Building Rectangular	_	t					
Footprint:	-							
Number Stories:	-	asement						
Bays Wide: Height:	3		Outhuile	ling Type		0	Contributing Status	
Width:	20		Outbuild	ing Type			John Duling Status	-
Depth/Length:	28							
SqFt:								
Volume:								
Lot Width			.	Para All I				
Lot Depth/Length: Lot SqFt:			Outbuild	ling Notes:				
Acreage:								
Has Driveway:	1							

Architectural Style(s)	1				
Italianate (Altered/C	Colonial Revival)				
Exterior & Architectu	ral Notes:				
one of originally for Pennsylvania Aventon a solid concrete the dwelling and is first story holds a scomposed of fluted pediment. Brick step been removed from windows and have elevation was not step.	onstructed in 1909 by Cur similar rowhouses coue, S.E. was replaced by foundation; the façade fronted along the façadingle-leaf door. The original pilasters and a broken by with metal balusters the façade. All window concrete sills and jack aurveyed or photographonis two-story rowhouse	enstructed from the say an apartment/store in (northeast elevation) is the by a projecting mologinal transom has been pediment. The original provide access to the openings on the first arches, as well as inoped by the volunteer su	me permit (#3025). The 1948. The dwelling is faced with Flemishled cornice with modin covered by a Colonial concrete jack arch is primary entrance. The and second stories he perable decorative me rveyor.	e dwelling address constructed of bond brick. A sle lions. The south al Revival-style os still visible behe original one-stold 6/6, double-htal shutters. The	essed as 1503 brick and is set oping roof caps heastern bay of the door surround hind the broken ory porch has hung, wood-sash rear (southwest)
approximately five	feet from the concrete s	idewalk. The dwelling	is adjacent to 1503 ar	nd 1507 Pennsylv	vania Avenue, S.E.
NOTABLE FEATU	IRES DATA				
Component	Featu	ire			
Roof Component Sloped	Material Not Visible	Color	Treatment Not Visible	Source	
	Material	Color	Treatment	Source	
•					
	Brick		Flemish Bond		
Wall Component Facade Structure Componen		Feature	Flemish Bond	Source	
Facade		Feature	Flemish Bond	Source	
Facade Structure Componen Foundation	t Material Concrete	Feature	Flemish Bond	Source	
Facade Structure Componen Foundation Walls	t Material Concrete	Feature	Flemish Bond	Source	
Facade Structure Componen Foundation Walls	t Material Concrete Brick	Feature	Flemish Bond	Source	
Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/I	Concrete Brick NTERIOR DATA Aperture Shape	Туре	Lig	hts	Material
Facade Structure Componen Foundation Walls Materials Notes: WINDOW/DOOR/I	t Material Concrete Brick			hts	Material Wood
Facade Structure Componen Foundation Walls Materials Notes: WINDOW/DOOR/I	Concrete Brick NTERIOR DATA Aperture Shape Rectangular Aperture Shape	Type Dbl-Hung Type	Lig 6/6	hts	
Facade Structure Componen Foundation Walls Materials Notes:	t Material Concrete Brick NTERIOR DATA Aperture Shape Rectangular	Type Dbl-Hung	Lig 6/6	hts	Wood
Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/I Window Location Facade Door Location	Concrete Brick NTERIOR DATA Aperture Shape Rectangular Aperture Shape Rectangular	Type Dbl-Hung Type	Lig 6/6	hts	Wood Material
Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/I Window Location Facade Door Location Main Door	Concrete Brick NTERIOR DATA Aperture Shape Rectangular Aperture Shape Rectangular	Type Dbl-Hung Type	Lig 6/6 Par	hts	Wood Material

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning:

Designation Event(s)

On the best of the						
Contributing:						
Survey(s) Capitol Hill Southeast Phase I (2009/2010)			Level(s) of Investigation Permit Research Volunteer Reconnaissance Survey			
PHOTOS - DIGITIZED)					
Caption:						
Databases\SE St\Database\Pi File: 1505_PA_AVSE	S\Documents\CHRS Phase I - D to G ctures\Square 1078\ E.JPG notog: R: Fr:		1503-			
Code	N. FI.					
PHOTOS - B/W OR N	ON-DIGITIZED					
Photo Code R	coll Frame(s)	Date	Photographer	Caption		
MISCELLANEOUS NO	OTES DATA					
Notes:						
PERMIT DATA						
Permit Issue Date	Number Type		Remarks			
02/18/1909	3025 Build					
Permit Notes:						
BIBLIOGRAPHIC DA	ТА					
SIGNIFICANCE DATA	A					
Study Unit						

DATA PROCESSING EVENTS DATA

Criteria

Code

ID Number: 1078-0818

BASICS DATA

BASICS DATA							
ID Number: 1078	-0818	Year B	uilt: 1937	Data	Source: Per	mit	
Number Extended	Street			Quad T	ype of Address		
922	15th Street			SE C	Current		
Name(s)			Туре	of Name			
Rowhouse, 922 15th	Street, S.E.		Com	mon		_	
TaxCode1 TaxCode	2 TaxCode3	Type	Exp	lain			
1078/0818		Square/L		rent		_	
STATUS/PURPOS	E/USE DATA	١					
Resource Type: Buil	_		_	tatus Curre	nt: Extant		
_	oric			uality:			
Purpose: Rov	vhouse		С	condition:	Good		
Function/Use		Start	Source	Stop	Source	e Explain	
Residential (Single-F	amily)	1937	Permit			Historic/Current	
CONSTRUCTION I Construction Event		tart	Source	Stop	Source	Cost Source	
Orig Construction	19	937	Permit			3300 Permit	
Construction Event		Associati	on		Associated	d Name	
Orig Construction		Architect	t		Dillon & A	bel	_
Orig Construction		Builder			Prince, L.		
Orig Construction		Owner			Prince, L.	E.F.	
Construction Notes:				I. (#####			
One of five rowhous	es constructe	ed from the	same perm	nit (#208927	').		
DEODI E/EVENTO	DATA						
PEOPLE/EVENTS							
Racial Segregation St	atus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Refe	erence Notes:		
Streetscape:	Intact						
Relate to Othr Bldgs:	, ,						
Relate to Street:	Face on Sett	oack Line					

Surroundings: Urban Cross Reference Notes:

Streetscape: Intact
Relate to Othr Bldgs: Row (1 of 5)
Relate to Street: Face on Setback Line
Massing: Row Building/Front Porch
Footprint: Rectangular

Number Stories: 2
Bays Wide: 2

Height: Outbuilding Type Contributing Status
Width: Garage

Depth/Length: 31

SqFt: Volume: Lot Width

Lot Depth/Length: Outbuilding Notes:

Lot SqFt:

Acreage:

September 2008: A one-story, one-bay garage, constructed c.

1937, is located east of the dwelling. The wood-frame garage is clad with German wood siding and is capped by a front-gabled roof. The roof is complemented with overhanging eaves. The

roof. The roof is complemented with overhanging eaves. The façade (south elevation) is pierced by a roll-up garage door.

		The garage was	not surveyed by the vo	lunteer survevor.	
		me garage mae	not our royou by the re	iamoor carroyer.	
STYLE/EXTERIOR DA	TA				
Architectural Style(s)					
Colonial Revival					
Exterior & Architectural N	otes:				
September 2008: Constr rowhouse is one of five brick and is set on a sol brick. A sloping roof cap with cornice returns hig northeast corner of the door. The northernmost one-story, full-width por brick posts. Metal balus second story is fenestra (east) elevation is fenes brick sill. Additionally, a posts and features squa	similar rowhouses co id concrete foundations the dwelling and is hlights the façade and dwelling and has a co bay contains paired of the spans the façade a ters encircle the porce ted with paired 6/6, de trated with single and single-leaf door piere	onstructed from the on; the façade (west of fronted along the fact of imitates a front-gap or beled brick cap. The fact of the	same permit (#208927). elevation) is faced with açade by a brick parape, bled roof. An exterior-rate southernmost bay of bood-sash windows, who did by poured concrete seash windows, which has hung, wood-sash windows,	The dwelling is consix-course, Americal wall. A raking word ear brick chimney rithe first story holds to have a rowlock to of of the porch is steps in the southern are a rowlock brick tows. All windows have	nstructed of an-bond od cornice ises from the s a single-leaf brick sill. A supported by a end bay. The sill. The rear ave a rowlock
•	ile wood baldsters.				
Site Notes: September 2008: This tv					
		•	•		•
slopes to the west and i bounds the western edg at the concrete sidewalk	s landscaped with ma ge of the property. Po c. A garage is located	ature shrubs, founda ured concrete steps	ation plantings, and En	glish ivy. A brick ret	aining wall
bounds the western edg at the concrete sidewalk	s landscaped with ma ge of the property. Po c. A garage is located	ature shrubs, founda ured concrete steps east of the dwelling	ation plantings, and En	glish ivy. A brick ret	aining wall
slopes to the west and i bounds the western edg at the concrete sidewalk NOTABLE FEATURES Component EXTERIOR MATERIAL	s landscaped with mage of the property. Pot A. A garage is located S. DATA Feature	ature shrubs, founda ured concrete steps east of the dwelling	ation plantings, and Englead from the front por	glish ivy. A brick ret ch of the dwelling a	aining wall
slopes to the west and i bounds the western edg at the concrete sidewalk NOTABLE FEATURES Component EXTERIOR MATERIAL Roof Component	s landscaped with mage of the property. Potential is a garage is located is DATA Feature LS DATA Material	ature shrubs, founda ured concrete steps east of the dwelling	ation plantings, and Englead from the front por	glish ivy. A brick ret	aining wall
slopes to the west and i bounds the western edg at the concrete sidewalk NOTABLE FEATURES Component EXTERIOR MATERIAL Roof Component Sloped	s landscaped with mage of the property. Pot A garage is located S DATA Feature LS DATA Material Not Visible	ature shrubs, founda ured concrete steps east of the dwelling Color	Treatment Not Visible	glish ivy. A brick ret ch of the dwelling a	aining wall
slopes to the west and i bounds the western edg at the concrete sidewalk NOTABLE FEATURES Component EXTERIOR MATERIAL Roof Component Sloped Wall Component	s landscaped with mage of the property. Pot a. A garage is located as DATA Feature LS DATA Material Not Visible Material	ature shrubs, founda ured concrete steps east of the dwelling	Treatment Not Visible Treatment	glish ivy. A brick ret ch of the dwelling a	aining wall
slopes to the west and i bounds the western edg at the concrete sidewalk NOTABLE FEATURES Component EXTERIOR MATERIAL Roof Component Sloped	s landscaped with mage of the property. Pot A garage is located S DATA Feature LS DATA Material Not Visible	ature shrubs, founda ured concrete steps east of the dwelling Color	Treatment Not Visible	glish ivy. A brick ret ch of the dwelling a	aining wall
slopes to the west and i bounds the western edg at the concrete sidewalk NOTABLE FEATURES Component EXTERIOR MATERIAL Roof Component Sloped Wall Component	s landscaped with mage of the property. Pot a. A garage is located as DATA Feature LS DATA Material Not Visible Material	ature shrubs, founda ured concrete steps east of the dwelling Color	Treatment Not Visible Treatment	glish ivy. A brick ret ch of the dwelling a	aining wall
slopes to the west and i bounds the western edg at the concrete sidewalk NOTABLE FEATURES Component EXTERIOR MATERIAL Roof Component Sloped Wall Component Facade Structure Component Foundation	s landscaped with made of the property. Pote A garage is located S DATA Feature LS DATA Material Not Visible Material Brick Material Concrete	cature shrubs, founda ured concrete steps east of the dwelling Color	Treatment Not Visible Treatment	Source	aining wall
slopes to the west and i bounds the western edg at the concrete sidewalk NOTABLE FEATURES Component EXTERIOR MATERIAL Roof Component Sloped Wall Component Facade Structure Component	s landscaped with made of the property. Potential S DATA Material Material Material Brick Material	cature shrubs, founda ured concrete steps east of the dwelling Color	Treatment Not Visible Treatment	Source	aining wall
slopes to the west and i bounds the western edg at the concrete sidewalk NOTABLE FEATURES Component EXTERIOR MATERIAL Roof Component Sloped Wall Component Facade Structure Component Foundation	s landscaped with made of the property. Pote A garage is located S DATA Feature LS DATA Material Not Visible Material Brick Material Concrete	cature shrubs, founda ured concrete steps east of the dwelling Color	Treatment Not Visible Treatment	Source	aining wall
slopes to the west and i bounds the western edg at the concrete sidewalk NOTABLE FEATURES Component EXTERIOR MATERIAL Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	s landscaped with made of the property. Pote A garage is located S DATA Feature LS DATA Material Not Visible Material Brick Material Concrete	cature shrubs, founda ured concrete steps east of the dwelling Color	Treatment Not Visible Treatment	Source	aining wall
slopes to the west and i bounds the western edg at the concrete sidewalk NOTABLE FEATURES Component EXTERIOR MATERIAL Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	s landscaped with made of the property. Pote A garage is located S DATA Feature LS DATA Material Not Visible Material Brick Material Concrete	cature shrubs, founda ured concrete steps east of the dwelling Color	Treatment Not Visible Treatment	Source	aining wall

Window Location	Aperture Shape	Туре	Lights	Material	
Facade	Rectangular	Dbl-Hung	6/6 Double	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single		Unknown	
Notable Interior Plan	n(s)		Notable Interior Feature(s)		

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighbo Subdivis	•	Hill		Historic District(s)		
Ward/Al Zoning: Contribu				Designation Event(s	s)	
Survey(s)			Level(s) of Investiga	ition	
Capitol	Hill Southeast Pha	se I (2009/2010)		Permit Research Volunteer Reconna	aissance Survey	
РНОТО	OS - DIGITIZED					
Caption	:					
Path:	C:\Users\CHRS\D Databases\SE Pha St\Database\Pictu	ase I - D to G				
File:	922_15STSE.JPG		1			
Date:: Code::	Photo	og: R:	Fr:			
PHOTO	OS - B/W OR NON	I-DIGITIZED Frame(s)	Date	Photographer	Caption	
MISCE	LLANEOUS NOT	ES DATA				
Notes:						
PERMI	IT DATA					
Permit I	ssue Date	Number Type		Remarks		
12/07/19	937	208927 Build				
Permit N	Notes:					
BIBLIC	OGRAPHIC DATA					
SIGNIF	FICANCE DATA					
Study U	Init					
Code	Criteria					
DATA	PROCESSING EV	ENTS DATA				

ID Number: 1078-0817

BASICS DATA

ID Number: 1078	3-0817	Year Built:	1937	Data	a Source:	Permit		
Number Extended	Street			Quad	Type of Add	lress		
924	15th Street			SE	Current			
Name(s)			Type of	Name				
Rowhouse, 924 15th	Street, S.E.		Commo	on				
TaxCode1 TaxCode	2 TaxCode3	Туре	Explair	า				
1078/0817		Square/Lot	Currer					
STATUS/PURPOS	E/USE DATA							
Resource Type: Buil	•				ent: Extant			
J	toric		Qua	-	0			
Purpose: Rov	vhouse		Con	dition:	Good			
Function/Use		Start S	Source	Stop	5	Source	Explain	
Residential (Single-I	Family)	1937 F	Permit				Historic/Current	
CONCEDUCTION	DATA							
CONSTRUCTION I Construction Event		art Sou	roo	Cton	Source		Cost Source	
Orig Construction		300 Peri		Stop	Source	*	3300 Permit	
					A	etera di Nico		
Construction Event Orig Construction		Association Architect				ciated Nar n & Abel	me	
Orig Construction		Builder				e, L.E.F.		
Orig Construction		Owner				e, L.E.F.		
Construction Notes:						,		
One of five rowhous	es constructe	d from the sar	ne permit	(#2089	27).			
			•	•				
PEOPLE/EVENTS	DATA							
Racial Segregation St	tatus:							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban		С	ross Re	eference Not	es:		
Streetscape:	Intact							
Relate to Othr Bldgs:								
Relate to Street:	Face on Setb							
Massing:		g/Front Porch						
Footprint:	Rectangular							
Number Stories:	2							
Bays Wide:	2		0 41 11 11	_		_		
Height: Width:	40		Outbuildin	ig Type		C	ontributing Status	=
Depth/Length:	16 31							
SqFt:	O.							
Volume:								
Lot Width								
Lot Depth/Length:			Outbuildin	g Notes	3:			7
Lot SqFt:								
Acreage:								
Has Driveway:								

STYLE/EXTERIOR DATA Architectural Style(s) Colonial Revival

Exterior & Architectural Notes:

September 2008: Constructed in 1937 by L.E.F. Prince, this two-story, two-bay Colonial Revival-style single-family rowhouse is one of five similar rowhouses constructed from the same permit (#208927). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (west elevation) is faced with six-course, American-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a brick parapet wall. A molded cornice and soldier brick string course complement the parapet. An exterior-rear brick chimney rises from the northeast corner of the dwelling and has a corbeled brick cap. The southernmost bay of the first story holds a single-leaf door. The northernmost bay contains paired double-hung sash windows, which have a rowlock brick sill. A one-story, full-width porch spans the façade and is set on a brick pier foundation that has been infilled with wood lattice. The roof of the porch is supported by brick posts. Metal balusters encircle the porch, which is accessed by poured concrete steps in the southern end bay. A full-width metal awning projects from the west elevation of the porch roof. The second story is fenestrated with 1/1, double-hung, vinyl-sash windows, which have a rowlock brick sills. The rear (east) elevation is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows. All windows have a rowlock brick sill. Additionally, a single-leaf door pierces the first story and is accessed by a wood deck. The deck is set on wood posts and features square wood balusters.

Site Notes:

September 2008: This two-story rowhouse is located on the east side of 15th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 922 and 926 15th Street, S.E. The grassy front yard slopes to the west and is landscaped with foundation plantings. A brick retaining wall bounds the western edge of the property. Poured concrete steps lead from the porch of the dwelling and end at the sidewalk.

NOTABLE FEATURES DATA Component Feature

EXTERIOR MATERIALS DATA

Material	Color	Treatment	Source	
Not Visible		Not Visible		
Material	Color	Treatment	Source	
Brick		American Bond		
Material	Feature		Source	
Concrete				
Brick				
	Not Visible Material Brick Material Concrete	Not Visible Material Color Brick Material Feature Concrete	Not Visible Material Color Treatment Brick American Bond Material Feature Concrete	Not Visible Material Color Treatment Source Brick American Bond Material Feature Source Concrete

WINDOW/DOOR/INTERIOR DATA

Notable Interior Plar	n(s)		Notable Interior Feature(s)	
Main Door	Rectangular	Single		Unknown
Door Location	Aperture Shape	Type	Pamels	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
1 Flr Windows	Rectangular	Dbl-Hung		Unknown
Window Location	Aperture Shape	Туре	Lights	Material

Г			
П			
П			
П			

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision:

Interior Notes

Ward/ANC:					
Zoning:			Designation Event(s)	
Contributing:					
Survey(s)			Level(s) of Investiga	tion	
Capitol Hill Southeast Phase	e I (2009/2010)		Permit Research		
			Volunteer Reconna	nissance Survey	
PHOTOS - DIGITIZED					
Caption:			100		
Path: C:\Users\CHRS\Doc Databases\SE Phas St\Database\Picture	se I - D to G				
File: 924_15STSE.JPG					
Date:: Photog					
Code::	R: Fr:				
PHOTOS - B/W OR NON-	DIGITIZED				
Photo Code Roll	Frame(s)	Date	Photographer	Caption	
MISCELLANEOUS NOTE	S DATA				
Notes:					
PERMIT DATA					
	Number Tune	D	o morteo		
Permit Issue Date 12/07/1937	Number Type 208927 Build	K	emarks		<u></u>
	200327 Build				
Permit Notes:					
BIBLIOGRAPHIC DATA					
SIGNIFICANCE DATA					
Study Unit					

DATA PROCESSING EVENTS DATA

Criteria

Code

ID Number: 1078-0048

BASICS DATA

ID Number: 1078	3-0048	Year Built:	1937	Data S	Source:	Permit		
Number Extended	Street			Quad Ty	pe of Addr	ess		
926	15th Street			SE C	urrent			
Name(s)			Type of	Name				
Rowhouse, 926 15th	Street, S.E.		Commo					
TaxCode1 TaxCode	2 TaxCode3	Туре	Explain					
1078/0048	- Taxooaco	Square/Lot	Curren					
		•						
STATUS/PURPOS	E/USE DATA							
Resource Type: Buil	lding		Statu	s Curren	t: Extant			
Desig. Status: Hist	toric		Quali	ity:				
Purpose: Rov	vhouse		Cond	lition:	Good			
Function/Use		Start S	Source	Stop	So	ource	Explain	
Residential (Single-F	Family)		Permit	•			Historic/Current	
CONSTRUCTION I	DATA							
Construction Event	St	art Sou	rce S	Stop	Source		Cost Source	
Orig Construction	19	37 Peri	nit				3300 Permit	
Construction Event		Association			Assoc	iated Nar	me	
Orig Construction		Architect			Dillon	& Abel		
Orig Construction		Builder			Prince	, L.E.F.		
Orig Construction		Owner			Prince	, L.E.F.		
Construction Notes:								
One of five rowhous	es constructe	d from the sar	ne permit (#208927)).			
PEOPLE/EVENTS	DATA							
Racial Segregation St	tatus:							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban		Cr	oss Refe	rence Note	s:		
Streetscape:	Intact							7
Relate to Othr Bldgs:								
Relate to Street:	Face on Setb							
Massing:		/Front Porch						
Footprint:	Rectangular							
Number Stories:	2							
Bays Wide:	2							_
Height:			Outbuilding	ј Туре		C	ontributing Status	_
Width:	16							
Depth/Length:	31							
SqFt: Volume:								
Lot Width								
Lot Depth/Length:			Outbuilding	Notes:				
Lot SqFt:								
Acreage:								
Has Driveway:								

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

September 2008: Constructed in 1937 by L.E.F. Prince, this two-story, two-bay Colonial Revival-style single-family rowhouse is one of five similar rowhouses constructed from the same permit (#208927). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (west elevation) is faced with six-course, American-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a brick parapet wall. A raking wood cornice with cornice returns highlights the façade and imitates a front-gabled roof. An exterior-rear brick chimney rises from the northeast corner of the dwelling and has a corbeled brick cap. The southernmost bay of the first story holds a single-leaf paneled wood door with lights. The northernmost bay contains paired 1/1, double-hung, wood-sash windows, which have a rowlock brick sill. A one-story, full-width porch spans the façade and is set on a brick pier foundation. The roof of the porch is supported by brick posts. Metal balusters encircle the porch, which is accessed by poured concrete steps in the southern end bay. The second story is fenestrated with paired 1/1, double-hung, wood-sash windows, which have a rowlock brick sill. The rear (east) elevation is fenestrated with single and paired 1/1, double-hung, wood-sash windows. All windows have a rowlock brick sill. Additionally, a single-leaf paneled wood door with lights pierces the first story and is accessed by a wood deck. The deck is set on wood posts and features wood balusters.

Site Notes:

September 2008: This two-story rowhouse is located on the east side of 15th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 924 and 928 15th Street, S.E. The grassy front yard slopes to the west and features mature shrubs. A low, brick retaining wall bounds the western edge of the yard. Poured concrete steps lead from the porch of the dwelling and end at the sidewalk.

Ν													

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		American Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
Facade	Rectangular	Dbl-Hung	1/1 Double	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single	Paneled	Wood/Glass	
Notable Interior Plan	n(s)		Notable Interior Feature(s)		

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Subdivision: Ward/ANC:

Historic District(s)

∠onıng: Contribı				Designation Event(s)						
Survey((s)			Level(s) of Investigat	ion					
Capitol	Hill Southeast Phase	l (2009/2010)		Permit Research Volunteer Reconnaissance Survey						
РНОТО	OS - DIGITIZED									
Caption	:									
Path: File:	C:\Users\CHRS\Doc Databases\SE Phas St\Database\Picture 926_15STSE.JPG	e I - D to G								
Date:: Code::	Photog:	R: Fr:								
РНОТО	OS - B/W OR NON-I	DIGITIZED								
Photo C		Frame(s)	Date	Photographer	Caption					
MISCE	ELLANEOUS NOTES	S DATA								
Notes:										
PERMI	IT DATA									
Permit I	Issue Date	Number Type		Remarks			_			
12/07/1	937	208927 Build								
Permit I	Notes:						٦			
BIBLIC	OGRAPHIC DATA									
SIGNIF	FICANCE DATA									
Study U	Jnit									
Code	Criteria									

DATA PROCESSING EVENTS DATA

ID Number: 1078-0047

BASICS DATA

ID Number: 1078	3-0047	Year Built:	1937	Dat	a Source:	Permit		
Number Extended	Street			Quad	Type of Add	dress		
928	15th Street			SE	Current			
Name(s)			Type of	Name				
Rowhouse, 928 15th	Street, S.E.		Commo	on				
TaxCode1 TaxCode	2 TaxCode3	Туре	Explair	1				
1078/0047		Square/Lot	Currer					
STATUS/PURPOS	E/USE DATA							
Resource Type: Buil	lding				rent: Extant			
_	toric		Qua	-				
Purpose: Rov	vhouse		Con	dition:	Good			
Function/Use		Start S	Source	Stop	,	Source	Explain	
Residential (Single-I	Family)	1937 F	Permit				Historic/Current	
CONSTRUCTION I	DATA							
Construction Event		art Sou		Stop	Source)	Cost Source	
Orig Construction	19	37 Peri	nit				3300 Permit	
Construction Event		Association			Asso	ciated Nar	me	
Orig Construction		Architect				n & Abel		
Orig Construction		Builder				ce, L.E.F.		
Orig Construction		Owner			Prin	ce, L.E.F.		
Construction Notes:								
One of five rowhous	es constructe	d from the sar	ne permit (#2089	27).			
DEODI E/EVENTS	DATA							
PEOPLE/EVENTS								
Racial Segregation St	tatus:							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban		С	ross Re	eference No	es:		
Streetscape:	Intact]
Relate to Othr Bldgs:	Row (1 of 5)							
Relate to Street:	Face on Setb	ack Line						
Massing:	Row Building	/Front Porch						
Footprint:	Rectangular							
Number Stories:	2							
Bays Wide:	2							1
Height:			Outbuildin	д Туре		С	contributing Status	_
Width:	16							
Depth/Length:	31							
SqFt: Volume:								
Lot Width								
Lot Depth/Length:			Outbuildin	g Note:	s:			
Lot SqFt:				<u> </u>				
Acreage:								
Has Driveway:								

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

September 2008: Constructed in 1937 by L.E.F. Prince, this two-story, two-bay Colonial Revival-style single-family rowhouse is one of five similar rowhouses constructed from the same permit (#208927). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (west elevation) is faced with six-course, American-bond brick. A sloping roof caps the dwelling and is fronted along the facade by a brick parapet wall. A molded cornice and soldier brick string course complement the parapet. An exterior-rear brick chimney rises from the northeast corner of the dwelling and has a corbeled brick cap. The southernmost bay of the first story holds a single-leaf door. The northernmost bay contains paired 6/6, double-hung wood-sash windows, which have a rowlock brick sill. A one-story, full-width porch spans the façade and is set on a brick pier foundation that has been infilled with concrete blocks. The roof of the porch is supported by brick posts. Metal balusters encircle the porch, which is accessed by poured concrete steps in the southern end bay. The second story is fenestrated with 6/6, double-hung, wood-sash windows, which have a rowlock brick sills. The rear (east) elevation is fenestrated with single and paired 6/6, double-hung, wood-sash windows. All windows have a rowlock brick sill. Additionally, a single-leaf door pierces the first story and is accessed by a wood deck. The deck is set on wood posts and features wood balusters.

Site Notes:

September 2008: This two-story rowhouse is located on the east side of 15th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 926 and 930 15th Street, S.E. The raised, grassy front yard is landscaped with a mature tree and is bounded by a brick retaining wall. Poured concrete steps lead from the front porch and end at the sidewalk.

NOTABLE FEATURES DATA	N	O.	TA	۱B	LΕ	FE.	AΤ	UR	ES	D	ΑТА	
-----------------------	---	----	----	----	----	-----	----	----	----	---	-----	--

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		American Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
1 Flr Windows	Rectangular	Dbl-Hung	6/6 Double	Wood	
2 Flr Windows	Rectangular	Dbl-Hung	6/6	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single		Unknown	
Notable Interior Plan	n(s)		Notable Interior Feature(s)		

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision: \A/ - .. - I/ A A I A

Interior Notes:

ID_Number: 1078-0047 Page 2

Ward/A Zoning: Contrib	uting:					Designation Event(s) Level(s) of Investigati	on	
	Hill Southea	st Phase I	(2009/2010)			Permit Research		
						Volunteer Reconnai	ssance Survey	
РНОТ	OS - DIGITIZ	ED.						
Caption								
Path: File:	Databases\	SE Phase e\Pictures\	ments\CHRS I - D to G .Square 1078\					
Date::		Photog:						
Code::			R:	Fr:				
РНОТ	OS - B/W OF	R NON-DI	GITIZED					
Photo C	Code	Roll	Frame(s)		Date	Photographer	Caption	
MISCE	ELLANEOUS	NOTES	DATA					
Notes:								
PERM	IT DATA							
Permit	Issue Date		Number Typ	е		Remarks		
12/07/1	937		208927 Bui	d				_
Permit	Notes:							
								_
BIBLIC	OGRAPHIC I	DATA						
SIGNII	FICANCE DA	ATA						
Study L	Jnit							
Code	Criter	ia						

Friday, August 30, 2013

DATA PROCESSING EVENTS DATA

ID Number: 1078-0046

BASICS DATA

ID Number: 1078	3-0046	Year Built:	1937	Data	a Source:	Permit		
Number Extended	Street			Quad	Type of Add	lress		
930	15th Street			SE	Current			
Name(s)			Type of	Name				
Rowhouse, 930 15th	Street, S.E.		Commo	on				
TaxCode1 TaxCode	2 TaxCode3	Туре	Explair	า				
1078/0046		Square/Lot	Currer					
STATUS/PURPOS	E/USE DATA							
Resource Type: Buil	lding				ent: Extant			
J	toric		Qua	-				
Purpose: Rov	vhouse		Con	dition:	Good			
Function/Use		Start S	Source	Stop	5	Source	Explain	
Residential (Single-I	Family)	1937 F	Permit				Historic/Current	
CONSTRUCTION								
Construction Event		art Sou		Stop	Source	!	Cost Source	
Orig Construction	19	937 Peri	nit				3300 Permit	
Construction Event		Association				ciated Nar	me	
Orig Construction		Architect				n & Abel		
Orig Construction		Builder				e, L.E.F.		
Orig Construction		Owner			Princ	e, L.E.F.		
Construction Notes:								
One of five rowhous	es constructe	d from the sar	ne permit ((#20892	27).			
PEOPLE/EVENTS	DATA							
Racial Segregation St	tatus:							
radiai eegreganen et								
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban		С	ross Re	eference Not	es:		
Streetscape:	Intact							
Relate to Othr Bldgs:								
Relate to Street:	Face on Setb							
Massing: Footprint:	L-Shaped	J/Front Porch						
	-							
Number Stories:	2							
Bays Wide:	2		0(1	.		0	and the officer Officer	
Height: Width:	40		Outbuildin	g rype		C	ontributing Status	
Depth/Length:	16 31							
SqFt:	O.							
Volume:								
Lot Width								
Lot Depth/Length:			Outbuildin	g Notes	3:			
Lot SqFt:								
Acreage:								
Has Driveway:								

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

September 2008: Constructed in 1937 by L.E.F. Prince, this two-story, two-bay Colonial Revival-style single-family rowhouse is one of five similar rowhouses constructed from the same permit (#208927). The dwelling is constructed of brick and is set on a solid concrete foundation; both are faced with six-course, American-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a brick parapet wall. A raking wood cornice with cornice returns highlights the façade and imitates a front-gabled roof. An exterior-rear brick chimney rises from the northeast corner of the dwelling and has a corbeled brick cap. The northernmost bay of the first story holds a single-leaf paneled wood door with lights. The southernmost bay contains paired 1/1, double-hung sash windows, which have a rowlock brick sill. A one-story, full-width porch spans the façade and is set on a brick pier foundation that has been infilled with wood lattice. The roof of the porch is supported by brick posts. Metal balusters encircle the porch, which is accessed by poured concrete steps in the northern end bay. The second story is fenestrated with paired 1/1, double-hung sash windows, which have a rowlock brick sill. The south (side) elevation is fenestrated with paired and triple 1/1, double-hung, vinylsash windows and a one-light window (possibly awning). All windows have rowlock brick sills. The rear (east) elevation is fenestrated with single and paired 1/1, double-hung, wood-sash windows. All windows have a rowlock brick sill. A twostory, rectangular bay projects from the southeast corner of the south elevation and is original to the main block. The bay shares the material treatment of the dwelling and is capped by a sloping roof. A brick parapet rises from the roof and features a raking wood cornice with cornice returns on the south elevation. Fenestration consists of paired and triple 1/1, double-hung, vinyl-sash windows and a one-light window (possibly awning). All windows have rowlock brick sills. The rear (east) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows and have rowlock brick sills. Additionally, a single-leaf door pierces the first story of the rear elevation and is accessed by poured concrete steps which are set on brick piers. Metal balusters complement the stairs.

Site Notes

September 2008: This two-story rowhouse is located on the northeast corner of 15th Street, S.E. and K Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The north (side) elevation of the dwelling is adjacent to 928 15th Street, S.E. The grassy front and side yards are landscaped with mature shrubs and are bounded by a brick retaining wall. The side yard slopes to the east. Poured concrete steps lead from the porch of the dwelling and end at the sidewalk lining 15th Street, S.E.

NOTABLE FEATURES DATA

Component	Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		American Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				
Materials Notes:					
Materials Notes:					_

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
Facade	Rectangular	Dbl-Hung	1/1 Double	Unknown	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single	Paneled	Wood/Glass	
Notable Interior Plan(s)		Notable Interior Feature(s)			

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Subdivision: Ward/ANC: Zoning:

Designation Event(s)

Historic District(s)

Contributing: Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G

St\Database\Pictures\Square 1078\

File: 930_15STSE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1078\

File: 930_15STSEb.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1078\

File: 930_15STSE-SoSide.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:			
PERMIT DATA			
Permit Issue Date	Number Type	Remarks	
12/07/1937	208927 Build		
Permit Notes:			
BIBLIOGRAPHIC DA	ATA		
SIGNIFICANCE DAT	ГА		
Study Unit			
Code Criteria			
DATA PROCESSING	G EVENTS DATA		

ID_Number: 1078-0046 Page 4

ID Number: 1078-0053

ID Number: 1078	3-0053	Year B	uilt: c. 2007	Data	a Source: Site V	/isit/Map	
Number Extended	Street			Quad	Type of Address		
920	15th Street	t			Current		
Name(s)			Tyne o	f Name			
Condominium, 920 1	15th Street, S	S.E.	Comm				
			E.mle:	_			
TaxCode1 TaxCode 1078/0053	2 TaxCode3	3 Type Square/L	Explai ot Histo i				
1070/0033		Square/L	ot ilistoi	ii.			
STATUS/PURPOS	F/USF DAT	.Δ					
Resource Type: Buil			Sta	tus Curr	ent: Extant		
	Historic			ality:	one Extern		
_	ndominium			ndition:	Excellent		
		O		0.	•	-	
Function/Use Residential (Multi Co	anda)	Start c. 2007	Source Site Visit/	Stop	Source	Explain Historic/Current	
Residential (Multi Co	ondo)	C. 2007	Site Visit			HIStoric/Current	
CONSTRUCTION I	DATA						
Construction Event	;	Start	Source	Stop	Source	Cost Source	
Orig Construction	(Site				
			Visit/Maps				
Construction Event		Association	on		Associated N	lame	
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		C	Cross Re	eference Notes:		
Streetscape:	Intact						
Relate to Othr Bldgs:	,						
Relate to Street:	Face on Se						
Massing: Footprint:	Vertical Blo						
	Rectangula						
Number Stories:	-	basement					
Bays Wide:	3		Outhuildis	. a Tuna		Contributing Status	
Height: Width:			Outbuildir	ig Type		Contributing Status	
Depth/Length:							
SqFt:							
Volume:							
Lot Width							
Lot Depth/Length:			Outbuildir	ng Notes	: :		
Lot SqFt:				-			
Acreage:							
Has Driveway:							

Exterior & Architectural Notes:

September 2008: Constructed c. 2007, this three-story, three-bay condominium building has a rectangular form and is set on a solid, raised concrete block foundation. The first story of the façade (west elevation) is faced with concrete blocks, while the second and third stories are faced with stretcher-bond brick. Soldier brick string courses span the façade above the first, second, and third story windows. A sloping roof caps the building and is fronted along the façade by an overhanging eave. A plain frieze boards finishes the roof. The foundation of the building serves as an integrated garage and supports the upper stories with concrete block piers. The end bays of the façade hold 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins and rowlock brick sills. A three-story oriel window rises from the first story of the façade and projects from the central bay. The wood-frame oriel is clad with wood paneling and is fenestrated with 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins. The rear (east) elevation was not surveyed or photographed by the volunteer surveyor.

Site	N	Ot.	٥٥

one notes.						<u></u>
	is three-story condominiu et from the concrete walk					
NOTABLE FEATUI	RES DATA					
Component	Feature					
EXTERIOR MATER	RIALS DATA					
Roof Component	Material	Color	Treatment	Source		
Sloped	Not Visible		Not Visible			
Wall Component	Material	Color	Treatment	Source		
Facade (Lower) Facade (Upper)	Concrete Block Brick		Stretcher Bond			
Structure Component	Material	Feature		Source		
Foundation Walls	Concrete Block Unknown					
Materials Notes:						
WINDOW/DOOR/IN						
Window Location	Aperture Shape	Туре	Lig	hts	Material	
Bay Windows Facade	Rectangular Rectangular	Dbl-Hung Dbl-Hung	1/1 1/1		Vinyl Vinyl	
Door Location	Aperture Shape	Type		mels	Material	
Notable Interior Plan(s	s)		Notable Interior Fe	eature(s)		
Interior Notes:						
PLAN/SURVEY/DE	SIGNATION DATA					
Neighborhood: Ca Subdivision: Ward/ANC:	apitol Hill		Historic District(s)			
Zoning: Contributing:			Designation Event	(s)		

Survey(s)		
-----------	--	--

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1078\

File: 920_15STSE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1078\

File: 920_15STSEb.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

ID_Number: 1078-0053 Page 3

ID Number: 1078-0016

ID Number: 1078	3-0016	Year Built:	1904	Data Sou	rce: Permit		
Number Extended	Street			Quad Type	of Address		
914	15th Street			SE Curre	ent		
Name(s)			Type of	Name			
Rowhouse, 914 15th	Street, S.E.		Commo				
		_					
	2 TaxCode3	Type	Explain				
1078/0016		Square/Lot	Curren	τ			
CTATUC/DUDDOC	E/UCE DATA						
STATUS/PURPOS			01-1				
Resource Type: Bui Desig. Status: His	laing toric		Statt Qual	is Current: E	extant		
_	vhouse				Good		
, and a second	Vilouse		Conc		,00a		
Function/Use		Start	Source	Stop	Source	Explain	
Residential (Single-I	Family)	1904	Permit			Historic/Current	
CONSTRUCTION	DATA						
Construction Event	Sta	art Sou	ırce S	Stop	Source	Cost Source	
Orig Construction	19	04 Per	mit			900 Permit	
Construction Event		Association			Associated Nar	me	
Hielt & Marshall		Builder			Hielt & Marsha	all	
Orig Construction		Architect			Shenk, W.S.		
Orig Construction		Owner			Davis, A.S.		
Construction Notes:							
One of three rowhou	ises constructe	ed from the s	ame permit	(#0574).			
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/	SIZE DATA						
Surroundings:	Urban						
Streetscape:			Cr	oss Referen	ce Notes:		
•			Cr	oss Referen	ce Notes:		
Relate to Othr Bldgs:	Intact		Cr	oss Referen	ce Notes:		
Relate to Othr Bldgs: Relate to Street:	Intact	ack Line	Cr	oss Referen	ce Notes:		
Relate to Street: Massing:	Intact Row (1 of 3)		Cr	oss Referen	ce Notes:		
Relate to Street:	Intact Row (1 of 3) Face on Setba		Cr	oss Referen	ce Notes:		
Relate to Street: Massing:	Intact Row (1 of 3) Face on Setba Row Building		Cr	oss Referen	ce Notes:		
Relate to Street: Massing: Footprint:	Intact Row (1 of 3) Face on Setba Row Building L-Shaped		Cr	oss Referen	ce Notes:		
Relate to Street: Massing: Footprint: Number Stories:	Intact Row (1 of 3) Face on Setba Row Building L-Shaped		Cr			ontributing Status	
Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width:	Intact Row (1 of 3) Face on Setba Row Building L-Shaped 2 2					ontributing Status	
Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length:	Intact Row (1 of 3) Face on Setba Row Building L-Shaped 2 2					ontributing Status	
Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt:	Intact Row (1 of 3) Face on Setba Row Building L-Shaped 2 2					ontributing Status	
Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume:	Intact Row (1 of 3) Face on Setba Row Building L-Shaped 2 2					ontributing Status	
Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width	Intact Row (1 of 3) Face on Setba Row Building L-Shaped 2 2		Outbuilding	з Туре		ontributing Status	
Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length:	Intact Row (1 of 3) Face on Setba Row Building L-Shaped 2 2			з Туре		ontributing Status	
Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width	Intact Row (1 of 3) Face on Setba Row Building L-Shaped 2 2		Outbuilding	з Туре		ontributing Status	
Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Lot SqFt:	Intact Row (1 of 3) Face on Setba Row Building L-Shaped 2 2		Outbuilding	з Туре		ontributing Status	

Architectural Style(s)					
Italianate (Vernacula	r)				
Exterior & Architectura	Il Notes:				
is one of three simila weatherboard siding façade (west elevation the first story is covered southernmost bay of dentils highlights the foundation. Square with façade hold 1/1, of Sanborn maps indications.	r rowhouses construction and is set on a solid ken) by a projected mole the first story holds a copening. A one-story wood balusters and wo double-hung, wood-sate that a two-story ori	lielt & Marshall, this two cted from the same per prick foundation. A slo ded cornice with scrol e door, which protects a single-leaf paneled we're deck provides access bod steps in the south ash windows and featu iginal ell extends from graphed by the volunt	rmit (#0574). The woo ping roof caps the do led modillions and be a breeze-way which a ood door. A wood su s to the primary entra ern bay complement re wood surrounds we the southern bay of the	od-frame dwelling welling and is from the control of the rear of the rear of the rear of the control of the con	g is clad with wood onted along the thernmost bay of of the property. The olded lintel with on a brick pier oldow openings on als with dentils.
Site Notes:	, ,	<u> </u>	•		
ten feet from the side	walk. The dwelling is by a concrete retaining	is located on the east adjacent to 912 and 9' ng wall. Poured concre	16 15th Street, S.E. TI	he grassy front y	ard slopes to the
NOTABLE FEATUR	RES DATA				
Component	Featu	ure			
Component EXTERIOR MATER	Featu	ure Color	Treatment	Source	
Component EXTERIOR MATER	Featu		Treatment Not Visible	Source	
Component EXTERIOR MATER Roof Component	Featu IALS DATA Material			Source Source	
EXTERIOR MATER Roof Component Sloped	Featu IALS DATA Material Not Visible	Color	Not Visible	Source	
EXTERIOR MATER Roof Component Sloped Wall Component	Featu IALS DATA Material Not Visible Material	Color	Not Visible Treatment	Source	
Component EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Feature Featur	Color	Not Visible Treatment	Source	
Component EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Feature Featur	Color	Not Visible Treatment Weatherboards	Source	Material
Component EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Feature Featur	Color Color Feature	Not Visible Treatment Weatherboards	Source	Material
Component EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/IN Window Location	Material Not Visible Material Wood Material Brick Frame	Color Color Feature	Not Visible Treatment Weatherboards Lig	Source	

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Interior Notes:

Ward/ANC: Zoning:

Contributing:

Designation Event(s)

Survey(s)	
-----------	--

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1078\

File: 914_15STSE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

09/19/1904 0574 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1078-0016 Page 3

ID Number: 1078-0015

ID Number: 1078	3-0015	Year Built:	1904	Dat	a Source:	Permit		
Number Extended	Street			Quad	Type of Add	dress		
916	15th Street			SE	Current			
Name(s)			Type of	Name				
Rowhouse, 916 15th	Street, S.E.		Commo	on				
TaxCode1 TaxCode	2 TaxCode3	Туре	Explair	1				
1078/0015		Square/Lot	Curren					
STATUS/PURPOS	E/USE DATA							
Resource Type: Bui	lding		State	us Curi	rent: Extant			
· ·	toric		Qua	-				
Purpose: Rov	vhouse		Con	dition:	Good			
Function/Use		Start S	Source	Stop	Ş	Source	Explain	
Residential (Single-I	Family)	1904 F	Permit				Historic/Current	
CONSTRUCTION	DATA							
Construction Event	St	art Sou	rce	Stop	Source)	Cost Source	
Orig Construction	19	004 Peri	nit				900 Permit	
Construction Event		Association			Asso	ciated Na	me	
Orig Construction		Architect			Sher	ık, W.S.		
Orig Construction		Builder				& Marsha	all	
Orig Construction		Owner			Davi	s, A.S.		
Construction Notes:								
One of three rowhou	uses construct	ed from the sa	ame permi	t (#057	4).			
PEOPLE/EVENTS	DATA							
Racial Segregation St	tatus:							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban		C	ross Re	eference No	es:		
Streetscape:	Intact]
Relate to Othr Bldgs:	Row (1 of 3)							
Relate to Street:	Face on Setb							
Massing:	Row Building	/Front Porch						
Footprint:	L-Shaped							
Number Stories:	2							
Bays Wide:	2					_		
Height:			Outbuildin	g Type		С	contributing Status	-
Width: Depth/Length:	17 23							
SqFt:	23							
Volume:								
Lot Width								
Lot Depth/Length:			Outbuildin	g Note	s:			_
Lot SqFt:								
Acreage:								
Has Driveway:								

STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Italianate (Vernacula	r)		<u> </u>		
Exterior & Architectura	al Notes:				
is one of three simila stretcher-bond brick dwelling and is front southernmost bay of the opening. All wind sills and soldier brick that has been infilled posts. Square wood maps indicate that a	or rowhouses construction the façade (west e ed along the façade by the first story holds a dow openings on the f k flat arches. A one-st I with wood lattice. Th balusters encircle the	lielt & Marshall, this two cted from the same per levation) and is set on y a projecting molded of a single-leaf paneled we açade hold 1/1, double ory, two-bay porch spa e roof of the porch has porch, which is acces extends from the south volunteer surveyor.	rmit (#0574). The v a solid brick foun cornice with scrol ood door with ligh hung, vinyl-sash ans the façade and s overhanging eav sed by brick steps	vood-frame dwell dation. A sloping led modillions an its. A rowlock bridwindows and feat is set on a concres and is supports in the southern	ing is faced with roof caps the d brackets. The ck flat arch highlights iture rowlock brick rete pier foundation ted by turned wood end bay. Sanborn
Site Notes:					
the west and is plant western edge of the p the dwelling.	ed with mature shrub: property. Poured cond	adjacent to 914 and 91 s and foundation plant crete steps provide acc	ings. A poured co	ncrete retaining v	wall bounds the
NOTABLE FEATUR Component	RES DATA Featu				
EXTERIOR MATER	RIALS DATA Material	Color	Treatment	Source	
Sloped	Not Visible	00101	Not Visible	000100	
Wall Component	Material	Color	Treatment	Source	
Facade	Brick	25101	Veneer	304.00	
Structure Component	Material	Feature		Source	
Foundation	Brick				
Walls	Frame				
Materials Notes:					
WINDOW/DOOR/IN	ITERIOR DATA				
Window Location	Aperture Shape	Туре		Lights	Material
Facade	Rectangular	Dbl-Hung		1/1	Vinyl
Door Location	Aperture Shape	Туре		Pamels	Material
Main Door	Rectangular	Single		Paneled	Wood/Glass

Window Location	Aperture Shape	Туре	Lights	Material		
Facade	Rectangular	Dbl-Hung	1/1	Vinyl		
Door Location	Aperture Shape	Туре	Pamels	Material		
Main Door	Rectangular	Single	Paneled	Wood/Glass		
Notable Interior Plan	n(s)		Notable Interior Feature(s)			

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision: Ward/ANC: Zoning:

Interior Notes:

Designation Event(s)

Survey(s)			Level(s) of Investiga	tion		
Capitol Hill Southeas	Phase I (2009/2010		Permit Research Volunteer Reconnaissance Survey			
PHOTOS - DIGITIZE	ED.					
Databases\S St\Database\ File: 916_15STSE	RS\Documents\CHR E Phase I - D to G Pictures\Square 107 .JPG Photog: R:					
PHOTOS - B/W OR	NON-DIGITIZED					
Photo Code	Roll Frame(s	s) Date	Photographer	Caption		
MICOEL LANGOUG	NOTEO DATA					
MISCELLANEOUS	NOTES DATA					
Notes:						
PERMIT DATA						
Permit Issue Date	Number Ty	/pe	Remarks			
	0574 B	uild				
09/19/1904						

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID Number: 1078-0014

ID Number: 1078	3-0014	Year Built:	1904	Data S	Source:	Permit		
Number Extended	Street			Quad Ty	pe of Add	ess		
918	15th Street			SE C	urrent			
Name(s)			Type of	Name				
Rowhouse, 918 15th	Street, S.E.		Commo	n				
TaxCode1 TaxCode	2 TaxCode3	Туре	Explain					
1078/0014		Square/Lot	Curren	t				
STATUS/PURPOS								
Resource Type: Buil	_				t: Extant			
_	toric vhouse		Qual Conc	ity. dition:	Good			
Function/Use	Tamilul		Source	Stop	S	ource	Explain	
Residential (Single-I	ramily)	1904 F	Permit				Historic/Current	
CONSTRUCTION I	DATA							
Construction Event		art Sou	rce S	Stop	Source		Cost Source	
Orig Construction	19	004 Peri		•			900 Permit	
Construction Event		Association			Assoc	iated Nar	me	
Orig Construction		Architect				k, W.S.		
Orig Construction		Builder			Hielt	& Marsha	all	
Orig Construction		Owner			Davis	, A.S.		
Construction Notes:								
One of three rowhou	uses construct	ed from the s	ame permit	(#0574).				
PEOPLE/EVENTS	DATA							
Racial Segregation St	tatus:							
SETTING/SHAPE/S	SIZE DATA							
			0	D-(-	NI	_		
Surroundings: Streetscape:	Urban Intact		Cr	oss Refe	rence Note	es: 		٦
Relate to Othr Bldgs:								
Relate to Street:	Face on Setb	ack Line						
Massing:		/Front Porch						
Footprint:	L-Shaped	,						
Number Stories:	2							
Bays Wide:	2							
Height:			Outbuilding	Type		С	ontributing Status	
Width:	17			, ,,				=
Depth/Length:	23							
SqFt:								
Volume:								
Lot Width			_					
Lot Depth/Length:			Outbuilding	Notes:				٦
Lot SqFt:								
Acreage:								
Has Driveway:								

Foundation Walls Materials Notes: WINDOW/DOOR/IN Window Location 1 Fir Windows 2 Fir Windows Door Location Main Door	Aperture Shape Rectangular Rectangular Aperture Shape Rectangular	Type Dbl-Hung Dbl-Hung Type Single		Lights 9/9 Double 1/1 Pamels Paneled	Material Wood Vinyl Material Unkown w/Lights
Walls Materials Notes: WINDOW/DOOR/IN Window Location 1 Fir Windows 2 Fir Windows	Aperture Shape Rectangular Rectangular	Dbl-Hung Dbl-Hung		9/9 Double 1/1	Wood Vinyl
Walls Materials Notes: WINDOW/DOOR/IN Window Location 1 Fir Windows	Aperture Shape Rectangular	Dbl-Hung		9/9 Double	Wood
Walls Materials Notes: WINDOW/DOOR/IN	Aperture Shape	**			
Walls Materials Notes: WINDOW/DOOR/IN		Typo		Lighte	Matarial
Walls					
Walls					
Walls					
	i iaiile				
	Brick Frame				
Structure Component		Feature		Source	
	Vinyl		Siding		
Wall Component Facade	Material	Color	Treatment	Source	
Sloped	Not Visible	6 .	Not Visible	_	
Roof Component	Material	Color	Treatment	Source	
EXTERIOR MATER	RIALS DATA				
Component	Featu	re			
NOTABLE FEATU					
ten feet from the sid west and is landsca Poured concrete ste	is two-story rowhouse is ewalk. The dwelling is a ped by foundation plant ps provide access to the	adjacent to 916 and 92 tings. A concrete retai	20 15th Street, S.E ining wall bounds	The grassy front to the western edge	yard slopes to the of the property.
Site Notes:					
from the southern b	ay of the rear (east) elev	ation. The rear elevat	tion was not surve	eyed or photograph	ed by the volunteer
holds a single-leaf popening on the first double-hung, vinyl-s louvered shutters. A porch has overhang which is accessed b	aneled door with lights story holds paired 9/9, ash windows and have one-story, two-bay por ing eaves and is suppo y wood steps in the so	. A square-edged bear double-hung, wood-sa false 9/9 vinyl muntin th spans the façade a rted by Tuscan wood uthern end bay. Sanbo	ded surround higl ash windows. The ns. All window ope and is set on a bri columns. Square orn maps indicate	hlights the opening e second story oper enings on the façac ck pier foundation. wood balusters en that a two-story or	j. The northernmost nings hold 1/1, de have inoperable The roof of the circle the porch, iginal ell extends
siding and is set on	ar rowhouses construct a solid brick foundation cting molded cornice w	n. A sloping roof caps	the dwelling and	is fronted along th	e façade (west
•	nstructed in 1904 by Hi	-	•		-
	al Notes:				
Exterior & Architectur	ır)				
talianate (Vernacula					

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision: Ward/ANC:

Interior Notes:

Zoning:				Designation Event(s)	1	
Contribu	uting:					
Survey(s)			Level(s) of Investigat	ion	
Capitol	Hill Southeast Pha	se I (2009/2010)		Permit Research		
				Volunteer Reconna	issance Survey	
РНОТО	OS - DIGITIZED					
Caption	:		3055 3055 3055 3055 3055			
Path:	C:\Users\CHRS\D Databases\SE Ph St\Database\Pictu 918_15STSE.JPG	ase I - D to G res\Square 1078\				
Date::	Photo	og:				
Code::		R: Fr:	1800			
РНОТО	OS - B/W OR NON	N-DIGITIZED				
Photo C	code Roll	Frame(s)	Date	Photographer	Caption	
MISCE	LLANEOUS NOT	FS DATA				
		LODAIN				
Notes:						
PERMI	IT DATA					
Permit I	ssue Date	Number Type		Remarks		
09/19/1	904	0574 Build				
Permit I	Notes:					
BIBLIC	GRAPHIC DATA					
SIGNIF	FICANCE DATA					
Study U						
Judy 0						
Code	Criteria					

DATA PROCESSING EVENTS DATA

ID Number: 1078-0802

ID Number: 1078	-0802	Year Built:	1885	Data Source:	Permit		
Number Extended	Street		Q	uad Type of Ad	dress		
912	15th Street		S				
Name(s)			Type of Na	me			
Single Dwelling, 912	15th Street, S.E.	i	Common	···· ·			
TaxCode1 TaxCode	2 TaxCode3 T	ype	Explain				
1078/0802		quare/Lot	Current				
		•					
STATUS/PURPOS	E/USE DATA						
Resource Type: Buil	ding		Status (Current: Extant	:		
Desig. Status: Hist	oric		Quality:				
Purpose: Res	idential		Condition	on: Good			
Function/Use	S	Start S	ource S	top	Source	Explain	
Residential (Single-F	amily) 1	885 P	ermit			Historic/Current	
CONSTRUCTION							
Construction Event	Start			p Sourc	е	Cost Source	
Orig Construction	1885	Perm	nit			800 Permit	
Construction Event	A	ssociation		Ass	ociated Nar	me	
Orig Construction		rchitect			nown		
Orig Construction		uilder			kins, Charl		
Orig Construction	U	wner		wes	stwood, Jo	onn 5.	
Construction Notes:							
Constructed with 91	0 15th Street, S.E	. from the s	ame permit (#1162).			
PEOPLE/EVENTS	DATA						
Racial Segregation St							
Nacial Ocylegation of	atus.						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		Cross	s Reference No	ites:		
Streetscape:	Intact						7
Relate to Othr Bldgs:	Attached						
Relate to Street:	Face on Setbac	k Line					
Massing:	Vertical Block						
Footprint:	Rectangular						
Number Stories:	2						
Bays Wide:	2				_		
Height:		-	Outbuilding T	ype	С	contributing Status	_
Width: Depth/Length:	14 28						
SqFt:	20						
Volume:							
Lot Width							
Lot Depth/Length:			Outbuilding N	otes:			_
Lot SqFt:							
Acreage:							
Has Driveway:							

Architectural Style(s)					
Italianate					
Exterior & Architectural	Notes:				
dwelling was built wit course, American-bor complemented along of the façade (west el- highlights the openin- façade hold 1/1, doub inoperable louvered s	h 910 15th Street, S.I. Ind brick and is set on the façade by a corbe evation) holds a sing g, which is accessed le-hung, vinyl-sash w hutters. A one-story, on is located on the	Charles W. Perkins, this E. from the same permin a solid brick foundation eled brick cornice and ele-leaf paneled wood do by a flight of brick stewindows and have confull-width porch has brear (east) elevation.	it (#1162). The dwellin on. A sloping roof cap a stretcher-bond bricl loor with lights. A solo ps with metal hand ra crete sills, soldier bric een removed from the	g is constructed s the dwelling a c architrave. The dier brick segments. All window of k segmental arce e façade since 1	d of mostly eight- and is a southernmost bay ental arch openings on the ches and 960. Sanborn maps
feet from the sidewall landscaped with matu to the primary entrand	c. The dwelling is adjure shrubs. A stone re ce.	s located on the east s acent to 910 and 914 1 etaining wall bounds th	5th Street, S.E. The fro	ont yard slopes	to the west and is
NOTABLE FEATUR	ES DATA				
Component	Feat	ure			
EXTERIOR MATERI	ALS DATA		Treatment	Source	
		ure Color	Treatment Not Visible	Source	
EXTERIOR MATERI Roof Component Sloped	ALS DATA Material			Source	
EXTERIOR MATERI	ALS DATA Material Not Visible	Color	Not Visible		
EXTERIOR MATERI Roof Component Sloped Wall Component	ALS DATA Material Not Visible Material	Color	Not Visible Treatment		
EXTERIOR MATERI Roof Component Sloped Wall Component Facade	ALS DATA Material Not Visible Material Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component	ALS DATA Material Not Visible Material Brick Material	Color	Not Visible Treatment	Source	
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation	ALS DATA Material Not Visible Material Brick Material Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	ALS DATA Material Not Visible Material Brick Material Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Material Not Visible Material Brick Material Brick Material Brick Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Brick Material Brick Brick	Color	Not Visible Treatment	Source	Material
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Brick Material Brick Brick	Color Color Feature	Not Visible Treatment American Bond	Source	Material Vinyl
EXTERIOR MATERI Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/INT Window Location	Material Not Visible Material Brick Material Brick Material Brick FICK Material Aperture Shape	Color Color Feature	Not Visible Treatment American Bond Lig	Source	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision: Ward/ANC: Zoning:

Designation Event(s)

Contributing:

Survey(s)	
-----------	--

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1078\

File: 912_15STSE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption

MISCELLANEOUS NOTES DATA

N١	otes:	
N	ULES.	

PERMIT DATA

Permit Notes:

Permit Issue Date	Number Type	Remarks	
12/04/1885	1162 Build		

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1078-0802 Page 3

ID Number: 1078-0051

ID Number: 1078	-0051	Year Built:	1885	Data Sou	ırce: Permit		
Number Extended	Street			Quad Type	of Address		
910	15th Street			SE Curr			
Name(s)			Type of N	Name			
Single Dwelling, 910	15th Street, S.E		Commo				
TaxCode1 TaxCode	2 TaxCode3 T	уре	Explain				
1078/0051		Square/Lot	Current	t			
STATUS/PURPOS	E/USE DATA						
Resource Type: Buil	ding		Status	s Current: I	Extant		
J	oric		Qualit	ty:			
Purpose: Row	house		Cond	lition:	Good		
Function/Use	;	Start S	Source	Stop	Source	Explain	
Residential (Single-F	amily) 1	885 P	ermit			Historic/Current	
CONSTRUCTION							
Construction Event	Star			Stop	Source	Cost Source	
Orig Construction	188	5 Pern	nit			800 Permit	
Construction Event	P	Association			Associated Nar	me	
Orig Construction		Architect			Unknown		
Orig Construction		Builder			Perkins, Charl		
Orig Construction		Owner			Westwood, Jo	onn S.	
Construction Notes:							
Constructed with 91	2 15th Street, S.	E. from the s	same permi	it (#1162).			
PEOPLE/EVENTS	DATA						
Racial Segregation St							
Nacial Ocylegation of	atus.						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		Cro	oss Referer	nce Notes:		
Streetscape:	Intact]
Relate to Othr Bldgs:	Attached						
Relate to Street:	Face on Setbac	k Line					
Massing:	Vertical Block						
Footprint:	Rectangular						
Number Stories:	2						
Bays Wide:	2			_	_		
Height:			Outbuilding	Туре	С	ontributing Status	-
Width: Depth/Length:	14 28						
SqFt:	20						
Volume:							
Lot Width							
Lot Depth/Length:			Outbuilding	Notes:			7
Lot SqFt:				_			
Acreage:							
Has Driveway:							

STYLE/EXTERIOR I	DATA					
Architectural Style(s)						
Italianate						
Exterior & Architectural	Notes:					
dwelling was built wit course, American-bon complemented along of the façade (west ele scrolled modillions ar casement windows ar	h 912 15th Street, S.E ad brick and is set on the façade by a corbe evation) holds a single end brackets shelt had have rowlock brick that an addition is	E. from the same perm a solid brick foundati eled brick cornice and le-leaf metal door and ers the entrance. All w sills, soldier brick se located on the rear (ea	s two-story, two-bay C it (#1162). The dwellin on. A sloping roof cap a stretcher-bond brick a one-light rectangula vindow openings on the gmental arches and in ast) elevation. The rear	g is constructed s the dwelling a c architrave. The r wood transom le façade hold o loperable louver	I of mostly eight- nd is southernmost bay A flat hood with ne-light metal red shutters.	
			side of 15th Street, S.E			
			Street, S.E. The grassy primary entrance of the			
NOTABLE FEATUR	ES DATA					
Component	Featu	ıre				
EXTERIOR MATERI	ALS DATA					
Roof Component	Material	Color	Treatment	Source		
Sloped	Not Visible		Not Visible			
Wall Component	Material	Color	Treatment	Source		
Facade	Brick		American Bond			
Structure Component	Material	Feature		Source		
Foundation	Brick					
Walls	Brick					
Materials Notes:						
WINDOW/DOOR/INT						
-	Aperture Shape	Type Casement	Ligi		Material	
	Rectangular	Casement		ght	Metal	
	Aperture Shape	Туре	Par	nels	Material	
Main Door	Rectangular	Single			Metal	
Notable Interior Plan(s)			Notable Interior Fe	ature(s)		
Interior Notes:						
PLAN/SURVEY/DES	SIGNATION DATA					
	itol Hill		Historic District(s)			

Zoning:

Contributing:

Survey(s)

Designation Event(s)

Level(s) of Investigation

Permit Research Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1078\

File: 910_15STSE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

40/04/4005	4400 Puild	
12/04/1885	1162 Build	

12/04/1005 1102 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

ID_Number: 1078-0051 Page 3

ID Number: 1078-0017

ID_Number: 1078-0017 Page 1

BASICS DATA

ID Numbe	r: 1078 -	-0017	Year Built:	1907	Da	ta Source:	Permit
Number	Extended	Street			Qua	d Type of Add	dress
1501		Pennsylvani	ia Avenue		SE	Current	_
904	-908	15th Street			SE	Alternate	
Name(s)				Type o	f Name	9	
Dwelling/	Store, 1501	Pennsylvania	Avenue, S.E.	Comm	on		
Pennsylva	ania Avenu	e Market		Curren	it		
TaxCode1	TaxCode	2 TaxCode3	Туре	Explai	n		
1078/0017	7		Square/Lot	Curre	nt		

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Dwelling & Store Condition: Fair

Function/Use Start Source Stop Source Explain

Dwelling & Store 1907 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Rear Addition c. 1955 Site

Visit/Maps

c. 1950 Site

Visit/Maps

Orig Construction 1907 Permit 1075 Permit

Construction EventAssociationAssociated NameOrig ConstructionArchitectWebb, C. EdgarOrig ConstructionOwnerSchlesser, J.G.Trumble, J.W.BuilderTrumble, J.W.

Construction Notes:

Rear Addition

Originally constructed as a drug store.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Lot SqFt:	Urban Intact Corner Attached Face on Line Vertical Block Rectangular (w/ additions) 2 3 21 47	Outbuilding Type Contributing Status Outbuilding Notes:	
Acreage:			
Has Driveway:			
STYLE/EXTERIOR	DATA		
Architectural Style(s)			
Classical Revival			
Exterior & Architectura	al Notes:		
concrete foundation has been painted. The of stretcher-bond briarchitrave spans the complemented by a brick stops with molethe west elevation. To door surround compaindows with heade paneled wood door whung, vinyl-sash win concrete sills and gas A two-story, full-wide addition is faced with American-bond brick window, which has a 904-908 15th Street, September 2008: Co Pennsylvania Avenu foundation; the façac caps the building an	The façade (northeast elevate east (side) elevation has lead to which simulate quoins. I façade and wraps partially projecting cornice with dent ded caps bracket the cornic he central bay of the first stoosed of pilasters and a brol r brick sills directly flank the with lights. The second stordows. The west elevation is buged brick segmental archeological archeology and the six-course, American-bonds. A flat roof caps the addition a rowlock brick sill. A first start of the six-course of the sill. A first start course of the sill cours	is a drug store. The building is constructed of brick and is set on a solid ation) and west (side) elevations are faced with stretcher-bond brick that been parged. The first story of the façade is flanked by projecting bands. The bands of brick partially wrap around to the west elevation. A molded around to the west elevation. A sloping roof caps the building and is itilis, swag molding and a molded architrave along the facade. Corbeled e and feature fleur-de-lis molding. A corbeled brick cornice complements ory holds a single-leaf wood-frame glass door. A Colonial Revival-style ken pediment with dentils highlights the opening. One-light fixed metal e door opening. The southeastern bay of the first story holds a single-leaf y window openings on the façade hold single and paired 1/1, double-fenestrated with 1/1, double-hung, vinyl-sash windows, which feature es. Several of the openings have been blocked with plywood. 1950, is located on the rear (south) elevation of the main block. The dibrick and is set on a solid foundation; also faced with six-course, on. The west elevation is fenestrated with a 1/1, double-hung, vinyl-sash cory single-leaf opening on the west elevation has been infilled with brick. 1950, four-bay Modern-style commercial building is similar to 1503 cructed of concrete blocks and is set on a solid concrete block with five-course, American-bond brick that has been painted. A flat roof tall coping. The northernmost bay of the first story holds a single-leaf	
and a one-light meta brick. The second st window and flanking concrete surround e by the volunteer surr Site Notes:	I transom. Several first wind ory is fenestrated with verting one-light fixed metal windoncloses all the second story veyor.	ansom. A second single-leaf opening contains a metal-frame glass door dow openings and a door opening on the façade have been infilled with cal tripartite windows composed of a central two-light sliding metal ows. Several of the openings have been blocked with plywood. A windows. The rear (east) elevation was not surveyed or photographed on the southeast corner of Pennsylvania Avenue, S.E. and 15th Street,	
S.E. and directly from Pennsylvania Avenu	nts the concrete sidewalk. The street is the concrete sidewalk. The street is the stre	he southeast (side) elevation of the building is adjacent to 1503 est) elevation is adjacent to 904 Pennsylvania Avenue, S.E.	
NOTABLE FEATUR	_		
Component	Feature		

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		_
Structure Component	Material	Feature		Source	
Foundation	Concrete				_
Walls	Brick				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
1 Flr Windows	Rectangular	Fixed	1-light	Metal	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
2 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single	Full Glass	Wood/Glass	
Side Door	Rectangular	Single	Paneled	Wood/Glass	
Notable Interior Plan	n(s)		Notable Interior Feature(s)		

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill
Subdivision: Historic District(s)

Ward/ANC:
Zoning:
Contributing:
Designation Event(s)

Survey(s) Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G St\Database\Pictures\Square 1078\

File: 1501_PA_AVSE_W_corner.JPG

Date:: Photog:

Code:: R: Fr:

ID_Number: 1078-0017 Page 3

Caption	:								
Path:	C:\Users\CHRS\Doct	e I - D to G							
File:	St\Database\Pictures 1501_PA_AVSEb.JP6								
Date::	Photog:								
Code::		R:	Fr:						
Caption	:								
Path:	C:\Users\CHRS\Doct Databases\SE Phase St\Database\Pictures	e I - D to G							
File:	1501_PA_AVSE-W_s								
Date::	Photog:								
Code::		R:	Fr:						
Caption	:								
Path:	C:\Users\CHRS\Docu Databases\SE Phase St\Database\Pictures	e I - D to G s\Square 1078\							
File: Date::	1501_PENNA_AVSE. Photog:	JPG							
Code::	Filolog.	R:	Fr:						
Caption									
оарион	•								
Path:	C:\Users\CHRS\Doci								
raui.	Databases\SE Phase	e I - D to G							
File:	St\Database\Pictures	-							
Date::	904-908_15SESEb.JI Photog:	PG							
Code::	Filolog.	R:	Fr:						
РНОТО	OS - B/W OR NON-D	IGITIZED							
Photo C		Frame(s)		Date	Pho	otographer	Caption		
						otog.upe.	- Сарион		
MISCE	LLANEOUS NOTES	DATA							
Notes:	-								
NOIUS.									
								J	

PERMIT DATA

Permit Issue Dat	e Numbe	r Type	Remarks	
06/01/1907	383	5 Build		
Permit Notes:				
DIDI IOODADI	UO DATA			
BIBLIOGRAPH	HIC DATA			
SIGNIFICANC	E DATA			
Study Unit			<u> </u>	
Code (Criteria			
DATA PROCE	SSING EVENTS DA	TA		

ID Number: 1078-0019

ID_Number: 1078-0019 Page 1

BASICS DATA

ID Number: 1078-0019 Year Built: 1948 Data Source: Permit

Number Extended Street Quad Type of Address

1503 Pennsylvania Avenue NW Current

Name(s) Type of Name

Apartment/Store, 1503 Pennsylvania Avenue, S.E. Common

Avenue Florist Current

TaxCode1 TaxCode2 TaxCode3 Type Explain

1078/0019 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Apartment/Store Condition: Fair

Function/Use Start Source Stop Source Explain

Residential/Store 1948 Permit Historic/Current

CONSTRUCTION DATA

 Construction Event
 Start
 Source
 Stop
 Source
 Cost Source

 Orig Construction
 1948
 Permit
 18000 Permit

Ong Construction 1946 Fernit 18000 Fernit

 Construction Event
 Association
 Associated Name

 Orig Construction
 Architect
 Conner, Evan J.

 Orig Construction
 Builder
 D & H Construction Co.

 Orig Construction
 Owner
 Buckler, Jesse & Marie

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Streetscape:	Intact					
Relate to Othr Bldgs:	Attached					
Relate to Street:	Face on Line					
Massing:	Vertical Box					
Footprint:	Triangular					
Number Stories:	2					
Bays Wide:	3					
Height:		Outbuilding Type	C	ontributing Status		
Width:						
Depth/Length:						
SqFt:						
Volume:						
Lot Width						
Lot Depth/Length:		Outbuilding Notes:				
Lot SqFt:						
Acreage:						
Has Driveway:						
,-						
STYLE/EXTERIOR	ΠΔΤΔ					
	אות					
Architectural Style(s)	1					
Modern (Commercia	1)					
a second story apart blocks and is set on parapet rises from th façade and is located bay of the first story	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block the façade of the buildin d beneath the second s holds a single-leaf met	& H Construction Compa wo-story Italianate-style r foundation; the façade (r ig and is clad with square story window openings. A tal-frame glass door and a pening; both have been bl	owhouse. The bunortheast elevation concrete panels. It is to concrete panels. It is to concrete panels to co	ilding is constructed on has been mostly part A concrete string coub building. The souther mand the northweste	of concrete irged. A irse spans t astern end irn end bay	ne
September 2008: Co a second story apart blocks and is set on parapet rises from th façade and is located bay of the first story has a single-leaf ope holds a band of mult story window openir	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block he façade of the building beneath the second s holds a single-leaf met ning and a transom op i-light fixed wood wind hogs hold 2/2, double-hu	wo-story Italianate-style r foundation; the façade (r g and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies ing, wood-sash windows.	owhouse. The bunortheast elevation concrete panels. Italian roof caps the concelight transoucked with plywors shelter all of the A square-edged	ilding is constructed on has been mostly part A concrete string court building. The souther mand the northweste od. The central bay of first story openings.	of concrete orged. A orse spans the astern end orn end bay of the first sto of concrete	ne
September 2008: Co a second story apart blocks and is set on parapet rises from the façade and is located bay of the first story has a single-leaf ope holds a band of multistory window opening second story window	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block he façade of the building beneath the second s holds a single-leaf met ning and a transom op i-light fixed wood wind hogs hold 2/2, double-hu	wo-story Italianate-style r foundation; the façade (r g and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies	owhouse. The bunortheast elevation concrete panels. Italian roof caps the concelight transoucked with plywors shelter all of the A square-edged	ilding is constructed on has been mostly part A concrete string court building. The souther mand the northweste od. The central bay of first story openings.	of concrete orged. A orse spans the astern end orn end bay of the first sto of concrete	ne
September 2008: Co a second story apart blocks and is set on parapet rises from the façade and is located bay of the first story has a single-leaf open holds a band of multistory window opening second story window Site Notes:	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block he façade of the building d beneath the second s holds a single-leaf met aning and a transom op hi-light fixed wood wind hogs hold 2/2, double-hutes and emphasizes the	wo-story Italianate-style r foundation; the façade (r ig and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies ing, wood-sash windows. horizontality of the seco	owhouse. The but northeast elevation concrete panels. Iflat roof caps the arrow ooked with plyworks shelter all of the A square-edged and story.	ilding is constructed on has been mostly particle of the concrete string court building. The souther mand the northweste od. The central bay of first story openings. It concrete surround end	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from the façade and is located bay of the first story has a single-leaf operation of multistory window opening second story window Site Notes: September 2008: This blocks a second story window Site Notes:	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block he façade of the buildin beneath the second s holds a single-leaf met aning and a transom op i-light fixed wood wind holds a single-hu ws and emphasizes the s two-story apartment	wo-story Italianate-style r foundation; the façade (r g and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies ing, wood-sash windows.	owhouse. The but northeast elevation concrete panels. Iflat roof caps the arone-light transpocked with plyworks shelter all of the A square-edged and story.	ilding is constructed of n) has been mostly pa A concrete string cout building. The souther m and the northweste od. The central bay of first story openings. I concrete surround end of Pennsylvania Aver	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from the façade and is located bay of the first story has a single-leaf operation of multistory window opening second story window Site Notes: September 2008: This blocks a second story window Site Notes:	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block he façade of the buildin beneath the second s holds a single-leaf met aning and a transom op i-light fixed wood wind holds a single-hu ws and emphasizes the s two-story apartment	two-story Italianate-style refoundation; the façade (refoundation; the façade (refoundation; the façade (refoundation); the façade (refoundation); and store is located on the foundation of the secondation of the secondatio	owhouse. The but northeast elevation concrete panels. Iflat roof caps the arone-light transpocked with plyworks shelter all of the A square-edged and story.	ilding is constructed of n) has been mostly pa A concrete string cout building. The souther m and the northweste od. The central bay of first story openings. I concrete surround end of Pennsylvania Aver	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from the façade and is located bay of the first story has a single-leaf open holds a band of multistory window opening second story window Site Notes: September 2008: This directly fronts the control of the second story window open in the control of the second story window story	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block a façade of the building beneath the second sholds a single-leaf mething and a transom opi-light fixed wood wings hold 2/2, double-huws and emphasizes the stwo-story apartment increte sidewalk. The b	two-story Italianate-style refoundation; the façade (refoundation; the façade (refoundation; the façade (refoundation); the façade (refoundation); and store is located on the foundation of the secondation of the secondatio	owhouse. The but northeast elevation concrete panels. Iflat roof caps the arone-light transpocked with plyworks shelter all of the A square-edged and story.	ilding is constructed of n) has been mostly pa A concrete string cout building. The souther m and the northweste od. The central bay of first story openings. I concrete surround end of Pennsylvania Aver	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from the façade and is located bay of the first story has a single-leaf open holds a band of multistory window openir second story window. Site Notes: September 2008: This directly fronts the county fronts the county window.	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block the façade of the building the beneath the second s holds a single-leaf met ning and a transom op i-light fixed wood winc type and emphasizes the stwo-story apartment the crete sidewalk. The b	two-story Italianate-style r foundation; the façade (r ag and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies and, wood-sash windows. Thorizontality of the secon and store is located on the building is adjacent to 150	owhouse. The but northeast elevation concrete panels. Iflat roof caps the arone-light transpocked with plyworks shelter all of the A square-edged and story.	ilding is constructed of n) has been mostly pa A concrete string cout building. The souther m and the northweste od. The central bay of first story openings. I concrete surround end of Pennsylvania Aver	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from the façade and is located bay of the first story has a single-leaf open holds a band of multistory window opening second story window Site Notes: September 2008: Thi	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block a façade of the building beneath the second sholds a single-leaf mething and a transom opi-light fixed wood wings hold 2/2, double-huws and emphasizes the stwo-story apartment increte sidewalk. The b	two-story Italianate-style r foundation; the façade (r ag and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies and, wood-sash windows. Thorizontality of the secon and store is located on the building is adjacent to 150	owhouse. The but northeast elevation concrete panels. Iflat roof caps the arone-light transpocked with plyworks shelter all of the A square-edged and story.	ilding is constructed of n) has been mostly pa A concrete string cout building. The souther m and the northweste od. The central bay of first story openings. I concrete surround end of Pennsylvania Aver	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from the façade and is located bay of the first story has a single-leaf open holds a band of multistory window openir second story window. Site Notes: September 2008: This directly fronts the county fronts the county window.	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block the façade of the building the beneath the second s holds a single-leaf met ning and a transom op i-light fixed wood winc type and emphasizes the stwo-story apartment the crete sidewalk. The b	two-story Italianate-style r foundation; the façade (r ag and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies and, wood-sash windows. Thorizontality of the secon and store is located on the building is adjacent to 150	owhouse. The but northeast elevation concrete panels. Iflat roof caps the arone-light transpocked with plyworks shelter all of the A square-edged and story.	ilding is constructed of n) has been mostly pa A concrete string cout building. The souther m and the northweste od. The central bay of first story openings. I concrete surround end of Pennsylvania Aver	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from the façade and is located bay of the first story has a single-leaf operation of multistory window opening second story window. Site Notes: September 2008: This directly fronts the component	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block te façade of the buildin d beneath the second s holds a single-leaf met ening and a transom op i-light fixed wood wind tys and emphasizes the s two-story apartment encrete sidewalk. The b	two-story Italianate-style r foundation; the façade (r ag and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies and, wood-sash windows. Thorizontality of the secon and store is located on the building is adjacent to 150	owhouse. The but northeast elevation concrete panels. Iflat roof caps the arone-light transpocked with plyworks shelter all of the A square-edged and story.	ilding is constructed of n) has been mostly pa A concrete string cout building. The souther m and the northweste od. The central bay of first story openings. I concrete surround end of Pennsylvania Aver	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from the façade and is located bay of the first story has a single-leaf operation of multistory window opening second story window. Site Notes: September 2008: This directly fronts the component	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block te façade of the buildin d beneath the second s holds a single-leaf met ening and a transom op i-light fixed wood wind tys and emphasizes the s two-story apartment encrete sidewalk. The b	two-story Italianate-style r foundation; the façade (r ag and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies and, wood-sash windows. Thorizontality of the secon and store is located on the building is adjacent to 150	owhouse. The but northeast elevation concrete panels. Iflat roof caps the arone-light transpocked with plyworks shelter all of the A square-edged and story.	ilding is constructed of n) has been mostly pa A concrete string cout building. The souther m and the northweste od. The central bay of first story openings. I concrete surround end of Pennsylvania Aver	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from the façade and is located bay of the first story has a single-leaf operation of multistory window openir second story window. Site Notes: September 2008: This directly fronts the component EXTERIOR MATER	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block he façade of the buildin d beneath the second s holds a single-leaf met ning and a transom op i-light fixed wood wind yes and emphasizes the s two-story apartment ncrete sidewalk. The b RES DATA Featu	rwo-story Italianate-style r foundation; the façade (r ag and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies and, wood-sash windows. Thorizontality of the secon and store is located on the building is adjacent to 150	owhouse. The but northeast elevation concrete panels. Italian roof caps the area one-light transo ocked with plyworks shelter all of the A square-edged and story. The southwest side and 1505 Penns	ilding is constructed on has been mostly particle of A concrete string court building. The souther mand the northweste od. The central bay of first story openings. To concrete surround ender of Pennsylvania Averue, S.E.	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from the façade and is located bay of the first story has a single-leaf open holds a band of multistory window openir second story window. Site Notes: September 2008: This directly fronts the component EXTERIOR MATER	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block he façade of the buildin d beneath the second s holds a single-leaf met ning and a transom op i-light fixed wood wind hos and emphasizes the s two-story apartment horcrete sidewalk. The b RES DATA RIALS DATA Material	two-story Italianate-style r foundation; the façade (r ag and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies and, wood-sash windows. Thorizontality of the secon and store is located on the building is adjacent to 150	owhouse. The but northeast elevation concrete panels. Iflat roof caps the area one-light transor ocked with plyworks shelter all of the Arguare-edged and story.	ilding is constructed of n) has been mostly pa A concrete string cout building. The souther m and the northweste od. The central bay of first story openings. I concrete surround end of Pennsylvania Aver	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from the façade and is located bay of the first story has a single-leaf open holds a band of multistory window opening second story window. Site Notes: September 2008: This directly fronts the component EXTERIOR MATER Roof Component	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block te façade of the buildin d beneath the second s holds a single-leaf met ening and a transom op i-light fixed wood wind tys and emphasizes the s two-story apartment encrete sidewalk. The b RES DATA RIALS DATA Material Not Visible	rwo-story Italianate-style r foundation; the façade (r g and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies ing, wood-sash windows. Individual canopies and store is located on th building is adjacent to 150 Color	owhouse. The but northeast elevation of concrete panels. Ital roof caps the annual one-light transon ocked with plyworks helter all of the A square-edged and story. Treatment Not Visible	ilding is constructed on has been mostly particle of the concrete string court building. The southers mand the northwester od. The central bay of first story openings. It concrete surround ender of Pennsylvania Avenue, S.E.	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from th façade and is located bay of the first story has a single-leaf ope holds a band of mult story window openir second story window Site Notes: September 2008: Thi directly fronts the co NOTABLE FEATUR Component EXTERIOR MATER Roof Component Flat Wall Component	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block the façade of the building d beneath the second s holds a single-leaf met ening and a transom op i-light fixed wood wind togs hold 2/2, double-hu tws and emphasizes the stwo-story apartment encrete sidewalk. The b RES DATA Material Not Visible Material	rwo-story Italianate-style r foundation; the façade (r g and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies ing, wood-sash windows. The horizontality of the secon and store is located on th building is adjacent to 150 Tre Color	owhouse. The but northeast elevation concrete panels. Iflat roof caps the among concern on the among coked with plywords shelter all of the Among coked with plywords and story. Treatment Treatment Not Visible Treatment	ilding is constructed on has been mostly particle of A concrete string court building. The souther mand the northweste od. The central bay of first story openings. To concrete surround ender of Pennsylvania Averue, S.E.	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from the façade and is located bay of the first story has a single-leaf open holds a band of multistory window openir second story window. Site Notes: September 2008: This directly fronts the component EXTERIOR MATER	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block te façade of the buildin d beneath the second s holds a single-leaf met ening and a transom op i-light fixed wood wind tys and emphasizes the s two-story apartment encrete sidewalk. The b RES DATA RIALS DATA Material Not Visible	rwo-story Italianate-style r foundation; the façade (r g and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies ing, wood-sash windows. The horizontality of the secon and store is located on th building is adjacent to 150 Tre Color	owhouse. The but northeast elevation of concrete panels. Ital roof caps the annual one-light transon ocked with plyworks helter all of the A square-edged and story. Treatment Not Visible	ilding is constructed on has been mostly particle of the concrete string court building. The southers mand the northwester od. The central bay of first story openings. It concrete surround ender of Pennsylvania Avenue, S.E.	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from th façade and is located bay of the first story has a single-leaf ope holds a band of mult story window openir second story window Site Notes: September 2008: Thi directly fronts the co NOTABLE FEATUR Component EXTERIOR MATER Roof Component Flat Wall Component	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block the façade of the building d beneath the second s holds a single-leaf met ening and a transom op i-light fixed wood wind togs hold 2/2, double-hu tws and emphasizes the stwo-story apartment encrete sidewalk. The b RES DATA Material Not Visible Material	rwo-story Italianate-style r foundation; the façade (r g and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies ing, wood-sash windows. The horizontality of the secon and store is located on th building is adjacent to 150 Tre Color	owhouse. The but northeast elevation concrete panels. Iflat roof caps the among concern on the among coked with plywords shelter all of the Among coked with plywords and story. Treatment Treatment Not Visible Treatment	ilding is constructed on has been mostly particle of the concrete string court building. The southers mand the northwester od. The central bay of first story openings. It concrete surround ender of Pennsylvania Avenue, S.E.	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from the façade and is located bay of the first story has a single-leaf open holds a band of multistory window opening second story window. Site Notes: September 2008: This directly fronts the component EXTERIOR MATER Roof Component Flat Wall Component	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block he façade of the buildin d beneath the second s holds a single-leaf met ning and a transom op i-light fixed wood wind hos and emphasizes the s two-story apartment crete sidewalk. The b RES DATA Material Not Visible Material Concrete Block	rewo-story Italianate-style representation foundation; the façade (regrand is clad with square story window openings. A stal-frame glass door and abening; both have been blows. Individual canopiesing, wood-sash windows. Individual canopiesing wood-sash wood-sash windows. Individual canopiesing wood-sash windows. Individual canopiesing wood-sash wood-sa	owhouse. The but northeast elevation concrete panels. Iflat roof caps the among concern on the among coked with plywords shelter all of the Among coked with plywords and story. Treatment Treatment Not Visible Treatment	ilding is constructed on has been mostly participated on his bounder of the central bay of first story openings. To concrete surround ender of Pennsylvania Averagilvania Avenue, S.E. Source Source	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from th façade and is located bay of the first story has a single-leaf ope holds a band of mult story window openir second story window Site Notes: September 2008: Thi directly fronts the co NOTABLE FEATUL Component EXTERIOR MATER Roof Component Flat Wall Component Facade Structure Component	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block he façade of the buildin d beneath the second s holds a single-leaf met ning and a transom op i-light fixed wood wind holds and emphasizes the stwo-story apartment horrete sidewalk. The b RES DATA RIALS DATA Material Not Visible Material Concrete Block Material	rwo-story Italianate-style r foundation; the façade (r g and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies ing, wood-sash windows. horizontality of the secon and store is located on the building is adjacent to 150 Color Color Feature	owhouse. The but northeast elevation concrete panels. Iflat roof caps the among concern on the among coked with plywords shelter all of the Among coked with plywords and story. Treatment the Treatment of the Treatmen	ilding is constructed on has been mostly participated on his bounder of the central bay of first story openings. To concrete surround ender of Pennsylvania Averagilvania Avenue, S.E. Source Source	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from th façade and is located bay of the first story has a single-leaf ope holds a band of mult story window openir second story window Site Notes: September 2008: Thi directly fronts the co NOTABLE FEATUR Component EXTERIOR MATER Roof Component Flat Wall Component Facade Structure Component Foundation Walls	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block le façade of the buildin d beneath the second s holds a single-leaf met ning and a transom op i-light fixed wood wind logs hold 2/2, double-hu vs and emphasizes the s two-story apartment increte sidewalk. The b RES DATA RIALS DATA Material Not Visible Material Concrete Block Material Concrete Block	rwo-story Italianate-style r foundation; the façade (r g and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies ing, wood-sash windows. horizontality of the secon and store is located on the building is adjacent to 150 Color Color Feature	owhouse. The but northeast elevation concrete panels. Iflat roof caps the among concern on the among coked with plywords shelter all of the Among coked with plywords and story. Treatment the Treatment of the Treatmen	ilding is constructed on has been mostly participated on his bounder of the central bay of first story openings. To concrete surround ender of Pennsylvania Averagilvania Avenue, S.E. Source Source	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e
September 2008: Co a second story apart blocks and is set on parapet rises from th façade and is located bay of the first story has a single-leaf ope holds a band of mult story window openir second story window Site Notes: September 2008: Thi directly fronts the co NOTABLE FEATUL Component EXTERIOR MATER Roof Component Flat Wall Component Facade Structure Component Foundation	nstructed in 1948 by D ment replaced a 1909 t a solid concrete block le façade of the buildin d beneath the second s holds a single-leaf met ning and a transom op i-light fixed wood wind logs hold 2/2, double-hu vs and emphasizes the s two-story apartment increte sidewalk. The b RES DATA RIALS DATA Material Not Visible Material Concrete Block Material Concrete Block	rwo-story Italianate-style r foundation; the façade (r g and is clad with square story window openings. A tal-frame glass door and a bening; both have been bl dows. Individual canopies ing, wood-sash windows. horizontality of the secon and store is located on the building is adjacent to 150 Color Color Feature	owhouse. The but northeast elevation concrete panels. Iflat roof caps the among concern on the among coked with plywords shelter all of the Among coked with plywords and story. Treatment the Treatment of the Treatmen	ilding is constructed on has been mostly participated on his bounder of the central bay of first story openings. To concrete surround ender of Pennsylvania Averagilvania Avenue, S.E. Source Source	of concrete arged. A arse spans the astern end arn end bay the first sto The second closes all th	ne ry e

1AP 1 1 P		-	11.14		
Window Location	Aperture Shape	Туре	Lights	Material	
1 Flr Windows	Rectangular	Fixed	Multi-lite	Wood	
2 FIr Windows	Rectangular	Dbl-Hung	2/2	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
First Floor	Rectangular	Single	Full Glass	Metal/Glas	
Notable Interior Plar	n(s)		Notable Interior Feature(s)		
nterior Notes:					
PLAN/SURVEY/D	ESIGNATION DATA				
-	Capitol Hill		Historic District(s)		
Subdivision:					
Ward/ANC: Zoning:			Designation Event(s)		
Contributing:					
Survey(s)			Level(s) of Investigation		
	ast Phase I (2009/2010))	Permit Research		
			Volunteer Reconnaissance	Survey	
NICTOR DIGIT	1750				
	ZED				
Caption: Path: C:\Users\ (CHRS\Documents\CHRS	s			
Caption: Path: C:\Users\0 Databases St\Databas	CHRS\Documents\CHRS \SE Phase I - D to G se\Pictures\Square 1076				
Caption: Path: C:\Users\C Databases St\Database File: 1503_PA_	CHRS\Documents\CHRS \SE Phase I - D to G se\Pictures\Square 1076				
Caption: Path: C:\Users\C Databases St\Database File: 1503_PA_	CHRS\Documents\CHRS S\SE Phase I - D to G se\Pictures\Square 1076 AVSE.JPG				
Path: C:\Users\C Databases St\Databases I503_PA_	CHRS\Documents\CHRS S\SE Phase I - D to G se\Pictures\Square 1076 AVSE.JPG Photog: R:	81			
Path: C:\Users\C Databases St\Databases I503_PA_	CHRS\Documents\CHRS \SE Phase I - D to G se\Pictures\Square 107 AVSE.JPG Photog:	8\ Fr:	Photographer C	aption	
Path: C:\Users\C Databases St\Databases I503_PA_	CHRS\Documents\CHRS S\SE Phase I - D to G se\Pictures\Square 1076 AVSE.JPG Photog: R: PR NON-DIGITIZED Roll Frame(s	8\ Fr:	Photographer C	aption	
Path: C:\Users\C Databases St\Databases File: 1503_PA_ Date:: Code:: PHOTOS - B/W C Photo Code	CHRS\Documents\CHRS S\SE Phase I - D to G se\Pictures\Square 1076 AVSE.JPG Photog: R: PR NON-DIGITIZED Roll Frame(s	8\ Fr:	Photographer C	aption	
Databases St\Database St\Database File: 1503_PA_ Date:: Code::	CHRS\Documents\CHRS S\SE Phase I - D to G se\Pictures\Square 1076 AVSE.JPG Photog: R: PR NON-DIGITIZED Roll Frame(s	8\ Fr:	Photographer C	aption	
Caption: Captio	CHRS\Documents\CHRS S\SE Phase I - D to G se\Pictures\Square 1076 AVSE.JPG Photog: R: PR NON-DIGITIZED Roll Frame(s	8\ Fr:	Photographer C	aption	
Caption: Path: C:\Users\C Databases St\Database St\Database Code:: PHOTOS - B/W C Photo Code MISCELLANEOU Notes: PERMIT DATA Permit Issue Date	CHRS\Documents\CHRS S\SE Phase I - D to G se\Pictures\Square 1076 AVSE.JPG Photog: R: PR NON-DIGITIZED Roll Frame(s	Fr: S) Date	Photographer C	aption	
Path: C:\Users\C Databases St\Databases File: 1503_PA_ Date:: Code:: PHOTOS - B/W C Photo Code	CHRS\Documents\CHRS\S\SE Phase I - D to G se\Pictures\Square 1076 AVSE.JPG Photog: R: OR NON-DIGITIZED Roll Frame(s	Fr: Date		caption	
Caption: Path: C:\Users\C Databases St\Database St\Database Code:: PHOTOS - B/W C Photo Code MISCELLANEOU Notes: PERMIT DATA Permit Issue Date	CHRS\Documents\CHRS\S\SE Phase I - D to G se\Pictures\Square 1076 AVSE.JPG Photog: R: PR NON-DIGITIZED Roll Frame(s	Fr: Date		aption	

SIGNIFIC	CANCE DATA		
Study Unit			
Code	Criteria		
ΠΔΤΔ ΡΕ	ROCESSING EVENTS DATA		

ID Number: 1078-0005

BASICS DATA

ID Number: 1078-0005 Year Built: c. 1955 Data Source: Site Visit/Map Number Extended Street Quad Type of Address 1512 K Street SE Current Name(s) Type of Name Church, 1512 K Street, S.E. Common **World of God Baptist Church** Current TaxCode1 TaxCode2 TaxCode3 Type Explain 1078/0005 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Church Condition: Fair

Function/Use Start Source Stop Source Explain

Church/Sunday School c. 1955 Site Visit/

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction c. 1955 Site

Visit/Maps Site

Rear Addition Site Visit/Maps

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

ID_Number: 1078-0005 Page 1

Surroundings:	Urban	Cross Re	eference Notes:		
Streetscape:	Intact				
Relate to Othr Bldgs:	Freestanding				
Relate to Street:	Front Yard w/ Setback				
Massing:	Block				
Footprint:	Rectangular				
Number Stories:	1				
Bays Wide:	5				
Height:	· ·	Outbuilding Type	C	Contributing Status	
Width:		Sign		John Balling Clarac	
Depth/Length:		Olgii			
SqFt:					
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes	<u>.</u>		
Lot SqFt:				d of brick, is located south	
Acreage:			d was constructed of		
Has Driveway:	1				
ilas Dilveway.					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
					
Exterior & Architectura	al Notes:				
ends of the church a roof caps the dwellin pierces the eastern shaped lights. A one The front-gabled root support the roof and The window opening (side) elevations are surveyor. Sanborn in surveyed or photographic A one-story concrete shed roof. Site Notes: September 2008: The approximately ten fee	are clad with German vinyling and is covered with aspectope of the church. The coestory, one-bay porch she of of the porch features a bid are set on the concrete bigs on the façade hold 1/1, applicated by window opening indicate that a one-straphed by the volunteer sure block addition is located is one-story freestanding of	siding. Parged pila phalt shingles. Ove entral bay of the factor of the primary erroxed cornice and it lock foundation. A double-hung sashings, however, the record of the property of the proveyor. on the northeast contact of the proveyor of the protect of the proveyor of the proveyor of the proveyor of the protect of the proveyor of the proveyor of the proveyor of the protect of the proveyor of	asters complement to rhanging eaves finis cade holds double-leatrance and is set on s covered with asph solid concrete block windows and have comuntin configuration in the north (rear) eleate orner of the east (sident yard is lined by a	have been parged. The upper he side elevations. A front-gath the roof. An interior brick of the part metal doors with diamond a solid concrete block foun that shingles. Tuscan column to balustrade completes the proncrete sills. The north and the was not surveyed by the volvation. The rear elevation was deep elevation and is capped to be considered to the property of the property	abled chimney d- dation. s orch. south lunteer as not
NOTABLE FEATU	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Gable	Asphalt		Shingled		
Wall Component	Material	Color	Treatment	Source	
Facade	Concrete Block		Parged		
Structure Component					
Otraotare Component	Material	Feature		Source	

Concrete Block

Walls

Materials Notes:				
WINDOW/DOOR/	INTERIOR DATA			
Window Location	Aperture Shape	Туре	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Unknown
Door Location	Aperture Shape	Type	Pamels	Material
Main Door	Rectangular	Double		Metal/Glas
Notable Interior Plan	n(s)		Notable Interior Feature(s)	
Lateria - Nata				
Interior Notes:				
	DESIGNATION DATA			
Neighborhood: Subdivision:	Capitol Hill		Historic District(s)	
Ward/ANC:				
Zoning:			Designation Event(s)	
Contributing:				
Survey(s)			Level(s) of Investigation	
Capitol Hill Southe	east Phase I (2009/2010)		Permit Research	
			Volunteer Reconnaissance Su	rvey
PHOTOS - DIGIT	IZED			
Caption:				
Path: C:\lleare\0	CHRS\Documents\CHRS			
Databases	s\SE Phase I - D to G			
St\Databa	se\Pictures\Square 1078\ 'SEa.JPG			
Date::	Photog:			
Code::	R:	Fr:		
Caption:				
Path: C:\Users\(CHRS\Documents\CHRS			
Databases	s\SE Phase I - D to G			
St\Databa	se\Pictures\Square 1078\			
Date::	Photog:			
Code:	Priotog.	Er:		

Caption:

Path:	Databases\	SE Phase	ments\CHRS I - D to G \Square 1078\							
File:	1512_KSTS	Ec.JPG								
Date::		Photog:								
Code::			R:	Fr:						
РНОТО	OS - B/W OF	R NON-DI	GITIZED							
Photo C	ode	Roll	Frame(s)	Dat	е	Photog	ırapher	Caption	า	
MISCE	LLANEOUS	NOTES	DATA							
Notes:										
PERMI	T DATA									
Permit I	ssue Date		Number Type			Remarks				<u></u>
Permit N	Notes:									
BIBLIC	GRAPHIC [DATA								
SIGNIF	ICANCE DA	ATA								
Study U	Init									
Code	Criter	ia								
ΠΔΤΔ	PROCESSIN	IG EVEN	TS DATA							

ID Number: 1078-0044

-							
ID Number: 1078	3-0044	Year Bu	uilt: c. 1955	Data	Source: Site	· Visit/Map	
Number Extended	Street			Quad	Type of Address		
1516	K Street			SE (Current		
Name(s)			Туре	of Name			
Apartment Building,	1516 K Street,	S.E.	Comr	mon			
The Logos Building			Curre	ent			
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	ain			
1078/0044		Square/L	ot Curr	ent		_	
CTATUS/DUDDOS	E/UCE DATA						
STATUS/PURPOS Resource Type: Bui			Q+	atus Curre	ent: Extant		
	toric			uality:	inc. Lataire		
_	rtment			ndition:	Good		
•		_		_			
Function/Use		Start	Source	Stop	Source	Explain Historic/Current	
Residential (Multi-Fa	amiiy)	c. 1955	Site Visit	1		Historic/Current	
CONSTRUCTION	DATA						
Construction Event	Sta	art S	Source	Stop	Source	Cost Source	
Orig Construction	C.	1955	Site	•			
		'	/isit/Maps				
Construction Event		Association	n		Associated	d Name	
Construction Notes:							
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/	SIZE DATA						
Surroundings:	Urban			Cross Ref	erence Notes:		
Streetscape:	Intact						
Relate to Othr Bldgs:	Freestanding						
Relate to Street:	Face on Setba	ack Line					
Massing:	Vertical Block	(
Footprint:	Irregular						
Number Stories:	3 plus ba	sement					
Bays Wide:	o p. a.o .a.						
Height:			Outbuild	ing Type		Contributing Status	
Width:			-	0 71		<u> </u>	
Depth/Length:							
SqFt:							
Volume:							
Lot Width							
Lot Depth/Length:			Outbuild	ing Notes:	•		
Lot SqFt:							
Acreage:							
Has Driveway:							

Architectural Style(s)					
Modern					
building is constructive-course, America first and third story south elevation hold rectangular bay projoriginal and has the central sliding one-liftom the eastern end sliding one-light vin (rear) elevations were	al Notes: onstructed c. 1955, this the ded of concrete blocks a can-bond brick. Stretcherwindow openings. The red sliding one-light vinyl viects from the western er material treatment of the ight vinyl windows and fed bay and is original to the light vindows. All windows re not surveyed or photo is three-story free-standing is three-story free-standing in the light vindows.	nd is set on a solid, bond beltcourses er oof of the building is vindows and 1/1, dound of the south elevate main block. Fenest lanking one-light vince main block and had on the south elevate graphed by the voluments.	raised concrete bloch neircle the building a cobscured by a brick uble-hung, vinyl-sash tion and is set on a retation consists of tri lyl fixed windows. A set the same material ion have rowlock brief inteer surveyor.	k foundation; both nd are located bel parapet. The cent windows. A three raised foundation. partite windows c three-story, rectan treatment. Fenest ck sills. The east,	are faced with ow and above the cral bays of the e-story, The bay is omposed of gular bay projects ration consists of west, and north
	tely ten feet from the stre e building. Metal chain-l			vith mature shrub	s. A concrete drive
		<u> </u>	· · ·		
NOTABLE FEATU					
Component	Feature	9			
EXTERIOR MATEI	Material	Color	Treatment	Source	
Not Visible	Not Visible		Not Visible		
Wall Component	Material Brick	Color	Treatment American Bond	Source	
Facade	Brick		American Bond		
Structure Component	Material	Feature		Source	
Foundation Walls	Concrete Block Concrete Block				
	Coliciete Block				
Materials Notes:					
WINDOW/DOOR/II	NTERIOR DATA				
Window Location	Aperture Shape	Туре	Li	ghts	Material
Facade	Rectangular	Dbl-Hung	1/	<u> </u>	Vinyl
Facade -	Rectangular	Sliding		light	Vinyl
Facade	Tripartite	Fixed	1-	light	Vinyl
Door Location	Aperture Shape	Туре	Pa	amels	Material
Notable Interior Plan(s)		Notable Interior F	Feature(s)	
Interior Notes:					
PLAN/SURVEY/DE	ESIGNATION DATA				
Subdivision:	apitol Hill		Historic District(s)	
Ward/ANC: Zoning:			Designation Ever	nt(s)	

STYLE/EXTERIOR DATA

Contrib	uting:							
			l aval(a) af lavasticati					
Survey(Capitol	Bill Southeast Phase I (2009/2010))	Permit Research Volunteer Reconnais					
РНОТ	OS - DIGITIZED							
Caption	:							
Path:	C:\Users\CHRS\Documents\CHR: Databases\SE Phase I - D to G St\Database\Pictures\Square 107 1516_KSTSE.JPG							
Date:: Code::	Photog: R:	Fr:						
Caption	i:							
Path:	C:\Users\CHRS\Documents\CHR: Databases\SE Phase I - D to G St\Database\Pictures\Square 107 1516_KSTSE-Eside.JPG							
Date::	Photog:							
Code::	R:	Fr:						
РНОТ	OS - B/W OR NON-DIGITIZED							
Photo C	Code Roll Frame(s) Date	Photographer	Caption				
MISCE	ELLANEOUS NOTES DATA							
Notes:								
PERM	IT DATA							
Permit	Issue Date Number Ty	ре	Remarks					
Permit	Notes:							
BIBLIC	OGRAPHIC DATA							
SIGNII	FICANCE DATA							
Study L	Jnit							
Code	Criteria							

ID Number: 1078-0052

ID Number: 1078	-0052	Year Built	1985	Data	a Source: Sanbo	rn Map	
Number Extended	Street			Quad	Type of Address		
1539 -1557	Pennsylvan	ia Avenue			Current		
Name(s)			Type of	f Name			
Restaurant, 1539-155	7 Pennsylvar	nia Avenue, S	E. Comm	on			
McDonald's			Curren	t			
TaxCode1 TaxCode	2 TaxCode3	,,	Explai	n			
1078/0052		Square/Lot	Curre	nt			
STATUS/PURPOS	E/USE DATA	\					
Resource Type: Buil	ding		Stat	us Curr	ent: Extant		
Desig. Status: Not	Historic		Qua	ality:			
Purpose: Res	taurant		Con	dition:	Good		
Function/Use		Start	Source	Stop	Source	Explain	
Restaurant/Carry-ou	t	1985	Sanborn M			Historic/Current	
CONSTRUCTION	DATA						
Construction Event			ırce	Stop	Source	Cost Source	
Orig Construction	19	985 Sai	nborn Map				
Construction Event		Association			Associated Na	ame	
Construction Notes: PEOPLE/EVENTS	DATA						
Racial Segregation St	atus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		C	ross Re	eference Notes:		
Streetscape:	Intact						
Relate to Othr Bldgs: Relate to Street:	Freestanding Paved Setba						
Massing:	Block	OK .					
Footprint:	Irregular						
Number Stories:							
Bays Wide:							
Height:			Outbuildin	ng Type	(Contributing Status	_
Width:							
Depth/Length: SqFt:							
Volume:							
Lot Width							
Lot Depth/Length:			Outbuildir	ng Notes	s:		_
Lot SqFt:							
Acreage:							
Has Driveway:							

Architectural Style(s)						
Commercial (Mode	rn)						
Exterior & Architectu	ıral Notes:						
wing located on the constructed of con panels. Belt course block and wing and	his two-story commercia e east elevation. The bui crete blocks and is set o es of rowlock brick encir d are complemented by r -light fixed metal windov	Iding features numeron on a solid concrete blo cle the main block and metal coping. The wes	ous projecting and rec ock foundation; both a d are sporadically loc	essed bays. The are faced with squated. Flat roofs ca	building is uare concrete ap both the main		
	ation of the one-story wi	•	_		e-thru windows		
Site Notes:							
	his two-story commercia ilding is sited on a aspha						
NOTABLE FEAT	JRES DATA						
Component	Featu	re					
EXTERIOR MATE	ERIALS DATA						
	Material	Color	Treatment	Source			
Roof Component Flat	Not Visible	Coloi	Not Visible	Source			
Wall Component	Material	Color	Treatment	Source			
Facade	Concrete	00101	Veneer	Oddicc			
Structure Componer	nt Material	Feature		Source			
Foundation	Concrete Block			Source			
Walls	Concrete Block						
Materials Notes:							
WINDOW/DOOR/	INTERIOR DATA						
Window Location	Aperture Shape	Туре	Lights		Material		
Windows (All)	Rectangular	Fixed	1-1	ight	Metal		
Door Location	Aperture Shape	Туре	Pa	mels	Material		
Notable Interior Plan	n(s)		Notable Interior Feature(s)				
Interior Notes:							
PLAN/SURVEY/D	ESIGNATION DATA						
Neighborhood: (Capitol Hill		Historic District(s)				
Subdivision:							
Ward/ANC: Zoning:			Designation Event(s)				
Contributing:				· /			
Survey(s)			Level(s) of Investi	gation			
	ast Phase I (2009/2010)		Permit Research				

STYLE/EXTERIOR DATA

Volunteer Reconnaissance Survey

РНОТ	OS - DIGITI	IZED									
Caption	ı:										
Path:	Databases	SE Phase	ments\CHRS I - D to G \Square 1078\								
File:	1539_PA_										
Date::		Photog:									
Code::			R:	Fr:							
Caption	1.										
Path:	Databases St\Databas	s\SE Phase se\Pictures	\Square 1078\								
File:	1539_PA_ <i>i</i>	AVSE-Eside	e.JPG								
Date:: Code::		Photog:	R:	Fr:							
Caption	ı:										
Path:	Databases St\Databas	s\SE Phase se\Pictures	\Square 1078\								
File: Date::	1539_PA_/	AVSE-W_si Photog:	de.JPG								
Code::		i notog.	R:	Fr:							
риот	OS - B/W O	NON-DI	GITIZED								
Photo C		Roll	Frame(s)		Date	F	Photographer	Caption			
			` ` `					·			
MISCE	LLANEOU	S NOTES	DATA								
Notes:										1	
PERM	IT DATA										
Permit I	Issue Date		Number Type			Rem	arks				_
				_							
Permit I	Notes:							 			
				-				 	-		

BIBLIOG	GRAPHIC DATA			
SIGNIFIC	CANCE DATA			
Study Unit	t			
Code	Criteria			
DATA PF	ROCESSING EVENTS DATA			

ID_Number: 1078-0052 Page 5