**ID Number: 0808-0003** 

## **BASICS DATA**

ID Number: 0808-0003	Year Built: 1872-1	873 Data Source:	Tax Records	
Number Extended Street		Quad Type of A	ddress	
414 H Street		NE Current		
Name(s)	Туре	of Name		
Single Dwelling, 414 H Street, N	I.E. Com	mon		
Capital Linoleum Co.	Histo	oric		
TaxCode1 TaxCode2 TaxCode	e3 Type Expl	lain		
0808/0003	Square/Lot Cur	rent		
STATUS/PURPOSE/USE DA	ТА			
Resource Type: Building		tatus Current: Extan	t	
Desig. Status: Historic	Q	uality:		
Purpose: Residential	С	ondition: Fair		
Function/Use	Start Source	Stop	Source Explain	
Residential (Single-Family)	1872-1873 Permit		Original	
Store	Мар		Historic	
Vacant	Site Visit	t	Current	
CONSTRUCTION DATA				
Construction Event	Start Source	Stop Sour	ce Cost Source	
Orig Construction	1872-1873 Tax Records	S		
Construction Event	Association	Ass	sociated Name	
Orig Construction	Owner	Po	rter, Richard A.	
Construction Notes:				
PEOPLE/EVENTS DATA				
Racial Segregation Status:				

Surroundings:	Urban	Cross Reference N	otes:
Streetscape:	Intact		
Relate to Othr Bldgs	Attached		
Relate to Street:	Face on Line		
Massing:	Vertical Block		
Footprint:	Rectangular		
Number Stories:	2		
Bays Wide:	3		
Height:		Outbuilding Type	Contributing Status
Width:			
Depth/Length:			
SqFt:			
Volume:			
Lot Width			
Lot Depth/Length:		Outbuilding Notes:	
Lot SqFt:			
Acreage:			
Has Driveway:	]		

## STYLE/EXTERIOR DATA

Architectural Style(s)

#### Exterior & Architectural Notes:

May 2009: Constructed between 1872 and 1873, this two-story, three-bay building has been substantially altered since its construction. The building is constructed of brick and is set on a solid brick foundation; the façade (south elevation) has been faced with five-course, American-bond brick. A sloping roof caps the dwelling and is fronted by a brick parapet. A one-story projection extends from the façade and spans its width. The metal-frame projection is capped by a flat roof with an ogee-molded cornice. The end bays contain single-leaf metal-frame glass doors and are topped with one-light metal transoms. The central bay contains paired one-light metal fixed windows. Transoms are visible over the first story openings of the main block. A soldier brick flat arch string course stretches across the façade above the first story. The three second story window openings contain one-light vinyl casement windows with concrete sills. A soldier brick string course spans the façade above the second story windows. Three symmetrically-placed recessed brick panels of basket-weave-bond brick are located above the three second story windows and have rowlock brick surrounds.

The rear (north) elevation of the building extends to the public alley. Constructed of irregular-course, American-bond brick, the rear elevation is fenestrated with one-light metal casement windows with concrete sills and double-leaf metal doors. A metal coal chute pierces the foundation and is sited in the westernmost bay.

#### Site Notes:

May 2009: This building is located on the north side of H Street, NE and directly fronts the concrete sidewalk. The building is adjacent to 412 and 416 H Street, NE. A public alley, paved with concrete, runs east to west and provides access to the rear of the building.

### **NOTABLE FEATURES DATA**

Component

Feature

### **EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible				
Wall Component	Material	Color	Treatment	Source	
Facade	Brick	Beige	American Bond		
Structure Component	Material	Feature		Source	
Foundation	Brick				
Walls	Brick				
Materials Notes:					

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material
1st Flr Bay	Rectangular	Fixed	1-light	Metal
2 Flr Windows	Rectangular	Casement	1-light	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
First Floor	Rectangular	Single		Metal/Glass
First Floor	Rectangular	Single		Metal/Glass

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Subdivision:	Capitol Hill	Historic District(s)	
Ward/ANC:			
Zoning:		Designation Event(s)	
Contributing:			
Survey(s)		Level(s) of Investigation	
Capitol Hill H Street (2009)		Permit Research	
		Reconnaissance Survey	
		Tax Book Research	

## PHOTOS - DIGITIZED

Caption:

Path:	C:\Users\CHRS\Documents\CHRS Databases\H Street - 2 to 15th St\Database\Pictures\0808\
File:	H Street_414_facade_looking_N.JPG
Date::	Photog:
Code::	R: Fr:



Caption:

Path:	C:\Users\CHRS\Docum Databases\H Street - 2 St\Database\Pictures\0	to 15th	
File:	H Street_414_facade_lo	ooking_NE.	JPG
Date::	Photog:		
Code::		R:	Fr:



Caption Path: File:	C:\Users\CHRS\Documents\0 Databases\H Street - 2 to 15t St\Database\Pictures\0808\ H Street_414_rear_elevation_	h	SE.JPG		
Date::	Photog:			AND	
Code::	R	!:	Fr:		

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
				· · · · · · · · · · · · · · · · · · ·	

## MISCELLANEOUS NOTES DATA

Note	es:
The	1869-1871

The 1869-1871 General Assesmment book indicates that there were no improvements on the property in th	ose
years. The 1872-1873 General Assessment book shows improvements equal to \$300.00 or 2,000 square fee	et at a
rate of .15. Richard A. Porter was assessed for this property.	
General Assessment, 1869-1871. Corporation of Washington. (Vol. 13 of 18) Records of Government of the	
District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C. p. 713.	
General Assessment, 1872-1873. Corporation of Washington. (Vol. 14 of 18) Records of Government of the	
District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C. p. 656.	
1928 Sanborn Map: Store	
1960 Sanborn Map: Store	
1999 Sanborn Map: Commercial	

## **PERMIT DATA**

Permit Issue	Date	Number	Туре		Remarks			
Permit Notes	:							
BIBLIOGR	APHIC DATA							
Short Citation	ı		Ту	ре	Date	Remarks		
Bibliographic	Notes:							
SIGNIFICA	NCE DATA							
Study Unit								
Code	Criteria						-	
DATA PRO	CESSING EVE	NTS DAT	A					
Date	Individual	I		Action				

9/14/2009	Dayton (MSD), Maria	Record Updated
8/27/2009	Dayton (MSD), Maria	Record Updated
7/29/2009	Dayton (MSD), Maria	Record Updated
7/29/2009	Dayton (MSD), Maria	Record Created

## **ID Number: 0808-0005**

## **BASICS DATA**

ID Number	: <b>0808</b> -	0005	Year Built:	1928	Data Source: Permit	
Number	Extended	Street			Quad Type of Address	
410		H Street			NE Current	
Name(s)				Туре о	f Name	
Store, 410	H Street, N	I.E.		Comm	on	
Bikram Yo	ga, Capito	Hill		Currer	nt	
TaxCode1	TaxCode2	2 TaxCode3	Туре	Explai	n	
0808/0005			Square/Lot	Curre	nt	

## STATUS/PURPOSE/USE DATA

Resource Type:	Building		Sta	atus Curre	nt: Extant	
Desig. Status:	Historic		Qu	ality:		
Purpose:	Store		Co	ndition:	Good	
Function/Use		Start	Source	Stop	Source	Explain
Store		1928	Permit			Original
Commercial/Re	sidential Single		Map/Site	v		Current
Wholesale Tob	acco		Мар			Historic

### **CONSTRUCTION DATA**

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1928	Permit			8500 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Arch	itect		Warwick, H	larvey
Orig Construction	Build	ler		John F. De	Muth & Sons
Orig Construction	Own	er		Ourisman,	Benjamin

Construction Notes:

## **PEOPLE/EVENTS DATA**

Racial Segregation Status:

Surroundings:	Urban	Cross Reference N	otes:
Streetscape:	Intact		
Relate to Othr Bldgs:	Attached		
Relate to Street:	Face on Line		
Massing:	Vertical Block		
Footprint:	Rectangular		
Number Stories:	2		
Bays Wide:	2		
Height:		Outbuilding Type	Contributing Status
Width:	20		
Depth/Length:	49		
SqFt:			
Volume:			
Lot Width			
Lot Depth/Length:		Outbuilding Notes:	
Lot SqFt:			
Acreage:			
Has Driveway:	]		

### STYLE/EXTERIOR DATA

Architectural Style(s)

#### Exterior & Architectural Notes:

May 2009: Constructed in 1928, this two-story, two-bay building is constructed of brick and is set on a solid concrete foundation. The first story of the façade (south elevation) is veneered with ashlar stone, while the second story is faced with stretcher-bond brick. A sloping roof caps the building. A molded cornice with brick corbelling complement the roof. The westernmost bay of the façade is pierced by double-leaf metal-frame glass doors, which are flanked by one-light metal sidelights. The easternmost bay contains a single-leaf wood-frame glass door. A molded architrave spans the façade and is sited above the first story openings. A band of five wood hopper windows is sited above the architrave. The westernmost three have six-lights and the easternmost two have three-lights. A molded lintel tops the band of transoms. The second story window openings contain paired 1/1, double-hung, wood-sash windows with soldier brick flat arches and a rowlock brick string course, which runs at the level of the sill.

#### Site Notes:

May 2009: This building is located on the north side of H Street, NE and directly fronts the concrete sidewalk. The building is adjacent to 408 and 412 H Street, NE. A public alley, paved with concrete, runs east to west and provides access to the rear of the building.

### NOTABLE FEATURES DATA

Component

Feature

#### **EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible			
Wall Component	Material	Color	Treatment	Source
Facade (Lower)	Stone		Ashlar (Smooth)	
Facade (Upper)	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			
Materials Notes:				

#### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
1 Flr Windows	Rectangular	Fixed	1-light	Metal	
2 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
First Floor	Rectangular	Double		Metal/Glass	
First Floor	Rectangular	Single		Wood/Glass	
Notable Interior Plan	u(s)		Notable Interior Feature(s)		

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

-	• •	Reconnaissance Survey	
Capitol Hill H St	treet (2009)	Permit Research	
Survey(s)		Level(s) of Investigation	
Contributing:			
Ward/ANC: Zoning:		Designation Event(s)	
Subdivision:			
Neighborhood:	Capitol Hill	Historic District(s)	

## **PHOTOS - DIGITIZED**

Caption:

Path:

File:

Date:: Code::

Caption:

1-11	
-	



Path:	C:\Users\CHRS\Documents\CHRS Databases\H Street - 2 to 15th St\Database\Pictures\0808\	
File:	H Street_410_facade_looking_NW.JP	G
Date::	Photog:	
Code::	R:	F

C:\Users\CHRS\Documents\CHRS Databases\H Street - 2 to 15th St\Database\Pictures\0808\

Photog:

H Street\_410\_facade\_looking\_NE.JPG

R:

Fr:



Notes:	
1928 Sanborn Map: Store	
1960 Sanborn Map: Tobacco Wholesale	
1999 Sanborn Map: Residential and Commerical	

## PERMIT DATA

Date	Individual	Action
7/29/2009	Dayton (MSD), Maria	Record Updated
7/29/2009	Dayton (MSD), Maria	Record Created

## **ID Number: 0808-0085**

## **BASICS DATA**

ID Number: 0808-0085			Year Built:	1912	Data Source:	Permit
Number	Extended	Street			Quad Type of Ac	ldress
402	-404	H Street			NE Current	
Name(s)				Туре о	f Name	
Flats/Gro	cery Store,	402-404 H Str	eet, N.E.	Origin	al	
Dynamic	Wellness			Currer		
TaxCode1	1 TaxCode	2 TaxCode3	Туре	Explai	n	
0808/008	5		Square/Lot	Curre	nt	

## STATUS/PURPOSE/USE DATA

Resource Type:	Sta	Status Current: Extant				
Desig. Status: Historic			Qu	ality:		
Purpose:	Purpose: Flats/Grocery Store		Condition:		Good	
Function/Use		Start	Source	Stop	Source	Explain
Flats/Grocery S	itore	1912	Permit			Original
Commercial & I	Residential Multi		Мар			Historic
Restaurant/R-M	l		Мар			Historic
Store & R-M			Site Visit			Current

## **CONSTRUCTION DATA**

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1912	Permit			18600 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Arch	itect		Wenig, Jul	ius
Orig Construction	Build	ler		Wahl, Hen	ry
Orig Construction	Own	er		Weber, J. \	William
Construction Notes:					

Constructed with a grocery on the first floor and four flats on upper stories.

## **PEOPLE/EVENTS DATA**

Racial Segregation Status:

Surroundings:	Urban	Cross Reference N	otes:
Streetscape:	Intact		
Relate to Othr Bldgs:	Attached		
Relate to Street:	Face on Line		
Massing:	Vertical Block		
Footprint:	U-Shaped		
Number Stories:	3		
Bays Wide:	5		
Height:		Outbuilding Type	Contributing Status
Width:	40		
Depth/Length:	25		
SqFt:			
Volume:			
Lot Width			
Lot Depth/Length:		Outbuilding Notes:	
Lot SqFt:			
Acreage:			
Has Driveway:	]		

### **STYLE/EXTERIOR DATA**

#### Architectural Style(s)

### **Renaissance Revival (Italian)**

#### Exterior & Architectural Notes:

May 2009: Constructed in 1912, this three-story, five-bay building Italian Renaissance-style building was originally constructed as a grocery store with four upper story apartments. A central airshaft divides the building almost into two halves. The building is constructed of brick and is set on a solid concrete foundation. The facade (south elevation) is faced with stretcher-bond brick and the side elevations are constructed of American-bond brick. A sloping roof caps the building and is finished with a molded copper cornice. A parapet fronts the building and is faced with three recessed brick panels. At the center of each panel is a projecting diamond-shaped panel constructed of stone with a brick surround. Copper coping and a centrally-placed copper ornament complement the parapet. Two interior-side brick chimneys rise from the east (side) elevation and have corbeled brick caps. The end bays of the first story of the facade contain multi-light wood doors with one-light wood transoms. The central bay contains a single-leaf metal-frame glass door with a one-light metal sidelight. The first story of the façade has been altered since 1912 with the construction of two, one-story rectangular bays, which flank the central door entry. Each metal-frame bay is set on a foundation that is faced with corrugated metal and is capped by a flat roof with a molded metal cornice. Fenestration consists of large, onelight fixed metal storefront windows. Transom windows originally were sited above the flanking window bays of the first story, but are not partially covered with plywood. A copper architrave spans the facade above the first story and runs parallel with the copper rain spouts. Three-sided, canted oriel windows project from the end bays of the façade and stretch from the second to third stories. Each wood-frame oriel window is clad with copper and has a flat roof with overhanging eaves. The central openings of each oriel window contain either a 1/1 or 1/2, double-hung, wood-sash window. Each of the flanking openings contain narrow, 1/1, double-hung, wood-sash windows and are separated from the central opening by copper pilasters. The central bay of the main block's second story is fenestrated with a 1/1 doublehung, wood-sash window which is flanked by narrow1/1, double-hung, wood-sash windows. Each window has a gauged brick jack arch with a concrete keystone. A wrought-iron balconet fronts the windows. The central bay of the third story features paired round-headed 1/1, double-hung, wood-sash windows. Three-course, rowlock brick rounded-head arches finish the windows and have concrete keystones and paneled concrete imposts. A wrought-iron balconet fronts the windows. A molded copper architrave stretches across the façade above the third story. The side elevations do not have fenestration. The rear (north) elevation is pierced by segmental openings which contain 1/1, double-hung, vinyl-sash windows with. Each story also features a segmental opening containing a single-leaf door with a three-course, rowlock brick segmental arch.

Two three-story, metal-frame porches are located on the rear elevation of the main block and flank the airshaft. Each story of the porch is supported by square metal posts. A three-story porch is noted on the 1928 Sanborn map, however, this porch was constructed ca. 1995.

#### Site Notes:

May 2009: This building is located on the north side of H Street, NE and directly fronts the concrete sidewalk. The building is adjacent to 400 and 406 H Street, NE. A public alley, paved with concrete, runs east to west and provides access to the rear of the building.

#### **NOTABLE FEATURES DATA**

Component

Feature

## **EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible				
Wall Component	Material	Color	Treatment	Source	
Facade	Brick	Gold	Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				
Materials Notes:					

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
1st Flr Bay	Rectangular	Fixed	1-light	Metal	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Wood	
2nd Flr Bay	Rectangular	Dbl-Hung	1/2	Wood	
2nd Flr Bay	Rectangular	Dbl-Hung	1/1	Wood	
3 Flr Windows	Round-Headed	Dbl-Hung	1/1 Double	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
First Floor	Rectangular	Glazed		Metal/Glass	
First Floor	Rectangular	Single		Wood/Glass	
Notable Interior Plar	n(s)		Notable Interior Feature(s)		

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Subdivision:	Capitol Hill	Historic District(s)	
Ward/ANC:			
Zoning:		Designation Event(s)	
Contributing:			
Survey(s)		Level(s) of Investigation	
Capitol Hill H Street (2009)		Permit Research	
		Reconnaissance Survey	

## **PHOTOS - DIGITIZED**

Caption:

Path:	C:\Users\CHRS\Documents\CHRS Databases\H Street - 2 to 15th St\Database\Pictures\0808\							
File:	H Street_402-404_facade	_looking	_NE.JPG					
Date::	Photog:							
Code::		R:	Fr:					





Path:	C:\Users\CHRS\Documents\CHRS Databases\H Street - 2 to 15th St\Database\Pictures\0808\							
File:	H Street	_402-404	_facade	looking	_NW.JPG			
Date::		Phote	og:					
Code::				R:	Fr:			

C:\Users\CHRS\Documents\CHRS

H Street\_402-404\_side\_looking\_ESE.JPG

R:

Fr:

Databases\H Street - 2 to 15th St\Database\Pictures\0808\

Photog:

Caption:

Path:

File:

Date:: Code::



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption

## **MISCELLANEOUS NOTES DATA**

Notes:								
1960 Sanbo	rn Map: Store rn Map: Restaurar rn Map: Commeric	t al						
PERMIT D	АТА							
Permit Issue	Date	Number	Туре		Remarks			
04/24/1912		4859	Build					
Permit Notes	5:							
BIBLIOGR	APHIC DATA							
Short Citatio	n		Тур	e	Date	Remarks		
Bibliographic	Notes:							
SIGNIFICA	NCE DATA							
Study Unit				_				
Code	Criteria						-	

Date	Individual	Action
7/29/2009	Dayton (MSD), Maria	Record Updated
7/29/2009	Dayton (MSD), Maria	Record Created

## **ID Number: 0808-0051**

## **BASICS DATA**

ID Number	: <b>0808</b> -	0051	Year Built:	1890	Data Source:	Permit
Number	Extended	Street			Quad Type of A	ddress
416		H Street			NE Current	
Name(s)				Туре о	f Name	
Rowhouse	e, 416 H Str	eet, N.E.		Comm	on	
Dissident	Display Stu	idios and Gal	lery	Curren	t	
TaxCode1	TaxCode2	2 TaxCode3	Туре	Explai	n	
0808/0051			Square/Lot	Curre	nt	

## STATUS/PURPOSE/USE DATA

Dwelling & Stor	re		Map/Site	V		Current
Residential (Mu	ılti-Family)	1890	Permit			Original
Function/Use		Start	Source	Stop	Source	Explain
Purpose:	Residential		Co	ndition:	Good	
Desig. Status:	Historic	Quality:				
Resource Type:	Building		Sta	atus Currei	nt: Extant	

## **CONSTRUCTION DATA**

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1890	Permit			13000 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Build	ler		Boss, Jose	eph S.
Orig Construction	Owne	Owner Boss, Joseph S.		eph S.	
Construction Notes:					
416-420 H Street, NE were	e constructed ir	n 1890 by Jose	ph S. Boss	under the same	permit (#1368).

## **PEOPLE/EVENTS DATA**

Racial Segregation Status:

Surroundings:	Urban	Cross Reference N	lotes:
Streetscape:	Intact		
Relate to Othr Bldgs	Attached		
Relate to Street:	Face on Line		
Massing:	Vertical Block		
Footprint:	Rectangular		
Number Stories:	2.5		
Bays Wide:	2		
Height:		Outbuilding Type	Contributing Status
Width:	16		
Depth/Length:	64		
SqFt:			
Volume:			
Lot Width			
Lot Depth/Length:		Outbuilding Notes:	
Lot SqFt:			
Acreage:			
Has Driveway:	]		

## STYLE/EXTERIOR DATA

Architectural Style(s)

#### Exterior & Architectural Notes:

May 2009: This two-and-one-half-story, two-bay, multi-family dwelling was constructed in 1890 as part of a five building project. The building is attached on two stories to the west and two-and-one-half to the east. The rectangular form of the building is offset by a three-story rear ell. Set on a solid brick foundation, this brick building has a stretcher-bond brick finish. An interior-side brick chimney extends from the east (side) party wall. The building is capped by a false Mansard roof of painted octagonal tin shingles. The roof has a paneled cornice, corbeled end braces, projecting party walls with fluted panels, and an ogee-molded coping. The roof has two aedicule dormers. The eastern dormer is a deck dormer and has paired 1/1, double-hung, vinyl-sash windows. The western dormer is pierced by a 1/1, double-hung, vinyl-sash windows. The western dormer is pierced by a 1/1, double-hung, vinyl-sash windows. The vestern dore projecting bay. The façade features a water table and a two-course brick string on the first story. The western door opening features a single-leaf, wood-frame glass door with a tall, narrow, two-light wood transom. The projecting bay features a large opening on the façade leading to an integral porch. The porch shelters a single-leaf, metal-frame door with sidelight. The second story is pierced by 1/1, double-hung, vinyl-sash windows and a large, fixed vinyl-sash window on the façade of the projecting bay. All of the façade openings feature splayed soldier brick flat aches with a string of projecting gauged bricks above. Additional decoration consists of reeded bands with roundels. The rear ell has a seven-course, American-brick bond veneer and is pierced by 1/1, double-hung, vinyl-sash windows with two-course, segmental brick arches.

#### Site Notes:

May 2009: This building is located north of H Street, NE and directly fronts the concrete sidewalk. The building has a typical setback for the 400 block of H Street, NE.

#### **NOTABLE FEATURES DATA**

Component

Feature

### **EXTERIOR MATERIALS DATA**

Materials Notes:					
Walls	Brick				
Foundation	Brick				
Structure Component	Material	Feature		Source	
Facade	Brick		Stretcher Bond		
Wall Component	Material	Color	Treatment	Source	
Mansard (False)	Tin		Octagonal Shap	e	
Roof Component	Material	Color	Treatment	Source	

## WINDOW/DOOR/INTERIOR DATA

First Floor	Rectangular	Single		Metal/Glass
First Floor	Rectangular	Single		Wood/Glass
Door Location	Aperture Shape	Туре	Pamels	Material
Dormer	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Dormer	Rectangular	Dbl-Hung	1/1	Vinyl
2nd FIr Bay	Rectangular	Fixed	1-light	Vinyl
2nd FIr Bay	Rectangular	Dbl-Hung	1/1	Vinyl
2 FIr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Window Location	Aperture Shape	Туре	Lights	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	Capitol Hill	Historic District(s)	
Subdivision:			
Ward/ANC:			
Zoning:		Designation Event(s)	
Contributing:			
Survey(s)		Level(s) of Investigation	
Capitol Hill H St	reet (2009)	Permit Research	
		Reconnaissance Survey	

## **PHOTOS - DIGITIZED**

Caption:

Path:	C:\Users\CHRS\Documents\CHRS Databases\H Street - 2 to 15th St\Database\Pictures\0808\					
File:	H Street_416_facade_	looking_NE.	JPG			
Date::	Photog:					
Code::		R:	Fr:			



Caption:

Path:	C:\Users\CHRS\Docum Databases\H Street - 2 St\Database\Pictures\0	to 15th	
File:	H Street_416_facade_lo	oking_NW	.JPG
Date::	Photog:		
Code::		R:	Fr:



Path:

File: Date::

Code::



## PHOTOS - B/W OR NON-DIGITIZED

C:\Users\CHRS\Documents\CHRS

Photog:

H Street\_416\_rear\_elevation\_looking\_S.JPG

R:

Fr:

Databases\H Street - 2 to 15th St\Database\Pictures\0808\

Photo Code	Roll	Frame	e(s)	Date	Photogra	pher	Caption	
MISCELLANEO	DUS NOTES	<b>DATA</b>						
Notes:								
1928 Sanborn M 1960 Sanborn M	ap: Dwelling ap: Flats							
PERMIT DATA								
Permit Issue Date	e	Number	Туре		Remarks			
01/30/1890		1368	Build					-
Permit Notes:								
BIBLIOGRAPH								1
Short Citation				Туре	Date	Remarks		-
Bibliographic Not	es:							
SIGNIFICANCE	E DATA							]
Study Unit								
Code C	riteria						_	

Date	Individual	Action
8/4/2009	Dayton (MSD), Maria	Record Updated
8/4/2009	Dayton (MSD), Maria	Record Created

## **ID Number: 0808-0006**

## **BASICS DATA**

ID Number:	: <b>0808</b> -	0006	Year Built:	1896	Data Sour	ce: Permit
Number	Extended	Street			Quad Type of	of Address
408		H Street			NE Curre	nt
Name(s)				Туре о	f Name	
Single Dwo	elling, 408	H Street, N.E.		Comm	on	
Fitness To	gether			Curren	t	
TaxCode1	TaxCode2	2 TaxCode3	Туре	Explai	n	
0808/0006			Square/Lot	Curre	nt	

## STATUS/PURPOSE/USE DATA

Resource Type:	Building		Sta	atus Curre	nt: Extant	
Desig. Status:	Historic		Qu	ality:		
Purpose:	Residential		Co	ndition:	Good	
Function/Use		Start	Source	Stop	Source	Explain
Residential (Si	ngle-Family)	1896	Permit			Original
Dwelling & Sto	re		Мар			Historic
Dwelling/Gym			Site Visit			Current

### **CONSTRUCTION DATA**

Orig Construction 1896 Permit 450   Construction Event Association Associated Name	500 Permit		
Construction Event Association Associated Name			
Orig Construction Architect Denson, Joseph F.	Denson, Joseph F.		
Orig Construction Owner Long, Bat.	Long, Bat.		
Plager Co. Builder Plager Co.			

Construction Notes:

## **PEOPLE/EVENTS DATA**

Racial Segregation Status:

Surroundings:	Urban	Cross Reference N	lotes:
Streetscape:	Intact		
Relate to Othr Bldgs:	Attached		
Relate to Street:	Face on Line		
Massing:	Vertical Block		
Footprint:	Rectangular		
Number Stories:	3		
Bays Wide:	3		
Height:		Outbuilding Type	Contributing Status
Width:	20		
Depth/Length:	68		
SqFt:			
Volume:			
Lot Width			
Lot Depth/Length:		Outbuilding Notes:	
Lot SqFt:			
Acreage:			
Has Driveway:	]		

## STYLE/EXTERIOR DATA

Architectural Style(s)

#### Exterior & Architectural Notes:

May 2009: This three-story, three-bay building has a two-story rear ell. Constructed in 1896, this building was originally constructed as a single-family dwelling. By 1928, the building had been rehabilitated to serve as a store and dwelling. It is a mixed-use building currently. Borrowing characteristics of many architectural styles, this imposing building is set on a solid brick and concrete foundation. The masonry building is constructed of brick and has a stretcher-bond finish. An elaborate false mansard roof of octagonal slate shingles caps the building. The false mansard roof is supplemented by a sloping roof which extends to the north to cover the majority of the building. Two interior-side brick chimneys extend from the east (side) elevation. The roof features a high-style entablature composed of a cushioned architrave and ogeemolded cornice supported by modillions. An ovular window opening protrudes from the mansard roof, though its sash has been removed in favor of plywood. Flanking the false mansard roof are brick columns with ogee-molded caps accentuated by large egg molding. The egg moldings are surrounded by ivy molding and supported by small tapered pilasters. The facade (south elevation) has a first story fenestrated by a single-leaf wood doors with lights and a singleleaf metal-frame glass door in the outer bays. The door openings have three-light transoms. The middle bay features a projecting square bay composed of brick. The bay holds single-light, metal fixed windows. A flat metal roof caps the bay and extends to shelter the western door opening. Three, three-light window openings are located above the projecting bay. The first story is corned by engaged pilasters which support large wood panels. The second story contains a threesided bay window supported by wood knee braces. Fenestration of the bay consists of 1/1, double-hung, vinyl-sash windows set in narrow, square-edge wood surrounds. The openings are flanked by bezant molding. Below the openings the bay is clad in board-and-batten siding. Above the window openings are panels with a diamond-shaped bas relief. The roof of the bay window was not visible from the public right-of-way, however, it is supported by small modillions with an ogee-molded cornice. The third story is fenestrated by a ribbon of four, 1/1, double-hung, vinyl-sash windows set in a wooden crossette. Ivy molding is located in the corners of the crossette. The east and west (side) elevations have no fenestration. The fenestration of the north (rear) elevation was not visible due to safety issues.

Site Notes:

May 2009: This building is located north of H Street, NE and directly fronts the concrete sidewalk. A small planting bed is located in front of the store, within the public sidewalk. The bed has an immature trees and flowers. An alley extends behind the building.

### NOTABLE FEATURES DATA

Component

Feature

### EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Octagonal Shape	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source

Facade	Brick	Stretcher Bond			
Structure Component	Material	Feature	Source		
Foundation	Brick & Concrete				
Walls	Brick				
Materials Notes:					

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material
1st FIr Bay	Rectangular	Fixed	3 Lite	Metal
2nd Flr Bay	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2nd Flr Bay	Rectangular	Dbl-Hung	1/1	Vinyl
3 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
First Floor	Rectangular	Single	2-Panel	Wood/Glass
First Floor	Rectangular	Single		Metal/Glass
Notable Interior Plan(s)			Votable Interior Feature(s)	

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Subdivision:	Capitol Hill	Historic District(s)	
Ward/ANC:			
Zoning:		Designation Event(s)	
Contributing:			
Survey(s)		Level(s) of Investigation	
Capitol Hill H Street (2009)		Permit Research	
		Reconnaissance Survey	

## **PHOTOS - DIGITIZED**

Caption:

Path:C:\Users\CHRS\Documents\CHRS<br/>Databases\H Street - 2 to 15th<br/>St\Database\Pictures\0808\File:H Street\_408\_faade\_looking\_NE.JPGDate::Photog:<br/>Code::Code::R:



Fr:

Ca	ption	•

Path:



Databases\H Street - 2 to 15th St\Database\Pictures\0808\ File: H Street\_408\_facade\_looking\_N.JPG Date:: Photog: Code:: R: Fr:

C:\Users\CHRS\Documents\CHRS

Caption:



Path:	C:\Users\CHRS\Documents\CHRS Databases\H Street - 2 to 15th St\Database\Pictures\0808\					
File:	H Street_408_facade_lo	oking_NW	.JPG			
Date::	Photog:					
Code::		R:	Fr:			

PHOTOS - B/W O	R NON-DIGITIZE	D						
Photo Code	Roll Fran	ne(s) I	Date	Photograph	ier	Caption		
MISCELLANEOU	S NOTES DATA							
Notes:								
							-	
PERMIT DATA								
Permit Issue Date	Number	Туре		Remarks				
04/10/1896	1392	Build						
Permit Notes:								
BIBLIOGRAPHIC	DATA							
Short Citation		Туре	•	Date	Remarks			

Bibliographic Notes:	

## SIGNIFICANCE DATA

Study Unit

Code

Criteria

Date	Individual	Action
8/4/2009	Dayton (MSD), Maria	Record Updated
8/4/2009	Dayton (MSD), Maria	Record Created

## **ID Number: 0808-0010**

## **BASICS DATA**

ID Number: 0808-0010	Year	Built: ca. 19	75 Data	Source: Map/S	Site Visit	
Number Extended Street			Quad	Type of Address		
400 H Stree	t		NE	Current		
Name(s)		Туре	of Name			
Store, 400 H Street, N.E.		Com	mon			
Studio 400		Curr	ent			
TaxCode1 TaxCode2 TaxCo	de3 Type	Exp	lain			
0808/0010	Square	/Lot Cur	rent			
STATUS/PURPOSE/USE D	ΑΤΑ		totuo Curr	ent: Extant		
Resource Type: Building Desig. Status: Not Historic			tatus Curre Juality:	nt. Extant		
Purpose: Store			condition:	Fair		
Function/Use	Start	Source	Stop	Source	Explain	
Store	ca. 197	5 Map/Site	e V		Original	
CONSTRUCTION DATA						
Construction Event	Start	Source	Stop	Source	Cost Source	
Addition	ca. 1980	Observatio	า			
Orig Construction	ca. 1975	Map/Site Visit				
Construction Event	Associa	ation		Associated N	lame	
Construction Notes:						
PEOPLE/EVENTS DATA						
Racial Segregation Status:						

Surroundings:	Urban	Cross Reference N	otes:
Streetscape:	Intact		
Relate to Othr Bldgs:	Attached		
Relate to Street:	Face on Line		
Massing:	Block		
Footprint:	Rectangular		
Number Stories:	1		
Bays Wide:			
Height:		Outbuilding Type	Contributing Status
Width:	22		
Depth/Length:			
SqFt:			
Volume:			
Lot Width			
Lot Depth/Length:		Outbuilding Notes:	
Lot SqFt:			
Acreage:			
Has Driveway:	]		

### STYLE/EXTERIOR DATA

Architectural Style(s)

#### Exterior & Architectural Notes:

May 2009: This one-story building was built ca. 1975 and replaced an earlier two-story building. The building, including the solid foundation, feature six-course, American-bond brick. The flat roof is finished with metal flashing. On the west (front) elevation is a one-light fixed window. Just north of the window is a bulkhead with a single-leaf metal door. The south (side) elevation is fenestrated by a two-light fixed window that is protected by a cloth awning. Spanning the width of the window is a brick garden wall. West of the window is a former entrance that has been infilled with stretcher-bond brick.

The main entry is located in a one-story, one-bay, ca. 1980 vestibule addition is located on the west (front) elevation of the building. It is located north of the bulkhead. The masonry addition, including the solid foundation, features stretcher brick veneer. A side-gabled roof of asphalt shingles caps the vestibule. Fenestration is made up of a single-leaf metal door on the south elevation and a one-light fixed window with a square-edged wood surround on the west elevation.

Another addition is constructed of brick and is set on a solid foundation that has been partially parged. A flat roof finished with metal flashing caps it. Fenestration is made up of a single-leaf metal door that is located on the west (front) elevation.

#### Site Notes:

May 2009: This property is located in the northeast corner of the intersection of H Street, NE and 4th Street, NE. The building fronts a concrete sidewalk on its south and west elevations. It is oriented towards 4th Street. The building is adjacent 402 H Street, which is located to the east.

## NOTABLE FEATURES DATA

Component

Feature

#### **EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source	
Flat	Not Visible				
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		American Bond		
Structure Component	Material	Feature		Source	
Foundation	Unknown				
Walls	Brick				

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
1 Flr Windows	Rectangular	Fixed	1-light	Unknown	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single		Metal	

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Subdivision:	Capitol Hill	Historic District(s)	
Ward/ANC:			
Zoning:		Designation Event(s)	
Contributing:			
Survey(s)		Level(s) of Investigation	
Capitol Hill H S	treet (2009)	Archival Research	
		Permit Research	
		Reconnaissance Survey	

## **PHOTOS - DIGITIZED**

Caption:

Path:	C:\Users\CHRS\Documents\CHRS Databases\H Street - 2 to 15th St\Database\Pictures\0808\
File:	H Street_400_facade_looking_NE.JPG
Date::	Photog:
Code::	R: Fr:



Caption:

Path:	C:\Users\CHRS\Docum Databases\H Street - 2 St\Database\Pictures\0	to 15th	
File:	H Street_400_facade_l	ooking_NW	.JPG
Date::	Photog:		
Code::		R:	Fr:



Path:

File: Date::

Code::



## PHOTOS - B/W OR NON-DIGITIZED

C:\Users\CHRS\Documents\CHRS

H Street\_400\_side\_looking\_NE.JPG

R:

Fr:

Photog:

Databases\H Street - 2 to 15th St\Database\Pictures\0808\

Photo Code	Roll	Frame(s)	Date	Photograp	her	Caption	
MISCELLANEC		S DATA					
		5 DATA					
Notes:							
PERMIT DATA							
Permit Issue Date	)	Number Type		Remarks			-
Permit Notes:							]
BIBLIOGRAPH	IC DATA						]
Short Citation			Туре	Date	Remarks		 -
Bibliographic Note	es:						 ]
SIGNIFICANCE	DATA						
Study Unit	DAIN						
Code C	riteria						

Date	Individual	Action
8/19/2009	Dayton (MSD), Maria	Record Updated
8/5/2009	Martinkowsky (CHM), Christin	Record Updated
8/4/2009	Martinkowsky (CHM), Christin	Record Updated
8/4/2009	Martinkowsky (CHM), Christin	Record Created

## **ID Number: 0808-0007**

## **BASICS DATA**

ID Number	: <b>0808</b> -	-0007	Year E	Built: 1	872-1873	Data	a Source:	Tax Re	ecords		
Number	Extended	Street				Quad	Type of Add	ress			
406		H Street				NE	Current			-	
Name(s)					Type of N	lame					
Single Dw	elling, 406	H Street, N.E			Commor	า					
TaxCode1	TaxCode	2 TaxCode3	Туре		Explain						
0808/0007			Square/	Lot	Current						
STATUS/	PURPOSE	E/USE DATA	L .								
Resource 1	Type: Buil	ding			Status	s Curr	ent: Extant				
Desig. Stat	tus: Hist	oric			Qualit	y:					
Purpose:	Resi	idential			Condi	tion:	Fair				
Function/U	se		Start	Sou	rce	Stop	S	ource	Expla	ain	
Residentia	al		1872-18	73 Writ	ten Da				Orig	inal	
Dwelling 8	& Store			Мар	/Site V				Histo	pric/Current	
Store/Vaca	ant			Site	Visit				Curr	ent	
CONSTR		ΔΑΤΑ									
Constructio	on Event	St	tart	Source	S	top	Source		Co	ost Source	
Orig Cons	truction	18	372-1873	Tax Re	cords						
Constructio	on Event		Associat	ion			Assoc	ciated N	ame		
Constructio	on Notes:										
PEOPLE/	EVENTS	DATA									

Racial Segregation Status:

Surroundings:	Urban	Cross Reference N	otes:	
Streetscape:	Intact			
Relate to Othr Bldgs:	Attached			
Relate to Street:	Face on Line			
Massing:	Vertical Block			
Footprint:	Rectangular			
Number Stories:	2			
Bays Wide:	3			
Height:		Outbuilding Type	Contributing Status	
Width:	24			
Depth/Length:				
SqFt:				
Volume:				
Lot Width				
Lot Depth/Length:		Outbuilding Notes:		
Lot SqFt:				
Acreage:				
Has Driveway:				

Architectural Style(s)

#### Italianate

Exterior & Architectural Notes:

May 2009: This two-story, four-bay building was constructed in between 1872 and 1873. It may have originally been a single dwelling, but now has a commercial unit is located in the first story. The masonry building and solid foundation is veneered in stretcher-bond brick. An Italianate cornice, with brackets, modillions, and a paneled frieze, finishes the roof, which could not be seen. The first story has a recessed half-canted arrangement that is created by two entrances and two canted bays. The three-sided canted projections, which are partially obscured by plywood covers, are located in the westernmost bay and the second bay to the east. The second bay to the west and the easternmost bay hold a singe-leaf paneled wood door with lights. Above the canted bays and entrances are transoms that are covered by plywood and topped by a tin cornice with modillions. Flanking the transom windows are the top sections of metal pilasters, which are largely obscured by plywood. The second story is fenestrated by 2/2, double-hung, wood-sash windows with concrete sills and lintels. The east and west (side) elevations are completely obscured by attached buildings. The north (rear) elevation was not accessible.

#### Site Notes:

May 2009: This building is located on the north side of H Street, NE and directly fronts the concrete sidewalk. It is adjacent 408 H Street, which is located to the east, and 404 H Street, which is located to the west.

#### NOTABLE FEATURES DATA

Component

Feature

### **EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source	
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Unknown				
Walls	Unknown				
Materials Notes:					

#### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
2 Flr Windows	Rectangular	Dbl-Hung	2/2	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
First Floor	Rectangular	Single	Paneled	Wood	
First Floor	Rectangular	Single	Paneled	Wood	
Notable Interior Plar	n(s)	1	Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Subdivision: Ward/ANC: Zoning: Contributing: Historic District(s)

Designation Event(s)

Tuesday, June 25, 2013

#### Capitol Hill H Street (2009)

#### Level(s) of Investigation

Archival Research Permit Research Reconnaissance Survey Tax Book Research

### **PHOTOS - DIGITIZED**

Caption		
Path: File:	C:\Users\CHRS\Documents\CHRS Databases\H Street - 2 to 15th St\Database\Pictures\0808\ H Street_406_facade_looking_NE.JPG	
Date::	Photog:	
Code::	R: Fr:	
Caption	<u>.</u>	
Path:	C:\Users\CHRS\Documents\CHRS Databases\H Street - 2 to 15th St\Database\Pictures\0808\	
File:	H Street_406_facade_looking_NW.JPG	
Date::	Photog:	
Code::	R: Fr:	

#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption

## MISCELLANEOUS NOTES DATA

Notes:

Until approximately 1869, Square 808 was committed as St. Peter's Grave Yard and is noted as such as early as 1854. The 1869-1871 General Assessment book indicates that Lot 7 was unimproved. The 1872-1873 General Assessment book notes that the lot was owned by John F. Ennis. The value of improvements totaled \$300 or 2,000 square feet at a rate of .15.

General Assessment, 1872-1873. Corporation of Washington. (Vol. 14 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C. p. 656.

General Assessment, 1869-1871. Corporation of Washington. (Vol. 13 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C. p. 714.

General Assessment, 1854. Corporation of Washington. Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C.

#### **PERMIT DATA**

Permit	Issue	Date
--------	-------	------

Number Type

Remarks

Permit Notes:				
BIBLIOGRAPHIC DATA				
Short Citation	Туре	Date	Remarks	
Bibliographic Notes:				
SIGNIFICANCE DATA				]
Study Unit				
Code Criteria				

Date	Individual	Action
9/14/2009	Dayton (MSD), Maria	Record Updated
9/9/2009	Dayton (MSD), Maria	Record Updated
8/19/2009	Dayton (MSD), Maria	Record Updated
8/4/2009	Martinkowsky (CHM), Christin	Record Updated
8/4/2009	Martinkowsky (CHM), Christin	Record Created

## **ID Number: 0808-0004**

## **BASICS DATA**

ID Number:	: <b>0808-</b>	0004	Year Built:	1917	Da	ta Source:	Permit
Number I	Extended	Street			Qua	d Type of Ad	dress
412		H Street			NE	Current	
Name(s)				Туре о	f Name	9	
Dwelling/F	uneral Hor	ne, 412 H Stro	eet, N.E.	Comm	on		
Phylis J. O	outlaw & As	sociates		Currer	nt		
TaxCode1	TaxCode2	2 TaxCode3	Туре	Explai	n		
0808/0004			Square/Lot	Permi	it		

## STATUS/PURPOSE/USE DATA

Resource Type:	Building		Sta	atus Currei	nt: Extant	
Desig. Status:	Historic			ality:		
Purpose:	Dwelling/Funera	I Home	Co	ndition:	Good	
Function/Use		Start	Source	Stop	Source	Explain
Funeral Home		1917	Permit			Original
Office			Site Visit			Current

## **CONSTRUCTION DATA**

Construction Event	Start	Source	Stop	Source	Cost Source	
Orig Construction	5/21/1917	Permit			13000 Permit	
Construction Event	Associa	tion		Associated Name		
Orig Construction	Archite	Architect		Wenig, Julius		
Sardo, William. H.	Owner		Sardo, William. H.			
Construction Notes:						

## **PEOPLE/EVENTS DATA**

Racial Segregation Status:

Surroundings:	Urban	Cross Reference Notes:	
Streetscape:	Intact		
Relate to Othr Bldgs:	Attached		
Relate to Street:	Face on Line		
Massing:	Vertical Block		
Footprint:	Rectangular		
Number Stories:	3		
Bays Wide:	3		
Height:		Outbuilding Type Contributing State	ls
Width:	20		
Depth/Length:	72		
SqFt:			
Volume:			
Lot Width			
Lot Depth/Length:		Outbuilding Notes:	
Lot SqFt:		May 2009: Attached to the north (rear) elevation is a	one-story
Acreage:		garage. According to Sanborn Fire Insurance maps	
Has Driveway:		constructed before 1928. It features stretcher-bond veneer and is partially covered in plywood. It is fene a rollup metal garage door.	

## **STYLE/EXTERIOR DATA**

Architectural Style(s)

#### Exterior & Architectural Notes:

May 2009: This three-story, three-bay building was designed by Julius Wenig and was constructed in 1917. It was originally designed as a funeral home and dwelling, but now serves as an office building. The structure is made of brick and sits on a solid concrete foundation. It is veneered on the façade by stretcher-bond brick on the second and third stories and limestone (painted) on the first story. A sloping roof is partially obscured by a brick parapet wall featuring stretcher-bond brick veneered with protruding sections made of soldier bricks. The parapet is finished with a modest wood cornice. Beneath the parapet is a more prominent cornice with block modillions and end brackets. The first story of the façade (south elevation) features a large, centrally placed, one-light window with a marble panel below. An awning protects the window. Single-leaf entries flank the projection and holds single-leaf paneled wood doors with one light. Each entry features hood molding and is protected by an awning.

A three-sided oriel is centrally located on the façade of the second and third stories. A flat roof finished by an ogeemolded cornice caps the oriel. The oriel if fenestrated on both the second and third stories by a one-light fixed window flanked by 1/1, double-hung, wood-sash windows. The second-story windows on the oriel have flared jack arches of brick with a keystone. Beneath the second-story windows is a concrete sill course. An ogee-molded stringcourse is located approximately one foot below the sill course. The second story windows have concrete sills and a continuous lintel that spans all three windows. There is no other fenestration on the second or third stories. The east and west (side) elevations are obscured by adjacent buildings.

Site Notes:

May 2009: This building is located on the north side of H Street, NE and directly fronts the concrete sidewalk. It is adjacent 414 H Street, which is located to the east, and 410 H Street, which is located to the west. A public alley is located to the north and provides access to the rear of the property. A garage is attached to the north (rear) elevation of the primary resource.

#### **NOTABLE FEATURES DATA**

Component

Feature

#### **EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible			
Wall Component	Material	Color	Treatment	Source
Facade (Lower)	Limestone		Coursed	
Facade (Middle)	Brick		Stretcher Bond	
Facade (Upper)	Brick		Stretcher Bond	

Structure Component	Material	Feature	Source	
Foundation	Concrete			
Walls	Brick			
Materials Notes:				

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material
1 Flr Windows	Rectangular	Fixed	1-light	Unknown
2nd Flr Bay	Rectangular	DoubleCase	1/1	Wood
2nd Flr Bay	Rectangular	Fixed	1-light	Unknown
Door Location	Aperture Shape	Туре	Pamels	Material
First Floor	Rectangular	Single	Paneled	Wood
First Floor	Rectangular	Single	Paneled	Wood
Notable Interior Plar	n(s)		Notable Interior Feature(s)	

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

•	<b>X Y</b>	Reconnaissance Survey	
Capitol Hill H St	reet (2009)	Permit Research	
Survey(s)		Level(s) of Investigation	
Contributing:			
Zoning:		Designation Event(s)	
Ward/ANC:			
Subdivision:			
Neighborhood:	Capitol Hill	Historic District(s)	

## **PHOTOS - DIGITIZED**

Caption:

Path:	C:\Users\CHRS\Docun Databases\H Street - 2 St\Database\Pictures\d	to 15th	
File:	H Street_412_facade_	looking_NE.	JPG
Date::	Photog:		
Code::		R:	Fr:

Path:	Databases St\Databas	s\H Street - 2 se\Pictures\	/8080/					
File:	H Street_4		looking_NW.JF	'G				
Date:: Code::		Photog:	R:	Fr:				
Captior	1:							
Path:	Databases	CHRS\Docu S\H Street - 2 Se\Pictures\					1115	
File:			_looking_SW.JF	PG				
Date::		Photog:		-	い、田田	1 al		
Code::			R:	Fr:				
РНОТ	OS - B/W C	R NON-DI	GITIZED					
Photo C	Code	Roll	Frame(s)	Date	Photog	rapher	Caption	
MISCE	ELLANEOU	S NOTES	DATA					
Notes:								
PERM	IT DATA							
Permit	Issue Date		Number Type		Remarks			
5/21/19	17		5046 Build					
Permit	Notes:							
BIBLIC	OGRAPHIC	DATA						
Short C	litation			Туре	Date	Remarks		
Bibliogr	aphic Notes:							 
SIGNI	FICANCE D	ATA						
Study L	Jnit							
<b>.</b> .								
Code	Crite	eria						

Date	Individual	Action
8/19/2009	Dayton (MSD), Maria	Record Updated
8/4/2009	Martinkowsky (CHM), Christin	Record Updated
8/4/2009	Martinkowsky (CHM), Christin	Record Created

## **ID Number: 0808-0050**

## **BASICS DATA**

ID Number:	0808-	0050	Year Built:	1890	Da	ta Source:	Permit	
Number I	Extended Street Quad Type of Address							
418		H Street			NE	Current		
Name(s)				Type of	Name	e		
Rowhouse	, 418 H Str	eet, N.E.	Common					
Tax Service Center				Curren	t			
TaxCode1	TaxCode2	TaxCode3	Туре	Explair	ו			
0808/0050			Square/Lot	Permit	t			

## STATUS/PURPOSE/USE DATA

Resource Type: Desig. Status:	Building Historic			atus Curren ality:	t: Extant	
Purpose:	Residential		Co	ndition:	Good	
Function/Use		Start	Source	Stop	Source	Explain
Residential		1890	Permit			Original
Dwelling & Stor	е		Map/Site	V		Historic/Current

## **CONSTRUCTION DATA**

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1/30/1890	Permit			1300 Permit
Construction Event	Associa	tion		Associated	Name
Orig Construction	Owner-	Builder		Boss, Jose	eph S.
Construction Notes:					
A single permit (#1368) wa	as issued in 1890	for the buil	dings at 416	and 420 H Stree	et, NE.

### **PEOPLE/EVENTS DATA**

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings:	Urban	Cross Reference	Notes:	
Streetscape:	Intact			
Relate to Othr Bldgs:	Attached			
Relate to Street:	Face on Line			
Massing:	Vertical Block			
Footprint:	Rectangular			
Number Stories:	2.5			
Bays Wide:	2			
Height:		Outbuilding Type	Contributing Status	
Width:	16			
Depth/Length:	64			
SqFt:				
Volume:				
Lot Width				
Lot Depth/Length:		Outbuilding Notes:		
Lot SqFt:				
Acreage:				
Has Driveway:				

Tuesday, June 25, 2013

Architectural Style(s)

#### Exterior & Architectural Notes:

May 2009: This two-and-one-half story, two-bay rowhouse was constructed in 1890 by Joseph S. Boss. It was constructed in coordination with the buildings at 416 and 420 H Street, which are extant. A commercial unit is now located in the first story. The building is capped by a false mansard roof of painted octagonal tin shingles. The roof has a paneled cornice, corbeled end braces, projecting party walls with fluted panels, and an ogee-molded coping. The building and solid foundation are constructed of brick and is finished with a stretcher-bond brick veneer. The first story of the façade (south elevation) is fenestrated by a tripled 1/1, double-hung, wood-sash window in the western bay and a single-leaf wood door with lights in the eastern bay. The windows are set in a wood surround and are protected by metal security bars. The door features a metal security storm door. A shed roof spans the façade and shelters the first story of the façade features a tripled 1/1, double-hung, wood-sash window in the second story of the façade features a tripled 1/1, double-hung, wood-sash in the westernmost bay and a paired 1/1, double-hung, wood-sash in the westernmost bay and a paired 1/1, double-hung, wood-sash in the westernmost bay and a paired 1/1, double-hung, wood-sash in the westernmost bay and a paired 1/1, double-hung, wood-sash is finished with a fluted surround and topped by a closed pediment.

An original ell is located off the north (rear) elevation of the main block. It is constructed of brick and capped by a sloping roof. Visible fenestration is made up of 1/1, double-hung, wood-sash windows. Further details could not be seen.

#### Site Notes:

May 2009: This building is located on the north side of H Street, NE and directly fronts the concrete sidewalk. It is adjacent 420 H Street, which is located to the east, and 416 H Street, which is located to the west. A public alley is located to the north and provides access to the rear of the property. A concrete wall spans the northern boundary line.

#### NOTABLE FEATURES DATA

Component

Feature

#### **EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source	
Mansard (False)	Tin		Octagonal Shap	e	
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Brick				
Walls	Brick				
Materials Notes:					

#### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
1 Flr Windows	Rectangular	Dbl-Hung	1/1	Wood	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single		Wood	
Notable Interior Plan(s)			Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	Capitol Hill	Historic District(s)	
Subdivision:			
Ward/ANC:			
Zoning:		Designation Event(s)	
Contributing:			
Survey(s)		Level(s) of Investigation	
Capitol Hill H S	treet (2009)	Permit Research	
		Reconnaissance Survey	
PHOTOS - DIO	SITIZED		

Caption:

Path:	Databases\	HRS\Docume H Street - 2 t e\Pictures\08	o 15th	5
File:	H Street_41	8_facade_lo	oking_N.J	PG
Date::		Photog:		
Code::			R:	Fr:

Caption:

Path:	C:\Users\CHRS\D Databases\H Stre St\Database\Pictu	et - 2 to	15th	i
File:	H Street_418_fac	ade_lool	king_NE.	.JPG
Date::	Phote	og:		
Code::			R:	Fr:

Caption:

Path:	C:\Users\CHRS\Documents\CHRS Databases\H Street - 2 to 15th St\Database\Pictures\0808\	
File:	H Street_418_rear_looking_S.JPG	
Date::	Photog:	
Code::	R:	Fr:

Photographer

Caption

## **MISCELLANEOUS NOTES DATA**

Roll

Frame(s)

Date

Notes:

Photo Code

## PERMIT DATA

Permit Issue Date	Number	Туре		Remarks		
1/30/1890	1368	Build				
Permit Notes:						
BIBLIOGRAPHIC DATA						
Short Citation			Туре	Date	Remarks	
Bibliographic Notes:						
SIGNIFICANCE DATA						
Study Unit						
Code Criteria						

Date	Individual	Action
8/4/2009	Martinkowsky (CHM), Christin	Record Updated
8/4/2009	Martinkowsky (CHM), Christin	Record Created

## **ID Number: 0808-0049**

## **BASICS DATA**

ID Number:	0808-0049	Ye	ear Built:	1890	Da	ta Source:	Permit
Number Exte	ended Stree	t			Qua	d Type of Add	dress
420	H Str	eet		l	NE	Current	
Name(s)				Type of N	lame	9	
Rowhouse, 42	0 H Street, N	Ε		Common	1		
BK Henry Fun	eral Home			Current			
TaxCode1 Ta	xCode2 Tax	Code3 Type	9	Explain			
0808/0049		Squ	are/Lot	Permit			

## STATUS/PURPOSE/USE DATA

Resource Type:	Building		Sta	atus Curre	nt: Extant	
Desig. Status:	Historic		Qu	ality:		
Purpose:	Residential		Co	ndition:	Good	
Function/Use		Start	Source	Stop	Source	Explain
Residential		1890	Permit			Original
Dwelling & Stor	re		Мар			Historic
Funeral Home			Site Visit			Current

## **CONSTRUCTION DATA**

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1/30/1890	Permit			13000 Permit
Construction Event	Associa	ation		Associated	Name
Orig Construction	Owner	Builder		Boss, Jose	eph S.
Construction Notes:					

## **PEOPLE/EVENTS DATA**

Racial Segregation Status:

Surroundings:	Urban	Cross Reference N	Notes:
Streetscape:	Intact		
Relate to Othr Bldgs:	Attached (1 side)		
Relate to Street:	Face on Line		
Massing:	Vertical Block		
Footprint:	Rectangular		
Number Stories:	2.5		
Bays Wide:	2		
Height:		Outbuilding Type	Contributing Status
Width:	16		
Depth/Length:	64		
SqFt:			
Volume:			
Lot Width			
Lot Depth/Length:		Outbuilding Notes:	
Lot SqFt:			
Acreage:			
Has Driveway:	]		

## STYLE/EXTERIOR DATA

Architectural Style(s)

#### Exterior & Architectural Notes:

May 2009: This two-and-one-half story, two-bay building was constructed in 1890 by Joseph S. Boss to be used as a dwelling. It was constructed in coordination with the buildings at 416 and 418 H Street, which are extant. The building features a mansard roof covered in tin octagonal shingles. It is constructed of brick and is set on a solid brick foundation. The second story is veneered in stretcher-bond brick, the first story is covered in stucco and the foundation is obscured by a tin mold pressed to look like rock-faced concrete blocks. Vinyl siding partially clad the north (rear) elevation. On the east (side) elevation is an interior-side brick chimney. A prominent cornice with fret detailing separates the first and second stories.

The first story of the façade (south elevation) is fenestrated by a one-light fixed window flanked by 1/1, double-hung, vinyl-sash windows in the western bay and a single-leaf glass door in a metal frame in the eastern bay. Above the entry is a two-light transom. The first story of the east elevation is fenestrated by three sets of a one-light fixed window flanked by 1/1, double-hung, vinyl-sash windows. Also on the east elevation is a paired one-light casement window,, a recessed entry holding a single-leaf wood door with a transom above and a two-story projecting bay fenestrated by 1/1, double-hung, vinyl-sash windows.

The southeast corner of the first-story is canted and features an ionic column that supports the cornice. Above the canted first-story corner is a three-sided oriel that is capped by a pyramidal roof covered in octagon shingles. The second and top stories (including the corner oriel) are fenestrated by 1/1, double-hung, vinyl-sash windows. Each window on the second story has a concrete sill which continues into a brick sill course that wraps around the south (front) and east (side) elevations. The windows located in the wall dormers on the top story are set in wood surround and feature a closed pediment on top. Visible fenestration on the north (rear) elevation is made up of a 1/1, double-hung, vinyl-sash window.

A one story extension, which may be original to the building, is located off the north (rear) elevation. It features stretcherbond brick and is capped by a flat roof. The roof features the same prominent cornice with fret detailing as the main block. On the east (side) elevation is a double-leaf entry with metal security gate. The entry is protected by an awning.

#### Site Notes:

May 2009: This property is located northwest of the intersection between H Street, NE and 5th Street, NE. The building directly fronts the concrete sidewalk. It is adjacent 418 H Street, which is located to the west. A public alley is located to the north and provides access to the rear of the property.

Color

## NOTABLE FEATURES DATA

Component

Feature

#### **EXTERIOR MATERIALS DATA**

Roof Component

Material

Treatment

Source

Mansard	Tin		Octagonal Shap	e	
Wall Component	Material	Color	Treatment	Source	
Facade (Lower)	Stucco				
Facade (Upper)	Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Brick				
Walls	Brick				
Materials Notes:					

## WINDOW/DOOR/INTERIOR DATA

Main Door	Rectangular	Single		Metal/Glass	
Door Location	Aperture Shape	Туре	Pamels	Material	
2nd FIr Bay	Rectangular	Dbl-Hung	1/1	Vinyl	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
1 Flr Windows	Rectangular	Fixed	1-light	Vinyl	
1 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Window Location	Aperture Shape	Туре	Lights	Material	

Notable Interior Plan(s)

Notable Interior Feature(s)

**Reconnaissance Survey** 

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

	Level(s) of Investigation	
	Designation Event(s)	
Capitol Hill	Historic District(s)	
	Capitol Hill	

## **PHOTOS - DIGITIZED**

Caption:

Path:	C:\Users\CHRS\Docum Databases\H Street - 2 St\Database\Pictures\0	to 15th		
File:	H Street_420_facade_looking_NE.JPG			
Date::	Photog:			
Code::		R:	Fr:	



Path:

Databases\H Street - 2 to 15th St\Database\Pictures\0808\ File: H Street\_420\_facade\_looking\_NW.JPG Photog: Date:: Code:: R:

C:\Users\CHRS\Documents\CHRS

C:\Users\CHRS\Documents\CHRS Databases\H Street - 2 to 15th St\Database\Pictures\0808\

Photog:

R:

Caption:

Path:

File:

Date::

Code::



Fr:

Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption

## **MISCELLANEOUS NOTES DATA**

Notes:					
PERMIT DATA					
Permit Issue Date	Number	Туре	Remarks		
1/30/1890	1368	Build			
Permit Notes:					
BIBLIOGRAPHI	C DATA				
Short Citation		Туре	Date	Remarks	
Bibliographic Note	5:				
SIGNIFICANCE	DATA				
Study Unit					
Code Cr	iteria				

Date	Individual	Action
8/19/2009	Dayton (MSD), Maria	Record Updated
8/5/2009	Martinkowsky (CHM), Christin	Record Updated
8/5/2009	Martinkowsky (CHM), Christin	Record Created