

# Resource All Data Report

**ID Number: 0809-0003**

## BASICS DATA

ID Number: **0809-0003** Year Built: **1893** Data Source: **Permit**

Number Extended Street Quad Type of Address

**715** **4th Street** **NE** **Current**

Name(s) Type of Name

**Single Dwelling, 715 4th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0003** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1893** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1893** **Permit** **1500 Permit**

Construction Event Association Associated Name

**McIntosh, J.N.** **Builder** **McIntosh, J.N.**

**Orig Construction** **Owner** **Brahler, Annie**

Construction Notes:

**Constructed with 717 4th Street, N.E. from the same permit (#0315).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **15**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

**Queen Anne**

## Exterior &amp; Architectural Notes:

**January 2010:** Constructed in 1893, this two-story, two-bay Queen Anne-style single-family dwelling was one of two constructed by J. N. McIntosh from the same permit (#0315). Set on a solid brick foundation, this masonry structure has a stretcher-bond brick veneer. Capped by a shed roof, this dwelling features a molded metal cornice supported by a corbeled brick table. The façade (west elevation) features a two-story projecting bay. Fenestration of the façade consists of 1/1, double-hung, vinyl-sash windows with concrete sills and soldier-brick segmental arches. The main entry is located in the south bay of the first story and holds a single-leaf, paneled metal door with lights sheltered by a metal awning. The south (side) elevation has no fenestration. The east (rear) elevation has a two-story, two-bay ell. This brick structure has a parged east elevation. A shed roof caps the ell. An exterior-side parged brick chimney extends from the north (side) elevation. Fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf, paneled metal door.

## Site Notes:

**January 2010:** This single-family dwelling is located east of 4th Street, N.E. and has a set back from the brick sidewalk of approximately fifteen feet. The north (side) elevation is attached to 717 4th Street, N.E. The front yard has been covered with concrete and is enclosed by a milled point fence. Brick steps lead to the main entry. The backyard is enclosed by a chain-link security fence.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

## Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Metal/Glas</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

## Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**PHOTOS - DIGITIZED**

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 715\_4th\_Street\_NE\_facade\_looking\_E.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 715\_4th\_Street\_NE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 715\_4th\_Street\_NE\_side\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
08/22/1893	0315	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

## SIGNIFICANCE DATA

---

Study Unit

---

Code	Criteria
------	----------

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0814**

## BASICS DATA

ID Number: **0809-0814** Year Built: **1893** Data Source: **Permit**

Number Extended Street Quad Type of Address

**717** **4th Street** **NE** **Current**

Name(s) Type of Name

**Single Dwelling, 717 4th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0814** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1893** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1893** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **McIntosh, J.N.**

**Orig Construction** **Owner** **Brahler, Annie**

Construction Notes:

**Constructed with 715 4th Street, N.E. from the same permit (#0315).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **15**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

January 2010: Constructed in 1893, this two-story, two-bay Queen Anne-style single-family dwelling was one of two constructed by J. N. McIntosh from the same permit (#0315). Set on a solid brick foundation, this masonry structure has a stretcher-bond brick veneer. Capped by a shed roof, this dwelling features a molded metal cornice supported by a corbeled brick table. The façade (west elevation) features a two-story projecting bay. Fenestration of the façade consists of 1/1, double-hung, vinyl-sash windows with concrete sills. Some of the openings have soldier-brick segmental arches and one has a rowlock brick flat arch. The main entry, located in the south bay of the first story, contains a single-leaf, paneled metal door and a single-light transom. The east (rear) elevation has a two-story, two-bay ell. This brick structure has a parged east elevation. A shed roof caps the ell. An exterior-side parged brick chimney extends from the north (side) elevation. Fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf, paneled metal door.

Site Notes:

January 2010: This single-family dwelling is located east of 4th Street, N.E. and has a set back from the brick sidewalk of approximately fifteen feet. The north (side) elevation is attached to 719 4th Street, N.E. and the south (side) elevation to 715 4th Street, N.E. The front yard has been covered with concrete and brick and enclosed by a milled point fence. Concrete steps lead to the main entry. The backyard is partially enclosed by a chain-link security fence and a wood fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>DbI-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Metal</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 717\_4th\_Street\_NE\_facade\_looking\_NE.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 717\_4th\_Street\_NE\_facade\_looking\_SE.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

08/22/1893	0315	Build	
------------	------	-------	--

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

## SIGNIFICANCE DATA

Study Unit

---

Code                      Criteria

---

**DATA PROCESSING EVENTS DATA**

---

Date	Individual	Action
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0809-0017**

## BASICS DATA

ID Number: **0809-0017** Year Built: **1877** Data Source: **Permit**

Number Extended Street Quad Type of Address

**719** **4th Street** **NE Current**

Name(s) Type of Name

**Rowhouse, 719 4th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0017** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1877** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1877** **Permit** **1000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Thompson, Archie**

**Orig Construction** **Owner** **Thompson, Archie**

Construction Notes:

**One of eight rowhouses constructed from the same permit (#0346).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 8)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **14**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate (Vernacular)**

Exterior & Architectural Notes:

January 2010: Constructed in 1877 by Archie Thompson, this two-story, two-bay vernacular single-family dwelling was influenced by the Italianate-style and is one of eight rowhouses constructed from the same permit (#0346). Inspired by the Italianate style, this dwelling has a rectangular form with a rear ell. The masonry structure has a stretcher-bond brick veneer and is set on a solid brick foundation. A sloping roof caps the dwelling and includes an exterior-side brick chimney located on the north (side) elevation of the rear ell. A molded cornice projects from the façade (west elevation) and includes scrolled modillions set between molded brackets placed on a wide plain frieze. The southern bay of the first story holds a single-leaf, paneled metal door with lights set in a narrow, square-edge wood surround. Window openings hold 1/1, double-hung, vinyl-sash windows with rowlock brick sills and inoperable louvered shutters.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 4th Street, N.E. and is set back approximately fifteen feet from the sidewalk. The south (side) elevation of the dwelling is attached to 717 4th Street, N.E. while the north (side) elevation is attached to 721 4th Street, N.E. The level front yard is enclosed by a hairpin and picket fence and includes a brick walkway extending from the sidewalk to the main entry. The rear of the property extends to an alley. The backyard is enclosed by a wood fence.

## NOTABLE FEATURES DATA

Component Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>DbI-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Metal/Glas</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

**PHOTOS - DIGITIZED**

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 719\_4th\_Street\_NE\_facade\_looking\_E.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 719\_4th\_Street\_NE\_facade\_looking\_SE.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 719\_4th\_Street\_NE\_rear\_looking\_W.JPG

Date:: Photog:

Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
05/14/1877	0346	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

## SIGNIFICANCE DATA

---

Study Unit

---

Code	Criteria
------	----------

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0018**

## BASICS DATA

ID Number: **0809-0018** Year Built: **1877** Data Source: **Permit**

Number Extended Street Quad Type of Address

**721** **4th Street** **NE Current**

Name(s) Type of Name

**Rowhouse, 721 4th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0018** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1877** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1877** **Permit** **1000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Thompson, Archie**

**Orig Construction** **Owner** **Thompson, Archie**

Construction Notes:

**One of eight rowhouses constructed from the same permit (#0346).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 8)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **14**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate (Vernacular)**

Exterior & Architectural Notes:

January 2010: Constructed in 1877 by Archie Thompson, this two-story, two-bay vernacular single-family dwelling is one of eight rowhouses constructed from the same permit (#0346). Inspired by the Italianate style, this dwelling has a rectangular form with a one-story rear ell. The masonry structure has a stretcher-bond brick veneer and is set on a solid brick foundation. A sloping roof caps the dwelling and includes an interior-side brick chimney on the north (side) elevation. A molded cornice projects from the façade (west elevation) and includes scrolled modillions set between molded brackets placed on a wide plain frieze. The southern bay of the first story holds a single-leaf, paneled wood door set in a narrow, square-edge wood surround. Window openings hold 1/1, double-hung, vinyl-sash windows with concrete sills and soldier-brick segmental arches. The rear of the main block has similar window fenestration. The one-story rear ell is constructed of brick and capped by a shed roof. An interior-brick chimney is located on the north (side) elevation of the ell. The stack is attached to the rear ell of 723 4th Street, N.E. Fenestration consists of 1/1, double-hung, vinyl-sash windows with soldier-brick segmental arches.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 4th Street, N.E. and is set back approximately fifteen feet from the sidewalk. The south (side) elevation of the dwelling is attached to 719 4th Street, N.E. while the north (side) elevation is attached to 723 4th Street, N.E. The grassy, level front yard is enclosed by a chain-link fence and includes a brick walkway extending from the sidewalk to the main entry. The rear of the property extends to an alley. The backyard is enclosed by a wood fence and includes a mature tree.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Tuesday, June 25, 2013

ID\_Number: 0809-0018 Page 2

Contributing:

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 721\_4th\_Street\_NE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 721\_4th\_Street\_NE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 721\_4th\_Street\_NE\_rear\_looking\_W.JPG  
Date:: Photog:  
Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/14/1877	0346	Build	

Permit Notes:

--

### BIBLIOGRAPHIC DATA

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

--

### SIGNIFICANCE DATA

---

Study Unit \_\_\_\_\_

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0809-0019**

## BASICS DATA

ID Number: **0809-0019** Year Built: **1877** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>723</b>		<b>4th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 723 4th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0809/0019</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1877</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Rear Addition</b>	<b>c. 1990</b>	<b>Site Visit/Map</b>			
----------------------	----------------	-----------------------	--	--	--

<b>Orig Construction</b>	<b>1877</b>	<b>Permit</b>			<b>1000 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Thompson, Archie</b>
--------------------------	----------------	-------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Thompson, Archie</b>
--------------------------	--------------	-------------------------

Construction Notes:

**One of eight rowhouses constructed from the same permit (#0346).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Row (1 of 8)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Row Building/Flat Front**  
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **14**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate (Vernacular)**

Exterior & Architectural Notes:

**January 2010:** Constructed in 1877 by Archie Thompson, this two-story, two-bay vernacular single-family dwelling is one of eight rowhouses constructed from the same permit (#0346). Inspired by the Italianate style, this dwelling has a rectangular form with a two-story rear addition. The masonry structure has a stretcher-bond brick veneer and is set on a solid brick foundation. A sloping roof caps the dwelling. A molded cornice projects from the façade (west elevation) and includes scrolled modillions set between molded brackets placed on a wide plain frieze. The southern bay of the first story holds a single-leaf, paneled door with fanlight and single-light transom. The door opening is composed of a wide plain surround and molded door hood with modillions and molded brackets. Window openings hold 6/6, double-hung, wood-sash windows with wood sills and soldier-brick segmental arches.

The rear of the building has a two-story addition which replaced, or encapsulated, the original one-story rear ell. This addition, based on its form and materials, appears to have been constructed c. 1990. The addition has a brick veneer and a shed roof with plain frieze. Fenestration consists of single and triple window openings with 1/1, double-hung, vinyl-sash windows with false muntins.

Site Notes:

**January 2010:** This single-family dwelling is located on the east side of 4th Street, N.E. and is set back approximately fifteen feet from the sidewalk. The south (side) elevation of the dwelling is attached to 721 4th Street, N.E. while the north (side) elevation is attached to 725 4th Street, N.E. The level front yard is enclosed by a milled point fence and has been hardscaped with brick. Landscaping includes immature trees, shrubs, and foundation plantings. An angled step of brick provides access to the main entry. A wood fence encloses the western half of the backyard. The eastern half has a gravel parking bay.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>6/6</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unknown w/Lights</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 723\_4th\_Street\_NE\_facade\_looking\_E.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 723\_4th\_Street\_NE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 723\_4th\_Street\_NE\_rear\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 723\_4th\_Street\_NE\_rear\_looking\_W.JPG  
Date:: Photog:  
Code:: R: Fr:



#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

#### MISCELLANEOUS NOTES DATA

Notes:

#### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/14/1877	0346	Build	

Permit Notes:

#### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

#### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0020**

## BASICS DATA

ID Number: **0809-0020** Year Built: **1877** Data Source: **Permit**

Number Extended Street Quad Type of Address

**725** **4th Street** **NE Current**

Name(s) Type of Name

**Rowhouse, 725 4th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0020** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1877** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1877** **Permit** **1000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Thompson, Archie**

**Orig Construction** **Owner** **Thompson, Archie**

Construction Notes:

**One of eight rowhouses constructed from the same permit (#0346).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 8)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **14**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate (Vernacular)**

Exterior & Architectural Notes:

January 2010: Constructed in 1877 by Archie Thompson, this two-story, two-bay vernacular single-family dwelling is one of eight rowhouses constructed from the same permit (#0346). Inspired by the Italianate style, this dwelling has a rectangular form with a one-story rear ell. The masonry structure has a stretcher-bond brick veneer and is set on a solid brick foundation. A sloping roof caps the dwelling. A molded cornice projects from the façade (west elevation) and includes scrolled modillions set between molded brackets placed on a wide plain frieze. The southern bay of the first story holds a single-leaf, paneled wood door with single-light transom. Dominating the façade, the door opening is composed of a wide plain surround and molded hood set with modillions and molded brackets. Window openings hold 2/2, double-hung, wood-sash windows with concrete sills and soldier-brick segmental arches. The rear of the main block has similar window fenestration and a single-leaf door opening. Constructed of brick, the one-story rear ell is capped by a shed roof. Fenestration consists of a 6/6, double-hung, wood-sash window with wood sill located on the east (rear) elevation.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 4th Street, N.E. and is set back approximately fifteen feet from the sidewalk. The south (side) elevation of the dwelling is attached to 723 4th Street, N.E. while the north (side) elevation is attached to 727 4th Street, N.E. The level front yard is enclosed by a milled point fence and includes a brick patio and mature shrubs. A brick walkway extends from the brick sidewalk to the main entry. The backyard is enclosed by a wood fence and includes mature trees.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>2/2</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Tuesday, June 25, 2013

ID\_Number: 0809-0020 Page 2

Contributing:

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 725\_4th\_Street\_NE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 725\_4th\_Street\_NE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 725\_4th\_Street\_NE\_rear\_looking\_W.JPG  
Date:: Photog:  
Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/14/1877	0346	Build	



Permit Notes:

--

### BIBLIOGRAPHIC DATA

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

--

### SIGNIFICANCE DATA

---

Study Unit

---

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0021**

## BASICS DATA

ID Number: **0809-0021** Year Built: **1877** Data Source: **Permit**

Number Extended Street Quad Type of Address

**727** **4th Street** **NE Current**

Name(s) Type of Name

**Rowhouse, 727 4th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0021** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1877** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1877** **Permit** **1000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Thompson, Archie**

**Orig Construction** **Owner** **Thompson, Archie**

Construction Notes:

**One of eight rowhouses constructed from the same permit (#0346).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 8)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **14**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

**Stable**

Contributing Status

Outbuilding Notes:

**January 2010: Located east of the dwelling, this one-story, one-bay stable fronts the paved alley. Based on its form and materials, as well as its documentation on the 1904 Sanborn Fire Insurance Company Map, a construction date of c. 1900 can be assigned. Constructed of brick, this stable has a shed**

roof. The stable has been rehabilitated to function as a garage with the installation of a paneled, roll-up garage door on the east elevation. A one-story, one-bay shed has been built on the south (side) elevation. This shed is not associated with 727 4th Street, N.E.

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate (Vernacular)**

Exterior & Architectural Notes:

January 2010: Constructed in 1877 by Archie Thompson, this two-story, two-bay vernacular single-family dwelling is one of eight rowhouses constructed from the same permit (#0346). Inspired by the Italianate style, this dwelling has a rectangular form with a one-story rear ell. The masonry structure has a stretcher-bond brick veneer and is set on a solid brick foundation. A sloping roof caps the dwelling. A molded cornice projects from the façade (west elevation) and includes scrolled modillions set between molded brackets placed on a wide plain frieze. The southern bay of the first story holds a single-leaf, paneled wood door with single-light transom. Dominating the façade, the door opening is composed of a wide plain surround and molded hood set with modillions and molded brackets. Window openings hold 2/2, double-hung, wood-sash windows with concrete sills and soldier-brick segmental arches. The east (rear) elevation of the main block contains 1/1, double-hung, vinyl-sash windows with concrete sills and segmental arches.

The east (rear) elevation has a two-story rear ell. Originally a one-story rear ell, the second story was added by the 1928 Sanborn Fire Insurance Company Map. The ell has a brick veneer is capped by a shed roof. An interior-brick chimney with a parged cap is located in the northeast corner. Fenestration of the ell consists of 1/1, double-hung, vinyl-sash windows with concrete sills and soldier-brick segmental arches.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 4th Street, N.E. and is set back approximately fifteen feet from the sidewalk. The south (side) elevation of the dwelling is attached to 725 4th Street, N.E. while the north (side) elevation is attached to 729 4th Street, N.E. The level front yard is enclosed by a milled point fence and includes mature shrubs. A brick walkway extends from the brick sidewalk to the main entry. The backyard includes a stable fronting the alley.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>2/2</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

---

## PLAN/SURVEY/DESIGNATION DATA

---

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

---

## PHOTOS - DIGITIZED

---

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **727\_4th\_Street\_NE\_facade\_looking\_E.JPG**

Date::

Photog:

Code::

R:

Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **727\_4th\_Street\_NE\_facade\_looking\_SE.JPG**

Date::

Photog:

Code::

R:

Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **727\_4th\_Street\_NE\_rear\_looking\_NW.JPG**

Date::

Photog:

Code::

R:

Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 727\_4th\_Street\_NE\_rear\_looking\_NW\_2.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 727\_4th\_Street\_NE\_stable\_looking\_N.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 727\_4th\_Street\_NE\_stable\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/14/1877	0346	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0021**

## BASICS DATA

ID Number: **0809-0021** Year Built: **1877** Data Source: **Permit**

Number Extended Street Quad Type of Address

**729** **4th Street** **NE Current**

Name(s) Type of Name

**Rowhouse, 729 4th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0021** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1877** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1877** **Permit** **1000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Thompson, Archie**

**Orig Construction** **Owner** **Thompson, Archie**

Construction Notes:

**One of eight rowhouses constructed from the same permit (#0346).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 8)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **14**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate (Vernacular)**

Exterior & Architectural Notes:

January 2010: Constructed in 1877 by Archie Thompson, this two-story, two-bay vernacular single-family dwelling is one of eight rowhouses constructed from the same permit (#0346). Inspired by the Italianate style, this dwelling has a rectangular form with a one-story rear ell. The masonry structure has a stretcher-bond brick veneer and is set on a solid brick foundation. A sloping roof caps the dwelling. A molded cornice projects from the façade (west elevation) and includes scrolled modillions set between molded brackets placed on a wide plain frieze. The southern bay of the first story holds a single-leaf, paneled metal door with twin lights surmounted by a single-light transom. Dominating the façade, the door opening is composed of a wide plain surround and molded hood set with modillions and molded brackets. Window openings hold 1/1, double-hung, vinyl-sash with 2/2, false muntins. The openings have concrete sills and soldier-brick segmental arches. The east (rear) elevation of the main block contains two 1/1, double-hung, vinyl-sash windows and one 2/2, double-hung, wood-sash window. All of the openings have concrete sills and segmental arches. The one-story, one-bay rear ell is constructed of brick and capped by a shed roof. The east (rear) elevation window opening now holds a metal-frame greenhouse window. The opening retains its concrete sill and soldier-brick segmental arch.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 4th Street, N.E. and is set back approximately fifteen feet from the sidewalk. The south (side) elevation of the dwelling is attached to 727 4th Street, N.E. while the north (side) elevation is attached to 731 4th Street, N.E. The level front yard is enclosed by a milled point fence and includes mature shrubs and an immature tree. A brick walkway extends from the brick sidewalk to the main entry. The backyard is covered with brick pavers and is enclosed by a wood fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbi-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Metal/Glas</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Tuesday, June 25, 2013

ID\_Number: 0809-0021 Page 2



Historic Photo:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research  
Reconnaissance Survey

### PHOTOS - DIGITIZED

Caption:



Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 729\_4th\_Street\_NE\_facade\_looking\_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 729\_4th\_Street\_NE\_facade\_looking\_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 729\_4th\_Street\_NE\_rear\_looking\_W.JPG

Date:: Photog:

Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

--

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/14/1877	0346	Build	

Tuesday, June 25, 2013

ID\_Number: 0809-0021 Page 3

Permit Notes:

--

### BIBLIOGRAPHIC DATA

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

--

### SIGNIFICANCE DATA

---

Study Unit

---

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0023**

## BASICS DATA

ID Number: **0809-0023** Year Built: **1877** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>731</b>		<b>4th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 731 4th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0809/0023</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1877</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Addition</b>	<b>c. 1965</b>	<b>Site Visit/Map</b>			
-----------------	----------------	-----------------------	--	--	--

<b>Orig Construction</b>	<b>1877</b>	<b>Permit</b>			<b>1000 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Thompson, Archie</b>
--------------------------	----------------	-------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Thompson, Archie</b>
--------------------------	--------------	-------------------------

Construction Notes:

**One of eight rowhouses constructed from the same permit (#0346).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Row (1 of 8)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Row Building/Flat Front**  
 Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**  
 Bays Wide: **2**  
 Height: **14**  
 Width: **14**  
 Depth/Length: **30**

Outbuilding Type

Contributing Status

SqFt:  
 Volume:  
 Lot Width  
 Lot Depth/Length:  
 Lot SqFt:  
 Acreage:  
 Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate (Vernacular)**

Exterior & Architectural Notes:

January 2010: Constructed in 1877 by Archie Thompson, this two-story, two-bay vernacular single-family dwelling is one of eight rowhouses constructed from the same permit (#0346). Inspired by the Italianate style, this dwelling has a rectangular form with a rear ell. The masonry structure has an eleven-course American-bond brick veneer and is set on a solid brick foundation. A sloping roof caps the dwelling. A molded cornice projects from the façade (west elevation) and includes scrolled modillions set between molded brackets placed on a wide plain frieze. The southern bay of the first story holds a single-leaf wood door surmounted by a single-light transom. Dominating the façade, the door opening is composed of a wide plain surround and molded hood set with modillions and molded brackets. Window openings hold 1/1, double-hung, vinyl-sash and have vinyl-clad sills and soldier-brick segmental arches. The east (rear) elevation of the main block holds a 1/1, double-hung, vinyl-sash windows.

The east (rear) elevation features a rear ell. Originally only one-story, a second story was added c. 1975. This date is assigned because the ell was documented as one-story in height at the time of the 1960 Sanborn Fire Insurance Company map. The ell has been parged and is capped by a shed roof with brick parged parapet walls along the north (side) and south (side) elevations. Fenestration consists of 1/1, double-hung, vinyl-sash windows with vinyl-clad sills.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 4th Street, N.E. and is set back approximately fifteen feet from the sidewalk. The south (side) elevation of the dwelling is attached to 729 4th Street, N.E. while the north (side) elevation is attached to 733 4th Street, N.E. The grassy, level front yard is enclosed by a milled point fence and includes mature shrubs and an immature tree. A brick walkway extends from the brick sidewalk to the main entry. The backyard has immature trees and is enclosed by a wood fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

--

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research  
Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **731\_4th\_Street\_NE\_facade\_looking\_E.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **731\_4th\_Street\_NE\_facade\_looking\_E\_2.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 731\_4th\_Street\_NE\_rear\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 731\_4th\_Street\_NE\_rear\_looking\_W.JPG  
Date:: Photog:  
Code:: R: Fr:



#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

#### MISCELLANEOUS NOTES DATA

Notes:

#### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/14/1877	0346	Build	

Permit Notes:

#### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

#### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0803**

## BASICS DATA

ID Number: **0809-0803** Year Built: **1877** Data Source: **Permit**

Number Extended Street Quad Type of Address

**733** **4th Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 733 4th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0803** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1877** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Rear Addition** **c. 1975** **Site Visit/Map**

**Orig Construction** **1877** **Permit** **1000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Thompson, Archie**

**Orig Construction** **Owner** **Thompson, Archie**

Construction Notes:

**One of eight rowhouses constructed from the same permit (#0346).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Row (1 of 8)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Row Building/Flat Front**  
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **14**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate (Vernacular)**

Exterior & Architectural Notes:

**January 2010:** Constructed in 1877 by Archie Thompson, this two-story, two-bay vernacular single-family dwelling is one of eight rowhouses constructed from the same permit (#0346). Inspired by the Italianate style, this dwelling has a rectangular form with a rear ell. The masonry structure has brick veneer and is set on a solid brick foundation. A sloping roof caps the dwelling and includes an interior-side brick chimney along the north (side) elevation. A molded cornice projects from the façade (west elevation) and includes scrolled modillions set between molded brackets placed on a wide plain frieze. The southern bay of the first story holds a single-leaf wood door surmounted by a single-light transom. Dominating the façade, the door opening is composed of a wide plain surround and molded hood set with modillions and molded brackets. Window openings hold 2/2, double-hung, wood-sash and have concrete sills and soldier-brick segmental arches. The north (side) elevation has been parged. The east (rear) elevation of the main block has a single-leaf wooden French door.

The east (rear) elevation features a rear ell. Originally only one-story, a second story was added c. 1975. This date is assigned because the ell was documented as one-story in height at the time of the 1960 Sanborn Fire Insurance Company map. The ell has been parged and is capped by a shed roof. Fenestration consists of 2/2, double-hung windows (material not discernable from the public right-of-way) with parged sills.

Site Notes:

**January 2010:** This single-family dwelling is located on the east side of 4th Street, N.E. and is set back approximately fifteen feet from the sidewalk. The south (side) elevation of the dwelling is attached to 731 4th Street, N.E. while the north (side) elevation fronts an asphalt alley. The grassy, level front yard is enclosed by a milled fence and includes mature shrubs and trees. A brick walkway extends from the brick sidewalk to the main entry. The backyard is enclosed by a wood fence and has been landscaped with mature trees and shrubs.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Veneer</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>2/2</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood</b>
Notable Interior Plan(s)			Notable Interior Feature(s)	

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b> <b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 733\_4th\_Street\_NE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 733\_4th\_Street\_NE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:



Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 733\_4th\_Street\_NE\_rear\_looking\_W.JPG

Date:: Photog:

Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

---

05/14/1877	0346	Build	
------------	------	-------	--

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0062**

## BASICS DATA

ID Number: **0809-0062** Year Built: **1929** Data Source: **Permit**

Number Extended Street Quad Type of Address

**400** **G Street** **NE Current**

Name(s) Type of Name

**Apartment Building, 400 G Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0062** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current:

Desig. Status: **Historic** Quality:

Purpose: **Apartment** Condition:

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1929** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1929** **Permit** **6000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Lane, Thomas J., Jr.**

**Orig Construction** **Builder** **Lane, Thomas J., Jr.**

**Orig Construction** **Owner** **Lane, Thomas J., Jr.**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Corner Attached (1 side)**  
Relate to Street: **Face on Setback Line**  
Massing: **Vertical Block**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **20**

Depth/Length: **50**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Colonial Revival

Exterior & Architectural Notes:

January 2010: Constructed in 1929 by Thomas J. Lane, Jr., this Colonial Revival-style, multi-family dwelling is set on a solid brick foundation. The masonry structure has seven- and eight-course American-bond brick coursing. A molded architrave delineates the structure from the brick parapet wall. With recessed brick panels and a thin molded cornice, the parapet wall serves to obscure the sloped roof. The architrave and cornice and brick parapet wall extends across the façade (south elevation) and west (side) elevation. An exterior-brick chimney is located on the north (rear) elevation. Fenestration of the dwelling consists of 1/1, double-hung, vinyl-sash windows with concrete sills and splayed brick jack arches with concrete keystones. The façade holds a single-leaf, paneled wood door with half-round transom located in the eastern bay. A metal awning shelters the opening. Located on the second story of the north (rear) elevation is a single-leaf, paneled wood door with single-light transom.

Site Notes:

January 2010: This dwelling is located on a corner lot northeast of the intersection of G Street, N.E. and 4th Street, N.E. Setback from the brick sidewalk along 4th Street, N.E. approximately fifteen feet, the east (side) elevation is attached to 402 G Street, N.E. The elevated yard features a brick retaining wall lined with mature shrubs. A concrete walkway extends from 4th Street, N.E. to the main entry. The rear of the property extends north to an alley. The backyard is enclosed by a wood fence. A second-story wood deck with stairs has been built on the north (rear) elevation of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

---

**PHOTOS - DIGITIZED**

---

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 400\_G\_Street\_NE\_facade\_looking\_N.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 400\_G\_Street\_NE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 400\_G\_Street\_NE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 400\_G\_Street\_NE\_rear\_looking\_S.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 400\_G\_Street\_NE\_rear\_looking\_SW.JPG

Date:: Photog:

Code:: R: Fr:



---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/04/1929	124219	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

---

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created

---

# Resource All Data Report

**ID Number: 0809-0061**

## BASICS DATA

ID Number: **0809-0061** Year Built: **1885** Data Source: **Permit**

Number Extended Street Quad Type of Address

**402** **G Street** **NE Current**

Name(s) Type of Name

**Single Dwelling, 402 G Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0061** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1885** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Rear Addition** **c. 1980** **Site Visit/Map**

**Orig Construction** **1885** **Permit** **1350 Permit**

Construction Event Association Associated Name

**Brooker, Bernard** **Owner** **Brooker, Bernard**

Construction Notes:

**Constructed with 404 G Street, N.E. from the same permit (#0666).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne  
Italianate

Exterior & Architectural Notes:

January 2010: Constructed in 1885 by Bernard Brooker, this two-story, two-bay dwelling is one of two dwellings constructed from the same permit (#0666). With influences of the Queen Anne style and Italianate style, this vernacular dwelling is set on a solid brick foundation. The masonry structure has stretcher-bond brick coursing and multiple brick string courses. A sloped roof with molded and corbeled cornice caps the dwelling. An interior-brick chimney pierces the roof. The façade (south elevation) features a full-height projecting bay. The bay features chamfered edges and a sill course. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows with concrete sills. All of the openings have segmental brick arches with molded brick cap. The main entry is located in the western bay of the first story. This opening holds a single-leaf, paneled wood door with single-light transom. The north (rear) elevation of the main block has a 1/1, double-hung, vinyl-sash window located in the western bay of the second story. A two-story, one-bay ell is located on the rear elevation. This brick structure is capped by a shed roof and includes 1/1, double-hung, vinyl-sash windows with concrete sills and segmental brick arches.

A one-story, one-bay addition is located west of the two-story ell. Based on its form and materials, this addition appears to have been constructed c. 1980. Clad in vinyl siding and capped by a shed roof, the addition holds a single-leaf, paneled metal door with two-lights.

Site Notes:

January 2010: This dwelling is located north of G Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The west (side) elevation is attached to 400 G Street, N.E. and the east (side) elevation to 404 G Street, N.E. The elevated front yard slopes to the south and features a coursed stone retaining wall. A mature tree highlights the front yard. A concrete walkway extends from the sidewalk to the main entry. The rear of the property extends north to an alley. The backyard is enclosed by a wood fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Tuesday, June 25, 2013

ID\_Number: 0809-0061 Page 2

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 402\_G\_Street\_NE\_facade\_looking\_N.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 402\_G\_Street\_NE\_facade\_looking\_NW.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 402\_G\_Street\_NE\_rear\_looking\_S.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
09/25/1885	0666	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0060**

## BASICS DATA

ID Number: **0809-0060** Year Built: **1885** Data Source: **Permit**

Number Extended Street Quad Type of Address

**404** **G Street** **NE** **Current**

Name(s) Type of Name

**Single Dwelling, 404 G Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0060** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1885** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1885** **Permit** **1350 Permit**

Construction Event Association Associated Name

**Orig Construction** **Owner** **Brooker, Bernard**

Construction Notes:

**Constructed with 402 G Street, N.E. from the same permit (#0666).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Tuesday, June 25, 2013

ID\_Number: 0809-0060 Page 1

## Architectural Style(s)

**Queen Anne**

**Italianate**

### Exterior & Architectural Notes:

**January 2010:** Constructed in 1885 by Bernard Brooker, this two-story, two-bay dwelling is one of two dwellings constructed from the same permit (#0666). With influences of the Queen Anne style and Italianate style, this vernacular dwelling is set on a solid brick foundation. The masonry structure has stretcher-bond brick coursing and multiple brick string courses. A sloped roof with molded and corbeled cornice caps the dwelling. An interior-brick chimney pierces the roof. The façade (south elevation) features a full-height projecting bay. The bay features chamfered edges and a sill course. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows with concrete sills. All of the openings have segmental brick arches with molded brick cap. The main entry is located in the western bay of the first story. This opening holds a single-leaf, paneled wood door with single-light transom. The north (rear) elevation of the main block has 1/1, double-hung, vinyl-sash windows with concrete sills and segmental brick arches. A two-story, one-bay ell is located on the rear elevation. This brick structure is capped by a shed roof and includes 1/1, double-hung, vinyl-sash windows with concrete sills and segmental brick arches.

### Site Notes:

**January 2010:** This dwelling is located north of G Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The west (side) elevation is attached to 402 G Street, N.E. and the east (side) elevation to 406 G Street, N.E. The elevated front yard has a brick retaining wall and includes immature plantings. A concrete walkway extends from the sidewalk to the main entry. The rear of the property extends north to an alley. The backyard is enclosed by a wood fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

### Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbi-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

### Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

---

**PHOTOS - DIGITIZED**

---

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 404-400\_G\_Street\_NE\_rear\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 404\_G\_Street\_NE\_facade\_looking\_N.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 404\_G\_Street\_NE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 404\_G\_Street\_NE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 404\_G\_Street\_NE\_rear\_looking\_S.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 404\_G\_Street\_NE\_rear\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

#### MISCELLANEOUS NOTES DATA

Notes:

#### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
09/25/1885	0666	Build	

Permit Notes:

#### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

#### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0809-0059**

## BASICS DATA

ID Number: **0809-0059** Year Built: **1888** Data Source: **Permit**

Number Extended Street Quad Type of Address

**406** **G Street** **NE Current**

Name(s) Type of Name

**Single Dwelling, 406 G Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0059** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1888** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1888** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Trumble & Gibson**

**Orig Construction** **Owner** **Trumble & Gibson**

Construction Notes:

**Constructed with 408 G Street, N.E. from the same permit (#1636).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Italianate

Exterior & Architectural Notes:

January 2010: Constructed in 1888 by Trumble & Gibson, this two-story, two-bay dwelling is one of two dwellings constructed from the same permit (#1636). With influences of the Queen Anne style and Italianate style, this vernacular dwelling is set on a solid brick foundation. The masonry structure has stretcher-bond brick coursing and includes brick sill courses. A sloped roof with molded and corbeled cornice caps the dwelling. An interior-brick chimney pierces the roof. The façade (south elevation) features a full-height projecting bay with chamfered edges. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows with concrete sills. The western bays contain multi-light fixed windows. All of the openings have segmental brick arches with a molded brick cap. The main entry is located in the eastern bay of the first story. This opening holds a single-leaf, paneled wood door with single-light transom. The north (rear) elevation of the main block has 1/1, double-hung, vinyl-sash windows with concrete sills and segmental brick arches. A two-story, one-bay ell is located on the rear elevation. This brick structure is capped by a shed roof and includes 1/1, double-hung, vinyl-sash windows with concrete sills and segmental brick arches and a single-leaf French door.

Site Notes:

January 2010: This dwelling is located north of G Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The west (side) elevation is attached to 404 G Street, N.E. and the east (side) elevation to 408 G Street, N.E. The elevated front yard has a brick retaining wall and includes immature trees and shrubs. A brick walkway extends from the sidewalk to the main entry. The rear of the property extends north to an alley. The backyard is enclosed by a wood fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>Multi-lite</b>	<b>Unknown</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research  
Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 406\_G\_Street\_NE\_facade\_looking\_NE.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 406\_G\_Street\_NE\_facade\_looking\_NW.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 406\_G\_Street\_NE\_rear\_looking\_S.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/31/1888	1636	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0058**

## BASICS DATA

ID Number: **0809-0058** Year Built: **1888** Data Source: **Permit**

Number Extended Street Quad Type of Address

**408** **G Street** **NE** **Current**

Name(s) Type of Name

**Single Dwelling, 408 G Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0058** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1888** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1888** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Trumble & Gibson**

**Orig Construction** **Owner** **Trumble & Gibson**

Construction Notes:

**Constructed with 406 G Street, N.E. from the same permit (#1636).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Italianate

Exterior & Architectural Notes:

January 2010: Constructed in 1888 by Trumble & Gibson, this two-story, two-bay dwelling is one of two dwellings constructed from the same permit (#1636). With influences of the Queen Anne style and Italianate style, this dwelling is set on a solid brick foundation. The masonry structure has stretcher-bond brick coursing and includes brick sill courses. A sloped roof with molded and corbeled cornice caps the dwelling. An interior-brick chimney pierces the roof. The façade (south elevation) features a full-height projecting bay with chamfered edges. Window openings on the façade hold single and paired 1/1, double-hung, wood-sash windows with wood sills. All of the openings have segmental brick arches with a molded brick cap. The main entry is located in the western bay of the first story. This opening holds a single-leaf, paneled wood door with single-light transom. A wood-frame glass storm door has been fitted to the opening. The north (rear) elevation of the main block has a 2/2, double-hung, wood-sash window with concrete sill and segmental brick arch and a single-leaf door opening with segmental arch. A two-story, one-bay ell is located on the rear elevation. This brick structure is capped by a shed roof and includes 2/2, double-hung, wood-sash windows with concrete sills and segmental brick arches and a double-leaf French door.

Site Notes:

January 2010: This dwelling is located north of G Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The west (side) elevation is attached to 406 G Street, N.E. and the east (side) elevation to 410 G Street, N.E. The elevated front yard has a brick retaining wall and includes mature trees and ground covering. A concrete walkway extends from the sidewalk to the main entry. The rear of the property extends north to an alley. The backyard is enclosed by a wood fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

---

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

---

Survey(s)

---

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

---

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

---

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **408\_G\_Street\_NE\_facade\_looking\_N.JPG**

Date:: Photog:

Code:: R: Fr:

---



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **408\_G\_Street\_NE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

---



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **408\_G\_Street\_NE\_rear\_looking\_S.JPG**

Date:: Photog:

Code:: R: Fr:

---



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **408\_G\_Street\_NE\_rear\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:

---



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/31/1888	1636	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0809-0057**

## BASICS DATA

ID Number: **0809-0057** Year Built: **c. 1980** Data Source: **Site Visit/Map**

Number Extended Street Quad Type of Address

**410** **G Street** **NE** **Current**

Name(s) Type of Name

**Single Dwelling, 410 G Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0057** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **c. 1980** **Site Visit/** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **c. 1980** **Site Visit/Map**

Construction Event Association Associated Name

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Modern**

Exterior & Architectural Notes:

January 2010: This two-story, two-bay single-family dwelling, based on its form and materials, appears to have been constructed c. 1980. Set on a solid foundation, this dwelling has a stretcher-bond brick veneer. The sloped roof has a molded wood cornice and plain fascia board. The façade (south elevation) features a two-story projecting bay. Window openings hold single or paired 1/1, double-hung, vinyl-sash windows with rowlock brick sills and inoperable louvered vinyl shutters. The main entry is located in the eastern bay and holds a single-leaf, paneled wood door with lights.

The north (rear) elevation features a two-story, full-height projection. It is likely that this was an original c. 1985 feature. This concrete-block appendage is partially clad in vinyl siding and capped by a shed roof. Fenestration consists of a single-leaf, metal door, sliding windows, and a sliding-glass door.

Site Notes:

January 2010: This dwelling is located north of G Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The west (side) elevation is attached to 408 G Street, N.E. and the east (side) elevation to 412 G Street, N.E. The elevated front yard has a brick retaining wall and includes mature shrubs. Brick steps lead from the sidewalk to the main entry, which is flanked by a brick partition wall. The rear of the property extends north to an alley. The backyard is enclosed by a metal fence and includes a concrete parking bay. A second-story wood deck has been constructed on the rear of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Unknown</b>			
<b>Walls</b>	<b>Unknown</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Tuesday, June 25, 2013

ID\_Number: 0809-0057 Page 2

Contributing:

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 410\_G\_Street\_NE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 410\_G\_Street\_NE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 410\_G\_Street\_NE\_rear\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

--

### **BIBLIOGRAPHIC DATA**

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

--

### **SIGNIFICANCE DATA**

---

Study Unit

---

Code	Criteria
------	----------

---

### **DATA PROCESSING EVENTS DATA**

---

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0056**

## BASICS DATA

ID Number: **0809-0056** Year Built: **1890** Data Source: **Permit**

Number Extended Street Quad Type of Address

**412** **G Street** **NE Current**

Name(s) Type of Name

**Single Dwelling, 412 G Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0056** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1890** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1890** **Permit** **1250 Permit**

Construction Event Association Associated Name

**Louthran & Co.** **Builder** **Louthran & Co.**

**Orig Construction** **Owner** **Brooker, Bernard**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Italianate

Exterior & Architectural Notes:

January 2010: Constructed in 1890 by Louthran & Co., this two-story, two-bay dwelling is one of two dwellings constructed from the same permit (#1423). This is the only extant dwelling built from that permit. With influences of the Queen Anne style and Italianate style, this dwelling is set on a solid brick foundation. The masonry structure has stretcher-bond brick coursing and includes brick sill courses. A sloped roof with molded and corbeled cornice caps the dwelling. An interior-brick chimney pierces the roof. The façade (south elevation) features a full-height projecting bay with chamfered edges. Window openings on the façade hold 6/6, double-hung, wood-sash windows with rowlock brick sills. The projecting bay features two, sixteen-light landscape windows. All of the openings have segmental brick arches with a molded brick cap. The main entry is located in the western bay of the first story. This opening holds a single-leaf, paneled metal door with single-light transom. The north (rear) elevation of the main block has a 6/6, double-hung, wood-sash window with rowlock brick sill and segmental arch. Additional details of the main block were not visible from the public right-of-way. A two-story, one-bay ell is located on the rear elevation. This brick structure is capped by a shed roof. The openings have been altered to allow the installation of tall, single-light fixed windows. The openings retain their rowlock brick sills.

Site Notes:

January 2010: This dwelling is located north of G Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The west (side) elevation is attached to 410 G Street, N.E. and the east (side) elevation to 412 G Street, N.E. The elevated front yard has a stone retaining wall and includes mature trees. A stone paver walkway extends from the sidewalk to the main entry. The rear of the property extends north to an alley. The backyard is enclosed by a wood fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>6/6</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>6/6</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>16 Lites</b>	<b>Unknown</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Metal</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

---

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

---

Survey(s)

---

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

---

**Permit Research**

**Reconnaissance Survey**

---

## PHOTOS - DIGITIZED

---

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **412\_G\_Street\_NE\_facade\_looking\_N.JPG**

Date:: Photog:

Code:: R: Fr:

---



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **412\_G\_Street\_NE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

---



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **412\_G\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

---



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **412\_G\_Street\_NE\_rear\_looking\_S.JPG**

Date:: Photog:

Code:: R: Fr:

---



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 412\_G\_Street\_NE\_rear\_looking\_SW.JPG

Date:: Photog:

Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
02/12/1890	1423	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0809-0055**

## BASICS DATA

ID Number: **0809-0055** Year Built: **1890** Data Source: **Permit**

Number Extended Street Quad Type of Address

**414** **G Street** **NE Current**

Name(s) Type of Name

**Single Dwelling, 414 G Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0055** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1890** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1890** **Permit** **1890 Permit**

Construction Event Association Associated Name

**Gibson, Luther** **Builder** **Gibson, Luther**

**Orig Construction** **Owner** **Brooker, B.H.**

Construction Notes:

**Constructed with 416 G Street, N.E. from the same permit (#1025).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Italianate

Exterior & Architectural Notes:

January 2010: Constructed in 1890 by Luther Gibson, this two-story, two-bay dwelling is one of two dwellings constructed from the same permit (#1025). With influences of the Queen Anne style and Italianate style, this dwelling has a rectangular form with a rear ell. Set on a solid brick foundation, this masonry structure has stretcher-bond brick coursing with brick sill courses. A sloped roof with molded and corbeled cornice caps the dwelling. An interior-brick chimney pierces the roof. The façade (south elevation) features a full-height projecting bay with chamfered edges. Window openings on the façade have single and paired 1/1, double-hung, vinyl-sash windows with concrete sills. All of the openings have segmental brick arches with a molded brick cap. The main entry is located in the western bay of the first story. This opening holds a single-leaf, paneled wood door with single-light transom. The north (rear) elevation of the main block has a 1/1, double-hung, vinyl-sash windows with concrete sills and segmental brick arch. A two-story, one-bay ell is located on the rear elevation. This brick structure is capped by a shed roof and includes a 6/6, double-hung, wood-sash window with concrete sill set in a narrow, square-edge wood surround and a single-leaf French door.

Site Notes:

January 2010: This dwelling is located north of G Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The west (side) elevation is attached to 412 G Street, N.E. and the east (side) elevation to 416 G Street, N.E. The elevated front yard slopes to the south and has a brick retaining wall. A brick walkway extends from the sidewalk to the main entry. The rear of the property extends north to an alley. The backyard is enclosed by a wood fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Tuesday, June 25, 2013

ID\_Number: 0809-0055 Page 2

Ward/ANC:  
Zoning:  
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 414\_G\_Street\_NE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 414\_G\_Street\_NE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 414\_G\_Street\_NE\_rear\_looking\_S.JPG  
Date:: Photog:  
Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

--

**BIBLIOGRAPHIC DATA**

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

--

**SIGNIFICANCE DATA**

---

Study Unit

--

Code	Criteria
------	----------

---

**DATA PROCESSING EVENTS DATA**

---

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0816**

## BASICS DATA

ID Number: **0809-0816** Year Built: **1890** Data Source: **Permit**

Number Extended Street Quad Type of Address

**416** **G Street** **NE Current**

Name(s) Type of Name

**Single Dwelling, 416 G Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0816** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1890** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1890** **Permit** **2000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Gibson, Luther**

**Orig Construction** **Owner** **Brooker, B.H.**

Construction Notes:

**Constructed with 414 G Street, N.E. from the same permit (#1025).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Italianate

Exterior & Architectural Notes:

January 2010: Constructed in 1890 by Luther Gibson, this two-story, two-bay dwelling is one of two dwellings constructed from the same permit (#1025). With influences of the Queen Anne style and Italianate style, this dwelling has a rectangular form with a rear ell. Set on a solid brick foundation, this masonry structure has stretcher-bond brick coursing with brick sill courses. A sloped roof with molded and corbeled cornice caps the dwelling. An interior-brick chimney pierces the roof of the rear ell. The façade (south elevation) features a full-height projecting bay with chamfered edges. Window openings on the façade contain 1/1, double-hung, vinyl-sash windows with wood sills. The projecting bay features two multi-light fixed landscape windows. All of the openings have segmental brick arches with a molded brick cap. The main entry is located in the western bay of the first story. This opening holds a single-leaf, paneled wood door with single-light transom. The east (side) elevation has been parged and has no window or door openings. The north (rear) elevation of the main block has a 1/1, double-hung, vinyl-sash windows with concrete sills and segmental brick arches. A two-story, one-bay ell is located on the rear elevation. This brick structure is capped by a shed roof and includes 1/1, double-hung, vinyl-sash windows with concrete sills and two-course, rowlock brick segmental arches. Additional details were not visible from the public right-of-way.

Site Notes:

January 2010: This dwelling is located north of G Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The west (side) elevation is attached to 414 G Street, N.E. The elevated front yard slopes to the south and has been terraced with stone and wood retaining walls. Mature shrubs mark the front yard. A brick walkway extends from the sidewalk to the main entry. The rear of the property extends north to an alley. The backyard is enclosed by a wood fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>Multi-lite</b>	<b>Unknown</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

---

Designation Event(s)

---

Survey(s)

---

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

---

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

---

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **416\_G\_Street\_NE\_facade\_looking\_N.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **416\_G\_Street\_NE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **416\_G\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **416\_G\_Street\_NE\_rear\_looking\_S.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 416\_G\_Street\_NE\_rear\_looking\_SW.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 416\_G\_Street\_NE\_side\_looking\_W.JPG

Date:: Photog:

Code:: R: Fr:

#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

#### MISCELLANEOUS NOTES DATA

Notes:

#### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/27/1890	1025	Build	

Permit Notes:

#### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

#### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Updated
2/24/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0068**

## BASICS DATA

ID Number: **0809-0068** Year Built: **1946** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>709</b>		<b>4th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Church, 709 4th Street, N.E.</b>	<b>Common</b>
<b>Holy Trinity Episcopal Church</b>	<b>Historic</b>
<b>Northeast Holy Trinity Church</b>	<b>Current</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0809/0068</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Church** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Church/Sunday School</b>	<b>1946</b>	<b>Permit</b>			<b>Historic/Current</b>
-----------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1946</b>	<b>Permit</b>			<b>20000 Permit</b>
--------------------------	-------------	---------------	--	--	---------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Northeast Holy Trinity Church</b>
<b>Vaughn, R.</b>	<b>Architect</b>	<b>Vaughn, R.</b>

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Freestanding**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Block with Tower(s)**  
Footprint: **Rectangular (w/ side bays)**

Cross Reference Notes:

Number Stories: **1 plus basement**  
Bays Wide: **3**

Height:

Outbuilding Type

Contributing Status

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Gothic Revival**

Exterior & Architectural Notes:

January 2010: Constructed in 1946 and opened in 1947, this Gothic Revival-style church is one story in height and three-bays wide. A one-bay addition was added to the north (side) elevation. Set on a solid concrete foundation, this concrete structure has six-course, American-bond brick coursing. A front-gabled roof caps the church and includes a raking wood cornice. A brick parapet wall extends down the south (side) elevation. The façade (west elevation) features a projecting central bay which extends to form a four-sided bell tower topped by a cross. Each face of the projecting bell tower features louvered vents set in pointed arch openings with concrete arches. The tower is flanked by sloped brick parapet walls which are anchored by brick corner pilasters. The parapet walls, pilasters, and bell tower have concrete coping. Fenestration of the façade consists of a double-leaf, metal-frame glass door with concrete lug lintel located in the central projecting bay. Above this opening is a metal sign and a 1/1, double-hung, wood-sash stained-glass window with concrete sill. Flanking the projecting bay are tall pointed arch stained-glass windows. This openings have rowlock brick sills and concrete arches. Panels of soldier brick highlight the area beneath the openings. This decorative element is also found on the projecting central bay. The south (side) elevation has four basement openings and four first-story openings. The basement openings hold 2/2, double-hung, wood-sash windows with rowlock brick sills. The first-story features pointed arch stained-glass windows set in rectangular openings with rowlock brick sills and soldier-brick jack arches. Additions have been constructed on the north (side) and east (rear) elevations.

The east (rear) elevation has a one-story, full-width addition. Based on its form and materials, this addition appears to have been constructed c. 1955 and replaced an earlier addition. The current addition is capped by a shed roof with plain fascia board and a brick parapet wall along the south and north elevations. An exterior brick chimney is located on the east (rear) elevation of the addition. Fenestration consists of 1/1, double-hung, vinyl-sash windows with rowlock brick sills and a porthole with rowlock brick surround.

The north (side) elevation has a one-story addition, which based on its form and materials, appears to have been constructed c. 1965. This addition has six-course, American-bond brick coursing and is capped by a shed roof obscured from view by a brick parapet wall. Like the main block, the addition has a concrete coping along the parapet wall and a brick corner pilaster. Fenestration of the façade (west) elevation consists of a tall pointed arch stained-glass window. Similar to the façade of the main block, this opening has a rowlock brick sill with a panel of soldier bricks beneath and a concrete arch. The north (side) elevation of the addition has pointed arch stained-glass windows set in rectangular openings with rowlock brick sills and soldier-brick jack arches. A single-leaf door is accessed via a concrete handicapped ramp with metal railing or concrete steps.

A third addition is located on the north (side) elevation of the rear addition. Based on its form and materials, this addition appears to have been constructed c. 1975. The addition has a stretcher-bond brick veneer and shed roof with plain fascia board and brick parapet wall along the north (side) elevation. Fenestration consists of a 6/6, double-hung, wood-sash window with rowlock brick sill.

Site Notes:

January 2010: This church is located east of 4th Street, N.E. and is set back from the brick and concrete sidewalk approximately twenty feet. This detached building fronts a paved alley to the south and to the east. The level lot has a grassy front yard with mature shrubs enclosed with a milled point fence. A brick sign is located in the front yard as well. Brick steps covered with carpet provide access to the main entry along 4th Street, N.E. A handicapped ramp is located in the north end of the property providing access from 4th Street, N.E. to the north (side) elevation of the church. The rear of the property is enclosed by a chain-link security fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Gable</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete Block</b>			
<b>Walls</b>	<b>Concrete Block</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Pointed-Arched</b>	<b>Fixed</b>	<b>Stained</b>	<b>Unknown</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>Stained</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Metal/Glas</b>

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 709\_4th\_Street\_NE\_facade\_looking\_NE.JPG**  
Date:: Photog:  
Code:: R: Fr:

---



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 709\_4th\_Street\_NE\_facade\_looking\_SE.JPG**  
Date:: Photog:  
Code:: R: Fr:

---



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 709\_4th\_Street\_NE\_rear\_looking\_NW.JPG**  
Date:: Photog:  
Code:: R: Fr:

---



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 709\_4th\_Street\_NE\_rear\_looking\_SW.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 709\_4th\_Street\_sign\_looking\_NE.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

10/16/1946	289752	Build	
------------	--------	-------	--

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0051**

## BASICS DATA

ID Number: **0809-0051** Year Built: **1886** Data Source: **Permit**

Number Extended Street Quad Type of Address

**700** **5th Street** **NE** **Current**

Name(s) Type of Name

**Single Dwelling, 700 5th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0051** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1886** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Rear Addition** **pre 1928** **Site Visit/Map**

**Addition (Top)** **pre 1928** **Site Visit/Map**

**Addition (Side)** **pre 1904** **Site Visit/Map**

**Orig Construction** **1886** **Permit** **1400 Permit**

Construction Event Association Associated Name

**Barr, Robert** **Builder** **Barr, Robert**

**Orig Construction** **Owner** **Kober, Mary C.**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Freestanding**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Vertical Block**  
Footprint: **Rectangular (w/ additions)**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **5**

Height:

Outbuilding Type

Contributing Status

Width: **16**

Depth/Length: **37**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

Exterior & Architectural Notes:

January 2010: Constructed in 1886 by Robert Barr, this Italianate-style single-family dwelling has a rectangular form. Set on a solid brick foundation, this two-story, five-bay masonry structure has been parged. The sloped roof is obscured by a parged parapet wall with corbelling. The façade (east elevation) features two-story, one-bay projection. This bay has chamfered corners and extends approximately two feet beyond the parapet of the main block. Located on the first story of the projection is the main entry composed of a single-leaf, paneled wood door with eight-light transom and three-light sidelights set in a narrow, square-edge wood surround. Sheltering the main entry is a one-story, one-bay porch. The porch has a front-gabled roof of tin with an open pediment and cornice returns. Tuscan columns set on a stone landing support the porch. The segmentally arched window openings hold 2/2, double-hung, wood-sash windows with concrete sills. A projecting string extends between the first- and second-story openings. The north (side) elevation has three window openings.

The south (side) elevation has a two-story, one-bay addition. Based on Sanborn Fire Insurance Company maps, the first story of this addition was completed by 1904 and may be original (though its form suggest against this). The second story, which has a slightly smaller footprint, was completed by 1928. The addition has been parged and is capped by a shed roof with thin overhanging eaves. Fenestration consists of paired and triple openings with 2/2, double-hung, wood-sash windows. The first-story openings have parged sills and are set in narrow, square-edge wood surrounds. The second-story openings have square-edge wood surrounds.

The west (rear) elevation features a two-story, two-bay deep addition. Based on Sanborn Fire Insurance Company maps, this addition was completed between 1904 and 1928. The first story originally served as a garage. Parged, this addition has a shed roof. Fenestration of the addition was only evident on the north (side) elevation. The first story has a 2/2, double-hung, wood-sash window with a concrete sill set in a narrow, square-edge wood surround and a single-leaf, paneled wood door with single-light transom. The door opening is sheltered by a shed-roof porch supported by a wood post set on a wood platform. A wood-frame projection extends off the main block approximately three feet. A single-leaf, paneled wood door is located on the west elevation of this projection. The second story of the rear addition is pierced by two segmentally arched window openings with 2/2, double-hung, wood-sash windows and concrete sills set in narrow, square-edge wood surrounds.

Site Notes:

January 2010: This single-family dwelling is located on a large corner lot northwest of the intersection of 5th Street, NE and G Street, NE. Thoroughly landscaped, this level, grassy lot features mature and immature trees, shrubs, and foundation plantings. A stone retaining wall extends along 5th Street and G Street and along the asphalt alley north of the dwelling. The asphalt alley provides access to a concrete parking bay northwest of the dwelling. A parged privacy wall with rounded top is located south of the dwelling and encloses a brick patio. The western boundary of the property is lined by a wood fence.

## NOTABLE FEATURES DATA

Component

Feature



## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Parged</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Segmental-Arched</b>	<b>DbI-Hung</b>	<b>2/2</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**  
**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**  
File: **700\_5th\_Street\_NE\_facade\_looking\_NW.JPG**  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 700\_5th\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 700\_5th\_Street\_NE\_rear\_elevation\_looking\_N  
E.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 700\_5th\_Street\_NE\_rear\_elevation\_looking\_S  
E.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 700\_5th\_Street\_NE\_south\_elevation.JPG  
Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
07/10/1886	0080	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

## SIGNIFICANCE DATA

---

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0050**

## BASICS DATA

ID Number: **0809-0050** Year Built: **1931** Data Source: **Permit**

Number Extended Street Quad Type of Address

**708** **5th Street** **NE Current**

Name(s) Type of Name

**Flat, 708 5th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0050** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1931** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1931** **Permit** **6000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Santmyers, George T.**

**Orig Construction** **Builder** **Sullivan Bros.**

**Orig Construction** **Owner** **Sullivan Bros.**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **19**

Depth/Length: **46**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Neoclassical**

Exterior & Architectural Notes:

January 2010: Constructed in 1931 by the Sullivan Brothers following the design of architect George T. Santmyers, this two-story, two-bay, multi-family dwelling has elements of the Neo Classical style. Set on a solid brick foundation, this brick structure has eight-course American-bond brick coursing on the façade (east elevation). A sloped roof caps the dwelling and features a brick parapet wall with concrete coping along the façade and south (side) elevation. An exterior-side brick chimney extends from the south elevation. The northern bay of the first story holds a single-leaf, paneled wood door with six lights and a three-light transom. The concrete Neo Classical-style door surround is composed of engaged fluted pilasters supporting a monumental frieze, cornice, and pediment. The southern bay holds paired 1/1, double-hung, vinyl-sash windows with false 6/6 muntins. The second story is pierced by a triple window composed of 1/1, double-hung, vinyl-sash windows with 6/6 and 4/4 false muntins. All of the window openings have concrete sills and soldier-brick jack arches. A molded architrave extends above the second-story openings. The eastern bay of the south (side) elevation projects slightly to form a defined southeast corner of the building. Fenestration of the south elevation consists of 1/1, double-hung, vinyl-sash windows with 6/6 false muntins and rowlock brick sills.

A two-story, full-width addition is located on the west (rear) elevation. Based on its form and materials, as well as its documentation on the 1960 Sanborn Fire Insurance Company map, it appears that this addition was completed c. 1950. The addition is clad in vinyl and capped by a shed roof. The roof has thin overhanging eaves with thin scrolled eaves brackets. Fenestration consists of three-light vinyl sliding windows and single-leaf paneled metal doors with fanlights. A metal spiral stair provides access to a second-story door opening.

Site Notes:

January 2010: This single-family dwelling is located on the west side of 5th Street, N.E. and is set back from the concrete sidewalk approximately fifteen feet. The north (side) elevation of the dwelling is attached to 710 5th Street, N.E. while the south (side) elevation fronts an asphalt driveway. An alley is located west of the property. The elevated front yard has a brick retaining wall and mature trees and shrubs. A concrete walkway extends from the sidewalk to concrete and brick steps with metal railing to provide access to the main entry. The backyard is enclosed by a wood fence and includes a mature tree. A concrete parking bay partially enclosed by a chain-link fence is located in the western end of the property.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>1 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>2 Flr Windows</b>	<b>Tripartite</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **708\_5th\_Street\_NE\_facade\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **708\_5th\_Street\_NE\_facade\_looking\_W.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **708\_5th\_Street\_NE\_rear\_looking\_SE.JPG**

Date:: Photog:

Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/15/1931	149067	Build	

Permit Notes:

--

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks

Bibliographic Notes:

--

### SIGNIFICANCE DATA

Study Unit

Code	Criteria

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0808**

## BASICS DATA

ID Number: **0809-0808** Year Built: **1896** Data Source: **Permit**

Number Extended Street Quad Type of Address

**710** **5th Street** **NE Current**

Name(s) Type of Name

**Rowhouse, 710 5th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0808** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1896** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1896** **Permit** **3000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Thomas, J.W.**

**Orig Construction** **Owner** **Thomas, J.W.**

Construction Notes:

**One of four rowhouses constructed from the same permit (#1065).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **L-Shaped**

Number Stories: **3 plus basement**

Bays Wide: **2**

Height:

Width: **15**

Depth/Length: **36**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Second Empire

Exterior & Architectural Notes:

January 2010: Constructed in 1896 by J.W. Thomas, this three-story on raised basement, two-bay multi-family dwelling is one of four rowhouses constructed from the same permit (#1065). The dwelling has stylistic influences of the Queen Anne style and Second Empire style. Set on a solid concrete foundation, this brick structure has stretcher-bond brick coursing. The façade (east elevation) has butter-bond brickwork. The dwelling is capped by a mansard roof of hexagonal slate shingles. Two dormers pierce the mansard roof. One of the dormers has a clipped gable roof while the other has a shed roof; both with asphalt shingles. Fenestration of the dormers consists of 1/1, double-hung, vinyl-sash windows. The façade features a molded cornice supported architecturally by corbeled end brackets. A checkerboard brick band extends below the cornice, visually representing a frieze. An interior-side brick chimney is located on the south party wall. The façade features a full-height projecting bay. Fenestration of the projecting bay consists of single and paired 1/1, double-hung, vinyl-sash with rough-cut concrete lug sills. A concrete sill course completes the window openings. The main entry, located in the northern bay of the first story, holds a single-leaf, paneled metal door with lights. The opening features a large, one-light transom with a concrete lug sill and lintel. The northern bay of the second story holds a 1/1, double-hung, vinyl-sash window with a concrete sill and two-course, rowlock brick segmental arch. The secondary opening, located below the main entry, holds a single-leaf, metal door. The west (rear) elevation of the main block holds 1/1, double-hung, vinyl-sash windows set in openings with concrete sills and two-course, rowlock brick segmental arches. The mansard roof features two dormers with 1/1, double-hung, vinyl-sash windows with pedimented openings.

The rear elevation features an original, two-story appendage. This block is narrower than the main block and attached to a similar rear appendage on 712 5th Street, N.E. Constructed of brick with various courses of American bond, this rear block is capped by a shed roof. An exterior-side brick chimney rises from the south (side) elevation. Fenestration consists of 1/1, double-hung, vinyl-sash windows with rowlock brick sills and two-course, rowlock brick segmental arches. A single-leaf, paneled metal door with one-light transom and two-course, rowlock brick segmental arch is located on the west (rear) elevation.

Site Notes:

January 2010: This multi-family dwelling is located on the west side of 5th Street, NE and has a setback from the concrete sidewalk of approximately fifteen feet. The south (side) elevation is attached to 708 5th Street, N.E. and the north (side) elevation to 712 5th Street, N.E. The level front yard is enclosed by a bow and picket fence and includes immature plantings, shrubs, and a brick patio and walkway. Iron stairs with gas pipe railing access the main entry. A secondary entry is located below the main entry and is accessed via concrete steps. The backyard is enclosed by a chain-link fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>Dormer</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>

Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Metal</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Metal/Glas</b>
Notable Interior Plan(s)			Notable Interior Feature(s)	

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 710\_5th\_Street\_NE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 710\_5th\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 710\_5th\_Street\_NE\_rear\_looking\_E.JPG

Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
02/01/1896	1065	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

---

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0807**

## BASICS DATA

ID Number: **0809-0807** Year Built: **1896** Data Source: **Permit**

Number Extended Street Quad Type of Address

**712** **5th Street** **NE Current**

Name(s) Type of Name

**Rowhouse, 712 5th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0807** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1896** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1896** **Permit** **3000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Thomas, J.W.**

**Orig Construction** **Owner** **Thomas, J.W.**

Construction Notes:

**One of four rowhouses constructed from the same permit (#1065).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **3 plus basement**

Bays Wide: **2**

Height:

Width: **15**

Depth/Length: **36**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Second Empire

Exterior & Architectural Notes:

January 2010: Constructed in 1896 by J.W. Thomas, this three-story on raised basement, two-bay, multi-family dwelling is one of four rowhouses constructed from the same permit (#1065). The dwelling has stylistic influences of the Queen Anne style and Second Empire style. Set on a solid concrete foundation, this brick structure has stretcher-bond brick coursing. The façade (east elevation) has butter-bond brickwork. The dwelling is capped by a mansard roof of hexagonal slate shingles. An interior brick chimney rises from the north side of the dwelling. Two dormers pierce the mansard roof. One of the dormers has a clipped gable roof while the other has a shed roof; both with asphalt shingles. Fenestration of the dormers consists of 1/1, double-hung, vinyl-sash windows. The façade features a molded cornice supported architecturally by corbeled end brackets. A checkerboard brick band extends below the cornice, visually representing a frieze. Window openings on the façade hold single or paired 1/1, double-hung, vinyl-sash. The first story window opening features a concrete sill course and a concrete lug lintel. The second story window openings have concrete sills and either a concrete lug lintel or two-course, rowlock brick segmental arch. The main entry, located in the southern bay of the first story, holds a single-leaf, paneled wood door. The opening features a large, one-light transom with a concrete lug sill and lintel. A secondary opening, located below the main entry, holds a single-leaf door. The west (rear) elevation of the main block holds 1/1, double-hung, vinyl-sash windows set in openings with concrete sills and two-course, rowlock brick segmental arches. The mansard roof features two dormers with 1/1, double-hung, vinyl-sash windows with pedimented openings.

The rear elevation features an original, two-story appendage. This block is narrower than the main block and attached to a similar rear appendage on 710 5th Street, N.E. Constructed of brick with various courses of American bond, this rear block is capped by a shed roof. An exterior-side brick chimney rises from the north (side) elevation. Fenestration consists of 1/1, double-hung, vinyl-sash windows with rowlock brick sills and two-course, rowlock brick segmental arches. A single-leaf, paneled wood door with light and a single-light transom is located on the west (rear) elevation. The opening also has a two-course, rowlock brick segmental arch.

Site Notes:

January 2010: This multi-family dwelling is located on the west side of 5th Street, NE and has a setback from the concrete sidewalk of approximately fifteen feet. The south (side) elevation is attached to 710 5th Street, N.E. and the north (side) elevation to 714 5th Street, N.E. The level front yard is enclosed by a milled point fence and includes mature plantings, shrubs, and a concrete patio and walkway. Iron stairs with gas pipe railing access the main entry. A secondary entry is located below the main entry and is accessed via concrete steps. The backyard is enclosed by a chain-link fence with lattice.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Dormer</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>

Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
Notable Interior Plan(s)			Notable Interior Feature(s)	

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 712\_5th\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 712\_5th\_Street\_NE\_facade\_looking\_W.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 712\_5th\_Street\_NE\_rear\_looking\_E.JPG  
Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
02/01/1896	1065	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0809**

## BASICS DATA

ID Number: **0809-0809** Year Built: **1896** Data Source: **Permit**

Number Extended Street Quad Type of Address

**714** **5th Street** **NE Current**

Name(s) Type of Name

**Rowhouse, 714 5th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0809** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1896** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1896** **Permit** **3000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Thomas, J.W.**

**Orig Construction** **Owner** **Thomas, J.W.**

Construction Notes:

**One of four rowhouses constructed from the same permit (#1065).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **3 plus basement**

Bays Wide: **2**

Height:

Width: **15**

Depth/Length: **36**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Second Empire

Exterior & Architectural Notes:

January 2010: Constructed in 1896 by J.W. Thomas, this three-story on raised basement, two-bay, multi-family dwelling is one of four rowhouses constructed from the same permit (#1065). The dwelling has stylistic influences of the Queen Anne style and Second Empire style. Set on a solid concrete foundation, this brick structure has stretcher-bond brick coursing. The façade (east elevation) has butter-bond brickwork. The dwelling is capped by a mansard roof of hexagonal slate shingles. An interior brick chimney rises from the south side of the dwelling. Two dormers pierce the mansard roof. One of the dormers has a clipped gable roof while the other has a shed roof; both with asphalt shingles. Fenestration of the dormers consists of 1/1, double-hung, vinyl-sash windows. The façade features a molded cornice supported architecturally by corbeled end brackets. A checkerboard brick band extends below the cornice, visually representing a frieze. Window openings on the façade hold 1/1, double-hung, metal-sash windows. The first story window opening features a concrete sill course and a concrete lug lintel. The second story window openings have concrete sills and either a concrete lug lintel or two-course, rowlock brick segmental arch. The main entry, located in the northern bay of the first story, holds a single-leaf, paneled wood door. The opening features a large, one-light transom with a concrete lug sill and lintel. A secondary opening, located below the main entry, holds a single-leaf door. The west (rear) elevation of the main block holds 1/1, double-hung, vinyl-sash windows set in openings with concrete sills and two-course, rowlock brick segmental arches. The mansard roof features two dormers with 1/1, double-hung, vinyl-sash windows with pedimented openings.

The rear elevation features an original, two-story appendage. This block is narrower than the main block and attached to a similar rear appendage on 716 5th Street, N.E. Constructed of brick with various courses of American bond, this rear block is capped by a shed roof. An exterior-side brick chimney rises from the south (side) elevation. Fenestration consists of 1/1, double-hung, vinyl-sash windows with rowlock brick sills and two-course, rowlock brick segmental arches. A single-leaf, paneled wood door with light and a single-light transom is located on the west (rear) elevation. Set in a narrow, square-edge wood surround, the door also has a two-course, rowlock brick segmental arch.

Site Notes:

January 2010: This multi-family dwelling is located on the west side of 5th Street, NE and has a setback from the concrete sidewalk of approximately fifteen feet. The south (side) elevation is attached to 712 5th Street, N.E. and the north (side) elevation to 716 5th Street, N.E. The level front yard is enclosed by a chain-link fence and includes a mature shrub. A concrete walkway extends from the sidewalk to an iron stair with gas pipe railing and the main entry. A second door opening is located below grade under the main entry. The rear of the property is enclosed by chain-link and wood fencing. The backyard is level and grassy.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard	Slate		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Dormer	Rectangular	Dbl-Hung	1/1	Vinyl
Facade	Rectangular	Dbl-Hung	1/1	Metal
Door Location	Aperture Shape	Type	Panels	Material

<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**  
**Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 714\_5th\_Street\_NE\_facade\_looking\_NW.JPG**  
Date:: Photog:  
Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 714\_5th\_Street\_NE\_facade\_looking\_SW.JPG**  
Date:: Photog:  
Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 714\_5th\_Street\_NE\_rear\_looking\_E.JPG**  
Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
02/01/1896	1065	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0805**

## BASICS DATA

ID Number: **0809-0805** Year Built: **1896** Data Source: **Permit**

Number Extended Street Quad Type of Address

**716** **5th Street** **NE Current**

Name(s) Type of Name

**Rowhouse, 716 5th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0805** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1896** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1896** **Permit** **3000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Thomas, J.W.**

**Orig Construction** **Owner** **Thomas, J.W.**

Construction Notes:

**One of four rowhouses constructed from the same permit (#1065).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **L-Shaped**

Number Stories: **3 plus basement**

Bays Wide: **2**

Height:

Width: **15**

Depth/Length: **36**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Second Empire

Exterior & Architectural Notes:

January 2010: Constructed in 1896 by J.W. Thomas, this three-story on raised basement, two-bay multi-family dwelling is one of four rowhouses constructed from the same permit (#1065). The dwelling has stylistic influences of the Queen Anne style and Second Empire style. Set on a solid concrete foundation, this brick structure has stretcher-bond brick coursing. The façade (east elevation) has butter-bond brickwork. Soldier-brick sill courses highlight the façade. The dwelling is capped by a mansard roof of hexagonal slate shingles. An interior-side brick chimney rises from the north (side) elevation. Two dormers pierce the mansard roof. One of the dormers has a clipped gable roof while the other has a shed roof. Fenestration of the dormers consists of 1/1, double-hung, vinyl-sash windows. The façade features a molded cornice supported architecturally by corbeled end brackets. A checkerboard brick band extends below the cornice, visually representing a frieze. Window fenestration of the façade consists of 1/1, double-hung, vinyl-sash. The façade features a full-height projecting bay. The bay has paired openings on the first and second stories and two, single openings on the raised basement. The first- and second-story openings of the projecting bay have rowlock brick sills while the basement openings have concrete sills. All of the projecting bay openings have concrete lug sills. The main entry, located in the southern bay of the first story, holds a single-leaf, paneled wood door with light. The opening has a single-light transom and concrete lug sill and lintel. The secondary door opening holds a single-leaf paneled door with lights. The west (rear) elevation of the main block holds 1/1, double-hung, vinyl-sash windows set in openings with concrete sills and two-course, rowlock brick segmental arches. The mansard roof features two dormers with 1/1, double-hung, vinyl-sash windows with pedimented openings.

The rear elevation features an original, two-story appendage. This block is narrower than the main block and attached to a similar rear appendage on 714 5th Street, N.E. Constructed of brick with various courses of American bond, this rear block is capped by a shed roof. An exterior-side brick chimney rises from the north (side) elevation. Fenestration consists of 1/1, double-hung, vinyl-sash windows with rowlock brick sills and two-course, rowlock brick segmental arches. A single-leaf, paneled door with lights is located on the west (rear) elevation. The opening has a large single-light transom and two-course, rowlock brick segmental arch.

Site Notes:

January 2010: This multi-family dwelling is located on the west side of 5th Street, NE and has a setback from the concrete sidewalk of approximately fifteen feet. The south (side) elevation is attached to 710 5th Street, N.E. and the north (side) elevation to 718 5th Street, N.E. The level front yard is enclosed by a bow and picket fence and includes immature plantings, tree, and a flagstone walkway. Iron stairs with gas pipe railing access the main entry. A secondary entry is located below the main entry and is accessed via concrete steps. The backyard is partially enclosed by a wood fence and includes a gravel parking bay.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>

<b>Dormer</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unknown w/Lights</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>
Notable Interior Plan(s)			Notable Interior Feature(s)	

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 716\_5th\_Street\_NE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 716\_5th\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 716\_5th\_Street\_NE\_rear\_looking\_E.JPG

Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
02/01/1896	1065	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code Criteria

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0044**

## BASICS DATA

ID Number: **0809-0044** Year Built: **1889** Data Source: **Permit**

Number Extended Street Quad Type of Address

**718** **5th Street** **NE Current**

Name(s) Type of Name

**Single Dwelling, 718 5th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0044** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1889** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1889** **Permit** **2000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Clark, John T.**

**Orig Construction** **Owner** **Danenhower, Washington**

Construction Notes:

**Constructed with 720 5th Street, N.E. from the same permit (#0911).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **33**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

January 2010: Constructed in 1889 by John T. Clark, this two-story on raised basement, two-bay, single-family dwelling is one of two dwellings constructed from the same permit (#0911). This Queen Anne-style dwelling is set on a solid brick foundation. The brick structure has stretcher-bond coursing. The façade features multiple strings of molded brick and brick sill courses. The dwelling is capped by a shed roof with a molded cornice complimented by strings of decorative brickwork to include dentils, honeycomb, and bead and reel molding. The façade (east elevation) features a full-height projecting bay. Brick molding defines the first story of the projecting bay. Chamfered corners and a corbeled table supporting a second-story opening define the second story. Window openings hold 1/1, double-hung, vinyl-sash windows with concrete sills and soldier-brick segmental arches. The main entry is located in the northern bay of the first story. This opening holds a single-leaf, paneled wood door with a large, single-light transom set in a molded wood surround. The opening is surmounted by a pediment with ornamental plant motif supported architecturally by brick pilasters. The west (rear) elevation of the main block contains 1/1, double-hung, vinyl-sash windows set in arched openings. A two-story rear ell is located on the rear of the dwelling. The rear ell, along with the rear of the main block, has been parged. The ell features a shed roof with an interior-side chimney. Fenestration consists of a single-leaf door and 1/1, double-hung, vinyl-sash windows all set in arched openings.

Site Notes:

January 2010: This single-family dwelling is located on the west side of 5th Street, N.E. and is set back from the sidewalk approximately fifteen feet. The south (side) elevation is attached to 716 5th Street, N.E. while the north (side) elevation is attached to 720 5th Street, N.E. The level front yard is slightly elevated and includes a concrete retaining wall, mature shrubs, and a concrete walkway extending from the sidewalk to the main entry. The backyard is enclosed by a wood fence and includes immature trees.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

--

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 718\_5th\_Street\_NE\_facade\_looking\_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 718\_5th\_Street\_NE\_facade\_looking\_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 708\_5th\_Street\_NE\_rear\_looking\_NE.JPG

Date:: Photog:

Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/22/1889	0911	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0043**

## BASICS DATA

ID Number: **0809-0043** Year Built: **1889** Data Source: **Permit**

Number Extended Street Quad Type of Address

**720** **5th Street** **NE Current**

Name(s) Type of Name

**Single Dwelling, 720 5th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0043** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1889** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1889** **Permit** **2000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Clark, John T.**

**Orig Construction** **Owner** **Danenhower, Washington**

Construction Notes:

**Constructed with 718 5th Street, N.E. from the same permit (#0911).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/Canted Bay**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **33**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

January 2010: Constructed in 1889 by John T. Clark, this two-story on raised basement, two-bay, single-family dwelling is one of two dwellings constructed from the same permit (#0911). This Queen Anne-style dwelling is set on a solid brick foundation. The brick structure has stretcher-bond coursing. The façade features multiple strings of molded brick and brick sill courses. The dwelling is capped by a shed roof with a molded cornice bracketed by corbeled brick pilasters. Complimenting the roofline are strings of decorative brickwork which include dentils, honeycomb, and bead and reel molding. The façade (east elevation) features a full-height projecting canted bay. The bay features projecting round brick corners which extend visually through the cornice terminating at rounded bulbs. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows with brick sills and soldier-brick segmental arches. The main entry, located in the northern bay of the first story, contains a single-leaf wood door with glass. A large single-light transom accompanies the door, which is framed by an ogee-molded cornice supported by corbeled brick pilasters. A projecting brick panel with ogee-molded cornice is located above the door surround. The west (rear) elevation features a two-story ell. The ell has been clad in Hardieplank and is capped by a shed roof with overhanging eave. Fenestration includes paired 1/1, double-hung, vinyl-sash windows set in square surrounds and a single-leaf wood door with light and single-light transom.

Site Notes:

January 2010: This single-family dwelling is located on the west side of 5th Street, N.E. The south (side) elevation is attached to 718 5th Street, N.E. and the north (side) elevation to 722 5th Street, N.E. The dwelling is set back from the sidewalk approximately 15 feet. The elevated front yard is flat and includes mature shrubs and an immature tree. A brick patio and concrete walkway leading to iron steps with gas pipe railing complete the front yard. The rear of the property extends to an alley. The backyard is enclosed by a wood fence and includes mature trees.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Full Glass</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

**Tuesday, June 25, 2013**

**ID\_Number: 0809-0043 Page 2**

Survey(s):

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 720\_5th\_Street\_NE\_facade\_looking\_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 720\_5th\_Street\_NE\_facade\_looking\_W.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 720\_5th\_Street\_NE\_rear\_looking\_SE.JPG

Date:: Photog:

Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

--

**BIBLIOGRAPHIC DATA**

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

--

**SIGNIFICANCE DATA**

---

Study Unit

--

Code	Criteria
------	----------

---

**DATA PROCESSING EVENTS DATA**

---

Date	Individual	Action
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0049**

## BASICS DATA

ID Number: **0809-0049** Year Built: **1890** Data Source: **Permit**

Number Extended Street Quad Type of Address

**722** **5th Street** **NE Current**

Name(s) Type of Name

**Rowhouse, 722 5th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0049** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1890** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1890** **Permit** **2500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Boss, Joseph S.**

**Orig Construction** **Owner** **Boss, Joseph S.**

Construction Notes:

**One of five rowhouses constructed from the same permit (#1950).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 5)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **19**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

### Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1890 by Jos. S. Boss, this two-story on raised basement, two-bay, single-family dwelling is one of five dwellings constructed from the same permit (#1950). This Queen Anne-style dwelling is set on a solid brick foundation. The brick structure has stretcher-bond coursing. The façade (east elevation) has multiple strings of thin molded brick and brick sill courses. A sloped roof caps the dwelling and features a molded cornice supported by a dominating corbeled brick cornice. The façade features a full-height projecting bay capped by a hipped roof of hexagonal asphalt shingles. A metal crown highlights the roof. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows with concrete lug sills. Lintels range from rough concrete lug, rough concrete, and soldier-brick segmental arches. The primary entry is located in a recessed opening in the north bay. This inset opening holds a double-leaf, paneled wood door. The outer opening features a stained glass transom with rough concrete lug sill. The west (rear) elevation of the main block has 1/1, double-hung, vinyl-sash windows set in segmental arches. A two-story rear ell is located on the rear elevation. This brick structure is capped by a shed roof and fenestrated with 1/1, double-hung, vinyl-sash windows with segmental brick arches. The window openings are located on the south (side) elevation.

On the west (rear) elevation of the ell is a two-story, full-width addition. Based on its form and materials, it appears that this addition was constructed c. 1990. Clad in aluminum siding, the addition is capped by a shed roof. Fenestration consists of 1/1, and tripled sliding vinyl-sash windows and a single-leaf French door. A wood porch shelters the first story. The porch has a hipped roof of cedar shingles and is supported by wood posts.

Site Notes:

January 2010: This single-family dwelling is located on the west side of 5th Street, N.E. and is set back from the concrete sidewalk approximately fifteen feet. The elevated front yard has a brick retaining wall and mature shrubs. Ivy covers the yard. A brick walkway and steps provide access to the iron stair with gas pipe railing to the main entry. The rear of the property extends to an alley. The backyard is enclosed by a wood fence and includes mature trees.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Bay Roof</b>	<b>Asphalt</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

---

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

---

Designation Event(s)

---

Survey(s)

---

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

---

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

---

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **722\_5th\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **722\_5th\_Street\_NE\_facade\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **722\_5th\_Street\_NE\_rear\_looking\_E.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 722\_5th\_Street\_NE\_rear\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/21/1890	1950	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

---

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0048**

## BASICS DATA

ID Number: **0809-0048** Year Built: **1890** Data Source: **Permit**

Number Extended Street Quad Type of Address

**724** **5th Street** **NE Current**

Name(s) Type of Name

**Rowhouse, 724 5th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0048** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1890** **Permit** **Original**

**Residential (Multi-Family)** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1890** **Permit** **2500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Boss, Joseph S.**

**Orig Construction** **Owner** **Boss, Joseph S.**

Construction Notes:

**One of five rowhouses constructed from the same permit (#1950).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 5)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **19**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

January 2010: Constructed in 1890 by Jos. S. Boss, this two-story on raised basement, two-bay, single-family dwelling is one of five dwellings constructed from the same permit (#1950). This Queen Anne-style dwelling is set on a solid brick foundation. The brick structure has stretcher-bond coursing highlighted with multiple strings of thin molded brick and brick sill courses. A sloped roof caps the dwelling and features a molded cornice supported by a dominating corbeled brick cornice. The façade (east elevation) features a full-height projecting bay with a pediment. The pediment includes a molded, raked cornice and scrollwork in the tympanum. Window openings on the façade hold paired, single-light casement, paired single-light awning, and 1/1, double-hung sash. All of the sash is vinyl and is set in openings with pedimented molded-brick lintels. The primary entry is located in a recessed opening in the north bay. This inset opening holds a double-leaf, paneled wood door. The secondary opening is located below the main opening and holds a single-leaf, paneled wood door with six-lights. The west (rear) elevation of the main block has two window openings with segmental arches. These openings have been enclosed with brick. A two-story rear ell is located on the rear elevation. This brick structure is capped by a shed roof and fenestrated with 1/1, double-hung, vinyl-sash windows with two-course, rowlock brick segmental arches.

Site Notes:

January 2010: This dwelling is located west of 5th Street, N.E. and is set back from the sidewalk approximately fifteen feet. The south (side) elevation is attached to 722 5th Street, N.E. and the north (side) elevation to 726 5th Street, N.E. The elevated front yard is covered with brick and includes a small ornamental tree. A concrete walkway extends from the sidewalk to a iron stair with gas pipe railing. The rear of the property extends to meet an alley. The backyard is enclosed by a wood fence and includes mature trees.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Bay Roof</b>	<b>Not Visible</b>		<b>Not Visible</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Awning</b>	<b>1-light</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>DoubleCase</b>	<b>1-light</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\F&G Street - 2 to 11th**  
**St\Database\Pictures\Square 0809\**

File: **724\_5th\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\F&G Street - 2 to 11th**  
**St\Database\Pictures\Square 0809\**

File: **724\_5th\_Street\_NE\_facade\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\F&G Street - 2 to 11th**  
**St\Database\Pictures\Square 0809\**

File: **724\_5th\_Street\_NE\_rear\_looking\_E.JPG**

Date:: Photog:

Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Tuesday, June 25, 2013

ID\_Number: 0809-0048 Page 3

Notes:

--

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/21/1890	1950	Build	

Permit Notes:

--

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks

Bibliographic Notes:

--

### SIGNIFICANCE DATA

Study Unit

Code	Criteria

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0047**

## BASICS DATA

ID Number: **0809-0047** Year Built: **1890** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>726</b>		<b>5th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 726 5th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0809/0047</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1890</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Rear Addition</b>	<b>c. 1900</b>	<b>Site Visit/Map</b>			
----------------------	----------------	-----------------------	--	--	--

<b>Orig Construction</b>	<b>1890</b>	<b>Permit</b>			<b>2500 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Boss, Joseph S.</b>
--------------------------	----------------	------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Boss, Joseph S.</b>
--------------------------	--------------	------------------------

Construction Notes:

**One of five rowhouses constructed from the same permit (#1950).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 5)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Rectangular Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **19**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

January 2010: Constructed in 1890 by Jos. S. Boss, this two-story on raised basement, two-bay, single-family dwelling is one of five dwellings constructed from the same permit (#1950). This Queen Anne-style dwelling is set on a solid brick foundation. The brick structure has stretcher-bond coursing and has brick sill courses. A sloped roof caps the dwelling and features a molded cornice supported by a dominating corbeled brick cornice. The façade (east elevation) has a full-height projecting bay with chamfered edges. The basement of the bay is pierced by a single-light and a two-light awning window. First-and second-story window openings on the façade hold 2/2, double-hung, vinyl-sash windows with concrete sills. The first- and second-story openings feature corbeled brick hoods with dentil ornamentation. The primary entry is located in a recessed opening in the north bay. This inset opening holds a double-leaf, paneled wood door with the same corbeled brick hood featured on the window openings. The below-grade door opening holds a single-leaf wood door. The west (rear) elevation features a two-story, two-bay ell. This brick structure is capped by a shed roof and fenestrated with 1/1, double-hung, vinyl-sash windows. The window openings have rowlock brick sills. Some of the openings have two-course, rowlock brick segmental arches. A single-leaf door with large, single-light transom is located in the southern bay of the west (rear) elevation.

Occupying the northern bay of the west (rear) elevation of the ell is a one-story addition. Based on its form and materials, as well as its documentation on the 1928 Sanborn Fire Insurance Company map, it appears that this addition was constructed c. 1900. The one-story, one-bay brick structure is capped by a shed roof. Fenestration consists of a 1/1, double-hung, vinyl-sash window with rowlock brick sills and two-course, rowlock brick segmental arch located on the west (rear) elevation.

Site Notes:

January 2010: This dwelling is located west of 5th Street, N.E. and is set back from the sidewalk approximately fifteen feet. The south (side) elevation is attached to 724 5th Street, N.E. and the north (side) elevation to 728 5th Street, N.E. The elevated front yard has a mature tree and immature ground cover. A brick walkway extends from the sidewalk to an iron stair. The stair has gas pipe railing and provides access to the main entry. A lower-level opening beneath the main entry is accessed via brick steps. The rear of the property extends to meet an alley. The backyard has a brick patio and is enclosed by a wood fence and includes mature trees.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	

Structure Component	Material	Feature	Source
<b>Foundation</b>	<b>Brick</b>		
<b>Walls</b>	<b>Brick</b>		
Materials Notes:			

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>2/2</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Awning</b>	<b>1-light</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Awning</b>	<b>2 Lite</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>2/2 Double</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>2/2 Double</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood</b>
<b>Main Door</b>				

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **726\_5th\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 726\_5th\_Street\_NE\_facade\_looking\_SW.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 726\_5th\_Street\_NE\_rear\_looking\_E.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/21/1890	1950	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0046**

## BASICS DATA

ID Number: **0809-0046** Year Built: **1890** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>728</b>		<b>5th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 728 5th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0809/0046</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1890</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Rear Addition</b>	<b>c. 1975</b>	<b>Site Visit/Map</b>			
----------------------	----------------	-----------------------	--	--	--

<b>Orig Construction</b>	<b>1890</b>	<b>Permit</b>			<b>2500 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Boss, Joseph S.</b>
--------------------------	----------------	------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Boss, Joseph S.</b>
--------------------------	--------------	------------------------

Construction Notes:

**One of five rowhouses constructed from the same permit (#1950).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 5)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Rectangular Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **19**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

January 2010: Constructed in 1890 by Jos. S. Boss, this two-story on raised basement, two-bay, single-family dwelling is one of five dwellings constructed from the same permit (#1950). This Queen Anne-style dwelling is set on a solid brick foundation. The brick structure has stretcher-bond coursing highlighted with multiple strings of thin molded brick and brick sill courses. A sloped roof caps the dwelling and features a molded cornice supported by a dominating corbeled brick cornice. The façade (east elevation) features a full-height projecting bay with pediment. The pediment includes a molded, raked cornice and scrollwork in the tympanum. A metal finial extends from the pediment. Window openings on the façade hold single and paired 1/1, double-hung, vinyl-sash with wood sills and paired 1/1, double-hung, wood-sash windows. All of the openings have pedimented molded-brick lintels. The foundation is pierced by a single-leaf metal door. The primary entry is located in a recessed opening in the north bay. This inset opening holds a double-leaf, paneled wood door with single-light transom. The west (rear) elevation features a two-story, two-bay ell. This brick structure is capped by a shed roof and fenestrated with 1/1, double-hung, vinyl-sash windows. The window openings have rowlock brick sills and two-course, rowlock brick segmental arches.

Occupying the northern bay of the west (rear) elevation of the ell is a one-story addition. This addition is not documented on the 1960 Sanborn Fire Insurance Company map, and as such, based on its form and materials appears to have been constructed c. 1975. The one-story, one-bay brick structure is capped by a shed roof. Fenestration consists of a 1/1, double-hung, vinyl-sash window.

Site Notes:

January 2010: This dwelling is located west of 5th Street, N.E. and is set back from the sidewalk approximately fifteen feet. The south (side) elevation is attached to 726 5th Street, N.E. and the north (side) elevation to 730 5th Street, N.E. The elevated front yard has a brick retaining wall and has been landscaped with ornamental plantings and trees. A brick-lined concrete walkway extends from the sidewalk. The main entry is accessed via a metal stair with small landing. A below-grade door opening is accessed via concrete steps beneath the metal stair. The rear of the property extends to meet an alley. The backyard is enclosed by a wood fence and includes mature trees. A roll-up metal garage door permits access to the backyard from the alley.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Not Visible		Not Visible	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	

Structure Component	Material	Feature	Source
<b>Foundation</b>	<b>Brick</b>		
<b>Walls</b>	<b>Brick</b>		
Materials Notes:			

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Metal</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Paneled</b>	<b>Wood</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 728\_5th\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 728\_5th\_Street\_NE\_facade\_looking\_W.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 728\_5th\_Street\_NE\_rear\_looking\_NE.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/21/1890	1950	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0817**

## BASICS DATA

ID Number: **0809-0817** Year Built: **1890** Data Source: **Permit**

Number Extended Street Quad Type of Address

**730** **5th Street** **NE Current**

Name(s) Type of Name

**Rowhouse, 730 5th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0817** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1890** **Permit** **Original**

**Residential (Multi-Family)** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1890** **Permit** **2500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Boss, Joseph S.**

**Orig Construction** **Owner** **Boss, Joseph S.**

Construction Notes:

**One of five rowhouses constructed from the same permit (#1950).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 5)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **19**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

January 2010: Constructed in 1890 by Jos. S. Boss, this two-story on raised basement, two-bay, single-family dwelling is one of five dwellings constructed from the same permit (#1950). This Queen Anne-style dwelling is set on a solid brick foundation. The brick structure has stretcher-bond coursing highlighted with multiple strings of thin molded brick and brick sill courses. A sloped roof caps the dwelling and features a molded cornice supported by a dominating corbeled brick cornice. The façade (east elevation) features a full-height projecting bay capped by a hipped roof of hexagonal shingles. The hipped roof is surmounted by a prominent molded crown. Window openings on the façade hold single and paired 1/1, double-hung, vinyl-sash with single-lights above. Additional window fenestration consists of a single-light casement window is located in the northern bay of the second story and paired, 1/1, double-hung, vinyl-sash basement windows. All of the openings have rock-faced concrete sills. The first-story openings feature rock-faced concrete lug lintels. Second-story openings have soldier-brick segmental arches. The primary entry is located in a recessed opening in the north bay. This inset opening holds a double-leaf, paneled wood door with single-light transom. The below-grade door opening holds a single-leaf wood door with light. The west (rear) elevation features a two-story, two-bay ell. This brick structure is capped by a shed roof and fenestrated with 1/1, double-hung, vinyl-sash windows. The window openings have rowlock brick sills and two-course, rowlock brick segmental arches.

Site Notes:

January 2010: This dwelling is located west of 5th Street, N.E. and is set back from the sidewalk approximately fifteen feet. The south (side) elevation is attached to 728 5th Street, N.E. and the north (side) elevation to 732 5th Street, N.E. The elevated front yard slopes to the east and has been landscaped with immature trees and shrubs. A milled point fence encloses the front yard. A concrete walkway and steps extends from the sidewalk. The main entry is accessed via a metal stair with gas pipe railing. A below-grade door opening is accessed via concrete steps beneath the metal stair. The rear of the property extends to an alley. The backyard is enclosed by a wood fence which includes a roll-up metal garage door fronting the alley.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Bay Roof</b>	<b>Not Visible</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Casement</b>	<b>1-light</b>	<b>Unknown</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood/Glass</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\F&G Street - 2 to 11th**  
**St\Database\Pictures\Square 0809\**

File: **730\_5th\_Street\_NE\_rear\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\F&G Street - 2 to 11th**  
**St\Database\Pictures\Square 0809\**

File: **730\_5th\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\F&G Street - 2 to 11th**  
**St\Database\Pictures\Square 0809\**

File: **730\_5th\_Street\_NE\_facade\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Tuesday, June 25, 2013

ID\_Number: 0809-0817 Page 3

Notes:

--

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/21/1890	1950	Build	

Permit Notes:

--

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks

Bibliographic Notes:

--

### SIGNIFICANCE DATA

Study Unit

Code	Criteria

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0036**

## BASICS DATA

ID Number: **0809-0036** Year Built: **1889** Data Source: **Permit**

Number Extended Street Quad Type of Address

**732** **5th Street** **NE Current**

Name(s) Type of Name

**Single Dwelling, 732 5th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0036** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1889** **Permit** **Original**

**Residential (Multi-Family)** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1889** **Permit** **1300 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Phillips, John W.**

**Orig Construction** **Owner** **Danenhower, Washington**

Construction Notes:

**One of four dwellings constructed from the same permit (#0952).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **35**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Italianate

Exterior & Architectural Notes:

January 2010: Constructed in 1889 by John W. Phillips, this two-story on raised basement, two-bay dwelling is one of four dwellings constructed from the same permit (#0952). With influences of the Queen Anne style and Italianate style, this dwelling is set on a solid concrete foundation. The masonry structure has stretcher-bond brick coursing. A sloped roof with molded and corbeled cornice caps the dwelling. Multiple two-course brick strings highlight the façade (east elevation). The façade features a full-height projecting bay. The bay features a lower-story, corbeled northeast corner. The edges of the first and second stories are chamfered. Window openings on the façade include single and paired 1/1, double-hung, vinyl-sash. The first-story window openings have soldier-brick flat arches while the second-story window openings have segmental brick arches. A porthole window is located in the northern bay of the second story. The main entry is located in the northern bay of the first story. This opening holds a single-leaf, paneled metal door with single-light transom and molded brick hood composed of a pediment supported by corbeled pilasters. The below-grade door opening holds a single-leaf, paneled metal door with single-light transom. The west (rear) elevation is fenestrated by two second-story window openings with 1/1, double-hung, vinyl-sash, brick sills, and two-course brick segmental arches. Additional details were not visible from the public right-of-way.

Site Notes:

January 2010: This dwelling is located west of 5th Street, N.E. and is set back from the sidewalk approximately fifteen feet. The south (side) elevation is attached to 730 5th Street, N.E. and the north (side) elevation to 734 5th Street, N.E. The elevated front yard is lined by a hairpin fence and includes immature trees. A concrete walkway extends from the sidewalk to a metal stair to the main entry. Concrete steps lead under the metal stair to a below-grade opening. The rear of the property is enclosed by a wooden privacy fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Circular</b>	<b>Fixed</b>	<b>1-light</b>	<b>Unknown</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Metal</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Metal</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

### Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **732\_5th\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

### Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **732\_5th\_Street\_NE\_facade\_looking\_W.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

### Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**

File: **732\_5th\_Street\_NE\_rear\_looking\_E.JPG**

Date:: Photog:

Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--



## PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
10/30/1889	0952	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

## SIGNIFICANCE DATA

---

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0035**

## BASICS DATA

ID Number: **0809-0035** Year Built: **1891** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>734</b>	<b>-734B</b>	<b>5th Street</b>	<b>NE</b>	<b>Current</b>
<b>734</b>		<b>5th Street</b>	<b>NE</b>	<b>Original</b>

Name(s)	Type of Name
<b>Single Dwelling, 734 5th Street, N.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>0809/0035</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1891</b>	<b>Permit</b>			<b>Original</b>
<b>Residential (Multi-Family)</b>					<b>Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1891</b>	<b>Permit</b>			<b>2750 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Builder</b>	<b>Boss, Joseph S.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Boss, Joseph S.</b>

Construction Notes:

**Constructed with 423 H Street, N.E. from the same permit (#1374), though it is no longer extant.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached**  
Relate to Street: **Face on Setback Line**  
Massing: **Vertical Box/rectang bay**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **36**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

**Italianate**

Exterior & Architectural Notes:

January 2010: Constructed in 1891 by J. S. Boss, this two-story on raised basement, two-bay dwelling is one of two dwellings constructed from the same permit (#01374). With influences of the Queen Anne style and Italianate style, this dwelling is set on a solid brick foundation. The masonry structure has stretcher-bond brick coursing. A sloped roof with molded and corbeled cornice caps the dwelling. Multiple two-course brick strings highlight the façade (east elevation). The façade features a full-height projecting bay. The bay features a lower-story, corbeled northeast corner. The edges of the first and second stories are chamfered. A hipped roof of hexagonal shingles caps the projecting bay. Window openings on the façade of the dwelling hold 1/1, double-hung, vinyl-sash windows with concrete sills and soldier-brick segmental arches. The first story of the projecting bay features a round arched window. The main entry, located in the northern bay of the first story, holds a single-leaf, paneled metal door with single-light transom. A brick hood composed of a molded cornice and corbeled pilasters completes the opening. The below-grade opening holds a single-leaf, paneled wood door with lights. The west (rear) elevation has been parged. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows with segmental arches. Additional details were not visible from the public right-of-way.

It appears that a one-story addition is located on the rear elevation. All that was visible from the public right-of-way was a metal sloping roof.

Site Notes:

January 2010: This dwelling is located west of 5th Street, N.E. and is set back from the sidewalk approximately fifteen feet. The south (side) elevation is attached to 732 5th Street, N.E. and the north (side) elevation to 736 5th Street, N.E. The elevated front yard is lined by a metal fence and includes immature trees. A brick-lined concrete walkway extends from the sidewalk to a metal stair to the main entry. Concrete steps lead under the metal stair to a below-grade opening. The rear of the property is enclosed by a wooden privacy fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			

**Walls**                      **Brick**

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>DbI-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>DbI-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood/Glass</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Metal</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path:    **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**  
File:    **734\_5th\_Street\_NE\_facade\_looking\_NW.JPG**  
Date::                      Photog:  
Code::                                      R:                      Fr:

Caption:

Undisplayable Image Format

Path:    **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\**  
File:    **734\_5th\_Street\_NE\_facade\_looking\_SW.JPG**  
Date::                      Photog:  
Code::                                      R:                      Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\  
File: 734\_5th\_Street\_NE\_rear\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
01/02/1891	1374	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

---

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0034**

## BASICS DATA

ID Number: **0809-0034** Year Built: **1889** Data Source: **Permit**

Number Extended Street Quad Type of Address

**736** **5th Street** **NE Current**

Name(s) Type of Name

**Rowhouse, 736 5th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0034** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1889** **Permit** **Original**

**Residential (Multi-Family)** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1889** **Permit** **1300 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Phillips, John W.**

**Orig Construction** **Owner** **Danenhower, Washington**

Construction Notes:

**One of four rowhouses constructed from the same permit (#0952).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 3)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **Rectangle Ad**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **35**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne  
Italianate

Exterior & Architectural Notes:

January 2010: Constructed in 1889 by John W. Phillips, this two-story on raised basement, two-bay dwelling is one of four dwellings constructed from the same permit (#0952). With influences of the Queen Anne style and Italianate style, this dwelling is set on a solid concrete foundation. The masonry structure has stretcher-bond brick coursing. A sloped roof with molded and corbeled cornice caps the dwelling. Multiple two-course brick strings highlight the façade (east elevation). The façade features a full-height projecting bay. The bay features a lower-story, corbeled northeast corner. The edges of the first and second stories are chamfered. A hipped roof of asphalt shingles caps the projecting bay. The hipped roof has metal coping and small finials at its base. Window openings on the façade include single and paired 6/6 and 8/8, double-hung, wood-sash. The window openings have rock-faced concrete sills and soldier-brick segmental arches. The main entry is located in the northern bay of the first story. This opening holds a single-leaf, paneled wood door with six-lights and a single-light transom. A molded brick hood composed of a pediment supported by corbeled pilasters completes the opening. The below-grade door opening holds a single-leaf, paneled wood door with lights. The west (rear) elevation has been parged. Fenestration consists of a 1/1, double-hung, vinyl-sash window. Additional details were not visible from the public right-of-way.

Site Notes:

January 2010: This dwelling is located west of 5th Street, N.E. and is set back from the sidewalk approximately fifteen feet. The south (side) elevation is attached to 734 5th Street, N.E. and the north (side) elevation to 738 5th Street, N.E. The elevated front yard has been covered with brick and lined by a milled point fence. A brick walkway extends from the sidewalk to an iron stair with gas pipe railing to the main entry. Concrete steps lead under the metal stair to a below-grade opening. The rear of the property is enclosed by a wooden privacy fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Asphalt		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	6/6	Wood
Bay Windows	Rectangular	Dbl-Hung	6/9 Double	Wood
Bay Windows	Rectangular	Dbl-Hung	8/8	Wood
Bay Windows	Rectangular	Dbl-Hung	6/6	Wood
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single	Paneled	Wood/Glass
Main Door	Rectangular	Single	Paneled	Wood/Glass

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\F&G Street - 2 to 11th**  
**St\Database\Pictures\Square 0809\**

File: **736\_5th\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\F&G Street - 2 to 11th**  
**St\Database\Pictures\Square 0809\**

File: **736\_5th\_Street\_NE\_facade\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

<b>10/30/1889</b>	<b>0952</b>	<b>Build</b>	
-------------------	-------------	--------------	--

Permit Notes:



## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

## SIGNIFICANCE DATA

Study Unit
------------

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0033**

## BASICS DATA

ID Number: **0809-0033** Year Built: **1889** Data Source: **Permit**

Number Extended Street Quad Type of Address

**738** **5th Street** **NE Current**

Name(s) Type of Name

**Rowhouse, 738 5th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0033** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1889** **Permit** **Original**

**Residential (Multi-Family)** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1889** **Permit** **1300 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Phillips, John W.**

**Orig Construction** **Owner** **Danenhower, Washington**

Construction Notes:

**One of four rowhouses constructed from the same permit (#0952).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **35**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Italianate

Exterior & Architectural Notes:

January 2010: Constructed in 1889 by John W. Phillips, this two-story on raised basement, two-bay dwelling is one of four dwellings constructed from the same permit (#0952). With influences of the Queen Anne style and Italianate style, this dwelling is set on a solid concrete foundation. The masonry structure has stretcher-bond brick coursing. A sloped roof with molded and corbeled cornice caps the dwelling. Multiple two-course brick strings highlight the façade (east elevation). The façade features a full-height projecting bay. The bay features a lower-story, corbeled northeast corner. The edges of the first and second stories are chamfered. Window openings on the façade hold 1/1, double-hung, vinyl-sash with concrete sills and soldier-brick segmental arches. The western bay on the first story features a round headed window with soldier-brick arch and keystone. The main entry is located in the northern bay of the first story. This opening holds a single-leaf, paneled metal door and single-light transom. A molded brick hood composed of a pediment supported by corbeled pilasters completes the opening. The below-grade door opening holds a single-leaf, paneled metal door with lights. The west (rear) elevation has been parged. Fenestration consists of a paired 1/1, double-hung, vinyl-sash window. Additional details were not visible from the public right-of-way.

Site Notes:

January 2010: This dwelling is located west of 5th Street, N.E. and is set back from the sidewalk approximately fifteen feet. The south (side) elevation is attached to 736 5th Street, N.E. and the north (side) elevation to 740 5th Street, N.E. The elevated front yard has been covered with brick and lined by a milled point fence. An iron stair with gas pipe railing provides access to the main entry. Steps lead under the iron stair to a below-grade opening. The rear of the property was not visible from the public right-of-way.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Metal/Glas</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Metal</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Tuesday, June 25, 2013

ID\_Number: 0809-0033 Page 2

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 738\_5th\_Street\_NE\_facade\_looking\_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

**Undisplayable Image Format**

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 738\_5th\_Street\_NE\_facade\_looking\_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0809\

File: 738\_5th\_Street\_NE\_rear\_looking\_NE.JPG

Date:: Photog:

Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
10/30/1889	0952	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

## SIGNIFICANCE DATA

---

Study Unit

Code Criteria

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0032**

## BASICS DATA

ID Number: **0809-0032** Year Built: **1889** Data Source: **Permit**

Number Extended Street Quad Type of Address

**740** **5th Street** **NE Current**

Name(s) Type of Name

**Rowhouse, 740 5th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0032** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1889** **Permit** **Original**

**Residential (Multi-Family)** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1889** **Permit** **1300 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Phillips, John W.**

**Orig Construction** **Owner** **Danenhower, Washington**

Construction Notes:

**One of four rowhouses constructed from the same permit (#0952).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 3)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **35**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

**Italianate**

Exterior & Architectural Notes:

January 2010: Constructed in 1889 by John W. Phillips, this two-story on raised basement, two-bay dwelling is one of four dwellings constructed from the same permit (#0952). With influences of the Queen Anne style and Italianate style, this dwelling is set on a solid concrete foundation. The masonry structure has stretcher-bond brick coursing. A sloped roof with molded and corbeled cornice caps the dwelling. Two-course brick sill strings highlight the façade (east elevation). The façade features a full-height projecting bay. The bay features a lower-story, corbeled northeast corner and chamfered first- and second-story edges. Window openings on the façade hold 1/1 and 6/6 double-hung wood-sash windows. The lower story and first story of the projecting bay feature large, single-light fixed picture windows. The lower-level opening has a soldier-brick segmental arch. The first- and second-story openings have soldier-brick segmental arches with drip molding. The main entry is located in the northern bay of the first story. This opening holds a single-leaf, wood-frame glass door and single-light transom. The below-grade door opening holds a single-leaf, paneled wood door with lights and single-light transom. The west (rear) elevation was not visible from the public right-of-way.

Site Notes:

January 2010: This dwelling is located west of 5th Street, N.E. and is set back from the sidewalk approximately fifteen feet. The south (side) elevation is attached to 738 5th Street, N.E. and the north (side) elevation to 421 H Street, N.E. The elevated front yard has been covered with brick and lined by a milled point fence. An metal stair provides access to the main entry. Steps lead under the metal stair to a below-grade opening. The rear of the property was not visible from the public right-of-way.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>6/6</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>6/6</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1-light</b>	<b>Unknown</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Full Glass</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\F&G Street - 2 to 11th**

**St\Database\Pictures\Square 0809\**

File: **740\_5th\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\F&G Street - 2 to 11th**

**St\Database\Pictures\Square 0809\**

File: **740\_5th\_Street\_NE\_facade\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

<b>10/30/1889</b>	<b>0952</b>	<b>Build</b>	
-------------------	-------------	--------------	--

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------



Bibliographic Notes:

--

## **SIGNIFICANCE DATA**

---

Study Unit

---

Code

Criteria

---

## **DATA PROCESSING EVENTS DATA**

---

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Updated
3/3/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0809-0029**

## BASICS DATA

ID Number: **0809-0029** Year Built: **1876** Data Source: **Permit**

Number Extended Street Quad Type of Address

**409** **H Street** **NE** **Current**

Name(s) Type of Name

**Dwelling/Store, 409 H Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0029** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Store & Dwelling** Condition: **Poor**

Function/Use Start Source Stop Source Explain

**Restaurant/Dwelling** **ca. 1960** **Map** **Historic/Current**

**Store/Dwelling** **1876** **Permit** **ca. 1960** **Map** **Original**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1876** **Permit** **9000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Owner** **Thompson, A.**

Construction Notes:

**407-411 H Street N.E. (lots 28-30) were constructed together in 1876. 409 and 411 H Street N.E. are extant.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Line**

Massing: **Vertical Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

**Italianate**

## Exterior &amp; Architectural Notes:

**May 2009:** Constructed in 1876, this two-story, three-bay Italianate dwelling and store was originally one of three similar buildings. The building is constructed of brick and is set on a solid brick foundation; the façade has been faced with stretcher-bond brick. A sloping roof caps the dwelling, though the roofing material was not visible from the public right-of-way. A cornice, featuring large wood brackets and modillions, finishes the roof. An interior brick chimney rises from the rear (south) elevation of the building and has a corbeled cap. The first story of the building has been substantially altered since its construction, though the end bays remain door entries. The easternmost bay contains a single-leaf paneled wood door with a one-light wood transom. The westernmost bay contains a single-leaf paneled wood door with lights and a one-light wood transom. A rectangular one-story, one-bay projection extends from the center of the first story of the façade. The wood-frame projection is set on a solid foundation that is faced with stretcher-bond brick and is capped by a flat roof with overhanging eaves. Fenestration consists of one-light fixed wood windows. A two-light wood transom pierces the main block and is sited above the projection. A molded wood architrave spans the façade and is located above the first story. The second story window openings contain 1/1, double-hung, wood-sash windows with rowlock brick sills. One-light wood transom windows are sited above each window and are set within segmental openings. A rowlock brick segmental window hood complements each opening.

A two-story ell is located on the southeast corner of the rear (south) elevation of the main block. The ell is constructed of seven-course, American-bond brick and is set on a solid foundation; also constructed of seven-course, American-bond brick. A sloping roof caps the ell, though the roofing material was not visible from the public right-of-way. The west elevation of the ell is pierced by 1/1, double-hung, vinyl-sash windows with soldier brick segmental arches.

A two-story, full-width enclosed porch is located on the rear elevation of the ell and is noted on the 1928 Sanborn map as a porch. The first story of the porch has been enclosed with concrete blocks, while the wood-frame second story is clad with asphalt siding. A shed roof caps the enclosed porch. The roofing material was not visible from the public right-of-way. Fenestration consists of a one-light wood fixed window with a square-edged wood surround.

## Site Notes:

**May 2009:** This building is sited on the south side of H Street, NE and directly fronts the concrete sidewalk. The building is adjacent to 407 and 411 H Street, NE. The rear yard is enclosed with a tall wood fence. A public alley, which runs east to west, is paved with concrete and provides access to the rear of the property.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>			
Wall Component	Material	Color	Treatment	Source
<b>Facade (Upper)</b>	<b>Brick</b>	<b>Blue</b>	<b>Painted</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

## Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
<b>Windows (All)</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>First Floor</b>	<b>Rectangular</b>	<b>Panel</b>	<b>6-Panel</b>	<b>Wood</b>
<b>First Floor</b>	<b>Rectangular</b>	<b>Pnl/Glazed</b>	<b>4-Panel</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill H Street (2009)**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\H Street - 2 to 15th**

**St\Database\Pictures\0809\**

File: **H Street\_409\_facade\_looking\_SE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\H Street - 2 to 15th**

**St\Database\Pictures\0809\**

File: **H Street\_409\_facade\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\H Street - 2 to 15th**

**St\Database\Pictures\0809\**

File: **H Street\_409\_rear\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

#### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
08/31/1876	7	Build	

Permit Notes:

--

#### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

#### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

#### DATA PROCESSING EVENTS DATA

Date	Individual	Action
7/28/2009	Dayton (MSD), Maria	Record Updated
7/27/2009	Dayton (MSD), Maria	Record Updated
7/27/2009	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0030**

## BASICS DATA

ID Number: **0809-0030** Year Built: **1876** Data Source: **Permit**

Number Extended Street Quad Type of Address

**411** **H Street** **NE Current**

Name(s) Type of Name

**Dwelling/Store, 411 H Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0030** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Store & Dwelling** Condition: **Fair**

Function/Use Start Source Stop Source Explain

**Residential** **ca. 2000** **Site Visit** **Current**

**Dwelling & Store** **1876** **Permit** **ca. 2000** **Site Visit** **Original**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Rear Addition** **ca. 1990** **Observation**

**Orig Construction** **1876** **Permit** **9000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Owner** **Thompson, A.**

Construction Notes:

**407-411 H Street N.E. (lots 28-30) were constructed together in 1876. 409 and 411 H Street N.E. are extant.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Line**

Massing: **Vertical Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

Exterior & Architectural Notes:

**May 2009:** Constructed in 1876, this two-story, three-bay Italianate dwelling and store was originally one of three similar buildings. The building is constructed of brick and is set on a solid brick foundation; the façade has been faced with stretcher-bond brick. A sloping roof caps the dwelling, though the roofing material was not visible from the public right-of-way. A cornice, featuring large wood brackets and modillions, finishes the roof. The first story of the building has been substantially altered since its construction. The central bay of the façade (north elevation) contains double-leaf doors with a one-light wood transom. The eastern bay of the façade has been covered over. The projecting western bay has also been covered with plywood, though paired one-light wood fixed windows are still slightly visible. A molded wood architrave with dentil molding spans the façade of the building and is sited above the first story. The second story segmental window openings contain 1/1, double-hung, vinyl-sash windows with concrete sills. A rowlock brick segmental window hood complements each opening. The fenestration of the rear (south) elevation was not visible.

A two-story ell is located on the southeast corner of the rear elevation and is original to the main block. The ell is constructed of brick and is set on a solid brick foundation. A sloping roof caps the ell.

A two-story, two-bay addition is located on the rear elevation of the ell and was constructed ca. 1990. The masonry addition is parged and is set on a solid foundation; that is also parged. A sloping roof caps the addition. The westernmost bay of the rear elevation contains a single-leaf metal door. Additional fenestration consists of 1/1, double-hung, vinyl-sash windows with header brick sills.

Site Notes:

**May 2009:** This building is located on the south side of H Street, NE and directly fronts the concrete sidewalk. The building is adjacent to 409 and 413 H Street, NE. The small, grassy rear yard is enclosed with metal chain-link fencing. A public alley, which runs east to west, is paved with concrete and provides access to the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>			
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>	<b>Red</b>	<b>Veneer</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Windows (All)</b>	<b>Segmental-Arched</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>		

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Tuesday, June 25, 2013

ID\_Number: 0809-0030 Page 2



Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill H Street (2009)**

Level(s) of Investigation

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\H Street - 2 to 15th**

**St\Database\Pictures\0809\**

File: **H Street\_411\_facade\_looking\_S.JPG**

Date::

Photog:

Code::

R:

Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\H Street - 2 to 15th**

**St\Database\Pictures\0809\**

File: **H Street\_411\_facade\_looking\_SW.JPG**

Date::

Photog:

Code::

R:

Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\H Street - 2 to 15th**

**St\Database\Pictures\0809\**

File: **H Street\_411\_rear\_looking\_N.JPG**

Date::

Photog:

Code::

R:

Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code

Roll

Frame(s)

Date

Photographer

Caption

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
08/31/1876	7	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

Date	Individual	Action
7/28/2009	Dayton (MSD), Maria	Record Updated
7/27/2009	Dayton (MSD), Maria	Record Updated
7/27/2009	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0818**

## BASICS DATA

ID Number: **0809-0818** Year Built: **1892** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>417</b>		<b>H Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-----------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 417 H Street, N.E.</b>	<b>Common</b>
<b>Sidamo</b>	<b>Current</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0809/0818</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Excellent**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential</b>	<b>1892</b>	<b>Permit</b>			<b>Original</b>

<b>Restaurant</b>		<b>Map</b>			<b>Historic</b>
<b>Store</b>		<b>Map</b>			<b>Historic</b>
<b>Store/Cafe</b>		<b>Site Visit</b>			<b>Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Rehabilitation</b>	<b>2006</b>	<b>Newspaper Clip</b>			
<b>Orig Construction</b>	<b>1892</b>	<b>Permit</b>			<b>8000 Permit</b>

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

**One of three rowhouses from the same permit.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row End (1 of 3)**  
Relate to Street: **Face on Line**  
Massing: **Vertical Block**  
Footprint: **Rectangular**

Number Stories: **2**  
Bays Wide: **3**

Height: **17**  
Width: **34**  
Depth/Length: **34**

SqFt:  
Volume:  
Lot Width  
Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**May 2009:** This two-story, three-bay, single-family dwelling is one of three rowhouses constructed in 1892. The easternmost rowhouse, this building is attached only to the west. Set on a solid brick foundation, this masonry structure has a stretcher-bond brick veneer. The roof type and material cladding were not visible from the public right-of-way. A brick parapet wall features a ogee-molded cornice with modillions and an ogee-molded architrave which extends the width of the dwelling. The façade (north elevation) has a canted one-story projection. The projection has a stretcher-bond brick veneer and features large, single-light storefront windows. An flat roof with ogee-molded cornice caps the projection. Located in the eastern bay of the façade is a recessed half-cant. This bay provides access to the first-story coffee shop via a single-leaf, wood-frame glass door as well as the second-story via a single-leaf, wood door with lights. A large, Craftsman-style transom is located above the bay. The transom window is mirrored to the west via three identical windows which provide balance to the first-story fenestration. Above the first-story openings is a large, molded architrave which extends the width of the three rowhouses. The second story has three window openings with 6/1, double-hung, wood-sash windows. The windows have a molded sill course which also extends the width of the three rowhouses. The outer window openings have soldier brick flat arches with clipped corners. The central bay has a round arch of rowlock bricks, imposts, and keystone. A diamond-shaped concrete medallion is located in the middle of the round arch. The east (side) elevation has a seven-course, American-bond brick veneer and no fenestration. The south (rear) elevation was not visible from the public right-of-way.

Site Notes:

**May 2009:** This building is located south of H Street, NE and directly fronts the concrete sidewalk. The building is attached to 415 H Street, NE to the west while a small alley extends along the east side of the building. The rear of the property was not visible from the public right-of-way.

## NOTABLE FEATURES DATA

Component Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>			
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Fixed	1	Metal
2 Flr Windows	Rectangular	Dbl-Hung	6/1	Wood
Door Location	Aperture Shape	Type	Panels	Material
First Floor	Rectangular	Single		Wood/Glass
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	Capitol Hill	Historic District(s)
Subdivision:		
Ward/ANC:		
Zoning:		Designation Event(s)
Contributing:		
Survey(s)		Level(s) of Investigation
Capitol Hill H Street (2009)		Permit Research Reconnaissance Survey

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File: H Street\_417\_facade\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File: H Street\_417\_facade\_looking\_SW.JPG

Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

1928 Sanborn: Furniture Store combining all three rowhouses.  
1960 Sanborn: Restaurant, only 417 H Street, N.E.

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/25/1892	0988	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
8/3/2009	Weishar (PJW), Paul	Record Updated
8/3/2009	Weishar (PJW), Paul	Record Created

# Resource All Data Report

**ID Number: 0809-0810**

## BASICS DATA

ID Number: **0809-0810** Year Built: **1892** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>415</b>		<b>H Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-----------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 415 H Street, N.E.</b>	<b>Common</b>
<b>Liquor/Checks Cashed</b>	<b>Current</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0809/0810</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Fair**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential</b>	<b>1892</b>	<b>Permit</b>			<b>Original</b>
<b>Store</b>		<b>Map</b>			<b>Historic</b>
<b>Vacant</b>		<b>Site Visit</b>			<b>Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Addition (Rear)</b>	<b>ca. 1950</b>	<b>Map/Site Visit</b>			
------------------------	-----------------	-----------------------	--	--	--

<b>Orig Construction</b>	<b>1892</b>	<b>Permit</b>			<b>8000 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Sommerville, C.W.</b>
--------------------------	------------------	--------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Getz, August</b>
--------------------------	----------------	---------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Weaver, Richard, Mrs.</b>
--------------------------	--------------	------------------------------

Construction Notes:

**One of three rowhouses from the same permit.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row attached**  
Relate to Street: **Face on Line**  
Massing: **Vertical Block**  
Footprint: **Rectangular**

Number Stories: **2**  
Bays Wide: **3**  
Height: **17**  
Width: **34**  
Depth/Length: **34**

SqFt:  
Volume:  
Lot Width  
Lot Depth/Length:  
Lot SqFt:  
Acreage:  
Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**May 2009:** This two-story, three-bay, single-family dwelling is one of three rowhouses constructed in 1892. The center building of the three, this building is set on a solid brick foundation. The masonry structure has a stretcher-bond brick veneer. The roof type and material cladding were not visible from the public right-of-way. A brick parapet wall features a ogee-molded cornice with modillions and an ogee-molded architrave which extends the width of the dwelling. Fenestration of the façade (north elevation) consists of a single-leaf, metal-frame glass door in the western bay. A large, multi-light transom is located above the door opening. East of the door opening is a projecting one-story, canted bay. The projection has a solid brick foundation fenestrated by large, single-light, metal-sash storefront windows. A flat roof caps the projection and extends across 413 H Street, NE. Located above the projecting bay are three window openings that have been enclosed or painted shut. Located above is a large, ogee-molded architrave that extends the width of the three similar buildings. The second story has three window openings with an projecting sill string that also extends across the width of the three buildings. The openings contain 1/1, double-hung, vinyl-sash windows. The outer bays have soldier brick flat arches while the central bay features a round arch of rowlock bricks, imposts, and keystone. A metal sign is affixed to the second story of the building.

A ca. 1950, two-story addition is located on the south (rear) elevation. The full-width addition has a six-course, American-bond brick veneer. The roof type and material were not visible from the public right-of-way. The west (side) elevation of the addition has no fenestration. The south (rear) elevation has an enclosed first-story window opening and two, 1/1, double-hung, vinyl-sash windows on the second story. The window openings have rowlock brick sills. The second story has a single-leaf door opening in the eastern bay accessed via a metal stair. The fenestration of the east (side) elevation was not visible from the public right-of-way.

Site Notes:

**May 2009:** This building is located south of H Street, NE and directly fronts the concrete sidewalk. The building is attached to 413 and 417 H Street, NE. The backyard is enclosed by a wood fence and is overgrown with mature trees and vines.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>			
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>	<b>Stretcher Bond</b>		
Structure Component	Material	Feature	Source	



Foundation                Brick  
Walls                      Brick

Materials Notes:

--

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Fixed	1	Metal
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal/Glass
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

--

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill H Street (2009)</b>	<b>Permit Research</b> <b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path:    **C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File:    H Street\_415\_facade\_looking\_SE.JPG**  
Date::                Photog:  
Code::                                R:                Fr:



Caption:

Path:    **C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File:    H Street\_415\_facade\_looking\_SW.JPG**  
Date::                Photog:  
Code::                                R:                Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File: H Street\_415\_rear\_elevation\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/25/1892	0988	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
8/3/2009	Weishar (PJW), Paul	Record Updated
8/3/2009	Weishar (PJW), Paul	Record Created

---

# Resource All Data Report

**ID Number: 0809-0812**

## BASICS DATA

ID Number: **0809-0812** Year Built: **1892** Data Source: **Permit**

Number Extended Street Quad Type of Address

**413** **H Street** **NE Current**

Name(s) Type of Name

**Single Dwelling, H Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0812** **Square/Lot** **Permit**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Boarded up**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential</b>	<b>1892</b>	<b>Permit</b>			<b>Original</b>
<b>Store</b>		<b>Map</b>			<b>Historic</b>
<b>Vacant</b>		<b>Site Visit</b>			<b>Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1892</b>	<b>Permit</b>			<b>8000 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Sommerville, C.W.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Getz, August</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Weaver, Richard, Mrs.</b>

Construction Notes:

**One of three rowhouses from the same permit.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached**  
Relate to Street: **Face on Line**  
Massing: **Vertical Block**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **34**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**May 2009:** This two-story, three-bay, single-family dwelling is one of three rowhouses constructed in 1892. This is the westernmost building in the group. Attached on both sides, this Colonial Revival-style dwelling is set on a solid brick foundation. This masonry dwelling has a stretcher-bond brick veneer. The roof type and material cladding were not visible from the public right-of-way. A brick parapet wall features a ogee-molded cornice with modillions and an ogee-molded architrave which extends the width of the dwelling. Fenestration of the façade (north elevation) consists of a single-leaf door opening in the western bay. The opening has no door, rather only a metal grate. A one-story, canted bay projects from the façade. The projection has a solid brick foundation and is clad in aluminum siding. Fenestration consists of a two-light, wood-sash window. A flat roof caps the projection and extends across 415 H Street, NE. Three large openings are located above the first-story openings. These openings have been enclosed with vertical-board siding. Located above is a large, ogee-molded architrave that extends the width of the three similar buildings. The second story has three window openings with an projecting sill string that also extends across the width of the three buildings. The central opening and eastern opening are enclosed with plywood while the western bay has no sash and is open. The outer bays have soldier brick flat arches while the central bay features a round arch of rowlock bricks, imposts, and keystone. All of the south (rear) elevation door and window openings have been enclosed with plywood. One-course, rowlock brick segmental arches compliment the openings.

Site Notes:

**May 2009:** This building is located south of H Street, NE and directly fronts the concrete sidewalk. The building is attached to 415 H Street, NE to the east and 411 H Street, NE to the west. The rear of the property is enclosed by a wood fence and is overgrown with mature trees and vines.

## NOTABLE FEATURES DATA

Component Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible			
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature	Source	
Foundation	Brick			
Walls	Brick			

Materials Notes:

--

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1st Flr Bay	Rectangular	Fixed	2-light	Wood
2 Flr Windows	Rectangular	Missing	Unknown	Unknown
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

--

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill H Street (2009)</b>	<b>Permit Research</b> <b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File: H Street\_413\_facade\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File: H Street\_413\_facade\_looking\_SW.JPG

Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

## MISCELLANEOUS NOTES DATA

Notes:

This building is one of three single-family rowhouses constructed in 1892. The 1928 Sanborn Fire Insurance Company map documents the building utilized as a furniture store. In fact, all three of the rowhouses were integrated as a furniture store. By the 1960 Sanborn map, the building functioned as a store, independent of the two other rowhouses. At the time of the 2009 on-site survey the building was vacant and in poor condition.

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/25/1892	0988	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

Date	Individual	Action
8/4/2009	Weishar (PJW), Paul	Record Updated
8/4/2009	Weishar (PJW), Paul	Record Created

# Resource All Data Report

**ID Number: 0809-0031**

## BASICS DATA

ID Number: **0809-0031** Year Built: **1927** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>421</b>		<b>H Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-----------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Dwelling/Store, 421 H Street, N.E.</b>	<b>Common</b>
<b>Pap &amp; Petey's</b>	<b>Current</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0809/0031</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Dwelling/Store** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Dwelling &amp; Store</b>	<b>1927</b>	<b>Permit</b>			<b>Original</b>
<b>Restaurant/Dwelling</b>		<b>Site Visit</b>			<b>Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1927</b>	<b>Permit</b>			<b>10000 Permit</b>
--------------------------	-------------	---------------	--	--	---------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Dittrich, Lloyd H.</b>
--------------------------	------------------	---------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Lanigan, W. B.</b>
--------------------------	----------------	-----------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Gleason, Johanna</b>
--------------------------	--------------	-------------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Corner Attached**  
Relate to Street: **Face on Line**  
Massing: **Vertical Block**  
Footprint: **Rectangular**

Number Stories: **2**

Bays Wide:

Height:

Width: **16**

Depth/Length: **52**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**May 2009:** This two-story building was designed by Lloyd H. Dittrich and built by W.B. Lanigan in 1927. It is five bays wide and one bay deep. The brick building is faced with stretcher-bond brick. The concrete foundation is covered in five-course, American-bond brickwork. A brick parapet wall that is finished with a concrete cap obscures the roof. The north (front) and east (side) elevations features a one-story projection that was constructed after 1960. It is fenestrated by a continual band of one-light fixed windows. The entry, which is centrally placed on the façade, does not project. It holds a double-leaf glass door in a metal frame with sidelights. The second story (on both the north and east elevations) features large one-light fixed windows. The windows are set in a brick surround with concrete corner blocks. A concrete sill course is sited beneath with second-story windows. Above the windows is a wide concrete belt course.

Off the west (side) elevation of the main block is a small, one-story, one-bay vestibule that may be original to the building. It is veneered in stone and is fenestrated by a single-leaf glass door set in a metal frame. Above the entry is a transom.

Site Notes:

**May 2009:** This property is located in the southwest corner of H Street, NE and 5th Street, NE. The building front a concrete sidewalk on the north (front) and east (side) elevations. The lot is wide and narrow. The building located at 417 H Street is located to the east.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
---------------	--------------	--	-----------------------	--

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

<b>Foundation</b>	<b>Concrete</b>		
<b>Walls</b>	<b>Brick</b>		

Materials Notes:



## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>1st Flr Bay</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1-light</b>	
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1-light</b>	
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Metal/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill H Street (2009)</b>	<b>Permit Research</b> <b>Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File: H Street\_421\_facade\_looking\_S.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File: H Street\_421\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\

File: H Street\_421\_side\_looking\_W.JPG

Date:: Photog:

Code:: R: Fr:



---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

1928 Sanborn Map: Store 1960 Sanborn Map: Store
--

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

---

06/22/1927	10532	Build	
------------	-------	-------	--

Permit Notes:

--

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

--

### SIGNIFICANCE DATA

Study Unit

---

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
8/4/2009	Dayton (MSD), Maria	Record Updated
8/4/2009	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0028**

## BASICS DATA

ID Number: **0809-0028** Year Built: **1876** Data Source: **Permit**

Number Extended Street Quad Type of Address

**407** **H Street** **NE Current**

Name(s) Type of Name

**Dwelling/Store, 407 H Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0028** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Dwelling/Store** Condition: **Fair**

Function/Use Start Source Stop Source Explain

**Dwelling & Store** **1876** **Permit** **Original**

**Vacant** **Map/Site V** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1876** **Permit** **9000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Owner** **Thompson, A.**

Construction Notes:

**407-411 H Street, NE were constructed in 1876 by A. Thompson under the same permit (#7).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Line**

Massing: **Vertical Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**May 2009:** This two-story, three-bay building was constructed in 1876. The building is set on a solid brick foundation and is constructed of brick faced with stretcher-bond brick. A stepped brick parapet wall topped by metal flashing obscures the roof from the public right-of-way. Plywood covers the fenestration on the first story, which appears to be made up of a centrally placed window flanked by two entrances. A vinyl awning spans the façade and shades the first story. The western two bays on the second story are also covered by plywood. The easternmost bay holds a 1/1, double-hung, vinyl-sash window. Each window opening on the second story features a concrete sills and a vinyl awning. The east and west (side) elevations are obscured by adjoining buildings.

Site Notes:

**May 2009:** This property is located on the south of H Street, NE. It fronts a concrete sidewalk. The building is adjacent 405 H Street, which is located to the west, and 409 H Street, which is located to the east.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill H Street (2009)**

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File: H Street\_407\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File: H Street\_407\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

1928 Sanborn Map: Store  
1960 Sanborn Map: Store

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
08/31/1876	7	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
8/4/2009	Dayton (MSD), Maria	Record Updated
8/4/2009	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0025**

## BASICS DATA

ID Number: **0809-0025** Year Built: **1872-1873** Data Source: **Tax Records**

Number Extended Street Quad Type of Address

**401** **H Street** **NE** **Current**

Name(s) Type of Name

**Dwelling/Store, 401 H Street, N.E.** **Common**  
**Institute for Behavioral Change and Research** **Current**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0025** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Dwelling/Store** Condition: **Fair**

Function/Use Start Source Stop Source Explain

**Dwelling & Store** **1872-1873** **Written Da**  
**Office** **Site Visit** **Original**  
**Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1872-1873** **Tax Records**

Construction Event Association Associated Name

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Corner Attached**  
Relate to Street: **Face on Line**  
Massing: **Vertical Block**  
Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

Exterior & Architectural Notes:

**May 2009:** This two-story Italianate building was constructed between 1872 and 1875. The structure is constructed of brick that is veneered in stretcher-bond brick. A wood cornice with modillions, brackets and dentils finishes the roof, which could not be seen from the public right-of-way. A one-story projection spans the north (front) and west (side) elevations. It is veneered in brick and capped by a shed roof of standing-seam metal. The first story of the façade holds a one-light fixed window in the easternmost bay. In the westernmost bay is a single-leaf metal-frame glass door that is recessed from the rest of the projecting first story. It features a one-light transom above and is protected by a cloth awning. Above the first story, spanning the north and west elevations, is a wood cornice with modillions. The top of the cornice is covered in standing-seam metal. The second story of the façade is fenestrated by one-light fixed windows with drip molding and wood sills. The west (side) elevation has one-light fixed windows that fenestrate the first story projection. Above the projection, but still on the first story are paired and tripled one-light fixed windows. On the second story of the west elevation are one-light fixed windows with brick segmental arches and wood sills. Adjoining buildings obscure the south (rear) and east (side) elevations of this resource.

Site Notes:

**May 2009:** This property is located on the southeast corner of the intersection of H Street, NE and 4th Street, NE. The building fronts a concrete sidewalk on its north and west elevations. The building located at 403 H Street abuts the east (side) elevation. Adjacent to the south (rear) elevation is 735 4th Street.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>1 Flr Windows</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1-light</b>	
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1-light</b>	
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Metal/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:



Zoning:  
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill H Street (2009)

Permit Research  
Reconnaissance Survey  
Tax Book Research

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File: H Street\_401\_corner\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File: H Street\_401\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

The 1869-1871 General Assessment book indicates that Lot 25 (originally known as Lot 6) was unimproved. The 1872-1873 General Assessment book notes that the lot was owned by William W. Corcoran. Corcoran also owned the lots now addressed as 403 and 405 H Street. The lot had an assessed value of \$1,786 or at a rate of .14 for 10,508 square feet.

General Assessment, 1869-1871. Corporation of Washington. (Vol. 13 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C. p. 714.

General Assessment, 1872-1873. Corporation of Washington. (Vol. 14 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C. p. 657.

1928 Sanborn Map: Store  
1960 Sanborn Map: Store

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

--

### BIBLIOGRAPHIC DATA

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

--

### SIGNIFICANCE DATA

---

Study Unit

---

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
9/14/2009	Dayton (MSD), Maria	Record Updated
8/26/2009	Dayton (MSD), Maria	Record Updated
8/5/2009	Dayton (MSD), Maria	Record Updated
8/5/2009	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0026**

## BASICS DATA

ID Number: **0809-0026** Year Built: **1872-1873** Data Source: **Tax Records**

Number Extended Street Quad Type of Address

**403** **H Street** **NE** **Current**

Name(s) Type of Name

**Dwelling/Store, 403 H Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0026** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Dwelling/Store** Condition: **Fair**

Function/Use Start Source Stop Source Explain

**Dwelling & Store** **1872-1873** **Written Da** **Original**

**Dwelling/Dry Cleaning** **Map/Site V** **Historic**

**Vacant** **Site Visit** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1872-1873** **Tax Records**

Construction Event Association Associated Name

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Line**

Massing: **Vertical Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

Exterior & Architectural Notes:

**May 2009:** This two-story, three-bay Italianate building was constructed between 1872 and 1873. The structure is constructed of brick that is veneered in stretcher-bond brick. A wood cornice with modillions, brackets and dentils finishes the roof, which could not be seen from the public right-of-way. The first story of the façade features a centrally-placed, one-story, three-sided projection. The projection is fenestrated by paired one-light storefront windows. It has wood boards under the windows and at the top of the projection is an ogee-molded cornice. Above the projection, but still on the first story, are two window openings. The eastern opening is covered in plywood, and the western opening holds a small two-light window. East of the projection on the first story is a single-leaf entrance that is obscured by a plywood cover. West of the projection is a single-leaf paneled wood door with a light and a two-light transom above. The second-story openings are covered in plywood and features drip molding and wood sills. The east and west (side) elevations are obscured by adjoining buildings.

Site Notes:

**May 2009:** This property is located on the south of H Street, NE. It fronts a concrete sidewalk. . The building is adjacent 401 H Street, which is located to the west, and 405 H Street, which is located to the east.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>1st Flr Bay</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1-light</b>	
Door Location	Aperture Shape	Type	Panels	Material
<b>First Floor</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Capitol Hill H Street (2009)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey  
Tax Book Research

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File: H Street\_403\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File: H Street\_403\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

The 1869-1871 General Assessment book indicates that Lot 26 (originally known as Lot 6) was unimproved. The 1872-1873 General Assessment book notes that the lot was owned by William W. Corcoran. Corcoran also owned the lots now addressed as 401 and 405 H Street. The lot had an assessed value of \$1,786 or at a rate of .14 for 10,508 square feet.

General Assessment, 1869-1871. Corporation of Washington. (Vol. 13 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C. p. 714.

General Assessment, 1872-1873. Corporation of Washington. (Vol. 14 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C. p. 657.

1928 Sanborn Map: Store  
1960 Sanborn Map: Dry Cleaning

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

## BIBLIOGRAPHIC DATA

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

## SIGNIFICANCE DATA

---

Study Unit

---

Code	Criteria
------	----------

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
9/14/2009	Dayton (MSD), Maria	Record Updated
8/5/2009	Dayton (MSD), Maria	Record Updated
8/5/2009	Dayton (MSD), Maria	Record Created

# Resource All Data Report

**ID Number: 0809-0027**

## BASICS DATA

ID Number: **0809-0027** Year Built: **1872-1873** Data Source: **Tax Records**

Number Extended Street Quad Type of Address

**405** **H Street** **NE Current**

Name(s) Type of Name

**Dwelling/Store, 405 H Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0809/0027** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Dwelling/Store** Condition: **Fair**

Function/Use Start Source Stop Source Explain

**Dwelling & Store** **1872-1873** **Written Da** **Original**

**Vacant** **Site Visit** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1872-1873** **Tax Records**

Construction Event Association Associated Name

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Line**

Massing: **Vertical Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

Exterior & Architectural Notes:

**May 2009:** This two-story, three-bay Italianate building was constructed between 1872 and 1873. The structure is constructed of brick that is veneered in stretcher-bond brick. A wood cornice with modillions, brackets and dentils finishes the roof, which could not be seen from the public right-of-way. The modillions are missing on the western half of the cornice. The first story of the façade features a centrally-placed, one-story, three-sided projection. The projection is veneered in jumbo brick and has a window opening that is covered by plywood. At the top of the projection is an ogee-molded cornice. Above the project, but still on the first story, are small window openings that are also covered in plywood. East of the projection is a single-leaf metal door with a transom that is obscured by a plywood cover. West of the projection is a single-leaf entry that has been boarded over. The second-story openings are covered in plywood and features drip molding and wood sills. The east and west (side) elevations are obscured by adjoining buildings.

Site Notes:

**May 2009:** This property is located on the south of H Street, NE. It fronts a concrete sidewalk. The building is adjacent 403 H Street, which is located to the west, and 407 H Street, which is located to the east.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
---------------	--------------	--	-----------------------	--

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

<b>Foundation</b>	<b>Brick</b>		
-------------------	--------------	--	--

<b>Walls</b>	<b>Brick</b>		
--------------	--------------	--	--

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Missing</b>		
----------------------	--------------------	----------------	--	--

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

<b>First Floor</b>	<b>Rectangular</b>	<b>Single</b>		<b>Metal</b>
--------------------	--------------------	---------------	--	--------------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill H Street (2009)**

**Permit Research**



## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File: H Street\_405\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\H Street - 2 to 15th  
St\Database\Pictures\0809\  
File: H Street\_405\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

The 1869-1871 General Assessment book indicates that Lot 27 (originally known as Lot 6) was unimproved. The 1872-1873 General Assessment book notes that the lot was owned by William W. Corcoran. The value of the lot was assessed at \$1,786 or at a rate of .14 for 10,508 square feet.

General Assessment, 1869-1871. Corporation of Washington. (Vol. 13 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C., p. 714.

General Assessment, 1872-1873. Corporation of Washington. (Vol. 14 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C. p. 657.

1928 Sanborn Map: Store  
1960 Sanborn Map: Store

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
9/14/2009	Dayton (MSD), Maria	Record Updated
8/5/2009	Dayton (MSD), Maria	Record Updated
8/5/2009	Dayton (MSD), Maria	Record Created

