BASICS DATA

ID Number: 0832-0017 Year Built: 1903 Data Source: Permit

Extended Street Quad Type of Address Number

504 **H** Street **NE** Current

Name(s) Type of Name

Single Dwelling, 504 H Street, N.E. Original **New Citi Pizza** Current

Explain TaxCode1 TaxCode2 TaxCode3 Type 0832/0017 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Residential Condition: Fair

Function/Use Start Source Stop Explain Source Residential (Single-Family) 1903 Permit Original **Dwelling & Store** Map/Site V Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1903	Permit			3000 Permit

ID Number: 0832-0017

Construction Event Association Associated Name Culhane, Thomas Builder Culhane, Thomas **Orig Construction** Architect Lantel, George **Orig Construction** Owner Culhane, Catherine

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0832-0017 Page 1

Surroundings:	Urban	Cross Re	ference Notes:		
Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Intact Attached Face on Line Vertical Block Rectangular				
Number Stories: Bays Wide:	2 3				
Height:		Outbuilding Type	Conti	ributing Status	
Width: Depth/Length:	19 33				
SqFt: Volume: Lot Width					
Lot Depth/Length:		Outbuilding Notes	:		
Lot SqFt: Acreage:					
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)			_		
stretcher-bond brick roof. An interior-real central bay of the fir doors flank the cent that have been infille features rosette mol concrete lintels. A constructed of irreg coursed, American-lobscured by a metal openings have three light fixed metal win concrete sills and two Site Notes: June 2009: This lot is not fixed read with the concrete sills and the sills and two sills	a. A sloping roof caps the prick chimney rises from the strong contains triple of the strong contains triple of the strong contains triple of the strong contains. The window oper concrete string course is the strong course, rowlock brick is the strong course, rowlock brick is the strong course, rowlock brick is strong course, rowlock brick	e building. A corbeled on the northwest corn one-light metal fixed we recessed. The three ball lintel stretches acronings of the second si sited below the window corner of the rear elevation of caps the ell. The east remost bay of the first segmental arches. The segmental arches.	I brick cornice with oge er of the building and hyindows with a rowlock ay openings on the first as the façade above the tory contain 1/1, double ow openings. Action of the building and foundation that is also sternmost bay contains t story has been infilled a easternmost bay of the double-hung, metal-said the building directly for the building directly for the double building directly for the building directly for the double building directly for the buildi	(south elevation) is facede molding complements as a parged chimney cap brick sill. Single-leaf woo story have transom open first story openings and hung, wood-sash window dis original. The ell is a constructed of irregular as a single-leaf door that we with brick. Both first store second story contains as him window. Both opening acces the concrete sideward, which is accessed by a	the b. The od nings ws with - vas ory a one- gs have
NOTABLE FEATU	RES DATA				
Component	Featur	е			
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible				
Wall Component	Material	Color	Treatment	Source	
Facade	Brick	Blue	Stretcher Bond		
Structure Component		Feature		Source	
Foundation	Concrete				

Walls

Brick

WINDOW/DOOR/INTERIOR DATA

First Floor	Rectangular	Single		Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
2 FIr Windows	Rectangular	Dbl-Hung	1/1	Wood	
1 FIr Windows	Rectangular	Fixed	3 Lite	Metal	
Window Location	Aperture Shape	Туре	Lights	Material	

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision:
Ward/ANC:
Zoning:

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill H Street (2009) Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_504_facade_looking_N.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\H Street - 2 to 15th

St\Database\Pictures\0832\

File: H Street_504_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:



Designation Event(s)



Ca		

Date

7/29/2009

7/29/2009

Individual

Dayton (MSD), Maria

Dayton (MSD), Maria

Path:

C:\Users\CHRS\Documents\CHRS Databases\H Street - 2 to 15th St\Database\Pictures\0832\

H Street_504_rear_looking_S.JPG File:

Date:: Photog:



PHOTOS - B/W								
Photo Code	Roll	Fram	e(s)	Date	Photograph	er	Caption	
MISCELLANEO	JS NOTE	S DATA						
Notes:								
PERMIT DATA								
Permit Issue Date		Number	Type		Remarks			
10/29/1903		0783			Remarks			
Permit Notes:								
BIBLIOGRAPHI	C DATA							
Short Citation	DAIA			Туре	Date	Remarks		
Short Citation				туре	Date	Remarks		
Bibliographic Notes	3:							
SIGNIFICANCE	DATA							
Study Unit								
Code Cri	teria							

Tuesday, June 25, 2013	ID_Number: 0832-0017 Page

Action

Record Updated

Record Created

ID Number: 0832-0016

BASICS DATA

ID Number: 0832-0016 Year Built: 1905 Data Source: **Permit** Quad Type of Address Number Extended Street 506 **H** Street Current Name(s) Type of Name Multi-Family Dwelling, 506 H Street, N.E. Original Cozy Home Insulation Co. Historic (1st) Cozy Home Company, Inc. Historic (2nd) Mailinh USA Current TaxCode1 TaxCode2 TaxCode3 Type Explain 0832/0016 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain Residential (Multi-Family) 1905 Permit Original Office/R-M Site Visit Current Store & R-M Historic Map

CONSTRUCTION DATA

Construction Event Start Source Stop Source Co	ost Source
Orig Construction 1905 Permit 70	000 Permit
Construction Event Association Associated Name	
Orig Construction Architect Bohn, Joseph A. Jr.	
Orig Construction Builder Getz (August) & Sor	า
Orig Construction Owner Allen, W.H.H.	
Construction Notes:	

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0832-0016 Page 1

Surroundings:	Urban	Cross Reference Notes:	
Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Intact Attached Face on Line Vertical Block Rectangular		
Number Stories: Bays Wide:	3 2		
Height: Width: Depth/Length: SqFt: Volume: Lot Width	19 32	Outbuilding Type Contributing Status	
Lot Depth/Length: Lot SqFt: Acreage:		Outbuilding Notes:	
Has Driveway:			
STYLE/EXTERIOR Architectural Style(s)	DATA		
foundation. The built faced with Permasto from the public right easternmost bay of the mimics a lintel with a bay is set on a solid eaves. Fenestration contained larger win lower half. The open mimicked by Permas windows with concrete to the constructed of five-chowever, the roofing northeast corner of the elevation of the ell a pebble-dashed and a have been infilled with concrete blocks easternmost bay of three-course, rowlock A three-story, metal-	ding was initially constructed ne. A sloping roof with a cro-of-way. An interior-side brick first story contains a single keystone. A one-story bay foundation that is faced wit consists of a band of two-light dows, however, the opening ing now contains triple 1/1, stone. The three third story stee sills and segmental archicated on the northeast corrected on the northeast corrected with a particular and has a parged caping stretch from the second are fenestrated with 1/1, dout the concrete block, though the each story on the rear elevals keepmental arch. The first is. The easternmost bay of the second and third stories is brick segmental arches.	y, two-bay building is constructed of brick and is set on a solid concrete ed as a dwelling for two families. The façade (south elevation) has been renellated parapet caps the building. The roofing material was not visible ick chimney rises from the west (side) elevation and has a plain cap. The ingle-leaf metal-frame glass door with a one-light transom. Permastone of projects from the southwest corner of the façade and is not original. The this tretcher-bond brick and is capped by a flat roof with overhanging ight metal fixed windows. The second story window opening originally ighas been decreased in size with the application of vinyl siding to the double-hung, vinyl-sash windows with false 6/6 vinyl muntins. A lintel is segmental window openings contain 1/1, double-hung, vinyl-sash hes mimicked by Permastone. The rear elevation of the main block and is original. The ell is the kand is set on a solid brick foundation. A sloping roof caps the ell, om the public right-of-way. An interior brick chimney rises from the position of the third story. Constructed ca. 1950, the oriel windows have been uble-hung, vinyl-sash windows. Many of the first story openings of the ell they still retain their three-course, rowlock brick segmental arches. The ation contains a single-leaf metal door with a blind transom and three-story door has one-light and a transom opening that has been infilled he first story has been infilled with concrete blocks. The segmental is contain 1/1, double-hung, vinyl-sash windows. All eastern bays contain 1/1, projects from the rear elevation of the ell and is capped by a sheater than the projects from the rear elevation of the ell and is capped by a sheater than the projects from the rear elevation of the ell and is capped by a sheater than the projects from the rear elevation of the ell and is capped by a sheater than the projects from the rear elevation of the ell and is capped by a sheater than the projects from the rear elevation of the ell and is capped by a sheater than the projects from the	
the 1928 Sanborn ma		posts. Square wood balusters finish the porch. A similar porch is noted on	
building is adjacent		n side of H Street, NE and directly fronts the concrete sidewalk. The E. A concrete public alley is sited north of the building and runs east to be property.	
NOTABLE FEATU	RES DATA		
Component	Feature		

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible				
Wall Component	Material	Color	Treatment	Source	
Facade	Permastone		Veneer		
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material
1st Flr Bay	Rectangular	Fixed	2-light	Metal
2 Flr Windows	Rectangular	Dbl-Hung	1/1 Triple	Vinyl
3 FIr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Main Door	Rectangular	Single		Metal/Glass

Notable Interior Plan(s) Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill H Street (2009)

Permit Research Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

File:

Path: C:\Users\CHRS\Documents\CHRS Databases\H Street - 2 to 15th

St\Database\Pictures\0832\ H Street_506_facade_looking_NE.JPG

Date:: Photog:

Fr: Code:: R:



O -	- 0	
Ca	nti	nη

Path: C:\Users\CHRS\Documents\CHRS
Databases\H Street - 2 to 15th

St\Database\Pictures\0832\

File: H Street_506_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_506_rear_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_506_rear_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:







PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

05/01/1905 2294 Build

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Bibliograph	nic Notes:			
SIGNIFIC	ANCE DATA			
Study Unit				
Code	Criteria			

DATA PROCESSING EVENTS DATA

Date	Individual	Action
7/30/2009	Dayton (MSD), Maria	Record Updated
7/29/2009	Dayton (MSD), Maria	Record Updated
7/29/2009	Dayton (MSD), Maria	Record Created

ID Number: 0832-0009

BASICS DATA

ID Number: 0832-0009 Year Built: 1909 Data Source: **Permit** Quad Type of Address Number Extended Street 528 **H** Street Current Name(s) Type of Name Dwelling/Store, 528 H Street, N.E. Common Taste of Jamaica (Ground Floor) Current State Farm (2nd Floor) Current TaxCode1 TaxCode2 TaxCode3 Type Explain 0832/0009 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Dwelling & Store Condition: Good

Function/Use Start Source Stop Source Explain

Dwelling & Store 1909 Permit Original

Restaurant/Office Site Visit Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1909	Permit	5500 Permit		5500 Permit

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0832-0009 Page 1

Surroundings: Streetscape:	Urban Intact	Cross	Reference Notes:		
Relate to Othr Bldgs:	Corner Attached (1 side)				
Relate to Street: Massing:	Face on Line Vertical Block				
Footprint:	Rectangular				
Number Stories: Bays Wide:	2				
Height: Width:		Outbuilding Ty	уре	Contributing Status	
Depth/Length:					
SqFt: Volume:					
Lot Width Lot Depth/Length:		Outbuilding N	otes:		
Lot SqFt:		- Catalananig i	<u> </u>		
Acreage:					
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
solid brick foundation sloping roof caps the leaf metal-frame glass door is flanked by or southernmost bay of fenestration consists concrete keystones. The canted bay projects the main block and in gauged brick jack are with brick and concrete with the same than the same slope slop	ted in 1909 as a dwelling and on. The façade (south elevate building. Overhanging earses door pierces the canted she-light sidelights and has a fithe east elevation contains of 2/2, double-hung, metal Additionally, a single-leaf indoor entry is approached by from the east elevation just soriginal. Fenestration contacts with concrete keystomete blocks, however, the two is located on the northeas the same material treatmentr of the ell and has a plain colocated on the east elevation.	tion) and east oves, with a mosoutheast corra one-light trait triple two-ligh l-sash windownetal-frame glay poured concincth of the sisists of 2/2, does. The windowo-course, row t corner of the t and is cappetap. Fenestration. The door is	(side) elevations are folded cornice and moder of the building and assom. The westernmost fixed metal windows as with concrete sills assodor pierces the earete steps with metal ingle-leaf door. The bouble-hung, metal-sas wo openings of the reallock brick segmental arear (north) elevation d by a flat roof. An into on is consistent with accessed by a flight of	onstructed of brick and is set of aced with stretcher-bond brick dillions complement the roof. A discress as the primary entranges bay of the façade and the set bay of the façade and second set by the second set by the set of the second set by the same material treat set windows with concrete sills are (north) elevation have been arches remain. In of the main block. Original to the second	A. A A single- ce. The story with ght sided ment as and infilled the from eaf wood- All
Site Notes:					
May 2009: This build concrete sidewalk. T	he west elevation of the dw	elling is adjac	ent to 526 H Street, N	Street, NE and directly fronts t E. A paved public alley is loca is enclosed with metal chain-l	ted
NOTABLE FEATUR	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible				
Wall Component	Material	Color	Treatment	Source	

Tuesday, June 25, 2013 ID_Number: 0832-0009 Page 2

Stretcher Bond

Red

Wall

Brick

Structure Component	Material	Feature	Source	
Foundation	Brick			
Walls	Brick			
Materials Notes:				

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 FIr Windows	Rectangular	Dbl-Hung	2/2	Metal
1 FIr Windows	Tripartite	Fixed	2-light	Metal
2 FIr Windows	Rectangular	Dbl-Hung	2/2	Metal
Door Location	Aperture Shape	Type	Pamels	Material
First Floor	Rectangular	Single		Metal/Glass
Side Door	Rectangular	Single		Metal/Glass
Notable Interior Plan	n(s)		Notable Interior Feature(s)	

Totalio monor ran(o)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision:
Ward/ANC:
Zoning:
Contributing:

Designation Event(s)

ID_Number: 0832-0009 Page 3

Survey(s)
Capitol Hill H Street (2009)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_528_facade_looking_N.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_528_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_528_rear_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_528_rear_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_528_side_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

STATE FARM







PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

1928 Sanborn Map: Store

1960 Sanborn Map: Front, Store; Rear, Dwelling

1999 Sanborn Map: Commerical

PERMIT DATA					
Permit Issue Date	Number	Туре	Remarks		
04/16/1909	3853	Build			
Permit Notes:					
BIBLIOGRAPHIC DA	ATA				
Short Citation		Туре	Date	Remarks	
Bibliographic Notes:					
SIGNIFICANCE DAT	- A				
Study Unit		<u></u>			
Code Criteria					
DATA PROCESSING	S EVENTS DAT	Δ			
Date Inc	dividual	Action			

Record Updated

Record Created

7/29/2009

7/29/2009

Dayton (MSD), Maria

Dayton (MSD), Maria

Tuesday, June 25, 2013 ID_Number: 0832-0009 Page 5

ID Number: 0832-0010

BASICS DATA

ID Number: 0832-0010 Year Built: 1912 Data Source: **Permit** Quad Type of Address Number Extended Street 526 **H** Street Current Name(s) Type of Name Single Dwelling, 526 H Street, N.E. Common Salvation Army Historic (1st) Dee & Kim's Nail Salon Current TaxCode1 TaxCode2 TaxCode3 Type Explain 0832/0010 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: **Historic** Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain 1912 Original Residential **Permit** Non Profit Organization Historic Map Map **Historic** Vacant/Commercial **Site Visit** Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
			Stop	Source	
Orig Construction	1912	Permit			3500 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Arch	itect		Talbott, W.I	R.
Orig Construction	Own	er-Builder		Howensteir	ո, H.R.
Construction Notes:					

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0832-0010 Page 1

Surroundings.	Orban	CIUSS RE	erence motes.		
Streetscape:	Intact				
Relate to Othr Bldgs:	Attached				
Relate to Street:	Face on Line				
Massing:	Vertical Block				
Footprint:	Rectangular				
Number Stories:	2				
Bays Wide:	3				
Height:	-	Outbuilding Type	Co	ontributing Status	
Width:	19				
Depth/Length:	50				
SqFt:					
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes	s:		
Lot SqFt:		_			
Acreage:					
Has Driveway:					
· · · · · · · · · · · ·					
STYLE/EXTERIOR	DATA				
	DAIA				
Architectural Style(s)					
Exterior & Architectur	al Notes:				
	ding is located north of and west. The rear of the				ouilding is
NOTABLE FEATU	RES DATA				
		ro			
Component	Featu	ıe			
EXTERIOR MATE	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible				
Wall Component	Material	Color	Treatment	Source	
Facade	Brick	33.01	Stretcher Bond	304.00	
	5.10K		C. C.O.IIC. DOILU		
Structure Component	Material	Feature		Source	
Foundation	Unknown				
Walls	Brick				
Materials Notes:					
Materials NOTES.					
<u> </u>					
WINDOW/DOOR/II	NTERIOR DATA				
WINDOW/DOOR/II Window Location	NTERIOR DATA Aperture Shape	Туре	Lig		Material

1 Flr Windows Rectangular **Fixed** 1 Metal 2/2 Vinyl 2 Flr Windows Rectangular **Dbl-Hung Door Location** Pamels Material Aperture Shape Type First Floor Rectangular Single First Floor Rectangular Single Metal/Glass Notable Interior Plan(s) Notable Interior Feature(s) Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s) Level(s) of Investigation

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Capitol Hill H Street (2009)

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_526_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_526_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Tuesday, June 25, 2013 ID_Number: 0832-0010 Page 3

Notes:

This building was constructed in 1912 as a single-family dwelling. In 1928, the Sanborn map documents the Salvation Army as occupying the building. In 1948, the Salvation Army was located at 1371 H Street, NE. It is unknown if the Salvation Army occupied this building past 1948. In 1960 and in 1999, the building was documented as a store. At the time of the 2009 on-site survey, the first story was a store and the second story vacant and advertised for rent.

PERMIT DATA Permit Issue Date Number Type Remarks 06/25/1912 6166 Build Permit Notes: **BIBLIOGRAPHIC DATA Short Citation** Type Date Remarks Bibliographic Notes: SIGNIFICANCE DATA Study Unit Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
8/4/2009	Weishar (PJW), Paul	Record Updated
8/4/2009	Weishar (PJW), Paul	Record Created

Tuesday, June 25, 2013 ID_Number: 0832-0010 Page 4

ID Number: 0832-0012

BASICS DATA

ID Number:	0832-0	0012	Year Built:	1912	Da	ta Source:	Permit
Number Ex	tended	Street			Qua	d Type of Ad	ddress
514		H Street			NE	Current	
512		H Street			NE	Original	
Name(s)				Type of	Name)	
Apartment, 512 H Street, N.E.			Original				
Adonai Ministry International, Inc.				Curren	t		
TaxCode1 T	axCode2	TaxCode3	Туре	Explair	า		
0832/0012			Square/Lot	Curre	nt		

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: **Historic** Quality:

Purpose: Apartment Condition: Good

Function/Use Start Source Stop Source Explain 1925 Residential Permit Original Church Site Visit Current Store Map Historic

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1925	Permit			10000 Permit
Construction Event	Association			Name	
Orig Construction	Architect			Powel, A. C	3.
Orig Construction	Owner-Builder			King, H.R.	
Construction Notes:					

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0832-0012 Page 1

Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Lot SqFt: Acreage:	Urban Intact Attached Face on Line Vertical Block Rectangular 2 3 19 60	Outbuilding Type Outbuilding Notes:		ntributing Status	
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
The parapet has a mpanels have a baske set on a solid brick fin the mid-twentieth have single-light traities anchored to the cornice. Sited above three, 1/1, double-huis located between t 1/1, double-hung, virsecond story includopening with a two-second-story porch elevation. Based on brick finish on the eleaf, metal door. It is opening. A flat roof of Site Notes: May 2009: This build to the east and west	olded cornice flanked the weave inlay. The first foundation with a single century. The bay is flanksoms. Sheltering the façade. Directly above the cornice is a wide and in the window openings where window openings while a single-leaf, panele course, rowlock brick swith square balusters, map research, this gar ast (side) elevation and probably that the reast caps the garage. The reling is located north of the backyard has been as foundation of the backyard has been as the same and t	by party walls and is decoral story of the façade (south ele-light display windows. Banked by replacement, single door openings and the projet the flat-roof porch are four-rowlock brick panel with a new with concrete lug sills and with a molded architrave about thin concrete sills and two-d wood door and a small, degmental arch. The door open supports, and a shed roof, age is an original feature to that has been parged on the note on the rear elevation is parget of has a metal railing with least the story of the same and the story of the same and the same an	ted with three ro levation) has a p sed on its form a seleaf, paneled meting bay is a milight, wood-sash letal sign affixed I rowlock brick selection of the course, rowlock 1, double-hung, ening is accessed and constant of the building. The rth (rear) elevaticed is to conceal attice work.	a pedimented brick parapet wal wlock brick panels. The outer rojecting, three-sided central band materials, this bay was added that doors with lights. The doors olded porch supported by cable awning windows with a molded. The second story is pierced by urrounds. Herringbone brickwor ar) elevation is fenestrated with brick segmental arches. The winyl-sash window set in a single divia a wood stair leading to a bay garage is located on the reat a garage has an American-bond on. The rear elevation has a sing the enclosure of a garage door	y d r k e r
NOTABLE FEATU	RES DATA				
Component	Featu	ire			
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	reatment	Source	
Sloped	Not Visible				
Wall Component	Material	Color	reatment	Source	
Facade	Brick	9	Stretcher Bond		

Tuesday, June 25, 2013 ID_Number: 0832-0012 Page 2

Source

Feature

Structure Component

Foundation

Material

Concrete

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
1st Flr Bay	Rectangular	Fixed	1	Metal	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
First Floor	Rectangular	Single	4-Panel	Metal	
First Floor	Rectangular	Single	4-Panel	Metal	
Notable Interior Plan)(c)	,	Notable Interior Feature(s)		

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision:
Ward/ANC:
Zoning:
Contributing:

ing: Designation Event(s)

Contributing.

Survey(s) Level(s) of Investigation

Capitol Hill H Street (2009)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_514_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_514_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_514_rear_elevation_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption

MISCELLANEOUS NOTES DATA

Notes:

1928 Sanborn: Store 1960 Sanborn: Store 1999 Sanborn: Store

PERMIT DATA

Permit Issue Date Number Type Remarks

04/03/1925 8639 Build

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
8/19/2009	Dayton (MSD), Maria	Record Updated
8/4/2009	Weishar (PJW), Paul	Record Updated
8/4/2009	Weishar (PJW), Paul	Record Created

Tuesday, June 25, 2013 ID_Number: 0832-0012 Page 4

ID Number: 0832-0018

BASICS DATA

ID Number: 0832-0018 Year Built: 1911 Data Source: **Permit** Number Extended Quad Type of Address Street 502 **H** Street Current Name(s) Type of Name Apartment Building, 502 H Street, N.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain 0832/0018 Current Square/Lot

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Apartment Building Condition: Fair

Function/Use Start Source Stop Source Explain Residential (Multi-Family) 1911 Permit Original **Dwelling & Store** Мар Historic Office/Residential Map Historic Site Visit Vacant Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1911	Permit			5000 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Arch	itect		Wenig, Juli	us
Orig Construction	Build	ler		DeLacy, E.	J.
Orig Construction	Own	er		Schreiber,	Dr. H. R.
Construction Notes:					

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0832-0018 Page 1

Surroundings:	Urban		Cross Refere	nce Notes:		
Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Intact Attached Face on Line Vertical Block Rectangular					
Number Stories: Bays Wide:	2 2					
Height:		Outbuild	ing Type	Con	ributing Status	-
Width: Depth/Length:	19 24					
SqFt: Volume:						
Lot Width Lot Depth/Length:		Outbuild	ing Notes:			
Lot SqFt:			9			
Acreage:						
Has Driveway:						
STYLE/EXTERIOR	DATA					
Architectural Style(s)						
Exterior & Architectura	al Notes:					
dentils. A blind dorn metal shingles and I brick round arch sup which is smaller tha with plywood. An up is a large opening ol sash windows with openings. The north opening has a three-segmental arch. The brick chimney exten stack that protrudes pierced by a single-l the first story, thoug segmental arches. T	he roof is covered with octaner capped by a shed roof whas a two-light, vinyl-sash supported by large, paneled in the opening. The remaining ward coiling security door by a upward coiling concrete lug sills and soldie (rear) elevation of the main course, rowlock brick segmerear ell has an irregular Amds from the northwest cornefrom the building approxime af door opening protected hit has been enclosed with the second story is pierced lek segmental arches. The felent-of-way.	vith thin colliding wind posts. The space has been go security or brick so block he had are the stately ten by an up brick. The by two, 1/2	over-hanging ndow. The file opening is occupied installed to gate. The segmental archids two, 1/1 ch while the ond brick fintack protrude feet from the ward coiling two first set/1, double-hu	eaves accentuates st story has a large now contains a sing by a single-light wip protect the door op econd story holds thes. A thin architra double-hung, viny second story has a ish and is capped the sone inch from the ground. The north security gate. A wittery openings have ung, vinyl-sash wing	the roof. The dormer is a door opening with a sol le-leaf, metal-frame glass adow and a transom covening. East of the door on one, 1/1, double-hung, voe extends above the wire-sash windows. The first two-course, rowlock bridge block and features a con (rear) elevation of the endow opening is also loc three-course, rowlock blows with concrete sills a door opening is also loc three-course, rowlock blows with concrete sills.	clad in dier s door ered pening inyl- ndow t story ck r-corner orbeled II is cated on rick and two-
	ling is located north of H St	reet, NE a	and directly f	ronts the concrete	sidewalk. The backyard h	nas been
•	concrete and is enclosed b	•	•			l l
NOTABLE FEATU	RES DATA					
Component	Feature					
EXTERIOR MATER	RIALS DATA					
Roof Component	Material	Col	or	Treatment	Source	_
Mansard (False)	Tin			Octagonal Shape		
Sloped	Not Visible			Not Visible		
Wall Component	Material	Col	or	Treatment	Source	

Tuesday, June 25, 2013 ID_Number: 0832-0018 Page 2

Stretcher Bond

Facade

Brick

Structure Component Material Source Feature **Foundation** Concrete Walls **Brick** Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Dormer	Rectangular	Sliding	2-light	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Main Door	Rectangular	Single		Metal/Glass
Notable Interior Plan	n(s)	,	Notable Interior Feature(s)	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Historic District(s) **Capitol Hill**

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s) Capitol Hill H Street (2009) Level(s) of Investigation **Permit Research**

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_502_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:



Path: C:\Users\CHRS\Documents\CHRS
Databases\H Street - 2 to 15th

St\Database\Pictures\0832\

File: H Street_502_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_502_rear_elevation_looking_S.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

1928 Sanborn Map: Office 1960 Sanborn Map: Store 1999 Sanborn Map: Dwelling

2009: Vacant

PERMIT DATA

Permit Issue Date Number Type Remarks

11/03/1911 2354 Build

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
8/4/2009	Dayton (MSD), Maria	Record Updated
8/4/2009	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0832-0018 Page 5

ID Number: 0832-0015

BASICS DATA

ID Number: 0832-0015 Year Built: 1911 Data Source: **Permit** Extended Quad Type of Address Number Street 508 **H** Street Current Name(s) Type of Name Store, 508 H Street, N.E. Common **British Ink Tattoos & Gallery** Current TaxCode1 TaxCode2 TaxCode3 Type Explain 0832/0015 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Store Condition: Good

Function/Use Start Source Stop Source Explain Retail (Furniture) 1911 Permit Original **Dwelling & Store** Map/Site V Current Store Мар Historic

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1911	Permit			6000 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Arch	itect		Germuiller,	, J.
Orig Construction	Build	ler		Yost, J.C.	
Orig Construction	Own	er		Blair, R. W.	
Construction Notes:					

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0832-0015 Page 1

Surroundings:	Urban	Cross Refe	erence Notes:		
Streetscape:	Intact]
Relate to Othr Bldgs:	Attached				
Relate to Street:	Face on Line				
Massing:	Vertical Block				
Footprint:	Rectangular				
Number Stories:	3				
Bays Wide:	2				
•	2	Outhwilding Tune	0	Contribution Ctatus	
Height:		Outbuilding Type	C	Contributing Status	-
Width:	20				
Depth/Length:	66				
SqFt:					
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes:			¬
Lot SqFt:					
Acreage:					
Has Driveway:					
					1
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Exterior & Architectur	al Notes:				
		na was constructed in 19	111 as a furnituro st	tore. The brick building is s	et on a
flush with the elevat large metal lintel. The windows with accor- arch. The third story lintels. The north (re- are two window ope story openings have sash windows with double-hung, vinyl- three-course, rowlood building has change	ion, behind the project the second story is pier in panying single-light at its fenestrated by two ear) elevation has a ceinings with concrete sit three-course, rowlock thin concrete sills and eash windows with this ck brick segmental arced, resulting in the lose	ting bay, is an upward coced by a large opening of awning windows above. 1/1, double-hung, vinylatral opening containing ills. The window opening three-course, rowlock be concrete sills and two-shes located at ground less of these window opening e first story of the rear elected.	ciling security gate, composed of three, The opening has a sash windows with a single-leaf metal is have been enclose. The second story rick segmental arcl course, rowlock brivel. It is probable tings.	sts of display windows. Loc . The first story openings sl 1/1, double-hung, wood-sa: concrete sill and vertical br a concrete sills and large, co door. Flanking the door op sed with brick. All three of t has two, 1/1, double-hung, hes. The third story holds to ick segmental arches. Of no hat the grade at the rear of	hare a sh cick flat concrete ening the first- wood- wo, 1/1, ote are the
Site Notes:					
May 2009: This build	•	-	ly fronts the concre	te sidewalk. The backyard	consists
of concrete parking	spaces serviced by a	small alley.			
NOTABLE FEATU	RES DATA				
Component	Feat	ure			
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
					-
W !! 0		6 1	-		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	

Foundation Concrete
Walls Brick

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Main Door	Rectangular	Single		Metal/Glass
Door Location	Aperture Shape	Туре	Pamels	Material
3 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
2 FIr Windows	Rectangular	Dbl-Hung	1/1 Triple	Wood
1st FIr Bay	Rectangular	Fixed	1-light	Metal
Window Location	Aperture Shape	Туре	Lights	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

9

Survey(s) Level(s) of Investigation

Capitol Hill H Street (2009) Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_508_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:



Designation Event(s)

_				
Ca	nti		n	•
υa	υu	v	11	

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_508_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_508_rear_elevation_looking_S.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

1928 Sanborn Map: Store 1960 Sanborn Map: Store 1999 Sanborn Map: Dwelling

PERMIT DATA

Permit Issue Date Number Type Remarks

08/19/1911 0933 Build

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
8/4/2009	Dayton (MSD), Maria	Record Updated
8/4/2009	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0832-0015 Page 5

ID Number: 0832-0011

BASICS DATA

ID Number: 0832-0011 Year Built: 1947 Data Source: **Permit** Extended Quad Type of Address Number Street 516 **H** Street Current Name(s) Type of Name Store/Office, 516 H Street, N.E. Common **Holyway Baptist Church** Current TaxCode1 TaxCode2 TaxCode3 Explain Type 0832/0011 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Store & Office Condition: Good

 Function/Use
 Start
 Source
 Stop
 Source
 Explain

 Store/Office
 1947
 Permit
 Original

 Church
 Site Visit
 Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1947	Permit			11000 Permit
Construction Event	Association		Associated Name		Name
Orig Construction	Arch	itect	ct Hallett, Marcus		rcus
Orig Construction	Owner			Maizels, A. J.	
Stephenson, Robert L.	Builder		Stephenson, Robert L.		
Construction Notes:					

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0832-0011 Page 1

Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street:	Intact Attached Face on Line	Cross Rete	erence Notes:		
Massing: Footprint:	Vertical Block Rectangular				
Number Stories: Bays Wide: Height:	2 2	Outbuilding Type	Co	ontributing Status	
Width: Depth/Length: SqFt: Volume: Lot Width				-	_
Lot Depth/Length: Lot SqFt: Acreage:		Outbuilding Notes:			
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Exterior & Architectura	-I Nista s				
fenestrated by 1/1, d obscured by adjoining	ouble-hung, vinyl-sas ng buildings. The first at are covered by plyv	h windows with rowlock story of the north (rear)	brick sills. The east elevation has a sing	om above. The second sto and west (side) elevation le-leaf paneled wood doo louble-hung, wood-sash v	s are r and two
Site Notes:					
				s a concrete sidewalk. It i the west. A public alley i	
NOTABLE FEATU	RES DATA				
Component	Feat	ure			
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	_
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		American Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete Bloc	k			
Walls	Concrete Bloc	k			
Materials Notes:					

Tuesday, June 25, 2013 ID_Number: 0832-0011 Page 2

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
1 Flr Windows	Rectangular	Fixed	2-light	Metal	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single	1-Panel	Wood	
Notable Interior Plan(s)		Notable Interior Feature(s)			
Interior Notes:					

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s) Level(s) of Investigation

Capitol Hill H Street (2009) Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\H Street - 2 to 15th

St\Database\Pictures\0832\

File: H Street_516_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_516_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:





Tuesday, June 25, 2013 ID_Number: 0832-0011 Page 3

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_516_rear_looking_SW.JPG

Date:: Photog:



Photo Code	Roll	Frame(s)	Date	Photographer	Caption	
-noto code	KOII	Frame(s)	Date	Filologiapher	Сарион	
MISCELLANEOUS	S NOTES I	DATA				
Notes:						
PERMIT DATA						
Permit Issue Date		Number Type		Remarks		
10/09/1947		299840 Build				
Permit Notes:						
BIBLIOGRAPHIC	DATA					
Short Citation			Туре	Date R	emarks	
Bibliographic Notes:						
	^ T^					
SIGNIFICANCE D	AIA					
SIGNIFICANCE D	NIA .					
	nia .					

DATA PROCESSING EVENTS DATA

Date	Individual	Action
8/5/2009	Dayton (MSD), Maria	Record Updated
8/4/2009	Dayton (MSD), Maria	Record Updated
8/4/2009	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0832-0011 Page 4

Resource All Data Report

ID Number: 0832-0013

BASICS DATA

ID Number: 0832-0013 Year Built: 1936 Data Source: **Permit** Number Extended Quad Type of Address Street 512 **H** Street Current Name(s) Type of Name Store, 512 H Street, N.E. Common

TaxCode1TaxCode2TaxCode3TypeExplain0832/0013Square/LotCurrent

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Store Condition: Fair

Function/Use Start Source Stop Source Explain Store 1936 Permit Original **Printing Company** Мар Historic Site Visit Vacant Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source		
Orig Construction	1936	Permit			4000 Permit		
Construction Event	Asso	ciation		Associated	Name		
Orig Construction	Arch	itect		Giles, Lewi	is W.		
Orig Construction	Build	ler		Benton & Miller			
Orig Construction	Own	er		Levy, Herb	ert		
Construction Notes:							

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0832-0013 Page 1

Surroundings:	Urban	Cross Re	ference Notes:			
Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Intact Attached Face on Line Block Rectangular					
Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume:	1 2 19 76	Outbuilding Type	Co	ontributing Status		
Lot Width Lot Depth/Length: Lot SqFt: Acreage: Has Driveway:		Outbuilding Notes	:			
STYLE/EXTERIOR	DATA					
Architectural Style(s)			_			
The brick building at metal flashing obscu western two-thirds of metal windows. Aboroof extends to the east and west (side) single-leaf metal docinfilled with concrete Site Notes: May 2009: This prop	story, two-bay building nd solid brick foundat ures the roof. Below the first the façade (south eleve the projection, is a east and covers the early elevations are obscur that is partially obsceptock.	g, designed by Lewis Wion are faced with stretche parapet wall is orname vation). It is made of boand of one-light fixed sternmost bay, which hed by adjoining buildincured by plywood. Flanknorth side of H Street, North east and 510 H Street.	cher-bond brick. A strental brickwork. A the rick and is fenestrate vinyl windows. A flat olds a single-leaf ent gs. The north (rear) exing the entry are two le. The building front	epped parapet wall to ree-sided projecting d by a band of one-lig roof caps the project ry that is covered by levation has a central window openings th	pped by bay spans the ght fixed ing bay. The plywood. The lly placed at have been	
NOTABLE FEATU	RES DATA					
Component	Feat	ure				
EXTERIOR MATER	RIALS DATA					
Roof Component	Material	Color	Treatment	Source		
Wall Component Facade	Material Brick	Color	Treatment Stretcher Bond	Source		
Structure Component Foundation Walls	Material Brick Brick	Feature		Source		
Materials Notes:						

Tuesday, June 25, 2013 ID_Number: 0832-0013 Page 2

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
1 Flr Windows	Rectangular	Fixed	1-light	Vinyl	
1st FIr Bay	Rectangular	Fixed	1-light	Metal	
Door Location	Aperture Shape	Туре	Pamels	Material	
Notable Interior Plan	n(s)		Notable Interior Feature(s)		
Interior Notes:					

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s) Level(s) of Investigation

Capitol Hill H Street (2009) Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\H Street - 2 to 15th

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_512_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\H Street - 2 to 15th

St\Database\Pictures\0832\

File: H Street_512_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_512_rear_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:



ı	P	Н	1	١	۲,	1	S	-	R	Λ	۸	•		E)	N	0	N	Ш	n	i	2	IT	ri	7	F	г	۱
ı	г	п	ľ	,	ı۷	•	J	_	D	•	w		u	'n	•	IV	u	ın		ט	ĸ	J		ш	_	.⊏	L	,

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

1960 Sanborn Map: Printing

PERMIT DATA

Permit Issue Date Number Type Remarks

04/10/1936 189836 Build

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date Individual Action

8/4/2009 Dayton (MSD), Maria Record Updated

8/4/2009 Dayton (MSD), Maria Record Created

Resource All Data Report

ID Number: 0832-0014

BASICS DATA

ID Number: 0832-0014 Year Built: 1910 Data Source: **Permit** Quad Type of Address Number Extended Street 510 **H** Street Current Type of Name Name(s) Single Dwelling, 510 H Street, N.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain 0832/0014 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Renovated

Desig. Status: Historic Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain

Dwelling & Store Map Historic

Office & Vacant Site Visit Current

Residential (Single-Family) Permit Original

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Alteration post 1999 Map/Site

Visit

Orig Construction 1910 Permit 4000 Permit

 Construction Event
 Association
 Associated Name

 Orig Construction
 Architect
 Howser, W. Edgar

 Orig Construction
 Builder
 Schaffert, Henry

 Orig Construction
 Owner
 Phillips, Samuel L.

Construction Notes:

A one-and-one-half-story addition was constructed to heighten the existing building post 1999.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0832-0014 Page 1

Surroundings:	Urban	Cross Refe	erence Notes:		
Streetscape:	Intact				
Relate to Othr Bldgs:	Attached				
Relate to Street:	Face on Line				
Massing:	Vertical Block				
Footprint:	Rectangular				
Number Stories:	3.5				
Bays Wide:	3				
Height:		Outbuilding Type	С	ontributing Status	
Width:					
Depth/Length:					
SqFt:					
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes:			
Lot SqFt:					
Acreage:					
Has Driveway:					
STYLE/EXTERIOR	R DATA				
Architectural Style(s)					
Exterior & Architectur	al Notes				
		ar W. Howeer, was const	ructed in 1910 by H	lenry Schaffert to be used as	. 2
metal door, a double metal door and two The one-and-one-ha third story is fenested deck to rest on top was not clearly visile	e-leaf metal door and one-light fixed metal values and start and story roof.	a one-light fixed window of windows. s the entire façade. It is cl pht metal windows. The up The deck features a wood façade. The north (rear) of	on the first story. T lad in metal sheets oper half-story is re d balustrade with h	rear) elevation features a single he second story has a single. The roof is not clearly visite eessed, leaving room for a norizontal balusters. Fenestrigle-leaf metal door, a one-lig	e-leaf ole. The rooftop ration
				nts a concrete sidewalk. It is to the west. A public alley is	
NOTABLE FEATU	RES DATA				
Component	Fea	ture			
<u> </u>					
EXTERIOR MATE	RIALS DATA				
Poof Comparant	Matarial	Color	Tractmast	Course	
Roof Component	Material	Color	Treatment	Source	
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		
Facade (Upper)	Metal		Siding		
Structure Component	t Material	Feature		Source	
Foundation	Concrete	i catule		Oouloe	
Walls	Brick				
**aii5	DITCK				

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 FIr Windows	Rectangular	Fixed	1-light	Metal
2 Flr Windows	Rectangular	Fixed	1-light	Metal
3 FIr Windows	Rectangular	Fixed	2-light	Metal
Door Location	Aperture Shape	Туре	Pamels	Material
First Floor	Rectangular	Single		Metal
First Floor	Rectangular	Single		Metal/Glass
Notable Interior Plan	n(s)		Notable Interior Feature(s)	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Historic District(s) **Capitol Hill**

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation **Permit Research**

Capitol Hill H Street (2009)

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

C:\Users\CHRS\Documents\CHRS Path:

> Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_510_facade_looking_NE.JPG

Date:: Photog:

Fr: Code:: R:

Caption:

C:\Users\CHRS\Documents\CHRS Path:

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_510_facade_looking_NW.JPG

Date:: Photog:

Fr: Code:: R:





Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_510_rear_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

1928 Sanborn Map: Store 1960 Sanborn Map: Store

PERMIT DATA

Permit Issue Date Number Type Remarks

07/13/1910 0213 Build

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

DateIndividualAction8/5/2009Dayton (MSD), MariaRecord Updated8/5/2009Dayton (MSD), MariaRecord Created

Resource All Data Report

ID Number: 0832-0019

BASICS DATA

ID Number:	0832-	0019	Year Built:	1916	Da	ta Source:	Permit
Number Exte	ended	Street			Qua	d Type of Add	dress
500		H Street			NE	Current	
801		5th Street			NE	Alternate	
Name(s)				Type of	Name)	
Single Dwellin	ng, 500	H Street, N.E.		Comm	on		
The Language	Docto	's		Curren	t		
Nouveau Fleu	r Floris	t		Curren	t		
TaxCode1 Ta	axCode2	TaxCode3	Туре	Explair	า		
0832/0019			Square/Lot	Curre	nt		

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: **Historic** Quality:

Purpose: Residential Condition: Excellent

Function/Use Start Source Explain Stop Source Residential (Single-Family) 1916 Permit Original Residential (Multi-Family) Map Historic Residential/Offices Site Visit Current Store Мар Historic

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1916	Permit			9100 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Arch	itect		Wenig, Juli	us
Orig Construction	Build	ler		Wahl, Henr	у
Orig Construction	Own	er		Schreiber,	Dr. H. R.
Construction Notes:					

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0832-0019 Page 1

Surroundings:	Urban	Cross Re	ference Notes:		
Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Intact Attached end Face on Line Vertical Block Rectangular				
Number Stories: Bays Wide:	3 3				
Height:		Outbuilding Type	Con	tributing Status	-
Width:	19				
Depth/Length: SqFt:	50				
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes	::		
Lot SqFt:					
Acreage:					
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Exterior & Architectura	al Notes:				
stucco and an adjoin modillions caps the a metal frame. One-l second story has on windows are finishe fenestrated by one-l façade. The first stollight fixed windows concrete sills and so concrete sills and so	ning building obscures the building. The first story of ight fixed windows flank e-light fixed windows cod with concrete sills, soloight fixed windows with or y has a centrally located with concrete sills and soldier-brick flat aches. The	ne east (side) elevation the façade has a cuthe door. The windown mplimented by singledier-brick arches with single-leaf, metal doubledier-brick flat arche outer bays are doreystones and impos	on. A flat roof with an of entrally placed entry hows have concrete sills e-light, round-arched who concrete keystones a lest (side) elevation has lor with fanlight. The fies. The second story honated by large, two-lits. The north (rear) elevation entre who have the second story honated by large, two-lits. The north (rear) elevations with a levation with the second story honated by large, two-lits.	(rear) elevation is covered by the coverhanging cornice with colding a single-leaf glass and soldier-brick flat achy windows above. The second imposts. The third stop is fenestration consistent for the consistent of the constant windows as one-light, fixed windows ght, round-headed window vation, which is covered intal door.	blocked door in nes. The and story ory is with the e one- ws with ows with
	lewalk on its south (front			nd 5th Street, NE. The buil is located to the north. Th	_
NOTABLE FEATU	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	-
Flat	Not Visible				
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				

Tuesday, June 25, 2013 ID_Number: 0832-0019 Page 2

Walls

Brick

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
1 Flr Windows	Rectangular	Fixed	1	Vinyl	
2 Flr Windows	Round-Headed	Fixed	2-light	Vinyl	
3 FIr Windows	Rectangular	Fixed	1	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single		Metal/Glass	

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s)
Capitol Hill H Street (2009)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_500_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_500_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:





Ca	

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_500_side_looking_E.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0832\

File: H Street_500_side_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

1928 Sanborn: Apartments 1960 Sanborn: Store

PERMIT DATA

Permit Issue Date Number Type Remarks

03/27/1916 4036 Build

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
8/5/2009	Weishar (PJW), Paul	Record Updated
8/5/2009	Weishar (PJW), Paul	Record Created

Tuesday, June 25, 2013 ID_Number: 0832-0019 Page 5

Tuesday, June 25, 2013 ID_Number: 0832-0019 Page 6