

Resource All Data Report

ID Number: 0833-0816

BASICS DATA

ID Number: **0833-0816** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

731 **5th Street** **NE** **Current**

Name(s) Type of Name

Single Dwelling, 731 5th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0816 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1897** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1897** **Permit** **3000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Gladden, C.H.**

Orig Construction **Builder** **Gladden, C.H.**

Orig Construction **Owner** **Twohy, John**

Construction Notes:

Constructed with 729 5th Street, N.E. from the same permit (#0638).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **34**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1897 by C.H. Gladden, this two-story, two-bay Queen Anne-style single-family dwelling was constructed from the same permit (#0638) as 729 5th Street, N.E. The dwelling is constructed of five-course, American-bond brick and is set on a solid, raised brick and concrete foundation. The façade (west elevation) is faced with pressed stretcher-bond brick. A stone watertable spans the façade and is located above the foundation. Concrete string courses travel across the façade below the first and second story window openings and above the second story window openings. Additionally, a stringcourse bisects the first story window openings. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard is covered with asphalt shingles. A molded cornice and corbeled brick cornice complement the roof. The southernmost bay of the first story holds a single-leaf paneled wood door and a one-light wood transom. A stone lintel tops the transom. Poured concrete steps with metal hand rails provide access to this entrance. The second story opening holds a 1/1, double-hung, vinyl-sash window. A three-sided, rectangular bay projects from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the same material treatment as the main block and is original. A pyramidal roof caps the bay and is covered with asphalt shingles. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows and sliding vinyl windows. All windows on the façade have concrete sills and stone lintels. The north (side) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows, which have rowlock brick sills and two-course, rowlock brick segmental arches. The rear (east) elevation is pierced by 1/1, double-hung, vinyl-sash windows and a single-leaf wood door with a soldier brick flat arch. All window openings have rowlock brick sills and soldier brick flat arches.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 5th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The south (side) elevation of the dwelling is adjacent to 729 5th Street, N.E. and is sited on a level lot. A concrete alley runs parallel to the north (side) elevation of the dwelling. The front yard is covered with wood chips and is landscaped with a mature tree. Chain-link metal fencing bounds the front yard. A concrete walkway leads from the primary entrance and ends at the sidewalk. The rear yard is covered with gravel and is edged by chain-link metal fencing.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Asphalt		Shingled	
Pyramidal	Asphalt		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete & Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Rectangular	Sliding		Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **731_5th_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **731_5th_Street_NE_facade_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **731_5th_Street_NE_rear_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 731_5th_Street_NE_rear_looking_W.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/23/1897	0638	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0817

BASICS DATA

ID Number: **0833-0817** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

729 **5th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 729 5th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0817 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1897** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1897** **Permit** **3000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Gladden, C.H.**

Orig Construction **Builder** **Gladden, C.H.**

Orig Construction **Owner** **Twohy, John**

Construction Notes:

Constructed with 731 5th Street, N.E. from the same permit (#0638).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **34**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1897 by C.H. Gladden, this two-story, two-bay Queen Anne-style single-family dwelling was constructed from the same permit (#0638) as 731 5th Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick and concrete foundation. The façade (west elevation) is faced with pressed stretcher-bond brick. A stone watertable spans the façade and is located above the foundation. Concrete string courses travel across the façade below the first and second story window openings and above the second story window openings. Additionally, a stringcourse bisects the first story window openings. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard is covered with rubber shingles. A molded cornice and corbeled brick cornice complement the roof. The southernmost bay of the first story holds a single-leaf paneled wood door with lights and a one-light wood transom. A stone lintel tops the transom. Poured concrete steps with metal hand rails provide access to this entrance. A single-leaf wood door pierces the foundation and is located beneath the primary entrance. The second story opening holds a 1/1, double-hung, vinyl-sash window. A three-sided, rectangular bay projects from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the same material treatment as the main block and is original. A pyramidal roof caps the bay and is covered with rubber shingles. The second story of the bay features corbeled corners. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows and sliding vinyl windows. The central opening of the first story holds a one-light fixed vinyl window. All windows on the façade have concrete sills and stone lintels. The rear (east) elevation is pierced by 1/1, double-hung, vinyl-sash windows, which have rowlock brick sills and two-course, rowlock brick segmental arches.

A two-story ell extends from the southernmost bay of the rear elevation and is original. The ell is constructed of American-bond brick and is set on a solid foundation. A sloping roof caps the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf paneled wood door with a one-light wood transom. Metal steps provide access to the first story door. All openings have two-course, rowlock brick segmental arches and the windows also feature rowlock brick sills.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 5th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 727 and 729 5th Street, N.E. The front yard is landscaped with small trees and is bounded by chain-link metal fencing. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The grassy rear yard is also bounded by chain-link metal fencing.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Rubberized		Shingled	
Pyramidal	Rubberized		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete & Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Rectangular	Sliding		Vinyl

Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood/Glass
Notable Interior Plan(s)			Notable Interior Feature(s)	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 729_5th_Street_NE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 729_5th_Street_NE_rear_looking_W.JPG**
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/23/1897	0638	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0818

BASICS DATA

ID Number: **0833-0818** Year Built: **1911** Data Source: **Permit**

Number Extended Street Quad Type of Address

727 **5th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 727 5th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0818 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1911** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1911** **Permit** **3000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Howenstein (H.R.) Company**

Orig Construction **Builder** **Howenstein (H.R.) Company**

Orig Construction **Owner** **Howenstein (H.R.) Company**

Construction Notes:

Constructed with 725 5th Street, N.E. from the same permit (#5907).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/front porch**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **33**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

January 2010: Constructed in 1911 by H.R. Howenstein, this two-story, three-bay Classical Revival-style single-family dwelling was constructed from the same permit (#5907) as 725 5th Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (west elevation) is faced with Flemish-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof that is covered with asphalt shingles. Two pedimented dormers project from the false mansard roof and are pierced by ten-light wood windows (possibly fixed). The tympanum of each dormer features decorative molding. A prominent molded metal cornice complements the roof. The northernmost bay of the first story holds a single-leaf paneled wood door and a one-light vinyl transom. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows and feature concrete sills and lintels. A one-story, full-width porch spans the façade and is set on a brick pier foundation. A flat roof caps the porch and features overhanging eaves. Brick posts, set on the brick piers, support the roof. Metal balusters encircle the porch, which is accessed via poured concrete steps in the northernmost end bay. A foundation entrance is obscured by the porch. The rear (east) elevation is fenestrated with a single-leaf wood-frame glass door with a one-light transom and 1/1, double-hung, vinyl-sash windows. The foundation and first story openings have two-course, rowlock brick segmental arches. The first story window has a rowlock brick sill and the second story opening has a concrete sill.

A two-story ell extends from the northernmost bay of the rear elevation and is original. The ell is constructed of brick and is set on a solid foundation. A sloping roof caps the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows, paired one-light vinyl sliding windows, and a single-leaf wood-frame glass door. Metal stairs provide access to the door opening, which is topped by a concrete lintel. All window openings have rowlock brick sills and soldier brick flat arches.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 5th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 725 and 729 5th Street, N.E. The dwelling is sited on a level lot and features a grassy front yard. The yard is landscaped with mature shrubs and is bounded by a chain-link metal fence. A concrete walkway leads from the primary entrance and ends at the sidewalk. The grassy rear yard is bounded by chain-link metal fencing and wood fencing. A concrete parking space is located east of the dwelling, as is a public alley.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False) Sloped	Asphalt Not Visible		Shingled Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Flemish Bond	
Structure Component	Material	Feature		Source
Foundation Walls	Brick Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Dormer	Rectangular	Unknown	10 Lite	Wood
Facade	Rectangular	Dbi-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **727_5th_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **727_5th_Street_NE_facade_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **727_5th_Street_NE_rear_looking_W.JPG**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/20/1911	5907	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0819

BASICS DATA

ID Number: **0833-0819** Year Built: **1911** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

725		5th Street	NE	Current
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

Single Dwelling, 725 5th Street, N.E.	Common
--	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0833/0819			Square/Lot	Current
------------------	--	--	-------------------	----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1911	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Orig Construction	1911	Permit			3000 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Architect	Howenstein (H.R.) Company
--------------------------	------------------	----------------------------------

Orig Construction	Builder	Howenstein (H.R.) Company
--------------------------	----------------	----------------------------------

Orig Construction	Owner	Howenstein (H.R.) Company
--------------------------	--------------	----------------------------------

Construction Notes:

Constructed with 727 5th Street, N.E. from the same permit (#5907).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Face on Setback Line**
Massing: **Vertical Box/flat front**
Footprint: **L-Shaped**

Cross Reference Notes:



Number Stories: **2 plus basement**
Bays Wide: **3**

Height:
Width: **17**
Depth/Length: **33**

Outbuilding Type

Contributing Status

Garage

SqFt:
Volume:
Lot Width
Lot Depth/Length:
Lot SqFt:
Acreage:
Has Driveway: ☐

Outbuilding Notes:

January 2010: A one-story, one-bay garage is located east of the dwelling and was constructed c. 1925. Noted on the 1928 Sanborn map, the garage is constructed of five-course, American-bond brick and is set on a solid brick foundation. A sloping roof caps the garage. The primary opening on the façade (east elevation) has been partially enclosed with T-111 siding and is topped by a metal lintel. A roll-up paneled metal door pierces the east elevation.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

January 2010: Constructed in 1911 by H.R. Howenstein, this two-story, three-bay Classical Revival-style single-family dwelling was constructed from the same permit (#5907) as 727 5th Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (west elevation) is faced with Flemish-bond brick that has been painted. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof that is covered with octagonal-shaped slate shingles. Two pedimented dormers project from the false mansard roof and are pierced by ten-light wood windows (possibly fixed). The tympanum of each dormer features decorative molding. A prominent molded metal cornice with scrolled modillions complements the roof. The foundation is pierced by a single-leaf wood-frame glass door. The southernmost bay of the first story holds a single-leaf replacement paneled wood door with lights and a one-light wood transom. A concrete lintel tops the transom. Brick steps with brick wing walls provide access to the primary entrance. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows and feature concrete sills and lintels. The original one-story, full-width porch has been removed from the façade. The rear (east) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows, which have concrete sills and two-course, rowlock brick segmental arches.

A two-story ell extends from the southernmost bay of the façade and is original to the main block. The ell is constructed of five-course, American-bond brick and is set on a solid foundation. A sloping roof caps the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows, which feature concrete sills and two-course, rowlock brick segmental arches.

A two-story, full-width enclosed porch extends from the rear elevation of the ell and was constructed c. 1925. The enclosed porch is wood-frame construction and is parged. A sloping roof caps the enclosed porch. Visible fenestration consists of double-leaf wood-frame glass doors flanked by one-light fixed windows.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 5th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 723 and 727 5th Street, N.E. The dwelling is sited on a level lot. The front yard is landscaped with mature shrubs and features a brick walkway leading from the sidewalk to the primary entrance. Hairpin and picket metal fencing bounds the front yard. The rear yard is edged by wood fencing.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Mansard (False) Sloped	Slate Not Visible		Shingled Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Flemish Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Dormer	Rectangular	Unknown	10 Lite	Wood
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single	Full Glass	Wood
Main Door	Rectangular	Single	Paneled	Wood/Glass
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 725_5th_Street_NE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 725_5th_Street_NE_facade_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 725_5th_Street_NE_garage_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 725_5th_Street_NE_rear_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/20/1911	5907	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0804

BASICS DATA

ID Number: **0833-0804** Year Built: **1913** Data Source: **Permit**

Number Extended Street Quad Type of Address

723 **5th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 723 5th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0804 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1913** **Permit** **Original**

Residential (Multi-Family) **Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Rear Addition **c. 1925** **Site Visit/Map**

Orig Construction **1913** **Permit** **3500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Jouvenal, A.H.**

Orig Construction **Builder** **Durity, James R.**

Orig Construction **Owner** **Durity, James R.**

Construction Notes:

--

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Face on Setback Line**
Massing: **Vertical Box/front porch**
Footprint: **L-Shaped**

Cross Reference Notes:



Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **20**

Depth/Length: **34**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Garage

Outbuilding Notes:

January 2010: A one-story, two-bay garage is located east of the dwelling and was constructed c. 1925. The garage was originally two stories and has been partially reconstructed with concrete blocks. The garage is constructed of five-course, American-bond brick and concrete blocks and is set on a solid, parged foundation. A sloping roof caps the garage. The façade (east elevation) is clad with T-111 siding and is pierced by a single-leaf paneled metal door and a roll-up paneled vinyl door. A one-story porch is located on the west elevation and has a shed roof. The roof is supported by metal posts.

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

January 2010: Constructed in 1913 by James R. Durity, this two-story, three-bay Colonial Revival-style single-family dwelling was also influenced by the Craftsman style. The dwelling was constructed from permit #5282. The dwelling is constructed of brick and is set on a solid concrete foundation. The façade (west elevation) has been faced with coursed stone. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof that is covered with tiles. The false mansard is set between stepped firewalls that are faced with stone. A denticulated cornice and prominent overhanging eave with exposed rafter ends finish the roof. The southernmost bay of the first story holds a single-leaf replacement paneled wood door with lights. Diamond-light wood sidelights and transom highlight the opening. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows and feature stone sills. The second story openings are topped by a continuous string course of concrete. A one-story, two-bay porch spans the façade and is set on a foundation of stone-faced piers. The flat roof has overhanging eaves with dentil molding and is supported by fluted Ionic columns with angled capitals. Metal balusters encircle the porch, which is accessed via stone steps with stone wing walls in the southernmost end bay. The basement-level entry was obscured by the porch. The rear (east) elevation is pierced by 1/1, double-hung, vinyl-sash windows, which feature three-course, rowlock brick segmental arches.

A two-story ell extends from the northernmost bay of the rear elevation and is original to the main block. The ell is constructed of brick and is set on a solid foundation. An interior-side brick chimney rises from the south elevation and has a parged cap. A sloping roof caps the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows.

A two-story, full-width enclosed porch is located on the rear elevation of the ell and was constructed c. 1925. Noted on the 1928 Sanborn map, the wood-frame enclosed porch is clad with T-111 siding and is capped by a sloping roof. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows, one-light vinyl casement windows, a garden window, single-leaf doors and a single-leaf wood-frame glass door.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 5th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 719 and 725 5th Street, N.E. The front yard is landscaped with mature shrubs and foundation plantings and is bounded by a hairpin and picket metal fence. A concrete walkway leads from the primary entrance and terminates at the sidewalk. The rear yard is bounded by wood fencing.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False) Sloped	Unknown Not Visible		Tile Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Stone		Veneer	
Structure Component	Material	Feature		Source
Foundation Walls	Concrete Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood/Glass

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **723_5th_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 723_5th_Street_NE_facade_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 723_5th_Street_NE_garage_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 723_5th_Street_NE_rear_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/05/1913	5282	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0803

BASICS DATA

ID Number: **0833-0803** Year Built: **1908** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

719		5th Street	NE	Current
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

Apartment Building, 719 5th Street, N.E.	Common
Union Park Condominium	Current

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0833/0803			Square/Lot	Current
------------------	--	--	-------------------	----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Apartment Building** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Multi-Family)	1908	Permit			Original
-----------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi Condo)					Current
----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Orig Construction	1908	Permit			6000 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Architect	Hunter & Bell
--------------------------	------------------	--------------------------

Orig Construction	Builder	Lockwood, W.P.
--------------------------	----------------	-----------------------

Orig Construction	Owner	Drown, Mary B.
--------------------------	--------------	-----------------------

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Face on Setback Line**
Massing: **Vertical Block**
Footprint: **T Shape P**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **40**

Depth/Length: **25**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1908 by W.P. Lockwood, this two-story, three-bay Queen Anne-style apartment building was constructed from permit #4126 and contained four apartments. The building is constructed of brick and is set on a solid concrete foundation. The façade (west elevation) is faced with pressed stretcher-bond brick. Two-course, stretcher-bond brick string courses span the façade and are located below the first and second story window openings. A sloping roof caps the building and is fronted along the façade by a prominent molded cornice with scrolled modillions and dentil molding. The first story central opening holds a single-leaf metal-frame glass door. The door is flanked by two-light metal sidelights and a three-light metal transom. A gauged brick segmental arch with molded brick and concrete keystone highlights the opening. The second story opening holds a 1/1, double-hung, wood-sash window, which has a concrete sill and lintel. Three-sided, canted bays extend from the end bays of the façade and rise the full height of the dwelling. Each bay is original to the main block and has the same material treatment. False pyramidal roofs, covered with cove-shaped slate shingles, cap each bay. Fenestration consists of 1/1, double-hung, wood-sash windows, which feature concrete sills and lintels. The rear (east) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows with two-course, rowlock brick segmental arches.

A two-story, four-bay block extends from the center of the rear elevation and is original. The block is constructed of five-course, American-bond brick and is set on a solid foundation. A sloping roof caps the block. Identical two-story canted bays project from the north and south elevations of the block and are original. The rear elevation is fenestrated with 1/1, double-hung, wood-sash windows and single-leaf paneled wood doors with lights. All openings have two-course, rowlock brick segmental arches and the windows feature rowlock brick sills. A two-story, full-width porch projects from the rear elevation of the block and has a shed roof. Square wood posts support the porch. The second story is encircled by square wood balusters and is accessed via a dog-leg wood stairway.

Site Notes:

January 2010: This apartment building is located on the east side of 5th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The building is adjacent to 717 and 723 5th Street, N.E. and is sited on a level lot. The front yard is landscaped with mature shrubs, small trees, and foundation plantings. A hairpin and picket metal fence encloses the yard, which is bisected by a concrete walkway which leads to the primary entrance. The rear yard is edged by wood fencing. Parking spaces and a public alley are located east of the building.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Pyramidal	Slate		Shingled	
Sloped	Not Visible		Not Visible	

Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	

Structure Component	Material	Feature	Source
Foundation	Brick		
Walls	Concrete		

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1	Wood

Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Full Glass	Metal

Notable Interior Plan(s) _____ Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s) _____
Subdivision: _____	
Ward/ANC: _____	
Zoning: _____	Designation Event(s) _____
Contributing: _____	
Survey(s) _____	Level(s) of Investigation _____
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **719_5th_Street_NE_facade_looking_NE.JPG**

Date:: _____ Photog: _____

Code:: _____ R: _____ Fr: _____



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 719_5th_Street_NE_facade_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 719_5th_Street_NE_rear_looking_W.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/23/1908	4126	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0802

BASICS DATA

ID Number: **0833-0802** Year Built: **1921** Data Source: **Permit**

Number Extended Street Quad Type of Address

717 **5th Street** **NE** **Current**

Name(s) Type of Name

Single Dwelling, 717 5th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0802 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1921** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Rear Addition **c. 1970** **Site Visit/Map**

Orig Construction **1921** **Permit** **4000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Williams, L.T.**

Orig Construction **Builder** **Howenstein (H.R.) Company**

Orig Construction **Owner** **King, H.R.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Attached**
 Relate to Street: **Face on Setback Line**
 Massing: **Vertical Box/front porch**
 Footprint: **L-Shaped**

Cross Reference Notes:



Number Stories: **2**
 Bays Wide: **3**

Height: **20**
 Width: **35**
 Depth/Length: **35**

SqFt:
 Volume:
 Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Garage

Outbuilding Notes:

January 2010: A two-story, one-bay garage is located east of the dwelling and was constructed c. 1925. The garage is constructed of seven-course, American-bond brick and is set on a solid brick foundation. A sloping roof caps the garage and is pierced by an interior-side brick chimney with a corbeled brick cap, which is located on the south (side) elevation. The original garage opening on the first story of the façade (east elevation) has been partially enclosed with German vinyl siding. The opening now contains a roll-up paneled vinyl door and a single-leaf paneled metal door. The second story of the façade is pierced by a single-leaf paneled metal door and 1/1, double-hung, vinyl-sash windows. The central and northernmost bays of the second story are topped by two-course, rowlock brick segmental arches.

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

January 2010: Constructed in 1921 by H.R. Howenstein, this two-story, three-bay Colonial Revival-style single-family dwelling was also influenced by the Craftsman style. The dwelling was constructed from permit #8145. The dwelling is constructed of brick and is set on a solid concrete foundation. The façade (west elevation) is faced with five-course, American-bond brick. A string course, composed of basket weave-bond brick, spans the façade and is located above the second story window openings. An interior brick chimney with a corbeled brick cap pierces the roof. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof covered with slate shingles. A prominent overhanging eave with exposed rafter ends finishes the false mansard roof. A shed dormer pierces the false mansard and is fenestrated with paired six-light wood awning windows. A shed roof, covered with slate shingles, caps the dormer and features overhanging eaves and exposed rafter ends. The southernmost bay of the first story holds a single-leaf paneled wood door with lights and a one-light wood transom. The first story window openings contain 1/1, double-hung, vinyl-sash windows with false 6/1 vinyl muntins. The second story openings contain 1/1, double-hung, vinyl-sash windows. All window openings have concrete sills. A one-story, two-bay porch spans the façade and is set on a brick pier foundation. The flat roof of the porch features overhanging eaves and is supported by brick posts set on the brick piers. Metal balusters encircle the porch which is accessed via poured concrete steps in the southern end bay. The foundation of the façade is fenestrated with a single-leaf door and a 1/1, double-hung, vinyl-sash window with false 6/1 vinyl muntins.

A two-story enclosed porch extends from the rear (east) elevation of the dwelling and was constructed c. 1970. The wood-frame enclosed porch is clad with plywood and is capped by a shed roof with exposed rafter ends. The first story is fenestrated with a single-leaf paneled wood door and 6/1, double-hung, wood-sash windows. The second story is pierced by paired 1/1, double-hung, wood-sash windows.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 5th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 715 and 719 5th Street, N.E. The grassy front yard is landscaped with mature shrubs. Hairpin and picket metal fencing encloses the front yard, which is accessed via a concrete walkway from the sidewalk. The rear yard is enclosed with wood fencing. A public alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False) Sloped	Slate Not Visible		Shingled Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation Walls	Concrete Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Dormer	Rectangular	Awning	6 Lite/dbl	Wood
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood/Glass

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 717_5th_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 717_5th_Street_NE_facade_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 717_5th_Street_NE_garage_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 717_5th_Street_NE_garage_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 717_5th_Street_NE_rear_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/24/1921	8145	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0801

BASICS DATA

ID Number: **0833-0801** Year Built: **1913** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

715		5th Street	NE	Current
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

Single Dwelling, 715 5th Street, N.E.	Common
--	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0833/0801			Square/Lot	Permit
------------------	--	--	-------------------	---------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1913	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Rear Addition	c. 1980	Site Visit/Map			
----------------------	----------------	-----------------------	--	--	--

Orig Construction	1913	Permit			3000 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Architect	Howenstein (H.R.) Company
--------------------------	------------------	----------------------------------

Orig Construction	Builder	Howenstein (H.R.) Company
--------------------------	----------------	----------------------------------

Orig Construction	Owner	Howenstein (H.R.) Company
--------------------------	--------------	----------------------------------

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Face on Setback Line**
Massing: **Vertical Box/front porch**
Footprint: **L-Shaped**

Cross Reference Notes:



Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **20**

Depth/Length: **40**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Garage

Outbuilding Notes:

January 2010: A one-story, one-bay garage is located east of the dwelling and was constructed c. 1925. The garage is constructed of five-course, American-bond brick and is set on a solid brick foundation. A sloping roof caps the garage. The original opening on the façade (east elevation) has been partially enclosed with plywood. A roll-up paneled metal door with a concrete lintel pierces the façade.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

January 2010: Constructed in 1913 by H.R. Howenstein, this two-story, three-bay Classical Revival-style single-family dwelling was constructed from permit #5121. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (west elevation) is faced with five-course, American-bond brick that has been painted. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof that is covered with octagonal-shaped rubber shingles. Two pedimented dormers project from the false mansard roof and are pierced by ten-light wood windows (possibly fixed). The tympanum of each dormer features decorative fleur-de-lis molding. A prominent molded metal cornice with scrolled modillions complements the roof. The foundation is pierced by a single-leaf paneled wood door with lights and a 6/6, double-hung, wood-sash window. The southernmost bay of the first story holds a single-leaf paneled wood door with lights and a stained glass wood transom. A concrete lintel tops the transom. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows and feature concrete sills and lintels. A one-story, two-bay porch spans the façade and is set on a brick pier foundation that has been infilled with brick. The flat roof of the porch has overhanging eaves with modillions and egg-and-dart molding and is supported by brick posts. Metal balusters encircle the porch, which is accessed via poured concrete steps with metal hand rails in the southernmost end bay. The foundation of the porch is pierced with paired one-light windows (possibly awning). The rear (east) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows, which have concrete sills and two-course, rowlock brick segmental arches. A two-story, canted bay extends from the northernmost bay of the rear (east) elevation and is original. The bay has the same material treatment as the main block and is fenestrated with 1/1, double-hung, vinyl-sash windows. These windows have concrete sills and two-course, rowlock brick segmental arches.

A second story enclosed porch projects from the southernmost bay of the rear elevation and was constructed c. 1980. The enclosed porch is faced with wood paneling and is capped by a sloping roof with scrolled modillions. Square, paneled wood posts support the second story enclosed porch. Fenestration consists of 1/1, double-hung, vinyl-sash windows with false 4/1 vinyl muntins.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 5th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 713 and 717 5th Street, N.E. and is sited on a level lot. The grassy front yard is bounded by a low, concrete retaining wall and hairpin and picket metal fencing. A brick walkway leads from the primary entrance and ends at the sidewalk. The rear yard is bound by fencing. A public alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Basemt Windows	Rectangular	Dbl-Hung	6/6	Wood
Dormer	Rectangular	Unknown	10 Lite	Wood
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single	Paneled	Wood/Glass
Main Door	Rectangular	Single	Paneled	Wood/Glass

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 715_5th_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 715_5th_Street_NE_facade_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 715_5th_Street_NE_garage_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 715_5th_Street_NE_rear_looking_W.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/25/1913	5121	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0040

BASICS DATA

ID Number: **0833-0040** Year Built: **1903** Data Source: **Permit**

Number Extended Street Quad Type of Address

713 **5th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 713 5th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0040 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1903** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1903** **Permit** **2500 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Burn, James D.**

Orig Construction **Owner** **Ackman, Minnie**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1903 by James D. Burn, this two-story, two-bay Queen Anne-style single-family dwelling was built from permit #1197. The dwelling is constructed of brick and is set on a solid concrete and brick foundation. The façade (west elevation) is faced with five-course, American-bond brick. A three-course, stretcher-bond brick watertable is located above the foundation. Two-course, stretcher-bond brick courses span the façade and are located beneath the first and second story window openings. A sloping roof caps the dwelling and is fronted along the façade by an ogee-molded metal cornice and a corbeled brick cornice. The northernmost bay of the façade holds a single-leaf, replacement paneled metal door with lights and a one-light wood transom. A concrete lintel tops the transom. Cast iron steps and railings provide access to the primary entrance. The second story opening holds a 1/1, double-hung, vinyl-sash windows. A three-sided, rectangular bay extends from the southernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is original. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. All window openings on the façade have concrete sills and lintels. The foundation is pierced by window openings that have been boarded with wood. The rear (east) elevation is pierced by 1/1, double-hung, vinyl-sash windows, which have concrete sills and two-course, rowlock brick sills.

A two-story ell extends from the northernmost bay of the rear elevation and is original. The ell is constructed of five-course, American-bond brick and is set on a solid brick foundation. A sloping roof caps the ell and is pierced by an interior-side brick chimney. Visible fenestration consists of a single-leaf paneled metal door and 1/1, double-hung, vinyl-sash windows, which have concrete sills and two-course, rowlock brick segmental arches. A wood deck extends from the rear elevation of the ell.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 5th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The north (side) elevation of the dwelling is adjacent to 715 5th Street, N.E. The front yard is landscaped with mature shrubs and wood chips and is encircled by hairpin and picket metal fencing. A concrete walkway leads from the primary entrance and ends at the sidewalk. The grassy rear yard is bounded by milled point metal fencing.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete & Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Segmental-Arched	Unknown	Boarded	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Metal/Glas

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **713_5th_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **713_5th_Street_NE_facade_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **713_5th_Street_NE_rear_looking_W.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 713_5th_Street_rear_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

01/28/1903	1197	Build	
------------	------	-------	--

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0044

BASICS DATA

ID Number: **0833-0044** Year Built: **1903** Data Source: **Permit**

Number Extended Street Quad Type of Address

711 **5th Street** **NE Current**

Name(s) Type of Name

Multiple Dwelling, 711 5th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0044 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multi-Family) **1903** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1903** **Permit** **4100 Permit**

Construction Event Association Associated Name

Ettinger, L.B. **Builder** **Ettinger, L.B.**

Orig Construction **Owner** **Sickel, Charles A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Freestanding**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **19**

Depth/Length: **55**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1903 by L.B. Ettinger, this two-story, two-bay Queen Anne-style multiple dwelling was constructed from permit #2052. The dwelling is constructed of five-course, American-bond brick and is set on a solid brick and stone foundation. The façade (west elevation) is faced with pressed stretcher-bond brick. Two-course, stretcher-bond brick string courses span the façade and are located below the first and second story window openings. A sloping roof caps the dwelling and is pierced by an interior-side brick chimney, which rises from the south (side) elevation and has a corbeled brick cap. A clerestory rises above the molded cornice and is constructed of brick. Fenestration consists of a one-light fixed wood window. The northernmost bay of the façade holds double-leaf wood-frame glass doors, which are topped by a one-light wood transom and stone lintel. Poured concrete steps with brick wing walls provide access to the primary entrance. The second story opening contains a 1/1, double-hung, wood-sash window. A three-sided, rectangular bay projects from the southernmost bay of the façade and is original. The bay has the same material treatment as the main block. A molded cornice complements the roof. A clerestory rises above the bay and is constructed of brick and is capped by a pyramidal roof. A molded cornice and frieze board with decorative molding finish the roof. The clerestory is pierced by one-light fixed wood windows. The bay is fenestrated with 1/1, double-hung, wood-sash window and one-light wood awning windows. All window openings have concrete sills and stone lintels. Recessed brick panels are located above the second story windows of the bay. The south (side) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows with false 2/2 vinyl muntins, which have two-course, rowlock brick segmental arches and rowlock brick sills. The rear (east) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows and single-leaf wood-frame glass doors with one-light wood transoms. All openings have two-course, rowlock brick segmental arches and rowlock brick sills. A two-story porch extends from the rear elevation and is capped by a shed roof. Square wood posts support the roof. Square wood balusters encircle the second story of the porch, which is accessed by wood steps.

Site Notes:

January 2010: This multiple dwelling is located on the east side of 5th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The free-standing dwelling is sited on a level lot and features a grassy front yard. A stone walkway leads from the primary entrance and terminates at the concrete sidewalk. The rear yard is enclosed with chain-link metal fencing. A public alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Pyramidal Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Awning	1-light	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1	Wood
Clerestory	Rectangular	Fixed	1-light	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Double	Full Glass	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **711_5th_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **711_5th_Street_NE_facade_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **711_5th_Street_NE_rear_looking_W.JPG**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/22/1903	2052	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0043

BASICS DATA

ID Number: **0833-0043** Year Built: **1903** Data Source: **Permit**

Number Extended Street Quad Type of Address

500 **G Street** **NE** **Current**

Name(s) Type of Name

Rowhouse, 500 G Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0043 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multi-Family) **1903** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Rear Addition **c. 1920** **Site Visit/Map**

Orig Construction **1903** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Ettinger, L.B.**

Orig Construction **Owner** **Sickel, Charles A.**

Construction Notes:

One of three rowhouses constructed from the same permit (#2051).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row Corner (1 of 3)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Canted Bay**
Footprint: **Rectangular**

Cross Reference Notes:



Number Stories: **2 plus 3-story tower**

Bays Wide: **2**

Height:

Width: **23**

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Garage

Outbuilding Notes:

January 2010: A one-story, one-bay garage is located north of the dwelling and was constructed c. 1925. The garage is noted on the 1928 Sanborn Fire Insurance map and is accessed from 5th Street, N.E. The garage is masonry construction and has been parged. A sloping roof caps the garage. The façade (west elevation) is pierced by a roll-up paneled wood door with lights.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1903 by L.F. Ettinger, this two-story, two-bay Queen Anne-style multi-family rowhouse was also influenced by the Classical Revival style. The dwelling is one of three rowhouses constructed from the same permit (#2051). The dwelling is constructed of brick and is set on a solid concrete and brick foundation. The façade (south elevation) is faced with pressed stretcher-bond brick. Two-course, stretcher-bond brick string courses span the façade and west (side) elevation and are located at the level of the first and second story sills. An interior brick chimney rises from the west elevation and has a plain cap. The roofing type is obscured by a clerestory along the façade and a brick parapet along the west elevation. The clerestory is constructed of brick and is pierced by a one-light wood window topped by a stone lintel. A molded metal cornice complements the façade and west elevation and is located beneath the clerestory and parapet. The easternmost bay of the façade holds double-leaf wood-frame glass doors with a one-light wood transom. The transom is topped by a stone lintel. The second story opening holds a 1/1, double-hung, wood-sash window. A recessed brick panel is sited above the second story window. A three-sided, canted bay rises the full height of the dwelling and extends from the westernmost bay of the façade. The bay has the same material treatment as the main block and is original. A clerestory tops the bay and is capped by a pyramidal roof covered with slate shingles. A finial tops the roof. A molded metal cornice with modillions and a frieze board of decorative molding highlights the pyramidal roof. The clerestory is pierced by one-light wood windows (possibly fixed). Fenestration consists of 1/1, double-hung, wood-sash windows. All window openings on the façade have concrete sills and stone lintels. Recessed brick panels are sited above the second story windows of the bay. The west elevation is fenestrated with 1/1, double-hung, wood-sash windows and a single-leaf multi-light wood door with a one-light wood transom. All windows have concrete sills and stone lintels. Recessed brick panels are sited above all second story openings.

A two-story, full-width enclosed porch is located on the rear (north) elevation of the dwelling and was constructed c. 1920. The first story originally consisted of brick posts supporting the second story. The brick posts have been infilled with brick and single and triple 1/1, double-hung, vinyl-sash windows. The wood-frame second story is clad with vinyl siding and is capped by a shed roof. Fenestration consists of single, paired, and triple, 1/1, double-hung, vinyl-sash windows with false 4/4 vinyl muntins.

Site Notes:

January 2010: This multi-family rowhouse is located on the northeast corner of 5th Street, N.E. and G Street, N.E. and is set back approximately ten feet from the sidewalk. The east (side) elevation of the dwelling is adjacent to 502 G Street, N.E. The front and side yards are landscaped with mature trees and shrubs, as well as foundation plantings. A parged retaining wall, topped with stone and milled point metal fencing, encircles the front and side yards. A walkway leads from the primary entrance and terminates at the brick sidewalk which lines G Street, N.E.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Pyramidal	Slate		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1	Wood
Clerestory	Rectangular	Unknown	1-light	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Double	Full Glass	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**
File: **500_G_Street_NE_door_detail.JPG**
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 500_G_Street_NE_facade_looking_N.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 500_G_Street_NE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 500_G_Street_NE_garage_looking_E.JPG
Date:: Photog:
Code:: R: Fr:




Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 500_G_Street_NE_garage_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 500_G_Street_NE_Main_Door_detail.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 500_G_Street_NE_rear_looking_SE.JPG

Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 500_G_Street_NE_rear_looking_SW.JPG

Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/22/1903	2051	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0042

BASICS DATA

ID Number: **0833-0042** Year Built: **1903** Data Source: **Permit**

Number	Extended	Street	Quad Type	Type of Address
502	-502B	G Street	NE	Current
502		G Street	NE	Original

Name(s)	Type of Name
Rowhouse, 502 G Street, N.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
0833/0042			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Multi-Family)	1903	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1903	Permit			3000 Permit

Construction Event	Association	Associated Name
Ettinger, L.F.	Builder	Ettinger, L.F.
Orig Construction	Owner	Sickel, Charles A.

Construction Notes:

One of three rowhouses constructed from the same permit (#2051).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 3)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Canted Bay**
Footprint: **Rectangular**

Number Stories: **2 plus basement**
Bays Wide: **2**

Height: **23**
Width: **23**

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1903 by L.F. Ettinger, this two-story, two-bay Queen Anne-style multi-family rowhouse was also influenced by the Classical Revival style. The dwelling is one of three rowhouses constructed from the same permit (#2051). The dwelling is constructed of brick and is set on a solid concrete and brick foundation. The façade (south elevation) is faced with pressed stretcher-bond brick. Two-course, stretcher-bond brick string courses span the façade and are located at the level of the first and second story sills. The roofing type is obscured by a clerestory along the façade, which is constructed of brick and is pierced by a one-light wood window topped by a stone lintel. A molded metal cornice complements the façade and is located beneath the clerestory and parapet. The easternmost bay of the façade holds double-leaf multi-light wood doors with a one-light wood transom. The transom is topped by a stone lintel. These doors provide access to the entry foyer. Single-leaf paneled vinyl doors are located within the foyer. The second story opening holds a 1/1, double-hung, vinyl-sash window with false 9/9 vinyl muntins. A recessed brick panel is sited above the second story window. A three-sided, canted bay rises the full height of the dwelling and extends from the westernmost bay of the façade. The bay has the same material treatment as the main block and is original. A clerestory tops the bay and is capped by a pyramidal roof covered with slate shingles. A finial tops the roof. A molded metal cornice and a frieze board of decorative molding highlights the pyramidal roof. The clerestory is pierced by one-light wood windows (possibly fixed). Fenestration consists of 1/1, double-hung, vinyl-sash windows with false 9/9 and 6/6 vinyl muntins. The foundation opening contains glass blocks. All window openings on the façade have concrete sills and stone lintels. Recessed brick panels are sited above the second story windows of the bay. The rear (north) elevation is parged. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf door with a one-light transom. All fenestration is set in segmental openings.

A two-story, full-width porch spans the rear elevation and is capped by a shed roof. Square wood posts support the roof. The second story is bounded by square wood balusters and is accessed by metal stairs.

Site Notes:

January 2010: This multi-family rowhouse is located on the north side of G Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 500 and 504 G Street, N.E. and is sited on a level lot. The front yard is landscaped with mature shrubs and plantings and is bounded by a low, stone retaining wall topped with milled point metal fencing. A concrete walkway leads from the primary entrance of the dwelling and terminates at the brick sidewalk.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Pyramidal	Slate		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete & Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Fixed	multi	Glass Bloc
Clerestory	Rectangular	Unknown	1-light	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Double		Wood/Glass

Main Door Rectangular Recessed Paneled Vinyl

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **502-
502B_G_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **502-
502B_G_Street_NE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **502-502B_G_Street_NE_rear_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

06/22/1903	2051	Build	
------------	------	-------	--

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0041

BASICS DATA

ID Number: **0833-0041** Year Built: **1903** Data Source: **Permit**

Number Extended Street Quad Type of Address

504 **G Street** **NE Current**

Name(s) Type of Name

Rowhouse, 504 G Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0041 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multi-Family) **1903** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1903** **Permit** **3000 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Ettinger, L.F.**

Orig Construction **Owner** **Sickel, Charles A.**

Construction Notes:

One of three rowhouses constructed from the same permit (#2051).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 3)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Canted Bay**

Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **23**

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1903 by L.F. Ettinger, this two-story, two-bay Queen Anne-style multi-family rowhouse was also influenced by the Classical Revival style. The dwelling is one of three rowhouses constructed from the same permit (#2051). The dwelling is constructed of brick and is set on a solid concrete and brick foundation. The façade (south elevation) is faced with pressed stretcher-bond brick. Two-course, stretcher-bond brick string courses span the façade and are located at the level of the first and second story sills. The roofing type is obscured by a clerestory along the façade, which is constructed of brick and is pierced by a one-light vinyl window topped by a stone lintel. A molded metal cornice complements the façade and is located beneath the clerestory and parapet. The easternmost bay of the façade holds double-leaf wood-frame glass doors with a one-light wood transom. The transom is topped by a stone lintel. These doors provide access to the entry foyer. Single-leaf, replacement paneled wood doors with lights are located within the foyer. The second story opening holds a 1/1, double-hung, vinyl-sash window with false 2/1 vinyl muntins. A recessed brick panel is sited above the second story window. A three-sided, canted bay rises the full height of the dwelling and extends from the westernmost bay of the façade. The bay has the same material treatment as the main block and is original. A clerestory tops the bay and is capped by a pyramidal roof covered with asphalt shingles. A molded metal cornice with a frieze board of decorative molding highlights the pyramidal roof. The clerestory is pierced by one-light vinyl windows (possibly fixed). Fenestration consists of 1/1, double-hung, vinyl-sash windows with false 2/1 vinyl muntins. The foundation opening contains a one-light vinyl window (possibly awning). All window openings on the façade have concrete sills and stone lintels. Recessed brick panels are sited above the second story windows of the bay. The rear (north) elevation is parged. Visible fenestration consists of a 1/1, double-hung, vinyl-sash window, a glass block window, and a single-leaf multi-light wood door with a one-light transom. The windows and door are set in segmental openings.

A two-story, full-width porch spans the rear elevation and is capped by a shed roof. Square wood posts support the roof. The second story is bounded by square wood balusters and is accessed by wood stairs.

Site Notes:

January 2010: This multi-family rowhouse is located on the north side of G Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 502-502B and 508 G Street, N.E. The front yard is landscaped with mature shrubs and is bounded by a low, stone wall. A brick walkway leads from the primary entrance of the dwelling and ends at the brick sidewalk.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Pyramidal	Asphalt		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete & Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Unknown	1-light	Vinyl
Clerestory	Rectangular	Unknown	1-light	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Double	Full Glass	Wood

Main Door Rectangular Recessed Paneled Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **504_G_Street_NE_facade_looking_N.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **504_G_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **504_G_Street_NE_rear_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

06/22/1903	2051	Build	
------------	------	-------	--

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0809

BASICS DATA

ID Number: **0833-0809** Year Built: **1891** Data Source: **Permit**

Number Extended Street Quad Type of Address

508 **G Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 508 G Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0809 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit** **Original**

Residential (Multi-Family) **Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit** **2250 Permit**

Construction Event Association Associated Name

Orig Construction **Owner** **Carver, Frank N.**

Construction Notes:

Constructed with 510 G Street, N.E. from the same permit (#2487).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:



Outbuilding Type

Contributing Status

Shed

Outbuilding Notes:

January 2010: A one-story, one-bay prefabricated shed is located north of the dwelling and was constructed c. 1980. The wood-frame shed is clad with standing-seam metal and is capped by a front-gabled roof, also covered with standing-seam metal.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891, this two-story, two-bay Queen Anne-style single-family dwelling was constructed from the same permit (#2487) as 510 G Street, N.E. The dwelling is constructed of brick and is set on a solid brick foundation. The façade (south elevation) is faced with pressed stretcher-bond brick. A four-course, stretcher-bond brick watertable travels across the façade and is located above the foundation. The roofing type was not discernible from the public right-of-way. An interior-side brick chimney rises from the east elevation and has a corbeled brick cap. A molded cornice and dentil molding complement the roof. The foundation is pierced by a single-leaf wood door with lights. The easternmost bay of the first story contains a single-leaf paneled metal door with lights. The door is sheltered by an awning and is accessed via cast iron steps and railings. The second story opening contains a 1/1, double-hung, vinyl-sash window, which features a concrete sill and soldier brick segmental arch. A three-sided, rectangular bay extends from the westernmost bay of the façade and rises the full height of the dwelling. The bay has the same material treatment as the main block and is original. Chamfered corners with brick corbelling highlight the bay, which is capped by a pyramidal roof. The roof is covered with asphalt shingles. A molded cornice with dentil molding complements the roof. Short, molded brick pilasters flank the frieze of the bay. The bay is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows. The central bay of the first story is topped by a blind transom. All windows have concrete sills and soldier brick segmental arches. Two-course, stretcher-bond string courses span the bay and are located below the first and second story window openings. Additional brick string courses span the bay and wrap around the soldier brick segmental arches which top the central window openings. The rear (north) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows, which have wood sills. The first story openings are topped by one-light transoms.

Site Notes:

January 2010: This single-family dwelling is located on the north side of G Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 504 and 510 G Street, N.E. The front yard is bounded by metal chain-link fencing. Wood fencing edges the rear yard of the property.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible			Not Visible	
Pyramidal	Asphalt		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single		Wood/Glass
Main Door	Rectangular	Single	Paneled	Metal/Glas

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **508_G_Street_NE_facade_looking_N.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **508_G_Street_NE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **508_G_Street_NE_Shed_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Tuesday, June 25, 2013

ID_Number: 0833-0809 Page 3

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

06/05/1891	2487	Build	
------------	------	-------	--

Permit Notes:

--

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

SIGNIFICANCE DATA

Study Unit

--

Code	Criteria
------	----------

--	--

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0810

BASICS DATA

ID Number: **0833-0810** Year Built: **1891** Data Source: **Permit**

Number	Extended	Street	Quad Type of Address
510	-510.5	G Street	NE Current
510		G Street	NE Original

Name(s)	Type of Name
Single Dwelling, 510 G Street, N.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
0833/0810			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1891	Permit			Original
Residential (Multi-Family)					Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1891	Permit			2250 Permit

Construction Event	Association	Associated Name
Orig Construction	Owner	Carver, Frank N.

Construction Notes:

Constructed with 508 G Street, N.E. from the same permit (#2487)

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Face on Setback Line**
Massing: **Vertical Box/rectang bay**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type	Contributing Status
------------------	---------------------

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891, this two-story, two-bay Queen Anne-style single-family dwelling was constructed from the same permit (#2487) as 508 G Street, N.E. The dwelling is constructed of brick and is set on a solid brick foundation. The façade (south elevation) is faced with pressed stretcher-bond brick. A four-course, stretcher-bond brick watertable travels across the façade and is located above the foundation. The roofing type was not discernible from the public right-of-way. An interior-side brick chimney rises from dwelling and has a plain brick cap. A molded cornice and dentil molding complement the roof. The foundation is pierced by a single-leaf paneled wood door and is topped by a soldier brick segmental arch. The easternmost bay of the first story contains a single-leaf paneled wood door and a one-light wood transom. A gauged brick segmental arch tops the transom. The door is accessed by brick steps with metal railings. The second story opening contains a 6/6, double-hung, wood-sash window, which features a concrete sill and soldier brick segmental arch. A three-sided, rectangular bay extends from the westernmost bay of the façade and rises the full height of the dwelling. The bay has the same material treatment as the main block and is original. Chamfered corners with brick corbelling highlight the bay, which is capped by a pyramidal roof. The roof is covered with asphalt shingles. A molded cornice with dentil molding complements the roof. Short, molded brick pilasters flank the frieze of the bay. The bay is fenestrated with single and paired 6/6, double-hung, wood-sash windows and 1/1, double-hung, wood-sash windows. The central bay of the first story holds a multi-light fixed wood window. All windows have concrete sills and soldier brick segmental arches. Two-course, stretcher-bond string courses span the bay and are located below the first and second story window openings. Additional brick string courses span the bay and wrap around the soldier brick segmental arches which top the central window openings. The rear (north) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows and double-leaf multi-light wood doors. The second story openings have two-course, rowlock brick segmental arches and header brick sills. The first story openings have been altered.

Site Notes:

January 2010: This single-family dwelling is located on the north side of G Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 508 and 512 G Street, N.E. and is sited on a level lot. The front yard is landscaped with English ivy and foundation plantings. A milled point metal fence bounds the front yard. A brick walkway leads from the primary entrance and ends at the sidewalk. The rear yard is bounded by wood fencing.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Pyramidal	Asphalt		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	6/6	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	6/6	Wood
Bay Windows	Rectangular	Dbl-Hung	6/6 Double	Wood
Bay Windows	Rectangular	Fixed	Multi-lite	Wood
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single	Paneled	Wood

Main Door Rectangular Single Paneled Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: **510_G_Street_NE_cornice_detail.JPG****

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: **510_G_Street_NE_facade_detail.JPG****

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: **510_G_Street_NE_facade_looking_N.JPG****

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 510_G_Street_NE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 510_G_Street_NE_rear_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/05/1891	2487	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0028

BASICS DATA

ID Number: **0833-0028** Year Built: **1905** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

512		G Street	NE	Current
------------	--	-----------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

Rowhouse, 512 G Street, N.E.	Common
-------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0833/0028			Square/Lot	Current
------------------	--	--	-------------------	----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1905	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Orig Construction	1905	Permit			2400 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Architect	Volland, E.
--------------------------	------------------	--------------------

Orig Construction	Builder	Haislip, J. R.
--------------------------	----------------	-----------------------

Orig Construction	Owner	Boyd, Charles
--------------------------	--------------	----------------------

Construction Notes:

One of five rowhouses constructed from the same permit (#2179).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 5)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Canted Bay**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **18**

Depth/Length: **35**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1905 by J.R. Haislip, this two-story, two-bay Queen Anne-style rowhouse is one of five rowhouses constructed from the same permit (#2179). The dwelling is constructed of brick and is set on a solid concrete foundation. The façade (south elevation) is faced with pressed stretcher-bond brick. Two-course, stretcher-bond brick string courses span the façade of the dwelling and are located below the first and second story window openings. A sloping roof caps the dwelling and is fronted along the façade by a molded metal cornice with modillions and a plain frieze board. The easternmost bay of the façade holds a single-leaf metal door and a one-light wood transom. A stone lintel tops the transom. Poured concrete steps with brick wing walls provide access to the entrance. Brick balusters enclose the small stoop. The basement-level opening is sited directly below the first story entrance and contains a single-leaf wood door. The second story opening contains a 1/1, double-hung, vinyl-sash window. A three-sided, canted bay extends from the westernmost bay of the façade and rises the full height of the dwelling. The bay has the same material treatment as the main block and is original. A pyramidal roof, with a finial, caps the bay and is covered with tin shingles. A molded metal cornice with modillions and plain frieze finish the roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows. All window openings have concrete sills and stone lintels. The rear (north) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows, which have wood sills and two-course, rowlock brick segmental arches.

A two-story ell extends from the easternmost bay of the rear elevation and is original to the main block. The ell is constructed of brick and is set on a solid, raised foundation. A sloping roof caps the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows, a single-leaf paneled metal door and a single-leaf metal door. Both doors are topped by one-light transoms. A two-story, full-width porch projects from the rear elevation of the ell and is set on a square wood post foundation. A shed roof caps the porch and is supported by square wood posts. The first and second story balustrades are composed of wood sunrise motifs.

Site Notes:

January 2010: This rowhouse is located on the north side of G Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 510 and 514 G Street, N.E. and is sited on a level lot. The grassy front yard is landscaped with a mature tree and is encircled by hairpin and picket metal fencing. A concrete walkway leads from the primary entrance and ends at the sidewalk. The grassy rear yard is planted with mature shrubs and is bounded by metal chain-link fencing and wood fencing. A concrete parking space is located north of the dwelling. A public alley is also located north of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Pyramidal	Tin		Shingled	
Sloped	Not Visible		Not Visible	

Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single		Wood
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**
File: **512_G_Street_NE_facade_looking_N.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 512_G_Street_NE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 512_G_Street_NE_rear_looking_S.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/20/1905	2179	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0029

BASICS DATA

ID Number: **0833-0029** Year Built: **1905** Data Source: **Permit**

Number Extended Street Quad Type of Address

514 **G Street** **NE** **Current**

Name(s) Type of Name

Rowhouse, 514 G Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0029 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1905** **Permit** **Original**

Residential (Multi-Family) **Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1905** **Permit** **2400 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Volland, E.**

Orig Construction **Builder** **Haislip, J. R.**

Orig Construction **Owner** **Boyd, Charles**

Construction Notes:

One of five rowhouses constructed from the same permit (#2179).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 5)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Canted Bay**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **18**

Depth/Length: **35**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1905 by J.R. Haislip, this two-story, two-bay Queen Anne-style rowhouse is one of five rowhouses constructed from the same permit (#2179). The dwelling is constructed of brick and is set on a solid concrete foundation. The façade (south elevation) is faced with pressed stretcher-bond brick. Two-course, stretcher-bond brick string courses span the façade of the dwelling and are located below the first and second story window openings. A sloping roof caps the dwelling and is fronted along the façade by a molded metal cornice with modillions and a plain frieze board. The easternmost bay of the façade holds a single-leaf paneled wood door and a one-light wood transom. A stone lintel tops the transom. Poured concrete steps with brick wing walls provide access to the entrance. Brick balusters enclose the small stoop. The basement-level opening is sited directly below the first story entrance and contains a single-leaf door. The second story opening contains a 1/1, double-hung, vinyl-sash window. A three-sided, canted bay extends from the westernmost bay of the façade and rises the full height of the dwelling. The bay has the same material treatment as the main block and is original. A pyramidal roof, with a finial, caps the bay and is covered with slate shingles. A molded metal cornice with modillions and plain frieze finish the roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows. All window openings have concrete sills and stone lintels. The rear (north) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows, which have sills and two-course, rowlock brick segmental arches.

A two-story ell extends from the westernmost bay of the rear elevation and is original to the main block. The ell is constructed of brick and is set on a solid foundation. A sloping roof caps the ell. Visible fenestration consists of paired 1/1, double-hung, vinyl-sash windows and single-leaf wood-frame glass doors. The second story door opening is topped by a one-light transom. A two-story, full-width porch projects from the rear elevation of the ell and is set on metal posts. The shed roof of the porch is supported by metal posts. Metal balusters encircle the second story of the porch.

Site Notes:

January 2010: This rowhouse is located on the north side of G Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 512 and 516 G Street, N.E. and is sited on a level lot. The grassy front yard is landscaped with small trees and is encircled by hairpin and picket metal fencing. A concrete walkway leads to the primary entrance from the sidewalk. The rear yard is enclosed with wood fencing.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Pyramidal	Slate		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source

Facade	Pressed Brick	Stretcher Bond
Structure Component	Material	Feature
Foundation	Concrete	
Walls	Brick	

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl

Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single		Unknown
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s) _____ Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED


Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 514_G_Street_NE_facade_looking_N.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 514_G_Street_NE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 514_G_Street_NE_rear_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/20/1905	2179	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0030

BASICS DATA

ID Number: **0833-0030** Year Built: **1905** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

516		G Street	NE	Current
------------	--	-----------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

Rowhouse, 516 G Street, N.E.	Common
-------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0833/0030			Square/Lot	Current
------------------	--	--	-------------------	----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1905	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Rear Addition	c. 1960	Site Visit/Map			
----------------------	----------------	-----------------------	--	--	--

Orig Construction	1905	Permit			2400 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Architect	Volland, E.
--------------------------	------------------	--------------------

Orig Construction	Builder	Haislip, J. R.
--------------------------	----------------	-----------------------

Orig Construction	Owner	Boyd, Charles
--------------------------	--------------	----------------------

Construction Notes:

One of five rowhouses constructed from the same permit (#2179).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 5)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Canted Bay**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **18**

Depth/Length: **35**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1905 by J.R. Haislip, this two-story, two-bay Queen Anne-style rowhouse is one of five rowhouses constructed from the same permit (#2179). The dwelling is constructed of brick and is set on a solid concrete foundation. The façade (south elevation) is faced with pressed stretcher-bond brick. Two-course, stretcher-bond brick string courses span the façade of the dwelling and are located below the first and second story window openings. A sloping roof caps the dwelling and is fronted along the façade by a molded metal cornice with modillions and a plain frieze board. The easternmost bay of the façade holds a single-leaf wood-frame glass door and a one-light wood transom. A stone lintel tops the transom. Poured concrete steps with brick wing walls provide access to the entrance. Brick balusters enclose the small stoop. The basement-level opening is sited directly below the first story entrance and contains a single-leaf wood door with lights. The second story opening contains a 1/1, double-hung, vinyl-sash window. A three-sided, canted bay extends from the westernmost bay of the façade and rises the full height of the dwelling. The bay has the same material treatment as the main block and is original. A pyramidal roof, with a finial, caps the bay and is covered with slate shingles. A molded metal cornice with modillions and plain frieze finish the roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows. The foundation of the bay is pierced by two-light fixed windows. All window openings have concrete sills and stone lintels. The rear (north) elevation is fenestrated with one-light fixed vinyl windows which have sills and two-course, rowlock brick segmental arches.

A two-story ell extends from the easternmost bay of the rear elevation and is original. The ell is constructed of brick and is set on a solid brick foundation. A sloping roof caps the ell.

A two-story, full-width enclosed porch is located on the rear elevation of the ell and was constructed c. 1960. The wood-frame enclosed porch is clad with German vinyl siding and is set on a solid foundation. A sloping roof caps the enclosed porch. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows, a one-light fixed vinyl window and a single-leaf paneled door with lights. All window openings have vinyl surrounds.

Site Notes:

January 2010: This rowhouse is located on the north side of G Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 514 and 518 G Street, N.E. and is sited on a level lot. The front yard is landscaped with mature shrubs and is bounded by a hairpin and picket metal fencing. A concrete walkway leads from the primary entrance and ends at the sidewalk. The rear yard is bounded by wood fencing.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Pyramidal	Slate		Shingled	
Sloped	Not Visible		Not Visible	

Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Fixed	2 Lite	Unknown
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single		Wood/Glass
Main Door	Rectangular	Single	Full Glass	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **516_G_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 516_G_Street_NE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 516_G_Street_NE_rear_looking_S.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/20/1905	2179	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0031

BASICS DATA

ID Number: **0833-0031** Year Built: **1905** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

518		G Street	NE	Current
------------	--	-----------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

Rowhouse, 518 G Street, N.E.	Common
-------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0833/0031			Square/Lot	Current
------------------	--	--	-------------------	----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1905	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Rear Addition	c. 2005	Site Visit/Map			
----------------------	----------------	-----------------------	--	--	--

Orig Construction	1905	Permit			2400 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Architect	Volland, E.
--------------------------	------------------	--------------------

Orig Construction	Builder	Haislip, J. R.
--------------------------	----------------	-----------------------

Orig Construction	Owner	Boyd, Charles
--------------------------	--------------	----------------------

Construction Notes:

One of five rowhouses constructed from the same permit (#2179).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 5)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Canted Bay**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **18**

Depth/Length: **35**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1905 by J.R. Haislip, this two-story, two-bay Queen Anne-style rowhouse is one of five rowhouses constructed from the same permit (#2179). The dwelling is constructed of brick and is set on a solid concrete foundation. The façade (south elevation) is faced with pressed stretcher-bond brick. Two-course, stretcher-bond brick string courses span the façade of the dwelling and are located below the first and second story window openings. A sloping roof caps the dwelling and is fronted along the façade by a molded metal cornice with modillions and a plain frieze board. The easternmost bay of the façade holds a single-leaf, replacement paneled wood door with lights and a one-light wood transom. A stone lintel tops the transom. Poured concrete steps with brick wing walls provide access to the entrance. Brick balusters enclose the small stoop. The basement-level opening is sited directly below the first story entrance and contains a single-leaf wood door. The second story opening contains a 1/1, double-hung, vinyl-sash window. A three-sided, canted bay extends from the westernmost bay of the façade and rises the full height of the dwelling. The bay has the same material treatment as the main block and is original. A pyramidal roof caps the bay and is covered with slate shingles. A molded metal cornice with modillions and plain frieze finish the roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows. All window openings have concrete sills and stone lintels. The rear (north) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows, which have sills and two-course, rowlock brick segmental arches.

A two-story ell extends from the westernmost bay of the rear elevation and is original. The ell is constructed of brick and is set on a solid foundation. A sloping roof caps the ell and is pierced by an interior-side brick chimney with a corbeled brick cap.

A two-story, full-width enclosed porch is located on the rear elevation of the ell and was constructed c. 2005. The wood-frame enclosed porch is clad with German vinyl siding and is capped by a sloping roof. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows, one-light vinyl casement windows, and a single-leaf wood-frame glass door.

Site Notes:

January 2010: This rowhouse is located on the north side of G Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 516 and 520 G Street, N.E. and is sited on a level lot. The front yard is landscaped with mature shrubs and foundation plantings and is enclosed with hairpin and picket metal fencing. A concrete walkway leads from the primary entrance and ends at the sidewalk. Wood fencing encloses the rear yard. An alley is located north of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Pyramidal	Slate		Shingled	

Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single		Wood
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 518_G_Street_NE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 518_G_Street_NE_rear_looking_SW.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 518_G_Street_NE_rear_looking_S.JPG

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/20/1905	2179	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
4/23/2010	Barnes (JLB), Jeanne	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0032

BASICS DATA

ID Number: **0833-0032** Year Built: **1905** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

520		G Street	NE	Current
------------	--	-----------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

Rowhouse, 520 G Street, N.E.	Common
-------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0833/0032			Square/Lot	Current
------------------	--	--	-------------------	----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1905	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Orig Construction	1905	Permit			2400 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Architect	Volland, E.
--------------------------	------------------	--------------------

Orig Construction	Builder	Haislip, J. R.
--------------------------	----------------	-----------------------

Orig Construction	Owner	Boyd, Charles
--------------------------	--------------	----------------------

Construction Notes:

One of five rowhouses constructed from the same permit (#2179).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 5)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Canted Bay**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories:

Bays Wide:

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1905 by J.R. Haislip, this two-story, two-bay Queen Anne-style rowhouse is one of five rowhouses constructed from the same permit (#2179). The dwelling is constructed of brick and is set on a solid concrete foundation. The façade (south elevation) is faced with pressed stretcher-bond brick. Two-course, stretcher-bond brick string courses span the façade of the dwelling and are located below the first and second story window openings. A sloping roof caps the dwelling and is fronted along the façade by a molded metal cornice with modillions and a plain frieze board. The easternmost bay of the façade holds a single-leaf wood-frame glass door and a one-light wood transom. A stone lintel tops the transom. Poured concrete steps with brick wing walls provide access to the entrance. Brick balusters enclose the small stoop. The basement-level opening is sited directly below the first story entrance and contains a single-leaf door. The second story opening contains a 1/1, double-hung, vinyl-sash window. A three-sided, canted bay extends from the westernmost bay of the façade and rises the full height of the dwelling. The bay has the same material treatment as the main block and is original. A pyramidal roof caps the bay and is covered with slate shingles. A molded metal cornice with modillions and plain frieze finish the roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows. All window openings have concrete sills and stone lintels. The rear (north) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows, which have concrete sills and two-course, rowlock brick segmental arches.

A two-story ell extends from the eastern bay of the rear elevation and is original. The ell is constructed of brick and is set on a solid foundation. A sloping roof caps the ell. An interior-side brick chimney rises from the west elevation and has a parged cap. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and two single-leaf wood doors with lights. All windows have concrete sills. A two-story, full-width porch projects from the rear elevation of the ell and was constructed c. 1980. The porch is capped by a shed roof and is supported by square wood posts. Square wood balusters encircle the second story of the porch.

Site Notes:

January 2010: This rowhouse is located on the north side of G Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 516 and 520 G Street, N.E. and is sited on a level lot. The grassy front yard is landscaped with mature shrubs and small trees. A hairpin and picket metal fence encloses the front yard. The rear yard is bounded by wood fencing.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Pyramidal	Slate		Shingled	
Sloped	Not Visible		Not Visible	

Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single		Unknown
Main Door	Rectangular	Single	Full Glass	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **520_G_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 520_G_Street_NE_facade_looking_NW.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 520_G_Street_NE_rear_looking_SE.JPG

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/20/1905	2179	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0033

BASICS DATA

ID Number: **0833-0033** Year Built: **1911** Data Source: **Permit**

Number Extended Street Quad Type of Address

700 **6th Street** **NE** **Current**

Name(s) Type of Name

Single Dwelling, 700 6th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0033 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1911** **Permit** **Original**

Residential (Multi-Family) **Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1911** **Permit** **5500 Permit**

Construction Event Association Associated Name

Gottwals, M.L. **Builder** **Gottwals, M.L.**

Orig Construction **Architect** **Vaughn, Merrill**

Orig Construction **Owner** **Childs, Frank H.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Corner Attached (1 side)**
 Relate to Street: **Face on Setback Line**
 Massing: **Vertical Block**
 Footprint: **Rectangular (w/ side bays)**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **5**

Height:

Outbuilding Type

Contributing Status

Width: **18**

Depth/Length: **60**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

January 2010: Constructed in 1911 by M.L. Gottwals, this two-story, five-bay Classical Revival-style single-family dwelling was constructed from permit #5009. The dwelling is constructed of brick and is set on a solid concrete foundation. The façade (east elevation) is faced with stretcher-bond brick. A molded belt course encircles the dwelling and is located above the second story window openings. The roofing type was not discernible from the public right-of-way. A molded metal cornice spans the dwelling and finishes the roof. An interior brick chimney rises from the northeast corner of the dwelling and has a corbeled brick cap. A single-leaf, replacement wood door with one diamond-light pierces the façade and is flanked by one-light sidelights and topped by a one-light wood transom. A concrete lintel spans the length of the transom. A one-story, one-bay porch shelters the primary entrance and is set on a solid foundation. The pedimented roof is supported by metal filigree posts, which are set on brick piers. Poured concrete steps, flanked by brick wing walls, provide access to the entrance. All window openings on the façade contain 1/1, double-hung, vinyl-sash windows and have concrete sills and lintels. A rectangular bay projects from the southeast corner of the dwelling and rises the full height of the dwelling. The bay is original to the dwelling and has the same material treatment. A pyramidal roof, covered with slate shingles, caps the bay. A finial tops the roof. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows and feature concrete sills and lintels. A three-sided, rectangular bay projects from the east elevation and rises the full height of the dwelling. The bay is original and has the same material treatment. A molded segmental pediment projects from the top of the bay and features a molded cornice. Fenestration consists of paired 1/1, double-hung, vinyl-sash windows, which have concrete sills and lintels. The south elevation has fenestration that is consistent with the façade. The north (side) elevation of the dwelling is fenestrated with single-leaf doors with one-light wood transoms and 1/1, double-hung windows. All openings have two-course, rowlock brick segmental arches and the windows additionally have concrete sills.

A one-story garage is located at the basement level of the north elevation of the dwelling and is original to the main block. The garage is constructed of American-bond brick and is capped by a flat roof. The original garage opening, which pierced the east elevation, is boarded with plywood. The flat roof supports a deck, which features square wood balusters.

A two-story porch extends from the rear elevation and is set on the garage. Square wood posts support the porch, which is capped by a shed roof. Square wood balusters encircle the second story of the porch.

Site Notes:

January 2010: This single-family dwelling is located on the northwest corner of 6th Street, N.E. and G Street, N.E. The west (side) elevation of the dwelling is adjacent to 520 G Street, N.E. The dwelling is sited on a level, grassy lot that features mature trees and shrubs, as well as foundation plantings. A metal chain-link fence encloses the front and side yards of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Pyramidal Sloped	Slate Not Visible		Shingled Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation Walls	Concrete Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood/Glass

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 700_6th_Street_NE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 700_6th_Street_NE_facade_looking_SW.JPG**
Date:: Photog:
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 700_6th_Street_NE_rear_porch_detail.JPG**
Date:: Photog:
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 700_6th_Street_NE_porch_detail.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 700_6th_Street_NE_side_looking_N.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 700_6th_Street_NE_side_looking_S.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 700_6th_Street_NE_side_looking_W.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/08/1911	5009	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0027

BASICS DATA

ID Number: **0833-0027** Year Built: **1891** Data Source: **Permit**

Number Extended Street Quad Type of Address

712 **6th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 712 6th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0027 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Richards, James**

Orig Construction **Owner** **Richards, James**

Construction Notes:

Constructed with 714 6th Street, N.E. from the same permit (#1311).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached (1 side)**
Relate to Street: **Face on Setback Line**
Massing: **Vertical box/Rectang. Oriel**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **3**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **36**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Romanesque Revival

Exterior & Architectural Notes:

January 2010: Constructed in 1891 by James Richards, this three-story, two-bay Romanesque Revival-style single-family dwelling was constructed from the same permit as 714 6th Street, N.E. (#1311). The dwelling is constructed of American-bond brick and is set on a solid brick foundation. The façade (east elevation) is faced with pressed stretcher-bond brick that has been painted. Corbeled brick pilasters flank the dwelling and rise from the second story to the cornice. A corbeled brick string course spans the façade and is located above the first story window openings and a three-course, dog-tooth string course travels across the façade and is located above the first story transom openings. A mansard roof caps the dwelling and is covered with asphalt shingles. A molded cornice complements the roof. A wall dormer pierces the roof and is constructed of brick and rusticated brick. A crenellated metal cornice tops the dormer and a two-course, dog-tooth course is located beneath the cornice. A tilted tripartite window, composed of a central 1/1, double-hung, vinyl-sash window and flanking one-light fixed vinyl windows pierces the dormer and is topped by a two-course, rowlock brick stilted arch. An interior brick chimney rises from the north (side) elevation and has a corbeled brick cap. The northernmost bay of the first story holds a single-leaf paneled wood door and is topped by a one-light wood round-headed transom. A two-course, rowlock brick round-headed arch complements the transom. The southernmost bay holds triple 1/1, double-hung, vinyl-sash windows, which are topped by a five-light elliptical transom. A three-course, rowlock brick elliptical arch finishes the transom. A centrally-located second story oriel window projects from the façade and is possibly wood-frame construction. The oriel is fenestrated with 1/1, double-hung, vinyl-sash windows and features a molded metal cornice, paneling, pilasters, and wave molding. The south (side) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows, which have rowlock brick sills. The rear (west) elevation of the third story is parged and is fenestrated with a single-leaf wood door with lights.

A two-story, full-width block extends from the rear elevation of the dwelling and is original. The block is constructed of American-bond brick and is set on a solid brick foundation. A sloping roof caps the block. Fenestration consists of 1/1, double-hung, vinyl-sash windows and sliding vinyl doors. Most windows have rowlock brick sills and two-course, rowlock brick segmental arches. The foundation of the rear elevation is pierced by a single-leaf multi-light wood door and a 1/1, double-hung, vinyl-sash window.

Site Notes:

January 2010: This single-family dwelling is located on the west side of 6th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The north (side) elevation of the dwelling is adjacent to 714 6th Street, N.E. An alley runs parallel to the south (side) elevation of the dwelling. The front yard is landscaped with mature shrubs and small trees and is bounded by a milled point metal fence. A brick patio extends from the rear (west) elevation of the dwelling. A concrete parking area and an alley are located west of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard	Asphalt		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Tripartite	Dbl-Hung	1/1	Vinyl
Dormer	Tripartite	Dbl-Hung	1/1	Vinyl
Dormer	Tripartite	Fixed	1-light	Vinyl
Oriel	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material

Main Door Rectangular Single Paneled Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **712_6th_Street_NE_facade_looking_N.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **712_6th_Street_NE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **712_6th_Street_NE_rear_looking_E.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 712_6th_Street_NE_rear_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/31/1891	1311	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0026

BASICS DATA

ID Number: **0833-0026** Year Built: **1891** Data Source: **Permit**

Number Extended Street Quad Type of Address

714 **6th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 714 6th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0026 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Richards, James**

Orig Construction **Owner** **Richards, James**

Construction Notes:

Constructed with 712 6th Street, N.E. from permit #1311.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Face on Setback Line**
Massing: **Vertical box/Rectang. Oriel**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **3**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **36**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Romanesque Revival

Exterior & Architectural Notes:

January 2010: Constructed in 1891 by James Richards, this three-story, two-bay Romanesque Revival-style single-family dwelling was constructed from the same permit as 712 6th Street, N.E. (#1311). The dwelling is constructed of brick and is set on a solid brick foundation. The façade (east elevation) is faced with pressed stretcher-bond brick that has been painted. Corbeled brick pilasters flank the dwelling and rise from the second story to the cornice. A corbeled brick string course spans the façade and is located above the first story window openings and a three-course, dog-tooth string course travels across the façade and is located above the first story transom openings. A mansard roof caps the dwelling and is covered with slate shingles. A molded cornice complements the roof. A wall dormer pierces the roof and is constructed of concrete and rusticated brick. A crenellated cornice tops the dormer and a two-course, dog-tooth course is located beneath the cornice. A stilted tripartite window, composed of a central 1/1, double-hung, vinyl-sash window and flanking two-light fixed vinyl windows pierces the dormer and is topped by a two-course, rowlock brick stilted arch. The northernmost bay of the first story holds a single-leaf paneled wood door and is topped by a blind round-headed transom. A two-course, rowlock brick round-headed arch complements the transom. The southernmost bay holds triple 1/1, double-hung, vinyl-sash windows and are topped by a five-light elliptical transom. A three-course, rowlock brick elliptical arch finishes the transom. A centrally-located second story oriel window projects from the façade and is wood-frame construction. The oriel is fenestrated with 1/1, double-hung, vinyl-sash windows and features paneling, pilasters, and wave molding. The rear (west) elevation of the third story is clad with wood weatherboard siding and is fenestrated with 1/1, double-hung, vinyl-sash windows. The rear elevation of the main block is pierced by 1/1, double-hung, vinyl-sash windows, which feature rowlock brick sills and two-course, rowlock brick segmental arches.

A two-story ell extends from the southernmost bay of the rear elevation and is original. The ell is constructed of American-bond brick and is set on a solid foundation. A sloping roof caps the ell. An exterior-rear brick chimney rises from the west elevation and has a parged cap. Visible fenestration consist of 1/1, double-hung, vinyl-sash windows. Two-course, rowlock brick segmental arches and rowlock brick sills finish the windows.

A one-story, full-width enclosed porch is located on the rear elevation of the ell and was constructed c. 1925. Noted on the 1928 Sanborn map, the enclosed porch is clad with wood weatherboard siding and is capped by a shed roof.

Site Notes:

January 2010: This single-family dwelling is located on the west side of 6th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 712 and 716 6th Street, N.E. and is sited on a level lot. The front yard is landscaped with mature shrubs and is bounded by a hairpin and picket metal fence. A concrete walkway leads from the primary entrance and ends at the sidewalk. The rear yard is bounded by wood fencing. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard	Asphalt		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Tripartite	Dbl-Hung	1/1	Vinyl
Dormer	Tripartite	Dbl-Hung	1/1	Vinyl
Dormer	Tripartite	Fixed	2 Lite	Vinyl
Oriel	Rectangular	Dbl-Hung	1/1	Vinyl

Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood
Notable Interior Plan(s)			Notable Interior Feature(s)	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 714_6th_Street_NE_cornice_detail.JPG**
Date:: Photog:
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 714_6th_Street_NE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 714_6th_Street_NE_facade_looking_SW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 714_6th_Street_NE_facade_looking_W.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 714_6th_Street_NE_oriel_detail.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 714_6th_Street_NE_rear_looking_SE.JPG

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/31/1891	1311	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0025

BASICS DATA

ID Number: **0833-0025** Year Built: **1892** Data Source: **Permit**

Number Extended Street Quad Type of Address

716 **6th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 716 6th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0025 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1892** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1892** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Richards, James**

Orig Construction **Owner** **Richards, James**

Construction Notes:

Constructed with 718 6th Street, N.E. from the same permit (#0538).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **L-Shaped**

Number Stories: **3**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **36**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Second Empire

Exterior & Architectural Notes:

January 2010: Constructed in 1892 by James Richards, this three-story, two-bay Second Empire-style single-family dwelling is one of two dwellings constructed from the same permit (#0538). The dwelling is constructed of brick and is set on a solid brick foundation. The façade (east elevation) is faced with five-course, American-bond brick. Stretcher-bond brick string course bisect the first and second story window openings and also span the façade below the second story window openings. A mansard roof caps the dwelling and is covered with tin shingles. A molded cornice and brick dentils complement the roof. A wall dormer pierces the mansard roof and is fenestrated with a 1/1, double-hung, vinyl-sash window with false 4/1 vinyl muntins. The window is complemented by a concrete sill and flat roof. The northernmost bay of the first story holds a single-leaf paneled wood door. A blind transom tops the door. The door is set in a round-headed opening and features a two-course, rowlock brick round-headed arch. The second story opening holds a 1/1, double-hung, vinyl-sash window with false 8/1 vinyl muntins and features a concrete sill and a two-course, rowlock brick segmental arch topped with header bricks. A three-sided, rectangular bay extends from the southernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the façade and is original. A mansard roof caps the bay and is covered with tin shingles. A wall dormer pierces the roof and is fenestrated with paired 1/1, double-hung, vinyl-sash windows with false 8/1 vinyl muntins. The dormer is complemented by a flat roof and concrete sill. The bay is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows with false 8/1 and 4/1 vinyl muntins. The windows have concrete sills and two-course, rowlock brick segmental arches topped by header bricks. The rear (west) elevation of third story is clad with aluminum siding and is fenestrated with 1/1, double-hung, vinyl-sash windows with false 6/1 vinyl muntins.

A two-story ell extends from the southernmost bay of the rear elevation and is original. The ell is parged and is set on a solid foundation. A sloping roof caps the ell. Visible fenestration consist of two single-leaf paneled metal doors with lights and 1/1, double-hung, vinyl-sash windows with false 6/1 vinyl muntins.

Site Notes:

January 2010: This single-family dwelling is located on the west elevation of 6th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 714 and 718 6th Street, N.E. The front yard is landscaped with mature shrubs and foundation plantings. A metal fence with brick pillars encircles the front yard. A brick patio extends from the rear elevation of the dwelling. The grassy rear yard is landscaped with mature shrubs and is bounded by wood fencing. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard	Tin		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Dormer	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Dormer	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s) _____

Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s) _____

Survey(s)

Level(s) of Investigation _____

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833

File: **716_6th_Street_NE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833

File: **716_6th_Street_NE_facade_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833

File: **716_6th_Street_NE_rear_looking_E.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
09/02/1892	0538	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0024

BASICS DATA

ID Number: **0833-0024** Year Built: **1892** Data Source: **Permit**

Number Extended Street Quad Type of Address

718 **6th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 718 6th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0024 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1892** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1892** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Richards, James**

Orig Construction **Owner** **Richards, James**

Construction Notes:

Constructed with 716 6th Street, N.E. from the same permit (#0538).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **L-Shaped**

Number Stories: **3**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **36**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Second Empire

Exterior & Architectural Notes:

January 2010: Constructed in 1892 by James Richards, this three-story, two-bay Second Empire-style single-family dwelling is one of two dwellings constructed from the same permit (#0538). The dwelling is constructed of brick and is set on a solid brick foundation. The façade (east elevation) is faced with five-course, American-bond brick. Stretcher-bond brick string course bisect the first and second story window openings and also span the façade below the second story window openings. A mansard roof caps the dwelling and is covered with tin shingles. A molded cornice and brick dentils complement the roof. A wall dormer pierces the mansard roof and is fenestrated with a 1/1, double-hung, vinyl-sash window. The window is complemented by a concrete sill and flat roof. The northernmost bay of the first story holds a single-leaf paneled wood door with an oval light. A blind transom tops the door. The door is set in a round-headed opening and features a two-course, rowlock brick round-headed arch. The second story opening holds a 1/1, double-hung, vinyl-sash window, which features a concrete sill and a two-course, rowlock brick segmental arch with molded brick. A three-sided, rectangular bay extends from the southernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the façade and is original. A mansard roof caps the bay and is covered with tin shingles. A wall dormer pierces the roof and is fenestrated with paired 1/1, double-hung, vinyl-sash windows. The dormer is complemented by a flat roof and concrete sill. The bay is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows, which have two-course, rowlock brick segmental arches topped by header bricks and concrete sills. The rear (west) elevation is pierced by 1/1, double-hung, vinyl-sash windows and a single-leaf wood-frame glass door and one-light transom.

A two-story ell extends from the northernmost bay of the rear elevation and is original. The ell is parged and is set on a solid foundation. The sloping roof supports a rooftop deck with square wood balusters. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf wood-frame glass door. A second story deck extends from the rear elevation and is supported by metal posts. Square wood balusters encircle the deck.

Site Notes:

January 2010: This single-family dwelling is located on the west elevation of 6th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 716 and 720A-720B 6th Street, N.E. and is sited on a level lot. The front yard is landscaped with small trees and is encircled by a hairpin and picket metal fence. A brick walkway leads from the primary entrance and ends at the sidewalk. The rear yard is laid with brick and is bounded by wood fencing. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard	Tin		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Dormer	Rectangular	Dbl-Hung	1/1	Vinyl
Dormer	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood/Glass

Notable Interior Plan(s) _____

Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s) _____

Designation Event(s) _____

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833

File: **718_6th_Street_NE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833

File: **718_6th_Street_NE_facade_looking_W.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833

File: **718_6th_Street_NE_rear_looking_E.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 718_6th_Street_NE_rear_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
09/02/1892	0538	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0023

BASICS DATA

ID Number: **0833-0023** Year Built: **1892** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
720	A-720B	6th Street	NE	Current
720		6th Street	NE	Original

Name(s)	Type of Name
Single Dwelling, 720 6th Street, N.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
0833/0023			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1892	Permit			Original
Residential (Multi-Family)					Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1892	Permit			3000 Permit

Construction Event	Association	Associated Name
Orig Construction	Builder	Richards, James
Orig Construction	Owner	Richards, James

Construction Notes:

Constructed with 722 6th Street, N.E. from the same permit (#1797).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Face on Setback Line**
Massing: **Vertical Box/rectang bay**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **3**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **18**

Depth/Length: **36**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Second Empire

Exterior & Architectural Notes:

January 2010: Constructed in 1892 by James Richards, this three-story, two-bay Second Empire-style single-family dwelling is one of two dwellings constructed from the same permit (#1797). The dwelling is constructed of brick and is set on a solid brick foundation. The façade (east elevation) is faced with irregular-coursed, American-bond brick. Stretcher-bond brick string course bisect the first story window openings and also span the façade below the second story window openings. A mansard roof caps the dwelling and is covered with tin shingles. A molded cornice and corbeled brick cornice complement the roof. A pedimented wall dormer pierces the mansard roof and is fenestrated with a 1/1, double-hung, vinyl-sash window. The northernmost bay of the first story holds a single-leaf wood door. The door is set in a round-headed opening and features a two-course, rowlock brick round-headed arch. The second story opening holds a 1/1, double-hung, vinyl-sash window, which features a concrete sill and a two-course, rowlock brick segmental. A three-sided, rectangular bay extends from the southernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the façade and is original. A mansard roof caps the bay and is covered with tin shingles. A pedimented wall dormer pierces the roof and is fenestrated with paired 1/1, double-hung, vinyl-sash windows. The bay is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows, which have one-course, rowlock brick segmental arches with molded brick and concrete sills. The foundation of the bay is pierced by a single-leaf paneled metal door with lights and sliding vinyl windows. The rear (west) elevation is pierced by 1/1, double-hung, vinyl-sash windows. The rear elevation of the third story is clad with aluminum siding and is pierced by two 1/1, double-hung, vinyl-sash windows.

A two-story ell extends from the northernmost bay of the rear elevation and is original. The ell is parged and is set on a solid foundation. A sloping roof caps the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf paneled wood door. The original transom opening does not hold a window.

Site Notes:

January 2010: This single-family dwelling is located on the west side of 6th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 718 and 722 6th Street, N.E. The front yard is laid with brick and is encircled by a hairpin and picket metal fence. The rear yard is paved with concrete and is edged by wood fencing. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard	Tin		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	

Structure Component	Material	Feature	Source
Foundation	Brick		
Walls	Brick		

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Dormer	Rectangular	Dbl-Hung	1/1	Vinyl
Dormer	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single	Paneled	Metal/Glas
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s) _____ Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s) _____
Subdivision: _____	
Ward/ANC: _____	
Zoning: _____	Designation Event(s) _____
Contributing: _____	
Survey(s) _____	Level(s) of Investigation _____
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **720A-
720B_6th_Street_NE_facade_looking_NW.JPG**

Date:: _____ Photog: _____

Code:: _____ R: _____ Fr: _____

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 720A-
720B_6th_Street_NE_facade_looking_SW.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 720A-
720B_6th_Street_NE_rear_looking_E.JPG

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/26/1892	1797	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
4/26/2010	Litowitz (DDL), Dana	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0022

BASICS DATA

ID Number: **0833-0022** Year Built: **1892** Data Source: **Permit**

Number Extended Street Quad Type of Address

722 **6th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 722 6th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0022 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1892** **Permit** **Original**

Residential (Multi-Family) **Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1892** **Permit** **3000 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Richards, James**

Orig Construction **Owner** **Richards, James**

Construction Notes:

Constructed with 720A-720B 6th Street, N.E. from the same permit (#1797).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **3**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **36**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Second Empire

Exterior & Architectural Notes:

January 2010: Constructed in 1892 by James Richards, this three-story, two-bay Second Empire-style single-family dwelling is one of two dwellings constructed from the same permit (#1797). The dwelling is constructed of brick and is set on a solid brick foundation. The façade (east elevation) is faced with irregular-coursed, American-bond brick. A stretcher-bond brick string course bisects the first story window openings and also spans the façade above and below the second story window openings. A mansard roof caps the dwelling and is covered with slate shingles. A molded cornice and corbeled brick cornice complement the roof. A pedimented wall dormer pierces the mansard roof and is fenestrated with a 1/1, double-hung, metal-sash window. The northernmost bay of the first story holds a single-leaf, replacement paneled wood door with lights. The door is set in a round-headed opening and features a two-course, rowlock brick round-headed arch. The second story opening holds a 1/1, double-hung, metal-sash window, which features a concrete sill and a soldier brick segmental arch with molded brick. A three-sided, rectangular bay extends from the southernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the façade and is original. A mansard roof caps the bay and is covered with slate shingles. A pedimented wall dormer pierces the roof and is fenestrated with paired 1/1, double-hung, metal-sash windows. The bay is fenestrated with single and paired 1/1, double-hung, metal-sash windows, which have rowlock brick segmental arches and concrete sills.

A two-story ell extends from the northernmost bay of the rear (west) elevation and is original. The ell is constructed of brick and is set on a solid brick foundation. The rear elevation of the ell is parged. A sloping roof caps the ell and supports a rooftop deck. Visible second story fenestration consists of sliding metal doors. A metal balcony with metal balusters and stairs provide access to these doors.

Site Notes:

January 2010: This single-family dwelling is located on the west side of 6th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 720A-720B 6th Street, N.E. and 724 6th Street, N.E. The grassy front yard is landscaped with mature shrubs and is bounded by a low, brick retaining wall and a milled point metal fence. The rear yard is enclosed with wood fencing. A gravel parking area and an alley are located west of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard	Slate		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Metal
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Metal
Bay Windows	Rectangular	Dbl-Hung	1/1	Metal
Dormer	Rectangular	Dbl-Hung	1/1	Metal
Dormer	Rectangular	Dbl-Hung	1/1 Double	Metal
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood/Glass

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **722_6th_Street_NE_facade_looking_SSW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **722_6th_Street_NE_facade_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833**

File: **722_6th_Street_NE_facade_looking_W.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 722_6th_Street_NE_rear_looking_E.JPG

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/26/1892	1797	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0011

BASICS DATA

ID Number: **0833-0011** Year Built: **1900** Data Source: **Permit**

Number Extended Street Quad Type of Address

724 **6th Street** **NE** **Current**

Name(s) Type of Name

Single Dwelling, 724 6th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0011 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1900** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Rear Addition **c. 2000** **Site Visit/Map**

Orig Construction **1900** **Permit** **1800 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Riddle, John, Sr.**

Orig Construction **Builder** **Riddle, John, Sr.**

Orig Construction **Owner** **Riddle, John, Sr.**

Construction Notes:

--

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Attached**
 Relate to Street: **Face on Setback Line**
 Massing: **Vertical Box/rectang bay**
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **15**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1900 by John Riddle, Sr., this two-story, two-bay Queen Anne-style single-family dwelling was built from permit #0400. The dwelling is constructed of brick and is set on a solid concrete foundation. The façade (east elevation) is faced with pressed stretcher-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a corbeled brick cornice. A frieze, composed of checkerboard brick, complements the cornice. The recessed southernmost bay of the façade holds a single-leaf paneled wood door with lights and a one-light wood transom. A concrete lintel tops the transom. The second story opening holds a 1/1, double-hung, wood-sash window. A three-sided, rectangular bay extends from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is original. Fenestration consists of 1/1, double-hung, wood-sash windows and one-light metal fixed windows. The first story windows are topped by one-light wood transoms and are separated from the primary window by dentil molding. All window openings on the façade have concrete sills and lintels. The rear (west) elevation is parged and is fenestrated with 1/1, double-hung, vinyl-sash windows.

A two-story ell extends from the southernmost bay of the rear elevation and is original. The ell is constructed of brick and is parged on the rear elevation. A sloping roof with a wide, overhanging eave, caps the ell. Visible fenestration consists of a 2/2, double-hung, wood-sash window.

A one-story addition is located on the rear elevation of the ell and was constructed c. 2000. The parged addition is capped by a shed roof with a wide, overhanging eave.

Site Notes:

January 2010: This single-family dwelling is located on the west side of 6th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 722 and 726 6th Street, N.E. and is sited on a level lot. The small, front yard is landscaped with mature shrubs and is bounded by hairpin and picket metal fencing. The rear yard is bounded with wood fencing. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			

Walls **Brick**

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	DbI-Hung	1/1	Wood
Bay Windows	Rectangular	DbI-Hung	1/1	Wood
Bay Windows	Rectangular	Fixed	1-light	Metal
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Vinyl/Glass
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 724_6th_Street_NE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 724_6th_Street_NE_facade_looking_SW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 724_6th_Street_NE_rear_looking_SE.JPG

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
09/13/1900	0400	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Updated
2/3/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0814

BASICS DATA

ID Number: **0833-0814** Year Built: **c. 1876** Data Source: **Site Visit/Map**

Number Extended Street Quad Type of Address

726 **6th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 726 6th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0814 **Square/Lot** **Current**

0833/0010 **Square/Lot** **Historic**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **c. 1876** **Site Visit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **c. 1876** **Site Visit/Map**

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/flat front**

Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate (Vernacular)

Exterior & Architectural Notes:

January 2010: Constructed c. 1876, this two-story, two-bay vernacular single dwelling was influenced by the Italianate style and is possibly wood-frame construction. The dwelling is set on a solid, raised parged foundation. The dwelling is clad with beaded vinyl siding and is set on a solid, raised foundation that has been parged. A sloping roof caps the dwelling and is fronted along the façade (east elevation) by a prominent molded cornice with modillions and brackets. An interior-side brick chimney rises from the north (side) elevation. The southernmost bay of the façade holds a single-leaf replacement paneled metal door with an oval light. Pilasters flank the opening and support a segmental pediment with a sunrise motif. Wood stairs provide access to the primary entrance. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins and are flanked with inoperable louvered shutters. The foundation is pierced by a single-leaf paneled metal door and paired 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins. Visible fenestration on the rear (west) elevation consists of 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins and a single-leaf replacement paneled metal door with lights.

Site Notes:

January 2010: This single-family dwelling is located on the west side of 6th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 724 and 728 6th Street, N.E. The small front yard is enclosed with hairpin and picket metal fencing. A brick walkway leads from the primary entrance and ends at the concrete sidewalk. The rear yard is enclosed with wood fencing. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Vinyl		Siding	
Structure Component	Material	Feature		Source
Foundation	Unknown			
Walls	Wood			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Basemt Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single	Paneled	Metal
Main Door	Rectangular	Single	Paneled	Metal/Glas

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/DAC:

Tuesday, June 25, 2013

ID_Number: 0833-0814 Page 2

ward/ANC:
Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 726_6th_Street_NE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 726_6th_Street_NE_facade_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 726_6th_Street_NE_facade_looking_W.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 726_6th_Street_NE_rear_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/4/2010	Dayton (MSD), Maria	Record Updated
2/4/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0813

BASICS DATA

ID Number: **0833-0813** Year Built: **1871-1872** Data Source: **Tax Records**

Number Extended Street Quad Type of Address

728 **6th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 728 6th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0833/0813 **Square/Lot** **Current**

0833/0009 **Square/Lot** **Historic**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1871-1872 Tax Recor** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1871-1872 Tax Records**

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/flat front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Vernacular

Colonial Revival

Exterior & Architectural Notes:

January 2010: Constructed 1871-1872, this two-story, two-bay vernacular single-family dwelling is wood-frame construction. The dwelling is clad with German vinyl siding and is set on a solid parged foundation. A sloping roof caps the dwelling and is pierced by an interior brick chimney. The northernmost bay of the façade (east elevation) holds a single-leaf paneled wood door. Fluted pilasters and an entablature with dentil molding highlight the opening. All window openings on the façade hold 2/2, double-hung, wood-sash windows and feature aluminum-clad surrounds and inoperable louvered shutters. The rear (west) elevation is clad with vinyl siding. Visible fenestration consists of 2/2, double-hung, wood-sash windows, which have aluminum-clad surrounds. Alterations are Colonial Revival in style.

Site Notes:

January 2010: This single-family dwelling is located on the west side of 6th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 726 and 730 6th Street, N.E. and is sited on a level lot. The small front yard is landscaped with mature shrubs. The rear yard is bounded by wood fencing. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Vinyl		Siding	
Structure Component	Material	Feature		Source
Foundation				
Walls	Wood			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	2/2	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 728_6th_Street_NE_facade_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 728_6th_Street_NE_facade_looking_W.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 728_6th_Street_NE_rear_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

The 1869-1871 General Assessment book indicates that the property was not improved. The 1872-1873 General Assessment book indicates that Cornelius Sheahan owns the property and it is valued at \$128.

General Assessment, 1869-1871. Corporation of Washington. (Vol. 13 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C.

General Assessment, 1872-1873. Corporation of Washington. (Vol. 14 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C.

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

No permit.

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
4/28/2010	Litowitz (DDL), Dana	Record Updated
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/4/2010	Dayton (MSD), Maria	Record Updated
2/4/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0046

BASICS DATA

ID Number: **0833-0046** Year Built: **1871-1872** Data Source: **Tax Records**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

730		6th Street	NE	Current
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

Single Dwelling, 730 6th Street, N.E.	Common
--	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0833/0046			Square/Lot	Current
------------------	--	--	-------------------	----------------

0833/0008			Square/Lot	Historic
------------------	--	--	-------------------	-----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1871-1872	Tax Recor			Historic/Current
------------------------------------	------------------	------------------	--	--	-------------------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Orig Construction	1871-1872	Tax Records			
--------------------------	------------------	--------------------	--	--	--

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/flat front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Vernacular

Colonial Revival

Exterior & Architectural Notes:

January 2010: Constructed 1871-1872, this two-story, two-bay vernacular single-family dwelling is wood-frame construction. The façade (east elevation) is faced with stretcher-bond brick and is set on a solid foundation. A side-gabled roof caps the dwelling and its western slope extends into a shed roof and is covered with standing-seam metal. Dentil molding finishes the roof. The northernmost bay of the façade holds a single-leaf replacement paneled wood door with lights. A Colonial Revival surround, composed of fluted pilasters and a broken pediment with dentil molding, highlights the opening. The façade is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows with false 6/1 vinyl muntins. All window openings on the façade have rowlock brick sills and inoperable louvered shutters. The rear (west) elevation is stuccoed and is pierced by double-leaf wood-frame glass doors and 1/1, double-hung, vinyl-sash windows with false 6/1 vinyl muntins.

Site Notes:

January 2010: This single-family dwelling is located on the west side of 6th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 728 and 732 6th Street, N.E. and is sited on a level lot. The small front yard is landscaped with mature shrubs and small trees and is bounded by a milled point metal fence. A brick walkway leads from the primary entrance and ends at the sidewalk. The rear yard is bounded by a stuccoed wall. A concrete parking area and alley are located west of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Side gable	Mansard		Standing Seam	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Veneer	
Structure Component	Material	Feature		Source
Foundation	Unknown			
Walls	Wood			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Vinyl/Glass

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Tuesday, June 25, 2013

ID_Number: 0833-0046 Page 2

Contributing:

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

Tax Book Research

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 730_6th_Street_NE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 730_6th_Street_NE_facade_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 730_6th_Street_NE_rear_looking_E.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 730_6th_Street_NE_rear_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

MISCELLANEOUS NOTES DATA

Notes:

The 1869-1871 General Assessment book indicates that the property was not improved. The 1872-1873 General Assessment book indicates that Patrick Maloney owns the property and it is valued at \$139.

General Assessment, 1869-1871. Corporation of Washington. (Vol. 13 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C.

General Assessment, 1872-1873. Corporation of Washington. (Vol. 14 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C.

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

No permit.

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
4/28/2010	Litowitz (DDL), Dana	Record Updated
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/4/2010	Dayton (MSD), Maria	Record Updated
2/4/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0833-0045

BASICS DATA

ID Number: **0833-0045** Year Built: **1871-1872** Data Source: **Tax Records**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

732		6th Street	NE	Current
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

Single Dwelling, 732 6th Street, N.E.	Common
--	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0833/0045			Square/Lot	Current
------------------	--	--	-------------------	----------------

0833/0007			Square/Lot	Historic
------------------	--	--	-------------------	-----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Fair**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1871-1872	Tax Recor			Historic/Current
------------------------------------	------------------	------------------	--	--	-------------------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Orig Construction	1871-1872	Tax Records			
--------------------------	------------------	--------------------	--	--	--

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/flat front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Vernacular

Colonial Revival

Exterior & Architectural Notes:

January 2010: Constructed 1871-1872 this two-story, two-bay vernacular single-family dwelling is wood-frame construction. The façade (east elevation) is faced with stretcher-bond brick and the north (side) elevation has been stuccoed. The dwelling is set on a solid foundation. A side-gabled roof caps the dwelling and the western slope of the roof extends into a shed roof. The roof is covered with standing-seam metal and is pierced by several skylights. Dentil molding complements the roof. The northernmost bay of the façade holds a single-leaf paneled wood door. A Colonial Revival surround highlights the opening and is composed of fluted pilasters and a segmental pediment with a sunrise motif. Dentil molding completes the surround. The southernmost bay holds paired 6/6 double-hung, wood-sash windows. The second story openings have 6/6, double-hung, wood-sash windows. All window openings on the façade feature rowlock brick sills and inoperable louvered shutters. The north elevation is not fenestrated. The rear elevation is stuccoed and is pierced by a single 6/6, double-hung, wood-sash window.

Site Notes:

January 2010: This single-family dwelling is located on the west side of 6th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The south (side) elevation of the dwelling is adjacent to 730 6th Street, N.E. A brick alley runs parallel to the north (side) elevation of the dwelling. The small front yard is bounded by milled point metal fencing. A brick walkway leads from the primary entrance and ends at the sidewalk. The rear yard is bounded by a parged wall. A concrete parking area and an alley are located west of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Side gable	Mansard		Standing Seam	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Veneer	
Structure Component	Material	Feature		Source
Foundation	Unknown			
Walls	Wood			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	6/6 Double	Wood
2 Flr Windows	Rectangular	Dbl-Hung	6/6	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Tuesday, June 25, 2013

ID_Number: 0833-0045 Page 2

Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research
Reconnaissance Survey
Tax Book Research

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 732_6th_Street_NE_door_entry.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 732_6th_Street_NE_facade_looking_NNW.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 732_6th_Street_NE_facade_looking_NW.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 732_6th_Street_NE_facade_looking_SW.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0833\
File: 732_6th_Street_NE_rear_looking_E.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

The 1869-1871 General Assessment book indicates that the property was not improved. The 1872-1873 General Assessment book indicates that Patrick McNanee owns the property and it is valued at \$136.

General Assessment, 1869-1871. Corporation of Washington. (Vol. 13 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C.

General Assessment, 1872-1873. Corporation of Washington. (Vol. 14 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C.

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

No permit.

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
4/28/2010	Litowitz (DDL), Dana	Record Updated
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/4/2010	Dayton (MSD), Maria	Record Updated

