

Resource All Data Report

ID Number: 0890-0022

BASICS DATA

ID Number: **0890-0022** Year Built: **1873-1874** Data Source: **Tax Records**

Number Extended Street Quad Type of Address

727 **7th Street** **NE** **Current**

Name(s) Type of Name

Single Dwelling, 727 7th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0022 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1873-1874** **Tax Recor** **Historic/Current**

Store/Dwelling **Historic**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1873-1874** **Tax Records**

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/front porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Garage

Outbuilding Notes:

January 2010: A one-story, one-bay garage is located east of the dwelling and was constructed c. 1925. The garage is constructed of five-course, American-bond brick and is set on a solid brick foundation. The façade is pierced by a roll-up paneled metal door, which is topped by a lintel clad with T-111 siding. A metal lintel is sited above the T-111 lintel. The opening that pierces the north elevation is boarded with T-111

siding. A metal lintel tops the opening.

STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate (Vernacular)

Exterior & Architectural Notes:

January 2010: Constructed 1873-1874, this two-story, two-bay vernacular single-family dwelling was influenced by the Italianate style. The wood-frame dwelling is clad with wood clapboard siding and is set on a solid poured foundation. A sloping roof caps the dwelling. A prominent molded cornice projects from the façade and features scrolled modillions and brackets. The northernmost bay of the first story holds a single-leaf paneled wood door and a one-light wood transom. A square-edged wood surround highlights the opening. The southernmost bay contains paired 1/1, double-hung, vinyl-sash windows with false 9/1 vinyl muntins. A one-story, full-width porch spans the façade and is set on a solid poured concrete foundation. The flat roof has overhanging eaves and is supported by brick posts with concrete molded capitals. Square wood balusters complete the porch. The second story openings hold 1/1, double-hung, vinyl-sash windows with false 6/1 vinyl muntins. All window openings on the façade have square-edged wood surrounds. The north elevation is pierced by 1/1, double-hung, vinyl-sash windows with false 4/1 vinyl muntins. Square-edged wood surrounds complete the openings. The rear (east) elevation is pierced by 6/6, double-hung, wood-ash windows and a 1/1, double-hung, vinyl-sash window. All windows have wood sills and aluminum surrounds.

A one-story bay, possibly original, extends from the southernmost bay of the rear elevation. The wood-frame addition is clad with wood clapboard siding and is capped by a shed roof. The fenestration was not discernible.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 7th Street, N.E. and is set back approximately ten feet from the sidewalk. The south (side) elevation of the dwelling is adjacent to 725 7th Street, N.E. and a concrete alley runs parallel to the north (side) elevation of the dwelling. The grassy front yard is landscaped with mature shrubs and foundation plantings and is encircled by hairpin and picket metal fencing. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is enclosed with wood fencing. A brick alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Clapboard Siding		Siding	
Structure Component	Material	Feature		Source
Foundation	Unknown			
Walls	Wood			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

Tax Book Research

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 727_7th_Street_NE_facade_looking_E.JPG**
Date:: Photog:
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 727_7th_Street_NE_facade_looking_SE.JPG**
Date:: Photog:
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 727_7th_Street_NE_garage_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 727_7th_Street_NE_garage_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 727_7th_Street_NE_rear_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

The 1872-1873 General Assessment book indicates that Thomas Ready owns the property and it is valued at \$151. The 1873-1874 General Assessment book indicates that a two-story frame building valued at \$600 is located on the property.

General Assessment, 1872-1873. Corporation of Washington. (Vol. 14 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C.

General Assessment, 1873-1874. Corporation of Washington. (Vol. 15 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C.

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

No permit.

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

DATA PROCESSING EVENTS DATA

Date	Individual	Action
4/28/2010	Litowitz (DDL), Dana	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/4/2010	Dayton (MSD), Maria	Record Updated
2/4/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0021

BASICS DATA

ID Number: **0890-0021** Year Built: **1891** Data Source: **Permit Index**

Number Extended Street Quad Type of Address

725 **7th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 725 7th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0021 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit Ind** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit Index**

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/Canted Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891, this two-story, two-bay Queen Anne-style rowhouse is constructed of brick and is set on a solid, raised foundation. The façade (west elevation) is faced with stretcher-bond brick. A four-course brick watertable spans the façade and is located above the foundation. A sloping roof caps the dwelling and is fronted along the façade by a brick parapet. An interior chimney pierces the roof and has been parged. A molded cornice with brick dentils complements the parapet. A string course, composed of nebule molding, spans the façade and is sited below the cornice. The northernmost bay of the first story holds a single-leaf, replacement paneled metal door with lights and a one-light wood transom. A stone lintel tops the transom. Cast iron steps with railings provide access to the door. The second story window opening holds a 1/1, double-hung, vinyl-sash window. A three-sided, canted bay rises the full height of the dwelling and projects from the southernmost bay of the façade. The canted bay has the material treatment of the main block and is capped by a pyramidal roof covered with slate shingles. A brick string course spans the canted bay between the first and second story windows. All window openings of the bay, except the foundation, hold 1/1, double-hung, vinyl-sash windows. The foundation is pierced by paired one-light vinyl sliding windows. The first story windows of the bay have stone sills and segmental arches with pearl and nailhead molding. The second story windows of the main block and bay have stone sills and lintels. The rear (east) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows.

A two-story ell extends from the northernmost bay of the rear elevation and is original. The ell is constructed of brick and is set on a solid foundation. The rear elevation is parged. Visible fenestration consists of a single-leaf wood-frame glass door with a ten-light wood transom and 1/1, double-hung, vinyl-sash windows. The door and windows are set in segmental openings and the windows have concrete sills.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 7th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 723 and 727 7th Street, N.E. The front yard is landscaped with mature shrubs and is encircled by a hairpin and picket metal fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the concrete sidewalk. Wood fencing bound the rear yard. An alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Unknown			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Sliding	1-light	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Metal/Glas

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **725_7th_Street_NE_facade_looking_E.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **725_7th_Street_NE_facade_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **725_7th_Street_NE_rear_looking_W.JPG**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Tuesday, June 25, 2013

ID_Number: 0890-0021 Page 3

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/18/1891	2012	Build	

Permit Notes:

Missing Permit.

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0020

BASICS DATA

ID Number: **0890-0020** Year Built: **1891** Data Source: **Permit Index**

Number Extended Street Quad Type of Address

723 **7th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 723 7th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0020 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit Ind** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Rear Addition **c. 1940** **Site**

Visit/Map

Orig Construction **1891** **Permit Index**

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/Canted Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type Contributing Status

Garage

Outbuilding Notes:

January 2010: A one-story, one-bay garage is located east of the dwelling and was constructed c. 1925. The garage is constructed of six-course, American-bond brick and is set on a solid brick foundation. A sloping roof caps the garage. The

façade (east elevation) contains double-leaf swing-out wood doors and are topped by a metal lintel. The northernmost door is pierced by a single-leaf metal door.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891, this two-story, two-bay Queen Anne-style rowhouse is constructed of brick and is set on a solid, raised foundation that is faced with stretcher-bond brick. The façade (west elevation) is faced with stretcher-bond brick. A four-course brick watertable spans the façade and is located above the foundation. A sloping roof caps the dwelling. A corbeled brick cornice highlights the roof. A string course, composed of nebule molding, spans the façade and is sited below the cornice. The northernmost bay of the first story holds a single-leaf wood door with a diamond light and a one-light wood transom. A segmental arch with pearl and nailhead molding toops the transom. Steps with metal railings provide access to the door. The second story window opening holds a 1/1, double-hung, vinyl-sash window. A three-sided, canted bay rises the full height of the dwelling and projects from the southernmost bay of the façade. The canted bay has the material treatment of the main block and is topped by metal cresting, which extends to the main block. A brick string course spans the canted bay between the first and second story windows. All window openings of the bay, except the foundation, hold 1/1, double-hung, vinyl-sash windows. The foundation is pierced by a two-light fixed wood window, which is topped by a rowlock brick segmental arch. The first story windows of the bay have stone sills and segmental arches with pearl and nailhead molding. The second story windows of the main block and bay have stone sills and lintels.

A two-story ell extends from the northernmost bay of the rear (east) elevation and is original. The ell is constructed of brick and is set on a solid foundation. The ell has been parged and is capped by a sloping roof. Two interior chimneys rise from the south elevation and is parged. Visible fenestration consists of 1/1 double-hung windows.

A two-story, full-width addition projects from the rear elevation of the ell and was constructed c. 1940 and is first noted on the 1960 Sanborn map. The addition is constructed of brick and is capped by a sloping roof. Visible fenestration consists of single, paired, and triple 1/1, double-hung, vinyl-sash windows and a single-leaf wood door with one-light. A self-supporting metal awning shelters the first story of the rear elevation. Horizontal siding has covered a first story opening of the south elevation.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 7th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 721 and 725 7th Street, N.E. The front yard is landscaped with mature shrubs and is encircled by hairpin and picket metal fencing. An alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Unknown			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Fixed	2 Lite	Wood

Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood/Glass
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 723_7th_Street_NE_facade_looking_E.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 723_7th_Street_NE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 723_7th_Street_NE_garage_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 723_7th_Street_NE_rear_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/18/1891	2012	Build	

Permit Notes:

Missing Permit.

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0019

BASICS DATA

ID Number: **0890-0019** Year Built: **1891** Data Source: **Permit Index**

Number Extended Street Quad Type of Address

721 **7th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 721 7th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0019 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit Ind** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit Index**

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/Canted Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Tuesday, June 25, 2013

ID_Number: 0890-0019 Page 1

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891, this two-story, two-bay Queen Anne-style rowhouse is constructed of brick and is set on a solid, raised foundation. The façade (west elevation) is clad with Permastone. A watertable spans the façade and is located above the foundation. A sloping roof caps the dwelling and is fronted along the façade by a Permastone-clad parapet. The northernmost bay of the first story holds a single-leaf wood door with a diamond-light and a one-light wood transom. A self-supporting metal awning shelters the entrance. Metal steps with railings provide access to the door. The second story window opening holds a 1/1, double-hung, vinyl-sash window and is set in a segmental opening. A three-sided, canted bay rises the full height of the dwelling and projects from the southernmost bay of the façade. The canted bay has the material treatment of the main block and is capped by a pyramidal roof covered with slate shingles. A curvilinear parapet rises from the pyramidal roof and is topped by a pedimented gable that is covered with Permastone. All window openings of the bay, except the foundation, hold 1/1, double-hung, vinyl-sash windows. A one-light vinyl window pierces the foundation. All window openings on the façade have stone sills and segmental arches of Permastone. The rear (east) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows.

A two-story ell extends from the northernmost bay of the rear elevation and is original to the main block. The ell is constructed of brick that has been parged and is set on a solid foundation. A sloping roof caps the ell. An interior chimney rises from the ell and is parged. Visible fenestration consists of a 1/1, double-hung, vinyl-sash window, a 2/2, double-hung, wood-sash window and a single-leaf paneled metal door. All windows have concrete sills and are set in segmental openings. A one-story, one-bay shed-roofed porch shelters the door. The porch is set on a metal post foundation and metal posts also support its roof.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 7th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 719 and 723 7th Street, N.E. and is sited on a level lot. The front yard is landscaped with mature shrubs and plantings and is encircled by a hairpin and picket metal fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The grassy rear yard is bounded by metal chain-link metal fencing. A concrete walkway leads from the rear entrance and ends at the public alley, which is sited east of the dwelling.

NOTABLE FEATURES DATA

Component	Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Permastone		Veneer	
Structure Component	Material	Feature		Source
Foundation	Unknown			
Walls	Brick			

Materials Notes:

--

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbi-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbi-Hung	1/1	Vinyl
Bay Windows	Rectangular	Unknown	1-light	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood/Glass

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **721_7th_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **721_7th_Street_NE_facade_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **721_7th_Street_NE_rear_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 721_7th_Street_NE_rear_looking_W.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/18/1891	2012	Build	

Permit Notes:

Missing Permit.

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0018

BASICS DATA

ID Number: **0890-0018** Year Built: **1891** Data Source: **Permit Index**

Number Extended Street Quad Type of Address

719 **7th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 719 7th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0018 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit Ind** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit Index**

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/Canted Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Garage

Outbuilding Notes:

January 2010: A one-story, one-bay garage, constructed c. 1940, is located east of the dwelling. The wood-frame shed is clad with German vinyl siding and is capped by a sloping roof. The façade (east elevation) is pierced by a garage opening. The fenestration was not visible at the time of the 2010 architectural survey.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891, this two-story, two-bay Queen Anne-style rowhouse is constructed of brick and is set on a solid, raised foundation. The façade (west elevation) is faced with stretcher-bond brick. A four-course brick waterable spans the façade and is located above the foundation. A sloping roof caps the dwelling and is fronted along the façade by a corbeled brick cornice with metal cresting. A string course, composed of nebule molding, spans the façade and is sited below the cornice. The northernmost bay of the first story holds a single-leaf paneled wood door with lights and a one-light wood transom. A stone lintel tops the transom. Cast iron steps with railings provide access to the door. The second story window opening holds a 1/1, double-hung, vinyl-sash window. A three-sided, canted bay rises the full height of the dwelling and projects from the southernmost bay of the façade. The canted bay has the material treatment of the main block and is topped by a corbeled brick cornice with metal cresting. A checkerboard brick panel spans the canted bay between the first and second story windows and is topped by a nebule-molded string course. All window openings of the bay, except the foundation, hold 1/1, double-hung, vinyl-sash windows. The foundation is pierced by paired one-light vinyl sliding windows. All first and second windows have stone sills and lintels. The foundation window features a rowlock brick segmental arch.

A two-story ell extends from the northernmost bay of the rear (east) elevation and is original. The ell is constructed of American-bond brick and is set on a solid foundation. A sloping roof caps the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf door with lights and a one-light transom. All window openings have two-course, rowlock brick segmental arches and concrete sills. A one-story, full-width porch spans the rear elevation and was constructed c. 1980. A wood-frame porch is noted on the 1928 Sanborn map. The shed roof of the porch is covered with asphalt shingles and is pierced by two rectangular panels (either solar panels or skylights). Square wood posts support the porch roof.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 7th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 717 and 721 7th Street, N.E. The front yard is laid with wood chips and is bounded by a hairpin and picket metal fence. A concrete walkway leads from the primary entrance and ends at the sidewalk. Wood fencing bound the rear yard. An alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Unknown			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Sliding	1-light	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood/Glass

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 719_7th_Street_NE_facade_looking_E.JPG**

Date:: Photog:
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 719_7th_Street_NE_facade_looking_NE.JPG**

Date:: Photog:
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 719_7th_Street_NE_garage_looking_NW.JPG**

Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 719_7th_Street_NE_rear_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/18/1891	2012	Build	

Permit Notes:

Missing Permit.

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0017

BASICS DATA

ID Number: **0890-0017** Year Built: **1891** Data Source: **Permit Index**

Number Extended Street Quad Type of Address

717 **7th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 717 7th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0017 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit Ind** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **c. 1890** **Site Visit/Map**

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/Canted Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891, this two-story, two-bay Queen Anne-style rowhouse is constructed of brick and is set on a solid, raised foundation. The façade (west elevation) is clad with Permastone. A watertable spans the façade and is located above the foundation. A sloping roof caps the dwelling and is fronted along the façade by a Permastone-clad parapet. The northernmost bay of the first story holds a single-leaf, replacement paneled metal door with an oval-light and a one-light wood transom. Cast iron steps with railings provide access to the door. The second story window opening holds a 1/1, double-hung, wood-sash window and is set in a segmental opening. A three-sided, canted bay rises the full height of the dwelling and projects from the southernmost bay of the façade. The canted bay has the material treatment of the main block and is capped by a pyramidal roof covered with slate shingles. A curvilinear parapet rises from the pyramidal roof and is topped by a pedimented gable that is covered with Permastone. All window openings of the bay, except the foundation, hold 1/1, double-hung, wood-sash windows. A one-light vinyl awning window pierces the foundation. All window openings on the façade have stone sills and segmental arches of Permastone. The rear (east) elevation is fenestrated with 1/1, double-hung windows.

A two-story ell extends from the northernmost bay of the rear elevation and is original. The ell is constructed of brick and is set on a solid foundation. The rear elevation is parged. A sloping roof caps the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows, which have rowlock brick sills and are set in segmental openings.

A one-story, full-width screened porch projects from the rear elevation of the ell and was constructed c. 1980. A wood-frame addition is noted on the 1928 Sanborn map. The screened porch is set on a wood pier foundation that has been covered with wood lattice. A shed roof, covered with asphalt shingles, caps the enclosed porch and is supported by square wood posts. A solid balustrade of T-111 siding partially encloses the screened porch. Wood steps provide access to a single-leaf screened wood door.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 7th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 715 and 719 7th Street, N.E. The front yard is landscaped with mature shrubs and foundation plantings and is encircled by a hairpin and picket metal fence. The rear yard is paved with concrete and is bounded by metal chain-link fencing. A public alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Permastone		Veneer	
Structure Component	Material	Feature		Source
Foundation	Unknown			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Awning	1-light	Unknown
Bay Windows	Rectangular	Dbl-Hung	1/1	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Metal/Glas

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **717_7th_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **717_7th_Street_NE_facade_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **717_7th_Street_NE_rear_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 717_7th_Street_NE_rear_looking_W.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/18/1891	2012	Build	

Permit Notes:

Missing Permit.

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0016

BASICS DATA

ID Number: **0890-0016** Year Built: **1891** Data Source: **Permit Index**

Number Extended Street Quad Type of Address

715 **7th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 715 7th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0016 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit Ind** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit Index**

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/Canted Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891, this two-story, two-bay Queen Anne-style rowhouse is constructed of brick and is set on a solid, raised foundation. The façade (west elevation) is faced with stretcher-bond brick. A four-course brick watertable spans the façade and is located above the foundation. A sloping roof caps the dwelling and is fronted along the façade by a corbeled brick cornice topped by metal cresting. A string course, composed of nebule molding, spans the façade and is sited below the cornice. The northernmost bay of the first story holds a single-leaf paneled wood door and a stained glass wood transom. A segmental arch with pearl and nailhead molding complements the door opening. Cast iron steps with railings provide access to the door. The second story window opening holds a 1/1, double-hung, vinyl-sash window. A three-sided, canted bay rises the full height of the dwelling and projects from the southernmost bay of the façade. The canted bay has the material treatment of the main block. A brick string course spans the canted bay between the first and second story windows. All window openings of the bay, except the foundation, hold 1/1, double-hung, vinyl-sash windows. The foundation is pierced by paired one-light vinyl sliding windows. The first story windows of the bay have stone sills and segmental arches with pearl and nailhead molding. The second story windows of the main block and bay have stone sills and lintels. The rear (east) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows and feature two-course, rowlock brick segmental arches and wood sills.

A two-story ell extends from the northernmost bay of the rear elevation and is original. The ell is constructed of seven-course, American-bond brick and is set on a solid foundation. The rear elevation is parged. A sloping roof caps the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf paneled wood door with lights and a one-light transom. The door and windows are set in segmental openings.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 7th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 713 and 717 7th Street, N.E. and is sited on a level lot. The front yard is landscaped with wood chips, mature shrubs and foundation plantings. A hairpin and picket metal fence bounds the front yard. A concrete walkway leads from the primary entrance of the dwelling and ends at the concrete sidewalk. Wood fencing bound the rear yard. A public alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Unknown			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Sliding	1-light	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **715_7th_Street_NE_facade_looking_E.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **715_7th_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **715_7th_Street_NE_rear_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 715_7th_Street_NE_rear_looking_W.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/18/1891	2012	Build	

Permit Notes:

Missing Permit.

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0015

BASICS DATA

ID Number: **0890-0015** Year Built: **1891** Data Source: **Permit Index**

Number Extended Street Quad Type of Address

713 **7th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 713 7th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0015 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit Ind** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit Index**

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/rectang bay**

Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Tuesday, June 25, 2013

ID_Number: 0890-0015 Page 1

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891, this two-story, two-bay Queen Anne-style rowhouse is constructed of brick and is set on a solid, raised foundation. The façade (west elevation) is faced with stretcher-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a brick parapet. A molded cornice and brick dentils complement the parapet. A string course, composed of nebule molding, spans the façade and is below the cornice. Two interior-side brick chimneys rise from the south (side) elevation and have plain concrete caps. The northernmost bay of the first story holds a single-leaf paneled wood door and a one-light wood transom. A stone lintel tops the transom. Cast iron steps and railings provide access to the primary entrance. The second story opening holds a 1/1, double-hung, vinyl-sash window, which has a stone sill and lintel. A three-sided, rectangular bay extends from the southernmost bay of the façade and rises the full height of the dwelling. The bay features chamfered corners with brick corbelling and a front-gabled brick parapet. The parapet features molded cornice returns and nebule molding. The bay is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows. The first story windows have stone sills and segmental arches with pearl and nailhead molding. The second story windows have stone sills and lintels. A blind transom of checkerboard brick with a molded round-headed arch highlights the central bay of the second story. The south (side) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows.

A two-story ell extends from the southernmost bay of the rear (east) elevation and is original. The ell is constructed of American-bond brick and is set on a solid foundation. A sloping roof caps the ell, which has a brick parapet along the south elevation. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and sliding glass doors with a one-light transom. The windows feature two-course, rowlock brick segmental arches and rowlock brick sills.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 7th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The north (side) elevation of the dwelling is adjacent to 715 7th Street, N.E. and a brick and concrete alley runs parallel to the south (side) elevation of the dwelling. The front yard is landscaped with mature shrubs and foundation plantings and is bounded by a brick retaining wall topped with milled point metal fencing. The rear yard is enclosed with wood fencing. A public alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Unknown			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **713_7th_Street_NE_cornice_detail.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **713_7th_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **713_7th_Street_NE_facade_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 713_7th_Street_NE_rear_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/18/1891	2012	Build	

Permit Notes:

Missing Permit.

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0052

BASICS DATA

ID Number: **0890-0052** Year Built: **1891** Data Source: **Permit**

Number Extended Street Quad Type of Address

711 **7th Street** **NE Current**

Name(s) Type of Name

Rowhouse, 711 7th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0052 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit** **2875 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Schneider, George A.**

Orig Construction **Builder** **Duchay, F. H.**

Orig Construction **Owner** **Schneider, George A.**

Construction Notes:

One of eight rowhouses constructed from the same permit (#1197) and one of five constructed along 7th Street, N.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891 by F.H. Duchay, this two-story, two-bay Queen Anne-style rowhouse is one of eight rowhouses constructed from the same permit (#1197) and one of five located on 7th Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (west elevation) is faced with pressed stretcher-bond brick. A brick watertable spans the façade and is located above the foundation. Brick string courses are also located below the first and second story window openings, as well as bisecting the first story windows. A sloping roof caps the dwelling and is fronted along the façade by a corbeled brick cornice. A egg-and-dart molded string course is located beneath the corbeled brick cornice. Three interior-side brick chimneys rise from the north (side) elevation. Two have corbeled brick caps. The recessed southernmost bay of the first story holds a single-leaf paneled wood door. A one-light segmental arched wood transom tops the storm door. A soldier brick segmental arch with nailhead molding tops the transom. Poured concrete steps with brick wing walls provide access to the door. A molded panel, composed of a roundel and tablet flower, is located between the first and second story openings. The second story opening holds a 1/1, double-hung, wood-sash window. A three-sided, rectangular bay projects from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and features chamfered corners with brick corbelling. The bay is fenestrated with single and paired 1/1, double-hung, wood-sash windows and one-light fixed wood windows. All window openings on the façade have concrete sills and soldier brick segmental arches with nailhead molding. The north (side) elevation is fenestrated with 2/2, double-hung, wood-sash windows and one-light wood fixed wood windows. Most openings have wood sills and two-course, rowlock brick segmental arches. The rear (east) elevation is fenestrated with 2/2, double-hung, wood-sash windows and a single-leaf paneled wood door with lights and a one-light wood transom. All openings have two-course, rowlock brick segmental arches and the windows have wood sills.

Site Notes:

January 2010: This rowhouse is located on the east side of 7th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The south (side) elevation of the dwelling is adjacent to 709 7th Street, N.E. and a paved and brick alley runs parallel to the north (side) elevation of the dwelling. The grassy front yard is landscaped with mature shrubs and is encircled by a wood picket fence. A concrete walkway leads from the primary entrance and ends at the sidewalk. Wood fencing and metal chain-link fencing bound the rear yard.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Wood
Bay Windows	Rectangular	Fixed	1-light	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **711_7th_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **711_7th_Street_NE_facade_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **711_7th_Street_NE_rear_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/02/1891	1197	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0051

BASICS DATA

ID Number: **0890-0051** Year Built: **1891** Data Source: **Permit**

Number Extended Street Quad Type of Address

709 **7th Street** **NE Current**

Name(s) Type of Name

Rowhouse, 709 7th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0051 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit** **2875 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Schneider, George A.**

Orig Construction **Builder** **Duchay, F. H.**

Orig Construction **Owner** **Schneider, George A.**

Construction Notes:

One of eight rowhouses constructed from the same permit (#1197) and one of five constructed along 7th Street, N.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Canted Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891 by F.H. Duchay, this two-story, two-bay Queen Anne-style rowhouse is one of eight rowhouses constructed from the same permit (#1197) and one of five located on 7th Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (west elevation) is faced with pressed stretcher-bond brick. A brick watertable spans the façade and is located above the foundation. Brick string courses are also located below the first and second story window openings, as well as bisecting the first and second story windows. A sloping roof caps the dwelling and is fronted along the façade by a corbeled brick cornice. An egg-and-dart molded string course is located beneath the corbeled brick cornice. The southernmost bay of the first story holds a single-leaf paneled wood door and a one-light segmental arched wood transom. A soldier brick segmental arch with nailhead molding tops the transom. Cast iron steps and railings provide access to the door. A molded panel, composed of a roundel and tablet flower, is located between the first and second story openings. The second story opening holds a 1/1, double-hung, wood-sash window. A three-sided, canted bay projects from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block. A pyramidal roof caps the bay and is covered with slate shingles. A finial complements the roof. The bay is fenestrated with 1/1, double-hung, wood-sash windows and a two-light fixed wood window. All window openings on the façade have concrete sills and soldier brick segmental arches with nailhead molding.

A two-story ell extends from the southernmost bay of the rear (east) elevation and is original. The ell is constructed of brick and is set on a solid foundation. A sloping roof caps the ell. Visible fenestration consists of a single-leaf door with a one-light transom and 2/2 and 6/6, double-hung, wood-sash windows. The second story opening features a two-course, rowlock brick segmental arch and a wood sill. A one-story, full-width porch projects from the rear elevation and has a shed roof. The roof is covered with asphalt shingles and is supported by square wood posts. Exposed rafter ends complement the roof.

Site Notes:

January 2010: This rowhouse is located on the east side of 7th Street, N.E. and is set back approximately on ten feet from the concrete sidewalk. The dwelling is adjacent to 707 and 711 7th Street, N.E. The grassy front yard is landscaped with mature shrubs and is bounded by a hairpin and picket metal fence. A concrete walkway leads from the primary entrance and ends at the sidewalk. The rear yard is bounded by wood fencing and metal chain-link fencing.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Slate		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Fixed	2 Lite	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 709_7th_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 709_7th_Street_NE_facade_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 709_7th_Street_NE_rear_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code

Roll

Frame(s)

Date

Photographer

Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/02/1891	1197	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0050

BASICS DATA

ID Number: **0890-0050** Year Built: **1891** Data Source: **Permit**

Number Extended Street Quad Type of Address

707 **7th Street** **NE Current**

Name(s) Type of Name

Rowhouse, 707 7th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0050 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit** **2875 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Schneider, George A.**

Orig Construction **Builder** **Duchay, F. H.**

Orig Construction **Owner** **Schneider, George A.**

Construction Notes:

One of eight rowhouses constructed from the same permit (#1197) and one of five constructed along 7th Street, N.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Canted Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891 by F.H. Duchay, this two-story, two-bay Queen Anne-style rowhouse is one of eight rowhouses constructed from the same permit (#1197) and one of five located on 7th Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (west elevation) is faced with pressed stretcher-bond brick. A brick watertable spans the façade and is located above the foundation. Brick string courses are also located below the first and second story window openings, as well as bisecting the first and second story windows. A sloping roof caps the dwelling and is fronted along the façade by a corbeled brick cornice. An egg-and-dart molded string course is located beneath the corbeled brick cornice. The southernmost bay of the first story holds a single-leaf wood-frame glass door and a one-light wood transom. A soldier brick segmental arch with nailhead molding tops the transom. Metal steps and railings provide access to the door. A molded panel, composed of a roundel and tablet flower, is located between the first and second story openings. The second story opening holds a 1/1, double-hung, vinyl-sash window. A three-sided, canted bay projects from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block. A pyramidal roof caps the bay and is covered with asphalt shingles. A finial complements the roof. The bay is fenestrated with 1/1, double-hung, vinyl-sash windows. All window openings on the façade have concrete sills and soldier brick segmental arches with nailhead molding.

A two-story ell extends from the southernmost bay of the rear (east) elevation and is original. The ell is constructed of seven-course, American-bond brick and is set on a solid foundation. A sloping roof caps the ell. Visible fenestration consists of a single-leaf wood-frame glass door with a one-light transom, a 1/1, double-hung, vinyl-sash window and paired one-light metal casement windows with a one-light transom. The second story window opening on the rear elevation has a two-course, rowlock brick segmental arch.

Site Notes:

January 2010: This rowhouse is located on the east side of 7th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 705 and 709 7th Street, N.E. and is set on a level lot. The landscaped front yard features wood chips, mature shrubs, and foundation plantings. The yard is enclosed with a hairpin and picket metal fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is bounded by fencing.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Asphalt		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Full Glass	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **707_7th_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **707_7th_Street_NE_facade_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **707_7th_Street_NE_rear_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/02/1891	1197	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0049

BASICS DATA

ID Number: **0890-0049** Year Built: **1891** Data Source: **Permit**

Number Extended Street Quad Type of Address

705 **7th Street** **NE Current**

Name(s) Type of Name

Rowhouse, 705 7th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0049 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit** **2875 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Schneider, George A.**

Orig Construction **Builder** **Duchay, F. H.**

Orig Construction **Owner** **Schneider, George A.**

Construction Notes:

One of eight rowhouses constructed from the same permit (#1197) and one of five constructed along 7th Street, N.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891 by F.H. Duchay, this two-story, two-bay Queen Anne-style rowhouse is one of eight rowhouses constructed from the same permit (#1197) and one of five located on 7th Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (west elevation) is faced with Permastone. A watertable spans the façade and is located above the foundation. A sloping roof caps the dwelling and is fronted along the façade by a corbeled cornice that has been covered in Permastone. A string course is located beneath the corbeled cornice. The southernmost bay of the first story holds a single-leaf paneled wood door and a one-light segmental arched wood transom. Poured concrete steps with metal railings provide access to the door. A molded panel, composed of a roundel and tablet flower, is located between the first and second story openings. The second story opening holds a 1/1, double-hung, wood-sash window. A three-sided, rectangular bay projects from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and features chamfered corners with corbeling. A pedimented roof caps the bay and has a molded cornice and decorative molding in the tympanum. The bay is fenestrated with single and paired 1/1, double-hung, wood-sash windows. All window openings on the façade have concrete sills and are set in segmental openings.

A two-story ell extends from the southernmost bay of the rear (east) elevation and is original. The ell is constructed of brick and is set on a solid brick foundation. A sloping roof caps the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf wood-frame glass door with a one-light transom. All openings are topped by two-course, rowlock brick segmental arches and the windows also have concrete sills.

Site Notes:

January 2010: This rowhouse is located on the east side of 7th Street, N.E. and is set back approximately ten feet from the concrete sidewalk. The north (side) elevation of the dwelling is adjacent to 707 7th Street, N.E. The landscaped front yard features mature shrubs, small trees and a planting bed. A hairpin and picket metal fence bounds the front yard. A concrete walkway leads from the primary entrance and ends at the sidewalk. The rear yard is bounded with fencing.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Gable	Not Visible		Not Visible	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Permastone		Veneer	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 705_7th_Street_NE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 705_7th_Street_NE_facade_looking_NNE.JPG**
Date:: Photog:
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 705_7th_Street_NE_facade_looking_SE.JPG**
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 705_7th_Street_NE_rear_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/02/1891	1197	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0048

BASICS DATA

ID Number: **0890-0048** Year Built: **1891** Data Source: **Permit**

Number	Extended	Street	Quad Type	Address
--------	----------	--------	-----------	---------

701		7th Street	NE	Current
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

Rowhouse, 701 7th Street, N.E.	Common
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0890/0048			Square/Lot	Current
------------------	--	--	-------------------	----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1891	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Orig Construction	1891	Permit			2875 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Architect	Schneider, George A.
--------------------------	------------------	-----------------------------

Orig Construction	Builder	Duchay, F. H.
--------------------------	----------------	----------------------

Orig Construction	Owner	Schneider, George A.
--------------------------	--------------	-----------------------------

Construction Notes:

One of eight rowhouses constructed from the same permit (#1197) and one of five constructed along 7th Street, N.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row Corner (1 of 4)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Multiple Bays**
Footprint: **Rectangular (w/ side bays)**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide:

Height:

Width: **32**

Depth/Length: **16**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891 by F.H. Duchay, this two-story Queen Anne-style rowhouse is one of eight rowhouses constructed from the same permit (#1197) and is one of five along 7th Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (west elevation) and south (side) elevation are faced with pressed stretcher-bond brick. A wide, brick watertable is located above the foundation. Molded string courses bisect the first and second story window openings and brick string courses are sited beneath the first and second story openings. The roofing type was not discernible from the public right-of-way. A molded cornice and corbeled brick cornice complement the roof. A beltcourse, composed of egg-and-dart-molding, encircles the dwelling beneath the corbeled brick cornice. The central bay of the façade holds a single-leaf wood door, which is topped by a blind transom. A 1/1, double-hung, vinyl-sash window is located directly north of the main entrance. A one-story, one-bay porch shelters the entrance and window and is set on a brick pier foundation. A half-hipped roof caps the porch and has overhanging eaves. Brick columns support the roof. Poured concrete steps with metal railings provide access to the entrance. The second story opening holds paired 1/1, double-hung, vinyl-sash windows. A rounded-bay projects from the southwest corner of the dwelling and rises the full height of the dwelling. The bay has the material treatment of the main block and has a flat roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows. A three-sided, canted bay projects from the northernmost bay of the façade and rises the full-height of the dwelling. The bay has the material treatment of the main block and is fenestrated with 1/1, double-hung, vinyl-sash windows. All first and second story window openings on the façade have concrete sills and soldier brick segmental arches with nailhead molding. Two-course, rowlock brick segmental arches top the windows that pierce the foundation. Additionally, molded panels composed of roundels and tablet flowers, are positioned between the first and second stories of each projecting bay. The north elevation of dwelling is parged and is fenestrated with a single-leaf fixed vinyl window and double-leaf metal-frame glass doors. The south (side) elevation has fenestration that is consistent with the façade.

Site Notes:

January 2010: This rowhouse is located on the northeast corner of 7th Street, N.E. and G Street, N.E. and is set back from the concrete and brick sidewalks approximately ten feet. The grassy front and side yards are bounded by milled point metal fencing. A concrete walkway leads from the primary entrance and ends at the sidewalk. A second concrete walkway leads around the north elevation of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	

Structure Component	Material	Feature	Source
Foundation	Brick		
Walls	Brick		
Materials Notes:			

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**
File: **701_7th_Street_NE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 701_7th_Street_NE_facade_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 701_7th_Street_NE_facade_looking_SSE.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 701_7th_Street_NE_side_looking_N.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/02/1891	1197	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0047

BASICS DATA

ID Number: **0890-0047** Year Built: **1891** Data Source: **Permit**

Number	Extended	Street	Quad Type of Address
--------	----------	--------	----------------------

700		G Street	NE Current
------------	--	-----------------	-------------------

Name(s)	Type of Name
---------	--------------

Rowhouse, 700 G Street, N.E.	Common
-------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0890/0047			Square/Lot	Current
------------------	--	--	-------------------	----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1891	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Orig Construction	1891	Permit			2875 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Architect	Schneider, George A.
--------------------------	------------------	-----------------------------

Orig Construction	Builder	Duchay, F. H.
--------------------------	----------------	----------------------

Orig Construction	Owner	Schneider, George A.
--------------------------	--------------	-----------------------------

Construction Notes:

One of eight rowhouses constructed from the same permit (#1197) and one of three constructed along G Street, N.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row (1 of 4)**
 Relate to Street: **Face on Setback Line**
 Massing: **Row Building/Circular Bay**
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **16**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891 by F.H. Duchay, this two-story, two-bay Queen Anne-style rowhouse is one of eight rowhouses constructed from the same permit (#1197) and one of three located on G Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (south elevation) is faced with pressed stretcher-bond brick that has been painted. A brick watertable spans the façade and is located above the foundation. Brick string courses are also located below the first and second story window openings. Molded string courses bisect the first and second story windows. A sloping roof caps the dwelling and is fronted along the façade by a corbeled brick cornice. An egg-and-dart molded string course is located beneath the corbeled brick cornice. A single-leaf paneled wood door with lights pierces the easternmost bay of the foundation. The easternmost bay of the first story holds double-leaf wood-frame glass door and a one-light segmental arched wood transom. A soldier brick segmental arch with nailhead molding tops the transom. Cast iron steps and railings provide access to the door. A molded panel, composed of a roundel and tablet flower, is located between the first and second story openings. The second story opening holds a 1/1, double-hung, wood-sash window. A projecting rounded bay projects from the westernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block. A conical roof caps the bay and is covered with slate shingles. A finial complements the roof. The bay is fenestrated with 1/1, double-hung, wood-sash windows. All first and second story openings on the façade have concrete sills and soldier brick segmental arches with nailhead molding. The foundation windows feature soldier brick segmental arches. The rear (north) elevation was not visible from the public right-of-way.

Site Notes:

January 2010: This rowhouse is located on the north side of G Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 701 7th Street, N.E. and 702 G Street, N.E. The front yard is landscaped with shrubs and is bounded by a hairpin and picket metal fence. A brick walkway leads from the primary entrance and ends at the sidewalk.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Slate		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			

Walls **Brick**

Materials Notes:

--

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1	Wood
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single	Paneled	Wood/Glass
Main Door	Rectangular	Double	Full Glass	Wood
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

--

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**
File: **700_G_Street_NE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**
File: **700_G_Street_NE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/02/1891	1197	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0046

BASICS DATA

ID Number: **0890-0046** Year Built: **1891** Data Source: **Permit**

Number	Extended	Street	Quad Type of Address
--------	----------	--------	----------------------

702		G Street	NE Current
------------	--	-----------------	-------------------

Name(s)	Type of Name
---------	--------------

Rowhouse, 702 G Street, N.E.	Common
-------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0890/0046			Square/Lot	Current
------------------	--	--	-------------------	----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1891	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Orig Construction	1891	Permit			2875 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Architect	Schneider, George A.
--------------------------	------------------	-----------------------------

Orig Construction	Builder	Duchay, F. H.
--------------------------	----------------	----------------------

Orig Construction	Owner	Schneider, George A.
--------------------------	--------------	-----------------------------

Construction Notes:

One of eight rowhouses constructed from the same permit (#1197) and one of three constructed along G Street, N.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row (1 of 4)**
 Relate to Street: **Face on Setback Line**
 Massing: **Row Building/Canted Bay**
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **16**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891 by F.H. Duchay, this two-story, two-bay Queen Anne-style rowhouse is one of eight rowhouses constructed from the same permit (#1197) and one of three located on G Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (south elevation) is faced with pressed stretcher-bond brick that has been painted. A brick watertable spans the façade and is located above the foundation. Brick string courses are also located below the first and second story window openings. Molded string courses bisect the first and second story windows. A sloping roof caps the dwelling and is fronted along the façade by a corbeled brick cornice. An egg-and-dart molded string course is located beneath the corbeled brick cornice. A single-leaf metal door pierces the easternmost bay of the foundation. The easternmost bay of the first story holds a replacement single-leaf paneled wood door with lights and a one-light rectangular wood transom. The transom opening was originally had a segmental arch. A soldier brick segmental arch with nailhead molding tops the transom. Metal steps and railings provide access to the door. A molded panel, composed of a roundel and tablet flower, is located between the first and second story openings. The second story opening holds a 1/1, double-hung, vinyl-sash window. A three-sided, canted bay projects from the westernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block. A pyramidal roof caps the bay and is covered with tin shingles. A finial complements the roof. The bay is fenestrated with 1/1, double-hung, vinyl-sash windows. All first and second story openings on the façade have concrete sills and soldier brick segmental arches with nailhead molding. The foundation windows feature soldier brick segmental arches. The rear (north) elevation is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows. All openings have wood sills and two-course, rowlock brick segmental arches.

Site Notes:

January 2010: This rowhouse is located on the north side of G Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 700 and 704 G Street, N.E. The front yard is landscaped with a mature tree and is bounded by a hairpin and picket metal fence. Fencing bound the rear yard.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Tin		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			

Walls **Brick**

Materials Notes:

--

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single		Metal
Main Door	Rectangular	Single	Paneled	Wood/Glass
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

--

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**
File: **702_G_Street_NE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**
File: **702_G_Street_NE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:



Caption:



Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 702_G_Street_NE_molding_detail.JPG

Date:: Photog:

Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 702_G_Street_NE_rear_looking_S.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/02/1891	1197	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0045

BASICS DATA

ID Number: **0890-0045** Year Built: **1891** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

704		G Street	NE	Current
------------	--	-----------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

Rowhouse, 704 G Street, N.E.	Common
-------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0890/0045			Square/Lot	Current
------------------	--	--	-------------------	----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1891	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Orig Construction	1891	Permit			2875 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Architect	Schneider, George A.
--------------------------	------------------	-----------------------------

Orig Construction	Builder	Duchay, F. H.
--------------------------	----------------	----------------------

Orig Construction	Owner	Schneider, George A.
--------------------------	--------------	-----------------------------

Construction Notes:

One of eight rowhouses constructed from the same permit (#1197) and one of three constructed along G Street, N.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row (1 of 3)**
 Relate to Street: **Face on Setback Line**
 Massing: **Row Building/Rectangular Bay**
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **16**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891 by F.H. Duchay, this two-story, two-bay Queen Anne-style rowhouse is one of eight rowhouses constructed from the same permit (#1197) and one of three located on G Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (south elevation) is faced with pressed stretcher-bond brick. A brick watertable spans the façade and is located above the foundation. Brick string courses are also located below the first and second story window openings. Molded string courses bisect the first and second story windows. A sloping roof caps the dwelling and is fronted along the façade by a corbeled brick cornice. An egg-and-dart molded string course is located beneath the corbeled brick cornice. A single-leaf paneled wood door pierces the easternmost bay of the foundation. The easternmost bay of the first story holds double-leaf wood doors and a one-light segmental arched wood transom. A soldier brick segmental arch with nailhead molding tops the transom. Cast iron steps and railings provide access to the door. A molded panel, composed of a roundel and tablet flower, is located between the first and second story openings. The second story opening holds a 1/1, double-hung, wood-sash window. A three-sided, rectangular bay projects from the westernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and feature chamfered corners with brick corbeling. A pyramidal roof caps the bay and is covered with tin shingles. A finial complements the roof. The bay is fenestrated with single and paired 1/1, double-hung, wood-sash windows. All first and second story openings on the façade have concrete sills and soldier brick segmental arches with nailhead molding. The foundation windows feature soldier brick segmental arches. The rear (north) elevation is partially covered with stucco and is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows. All openings have concrete sills and segmental arches.

Site Notes:

January 2010: This rowhouse is located on the north side of G Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 702 and 706 G Street, N.E. The front yard is landscaped with mature shrubs and a small tree and is bounded by a hairpin and picket metal fence. A brick walkway leads from the primary entrance and ends at the sidewalk.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Tin		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source

Foundation Brick
Walls Brick

Materials Notes:

--

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Wood
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single	Paneled	Wood
Main Door	Rectangular	Double		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**
File: **704_G_Street_NE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 704_G_Street_NE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/02/1891	1197	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0010

BASICS DATA

ID Number: **0890-0010** Year Built: **1916** Data Source: **Permit**

Number Extended Street Quad Type of Address

708 **G Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 708 G Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0010 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1916** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1916** **Permit** **3000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Jouvenal, A.H.**

Orig Construction **Builder** **Duritz, James R.**

Orig Construction **Owner** **Duritz, James R.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/front porch**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type Contributing Status

Shed

Outbuilding Notes:

January 2010: A one-story, one-bay prefabricated shed is located north of the dwelling and was constructed c. 1985. The wood-frame shed is clad with standing-seam metal and is capped by a front-gabled roof, also of standing-seam metal.

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

January 2010: Constructed in 1916 by James R. Duritz, this two-story, three-bay Colonial Revival-style single-family dwelling was designed by A.H. Jouvenal. The dwelling is constructed brick and is set on a solid brick foundation. The façade (south elevation) is faced with coursed stone. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard roof is covered with tiles and is flanked by stone-faced firewalls. A prominent overhanging eaves highlights the false mansard roof. The easternmost bay of the first story holds a single-leaf paneled metal door with lights. The door is flanked by diamond-light sidelights and is topped by a diamond-light transom. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows and have stone sills. The foundation of the dwelling is pierced by a single-leaf door and a 1/1, double-hung, vinyl-sash window. A one-story, two-bay porch spans the façade and is set on a stone pier foundation. The flat roof of the porch has overhanging eaves with dentil molding and is supported by Tuscan wood columns set on brick piers. Stone balusters encircle the porch, which is accessed via poured concrete steps with stone wing walls in the easternmost end bay. The rear (north) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows, which have wood sills and two-course, rowlock brick segmental arches.

A two-story ell extends from the easternmost bay of the rear elevation and is original. The ell is constructed of American-bond brick and is set on a solid brick foundation. A sloping roof caps the ell. An interior-side brick chimney rises from the west (side) elevation of the ell and has a parged cap. The rear elevation is fenestrated with a single-leaf paneled wood door with lights and a 1/1, double-hung, vinyl-sash window.

A two-story porch extends from the rear elevation of the ell and was constructed c. 1960. The first story of the porch is enclosed with vinyl siding and is set on a brick pier foundation that has been infilled with concrete blocks. The first story is fenestrated with a single-leaf wood door and paired 1/1, double-hung, vinyl-sash windows. A shed roof, covered with standing-seam metal, caps the second story of the porch and is supported by square wood posts with scrolled brackets. Balusters encircle the second story.

Site Notes:

January 2010: This single-family dwelling is located on the north side of G Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 704 and 710 G Street, N.E. A hairpin and picket metal fence encircles the small front yard. Metal chain-link fencing bound the grassy rear yard.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Unknown		Tile	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Stone		Coursed	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Basemt Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Pamels	Material
Basement	Rectangular	Single		Unknown
Main Door	Rectangular	Single	Paneled	Metal/Glas

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **708_G_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **708_G_Street_NE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **708_G_Street_NE_rear_looking_S.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 708_G_Street_NE_shed_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/11/1916	4319	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0064

BASICS DATA

ID Number: **0890-0064** Year Built: **c. 1989** Data Source: **DC Real Property Database**

Number Extended Street Quad Type of Address

710 **G Street** **NE** **Current**

Name(s) Type of Name

Single Dwelling, 710 G Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0064 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **c. 1989** **DC Real Pr** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **c. 1989** **DC Real Property Database**

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

January 2010: Constructed c. 1989, this two-story, three-bay single-family dwelling replaced a multi-family dwelling constructed in 1904. The dwelling is set on a solid foundation and its façade (south elevation) is faced with stretcher-bond brick. A soldier brick string course spans the façade and is located between the first and second stories. The roofing type was not visible from the public right-of-way. A false mansard roof projects from the façade and is covered with slate shingles. It features an overhanging eave. The easternmost bay of the façade holds a single-leaf metal-frame glass door and a one-light transom. A soldier brick flat arch tops the transom. Metal steps and stairs provide access to the primary entrance. All window openings on the façade hold 1/1, double-hung, metal-sash windows, which have rowlock brick sills and soldier brick flat arches. The rear (north) elevation is fenestrated with sliding wood doors, a single-leaf wood-frame glass door, double-leaf wood-frame glass doors, and a 1/1, double-hung, metal-sash window. All openings have soldier brick flat arches. A wood deck extends from the first story and has square wood balusters.

Site Notes:

January 2010: This single-family dwelling is located on the north side of G Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 708 and 712 G Street, N.E. The front yard is landscaped with small trees and foundation plantings and is encircled by a milled picket metal fence. A concrete walkway leads from the primary entrance and ends at the sidewalk. The rear yard is enclosed with wood fencing.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Metal
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Full Glass	Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 710_G_Street_NE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 710_G_Street_NE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 710_G_Street_NE_rear_looking_S.JPG
Date:: Photog:
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

--

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0063

BASICS DATA

ID Number: **0890-0063** Year Built: **1904** Data Source: **Permit**

Number Extended Street Quad Type of Address

712 **G Street** **NE Current**

Name(s) Type of Name

Rowhouse, 712 G Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0063 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multi-Family) **1904** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1904** **Permit** **6250 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Sherman Lockwood & Paschel**

Orig Construction **Builder** **Stilson, S.J.**

Orig Construction **Owner** **Ellis, Lyman F.**

Construction Notes:

Originally one of four rowhouses constructed from the same permit (#1803). 710 G Street, N.E. is not extant.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 3)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Canted Bay**

Footprint: **Rectangular**

Number Stories: **3**

Bays Wide: **2**

Height:

Width: **22**

Depth/Length: **54**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne (Classical Revival)

Exterior & Architectural Notes:

January 2010: Constructed in 1904 by S.J. Stilson, this three-story, two-bay multiple-family rowhouse was influenced by the Queen Anne and Classical Revival styles. The dwelling was originally one of four rowhouses constructed from the same permit (#1803), however, 710 G Street, N.E. is no longer standing. The dwelling is constructed of brick and is set on a solid brick foundation. The façade (south elevation) is faced with stretcher-bond brick. A brick string course spans the façade and is located beneath the second story window openings. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard roof is covered with asphalt shingles and is pierced by two shed dormers. Each dormer has a roof covered with asphalt shingles and contains a 1/1, double-hung, vinyl-sash window. A projecting molded cornice and a frieze board finish the roof. The westernmost bay of the first story holds a single-leaf paneled wood door with a two-light elliptical wood transom. The door is flanked by sidelights and a molded elliptical wood arch with impostes tops the transom. The westernmost bay of the second and third stories holds a 1/1, double-hung, vinyl-sash window and have concrete sills. A three-sided, canted bay projects from the easternmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is fenestrated with 1/1, double-hung, vinyl-sash windows. All windows have concrete sills. The first and second story windows of the bay and main block feature gauged brick arches. The rear (north) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows, a single-leaf wood-frame glass door with a one-light transom, and a single-leaf paneled wood door with a blind transom. A two-course, rowlock brick segmental arch tops all openings and the windows have concrete sills. A three-sided, canted bay projects from the westernmost bay of the rear elevation and is wood-frame construction. The bay is clad with vinyl siding and is capped by a half-hipped roof. Visible fenestration consists of tripartite windows composed of a central one-light fixed vinyl window and flanking 1/1, double-hung, vinyl-sash windows. A three-story porch extends from the rear elevation of the main block and is supported by square wood posts. Square wood balusters enclose each story of the porch.

Site Notes:

January 2010: This rowhouse is located on the north side of G Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 710 and 714 G Street, N.E. The front yard is landscaped with mature shrubs and foundation plantings. A brick walkway leads from the primary entrance and ends at the brick sidewalk. Milled point metal fencing encircles the front yard. The rear yard is enclosed with wood fencing. An alley is located north of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False) Sloped	Asphalt Not Visible		Shingled Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Dormer	Rectangular	Dbl-Hung	1/1	Vinyl
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s) _____

Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s) _____

Contributing:

Survey(s) _____

Level(s) of Investigation _____

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **712_G_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **712_G_Street_NE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **712_G_Street_NE_rear_looking_S.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/21/1904	1803	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0062

BASICS DATA

ID Number: **0890-0062** Year Built: **1904** Data Source: **Permit**

Number Extended Street Quad Type of Address

714 **G Street** **NE Current**

Name(s) Type of Name

Rowhouse, 714 G Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0062 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multi-Family) **1904** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1904** **Permit** **6250 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Sherman Lockwood & Paschel**

Orig Construction **Builder** **Stilson, S.J.**

Orig Construction **Owner** **Ellis, Lyman F.**

Construction Notes:

Originally one of four rowhouses constructed from the same permit (#1803). 710 G Street, N.E. is not extant.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 3)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Canted Bay**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **22**

Depth/Length: **54**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne (Classical Revival)

Exterior & Architectural Notes:

January 2010: Constructed in 1904 by S.J. Stilson, this three-story, two-bay multiple-family rowhouse was influenced by the Queen Anne and Classical Revival styles. The dwelling was originally one of four rowhouses constructed from the same permit (#1803), however, 710 G Street, N.E. is no longer standing. The dwelling is constructed of brick and is set on a solid brick foundation. The façade (south elevation) is faced with stretcher-bond brick. A brick string course spans the façade and is located beneath the second story window openings. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard roof is covered with asphalt shingles. A projecting molded cornice and a frieze board finish the roof. The recessed westernmost bay of the first story holds two single-leaf paneled wood doors. The opening is flanked by pilasters, which support a pediment. The westernmost bay of the second and third stories holds a 12/12, double-hung, wood-sash window and have concrete sills. A three-sided, canted bay projects from the easternmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is fenestrated with 12/12 and 9/9, double-hung, wood-sash windows. All windows have concrete sills. The first and second story windows of the bay and main block feature gauged brick arches. The rear (north) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows, 9/9, double-hung, wood-sash windows, a single-leaf door with a one-light transom, and a single-leaf paneled wood door with lights and a one-light transom. A two-course, rowlock brick segmental arch tops all openings and the windows have concrete sills. A wood deck extends from the second story entrance and is supported by square wood posts. A three-sided, canted bay projects from the westernmost bay of the rear elevation and is stuccoed. The bay is capped by a half-hipped roof. Visible fenestration consists of 9/9, double-hung, wood-sash windows.

Site Notes:

January 2010: This multiple-family rowhouse is located on the north side of G Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 712 and 716-718 G Street, N.E. The grassy front yard is enclosed with metal fencing. A brick walkway leads from the primary entrance and ends at the sidewalk. The rear yard is enclosed with wood fencing.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False) Sloped	Asphalt Not Visible		Shingled Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Bay Windows	Rectangular	Dbl-Hung	12/12	Wood
Bay Windows	Rectangular	Dbl-Hung	9/9	Wood
Facade	Rectangular	Dbl-Hung	12/12	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **714_G_Street_NE_facade_looking_N.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **714_G_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **714_G_Street_NE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 714_G_Street_NE_rear_looking_S.JPG

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/21/1904	1803	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0061

BASICS DATA

ID Number: **0890-0061** Year Built: **1904** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
716	-718	G Street	NE	Current
716		G Street	NE	Original

Name(s)	Type of Name
Rowhouse, 716 G Street, N.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
0890/0061			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Multi-Family)	1904	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1904	Permit			6250 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Sherman Lockwood & Paschel
Orig Construction	Builder	Stilson, S.J.
Orig Construction	Owner	Ellis, Lyman F.

Construction Notes:

Originally one of four rowhouses constructed from the same permit (#1803). 710 G Street, N.E is not extant.


PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 3)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Canted Bay**
Footprint: **Rectangular**

Cross Reference Notes:



Number Stories: **3**

Bays Wide: **2**

Height:

Width: **22**

Depth/Length: **54**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Garage

Outbuilding Notes:

January 2010: A one-story, one-bay garage is located north of the dwelling and was constructed c. 1980. The wood-frame garage is clad with T-111 siding and is set on a solid foundation. A front-gabled roof caps the garage and is covered with asphalt shingles. Raking wood boards are located in the upper gable end. The façade (north elevation) is pierced by a roll-up paneled metal door.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne (Classical Revival)

Exterior & Architectural Notes:

January 2010: Constructed in 1904 by S.J. Stilson, this three-story, two-bay multiple-family rowhouse was influenced by the Queen Anne and Classical Revival styles. The dwelling was originally one of four rowhouses constructed from the same permit (#1803), however, 710 G Street, N.E. is no longer standing. The dwelling is constructed of brick and is set on a solid brick foundation. The façade (south elevation) is faced with stretcher-bond brick. A brick string course spans the façade and is located beneath the second story window openings. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard roof is covered with asphalt shingles. A projecting molded cornice and a frieze board finish the roof. An interior-side brick chimney rises from the east elevation. The recessed westernmost bay of the first story holds two replacement, single-leaf paneled wood doors with lights. A two-course, rowlock brick elliptical arch highlights the opening. The westernmost bay of the second and third stories holds a 1/1, double-hung, wood-sash window and have concrete sills. A three-sided, canted bay projects from the easternmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is fenestrated with 1/1, double-hung, wood-sash windows and one-light fixed wood windows. All windows have concrete sills. The first and second story windows of the bay and main block feature gauged brick arches. The rear (north) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows and single-leaf wood-frame glass doors with one-light wood transoms. A two-course, rowlock brick segmental arch tops all openings and the windows have concrete sills. A two-story wood deck extends from the second story entrance and is supported by square wood posts. A three-sided, canted bay projects from the westernmost bay of the rear elevation and is wood-frame construction. The bay is covered with vinyl siding and is capped by a half-hipped roof. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows.

Site Notes:

January 2010: This multiple-family rowhouse is located on the north side of G Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 714 and 720 G Street, N.E. The front yard is landscaped with mature shrubs and foundation plantings and is encircled with milled point metal fencing. A brick walkway leads from the primary entrance and ends at the brick sidewalk. The rear yard is landscaped with small trees and is bounded by a wood fence.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Asphalt		Shingled	
Sloped	Not Visible		Not Visible	

Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Basemt Windows	Rectangular	Fixed	1-light	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1	Wood
Facade	Rectangular	Dbl-Hung	1/1	Wood
Door Location	Aperture Shape	Type	Pamels	Material
Main Door	Rectangular	Single	Paneled	Wood/Glass
Main Door	Rectangular	Single	Paneled	Wood/Glass

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **716-718_G_Street_NE_facade_looking_N.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 716-
718_G_Street_NE_facade_looking_NE.JPG

Date:: Photog:
Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 716-
718_G_Street_NE_garage_looking_SE.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 716-718_G_Street_NE_rear_looking_SE.JPG

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/21/1904	1803	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0060

BASICS DATA

ID Number: **0890-0060** Year Built: **1892** Data Source: **Permit**

Number	Extended	Street	Quad Type of Address
--------	----------	--------	----------------------

720		G Street	NE Current
------------	--	-----------------	-------------------

Name(s)	Type of Name
---------	--------------

Rowhouse, 720 G Street, N.E.	Common
-------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0890/0060			Square/Lot	Current
------------------	--	--	-------------------	----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1892	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Orig Construction	1892	Permit			3000 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Architect	Schneider, T. Franklin
--------------------------	------------------	-------------------------------

Orig Construction	Builder	Darby & Davis
--------------------------	----------------	--------------------------

Orig Construction	Owner	Darby & Davis
--------------------------	--------------	--------------------------

Construction Notes:

One of eight rowhouses constructed from the same permit (#1659) and one of four along G Street, N.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row (1 of 4)**
 Relate to Street: **Face on Setback Line**
 Massing: **Row Building/Rectangular Bay**
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **18**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1892 by Darby & Davis, this two-story, two-bay Queen Anne-style rowhouse is one of eight rowhouses constructed from the same permit (#1659) and is one of four located along G Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (south elevation) is faced with irregular-coursed, American-bond brick. Thin molded string courses span the façade and bisect the first and second story window openings. A third projecting string course is located beneath the second story window openings. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard roof is covered with slate shingles. A molded metal cornice and corbeled brick cornice finishes the roof. The westernmost bay of the first story holds a single-leaf paneled metal door with a semi-circular leaded light. A round-headed wood transom tops the door and is complemented by a soldier brick round-headed arch. Cast iron steps and railings provide access to the primary entrance. The second story opening holds a 1/1, double-hung, vinyl-sash window. A gauged brick segmental arch tops the window. A three-sided, rectangular bay projects from the easternmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is set on a solid, raised foundation. A pedimented roof caps the bay and is highlighted by a molded cornice with dentil molding. Additionally, a corbeled brick cornice, Greek fret molding, and brick dentils highlight the pediment. The upper gable end of the tympanum features decorative molding and is pierced by a twelve-light fixed wood window. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. Fluted pilasters divide the paired windows, which are sited in the central openings. The first story windows have concrete sills and all windows have gauged brick segmental arches. A single-leaf paneled wood door with lights pierces the foundation. The rear (north) elevation was not visible from the public right-of-way.

Site Notes:

January 2010: This rowhouse is located on the north side of G Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 716-718 G Street, N.E. and 722-722B G Street, N.E. The front yard is landscaped with mature shrubs and small trees and is bounded by a hairpin and picket metal fence.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Not Visible		Not Visible	
Mansard (False)	Slate		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source

Foundation Brick
Walls Brick

Materials Notes:

--

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single	Paneled	Wood/Glass
Main Door	Rectangular	Single	Paneled	Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**
File: **720_G_Street_NE_bay_detail.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 720_G_Street_NE_cornice_detail.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 720_G_Street_NE_facade_looking_NE.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 720_G_Street_NE_facade_looking_NW.JPG

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/10/1892	1659	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0059

BASICS DATA

ID Number: **0890-0059** Year Built: **1892** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
722	-722B	G Street	NE	Current
722		G Street	NE	Original

Name(s)	Type of Name
Rowhouse, 722 G Street, N.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
0890/0059			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1892	Permit			Original
Residential (Multi-Family)					Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1892	Permit			3000 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Schneider, T. Franklin
Orig Construction	Builder	Darby & Davis
Orig Construction	Owner	Darby & Davis

Construction Notes:

One of eight rowhouses constructed from the same permit (#1659) and one of four constructed along G Street, N.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row (1 of 4)**
 Relate to Street: **Face on Setback Line**
 Massing: **Row Building/Rectangular Bay**
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **18**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1892 by Darby & Davis, this two-story, two-bay Queen Anne-style rowhouse is one of eight rowhouses constructed from the same permit (#1659) and is one of four located along G Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (south elevation) is faced with irregular-coursed, American-bond brick. Thin molded string courses span the façade and bisect the first and second story window openings. A third projecting string course is located beneath the second story window openings. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard roof is covered with slate shingles. A molded metal cornice and corbeled brick cornice finishes the roof. A single-leaf metal door with lights pierces the westernmost bay of the foundation. The westernmost bay of the first story holds a single-leaf wood-frame glass door. A round-headed blind transom tops the door and is complemented by a soldier brick round-headed arch. Cast iron steps and railings provide access to the primary entrance. The second story opening holds a 1/1, double-hung, wood-sash window. A gauged brick segmental arch tops the window. A three-sided, rectangular bay projects from the easternmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is set on a solid, raised foundation. A pyramidal roof caps the bay and is highlighted by a molded cornice with dentil molding. Slate shingles cover the roof, which is topped by a finial. Additionally, a corbeled brick cornice, Greek fret molding, and brick dentils highlight the roof. Fenestration consists of single and paired 1/1, double-hung, wood-sash windows. Fluted pilasters divide the paired windows, which are sited in the central openings. The first story windows have concrete sills and all windows have gauged brick segmental arches. The rear (north) elevation was not visible from the public right-of-way.

Site Notes:

January 2010: This rowhouse is located on the north side of G Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 720 and 724 G Street, N.E. The front yard is bounded by hairpin and picket metal fence. The rear yard was not visible from the public right-of-way.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Slate		Shingled	
Mansard (False)	Slate		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source

Foundation Brick
Walls Brick

Materials Notes:

--

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Wood
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single		Metal/Glas
Main Door	Rectangular	Single	Full Glass	Wood
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

--

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**
File: **722-722B_G_Street_NE_door_entry.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 722-
722B_G_Street_NE_facade_looking_NE.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 722-
722B_G_Street_NE_facade_looking_NW.JPG

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/10/1892	1659	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0058

BASICS DATA

ID Number: **0890-0058** Year Built: **1892** Data Source: **Permit**

Number	Extended	Street	Quad Type of Address
--------	----------	--------	----------------------

724		G Street	NE Current
------------	--	-----------------	-------------------

Name(s)	Type of Name
---------	--------------

Rowhouse, 724 G Street, N.E.	Common
-------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0890/0058			Square/Lot	Permit
------------------	--	--	-------------------	---------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1892	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Orig Construction	1892	Permit			3000 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Architect	Schneider, T. Franklin
--------------------------	------------------	-------------------------------

Orig Construction	Builder	Darby & Davis
--------------------------	----------------	--------------------------

Orig Construction	Owner	Darby & Davis
--------------------------	--------------	--------------------------

Construction Notes:

One of eight rowhouses constructed from the same permit (#1659) and one of four constructed along G Street, N.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row (1 of 4)**
 Relate to Street: **Face on Setback Line**
 Massing: **Row Building/Rectangular Bay**
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **18**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1892 by Darby & Davis, this two-story, two-bay Queen Anne-style rowhouse is one of eight rowhouses constructed from the same permit (#1659) and is one of four located along G Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (south elevation) is faced with irregular-coursed, American-bond brick. Thin molded string courses span the façade and bisect the first and second story window openings. A third projecting string course is located beneath the second story window openings. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard roof is covered with asphalt shingles. A molded metal cornice and corbeled brick cornice finishes the roof. The westernmost bay of the foundation holds a single-leaf multi-light wood door. The westernmost bay of the first story holds a single-leaf paneled wood door with lights. A round-headed wood transom tops the door and is complemented by a gauged brick round-headed arch. Cast iron steps and railings provide access to the primary entrance. The second story opening holds a 1/1, double-hung, vinyl-sash window. A gauged brick segmental arch tops the window. A three-sided, rectangular bay projects from the easternmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is set on a solid, raised foundation. A pedimented roof caps the bay and is highlighted by a molded cornice with dentil molding. Additionally, a corbeled brick cornice, Greek fret molding, and brick dentils highlight the pediment. The upper gable end of the tympanum features decorative molding and is pierced by an eight-light fixed window. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. Fluted pilasters divide the paired windows, which are sited in the central openings. The first story windows have concrete sills and all windows have gauged brick segmental arches. The rear (north) elevation was not visible from the public right-of-way.

Site Notes:

January 2010: This rowhouse is located on the north side of G Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 722-722B and 726 G Street, N.E. A hairpin and picket metal fence bound the front yard. The rear yard was not visible from the public right-of-way.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Not Visible		Not Visible	
Mansard (False)	Asphalt		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source

Foundation Brick
Walls Brick

Materials Notes:

--

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Rectangular	Fixed	8 Lite	Unknown

Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single		Wood/Glass
Main Door	Rectangular	Single	Paneled	Wood/Glass

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **724_G_Street_NE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 724_G_Street_NE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/10/1892	1659	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0057

BASICS DATA

ID Number: **0890-0057** Year Built: **1892** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
726		G Street	NE	Current
700		8th Street	NE	Alternate
702		8th Street	NE	Alternate

Name(s)	Type of Name
Rowhouse, 726 G Street, N.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
0890/0057			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1892	Permit			Original
Dwelling & Store					Historic
Residential (Multi-Family)					Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Garage	c. 1930	Site Visit/Map			
Orig Construction	1892	Permit			3000 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Schneider, T. Franklin
Orig Construction	Builder	Darby & Davis
Orig Construction	Owner	Darby & Davis

Construction Notes:

One of eight rowhouses constructed from the same permit (#1659) and one of four constructed along G Street, N.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row Corner (1 of 4)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Circular Bay**
Footprint: **Rectangular (w/ side bays)**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **18**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1892 by Darby & Davis, this two-story, two-bay Queen Anne-style rowhouse is one of eight rowhouses constructed from the same permit (#1659) and is one of four located along G Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (south elevation) is faced with irregular-coursed, American-bond brick. Thin molded string courses span the façade and east (side) elevation and bisect the first and second story window openings. A third projecting string course is located beneath the second story window openings. A sloping roof caps the dwelling and is fronted along the façade and east elevation by a false mansard roof. The false mansard roof is covered with slate shingles. A molded metal cornice and corbeled brick cornice finishes the roof. The westernmost bay of the first story of the facade holds a single-leaf paneled metal door. A round-headed wood transom tops the door and is complemented by a gauged brick round-headed arch. Cast iron steps and railings provide access to the primary entrance. The second story opening holds a 1/1, double-hung, wood-sash window. A gauged brick segmental arch tops the window. A rounded bay projects from the southeast corner of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is set on a solid, raised foundation. A conical roof of slate shingles caps the bay and is highlighted by a molded cornice with dentil molding. A frieze, composed of staggered projecting bricks, complements the roof. Fenestration consists of 1/1, double-hung, wood-sash windows. A string course, composed of square billet molding, encircles the bay below the second story window openings. All windows have stone sills and concrete lintels. The foundation of the east elevation is fenestrated with a single-leaf paneled metal door, which is flanked by 1/1, double-hung, vinyl-sash windows. A two-story, rectangular bay projects from the northernmost bay of the east elevation and is original. The bay has the material treatment of the main block and is set on a solid, raised foundation. A pyramidal roof caps the bay and is covered with slate shingles. Fenestration consists of paired 1/1, double-hung, vinyl-sash windows and 1/1, double-hung, vinyl-sash windows. All windows have concrete sills and gauged brick segmental arches.

A one-story garage extends from the easternmost bay of the rear (north) elevation and was constructed c. 1930. The garage was rehabilitated as a store by 1960 as noted on the 1960 Sanborn map. The garage is constructed of six-course, American-bond brick and is set on a solid foundation. A sloping roof caps the garage and is fronted along the façade (east elevation) by a brick parapet. Concrete diamond-shaped panels flank a rectangular panel on the parapet. The northernmost bay contains a single-leaf paneled wood door and a one-light wood transom. Dentil molding divides the door from the transom. A one-story, one-bay projection extends from the southernmost bay and is constructed of concrete block. The concrete block is faced with stretcher-bond brick and is capped by a shed roof covered with asphalt shingles. Fenestration consists of fixed two-light windows, which have rowlock brick sills.

Site Notes:

January 2010: This rowhouse is located on the northwest corner of G Street, N.E. and 8th Street, N.E. and is set back approximately five feet from the brick sidewalk. The west (side) elevation is adjacent to 724 G Street, N.E. The front and side yards are landscaped with mature shrubs and foundation plantings and are bounded by wood picket fencing. A concrete walkway leads from the entrance on the east (side) elevation.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Slate		Shingled	
Mansard (False)	Slate		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 726_G_Street_NE_700_8th_Street_NE_bay_de
tail.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 726_G_Street_NE_700_8th_Street_NE_door_e
ntry.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 726_G_Street_NE_700_8th_Street_NE_facade
_looking_N.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 726_G_Street_NE_700_8th_Street_NE_facade
_looking_NE.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 726_G_Street_NE_700_8th_Street_NE_facade
_looking_NW.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 726_G_Street_NE_700_8th_Street_NE_side_lo
oking_W.JPG

Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 726_G_Street_NE_700_8th_Street_NE_side_lo
oking_WNW.JPG

Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 726_G_Street_NE_702_8th_Street_NE_facade
_looking_NW.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 726_G_Street_NE_702_8th_Street_NE_facade
_looking_SW.JPG

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/10/1892	1659	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0056

BASICS DATA

ID Number: **0890-0056** Year Built: **1892** Data Source: **Permit**

Number Extended Street Quad Type of Address

704 **8th Street** **NE Current**

Name(s) Type of Name

Rowhouse, 704 8th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0056 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1892** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1892** **Permit** **3000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Schneider, T. Franklin**

Orig Construction **Builder** **Darby & Davis**

Orig Construction **Owner** **Darby & Davis**

Construction Notes:

One of eight rowhouses constructed from the same permit (#1659) and one of four constructed along 8th Street, N.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1892 by Darby & Davis, this two-story, two-bay Queen Anne-style rowhouse is one of eight rowhouses constructed from the same permit (#1659) and is one of four located along 8th Street, N.E. The dwelling is constructed of seven-course, American-bond brick and is set on a solid, raised brick foundation. The façade (east elevation) is faced with irregular-coursed, American-bond brick. Thin molded string courses span the façade and bisect the first and second story window openings. A third projecting string course is located beneath the second story window openings. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard roof is covered with slate shingles. A molded metal cornice and corbeled brick cornice finishes the roof. The westernmost bay of the first story holds a single-leaf paneled wood door. A round-headed wood transom tops the door and is complemented by a gauged brick round-headed arch. Cast iron steps and railings provide access to the primary entrance. The second story opening holds a 1/1, double-hung, vinyl-sash window with false 6/6 vinyl muntins. A gauged brick segmental arch tops the window. A three-sided, rectangular bay projects from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is set on a solid, raised foundation. A pedimented roof caps the bay and is highlighted by a molded cornice with dentil molding. Additionally, a corbeled brick cornice, Greek fret molding, and brick dentils highlight the pediment. The upper gable end of the tympanum features decorative molding and is pierced by a fixed window. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows with false 4/4 and 6/6 vinyl muntins. Fluted pilasters divide the paired windows, which are sited in the central openings. Two-light fixed vinyl windows pierce the foundation. The first story windows have concrete sills and all windows have gauged brick segmental arches. The rear (north) elevation was not visible from the public right-of-way.

A two-story ell extends from the southernmost bay of the rear elevation and is original. The ell is constructed of American-bond brick and is set on a solid foundation. A sloping roof caps the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows, which have two-course, rowlock brick segmental arches.

Site Notes:

January 2010: This rowhouse is located on the west side of 8th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 702 and 706 8th Street, N.E. The front yard is landscaped with small shrubs and is bounded by a chain-link metal fence. The rear yard was not discernible from the public right-of-way.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Not Visible		Not Visible	
Mansard (False)	Slate		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Rectangular	Fixed	Unknown	Unknown
Bay Windows	Rectangular	Fixed	2 Lite	Vinyl

Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood
Notable Interior Plan(s)			Notable Interior Feature(s)	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 704_8th_Street_NE_bay_detail.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 704_8th_Street_NE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 704_8th_Street_NE_facade_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 704_8th_Street_NE_rear_loking_SE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/10/1892	1659	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0055

BASICS DATA

ID Number: **0890-0055** Year Built: **1892** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

706		8th Street	NE	Current
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

Rowhouse, 706 8th Street, N.E.	Common
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0890/0055			Square/Lot	Current
------------------	--	--	-------------------	----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1892	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Orig Construction	1892	Permit			3000 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Architect	Schneider, T. Franklin
--------------------------	------------------	-------------------------------

Orig Construction	Builder	Darby & Davis
--------------------------	----------------	--------------------------

Orig Construction	Owner	Darby & Davis
--------------------------	--------------	--------------------------

Construction Notes:

One of eight rowhouses constructed from the same permit (#1659) and one of four along 8th Street, N.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row (1 of 4)**
 Relate to Street: **Face on Setback Line**
 Massing: **Row Building/Rectangular Bay**
 Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **18**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1892 by Darby & Davis, this two-story, two-bay Queen Anne-style rowhouse is one of eight rowhouses constructed from the same permit (#1659) and is one of four located along 8th Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (east elevation) is faced with irregular-coursed, American-bond brick. Thin molded string courses span the façade and bisect the first and second story window openings. A third projecting string course is located beneath the second story window openings. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard roof is covered with asphalt shingles. A molded metal cornice and corbeled brick cornice finishes the roof. The southernmost bay of the first story holds a replacement, single-leaf paneled wood door with lights. A round-headed blind transom tops the door and is complemented by a soldier brick round-headed arch. Cast iron steps and railings provide access to the primary entrance. The second story opening holds a 1/1, double-hung, vinyl-sash window with false 6/9 vinyl muntins. A gauged brick segmental arch tops the window. A three-sided, rectangular bay projects from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is set on a solid, raised foundation. A pyramidal roof caps the bay and is highlighted by a molded cornice with dentil molding. Asphalt shingles cover the roof, which is topped by a finial. Additionally, a corbeled brick cornice, Greek fret molding, and brick dentils highlight the roof. A string course of square billet molding encircles the bay beneath the second story window openings. Double-leaf multi-light vinyl doors pierce the foundation. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows with false 6/9 vinyl muntins. Fluted pilasters divide the paired windows, which are sited in the central openings. The first story windows have concrete sills and all windows have gauged brick segmental arches. The rear (west) elevation was not visible from the public right-of-way.

Site Notes:

January 2010: This rowhouse is located on the west side of 8th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 704 and 708 8th Street, N.E. The front yard has been laid with brick and is enclosed by a hairpin and picket metal fence. The rear yard was not visible from the public right-of-way.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Asphalt		Shingled	
Mansard (False)	Asphalt		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	

Structure Component	Material	Feature	Source
Foundation	Brick		
Walls	Brick		
Materials Notes:			

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Double		Vinyl/Glass
Main Door	Rectangular	Single	Paneled	Wood/Glass
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**
File: **706_8th_Street_NE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 706_8th_Street_NE_facade_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/10/1892	1659	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0054

BASICS DATA

ID Number: **0890-0054** Year Built: **1892** Data Source: **Permit**

Number Extended Street Quad Type of Address

708 **8th Street** **NE Current**

Name(s) Type of Name

Rowhouse, 708 8th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0054 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1892** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1892** **Permit** **3000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Schneider, T. Franklin**

Orig Construction **Builder** **Darby & Davis**

Orig Construction **Owner** **Darby & Davis**

Construction Notes:

One of eight rowhouses constructed from the same permit (#1659) and one of four constructed along 8th Street, N.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1892 by Darby & Davis, this two-story, two-bay Queen Anne-style rowhouse is one of eight rowhouses constructed from the same permit (#1659) and is one of four located along 8th Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (east elevation) is faced with irregular-coursed, American-bond brick. Thin molded string courses span the façade and bisect the first and second story window openings. A third projecting string course is located beneath the second story window openings. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard roof is covered with asphalt shingles. A molded metal cornice and corbeled brick cornice finishes the roof. A single-leaf paneled wood door with lights pierces the southernmost bay of the first story. A round-headed transom tops the door and is complemented by a gauged brick round-headed arch. Cast iron steps and railings provide access to the primary entrance. The second story opening holds a 1/1, double-hung, vinyl-sash window. A gauged brick segmental arch tops the window. A three-sided, rectangular bay projects from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is set on a solid, raised foundation. A pyramidal roof caps the bay and is highlighted by a molded cornice with dentil molding. Asphalt shingles cover the roof, which is topped by a finial. Additionally, a corbeled brick cornice, Greek fret molding, and brick dentils highlight the roof. A string course of square billet molding encircles the bay beneath the second story window openings. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. Fluted pilasters divide the paired windows, which are sited in the central openings. The first story windows have concrete sills and all first and second windows have gauged brick segmental arches. Soldier brick segmental arches top the foundation windows. The rear (west) elevation was not visible from the public right-of-way.

A two-story ell extends from the southernmost bay of the rear elevation and is original. The ell is constructed of American-bond brick and is set on a solid foundation. A sloping roof caps the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows, which have concrete sills and two-course, rowlock brick segmental arches.

Site Notes:

January 2010: This rowhouse is located on the west side of 8th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 706 and 710 8th Street, N.E. The front yard is landscaped with small trees and shrubs and is bounded with a hairpin and picket metal fence. The rear yard was not discernible from the public right-of-way.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Asphalt		Shingled	
Mansard (False)	Asphalt		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material

Main Door Rectangular Single Paneled Wood/Glass

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\

File: 708_8th_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\

File: 708_8th_Street_NE_facade_looking_W.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\

File: 708_8th_Street_NE_rear_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/10/1892	1659	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0053

BASICS DATA

ID Number: **0890-0053** Year Built: **1892** Data Source: **Permit**

Number Extended Street Quad Type of Address

710 **8th Street** **NE Current**

Name(s) Type of Name

Rowhouse, 710 8th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0053 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1892** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1892** **Permit** **3000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Schneider, T. Franklin**

Orig Construction **Builder** **Darby & Davis**

Orig Construction **Owner** **Darby & Davis**

Construction Notes:

One of eight rowhouses constructed from the same permit (#1659) and one of four constructed along 8th Street, N.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1892 by Darby & Davis, this two-story, two-bay Queen Anne-style rowhouse is one of eight rowhouses constructed from the same permit (#1659) and is one of four located along 8th Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (east elevation) is faced with irregular-coursed, American-bond brick. Thin molded string courses span the façade and bisect the first and second story window openings. A third projecting string course is located beneath the second story window openings. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard roof is covered with slate shingles. A molded metal cornice and corbeled brick cornice finishes the roof. Two interior-side brick chimneys rise from the north (side) elevation and have corbeled brick caps. The southernmost bay of the first story holds a replacement, single-leaf wood door with a semi-circular light. A round-headed wood transom tops the door and is complemented by a gauged brick round-headed arch. Cast iron steps and railings provide access to the primary entrance. The second story opening holds a 1/1, double-hung, vinyl-sash window. A gauged brick segmental arch tops the window. A three-sided, rectangular bay projects from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is set on a solid, raised foundation. A pedimented roof caps the bay and is highlighted by a molded cornice with dentil molding. Additionally, a corbeled brick cornice, Greek fret molding, and brick dentils highlight the pediment. The upper gable end of the tympanum features decorative molding and is pierced by a twelve-light wood window (possibly fixed). Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. Fluted pilasters divide the paired windows, which are sited in the central openings. Paired one-light vinyl sliding windows pierce the foundation. The first story windows have concrete sills and all first and second story windows have gauged brick segmental arches. Soldier brick segmental arches top the foundation windows. The north (side) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows, which have concrete sills and two-course, rowlock brick segmental arches. The rear (west) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows and a single-leaf multi-light wood door. All openings have two-course, rowlock brick segmental arches and the windows also have concrete sills.

Site Notes:

January 2010: This rowhouse is located on the west side of 8th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The south (side) elevation of the dwelling is adjacent to 708 8th Street, N.E. A concrete alley travels parallel to the north (side) elevation. The front yard is landscaped with mature shrubs and small trees. A concrete walkway leads from the primary entrance and ends at the sidewalk. The rear yard is enclosed with wood fencing.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Not Visible		Not Visible	
Mansard (False)	Slate		Shingled	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Fixed	12 Lite	Wood
Bay Windows	Rectangular	Sliding	1-light	Vinyl

Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood
Notable Interior Plan(s)		Notable Interior Feature(s)		
Interior Notes:				

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 710_8th_Street_NE_cornice_detail.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 710_8th_Street_NE_facade_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 710_8th_Street_NE_facade_looking_W.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 710_8th_Street_NE_rear_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/10/1892	1659	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0066

BASICS DATA

ID Number: **0890-0066** Year Built: **1891** Data Source: **Permit**

Number Extended Street Quad Type of Address

712 **8th Street** **NE Current**

Name(s) Type of Name

Rowhouse, 712 8th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0066 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit** **2750 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Thompson, A.**

Orig Construction **Owner** **Buckert, John I.**

Construction Notes:

One of four rowhouses constructed from the same permit (#2632)

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **33**

SqFt:

Volume:

Lot Width


Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:



Outbuilding Type

Contributing Status

Garage

Outbuilding Notes:

January 2010: Constructed c. 1925, this one-story, one-bay garage is located west of the dwelling. The garage is masonry construction and is parged. A sloping roof with metal flashing caps the garage. The façade (west elevation) is pierced by a swing-out metal door, which is topped by a wood lintel.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891 by A. Thompson, this two-story, two-bay Queen Anne-style single-family rowhouse is one of four rowhouses constructed from the same permit (#2632). The dwelling is constructed of seven-course, American-bond brick and is set on a solid brick foundation. The façade (east elevation) is faced with pressed stretcher-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a molded cornice and a corbeled brick cornice. Three interior-side brick chimneys rise from the south (side) elevation and have corbeled brick caps. The northernmost bay of the first story holds a single-leaf paneled wood door and a one-light transom. A soldier brick segmental arch with molded brick tops the transom. Brick steps with brick wing walls provides access to the primary entrance. The second story opening holds a 1/1, double-hung, metal-sash window. A three-sided, rectangular bay extends from the southernmost bay of the façade and extends the full height of the dwelling. The bay has the material treatment of the main block and is fenestrated with single and paired 1/1, double-hung, metal-sash windows and two-light metal sliding metal windows. All first and second story openings on the façade have concrete sills and soldier brick segmental arches with molded brick. The foundation window has a stone lintel and sill. The south elevation is fenestrated with 1/1, double-hung, metal-sash windows, which have concrete sills and two-course, rowlock brick segmental arches. The rear (west) elevation is parged and is fenestrated with 1/1, double-hung, metal-sash windows and a single-leaf paneled wood door with lights and a one-light vinyl transom. The windows are set in segmental openings and have wood sills.

Site Notes:

January 2010: This rowhouse is located on the west side of 8th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The north (side) elevation of the dwelling is adjacent to 714 8th Street, N.E. A concrete alley runs parallel to the south (side) elevation of the dwelling. The front yard is landscaped with mature shrubs and is bounded by hairpin and picket metal fencing. A concrete and brick walkway leads from the primary entrance and ends at the sidewalk. The rear yard is bounded by wood fencing.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Metal
Bay Windows	Rectangular	Dbl-Hung	1/1	Metal
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Metal
Bay Windows	Rectangular	Sliding	2 Lite	Metal
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890

File: **712_8th_Street_NE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890

File: **712_8th_Street_NE_facade_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890

File: **712_8th_Street_NE_garage_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 712_8th_Street_NE_rear_looking_ENE.JPG

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/22/1891	2632	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0065

BASICS DATA

ID Number: **0890-0065** Year Built: **1891** Data Source: **Permit**

Number Extended Street Quad Type of Address

714 **8th Street** **NE Current**

Name(s) Type of Name

Rowhouse, 714 8th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0065 **Square/Lot** **Permit**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit** **2750 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Thompson, A.**

Orig Construction **Owner** **Buckert, John I.**

Construction Notes:

One of four rowhouses constructed from the same permit (#2632).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **33**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Garage

Outbuilding Notes:

January 2010: Constructed c. 1925, this one-story, one-bay garage is located west of the dwelling and opens onto the alley. The garage is constructed of brick and is parged. A sloping roof caps the garage and is complemented by metal flashing. The vehicular opening on the façade (west elevation)

has been enclosed with T-111 siding. A single-leaf metal door pierces the T-111 siding.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891 by A. Thompson, this two-story, two-bay Queen Anne-style single-family rowhouse is one of four rowhouses constructed from the same permit (#2632). The dwelling is constructed of brick and is set on a solid brick foundation. The façade (east elevation) is faced with pressed stretcher-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a molded metal cornice and a corbeled brick cornice. The northernmost bay of the first story holds a replacement, single-leaf paneled wood door with leaded lights and a one-light transom. A soldier brick segmental arch with molded brick tops the transom. Cast iron steps and railings provide access to the primary entrance. The second story opening holds a 6/6, double-hung, wood-sash window. A three-sided, rectangular bay extends from the southernmost bay of the façade and extends the full height of the dwelling. The bay has the material treatment of the main block and is fenestrated with single and paired 6/6, double-hung, wood-sash windows and paired one-light sliding and casement windows. All first and second story openings on the façade have concrete sills and soldier brick segmental arches with molded brick. The foundation window has a concrete sill and lintel. The rear (west) elevation was not visible from the public right-of-way.

A two-story ell extends from the northernmost bay of the rear elevation and is original. The ell is constructed of brick and is set on a solid foundation. The rear elevation has been stuccoed. A sloping roof caps the ell. Visible fenestration consists of 6/6, double-hung, wood-sash windows and a single-leaf multi-light wood door with a one-light transom. All windows are set in segmental openings and have sills.

Site Notes:

January 2010: This rowhouse is located on the west side of 8th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 712 and 716 8th Street, N.E. The small front yard is landscaped with mature shrubs and is bounded by a hairpin and picket metal fence. A concrete walkway leads from the primary entrance and ends at the sidewalk. The rear yard is enclosed with wood fencing. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	6/6	Wood
Bay Windows	Rectangular	Casement	1-light	Unknown
Bay Windows	Rectangular	Dbl-Hung	6/6	Wood
Bay Windows	Rectangular	Dbl-Hung	6/6 Double	Wood
Bay Windows	Rectangular	Sliding	1-light	Unknown
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood/Glass

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **714_8th_Street_NE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **714_8th_Street_NE_facade_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **714_8th_Street_NE_facade_looking_W.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 714_8th_Street_NE_garage_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 714_8th_Street_NE_rear_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/22/1891	2632	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0042

BASICS DATA

ID Number: **0890-0042** Year Built: **1891** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

716		8th Street	NE	Current
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

Rowhouse, 716 8th Street, N.E.	Common
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0890/0042			Square/Lot	Current
------------------	--	--	-------------------	----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1891	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Rear Addition	c. 1920	Site Visit/Map			
----------------------	----------------	-----------------------	--	--	--

Orig Construction	1891	Permit			2750 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Builder	Thompson, A.
--------------------------	----------------	---------------------

Orig Construction	Owner	Buckert, John I.
--------------------------	--------------	-------------------------

Construction Notes:

One of four rowhouses constructed from the same permit (#2632).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 4)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Rectangular Bay**
Footprint: **L-Shaped**

Cross Reference Notes:



Number Stories: **3 plus basement**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **33**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Garage

Outbuilding Notes:

January 2010: Constructed c. 1925, this one-story, one-bay garage is located west of the dwelling. The garage is constructed of five-course, American-bond brick and is set on a solid brick foundation. The south (side) elevation has been partially reinforced with concrete blocks. A sloping roof caps the garage. A roll-up paneled metal door pierces the façade (west elevation) and is topped by a lintel.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891 by A. Thompson, this three-story, two-bay Queen Anne-style single-family rowhouse is one of four rowhouses constructed from the same permit (#2632). The dwelling is constructed of brick and is set on a solid brick foundation. The façade (east elevation) is faced with pressed stretcher-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a molded metal cornice and a corbeled brick cornice. An interior-side brick chimney rises from the south (side) elevation and has corbeled brick cap. A single-leaf paneled metal door with lights pierces the northernmost bay of the foundation. The northernmost bay of the first story holds outer and inner doors. The outer single-leaf wood-frame glass door shelters the recessed single-leaf paneled wood door with lights. A one-light wood transom tops the bay and is complemented by a soldier brick segmental arch with molded brick. Cast iron steps provide access to the primary entrance. The second and third story openings hold 1/1, double-hung, vinyl-sash windows. A three-sided, rectangular bay extends from the southernmost bay of the façade and extends the full height of the dwelling. The bay has the material treatment of the main block and is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows. All window openings on the façade (except the foundation) have concrete sills and soldier brick segmental arches with molded brick. The foundation window has a concrete lintel and sill. The rear (west) elevation was not visible from the public right-of-way.

A three-story ell extends from the northernmost bay of the rear elevation and is original. The ell is constructed of American-bond brick and is set on a solid foundation. A sloping roof caps the ell and features an interior-side brick chimney along the north elevation. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and single-leaf paneled wood doors with lights. All openings have two-course, rowlock brick segmental arches and concrete sills.

A one-story, full-width addition is located on the rear elevation of the ell and was constructed c. 1920. The addition is constructed of brick and is set on a solid foundation. The rear elevation is parged. A sloping roof caps the addition. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf paneled metal door with lights.

Site Notes:

January 2010: This rowhouse is located on the west side of 8th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 714 and 718 8th Street, N.E. The small front yard is landscaped with mature shrubs and is enclosed with hairpin and picket metal fencing. A concrete walkway leads from the primary entrance and ends at the concrete sidewalk. The rear yard is enclosed with fencing. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Facade Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panel(s)	Material
Basement	Rectangular	Single	Paneled	Wood/Glass
Main Door	Rectangular	Recessed	Paneled	Wood/Glass
Main Door	Rectangular	Single	Full Glass	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**
File: **716_8th_Street_NE_door_entry.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 716_8th_Street_NE_facade_looking_nW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 716_8th_Street_NE_facade_looking_W.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 716_8th_Street_NE_garage_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 716_8th_Street_NE_rear_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/22/1891	2632	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0041

BASICS DATA

ID Number: **0890-0041** Year Built: **1891** Data Source: **Permit**

Number Extended Street Quad Type of Address

718 **8th Street** **NE Current**

Name(s) Type of Name

Rowhouse, 718 8th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0041 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit** **2750 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Thompson, A.**

Orig Construction **Owner** **Buckert, John I.**

Construction Notes:

One of four rowhouses constructed from the same permit (#2632).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **33**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Garage

Outbuilding Notes:

January 2010: Constructed c. 1925, this one-story, one-bay garage is located west of the dwelling. The wood-frame garage is clad with corrugated metal and is set on a solid concrete foundation. A sloping roof, covered with corrugated metal, caps the garage. The façade (west elevation) is pierced by

double-leaf folding metal doors.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891 by A. Thompson, this two-story, two-bay Queen Anne-style single-family rowhouse is one of four rowhouses constructed from the same permit (#2632). The dwelling is constructed of brick and is set on a solid brick foundation. The façade (east elevation) is faced with pressed stretcher-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a molded metal cornice and a corbeled brick cornice. The northernmost bay of the first story holds a single-leaf paneled wood door and a one-light transom. A soldier brick segmental arch with molded brick tops the transom. Cast iron steps with railings provides access to the primary entrance. The second story opening holds a 1/1, double-hung, wood-sash window. A three-sided, rectangular bay extends from the southernmost bay of the façade and extends the full height of the dwelling. The bay has the material treatment of the main block and is fenestrated with single and paired 1/1, double-hung, wood-sash windows. The foundation opening has been boarded with plywood. All first and second story openings on the façade have concrete sills and soldier brick segmental arches with molded brick. The rear (west) elevation was not visible from the public right-of-way.

A two-story ell extends from the northernmost bay of the rear elevation and is original. The ell is constructed of brick and is set on a solid foundation. The ell is stuccoed and is capped by a sloping roof. Visible fenestration consists of 1/1, double-hung, wood-sash windows, a two-light wood window, a single-leaf door with a boarded transom, and a single-leaf wood door. All fenestration is set in a segmental opening. The windows have sill. Metal steps provide access to the first and second story entrances.

Site Notes:

January 2010: This rowhouse is located on the west side of 8th Street, N.E. and set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 716 and 720 8th Street, N.E. A hairpin and picket metal fence encircles the grassy front yard. A brick alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0890

File: **718_8th_Street_NE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0890

File: **718_8th_Street_NE_facade_looking_W.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0890

File: **718_8th_Street_NE_garage_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 718_8th_Street_NE_rear_looking_E.JPG

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/22/1891	2632	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0040

BASICS DATA

ID Number: **0890-0040** Year Built: **1892** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

720		8th Street	NE	Current
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

Single Dwelling, 720 8th Street, N.E.	Common
--	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0890/0040			Square/Lot	Current
------------------	--	--	-------------------	----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1892	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Rear Addition	c. 1980	Site Visit/Map			
----------------------	----------------	-----------------------	--	--	--

Orig Construction	1892	Permit			3000 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Owner	Mitchell, John, Jr.
--------------------------	--------------	----------------------------

Rodbird, James A.	Builder	Rodbird, James A.
--------------------------	----------------	--------------------------

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Face on Setback Line**
Massing: **Vertical Box/rectang bay**
Footprint: **L-Shaped**

Cross Reference Notes:



Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Carport

Outbuilding Notes:

January 2010: A carport, constructed c. 1960, is located west of the dwelling. A flat roof caps the carport and is covered with corrugated metal. Square wood posts with wood knee brackets support the roof.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1892 by James A. Rodbird, this two-story, two-bay Queen Anne-style single-family dwelling was constructed from permit #1867. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (east elevation) is covered with Permastone. A sloping roof caps the dwelling and is fronted along the façade by a molded metal cornice. A single-leaf wood door with a diamond-light pierces the northernmost bay of the foundation. The northernmost bay of the façade holds a single-leaf paneled wood door and a one-light wood transom. Cast iron steps with railings provide access to the primary entrance. The second story opening holds a 1/1, double-hung, vinyl-sash window. A three-sided, rectangular bay extends from the southernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows. All openings on the façade have segmental arches composed of Permastone. The rear (west) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows, which have two-course, rowlock brick segmental arches.

A two-story ell extends from the northernmost bay of the rear elevation and is original. The ell is constructed of brick and is set on a solid foundation. A sloping roof caps the ell.

A two-story, full-width enclosed porch is located on the rear elevation of the ell and was constructed c. 1980. A two-story porch is noted on the 1928 Sanborn map. The wood-frame enclosed porch is clad with vinyl siding and is set on a brick pier foundation. A sloping roof with overhanging eaves caps the enclosed porch. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows, sliding one-light vinyl windows and a single-leaf wood door with a diamond light.

Site Notes:

January 2010: This single-family dwelling is located on the west side of 8th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 718 and 722 8th Street, N.E. Hairpin and picket metal fencing bound the small front yard. The rear yard is bounded by wood fencing. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Permastone		Veneer	
Structure Component	Material	Feature		Source
Foundation	Brick			

Walls **Brick**

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	DbI-Hung	1/1	Vinyl
Bay Windows	Rectangular	DbI-Hung	1/1	Vinyl
Bay Windows	Rectangular	DbI-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single		Wood/Glass
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **720_8th_Street_NE_carport_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **720_8th_Street_NE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 720_8th_Street_NE_facade_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 720_8th_Street_NE_rear_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/02/1892	1867	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Updated
2/12/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0039

BASICS DATA

ID Number: **0890-0039** Year Built: **1892** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

722		8th Street	NE	Current
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

Single Dwelling, 722 8th Street, N.E.	Common
--	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0890/0039			Square/Lot	Current
------------------	--	--	-------------------	----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1892	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Rear Addition	c. 2005	Site Visit/Map			
----------------------	----------------	-----------------------	--	--	--

Orig Construction	1892	Permit			3000 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Orig Construction	Builder	Rodbird, James A.
--------------------------	----------------	--------------------------

Orig Construction	Owner	Reed, George F.
--------------------------	--------------	------------------------

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Face on Setback Line**
Massing: **Vertical Box/rectang bay**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **16**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1892 by James A. Rodbird, this two-story, two-bay Queen Anne-style single-family dwelling was constructed from permit #1868. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The façade (east elevation) is faced with stretcher-bond brick. Soldier brick string courses span the façade and are located above the foundation, first and second story window openings. The first and second story string courses are also flanked by header bricks. A sloping roof caps the dwelling. A corbeled brick cornice highlights the roof. The northernmost bay of the foundation is pierced by a replacement, single-leaf paneled wood door with a three-light transom. The first story is also pierced by a replacement, single-leaf paneled wood door with a three-light transom. A soldier brick flat arch with molded brick tops the transom. Metal stairs provide access to the first story entrance. The second story opening holds a 1/1, double-hung, wood-sash window. A three-sided, rectangular bay extends from the southernmost bay of the façade and it rises the full height of the dwelling. The bay has the material treatment of the main block and is fenestrated with single and paired 1/1, double-hung, wood-sash windows. All window openings on the façade have soldier brick flat arches with molded brick and rowlock brick sills.

A two-story ell extends from the northernmost bay of the rear elevation and is original. The ell is constructed of brick and is capped by a sloping roof.

A two-story, full-width addition is located on the rear elevation of the ell and was constructed c. 2005. The addition is constructed of concrete blocks and is set on a solid, raised concrete block foundation. A sloping roof caps the addition. The rear elevation is clad with Hardiplank siding. Visible fenestration consists of two single-leaf paneled metal doors with a three-light vinyl transoms and 1/1, double-hung, vinyl-sash windows. All openings have square-edged surrounds with bulls-eye corner blocks. Metal stairs provide access to the first story entrance on the rear elevation.

Site Notes:

January 2010: This single-family dwelling is located on the west side of 8th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 720 and 724 8th Street, N.E. Milled point metal fencing encircles the small front yard. The rear yard is laid with concrete and is bounded by wood fencing and metal chain-link gates. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	

Structure Component	Material	Feature	Source
Foundation	Brick		
Walls	Brick		
Materials Notes:			

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1	Wood
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Wood
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single	Paneled	Wood
Main Door	Rectangular	Single	Paneled	Wood
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 722_8th_Street_NE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 722_8th_Street_NE_facade_looking_W.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 722_8th_Street_NE_rear_looking_E.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 722_8th_Street_NE_rear_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/02/1892	1868	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0038

BASICS DATA

ID Number: **0890-0038** Year Built: **1891** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

724		8th Street	NE	Current
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

Single Dwelling, 724 8th Street, N.E.	Common
--	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

0890/0038			Square/Lot	Current
------------------	--	--	-------------------	----------------

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Fair**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

Residential (Single-Family)	1891	Permit			Original
------------------------------------	-------------	---------------	--	--	-----------------

Residential (Multi-Family)					Current
-----------------------------------	--	--	--	--	----------------

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

Rear Addition	c. 1945	Site Visit/Map			
----------------------	----------------	-----------------------	--	--	--

Orig Construction	1891	Permit			3500 Permit
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Nicholson, R.	Builder	Nicholson, R.
----------------------	----------------	----------------------

Orig Construction	Architect	Reed, George F.
--------------------------	------------------	------------------------

Orig Construction	Owner	Reed, George F.
--------------------------	--------------	------------------------

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Attached**
 Relate to Street: **Face on Setback Line**
 Massing: **Vertical Box/rectang bay**
 Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **16**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

January 2010: Constructed in 1891 by R. Nicholson, this two-story, two-bay Queen Anne-style single-family dwelling was constructed from permit #2394. The dwelling is constructed of brick and is set on a solid, raised brick foundation. The foundation is faced with rock-faced concrete block, and the façade (east elevation) is faced with stretcher-bond brick. String courses, composed of roundels and reed molding, span the façade and are located above the first and second story window openings. A third string course, possibly of concrete, is located beneath the first story windows. A sloping roof caps the dwelling and is fronted along the façade by a corbeled brick cornice. A single-leaf paneled wood door with lights pierces the northernmost bay of the foundation. The first story opening holds a single-leaf paneled wood door with lights and a one-light transom. A segmental brick arch with pearl molding and a brick pediment top the transom. Metal steps provide access to the first story entrance. The second story opening holds a 6/9, double-hung, wood-sash window. A three-sided, rectangular bay projects from the southernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a pyramidal roof of fish scale slate shingles. A finial tops the roof. Fenestration consists of paired 6/9, double-hung, wood-sash windows, 6/6, double-hung, wood-sash windows, and 4/6, double-hung, wood-sash windows. All window openings on the façade have concrete sills and brick segmental arches with pearl molding. The rear (west) elevation is fenestrated with metal jalousie windows, which have rowlock brick sills.

A two-story ell extends from the northernmost bay of the rear elevation and is original. The ell is constructed of brick and is set on a solid foundation. An interior-rear brick chimney rises from the west elevation. A sloping roof caps the ell.

An addition, constructed of six-course, American-bond brick, is located on the rear elevation of the ell. Constructed c. 1945, the addition is set on a solid foundation and is capped by a sloping roof. Visible fenestration consists of single-leaf paneled wood doors with lights, a single-leaf metal door, a four-light fixed window, a 1/1, double-hung, metal-sash window, and a metal jalousie window. All window openings have rowlock brick sills. Metal stairs provide access to the first and second story entrances on the rear elevation.

Site Notes:

January 2010: This single-family rowhouse is located on the west side of 8th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The dwelling is adjacent to 722 and 726 8th Street, N.E. The front yard is landscaped with mature shrubs and is bounded by metal fencing. A concrete walkway leads from the primary entrance and ends at the sidewalk. Wood fencing and chain-link metal fencing bound the grassy rear yard. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component

Material

Color

Treatment

Source

Bay Roof	Slate		Fishscale Pattern	
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	6/9	Wood
Bay Windows	Rectangular	Dbl-Hung	6/6	Wood
Bay Windows	Rectangular	Dbl-Hung	4/6	Wood
Bay Windows	Rectangular	Dbl-Hung	6/9 Double	Wood
Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single	Paneled	Wood/Glass
Main Door	Rectangular	Single	Paneled	Wood/Glass

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890**

File: **724_8th_Street_NE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 724_8th_Street_NE_facade_looking_SW.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 724_8th_Street_NE_rear_looking_E.JPG

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/25/1891	2394	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0890-0800

BASICS DATA

ID Number: **0890-0800** Year Built: **1886** Data Source: **Permit**

Number Extended Street Quad Type of Address

726 **8th Street** **NE Current**

Name(s) Type of Name

Single Dwelling, 726 8th Street, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0800 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1886** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Major Alteration **c. 1965** **Site Visit/Map**

Orig Construction **1886** **Permit** **500 Permit**

Construction Event Association Associated Name

Orig Construction **Owner** **Reed, George F.**

Wheeler, W.H. **Builder** **Wheeler, W.H.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Attached (1 side)**
 Relate to Street: **Face on Setback Line**
 Massing: **Vertical Box/rectang bay**
 Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate (Vernacular)

Exterior & Architectural Notes:

January 2010: Constructed in 1886 by W.H. Wheeler, this vernacular two-story, two-bay Italianate-style single-family dwelling was constructed from permit #1453. The dwelling is constructed of brick and is set on a solid brick foundation. The façade (east elevation) is faced with irregular-coursed, American-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a string course of dog-tooth molding. Brick string courses span the façade and are located at the level of the lintel of the first and second story window openings and also above these openings. The southernmost bay of the façade holds a replacement, single-leaf wood-frame glass door and a one-light wood transom. The inner, recessed opening holds a single-leaf paneled door. A one-story, one-bay porch shelters the primary entrance and has a shed roof. Turned wood posts support the roof. The second story opening holds a 1/1, double-hung, vinyl-sash window with false 4/4 vinyl muntins. The window is set in a round-headed opening, which is highlighted by a soldier brick round-headed arch. A three-sided, rectangular bay projects from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is fenestrated with paired 1/1, double-hung, vinyl-sash windows with 6/6 false vinyl muntins, 1/1, double-hung, vinyl-sash windows with false 4/4 vinyl muntins, and 1/1, double-hung, vinyl-sash windows with false 9/9 vinyl muntins. The first story window openings have soldier brick segmental arches and the second story openings have soldier brick round-headed arches. All windows have concrete sills. The north (side) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows with false 6/6 and 9/9 vinyl muntins and rowlock brick sills.

A full third story with a rear addition was constructed c. 1965. The upper story is constructed of brick and mimics the main block and bay on the façade. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins. These windows have rowlock brick sills. The north (side) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins. The rear (west) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows with false 6/6 and 9/9 vinyl muntins. Additional fenestration consists of a single-leaf paneled metal door and a single-leaf paneled metal door with lights. A full-width, second story deck extends from the rear elevation of the addition and is constructed of wood. The deck is supported by square wood posts and is encircled by square wood balusters.

Site Notes:

January 2010: This single-family dwelling is located on the west side of 8th Street, N.E. and is set back approximately five feet from the concrete sidewalk. The south (side) elevation of the dwelling is adjacent to 724 8th Street, N.E. and an alley runs parallel to the north (side) elevation. The grassy front yard is bounded by a milled point metal fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is laid with concrete and is bounded by chain-link metal fencing.

NOTABLE FEATURES DATA

Component	Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source

Sloped	Not Visible	Not Visible		
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl

Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Full Glass	Wood/Glass

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 726_8th_Street_NE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 726_8th_Street_NE_facade_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 726_8th_Street_NE_facade_looking_W.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0890\
File: 726_8th_Street_NE_rear_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/21/1886	1453	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
2/16/2010	Dayton (MSD), Maria	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Created

Resource All Data Report

ID Number: 0860-0182

BASICS DATA

ID Number: **0860-0182** Year Built: **1894** Data Source: **Permit**

Number Extended Street Quad Type of Address

625 **Morris Place** **NE** **Current**

Name(s) Type of Name

Rowhouse, 625 Morris Place, N.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

0890/0182 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1894** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1894** **Permit** **2000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Beall, R.J., Jr.**

Orig Construction **Builder** **Beall, R.J., Jr.**

Orig Construction **Owner** **Gottwals, D.B.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 12)**

Relate to Street: **Face on Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Carport

Contributing Status

Non-Contributing

Outbuilding Notes:

March 2010: This one-story, one-bay carport was constructed ca. 1995. The square wood posts of the structure are covered with lattice and support the flat roof of corrugated metal. The vehicular opening holds a paneled metal roll-up door.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Italianate

Exterior & Architectural Notes:

March 2010: This rowhouse is one of 12 buildings constructed from the same permit in 1894 by architect/builder R.J. Beall, Jr. for owner D.B. Gottwals. The dwelling is two stories high, two bays wide, and has a shallow rectangular projecting bay on the facade (north elevation). The building sits on a solid brick and concrete foundation that is raised. The dwelling is constructed of brick and is faced with stretcher-bond brick. It has a sloping roof (materials not visible) that is ornamented with a molded metal cornice with brick corbeling and a brick frieze. Multiple brick stringcourses are located on the facade, including a four-course water table and two-course continuous sills. The dwelling is fenestrated with a single-leaf paneled wood door with lights and a one-light transom and 1/1, double-hung, wood-sash windows with concrete lug sills. All window and door openings on the first and second story have segmental brick arches with drip molding. Window openings on the bay are paired. The basement level window openings were obscured by plantings. The main entry is reached by metal steps with a gas pipe railing. The two-story, two-bay ell on the rear elevation has the same material treatment as the main block and has an exterior brick chimney. The rear of the main block and the ell are fenestrated with 1/1, double-hung, vinyl-sash windows with concrete lug sills and segmental brick arches. The first story of the ell was obscured from view by a privacy fence and by the one-story, one-bay, shed roofed screened porch on the rear elevation of the ell. The corrugated metal roof is supported by square wood posts.

Site Notes:

March 2010: This rowhouse is located on the south side of the street and is set back approximately ten feet from the public brick sidewalk. The dwelling is adjacent to 623 and 627 Morris Place, N.E. A brick walkway with steps leads from the main entry to the sidewalk. The front yard is covered with plantings and is edged with a concrete and brick retaining wall with a metal picket fence. A carport is located to the rear (south) of the house.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick & Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Bay Windows	Segmental-Arched	Dbl-Hung	1/1 Double	Wood
Facade	Segmental-Arched	Dbl-Hung	1/1	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Arched (Segmental)	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0860**

File: **625_Morris_Place_NE_facade_looking_S.jpg**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0860**

File: **625_Morris_Place_NE_facade_looking_SW.jp
g**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0860**

File: **625_Morris_Place_NE_rear_looking_NE.jpg**

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0860\
File: 625_Morris_Place_NE_carport_looking_NE.jp
g

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
3/13/1894	1239	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
4/26/2010	Litowitz (DDL), Dana	Record Updated
4/16/2010	Barnes (JLB), Jeanne	Record Updated
3/19/2010	Barnes (JLB), Jeanne	Record Updated
3/19/2010	Barnes (JLB), Jeanne	Record Created

