ID Number: 0912-0059

BASICS DATA

ID Number: 0912	2-0059 Ye	ear Built: c. 1 9	990 Dat	a Source: DC Re	eal Property Database		
	•						
Number Extended	Street			Type of Address			
719	8th Street		NE	Current			
Name(s)			pe of Name				
Single Dwelling, 719	8th Street, N.E.	Co	mmon				
TaxCode1 TaxCode	2 TaxCode3 Type	e E	xplain				
0912/0059	Squ	are/Lot C	urrent				
STATUS/PURPOS	E/USE DATA						
Resource Type: Buil	_			rent: Extant			
o .	Historic		Quality:				
Purpose: Res	idential		Condition:	Good			
Function/Use	Star	t Source	Stop	Source	Explain		
Residential (Single-F		90 DC Re	al Pr		Original		
Residential (Multi-Fa	amily)				Current		
CONSTRUCTION I							
Construction Event	Start	Source	Stop	Source	Cost Source		
Orig Construction	c. 1990	DC Real Property					
		Database					
Construction Event	Asso	ciation		Associated N	Name		
						=	
Construction Notes:							
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		Cross R	eference Notes:			
Streetscape:	Intact		0100011	Cicionoc i votos.			
Relate to Othr Bldgs:	Attached (1 side)						
Relate to Street:	Face on Setback L	ine					
Massing:	Vertical Box/rectar	ng bay					
Footprint:	Rectangular						
Number Stories:	2 plus basem	ent					
Bays Wide:	2						
Height:		Outb	uilding Type		Contributing Status		
Width:							
Depth/Length: SqFt:							
Volume:							
Lot Width							
Lot Depth/Length:		Outb	uilding Note	s:			
Lot SqFt:							
Acreage:							
Has Driveway:							

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

January 2010: Constructed c. 1990, this two-story, two-bay single-family dwelling is constructed of concrete blocks and is set on a solid, raised concrete block foundation; both are faced with stretcher-bond brick. Soldier brick string courses are located above the foundation and first story openings. A side-gabled roof caps the dwelling and is covered with asphalt shingles. A soldier brick string course spans the façade (west elevation) and is located beneath the eaves. A single-leaf metal door pierces the southernmost bay of the foundation. The southernmost bay of the facade is recessed forming an integrated porch and is pierced by a single-leaf paneled wood door with lights and a one-light transom. A stuccoed surround complements the opening. The second story opening holds sliding one-light vinyl windows. A threesided, rectangular bay projects from the northernmost bay of the facade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a front-gabled roof. The roof is covered with asphalt shingles and feature raking metal boards. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows and two-light fixed metal windows. A round-headed fixed light is positioned over the central opening of the second story. A soldier brick round-headed arch complements the light and continues as a string course. A stuccoed panel is located between the first and second story central openings. The north (side) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows and sliding one-light vinyl windows. The rear (east) elevation is stuccoed and is pierced by single and paired 1/1, double-hung, vinyl-sash windows and a single-leaf paneled metal door with lights. A one-story, one-bay porch shelters the entrance and is set on a square wood post and concrete foundation. The shed roof is covered with asphalt shingles and is supported by square wood posts. A solid wood balustrade complements the porch.

Site Notes:

January 2010: This single-family dwelling is located on the east side of 8th Street, N.E and is set back approximately five feet from the concrete sidewalk. The south (side) elevation is adjacent to 717 8th Street, N.E. and an alley runs parallel to the north (side) elevation of the dwelling. The grassy front yard features mature shrubs and is bounded by a milled point metal fence. A concrete walkway leads from the primary entrance and ends at the sidewalk. A concrete parking bay is located east of the dwelling and is accessed from an alley. The grassy rear yard is bounded by wood fencing.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Asphalt		Shingled	
Side gable	Asphalt		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete Block			
Walls	Concrete Block			
Materials Notes:				

WINDOW/DOOR/INTERIOR DATA

Main Door	Rectangular	Single	Paneled	Wood/Glass
Basement	Rectangular	Single		Metal
Door Location	Aperture Shape	Туре	Pamels	Material
Bay Windows	Round-Headed	Fixed	1-light	Metal
Bay Windows	Rectangular	Fixed	2 Lite	Metal
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Metal
Bay Windows	Rectangular	Dbl-Hung	1/1	Metal
2 Flr Windows	Rectangular	Sliding	1-light	Vinyl
Window Location	Aperture Shape	Туре	Lights	Material

Tuesday, June 25, 2013 ID_Number: 0912-0059 Page 2

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Capitol Hill F & G Streets (2010)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Historic District(s)

Survey(s)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 719_8th_Street_NE_facade_looking_E.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 719_8th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0890\

File: 719_7th_Street_NE_garage_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:





Caption:									
Path: File:	Databases\F St\Database	HRS\Docume F&G Street - t\Pictures\Sq eet_NE_rear	2 to 11th uare 0912\	/.JPG					
Date::		Photog:							
Code::			R:	Fr:	-				
РНОТС	S - B/W OR	NON-DIGI	TIZED						
Photo C	ode	Roll	Frame(s)		Date	Photograp	pher	Caption	
MISCE	LLANEOUS	NOTES DA	ATA						
Notes:									
. 10100.									

PERMIT DATA

Permit Issue Date Number Type Remarks

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Created

ID Number: 0912-0060

BASICS DATA

ID Number: 0912-0060 Year Built: c. 1990 Data Source: DC Real Property Database

Number Extended Street Quad Type of Address

717 8th Street NE Current

Name(s) Type of Name

Single Dwelling, 717 8th Street, N.E. Common

 TaxCode1
 TaxCode2
 TaxCode3
 Type
 Explain

 0912/0060
 Square/Lot
 Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Not Historic Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) c. 1990 DC Real Pr Original

Residential (Multi-Family)

Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction c. 1990 DC Real Property

Database

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: Streetscape:	Urban Intact	Cross Refe	rence Notes:		
Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Attached Face on Setback Line Vertical Box/rectang bay Rectangular				
Number Stories: Bays Wide:	2 plus basement 2				
Height: Width: Depth/Length: SgFt:		Outbuilding Type	Co	ontributing Status	
Volume: Lot Width					
Lot Depth/Length: Lot SqFt: Acreage:		Outbuilding Notes:			
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Modern					
Exterior & Architectur	al Notes: tructed c. 1990, this two-sto				
A soldier brick string pierces the northern porch with a quarter stuccoed surround or rectangular bay project the material treatme feature raking metal one-light vinyl sliding soldier brick quarter between the first an paired 1/1, double-highers the entrancishingles and is suppose. Site Notes: January 2010: This services the north services.	d second story windows. A g course spans the façade (amost bay of the foundation r-circle opening and is piero complements the opening. Lects from the southernmos int of the main block and is boards. Fenestration consig windows. A quarter-circle arch complements to d second story central oper ung, vinyl-sash windows are and is set on a square wood posterior of the second story central oper ung, vinyl-sash windows are and is set on a square wood posterior of the second story central oper ung, vinyl-sash windows are and is set on a square wood posterior of the second story central oper ung, vinyl-sash windows are and is set on a square wood posterior of the second story central oper ung, vinyl-sash windows are and is set on a square wood posterior of the second story central oper ung, vinyl-sash windows are second story central oper ung, vinyl-sash	west elevation) and . The northernmost . The northernmost ced by a single-leaf part to bay of the façade a capped by a shed roists of single and part is the light and continuings. The rear (east and a single-leaf woo and post and concrets. A solid wood balacted on the east side.	is located beneath bay of the façade is caneled wood door bening holds a two-send rises the full he pof. The roof is coviered 1/1, double-hu oned over the cent less as a string cour close the country of elevation is stuced frame glass door the foundation. The ustrade complement	the eaves. A single-leaf dos recessed forming an integrand a one-light transom. A light window. A three-sidedight of the dwelling. The barred with asphalt shingles and in the second state of the second state. A stuccoed panel is located and is pierced by single. A one-story, one-bay porceshed roof is covered with a nest the porch.	or grated d, hy has and d paired story. A ated e and h sphalt
the front yard. A con located east of the d	ete sidewalk. The dwelling is acrete walkway leads from to lwelling and is accessed via	he primary entrance	and ends at the si	dewalk. A concrete parking	
NOTABLE FEATU					
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Bay Roof Side gable	Asphalt Asphalt		Shingled Shingled		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	

Foundation

Concrete Block

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
2 FIr Windows	Rectangular	Unknown	2 Lite	Unknown	
Bay Windows		Fixed	1-light	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Bay Windows	Rectangular	Sliding	1-light	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single		Unknown	
Main Door	Rectangular	Single	Paneled	Wood	
Notable Interior Plan	n(s)	1	Notable Interior Feature(s)		

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Subdivision: Ward/ANC: Zoning: Contributing:

ning: Designation Event(s)

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Historic District(s)

Permit Research Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 717_8th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 717_8th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 717_8th_Street_NE_rear_looking_W.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0912-0060 Page 5

ID Number: 0912-0061

Current

BASICS DATA

0912/0061

ID Number: 0912-0061 Year Built: c. 1990 Data Source: **DC Real Property Database** Quad Type of Address Number Extended Street 715 8th Street Current Type of Name Name(s) Single Dwelling, 715 8th Street, N.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Square/Lot

Desig. Status: Not Historic Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) c. 1990 DC Real Pr Original

Current

Residential (Multi-Family)

CONSTRUCTION DATA

 Construction Event
 Start
 Source
 Stop
 Source
 Cost Source

 Orig Construction
 c. 1990
 DC Real

Property

Database

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0912-0061 Page 1

Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width	Urban Intact Attached Face on Setback Line Vertical Box/rectang bay Rectangular 2 plus basement 2	Cross Refer	cence Notes:	ributing Status	
Lot Width Lot Depth/Length: Lot SqFt: Acreage: Has Driveway:		Outbuilding Notes:			
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Modern					
Exterior & Architectura	al Notes:				
A soldier brick string pierces the southern porch with a quarter transom. A stuccoed sided, rectangular bas the material trea feature raking metal two-light vinyl windo brick quarter-circle at the first and second double-hung, vinyl-sone-bay porch shelter.	second story windows. A sign course spans the façade (simost bay of the foundation-circle opening and is pierce surround complements the say projects from the norther timent of the main block and boards. Fenestration considers. A quarter-circle fixed limited the story central openings. The ash windows, a two-light story the entrance and is set of and is supported by square.	west elevation) and . The northernmost ed by a single-leaf p e opening. The seco rnmost bay of the fa- d is capped by a she sts of single and pa ght is positioned ov and continues as a e rear (east) elevation iding vinyl window, on a square wood po	is located beneath the bay of the façade is reaneled wood door wand story opening hold gade and rises the full force. The roof is coired 1/1, double-hunger the central opening string course. A stuch is stuccoed and is and a single-leaf woost and concrete four	e eaves. A single-leaf me ecessed forming an integith lights and a one-light ds a two-light window. A II height of the dwelling. Evered with asphalt shing y vinyl-sash windows and g of the second story. A scoed panel is located bet pierced by single and paid of-frame glass door. A or adation. The shed roof is	tal door grated three- The bay les and d fixed soldier ween red 1/1, ne-story,
Site Notes:					
feet from the concret by a milled point me	ingle-family dwelling is locate sidewalk. The dwelling is tal fence. A concrete walkway is located east of the dwel	adjacent to 713 and ay leads from the pr	l 717 8th Street, N.E. imary entrance and e	The grassy front yard is bends at the concrete side	oounded walk. A
NOTABLE FEATUR	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Bay Roof Side gable	Asphalt Asphalt		Shingled Shingled		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		

Tuesday, June 25, 2013 ID_Number: 0912-0061 Page 2

Source

Feature

Structure Component

Material

Foundation Concrete Block Walls Concrete Block

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material
2 Flr Windows	Rectangular	Unknown	2 Lite	Unknown
Bay Windows		Fixed	1-light	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Rectangular	Fixed	2 Lite	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single		Metal
Main Door	Rectangular	Single	Paneled	Wood/Glass
		-		

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s) Level(s) of Investigation

Capitol Hill F & G Streets (2010) Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 715_8th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:



Tuesday, June 25, 2013 ID_Number: 0912-0061 Page 3

otion

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 715_8th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 715_8th_Street_NE_rear_looking_W.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0912-0061 Page 5

ID Number: 0912-0062

BASICS DATA

ID Number: 0912-0062 Year Built: c. 1990 Data Source: DC Real Property Database

Number Extended Street Quad Type of Address

713 8th Street NE Current

Name(s) Type of Name

Single Dwelling, 713 8th Street, N.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

0912/0062 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Not Historic Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) c. 1990 DC Real Pr Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction c. 1990 DC Real Property

Database

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings:	Urban	Cross Refe	erence Notes:		
Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Intact Attached Face on Setback Line Vertical Box/rectang bay Rectangular				
•	Rectangular				
Number Stories:	2 plus basement				
Bays Wide: Height:	2	Outbuilding Type	Con	tributing Status	
Width:		Outbuilding Type		thouting Otatus	
Depth/Length:					
SqFt:					
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes:			
Lot SqFt: Acreage:					
9					
Has Driveway:					
CTVI E/EVTEDIAD	DATA				
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Modern					
Exterior & Architecture	al Notes: tructed c. 1990, this two-sto				
sided, rectangular b has the material trea and feature overhan one-light metal slidi and paired 1/1, doub shelters the entranc	ents the opening. The secon ay projects from the southe atment of the main block an ging eaves. Fenestration con ng windows, and clerestory ble-hung, vinyl-sash window e and is set on a square wo ported by square wood pos	ernmost bay of the f d is capped by a py onsists of single and windows. The rear ws and a single-leaf and post and concre	açade and rises the furamidal roof. The roof depaired 1/1, double-h (east) elevation is stuwood-frame glass do te foundation. The sh	ull height of the dwelling. If is covered with asphalt soung, vinyl-sash windows, Iccoed and is pierced by soor. A one-story, one-bay poed roof is covered with as	The bay shingles paired single orch
Site Notes:					
January 2010: This s feet from the concre landscaped with sm entrance and ends a	single-family dwelling is loc te sidewalk. The dwelling is all trees and is bounded by It the sidewalk. A concrete I is bounded by wood fenci	s adjacent to 711 an milled point metal parking bay is locat	d 715 8th Street, N.E. fencing. A concrete w	The grassy front yard is ralkway leads from the pri	mary
NOTABLE FEATU	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Bay Roof	Asphalt		Shingled		
Side gable	Asphalt		Shingled		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		
01	Mark 11	.		0	
Structure Component		Feature		Source	
Foundation	Concrete Block				

Walls

Concrete Block

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
2 FIr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Bay Windows	Rectangular	Sliding	1-light	Metal	
Clerestory	Rectangular	Unknown	1-light	Metal	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single		Unknown	

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

ntributing:

Survey(s) Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0912\

File: 713_8th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0912\

File: 713_8th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:



Designation Event(s)



_				
Ca	nti	\mathbf{a}	n	•
υa	υu	v	11	

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 713_8th_Street_NE_rear_looking_W.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED Photo Code Roll Frame(s) Date Photographer Caption **MISCELLANEOUS NOTES DATA** Notes: **PERMIT DATA** Permit Issue Date Number Type Remarks Permit Notes: **BIBLIOGRAPHIC DATA Short Citation** Type Date Remarks Bibliographic Notes: SIGNIFICANCE DATA Study Unit Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Created

ID Number: 0912-0063

BASICS DATA

ID Number: 0912-0063 Year Built: c. 1990 Data Source: **DC Real Property Database**

Quad Type of Address Number Extended Street

711 8th Street Current

Name(s) Type of Name

Single Dwelling, 711 8th Street, N.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain 0912/0063 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: **Not Historic** Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) c. 1990 DC Real Pr Original Current

Residential (Multi-Family)

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction c. 1990 DC Real **Property**

Database

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories:	Urban Intact Attached Face on Setback Line Vertical Box/rectang bay Rectangular 2 plus basement	Cross Refe	erence Notes:		
Bays Wide: Height: Width: Depth/Length: SqFt:	2	Outbuilding Type	Contri	buting Status	
Volume: Lot Width Lot Depth/Length:		Outbuilding Notes:			
Lot SqFt: Acreage:		Outbuilding Notes.			
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Modern Exterior & Architectura	1.11				
and is pierced by a s complements the op bay projects from the treatment of the mail overhanging eaves a windows and a circurear (east) elevation leaf wood-frame glas second story window concrete foundation	by of the foundation. The so ingle-leaf paneled wood do ening. The second story ope northernmost bay of the fan block and is capped by a and raking metal boards. Fellar fixed window in the uppies stuccoed and is pierced so door. A header brick striit openings. A one-story, on The shed roof is covered an plements the porch.	or with lights and a pening holds paired açade and rises the front-gabled roof. T enestration consists per gable end. The c by single and paire ng course travels and pe-bay porch shelte	n one-light transom. A some-light fixed window full height of the dwelf the roof is covered with for single and paired 1 sircular window is surround 1/1, double-hung, vincross the rear elevations the entrance and is so	stuccoed surround ys. A three-sided, rectangling. The bay has the may asphalt shingles and fe/1, double-hung, vinyl-sabunded by rowlock brick yl-sash windows and a so and is sited beneath the set on a square wood po	gular terial eature ash s. The single- e st and
feet from the concrewith mature shrubs	ingle-family dwelling is loc te sidewalk. The dwelling is and is bounded by a milled walk. The rear yard is lands welling.	adjacent to 709 an point metal fence.	d 713 8th Street, N.E. T A concrete walkway lea	he front yard is landscapds from the primary enti	ped rance
NOTABLE FEATU	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Bay Roof Side gable	Asphalt Asphalt		Shingled Shingled		
Wall Component Facade	Material Brick	Color	Treatment Stretcher Bond	Source	

Source

Feature

Structure Component

Material

Foundation Concrete Block Walls Concrete Block

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Main Door	Rectangular	Single	Paneled	Wood/Glass
Basement	Rectangular	Single		Metal
Door Location	Aperture Shape	Туре	Pamels	Material
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Circular	Fixed	1-light	Unknown
2 Flr Windows	Rectangular	Fixed	1-light	Unknown
Window Location	Aperture Shape	Туре	Lights	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 711_8th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:



Caption	:						
Path:	C:\Users\CHRS\Do Databases\F&G Sti St\Database\Pictur	reet - 2 to 11th					
File:	711_8th_Street_NE		_SE.JPG	A CHARLES TO SERVICE			
Date:: Code::	Photog	g: R:	Fr:				
Caption							
Path:	C:\Users\CHRS\Do Databases\F&G St St\Database\Pictur	reet - 2 to 11th es\Square 0912\					
File:	711_8th_Street_NE		W.JPG				
Date:: Code::	Photog	g: R:	Fr:				
PHOTOS - B/W OR NON-DIGITIZED							
РНОТО	OS - B/W OR NON-	DIGITIZED					
Photo C		Frame(s)	Date	Photographer	Caption		
Photo C		Frame(s)	Date	Photographer	Caption		
Photo C	code Roll	Frame(s)	Date	Photographer	Caption		
Photo C	code Roll	Frame(s)	Date	Photographer	Caption		
Photo C MISCE Notes:	code Roll	Frame(s)	Date	Photographer	Caption		
Photo C MISCE Notes:	code Roll	Frame(s)	Date	Photographer	Caption		
Photo C MISCE Notes:	LLANEOUS NOTE T DATA ssue Date	Frame(s)	Date		Caption		
Photo C MISCE Notes: PERMI Permit I	LLANEOUS NOTE T DATA ssue Date	Frame(s)	Date		Caption		

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0912-0063 Page 5

ID Number: 0912-0064

BASICS DATA

ID Number: 0912-0064 Year Built: c. 1990 Data Source: DC Real Property Database

Number Extended Street Quad Type of Address

709 8th Street NE Current

Name(s) Type of Name

Single Dwelling, 709 8th Street, N.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

0912/0064 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Not Historic Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) c. 1990 DC Real Pr Original Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction c. 1990 DC Real Property

Database

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Rays Wide:	Urban Intact Attached Face on Setback Line Vertical Box/rectang bay Rectangular 2 plus basement 2	Cross Refe	rence Notes:		
Bays Wide: Height: Width: Depth/Length: SqFt: Volume:	2	Outbuilding Type	Contr	ibuting Status	
Lot Width Lot Depth/Length: Lot SqFt: Acreage: Has Driveway:		Outbuilding Notes:			
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Modern					
brick string course sethe northernmost bathe integrated porch and soldier-brick round-late second story optectangular bay projethe material treatment and feature overhand vinyl-sash windows and has a circular round to be second soldier-bung, vinyl-sethe rear elevation and entrance and is set of is supported by square.	ry windows. A side-gabled repans the façade (west elevary of the foundation. The not is pierced by a single-leaf neaded surround complements of the main block and is eiging eaves and raking metated one-light vinyl swlock brick surround. The ash windows and a single-led is sited beneath the secondare wood posts. A solid worth	ation) and is located rthernmost round-h paneled metal door ents the recessed op window with a row to bay of the façade a capped by a front-gal boards. Fenestratiliding windows. A crear (east) elevation leaf wood-frame gland story window op concrete foundation	I beneath the eaves. A eaded bay of the façac with a round-headed bening. A stuccoed su lock brick circular sure and rises the full heigh abled roof. The roof is on consists of single ircular fixed window is stuccoed and is piess door. A header brice enings. A one-story, on. The shed roof is covered.	single-leaf metal door p de is recessed forming al light and a one-light tran rround complements the round. A three-sided, t of the dwelling. The bar covered with asphalt sh and paired 1/1, double-his s sited in the upper gable erced by single and paired k string course travels a ne-bay porch shelters th	ierces n som. A e door. y has ingles ung, e end ed 1/1, cross e
feet from the concret by a milled point me	ingle-family dwelling is locate sidewalk. The dwelling is tal fence. A concrete walkw scaped with mature trees a	adjacent 707 and 7 ay leads from the p	11 8th Street, N.E. The imary entrance and e	grassy front yard is bounds at the concrete sidev	ınded valk.
NOTABLE FEATUR	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Bay Roof Side gable	Asphalt Asphalt		Shingled Shingled		
Wall Component Facade	Material Brick	Color	Treatment Stretcher Bond	Source	

Source

Feature

Structure Component

Material

Foundation Concrete Block Walls Concrete Block

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Aperture Shape	Type	Lights	Material	
Circular	Fixed	1-light	Unknown	
Circular	Fixed	1-light	Unknown	
Rectangular	Dbl-Hung	1/1	Vinyl	
Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Rectangular	Sliding	1-light	Vinyl	
Aperture Shape	Туре	Pamels	Material	
Rectangular	Single		Metal	•
Rectangular	Single	Paneled	Metal	
	Circular Circular Rectangular Rectangular Rectangular Aperture Shape Rectangular	Circular Fixed Circular Fixed Rectangular Dbl-Hung Rectangular Dbl-Hung Rectangular Sliding Aperture Shape Type Rectangular Single	Circular Fixed 1-light Circular Fixed 1-light Rectangular Dbl-Hung 1/1 Rectangular Dbl-Hung 1/1 Double Rectangular Sliding 1-light Aperture Shape Type Pamels Rectangular Single	Circular Fixed 1-light Unknown Circular Fixed 1-light Unknown Rectangular Dbl-Hung 1/1 Vinyl Rectangular Dbl-Hung 1/1 Double Vinyl Rectangular Sliding 1-light Vinyl Aperture Shape Type Pamels Material Rectangular Single Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s) Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

File:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0912\
709_8th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:



Caption: Path: File: Date:: Code::	C:\Users\CH Databases\l St\Database	F&G Street e\Pictures\S		SE.JPG Fr:				
Caption: Path: File: Date:: Code::	C:\Users\Cl Databases\l St\Database	F&G Street e\Pictures\S	ents\CHRS					
РНОТО	OS - B/W OF	R NON-DIG	ITIZED					
Photo C	ode	Roll	Frame(s)	Date	Photograph	ier	Caption	
MISCE	LLANEOUS	NOTES D	ATA					
Notes:	T DATA							
	T DATA ssue Date	N	lumber Type		Remarks			
Permit N	Notes:							
BIBLIC	GRAPHIC I	DATA						
Short Ci	tation			Туре	Date	Remarks		

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0912-0064 Page 5

ID Number: 0912-0065

BASICS DATA

 ID Number:
 0912-0065
 Year Built:
 c. 1990
 Data Source:
 DC Real Property Database

 Number
 Extended
 Street
 Quad Type of Address

 707
 8th Street
 NE Current

Name(s) Type of Name

Single Dwelling, 707 8th Street, N.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

0912/0065 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Not Historic Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) c. 1990 DC Real Pr Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction c. 1990 DC Real

Property Database

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0912-0065 Page 1

Surroundings:	Urban	Cross Refe	rence Notes:		
Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Intact Attached Face on Setback Line Vertical Box/rectang bay Rectangular				
Number Stories: Bays Wide:	2 plus basement 2				
Height: Width: Depth/Length: SgFt:		Outbuilding Type	Con	tributing Status	
Volume: Lot Width					
Lot Width Lot Depth/Length:		Outbuilding Notes:			
Lot SqFt: Acreage:		Catibalian g Notes.			
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Modern					
Exterior & Architectura	al Notes:				
door pierces the sou integrated porch and surround compleme second story openin northernmost bay of block and is capped Fenestration consist clerestory windows. sash windows and a set on a square woo	spans the façade (west elevathernmost bay of the found dispierced by a single-leaf not the opening. Poured coag holds a 1/1, double-hung the façade and rises the fuby a pyramidal roof. The rots of single and paired 1/1, The rear (east) elevation is a single-leaf paneled metal of post and concrete foundary.	dation. The southerr paneled metal door norete steps with m, vinyl-sash window all height of the dwelf is covered with a double-hung, vinyl-s stuccoed and is piedoor with lights. A oation. The shed roof	amost bay of the façan with lights and a one etal hand rails provice. A three-sided, rectandling. The bay has the sphalt shingles and for each windows, fixed the erced by single and particled by single and particled is covered with asphales.	de is recessed forming a e-light transom. A stucco le access to the opening, ngular bay projects from material treatment of the feature overhanging eave two-light vinyl windows, aired 1/1, double-hung, vech shelters the entrance	n ed The the main es. and inyl- and is
January 2010: This s feet from the concre landscaped with shr the primary entrance	single-family dwelling is loc te sidewalk. The dwelling is ubs and small trees and is and ends at the sidewalk. rear yard is landscaped wit	s adjacent to 705 and encircled by milled A concrete parking	d 709 8th Street, N.E. point metal fencing. A bay is located east of	The grassy front yard is A concrete walkway leads the dwelling and is acce	s from
NOTABLE FEATU	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Bay Roof	Asphalt	2 2.3.	Shingled		
Side gable	Asphalt		Shingled		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	

Foundation

Concrete Block

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Bay Windows	Rectangular	Fixed	2 Lite	Vinyl	
Clerestory	Rectangular	Unknown	1-light	Unknown	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single	Full Glass	Wood/Glass	
Main Door	Rectangular	Single	Paneled	Metal/Glas	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s)
Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 707_8th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:



Ca		

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 707_8th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 707_8th_Street_NE_rear_looking_E.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0912-0065 Page 5

ID Number: 0912-0066

BASICS DATA

ID Number: 0912-0066 Year Built: c. 1990 Data Source: DC Real Property Database

Number Extended Street Quad Type of Address

705 8th Street NE Current

Name(s) Type of Name

Single Dwelling, 705 8th Street, N.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

0912/0066 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Not Applicable Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) c. 1990 DC Real Pr Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction c. 1990 DC Real Property

Database

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length:	Urban Intact Attached Face on Setback Line Vertical Box/rectang bay Rectangular 2 plus basement 2	Cross Refer	rence Notes:	ributing Status	
SqFt: Volume: Lot Width					
Lot Depth/Length: Lot SqFt: Acreage: Has Driveway:		Outbuilding Notes:			
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Modern					
is set on a solid, rais are located above th beneath the first and A soldier brick string pierces the northern porch with a quarter transom. A stuccoed window. A three-sidd dwelling. The bay ha asphalt shingles and windows. A quarter-circle arch complem second story central hung, vinyl-sash wir is set on a square wood pos Site Notes: January 2010: This sfeet from the concre landscaped with mare	ructed c. 1990, this two-sto- sed concrete block foundati- e foundation, first, and seco- second story windows. A sign course spans the façade (most bay of the foundation- circle opening and is pierce surround complements the ed, rectangular bay projects s the material treatment of facture raking metal board circle fixed light is positione ents the light and continue openings. The rear (east) er dows and a single-leaf word board concrete found ts. A solid wood balustrade cingle-family dwelling is locate sidewalk. The dwelling is ture shrubs and is encircled	on; both are faced wond story openings. side-gabled roof cap west elevation) and. The northernmost led by a single-leaf peed door. The second is from the southernment les. Fenestration consed over the central consed over the central consederation is stucceed of-frame glass doord dation. The shed roof complements the peed over the cest side adjacent to 703 and by a milled point message.	with stretcher-bond by Additional string course the dwelling and is is located beneath the bay of the façade is reaneled wood door wistory opening holds a most bay of the façade is capped by a shed resists of single and papening of the second A stuccoed panel is A one-story, one-bay of is covered with as orch.	rick. Soldier brick string of the action of header brick are covered with asphalt shifted exessed forming an integrith lights and a one-light a 1/1, double-hung, vinyles and rises the full height oof. The roof is covered wired 1/1, double-hung, vind story. A soldier brick quilocated between the first porch shelters the entraphalt shingles and is suponal is set back approxima. The grassy front yard is e walkway leads from the	courses located ingles. tal door rated sash t of the with nyl-sash parter- and ple- ince and ported tely five
primary entrance of	the dwelling and ends at the ssed via an alley. The grass	e concrete sidewalk.	A concrete parking I	•	
Component	Feature				
EXTERIOR MATER					
Roof Component	Material	Color	Treatment	Source	
Bay Roof Side gable	Asphalt Asphalt		Shingled Shingled		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		

Source

Feature

Structure Component

Material

Foundation Concrete Block Walls Concrete Block

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
2 FIr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows		Fixed	1-light	Unknown	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single			

Main Door Rectangular Single

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s)

Capitol Hill F & G Streets (2010) Permit Research

Reconnaissance Survey

Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 705_8th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:



Caption	:							
Path:	Databases\	F&G Street	ments\CHRS t - 2 to 11th Square 0912\					
File: Date:: Code::	705_8th_Sti	reet_NE_fa	rcade_looking_ R:	SE.JPG Fr:				
Caption Path: File: Date:: Code::	C:\Users\Cl Databases\l St\Database	F&G Street NPictures	ments\CHRS t - 2 to 11th Square 0912\ ear_looking_W R:	.JPG Fr:				
РНОТО	OS - B/W OF	R NON-DIG						
Photo C		Roll	Frame(s)	Date	Photograph	her	Caption	
MISCE	LLANEOUS	NOTES I	DATA					
Notes:								
PERMI	T DATA							
Permit I	ssue Date		Number Type		Remarks			-
Permit N	Notes:							
BIBLIC	GRAPHIC I	DATA						
Short Ci	tation			Tyne	Date	Remarks		

Short Citation Type Date Remarks

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0912-0066 Page 5

ID Number: 0912-0067

BASICS DATA

ID Number: 0912-0067 Year Built: c. 1990 Data Source: DC Real Property Database

Number Extended Street Quad Type of Address

703 8th Street NE Current

Name(s) Type of Name

Single Dwelling, 703 8th Street, N.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

0912/0067 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Not Historic Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) c. 1990 DC Real Pr Original Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction c. 1990 DC Real Property

Database

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0912-0067 Page 1

Surroundings:	Urban	Cross Refe	erence Notes:		
Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Intact Attached Face on Setback Line Vertical Box/rectang bay Rectangular				
Number Stories: Bays Wide:	2 plus basement 2				
Height: Width: Depth/Length:	-	Outbuilding Type		Contributing Status	
SqFt: Volume: Lot Width					
Lot Depth/Length: Lot SqFt:		Outbuilding Notes:			
Acreage:					
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Modern					
Exterior & Architectur	al Notes:				
transom. A stuccoed the primary entrance bay projects from the treatment of the mainetal boards. Fenes windows. A quarter-circle arch complem second story central hung, vinyl-sash windows bay porch shelters thattice. The shed roccomplement the por Site Notes:	I surround complements the The second story opening e northernmost bay of the fin block and is capped by a stration consists of single a circle fixed light is position tents the light and continued to openings. The rear (east) of dows, a two-light sliding whe entrance and is set on a fi is covered with asphalt slich.	e opening. Poured of holds a 1/1, double a specified and rises the shed roof. The roof and paired 1/1, doubled over the central as as a string course elevation is stuccoe in a square wood post a hingles and is supp	concrete steps we-hung, vinyl-sase full height of the is covered with le-hung, vinyl-sase opening of the se. A stuccoed pard and is pierced single-leaf woodand concrete fou orted by square v	or with lights and a one-light ith metal hand rails provide and his window. A three-sided, rect adwelling. The bay has the massphalt shingles and feature right windows and fixed two-light econd story. A soldier brick quited is located between the first by single and paired 1/1, doub frame glass door. A one-story ndation that is covered with wood posts. Square wood bale	angular aterial aking nt vinyl uarter- and ole- y, one- yood usters
feet from the concre with mature shrubs of the dwelling and	te sidewalk. The dwelling is and is encircled by a milled	s adjacent to 701 an I point metal fence. alk. A concrete park	d 705 8th Street, A concrete walky	I.E. and is set back approxima N.E. The front yard is landsca vay leads from the primary end d east of the dwelling and is a	ped trance
NOTABLE FEATU	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Bay Roof	Asphalt		Shingled		
Side gable	Asphalt		Shingled		
Wall Component	Material	Color	Treatment	Source	

Stretcher Bond

Brick

Facade

Structure Component Material Feature Source

Foundation Concrete Block
Walls Concrete Block

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows		Fixed	1-light	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Bay Windows	Rectangular	Fixed	2 Lite	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single		Metal	
Main Door	Rectangular	Single	Paneled	Metal/Glas	
Notable Interior Plar	n(s)		Notable Interior Feature(s)		

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision:
Ward/ANC:
Zoning:
Contributing:

Designation Event(s)

Capitol Hill F & G Streets (2010)

Permit Research Reconnaissance Survey

Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:

Survey(s)

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 703_8th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:



<u> </u>		
(:a	ptioi	٦
Ou	Puoi	•

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 703_8th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 703_8th_Street_NE_rear_looking_W.JPG

Date:: Photog: Code:: R: Fr: **PHOTOS - B/W OR NON-DIGITIZED** Photo Code Roll Date Photographer Frame(s) Caption **MISCELLANEOUS NOTES DATA** Notes: **PERMIT DATA** Permit Issue Date Number Type Remarks Permit Notes: **BIBLIOGRAPHIC DATA Short Citation** Type Date Remarks Bibliographic Notes: **SIGNIFICANCE DATA** Study Unit Criteria Code

Tuesday, June 25, 2013 ID_Number: 0912-0067 Page 4

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0912-0067 Page 5

ID Number: 0912-0068

BASICS DATA

ID Number: 0912-0068 Year Built: c. 1990 Data Source: DC Real Property Database

Number Extended Street Quad Type of Address

701 8th Street NE Current

Name(s) Type of Name

Single Dwelling, 701 8th Street, N.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

0912/0068 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Not Historic Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) c. 1990 DC Real Pr Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction c. 1990 DC Real

Orig Construction c. 1990 DC Real Property Database

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0912-0068 Page 1

Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street:	Urban Intact Attached Face on Setback Line	Cross Refe	rence Notes:		
Massing: Footprint:	Vertical Box/rectang bay Rectangular				
Number Stories: Bays Wide:	2 plus basement 2				
Height: Width: Depth/Length:		Outbuilding Type	Cont	ributing Status	
SqFt: Volume: Lot Width					
Lot Depth/Length: Lot SqFt:		Outbuilding Notes:			
Acreage: Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Modern					
Exterior & Architectura	al Notes: ructed c. 1990, this two-sto				
is pierced by a single opening. The second southernmost bay of block and is capped Fenestration consist round-headed fixed complements the lig central openings. The windows and a single square wood post as wood posts. A solid Site Notes: January 2010: This set from the concretandscaped with smeentrance to the sides.	y of the foundation. The noe-leaf paneled wood door was story opening holds fixed the façade and rises the fuby a front-gabled roof. The sof single and paired 1/1, olight is positioned over the ht and continues as a stringe rear (east) elevation is stree-leaf wood-frame glass do do concrete foundation. The wood balustrade complementation of the sidewalk. The dwelling is locate sidewalk. The dwelling is all trees and is encircled by walk. A concrete parking ball by small trees and is boundation.	with lights and a one- vinyl windows. A the angle of the dwell roof is covered with double-hung, vinyl-secentral opening of the approximation of the angle of the	elight transom. A studing ree-sided, rectangular ling. The bay has the asphalt shingles and ash windows and two he second story. A so did panel is located beto be beto by single and paire bay porch shelters to be with asphalt shing end of 8th Street, N.E. and 800 encing. A concrete with a did not said the dwelling and is active.	coed surround complement bay projects from the material treatment of the different feature raking metal boat olight fixed metal window oldier brick round-headed ween the first and second at 1/1, double-hung, vinylhe entrance and is set on les and is supported by so and is set back approximated Street, N.E. The front yalkway leads from the princessed via an alley. The general treatment of the set of the s	ents the main urds. vs. A arch I story sash a quare ely five urd is mary
NOTABLE FEATU	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Bay Roof	Asphalt		Shingled Shingled		
Side gable	Asphalt	Color	Shingled	Source	
Wall Component Facade	Material Brick	Color	Treatment Stretcher Bond	Source	

Source

Feature

Structure Component

Material

Foundation Concrete Block Walls Concrete Block

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material
2 Flr Windows	Rectangular	Fixed	Unknown	Vinyl
Bay Windows		Fixed	1-light	Unknown
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Rectangular	Fixed	2 Lite	Metal
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single		Metal
Main Door	Rectangular	Single	Paneled	Wood/Glass
Main Door	Rectangular	Single	raneled	wood/Glass

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 701_8th_Street_NE_facade_looking_E.JPG

Date:: Photog:

Code:: R: Fr:



Ca	- 4:	
ı.a	M	nn

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 701_8th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 701_8th_Street_NE_rear_looking_W.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Updated
2/16/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0912-0068 Page 5

ID Number: 0912-0069

BASICS DATA

ID Number: 0912-0069 Year Built: c. 1990 Data Source: **DC Real Property Database** Quad Type of Address Number Extended Street 800 **G** Street Current Type of Name Name(s) Single Dwelling, 800 G Street, N.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain 0912/0069 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Not Historic Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) c. 1990 DC Real Pr Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction

C. 1990 DC Real Property Database

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0912-0069 Page 1

Surroundings: Streetscape:	Urban Intact	Cross R	eference Notes:		
Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Attached (1 side) Face on Setback Line Vertical Block Rectangular (w/ side bays)				
Number Stories: Bays Wide:	2 plus basement 3				
Height: Width: Depth/Length:		Outbuilding Type	Con	tributing Status	
SqFt: Volume: Lot Width					
Lot Depth/Length: Lot SqFt: Acreage:		Outbuilding Note	s:		
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)			<u></u>		
Modern					
Exterior & Architectura	al Notes:				
foundation. A single with metal hand rails The flat roof of the pholds paired one-lig upper gable end. A sfrom the end bays or treatment of the mais shed roof. Fenestrat windows. The west ((side) elevation is st wood-frame glass of foundation. The she complements the positive site Notes: January 2010: This stack approximately Street, N.E. The grasmetal fence. A wood	tal boards complement the releaf paneled metal door wit is provide access to the primorch serves as a second stock the vinyl windows (possibly stock and is capped by a stock and is pierced by sit boor. A one-story, one-bay poor or of is covered with aspharch. Single dwelling is located on five feet from the brick side privacy fence extends from triking bay is located east of the stock and is pierced.	h lights pierces thary entrance. The pry balcony and fishing. A semi-curround highlight) and rise the fulshed roof covere aired 1/1, double aired 1/1, double and paired forch shelters the alt shingles and in the northeast cowalk. The rear (nowith mature shruthe east (side) e	the central bay of the fire entrance is sheltered features metal balusters sircular two-light fixed verse the opening. Three-sill height of the dwelling of with asphalt shingles e-hung, vinyl-sash winder with 1/1, double-hung, vinyl-sentrance and is set on a set o	st story. Poured concrete by a one-story, one-bay p s. The second story openi inyl window fenestrates t ided, rectangular bays pr . Each bay has the materi . Raking metal boards fin ows and two-light fixed v vinyl-sash windows. The sash windows and a sing a square wood post and o wood posts. A wood balu and G Street, N.E. and is velling is adjacent to 701 is bounded by a milled p and divides the front and	e steps porch. ing ihe oject al iish each inyl e east le-leaf concrete istrade
NOTABLE FEATU	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Bay Roof Side gable	Asphalt Asphalt		Shingled Shingled		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		

Structure Component Material Feature Source

Foundation Concrete Block
Walls Concrete Block

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

	0 ! 0! !	Electrical Control of the Control of	21:40	\/:d	
	Semi-Circular	Fixed	2 Lite	Vinyl	
	Semi-Circular	Fixea	2 Lite	vinyi	
	Semi-Circular	rixea	2 Lite	vinyi	
	0! 0!!	Fired	0.1.46	\/:d	
uows	•			•	
dows	Rectangular	Fixed	2 Lite	Vinyl	
dows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
	•	•	4/4 5 11	\.,'.	
dows	Rectangular	Dbl-Hung	1/1	Vinvl	
ndows	Rectangular	Unknown	2 Lite	Vinyi	
ndows	Rectangular	Unknown	2 Lite	Vinvl	
Location	Aperture Snape	туре	Lights	Material	
Location	Aperture Shape	Туре	Lights	Mater	ial

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Survey(s)

Designation Event(s)

Capitol Hill F & G Streets (2010)

Permit Research Reconnaissance Survey

Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0912\

File: 800_G_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:



Ca	

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 800_G_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 800_G_Street_NE_side_looking_NW.JPG

Date:: Photog: Code:: R: Fr: **PHOTOS - B/W OR NON-DIGITIZED** Photo Code Roll Date Photographer Frame(s) Caption **MISCELLANEOUS NOTES DATA** Notes: **PERMIT DATA** Permit Issue Date Number Type Remarks Permit Notes: **BIBLIOGRAPHIC DATA Short Citation** Type Date Remarks Bibliographic Notes: **SIGNIFICANCE DATA** Study Unit Criteria Code

Tuesday, June 25, 2013 ID_Number: 0912-0069 Page 4

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/17/2010	Dayton (MSD), Maria	Record Updated
2/17/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0912-0069 Page 5

ID Number: 0912-0080

BASICS DATA

ID Number: 0912	-0080	Year Built	c. 1990	Data	a Source: DC R	eal Property Database	
Number Extended	Street			Quad	Type of Address		
910	G Street			NE	Current		
Name(s)			Type of	Name			
Single Dwelling, 910	G Street, N.E.		Commo	on			
TaxCode1 TaxCode	2 TaxCode3 T	уре	Explair	า			
0912/0080		Square/Lot	Currer				
STATUS/PURPOS	E/USE DATA						
Resource Type: Bui	_				ent: Extant		
	Applicable		Qua	-			
Purpose: Res	idential		Con	dition:	Good		
Function/Use		Start	Source	Stop	Source	Explain	
Residential (Single-I	Family) o	. 1990	DC Real Pr			Historic/Current	
CONSTRUCTION				_			
Construction Event	Star		urce Real	Stop	Source	Cost Source	
Orig Construction	c. 19		perty				
		Da	tabase				
Construction Event	A	Association			Associated N	Name	
Construction Notes:							
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		С	ross Re	eference Notes:		
Streetscape:	Intact						
Relate to Othr Bldgs: Relate to Street:	Attached (1 sid						
Massing:	Vertical Block	KLINE					
Footprint:	Rectangular (w	/ side bays)				
Number Stories:	2	-					
Bays Wide:	3						
Height:	-		Outbuildin	ід Туре		Contributing Status	
Width:							
Depth/Length:							
SqFt:							
Volume: Lot Width							
Lot Depth/Length:			Outbuildin	g Notes	S:		
Lot SqFt:							
Acreage:							
Has Driveway:							

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

January 2010: Constructed c. 1990, this two-story, three-bay single-family dwelling is constructed of concrete blocks and is set on a solid, raised concrete block foundation; both are faced with stretcher-bond brick. Soldier brick veneer belt courses are located above the foundation, first, and second story openings. Additional header brick string courses are sited beneath the first and second story openings. A front-gabled roof caps the dwelling and is covered with asphalt shingles. Raking metal boards complement the upper gable end. A single-leaf paneled door with lights pierces the central bay of the first story. Poured concrete steps with metal hand rails provide access to the primary entrance. The entrance is sheltered by a one-story, one-bay porch. The flat roof of the porch serves as a second story balcony and features metal balusters. The second story opening holds paired one-light vinyl windows (possibly sliding). A semicircular two-light fixed vinyl window fenestrates the upper gable end. A soldier brick semi-circular surround highlights the opening. Three-sided, rectangular bays project from the end bays of the façade (south elevation) and rise the full height of the dwelling. Each bay has the material treatment of the main block and is capped by a shed roof covered with asphalt shingles. Raking metal boards finish each shed roof. Fenestration consists of single and paired 1/1, doublehung, vinyl-sash windows. The east (side) elevation of the dwelling is fenestrated with 1/1, double-hung, vinyl-sash windows. The west (side) elevation is stuccoed and is pierced by single and paired 1/1, double-hung, vinyl-sash windows and a single-leaf door. A one-story, one-bay porch shelters the entrance and is set on a square wood post and concrete foundation. The shed roof is covered with asphalt shingles and is supported by square wood posts. A wood balustrade complements the porch.

Site Notes:

January 2010: This single-family dwelling is located on the northwest corner of G Street, N.E. and 10th Street, N.E. and is set back approximately five feet from the brick sidewalk. The rear (north) elevation of the dwelling is adjacent to 10th Street, N.E. The grassy front yard is landscaped with mature shrubs and small trees and is encircled by milled point metal fencing. A wood privacy fence extends from the west (side) elevation of the dwelling and divides the front and side yards. A concrete parking bay is located west of the dwelling and is accessed via the concrete alley.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Asphalt		Shingled	
Side gable	Asphalt		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete Block			
Walls	Concrete Block			
Materials Notes:				

WINDOW/DOOR/INTERIOR DATA

2 Flr Windows	Rectangular	Unknown	1-light	Vinyl
2 Flr Windows	Semi-Circular	Fixed	2 Lite	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Type	Pamels	Material
Main Door	Rectangular	Single	Paneled	Unknown w/Lights
Notable Interior Plan	n(s)		Notable Interior Feature(s)	

Tuesday, June 25, 2013 ID_Number: 0912-0080 Page 2

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision: Ward/ANC: Zoning:

Contributing:

Level(s) of Investigation Survey(s) Capitol Hill F & G Streets (2010)

Permit Research Reconnaissance Survey

Historic District(s)

Designation Event(s)

PHOTOS - DIGITIZED

Caption:

C:\Users\CHRS\Documents\CHRS Path:

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 910_G_Street_NE_700-718

10th_Street_NE_rear_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

> Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

910_G_Street_NE_facade_looking_N.JPG File:

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

910_G_Street_NE_facade_looking_NW.JPG File:

Date:: Photog:

Code:: R: Fr:







Ca		

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 910_G_Street_NE_side_looking_W.JPG

Date:: Photog:



Code:: R: Fr: **PHOTOS - B/W OR NON-DIGITIZED** Photo Code Roll Frame(s) Date Photographer Caption **MISCELLANEOUS NOTES DATA** Notes: **PERMIT DATA** Permit Issue Date Number Type Remarks Permit Notes: **BIBLIOGRAPHIC DATA Short Citation** Туре Date Remarks Bibliographic Notes: SIGNIFICANCE DATA Study Unit Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/17/2010	Dayton (MSD), Maria	Record Updated
2/17/2010	Dayton (MSD), Maria	Record Created

ID Number: 0912-0079

BASICS DATA

ID Number: 0912	-0079	Year Bui	t: c. 1990	Data	a Source: DC Re	eal Property Database	
Number Extended	Street			Quad	Type of Address		
700	10th Street			NE	Current		
Name(s)			Type of	Name			
Single Dwelling, 700	10th Street, N	l.E.	Comm	on			
TaxCode1 TaxCode	2 TaxCode3	Туре	Explair	า			
0912/0079		Square/Lo	Curre	nt			
STATUS/PURPOS							
Resource Type: Bui Desig. Status: Not	lding Historic		Stat Qua		ent: Extant		
-	idential			dition:	Good		
		. .		•			
Function/Use Residential (Single-I	Family)	Start c. 1990	Source DC Real Pr	Stop	Source	Explain Historic/Current	
Residential (Omgle-I	anny	C. 1330	DO Real I			matoric/ourrent	
CONSTRUCTION I	DATA						
Construction Event	St	art So	ource	Stop	Source	Cost Source	
Orig Construction	C.		C Real				
			operty atabase				
Construction Event		Association			Associated N	Jame	
Construction Notes:							
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		С	ross Re	eference Notes:		
Streetscape: Relate to Othr Bldgs:	Intact						
Relate to Street:	Face on Setb	ack Line					
Massing:	Vertical Box/						
Footprint:	Rectangular						
Number Stories:	2						
Bays Wide:	2						
Height:			Outbuildin	ig Type		Contributing Status	
Width: Depth/Length:							
SqFt:							
Volume:							
Lot Width			O				
Lot Depth/Length: Lot SqFt:			Outbuildin	g Notes	S:		
Acreage:							
Has Driveway:							

OTVI		(TERI		A T A
~ I V I	-/-		1 K 1 1	$\Delta I \Delta$

Architectural Style(s)

Modern

Exterior & Architectural Notes:

January 2010: Constructed c. 1990, this two-story, two-bay single-family dwelling is constructed of concrete blocks and is set on a solid, raised concrete block foundation; both are faced with stretcher-bond brick. Soldier brick veneer string courses are located above the foundation, first, and second story openings. Additional header brick string courses are sited beneath the first and second story openings. A side-gabled roof caps the dwelling and is covered with asphalt shingles. The northernmost bay of the façade is recessed forming an integrated porch and is pierced by a single-leaf paneled door with lights and a one-light transom. A stuccoed surround complements the opening. The second story opening holds a two-light vinyl window (possibly fixed). A three-sided, rectangular bay projects from the southernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a front-gabled roof. The roof is covered with asphalt shingles and feature raking metal boards. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. A round-headed fixed light is positioned over the central opening of the second story. A soldier brick round-headed arch complements the light and continues as a string course. A stuccoed panel is located between the first and second story central openings. The rear (west) elevation is stuccoed and is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows.

Site Notes

January 2010: This single dwelling is located on the west side of 10th Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 910 G Street, N.E. and 702 10th Street, N.E. The grassy front yard is landscaped with foundation plantings and is encircled by milled point metal fencing. A concrete walkway leads from the primary entrance and ends at the sidewalk. A concrete alley is located west of the dwelling.

NOTABLE FEATURES DATA

|--|

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Asphalt		Shingled	
Side gable	Asphalt		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete Block			
Walls	Concrete Block			
Materials Notes:				

WINDOW/DOOR/INTERIOR DATA

Interior Notes:

Window Location	Aperture Shape	Туре	Lights	Material
2 Flr Windows	Rectangular	Unknown	2 Lite	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Round-Headed	Fixed	2 Lite	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Main Door	Rectangular	Single	Paneled	Unknown w/Lights
Notable Interior Plar	n(s)		Notable Interior Feature(s)	

Tuesday, June 25, 2013 ID_Number: 0912-0079 Page 2

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Subdivision: Ward/ANC: Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010) Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 700_10th_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 700_10th_Street_NE_facade_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 910 G Street NE 700-718

10th_Street_NE_rear_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

Permit Issue Date Number Type Remarks Permit Notes: BIBLIOGRAPHIC DATA Short Citation Type Date Remarks Bibliographic Notes: SIGNIFICANCE DATA Study Unit Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/17/2010	Dayton (MSD), Maria	Record Updated
2/17/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0912-0079 Page 4

ID Number: 0912-0078

BASICS DATA

ID Number: 0912	2-0078	Year Buil	t: c. 1990	Data	a Source: DC R	eal Property Database	
Number Extended	Street			Quad	Type of Address		
702	10th Street			NE	Current		
Name(s)			Type of	Name			
Single Dwelling, 702	10th Street, N	.E.	Commo	on			
TaxCode1 TaxCode	2 TaxCode3	Туре	Explair	า			
0912/0078		Square/Lot	Currer	nt			
STATUS/PURPOS							
Resource Type: Bui	-				ent: Extant		
_	Historic idential		Qua	ılıty: dition:	Good		
i dipose. Res	iuentiai		Con	dition.	Good		
Function/Use		Start	Source	Stop	Source	Explain	
Residential (Single-I	Family)	c. 1990	DC Real Pr	•		Historic/Current	
CONSTRUCTION							
Construction Event			ource C Real	Stop	Source	Cost Source	
Orig Construction	C.		operty				
		Da	tabase				
Construction Event		Association			Associated N	Name	
Construction Notes:							
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		С	ross Re	eference Notes:		
Streetscape:	Intact						
Relate to Othr Bldgs:	Attached						
Relate to Street:	Face on Setb						
Massing: Footprint:	Vertical Box/r Rectangular	ectang bay					
	_						
Number Stories:	2						
Bays Wide: Height:	2		Outbuildin	a Type		Contributing Status	
Width:			Outbuildin	ig Type		Contributing Ctatus	<u></u>
Depth/Length:							
SqFt:							
Volume:							
Lot Width			0.44 33.5	N.I			
Lot Depth/Length: Lot SqFt:			Outbuildin	g Notes	S:		
Acreage:							
Has Driveway:							

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

January 2010: Constructed c. 1990, this two-story, two-bay single-family dwelling is constructed of concrete blocks and is set on a solid, raised concrete block foundation; both are faced with stretcher-bond brick. Soldier brick veneer string courses are located above the foundation, first, and second story openings. Additional string courses of header brick are located beneath the first and second story windows. A side-gabled roof caps the dwelling and is covered with asphalt shingles. The southernmost bay of the façade is recessed forming an integrated porch with a quarter-circle opening and is pierced by a single-leaf paneled door with lights and a one-light transom. A stuccoed surround complements the opening. Poured concrete steps with metal hand rails provide access to the primary entrance. The second story opening holds a 1/1, double-hung, vinyl-sash window. A three-sided, rectangular bay projects from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a shed roof. The roof is covered with asphalt shingles and feature raking metal boards. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. A quarter-circle fixed light is positioned over the central opening of the second story. A soldier brick quarter-circle arch complements the light and continues as a string course. A stuccoed panel is located between the first and second story central openings. The rear (west) elevation is stuccoed and is pierced by single and paired 1/1, double-hung, vinyl-sash windows.

Site Notes:

January 2010: This single dwelling is located on the west side of 10th Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 700 and 704 10th Street, N.E. The grassy front yard is encircled by milled point metal fencing. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. A concrete alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Walls Materials Notes:	Concrete Block				
Foundation	Concrete Block				
Structure Component	Material	Feature		Source	
Facade	Brick		Stretcher Bond		
Wall Component	Material	Color	Treatment	Source	
Side gable	Asphalt		Shingled		
Bay Roof	Asphalt		Shingled		
Roof Component	Material	Color	Treatment	Source	

WINDOW/DOOR/INTERIOR DATA

Notable Interior Plan(s)			Notable Interior Feature(s)	
Main Door	Rectangular	Single	Paneled	Unknown w/Lights
Door Location	Aperture Shape	Type	Pamels	Material
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows		Fixed		Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Window Location	Aperture Shape	Type	Lights	Material

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Subdivision: Ward/ANC: Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 702_10th_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 702_10th_Street_NE_facade_looking_W.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 910_G_Street_NE_700-718

10th_Street_NE_rear_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DA	TA				
Permit Issue [Date Number	Туре	Remarks		
Permit Notes:					
BIBLIOGRA	PHIC DATA				
Short Citation		Туре	Date	Remarks	
Bibliographic I	Notes:				
SIGNIFICAN	CE DATA				
Study Unit					
Code	Criteria				
DATA PROC	CESSING EVENTS DAT	ГА			
Date	Individual	Action			
3/18/2010	Trieschmann (LVT), Laura Record	Updated		

Record Updated

Record Created

2/17/2010

2/17/2010

Dayton (MSD), Maria

Dayton (MSD), Maria

ID Number: 0912-0077

BASICS DATA

ID Number: 0912	2-0077	Year Bui	t: c. 1990	Data	a Source: DC Re	eal Property Database	
Number Extended	Street			Quad	Type of Address		
704	10th Street			NE	Current		
Name(s)			Type of	Name			
Single Dwelling, 704	10th Street, N	N.E.	Comm	on			
TaxCode1 TaxCode	2 TaxCode3	Туре	Explai	n			
0912/0077		Square/Lot	Curre	nt			
STATUS/PURPOS		1					
Resource Type: Bui Desig. Status: Not	lding Historic		Stat Qua		ent: Extant		
-	idential			inty. idition:	Good		
		. .		٥.			
Function/Use Residential (Single-I	Family)	Start c. 1990	Source DC Real Pr	Stop	Source	Explain Historic/Current	
Residential (Omgle-I	anny,	0. 1550	DO Real I			riistorio/ourrent	
CONSTRUCTION I	DATA						
Construction Event	S	tart So	ource	Stop	Source	Cost Source	
Orig Construction	C.		C Real				
			operty atabase				
Construction Event		Association			Associated N	Name	
Construction Notes:							
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		C	ross Re	eference Notes:		
Streetscape: Relate to Othr Bldgs:	Intact Attached						
Relate to Street:	Face on Sett	ack Line					
Massing:	Vertical Box/	rectang bay					
Footprint:	Rectangular						
Number Stories:	2						
Bays Wide:	2			_		0	
Height: Width:			Outbuildin	ig Type		Contributing Status	
Depth/Length:							
SqFt:							
Volume:							
Lot Width			المالية المالية	a Note:	. .		
Lot Depth/Length: Lot SqFt:			Outbuildir	ig inotes	o.		
Acreage:							
Has Driveway:							

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

January 2010: Constructed c. 1990, this two-story, two-bay single-family dwelling is constructed of concrete blocks and is set on a solid, raised concrete block foundation; both are faced with stretcher-bond brick. Soldier brick veneer string courses are located above the foundation, first, and second story openings. Additional string courses of header brick are located beneath the first and second story windows. A side-gabled roof caps the dwelling and is covered with asphalt shingles. The northernmost bay of the façade is recessed forming an integrated porch with a quarter-circle opening and is pierced by a single-leaf paneled door with lights and a one-light transom. A stuccoed surround complements the door. The second story opening holds a 1/1, double-hung, vinyl-sash window. A three-sided, rectangular bay projects from the southernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a shed roof. The roof is covered with asphalt shingles and feature raking metal boards. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. A quarter-circle fixed light is positioned over the central opening of the second story. A soldier brick quarter-circle arch complements the light and continues as a string course. A stuccoed panel is located between the first and second story central openings. The rear (west) elevation is stuccoed and is pierced by single and paired 1/1, double-hung, vinyl-sash windows and a single-leaf door. The door is sheltered by a one-story, one-bay porch with a shed roof.

Site Notes:

January 2010: This single dwelling is located on the west side of 10th Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 702 and 706 10th Street, N.E. The grassy front yard is encircled by a milled point metal fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the brick sidewalk. A concrete alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Asphalt		Shingled	
Side gable	Asphalt		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete Block			
Walls	Concrete Block			
Materials Notes:				

WINDOW/DOOR/INTERIOR DATA

Notable Interior Plan(s)			Notable Interior Feature(s)	
Main Door	Rectangular	Single	Paneled	Unknown w/Lights
Door Location	Aperture Shape	Type	Pamels	Material
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows		Fixed		Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Window Location	Aperture Shape	Туре	Lights	Material

Interior Notes:		

Tuesday, June 25, 2013 ID_Number: 0912-0077 Page 2

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Subdivision: Ward/ANC: Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010) Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 704_10th_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 704_10th_Street_NE_facade_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 910_G_Street_NE_700-718

10th_Street_NE_rear_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DAT	ΓΑ					
Permit Issue D	ate Nu	umber Type		Remarks		
Permit Notes:						
BIBLIOGRAI	PHIC DATA					
Short Citation			Туре	Date	Remarks	
Bibliographic N						
Study Unit	OL DATA					
Code	Criteria					
DATA PROC	ESSING EVENTS	DATA				
Date	Individual		Action			
3/18/2010 2/17/2010	Trieschmann Dayton (MSD		a Record Up Record Up			

Record Created

2/17/2010

Dayton (MSD), Maria

ID Number: 0912-0076

BASICS DATA

ID Number: 0912	-0076	Year Bui	t: c. 1990	Dat	a Source: DC R	eal Property Database	
Number Extended	Street			Quad	Type of Address		
706	10th Street			NE	Current		
Name(s)			Type of	Name			
Single Dwelling, 706	10th Street, N	I.E.	Comm	on			
TaxCode1 TaxCode	2 TaxCode3	Туре	Explair	n			
0912/0076		Square/Lot	Curre	nt			
STATUS/PURPOS		1					
Resource Type: Buil Desig. Status: Not	lding Historic		Stat Qua		rent: Extant		
-	idential			iiity. idition:	Good		
		. .		a .			
Function/Use Residential (Single-F	Family)	Start c. 1990	Source DC Real Pr	Stop	Source	Explain Historic/Current	
Residential (Omgle-I	anny)	0. 1550	DO Real I			matoric/Ourrent	
CONSTRUCTION I	DATA						
Construction Event	S	tart So	ource	Stop	Source	Cost Source	
Orig Construction	C.		C Real				
			operty atabase				
Construction Event		Association			Associated N	Name	
Construction Notes:							
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		С	ross Re	eference Notes:		
Streetscape: Relate to Othr Bldgs:	Intact Attached						
Relate to Street:	Face on Sett	ack Line					
Massing:	Vertical Box/	rectang bay					
Footprint:	Rectangular						
Number Stories:	2						
Bays Wide:	2			_		0	
Height: Width:			Outbuildin	ig Type		Contributing Status	<u></u>
Depth/Length:							
SqFt:							
Volume:							
Lot Width			د نامان بالمان	a Note:	٠.		
Lot Depth/Length: Lot SqFt:			Outbuildin	ig inotes	S.		
Acreage:							
Has Driveway:							

Architectural Style(s)					
Modern			<u> </u>		
Exterior & Architectural N	otes:				
is set on a solid, raised courses are located about beneath the first and se The southernmost bay with lights and a one-lighand rails provide accethree-sided, rectangular The bay has the materiashingles and clerestory windows and clerestory	concrete block foundation and fit cond story windows. A sof the façade is recessed that transom. A stuccoed as to the opening. The sof bay projects from the null treatment of the main berhanging eaves. Fenestry windows. The rear (westrond to the fact that the rear (westrond to the fact that the	on; both are face irst story opening side-gabled roof of forming an integer surround comple econd story oper orthernmost bay plock and is capp tration consists of elevation is store ir store the store is the store of the store is store in the store of	d with stretcher-bond gs. Additional header caps the dwelling and grated porch and is p ements the opening. I ning holds a 1/1, douk of the façade and ris led by a pyramidal roo of single and paired 1, uccoed and is pierced	onstructed of concrete blad brick. Soldier brick venderick string courses are all is covered with asphalt ierced by a single-leaf part poured concrete steps will be the full height of the dof. The roof is covered with double-hung, vinyl-sast by single and paired 1/1 the entrance and is capp	eer string sited shingles. neled door ith metal ow. A welling. ith asphalt sh
shed roof.					
Site Notes: January 2010: This sing from 10th Street, N.E. T milled point metal fence	he dwelling is adjacent t e. A concrete walkway le	o 704 and 708 10	th Street, N.E. The gra	is set back approximate assy front yard is encircle welling and ends at the s	ed by a
Site Notes: January 2010: This sing from 10th Street, N.E. T	he dwelling is adjacent to the dwelling is adjacent to the dwelling.	o 704 and 708 10	th Street, N.E. The gra	assy front yard is encircle	ed by a
Site Notes: January 2010: This sing from 10th Street, N.E. Ti milled point metal fence concrete alley is located NOTABLE FEATURES	he dwelling is adjacent to a Concrete walkway lead west of the dwelling. S DATA Feature	o 704 and 708 10	th Street, N.E. The gra	assy front yard is encircle	ed by a
Site Notes: January 2010: This sing from 10th Street, N.E. The milled point metal fence concrete alley is located NOTABLE FEATURE: Component	he dwelling is adjacent to a Concrete walkway lead west of the dwelling. S DATA Feature	o 704 and 708 10	th Street, N.E. The gra	assy front yard is encircle	ed by a
Site Notes: January 2010: This sing from 10th Street, N.E. Ti milled point metal fence concrete alley is located NOTABLE FEATURES Component EXTERIOR MATERIA	he dwelling is adjacent to A concrete walkway lead west of the dwelling. S DATA Feature	o 704 and 708 10 ads from the prin	th Street, N.E. The grant of the description of the	assy front yard is encircle	ed by a
Site Notes: January 2010: This sing from 10th Street, N.E. The milled point metal fence concrete alley is located NOTABLE FEATURE: Component EXTERIOR MATERIA	he dwelling is adjacent to the Aconcrete walkway lead west of the dwelling. S DATA Feature LS DATA Material	o 704 and 708 10 ads from the prin	th Street, N.E. The granary entrance of the d	assy front yard is encircle	ed by a
Site Notes: January 2010: This sing from 10th Street, N.E. Timilled point metal fence concrete alley is located NOTABLE FEATURE: Component EXTERIOR MATERIA Roof Component Bay Roof	he dwelling is adjacent to the Aconcrete walkway lead west of the dwelling. S DATA Feature LS DATA Material Asphalt	o 704 and 708 10 ads from the prin	th Street, N.E. The granary entrance of the definition of the defi	assy front yard is encircle	ed by a
Site Notes: January 2010: This sing from 10th Street, N.E. Timilled point metal fence concrete alley is located NOTABLE FEATURE: Component EXTERIOR MATERIA Roof Component Bay Roof Side gable Wall Component	he dwelling is adjacent to A concrete walkway lead west of the dwelling. S DATA Feature LS DATA Material Asphalt Asphalt	o 704 and 708 10 ads from the prin	Treatment Shingled Shingled	Source	ed by a
Site Notes: January 2010: This sing from 10th Street, N.E. The milled point metal fence concrete alley is located NOTABLE FEATURE: Component EXTERIOR MATERIA Roof Component Bay Roof Side gable	he dwelling is adjacent to the Aconcrete walkway lead west of the dwelling. S DATA Feature LS DATA Material Asphalt Asphalt Material	o 704 and 708 10 ads from the prin	Treatment Shingled Shingled Treatment	Source	ed by a
Site Notes: January 2010: This sing from 10th Street, N.E. The milled point metal fence concrete alley is located NOTABLE FEATURE: Component EXTERIOR MATERIA Roof Component Bay Roof Side gable Wall Component Facade	he dwelling is adjacent to A concrete walkway lead west of the dwelling. S DATA Feature LS DATA Material Asphalt Asphalt Material Brick	c 704 and 708 10 ads from the prin	Treatment Shingled Shingled Treatment	Source	ed by a

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Clerestory	Rectangular	Unknown	1-light	Vinyl	
Door Location	Aperture Shape	Type	Pamels	Material	
Main Door	Rectangular	Single	Paneled	Unknown w/Lights	
Notable Interior Plan(s)			Notable Interior Feature(s)		

Tuesday, June 25, 2013 ID_Number: 0912-0076 Page 2

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Capitol Hill F & G Streets (2010)

Subdivision: Ward/ANC: Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s) Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 706_10th_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 706_10th_Street_NE_facade_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 910 G Street NE 700-718

10th_Street_NE_rear_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

Permit Issue Date Number Type Remarks Permit Notes: BIBLIOGRAPHIC DATA Short Citation Type Date Remarks Bibliographic Notes: SIGNIFICANCE DATA Study Unit Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/17/2010	Dayton (MSD), Maria	Record Updated
2/17/2010	Dayton (MSD), Maria	Record Created

ID Number: 0912-0075

BASICS DATA

ID Number: 0912	-0075 Year	Built: c. 1990	Data	Source: DC Rea	al Property Database	
Number Extended	Street		Quad	Type of Address		
708	10th Street		NE	Current		
Name(s) Single Dwelling, 708	10th Street, N.E.	Type o				
TaxCode1 TaxCode 0912/0075	2 TaxCode3 Type Square	Explai /Lot Curre				
STATUS/PURPOSI	E/USE DATA					
Resource Type: Buil	_			ent: Extant		
o .	Historic idential	Qua	ality: ndition:	Good		
ruipose. Res	identiai	Cor	idition.	Good		
Function/Use	Start	Source	Stop	Source	Explain	
Residential (Single-F	family) c. 1990	DC Real Pi			Historic/Current	
CONSTRUCTION I	DATA					
Construction Event	Start	Source	Stop	Source	Cost Source	
Orig Construction	c. 1990	DC Real				
		Property Database				
Construction Event	Associa	ation		Associated Na	ame	
						
Construction Notes:						
DEODI E/EVENTO	D.1.T.1					
PEOPLE/EVENTS						
Racial Segregation St	atus:					
SETTING/SHAPE/S	SIZE DATA					
Surroundings:	Urban		ross Re	ference Notes:		
Streetscape:	Intact	_				
Relate to Othr Bldgs:						
Relate to Street: Massing:	Face on Setback Line					
Footprint:	Vertical Box/rectang	bay				
Number Stories:	2					
Bays Wide:	2					
Height:		Outbuildir	ng Type	C	Contributing Status	
Width:						
Depth/Length: SqFt:						
Volume:						
Lot Width						
Lot Depth/Length:		Outbuildir	ng Notes	:		
Lot SqFt:						
Acreage:						
Has Driveway:						

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

January 2010: Constructed c. 1990, this two-story, two-bay single-family dwelling is constructed of concrete blocks and is set on a solid, raised concrete block foundation; both are faced with stretcher-bond brick. Soldier brick string courses are located above the foundation, first, and second story openings. Additional header brick string courses are sited beneath the first and second story windows. A side-gabled roof caps the dwelling and is covered with asphalt shingles. The northernmost round-headed bay of the façade (east elevation) is recessed forming an integrated porch and is pierced by a single-leaf paneled door with a round-headed light and a one-light transom. A soldier-brick round-headed surround complements the recessed opening. A stuccoed surround complements the door. The second story opening holds a fixed circular window with a rowlock brick circular surround. A three-sided, rectangular bay projects from the southernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a front-gabled roof. The roof is covered with asphalt shingles and feature overhanging eaves and raking metal boards. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. A circular fixed window is sited in the upper gable end and has a circular rowlock brick surround. The rear (west) elevation is stuccoed and is pierced by single and paired 1/1, double-hung, vinyl-sash windows and a single-leaf door. A one-story, one-bay porch shelters the entrance and is capped by a shed roof.

Site Notes:

January 2010: This single dwelling is located on the west side of 10th Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 706 and 710 10th Street, N.E. The grassy front yard is landscaped with small shrubs and trees and is encircled with a milled point metal fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. A concrete alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Asphalt		Shingled	
Side gable	Asphalt		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete Block			
Walls	Concrete Block			
Materials Notes:				

WINDOW/DOOR/INTERIOR DATA

Notable Interior Plan(s)			Notable Interior Feature(s)		
Main Door	Rectangular	Single	Paneled	Unknown	
Door Location	Aperture Shape	Туре	Pamels	Material	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Circular	Fixed	4 Lite	Unknown	
2 Flr Windows	Circular	Fixed	4 Lite	Unknown	
Window Location	Aperture Shape	Type	Lights	Material	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC: Zoning:

Contributing: Survey(s)

Capitol Hill F & G Streets (2010)

Historic District(s)

Designation Event(s)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

C:\Users\CHRS\Documents\CHRS Path:

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 708_10th_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

C:\Users\CHRS\Documents\CHRS Path:

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 708_10th_Street_NE_facade_looking_SW.JPG

Date:: Photog:

Fr: Code:: R:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 910 G Street NE 700-718

10th_Street_NE_rear_looking_NE.JPG

Date:: Photog:

Code:: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Frame(s) Date Photographer Caption Roll

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA	1				
Permit Issue Dat	e Number Type		Remarks		
Permit Notes:					
BIBLIOGRAPH	HIC DATA				
Short Citation		Туре	Date	Remarks	
Bibliographic Not	tes:				
SIGNIFICANC	E DATA				
Study Unit					
Code 0	Criteria				
DATA PROCE	SSING EVENTS DATA				
Date 3/18/2010	Individual Trieschmann (LVT), Laura	Action	utod.		

Record Updated

Record Created

Dayton (MSD), Maria

Dayton (MSD), Maria

2/18/2010 2/18/2010

ID Number: 0912-0074

BASICS DATA

ID Number: 0912	-0074	Year Built	t: c. 1990	Data :	Source: DC	Real Property Database		
Number Extended	Street			Quad T	ype of Address			
710	10th Street			NE C	urrent			
Name(s)			Type of	Name		<u> </u>		
Single Dwelling, 710	10th Street, N.E		Commo	on				
TaxCode1 TaxCode	2 TaxCode3 T	уре	Explair	า				
0912/0074	S	quare/Lot	Currer	nt		_		
STATUS/PURPOS	E/USE DATA							
Resource Type: Buil	ding		Stat	us Currer	nt: Extant			
o .	Historic		Qua	-				
Purpose: Res	idential		Con	dition:	Good			
Function/Use	Ş	Start	Source	Stop	Source	e Explain		
Residential (Single-F	amily) c	. 1990	DC Real Pr				_	
CONSTRUCTION I	DATA							
Construction Event	Start	t So	urce	Stop	Source	Cost Source		
Orig Construction	c. 19	Pro	Real operty itabase					
Construction Event	Д	ssociation			Associated	I Name		
							_	
Construction Notes:								
PEOPLE/EVENTS	DATA							
Racial Segregation St	atus:							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban		С	ross Refe	erence Notes:			
Streetscape:	Intact							
Relate to Othr Bldgs:	Attached							
Relate to Street:	Face on Setbac	k Line						
Massing:	Vertical Box/red	ctang bay						
Footprint:	Rectangular							
Number Stories:	2							
Bays Wide:	2							
Height:			Outbuildin	g Type		Contributing Status		
Width:								
Depth/Length:								
SqFt: Volume:								
Lot Width								
Lot Depth/Length:			Outbuildin	g Notes:				
Lot SqFt:								
Acreage:								
Has Driveway:								

STYLE/EXTERIOR DATA
Architectural Style(s)
Modern
Exterior & Architectural Notes:
January 2010: Constructed c. 1990, this two-story, two-bay single-family dwelling is constructed of concrete blocks and is set on a solid, raised concrete block foundation; both are faced with stretcher-bond brick. Soldier brick veneer string courses are located above the foundation, first, and second story openings. Additional header brick string courses are sited beneath the first and second story windows. A side-gabled roof caps the dwelling and is covered with asphalt shingles. The southernmost bay of the façade is recessed forming an integrated porch and is pierced by a single-leaf paneled door with lights and a one-light transom. A stuccoed surround complements the opening. The second story opening holds paired one-light fixed windows. A three-sided, rectangular bay projects from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a front-gabled roof. The roof is covered with asphalt shingles and feature overhanging eaves and raking metal boards. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows and a circular fixed window in the upper gable end. The circular window is surrounded by rowlock bricks. The rear (west) elevation is stuccoed and is pierced by single and paired 1/1, double-hung, vinyl-sash windows and a single-leaf door. A one-story, one-bay shed shelters the door and has a shed roof.
Site Notes:
January 2010: This single dwelling is located on the west side of 10th Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 708 and 712 10th Street, N.E. The landscaped front yard is planted with mature shrubs and is encircled with a milled point metal fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. A concrete alley is located west of the dwelling.

NOTABLE FEATURES DATA

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Asphalt		Shingled	
Side gable	Asphalt		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete Block			
Walls	Concrete Block			
Materials Notes:				

WINDOW/DOOR/INTERIOR DATA

Interior Notes:

Window Location	Aperture Shape	Туре	Lights	Material	
2 Flr Windows	Rectangular	Fixed	1-light	Vinyl	
Bay Windows	Circular	Fixed	Unknown	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single	Paneled	Unknown w/Lights	
Notable Interior Plan(s)			Notable Interior Feature(s)		

Tuesday, June 25, 2013 ID_Number: 0912-0074 Page 2

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Subdivision: Ward/ANC: Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 710_10th_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 710_10th_Street_NE_facade_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 910 G Street NE 700-718

10th_Street_NE_rear_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

Permit Issue Date Number Type Remarks Permit Notes: BIBLIOGRAPHIC DATA Short Citation Type Date Remarks Bibliographic Notes: SIGNIFICANCE DATA Study Unit Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/18/2010	Dayton (MSD), Maria	Record Updated
2/18/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0912-0074 Page 4

ID Number: 0912-0073

BASICS DATA

ID Number: 0912	-0073	Year Buil	t: c. 1990	Data	a Source: DC Re	eal Property Database	
Number Extended	Street			Quad	Type of Address		
712	10th Street			NE	Current		
Name(s)			Type of	Name			
Single Dwelling, 712	10th Street, N	.E.	Commo	on			
TaxCode1 TaxCode	2 TaxCode3	Туре	Explair	า			
0912/0073		Square/Lot	Currer	nt			
STATUS/PURPOS							
Resource Type: Buil Desig. Status: Not	laing Historic		Stat Qua		ent: Extant		
-	idential			dition:	Good		
Function/Use		Start	Source	Stop	Source	Explain	
Residential (Single-F	Family)	c. 1990	DC Real Pr		Source	Historic/Current	
, -							
CONSTRUCTION I	DATA						
Construction Event	Sta			Stop	Source	Cost Source	
Orig Construction	C.		C Real operty				
			atabase				
Construction Event		Association			Associated N	Name	
Construction Notes:							
PEOPLE/EVENTS	ΠΑΤΑ						
Racial Segregation St	latus.						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		С	ross Re	eference Notes:		
Streetscape:	Intact						
Relate to Othr Bldgs: Relate to Street:		l - l - l					
Massing:	Face on Setba						
Footprint:	Rectangular	0 ,					
Number Stories:	2						
Bays Wide:	2						
Height: Width:			Outbuildin	g Type		Contributing Status	
Depth/Length:							
SqFt:							
Volume:							
Lot Width Lot Depth/Length:			Outbuildin	a Notes	s:		
Lot SqFt:			- Casanan		- -		
Acreage:							
Has Driveway:							

STYLE/EXTERIOR	DATA				
Architectural Style(s)			_		
Modern					
Exterior & Architectura					
is set on a solid, rais courses are located sited beneath the firs shingles. The northe paneled door with ligopening holds a 1/1, of the façade and ris by a pyramidal roof. single and paired 1/1 and is pierced by sin	ructed c. 1990, this two led concrete block four above the foundation, is and second story wir rnmost bay of the faça lights and a one-light tradouble-hung, vinyl-sases the full height of the The roof is covered wit, double-hung, vinyl-sagle and paired 1/1, dountrance and has a shed	ndation; both are face first, and second story ndows. A side-gabled de is recessed formin nsom. A stuccoed sur sh window. A three-side dwelling. The bay ha th asphalt shingles and ash windows and clere able-hung, vinyl-sash	d with stretcher-bon y openings. Addition roof caps the dwelli g an integrated porc rround complements ded, rectangular bay s the material treatn d feature overhangi estory windows. The	ad brick. Soldier be all header brick so all header brick so and is covered be and is pierced be the opening. The projects from the nent of the main be aves. Fenestre rear (west) eleva	rick veneer string cring courses are I with asphalt by a single-leaf e second story e southernmost bay lock and is capped ration consists of tion is stuccoed
Site Notes:					
NOTABLE FEATUR	RES DATA Featur	•		····· 3 ·	
EVTEDIOD MATER	NALO DATA				
Roof Component	Material	Color	Treatment	Source	
Bay Roof	Asphalt	00101	Shingled	Cource	
Side gable	Asphalt		Shingled		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond	1	
	Material	Feature		Source	
Structure Component	iviatoriai				
	Concrete Block	- Catalo			
<u>'</u>		. outdro			
Foundation	Concrete Block	- r sandro			
Foundation Walls	Concrete Block	T GALGIO			
Foundation Walls	Concrete Block	, odiaio			
Foundation Walls	Concrete Block Concrete Block	1 64.610			
Foundation Walls Materials Notes:	Concrete Block Concrete Block	Type	L	ights	Material
Foundation Walls Materials Notes: WINDOW/DOOR/IN	Concrete Block Concrete Block				Material Vinyl
Foundation Walls Materials Notes: WINDOW/DOOR/IN Window Location	Concrete Block Concrete Block ITERIOR DATA Aperture Shape	Туре	1.	ights	
Foundation Walls Materials Notes: WINDOW/DOOR/IN Window Location 2 Flr Windows	Concrete Block Concrete Block ITERIOR DATA Aperture Shape Rectangular	Type Dbl-Hung	1, 1, 1,	ights /1	Vinyl

Notable Interior Plan(s)			Notable Interior Feature(s)			
Main Door	Rectangular	Single	Paneled	Unknown w/Lights		
Door Location	Aperture Shape	Туре	Pamels	Material		
Clerestory	Rectangular	Unknown	1-light	Vinyl		
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl		
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl		
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl		
Window Location	Aperture Shape	Туре	Lights	Material		

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill
Subdivision:

Ward/ANC:

Historic District(s)

Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 712_10th_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 712_10th_Street_NE_facade_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 910_G_Street_NE_700-718

10th_Street_NE_rear_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:		

PERMIT DATA			
Permit Issue Date	Number Type	Remarks	
Permit Notes:			
BIBLIOGRAPHIC DATA			
Short Citation	Туре	Date Remarks	
Bibliographic Notes:			
SIGNIFICANCE DATA			
Study Unit			
Code Criteria			_
DATA PROCESSING EVE	NTS DATA		

Action

Record Updated

Record Updated

Record Created

Individual

Trieschmann (LVT), Laura

Dayton (MSD), Maria

Dayton (MSD), Maria

Date 3/18/2010

2/18/2010

2/18/2010

ID Number: 0912-0072

BASICS DATA

ID Number: 0912	-0072	Year Bui	t: c. 1990	Dat	a Source: DC R	eal Property Database	
Number Extended	Street			Quad	Type of Address		
714	10th Street			NE	Current		
Name(s)			Type of	f Name			
Single Dwelling, 714	10th Street, N	I.E.	Comm	on			
TaxCode1 TaxCode	2 TaxCode3	Туре	Explair	n			
0912/0072		Square/Lo					
STATUS/PURPOS		1					
Resource Type: Bui Desig. Status: Not	lding Historic				ent: Extant		
-	idential		Qua Con	iiity. idition:	Good		
		. .					
Function/Use Residential (Single-I	Family)	Start c. 1990	Source DC Real Pr	Stop	Source	Explain Historic/Current	
Residential (Omgle-I	anny)	0. 1550	DO Real I			riistorio/Ourrent	
CONSTRUCTION I	DATA						
Construction Event	St	art So	ource	Stop	Source	Cost Source	
Orig Construction	C.		C Real				
			operty atabase				
Construction Event		Association			Associated N	Name	
Construction Notes:							
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
0====							
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		C	ross Re	eference Notes:		
Streetscape: Relate to Othr Bldgs:	Intact Attached						
Relate to Street:	Face on Seth	ack Line					
Massing:	Vertical Box/	rectang bay					
Footprint:	Rectangular						
Number Stories:	2						
Bays Wide: Height:	2		Outbuildin	na Type		Contributing Status	
Width:			Outbuildin	ig Type		Contributing Status	
Depth/Length:							
SqFt:							
Volume: Lot Width							
Lot Depth/Length:			Outbuildin	ng Note:	s:		
Lot SqFt:							
Acreage:							
Has Driveway:							

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

January 2010: Constructed c. 1990, this two-story, two-bay single-family dwelling is constructed of concrete blocks and is set on a solid, raised concrete block foundation; both are faced with stretcher-bond brick. Soldier brick veneer string courses are located above the foundation, first, and second story openings. Additional string courses of header brick are located beneath the first and second story windows. A side-gabled roof caps the dwelling and is covered with asphalt shingles. The southernmost bay of the façade is recessed forming an integrated porch with a quarter-circle opening and is pierced by a single-leaf paneled door with lights and a one-light transom. A stuccoed surround complements the opening. The second story opening holds a two-light window. A three-sided, rectangular bay projects from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a shed roof. The roof is covered with asphalt shingles and feature raking metal boards. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. A quarter-circle fixed light is positioned over the central opening of the second story. A soldier brick quarter-circle arch complements the light and continues as a string course. A stuccoed panel is located between the first and second story central openings. The rear (west) elevation is stuccoed and is pierced by single and paired 1/1, double-hung, vinyl-sash windows and a single-leaf door. A one-story, one-bay porch shelters the entrance and is capped by a shed roof.

Site Notes:

January 2010: This single dwelling is located on the west side of 10th Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 712 and 716 10th Street, N.E. The landscaped front yard is planted with mature shrubs and is encircled by a milled point metal fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. A concrete alley is located west of the dwelling.

NOTABLE FEATURES DATA

|--|

EXTERIOR MATERIALS DATA

Walls Materials Notes:	Concrete Block				
Foundation	Concrete Block				
Structure Component	Material	Feature		Source	
Facade	Brick		Stretcher Bond		
Wall Component	Material	Color	Treatment	Source	
Side gable	Asphalt		Shingled		
Bay Roof	Asphalt		Shingled		
Roof Component	Material	Color	Treatment	Source	

WINDOW/DOOR/INTERIOR DATA

Notable Interior Plan(s)			Notable Interior Feature(s)		
Main Door	Rectangular	Single	Paneled	Unknown w/Lights	
Door Location	Aperture Shape	Type	Pamels	Material	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows		Fixed	multi	Vinyl	
2 Flr Windows	Rectangular	Unknown	2 Lite	Unknown	
Window Location	Aperture Shape	Туре	Lights	Material	

Interior Notes:		

Tuesday, June 25, 2013 ID_Number: 0912-0072 Page 2

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision: Ward/ANC: Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 714_10th_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

C:\Users\CHRS\Documents\CHRS Path:

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 714_10th_Street_NE_facade_looking_W.JPG

Date:: Photog:

Fr: Code:: R:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 910 G Street NE 700-718


10th_Street_NE_rear_looking_NE.JPG

Date:: Photog:

Fr:







PHOTOS - B/W OR NON-DIGITIZED

Photo Code Frame(s) Date Photographer Caption Roll

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DA	TA					
Permit Issue [Date N	lumber Type		Remarks		
Permit Notes:						
BIBLIOGRA	PHIC DATA					
Short Citation			Туре	Date	Remarks	
Bibliographic I	Notes:					
SIGNIFICAN	ICE DATA					
Study Unit						
Code	Criteria					
DATA PROC	CESSING EVENT	S DATA				
Date	Individual		Action			
3/18/2010 2/18/2010	Trieschman Dayton (MS	n (LVT), Laura D), Maria	Record Upo Record Upo			

Record Created

2/18/2010

Dayton (MSD), Maria

ID Number: 0912-0071

BASICS DATA

ID Number: 0912	-0071	Year Bui	lt: c. 1990	Data	a Source: DC Re	eal Property Database	
Number Extended	Street			Quad	Type of Address		
716	10th Street			NE	Current		
Name(s)			Type of	Name			
Single Dwelling, 716	10th Street, N	l.E.	Comm	on			
TaxCode1 TaxCode	2 TaxCode3	Туре	Explair	n			
0912/0071		Square/Lo	t Currei	nt			
STATUS/PURPOS							
Resource Type: Bui Desig. Status: Not	lding Historic		Stat Qua		ent: Extant		
-	idential			dition:	Good		
Function/Use		Start	Cauras	Cton	Cauras	Fynlein	
Residential (Single-I	Family)	c. 1990	Source DC Real Pr	Stop	Source	Explain Historic/Current	
g.c	, ,						
CONSTRUCTION I	DATA						
Construction Event	St	art So	ource	Stop	Source	Cost Source	
Orig Construction	c.		C Real operty				
			atabase				
Construction Event		Association			Associated N	lame	
Construction Notes:							
DEODI E/EVENTO	DATA						
PEOPLE/EVENTS							
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		C	ross Re	eference Notes:		
Streetscape:	Intact						
Relate to Othr Bldgs:							
Relate to Street: Massing:	Face on Setb Vertical Box/						
Footprint:	Rectangular	lectaring Day					
Number Stories:	2						
Bays Wide:	2		L				
Height:			Outbuildin	ig Type		Contributing Status	
Width: Depth/Length:							
SqFt:							
Volume:							
Lot Width			0	- N			
Lot Depth/Length: Lot SqFt:			Outbuildin	ig inotes	5:		
Acreage:							
Has Driveway:							

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

January 2010: Constructed c. 1990, this two-story, two-bay single-family dwelling is constructed of concrete blocks and is set on a solid, raised concrete block foundation; both are faced with stretcher-bond brick. Soldier brick veneer string courses are located above the foundation, first, and second story openings. Additional string courses of header brick are located beneath the first and second story windows. A side-gabled roof caps the dwelling and is covered with asphalt shingles. The northernmost bay of the façade is recessed forming an integrated porch with a quarter-circle opening and is pierced by a single-leaf paneled door and a one-light transom. A stuccoed surround complements the opening. The second story opening holds a two-light window. A three-sided, rectangular bay projects from the southernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a shed roof. The roof is covered with asphalt shingles and feature raking metal boards. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. A quarter-circle fixed light is positioned over the central opening of the second story. A soldier brick quarter-circle arch complements the light and continues as a string course. A stuccoed panel is located between the first and second story central openings. The rear (west) elevation is stuccoed and is pierced by single and paired 1/1, double-hung, vinyl-sash windows and a single-leaf door. A one-story, one-bay porch shelters the entrance and is capped by a shed roof.

Site Notes:

January 2010: This single dwelling is located on the west side of 10th Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 714 and 718 10th Street, N.E. The landscaped front yard is planted with foundation plantings and is encircled by a milled picket metal fence. A concrete walkway leads from the primary entrance and ends at the sidewalk. A concrete alley is located west of the dwelling.

NOTABLE FEATURES DATA

|--|--|--|

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Asphalt		Shingled	
Side gable	Asphalt		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete Block			
Walls	Concrete Block			
Materials Notes:				

WINDOW/DOOR/INTERIOR DATA

Notable Interior Plan	n(s)		Notable Interior Feature(s)		
Main Door	Rectangular	Single	Paneled	Unknown	
Door Location	Aperture Shape	Туре	Pamels	Material	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows		Fixed	multi	Vinyl	
2 Flr Windows	Rectangular	Unknown	2 Lite	Vinyl	
Window Location	Aperture Shape	Туре	Lights	Material	

Interior Notes:

Tuesday, June 25, 2013 ID_Number: 0912-0071 Page 2

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill
Subdivision:
Ward/ANC:
Zoning: Designation Event(s)

Contributing:

Survey(s)
Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 716_10th_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 716_10th_Street_NE_facade_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Tuesday, June 25, 2013 ID_Number: 0912-0071 Page 3

Bibliograph	nic Notes:			
SIGNIFIC	ANCE DATA			
Study Unit				
Code	Criteria			

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/18/2010	Dayton (MSD), Maria	Record Updated
2/18/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0912-0071 Page 4

ID Number: 0912-0070

BASICS DATA

ID Number: 0912	-0070	Year Bui	t: c. 1990	Data	a Source: DC Re	eal Property Database	
Number Extended	Street			Quad	Type of Address		
718	10th Street			NE	Current		
Name(s)			Type of	Name			
Single Dwelling, 718	10th Street, N	.E.	Commo	on			
TaxCode1 TaxCode	2 TaxCode3	Туре	Explair	n			
0912/0070		Square/Lot	Currer	nt			
STATUS/PURPOS							
Resource Type: Bui Desig. Status: Not	lding Historic		Stat Qua		ent: Extant		
-	idential			inty. idition:	Good		
		. .		•			
Function/Use Residential (Single-I	Family)	Start c. 1990	Source DC Real Pr	Stop	Source	Explain Historic/Current	
Residential (Omgle-I	anny)	C. 1330	DO Real I			riistoric/ourrent	
CONSTRUCTION I	DATA						
Construction Event	St	art So	ource	Stop	Source	Cost Source	
Orig Construction	C.		C Real				
			operty atabase				
Construction Event		Association			Associated N	Name	
Construction Notes:							
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		С	ross Re	eference Notes:		
Streetscape: Relate to Othr Bldgs:	Intact Attached						
Relate to Street:	Face on Setb	ack Line					
Massing:	Vertical Box/	rectang bay					
Footprint:	Rectangular						
Number Stories:	2						
Bays Wide:	2		0 4 31	_		0 1 1 1 0 1	
Height: Width:			Outbuildin	ig Type		Contributing Status	
Depth/Length:							
SqFt:							
Volume:							
Lot Width Lot Depth/Length:			Outbuildin	na Notes	ş.·		
Lot SqFt:			Catballall	9 140168	,		
Acreage:							
Has Driveway:							

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

January 2010: Constructed c. 1990, this two-story, two-bay single-family dwelling is constructed of concrete blocks and is set on a solid, raised concrete block foundation; both are faced with stretcher-bond brick. Soldier brick veneer string courses are located above the foundation and first story openings. A side-gabled roof caps the dwelling and is covered with asphalt shingles. The southernmost bay of the façade is recessed forming an integrated porch and is pierced by a single-leaf wood door and a one-light transom. A stuccoed surround complements the opening. The second story opening holds sliding one-light vinyl windows. A three-sided, rectangular bay projects from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a front-gabled roof. The roof is covered with asphalt shingles and feature raking metal boards. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. A round-headed fixed light is positioned over the central opening of the second story. A soldier brick round-headed arch complements the light and continues as a string course. A stuccoed panel is located between the first and second story central openings. The north (side) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows and sliding one-light vinyl windows. The rear (west) elevation is stuccoed and is pierced by single and paired 1/1, double-hung, vinyl-sash windows and a single-leaf door. A one-story, one-bay porch shelters the entrance and is capped by a shed roof.

Site Notes:

January 2010: This single dwelling is located on the west side of 10th Street, N.E. and is set back approximately five feet from the brick sidewalk. The south (side) elevation of the dwelling is adjacent to 716 10th Street, N.E. An alley is located north of the dwelling. The grassy front yard is landscaped with foundation plantings and is encircled by milled point metal fencing. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. A concrete alley is located west of the dwelling.

NOTABLE FEATURES DATA Component Feature

EXTERIOR MATERIALS DATA

Asphalt		Shingled	
Asphalt		Shingled	
Material	Color	Treatment	Source
Brick		Stretcher Bond	
Material	Feature		Source
Concrete Block			
Concrete Block			
_	Material Brick Material Concrete Block	Material Color Brick Material Feature Concrete Block	Material Color Treatment Brick Stretcher Bond Material Feature Concrete Block

WINDOW/DOOR/INTERIOR DATA

Notable Interior Plan(s)		Notable Interior Feature(s)			
Main Door	Rectangular	Single		Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
Bay Windows	Semi-Circular	Fixed	1-light	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
2 Flr Windows	Rectangular	Sliding	1-light	Vinyl	
Window Location	Aperture Shape	Type	Lights	Material	

Interior Notes:

Tuesday, June 25, 2013 ID_Number: 0912-0070 Page 2

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Subdivision: Ward/ANC: Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0912\

File: 718_10th_Street_NE_facade_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 718_10th_Street_NE_facade_looking_W.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 910_G_Street_NE_700-718

10th_Street_NE_rear_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

						_	
PERMIT D	DATA						
Permit Issu	ue Date	Number Type		Remarks			
Permit Note	es:						
BIBLIOGE	RAPHIC DATA						
Short Citati	ion		Туре	Date	Remarks		
Bibliograph	nic Notes:						
SIGNIFIC	ANCE DATA						
Study Unit							
Code	Criteria						
DATA PR	OCESSING EVE	ENTS DATA					
Date	Individua	al	Action				

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
2/18/2010	Dayton (MSD), Maria	Record Updated
2/18/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0912-0070 Page 4

ID Number: 0912-0057

BASICS DATA

ID Number: 0912-0057 Year Built: 1980 Data Source: Sanborn Map Quad Type of Address Number Extended Street 900 **G** Street Current Name(s) Type of Name Apartment Building, 900 G Street, N.E. Common Housing for the Elderly Historic **Capitol Hill Towers** Current TaxCode1 TaxCode2 TaxCode3 Type Explain 0912/0057 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Not Historic Quality:

Purpose: Apartment Condition: Good

Function/UseStartSourceStopSourceExplainResidential (Multi-Family)1980Site VisitHistoric/Current

Residential (Elderly Housing) Sanborn M Historic

CONSTRUCTION DATA

 Construction Event
 Start
 Source
 Stop
 Source
 Cost Source

 Orig Construction
 1980
 Sanborn Map

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0912-0057 Page 1

Surroundings:	Urban	Cross Refe	ence Notes:		
Streetscape:	Intact				l
Relate to Othr Bldgs:	~				l
Relate to Street:	Front Yard w/ Setback				l
Massing:	Vertical Block				l
Footprint:	S Shaped				l
Number Stories: Bays Wide:	8				
Height:		Outbuilding Type	Со	ntributing Status	
Width:		Gazebo			
Depth/Length:					
SqFt:					
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes:			
Lot SqFt:				c. 1995, is located north	İ
Acreage:			e wood-frame gazel	bo is capped by an phalt shingles. A cupola	İ
Has Driveway:		-		Square wood balusters	l
_		encircle the gazebo	•	- quai	l
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Modern					
	al Natas.				
Exterior & Architectura		- (ow known as Capitol Hill 1	
east (side) elevation Multiple balconies p projecting brick wall building does not fedoors and paired on light vinyl sliding with balcony units. An aw	of the western block. A flat roject from the façade (so its that rise the full height cature balconies. The face e-light vinyl sliding windoundows. The rear elevation whing extends from the east	at roof caps the buildi uth elevation), east (s of the dwelling. Metal of each balcony unit i ws. The first story un is fenestrated by pair sternmost bay of the f	ng and is fronted b ide), and rear (north balusters enclose e s stuccoed and is p its of the building a ed one-light vinyl s açade of the weste	om the southernmost bay y a short, brick parapet wan) elevations and are divideach balcony. The first storierced by sliding vinyl-frar re fenestrated with paired liding windows and also forn block and reaches the balcors and a one-light metals.	ill. ed by ry of the ne glass one- eatures orick
Site Notes:					
feet from the brick s foundation plantings edges the westernm	idewalk. The building is si s. A metal picket fence bou	ted on a level, grassy unds the southernmo idaries of the propert	lot that features ma st boundary of the p y. The rear yard of t	d is set back approximately ature trees and shrubs, as property and chain-link fen he property is paved with a	well as cing
NOTABLE FEATUR	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Poof Company	Motorial	Color	Trootmant	Course	
Roof Component Flat	Material Not Visible	Color	Treatment Not Visible	Source	
		0.1		0	
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	

Tuesday, June 25, 2013 ID_Number: 0912-0057 Page 2

Foundation

Walls

Concrete Block

Concrete Block

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
Facade Windows	Rectangular	Sliding	1-light	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Double	Full Glass	Vinyl/Glass	
Main Door	Rectangular	Double		Metal	
Notable Interior Plan	(s)		Notable Interior Feature(s)		

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Subdivision: Ward/ANC: Zoning: Contributing:

Survey(s)

Capitol Hill F & G Streets (2010)

Historic District(s)

Designation Event(s)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 900_G_Street_NE_closeup_rear_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0912\

File: 900_G_Street_NE_facade_looking_NE(1).JPG

Date:: Photog:

Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 900_G_Street_NE_facade_looking_NE(2).JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 900_G_Street_NE_facade_looking_NE(3).JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 900_G_Street_NE_facade_looking_NNE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 900_G_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 900_G_Street_NE_facade_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:









\sim				
Ca	nti	\cap	n	•
Οu	ν u	\mathbf{c}		

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 900_G_Street_NE_gazebo_looking_E.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 900_G_Street_NE_rear_looking_SE(1).JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\

File: 900_G_Street_NE_side_looking_SE(1).JPG

Date:: Photog:

Code:: R: Fr:

Caption:

File:

Path: C:\Users\CHRS\Documents\CHRS

Database\F&G Street - 2 to 11th St\Database\Pictures\Square 0912\ 900_G_Street_rear_looking_SE(2).JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue	Date	Number Type		Remarks			
Permit Notes	X:						
BIBLIOGRA	APHIC DATA						
Short Citation	n		Туре	Date	Remarks		_
Bibliographic	: Notes:						
SIGNIFICA	NCE DATA						
Study Unit							
Code	Criteria					-	
DATA PRO	CESSING EVEN	NTS DATA					
Date	Individual		Action				
2/18/2010 2/18/2010		ISD), Maria ISD), Maria	Record Upda Record Crea				

Tuesday, June 25, 2013 ID_Number: 0912-0057 Page 6

ID Number: 0912-0055a

BASICS DATA

ID Numbe	er: 0912	-0055a	Year Built:	1986-1987 Da	ata Source:	Sanborn Map
Number	Extended	Street		Qua	nd Type of Ad	dress
801a	-957	H Street		NE	Current	
Name(s)				Type of Nam	e	
Shopping	g Center, 80	1a-957 H Str	eet, N.E.	Common		
UPS				Current		
Dana Jev	velry			Current		
Smile Dr	y Cleaners			Current		
Ace Chec	ck Cashing			Current		
Executiv	e Flowers			Current		
Styles				Current		
Ann's Na	ils			Current		
McDonal	d's Express	;		Current		
Rainbow	Juniors Sh	oes		Current		
Freddy's	Subs and F	ries		Current		
Game St	ор			Current		
Subway				Current		
Rent-a-C	enter			Current		
Rite Aid				Current		
Sports Z	one			Current		
TaxCode	1 TaxCode	2 TaxCode3	Туре	Explain		
0912/005	5a		Square/Lot	Current		

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Not Historic Quality:

Purpose: Shopping Center Condition: Good

Function/Use Start Source Stop Source Explain

Shopping Center/Retail 1986-1987 Map Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source	
Orig Construction	1986-198	7 Sanborn N	І ар			
Construction Event	Assoc	ciation		Associated	Name	

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0912-0055a Page 1

Site Notes: May 2009: This free- An asphalt parking I NOTABLE FEATU Component EXTERIOR MATE Roof Component Flat Vall Component Facade Structure Component Foundation Valls	RIALS DATA Material Not Visible Material Brick Material Concrete Block Concrete Block			Source Source	the street.
Site Notes: May 2009: This free-	RES DATA Feature RIALS DATA Material Not Visible Material Brick Material Concrete Block	Color Color	Treatment Not Visible Treatment	Source	the street.
Site Notes: May 2009: This free- An asphalt parking I NOTABLE FEATU Component EXTERIOR MATE Roof Component Flat Wall Component Facade Structure Component Foundation Walls	RES DATA Feature RIALS DATA Material Not Visible Material Brick Material Concrete Block	Color Color	Treatment Not Visible Treatment	Source	the street.
Site Notes: May 2009: This free- An asphalt parking I NOTABLE FEATU Component EXTERIOR MATE Roof Component Flat Wall Component Facade Structure Component Foundation Walls	RES DATA Feature RIALS DATA Material Not Visible Material Brick Material Concrete Block	Color Color	Treatment Not Visible Treatment	Source	the street.
Site Notes: May 2009: This free- An asphalt parking I NOTABLE FEATU Component EXTERIOR MATE Roof Component Flat Wall Component Facade Structure Component Foundation	RES DATA Feature RIALS DATA Material Not Visible Material Brick Material Concrete Block	Color Color	Treatment Not Visible Treatment	Source	the street.
Site Notes: May 2009: This free- An asphalt parking I NOTABLE FEATU Component EXTERIOR MATE Roof Component Flat Vall Component Facade Structure Component	RES DATA Feature RIALS DATA Material Not Visible Material Brick Material	Color Color	Treatment Not Visible Treatment	Source	the street.
Site Notes: May 2009: This free- An asphalt parking I NOTABLE FEATU Component EXTERIOR MATE Roof Component Flat Wall Component	RES DATA Feature RIALS DATA Material Not Visible Material	ct is landscaped with	Treatment Not Visible Treatment	Source	the street.
Site Notes: May 2009: This free- An asphalt parking I NOTABLE FEATU Component EXTERIOR MATE Roof Component Flat Wall Component	RES DATA Feature RIALS DATA Material Not Visible Material	ct is landscaped with	Treatment Not Visible Treatment	Source	the street.
Site Notes: May 2009: This free- An asphalt parking I NOTABLE FEATU Component EXTERIOR MATER Roof Component	RES DATA Feature RIALS DATA Material	ot is landscaped with	Treatment		the street.
Site Notes: May 2009: This free- An asphalt parking I NOTABLE FEATU Component EXTERIOR MATER Roof Component	RES DATA Feature RIALS DATA Material	ot is landscaped with	Treatment		the street.
Site Notes: May 2009: This free- An asphalt parking I NOTABLE FEATU Component	RES DATA Feature			IE and is setback from	the street.
Site Notes: May 2009: This free- An asphalt parking I NOTABLE FEATU Component	RES DATA Feature			IE and is setback from	the street.
Site Notes: May 2009: This free- An asphalt parking	RES DATA			IE and is setback from	the street.
Site Notes: May 2009: This free- An asphalt parking	RES DATA			IE and is setback from	the street.
Site Notes: May 2009: This free- An asphalt parking	ot fronts the stores. The le			IE and is setback from	the street.
Site Notes: May 2009: This free-				IE and is setback from	the street.
Site Notes:	otonding oberming acute	in located on the	ith aide of U Ctuest h	IE and is setherly from	the etreet
sixteen businesses. blocks and is set on brick. A flat roof cap seam metal. An arca	This building replaced a nation as a solid concrete block for some the building. Mock gablade spans the entirety of the tion consists of one-light	row of three-story stor undation. The façade es, featuring barrel va ne façade and support	res. The L-shaped ce (north elevation) is n ults, rise from the ro ts the roof with squa	nter is constructed of one of the constly faced with stretcon of and are covered with the masonry posts that a	concrete her-bond h standing- are faced
Exterior & Architectur May 2009: This one-	al Notes: story, multi-bay shopping	center was construct	ed from 1986 to 1987	and has space for app	oroximately
`	•				
Architectural Style(s) Commercial (Moder	n)				
Architectural Style(s)	LDAIM				
STYLE/EXTERIOR	P DATA				
Has Driveway:					
Acreage:	1				
Lot SqFt:					
Lot Depth/Length:		Outbuilding Notes:			
Lot Width					
SqFt: Volume:					
Depth/Length:					
Width:		Cate and my Type			
Bays Wide: Height:		Outbuilding Type	Con	tributing Status	
Number Stories:	1				
	L-Shaped				
Footprint:					
Massing: Footprint:	Block				
Relate to Street: Massing:	Parking Lot Setback				1
Massing:	Parking Lot Setback				

Tuesday, June 25, 2013 ID_Number: 0912-0055a Page 2

1-light

Metal

Fixed

Windows (All)

Rectangular

 Door Location
 Aperture Shape
 Type
 Pamels
 Material

 First Floor
 Rectangular
 Single
 Metal/Glass

 Notable Interior Plan(s)
 Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Subdivision: Ward/ANC: Zoning: Contributing: Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill H Street (2009)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0912\

File: H Street_801-957_side_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0912\

File: H Street_801A-957_facade detail3.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0912\

File: H Street_801A-957_facade detail6.JPG

Date:: Photog:

Code:: R: Fr:







Ca		

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0912\

File: H Street_801A-957_facade_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0912\

File: H Street_801A-957_facade_detail11.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0912\

File: H Street_801A-957_facade detail8.JPG

Date:: Photog:

Code:: R: Fr:







PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Tuesday, June 25, 2013 ID_Number: 0912-0055a Page 4

Bibliographic Notes:			
			<u></u>
SIGNIFICANCE DATA			
Study Unit			

DATA PROCESSING EVENTS DATA

Criteria

Code

Date	Individual	Action	
8/5/2009	Dayton (MSD), Maria	Record Updated	
8/3/2009	Dayton (MSD), Maria	Record Updated	
8/3/2009	Dayton (MSD), Maria	Record Created	

Tuesday, June 25, 2013 ID_Number: 0912-0055a Page 5

ID Number: 0912-0055b

BASICS DATA

ID Number: 0912	-0055b	Year Built:	1988	Dat	a Source:	Maps		
Number Extended	Street			Quad	Type of Add	dress		
961	H Street				Current			
Name(s)			Type of	Name				
Bank, 961 H Street, I	N.E.		Commo	n				
Bank of America			Current	:				
965 H Street, N.E.			Origina	I				
TaxCode1 TaxCode	2 TaxCode3	В Туре	Explain	l				
0912/0055b		Square/Lot	Permit					
STATUS/DUDDOS	E/USE DAT	Α.						
STATUS/PURPOS Resource Type: Buil		A	Stati	ıs Curr	rent: Extant			
	Historic		Qual		ont. Extent			
Purpose: Ban				dition:	Good			
Function/Use		Start	Source	Ston		Source	Explain	
Bank			Map	Stop	•	Jource	Original	
Dairk		1300	wap				Original	
CONSTRUCTION I	DATA							
Construction Event		Start Sou	ırce :	Stop	Source	9	Cost Source	
Orig Construction		1988 Ma						
Construction Event		Association	-		Asso	ciated Na	me	
							<u> </u>	
Construction Notes:								
Construction (Votes:								
PEOPLE/EVENTS	DATA							
Racial Segregation St	tatus:							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban		Cı	oss Re	eference No	tes:		
Streetscape:	Intact							
Relate to Othr Bldgs:	Detached							
Relate to Street:	Face on Lin	e						
Massing:	Block							
Footprint:	Rectangula	r						
Number Stories:	1							
Bays Wide:								
Height:			Outbuilding	д Туре	!	C	Contributing Status	_
Width:								
Depth/Length: SqFt:								
Volume:								
Lot Width								
Lot Depth/Length:			Outbuilding	g Notes	s:			
Lot SqFt:								
Acreage:								
Has Driveway:								

STYL			

Architectural Style(s)

Exterior & Architectural Notes:

May 2009: This one-story bank was constructed in 1988. The masonry building and solid foundation are veneered in stretcher-bond brick. On the east, south, and west elevations is a stringcourse made of tile. All elevations feature a wide band on concrete, which is located towards the top of the building. A flat roof is partially hidden behind a parapet wall veneered in stretcher-bond brick and finished with metal flashing. On the north (front) and south (rear) elevations of the building is a decorative, front-gabled pediment made of metal and featuring a segmental arch. Fenestration on the façade is made up of a band of one-light metal storefront windows with a wide concrete panel above. The western third of the façade is recessed, protected by an overhang that continues the concrete panel motif. The entry, which holds a double-leaf glass door in a metal frame, is located under the overhang. In the northern portion of the east (side) elevation are two examples of one-light fixed windows with a one-light, round-arched window above. On the south (rear) elevation is a two-bay carport that is supported by concrete columns. The only fenestration on the south elevation is a single-leaf window used by the bank teller. The west (side) elevation has a single-leaf metal door and a one-light fixed window with a one-light, round-arched window above.

Site Notes:

May 2009: This property is located on the southwest corner of the intersection between H Street, NE and 10th Street, NE. The building fronts a concrete sidewalk on its north and east elevations. An asphalt parking area is located in the rear, south of the building.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Flat	Not Visible				
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Unknown				
Walls	Unknown				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Fixed	1-light	Metal
Door Location	Aperture Shape	Туре	Pamels	Material
Main Door	Rectangular	Double		Metal/Glass
Notable Interior Plan	n(s)		Notable Interior Feature(s)	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC:

Zoning:

Designation Event(s)

Tuesday, June 25, 2013

Survey(s)

Level(s) of Investigation

Permit Research Reconnaissance Survey

PHOTOS - DIGITIZED

Capitol Hill H Street (2009)

Caption:

C:\Users\CHRS\Documents\CHRS Path:

Databases\H Street - 2 to 15th St\Database\Pictures\0912\

H Street_961_facade_looking_S.JPG File:

Date:: Photog:

Code:: R: Fr:

Caption:

C:\Users\CHRS\Documents\CHRS Path:

Databases\H Street - 2 to 15th St\Database\Pictures\0912\

H Street_961_facade_looking_SW.JPG File:

Date:: Photog:

Code:: R: Fr:

Caption:

C:\Users\CHRS\Documents\CHRS Path:

Databases\H Street - 2 to 15th St\Database\Pictures\0912\

File: H Street_961_rear_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\H Street - 2 to 15th St\Database\Pictures\0912\

File: H Street_961_rear-looking_NE.JPG

Date:: Photog:

Code:: R: Fr:











Photo Code Roll Frame(s) Date Photographer Caption

MISCELLA	NEOUS NOTES D	ATA						
Notes:								
PERMIT DA	ATA							
Permit Issue	Date N	lumber Type	Re	marks				
Permit Notes	:							
BIBLIOGRA	APHIC DATA							
Short Citation	1	Ту	pe D	ate	Remarks			
Bibliographic	Notes:							
SIGNIFICA	NCE DATA							
Study Unit								
								
Code	Criteria					-		
DATA PRO	CESSING EVENT	S DATA						
Date	Individual		Action					
8/5/2009	Martinkows	ky (CHM), Christin	Record Updated					

Martinkowsky (CHM), Christin Record Created

8/5/2009

Tuesday, June 25, 2013 ID_Number: 0912-0055b Page 5