

# Resource All Data Report

**ID Number: 0913-0842**

## BASICS DATA

ID Number: **0913-0842** Year Built: **1896** Data Source: **Permit**

Number Extended Street Quad Type of Address

**628** **9th Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 628 9th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0842** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1896** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1896** **Permit** **2750 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **McGee Inc.**

**Orig Construction** **Owner** **Pickford, Charles R.**

Construction Notes:

**One of nineteen rowhouses constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 19)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Rectangular Bay**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

### Queen Anne

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete foundation with a coursed, rock-faced stone veneer, the façade (east elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of asphalt shingles with a metal cornice of scroll moldings and decorative modillions. An interior brick chimney pierces the roof. Projecting from the façade is a full-height bay capped by a front-gabled roof. The projecting bay features the same cornice found on the main block to include raking concrete molding and molded corner pendants. The façade includes a molded concrete sill course extending across the first-story and a molded metal architrave below the second-story openings. Window openings hold landscape windows and 6/6, double-hung, wood-sash. A wide, rock-faced concrete lintel extends above the second-story openings of the projecting bay. The main entry is composed of a vestibule comprised of an outer double-leaf, wood-frame glass door with one-light transom. The inner door was not visible from the public right-of-way. The secondary door opening is located below and holds a single-leaf wood door with lights. The west (rear) elevation of the main block is pierced by 1/1, double-hung, vinyl-sash windows with two-course, rowlock brick segmental arches. A two-story, two-bay ell is located on the rear elevation of the main block. This brick structure has seven-course, American-bond brick coursing and is capped by a shed roof. Fenestration consists of a 1/1, double-hung, wood-sash window with two-course, rowlock brick segmental arch.

The first story of the west (rear) elevation of the ell has an enclosed porch. This wood-frame enclosure, based on its form and materials, was completed c. 1980. The porch includes 1/1, double-hung, metal-sash storm windows and is capped by a shed roof of asphalt shingles.

Site Notes:

**March 2010:** This dwelling is located west of 9th Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The south (side) elevation is attached to 626 9th Street, N.E. and the north (side) elevation to 630 9th Street, N.E. Mature shrubs line the brick sidewalk. A brick walkway extends from the sidewalk to the main entry with metal stairs and deck. The property extends west to a narrow brick alley. The backyard is enclosed by a milled point metal fence. Wood steps provide access to the enclosed rear porch.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False) Sloped</b>	<b>Asphalt Not Visible</b>		<b>Shingled Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>6/6</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>4/4</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>Multi-lite</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Wood/Glass</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)



Interior Notes:

---

## PLAN/SURVEY/DESIGNATION DATA

---

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

---

## PHOTOS - DIGITIZED

---

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **628\_9th\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **628\_9th\_Street\_NE\_facade\_looking\_W.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **628\_9th\_Street\_NE\_rear\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 628\_9th\_Street\_NE\_rear\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created

---



# Resource All Data Report

**ID Number: 0913-0841**

## BASICS DATA

ID Number: **0913-0841** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>630</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 630 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0841</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>McGee, Inc.</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen rowhouses constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 19)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Canted Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete foundation with a coursed, rock-faced stone veneer, the façade (east elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of tin shingles with a metal cornice of scroll moldings and decorative modillions. An interior brick chimney pierces the roof. Projecting from the façade is a full-height canted bay. Extending higher than the main roof line, the projecting bay features one-light fixed wood clerestory windows and overhanging eaves replete with scrolled moldings. Atop the projecting bay is a pyramidal roof of tin shingles adorned with a small metal globe. A molded concrete sill course extends across the first-story in harmony with a molded metal architrave which extends below the second-story openings. A single-leaf paneled wood door pierces the foundation of the façade. The southernmost bay of the first story holds double-leaf wood-frame glass doors with a one-light transom. A three-course, rowlock brick segmental arch tops the transom. Window openings on the façade hold 1/1, double-hung, wood-sash. The foundation of the bay is pierced by one-light wood windows (possibly fixed). A three-course, rowlock brick segmental arch highlights all first story windows. The rear (west) elevation is fenestrated with 2/2, double-hung, wood-sash windows, which have rowlock brick sills.

A two-story ell extends from the southernmost bay of the rear elevation and is original. The parged ell is constructed of brick and is set on a solid foundation. A sloping roof caps the ell. An interior parged chimney pierces the roof. Visible fenestration consists of 2/2, double-hung, wood-sash windows and a single-leaf paneled wood door with lights and a one-light wood transom. The windows have wood sills and are set in segmental openings. A one-story, full-width deck extends from the rear elevation of the ell.

Site Notes:

**March 2010:** This two-story rowhouse is located on the west side of 9th Street, N.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 628 and 632 9th Street, N.E. The front yard is landscaped with mature shrubs. Poured concrete steps lead from the yard to the sidewalk. Wood fencing edges the rear yard. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Tin		Shingled	
Mansard (False)	Tin		Shingled	
Sloped	Not Visible		Not Visible	



Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>1-light</b>	<b>Wood</b>
<b>Clerestory</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1-light</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**  
File: **630\_9th\_Street\_NE\_facade\_looking\_NW.JPG**  
Date:: Photog:  
Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 630\_9th\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 630\_9th\_Street\_NE\_rear\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

#### MISCELLANEOUS NOTES DATA

Notes:

#### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

#### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

#### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0840**

## BASICS DATA

ID Number: **0913-0840** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>632</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 632 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0840</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen rowhouses constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Row (1 of 19)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Row Building/Rectangular Bay**  
 Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**  
 Bays Wide: **2**

Height:	Outbuilding Type	Contributing Status
Width: <b>17</b>		
Depth/Length: <b>32</b>		

SqFt:  
 Volume:  
 Lot Width

Lot Depth/Length: Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling is set on a solid concrete foundation with a course, rock-faced stone veneer. The façade (east elevation) of this brick structure has stretcher-bond brick coursing. The sloped roof is obscured by a false mansard roof of slate shingles with a metal cornice of scrolled moldings and decorative modillions. An interior brick chimney pierces the roof. The façade features a two-story projecting bay capped by a flat roof with brick parapet wall. The parapet wall has scroll molding, dentil molding, and corner pilasters. The façade features a molded concrete sill course extending across the first-story and a molded metal architrave below the second-story openings. Window openings on the façade hold single and paired 1/1, double-hung, vinyl-sash with either one- or three-course, rowlock brick segmental arches. The second-story window openings on the projecting bay have a wide lintel course of pressed metal. The foundation is pierced by paired one-light vinyl sliding windows. The main entry is comprised of a vestibule composed of a single-leaf, paneled wood door with lights and double-leaf wood-frame glass doors; both with one-light transoms. The basement door opening holds a single-leaf, paneled wood door. The rear (west) elevation is fenestrated with a single-leaf metal door and 1/1, double-hung, vinyl-sash windows. All openings have two-course, rowlock brick segmental arches.

A two-story, two-bay ell is located on the west (rear) elevation. This brick structure is capped by a shed roof and pierced by 1/1, double-hung, vinyl-sash windows and a single-leaf wood door with a one-light transom. Window openings have concrete sills and two-course, rowlock brick segmental arches.

A one-story, full-width porch extends the length of the rear elevation of the ell and is set on a square wood post foundation. A shed roof caps the porch and is supported by square wood posts. Square wood balusters encircle the porch, which is accessed via wood steps in the southernmost end bay. Constructed c. 1975, this porch replaced an earlier porch that was noted on the 1928 Sanborn map.

Site Notes:

**March 2010:** This two-story rowhouse is located on the west side of 9th Street, N.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 630 and 634 9th Street, N.E. The landscaped front yard is planted with mature shrubs and is encircled by a metal bow and picket fence. A concrete walkway leads from the primary entrance and ends at the brick sidewalk. The rear yard is bounded by a metal bow and picket fence. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	



<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Sliding</b>	<b>1-light</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Wood/Glass</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 632\_9th\_Street\_NE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 632\_9th\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 632\_9th\_Street\_NE\_rear\_looking\_E.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 632\_9th\_Street\_NE\_rear\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------



Bibliographic Notes:

--

## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0839**

## BASICS DATA

ID Number: **0913-0839** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>634</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 634 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0839</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen rowhouses constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 19)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Canted Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete foundation with a coursed, rock-faced stone veneer, the façade (east elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of rubber shingles with a metal cornice of scroll moldings and decorative modillions. An interior brick chimney pierces the roof. Projecting from the façade is a full-height canted bay. Extending higher than the main roof line, the projecting bay features one-light fixed wood clerestory windows and overhanging eaves replete with scrolled moldings. Atop the projecting bay is a pyramidal roof of rubber shingles adorned with a small metal globe. A molded concrete sill course extends across the first-story in harmony with a molded metal architrave which extends below the second-story openings. A single-leaf paneled metal door with lights pierces the foundation of the façade. The southernmost bay of the first story holds double-leaf wood-frame glass doors with a one-light transom. A three-course, rowlock brick segmental arch tops the transom. Window openings on the façade hold 1/1, double-hung, wood-sash. The foundation of the bay is pierced by one-light wood windows (possibly fixed). A three-course, rowlock brick segmental arch highlights all first story windows. The rear (west) elevation is fenestrated with 1/1, double-hung, wood-sash windows, which have two-course, rowlock brick sills.

A two-story ell extends from the southernmost bay of the rear elevation and is original. The ell is constructed of seven-course, American-bond brick and is set on a solid foundation. A sloping roof caps the ell. An interior brick chimney rises from the north (side) elevation of the ell. Visible fenestration consists of 1/1, double-hung, wood-sash windows and a single-leaf door with a one-light wood transom. The windows have wood sills and all openings are topped by a two-course, rowlock brick segmental arch. Wood-frame steps provide access to the rear entrance.

Site Notes:

**March 2010:** This two-story rowhouse is located on the west side of 9th Street, N.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 632 and 636 9th Street, N.E. The front yard is encircled by a metal bow and picket fence. The rear yard is edged by wood fencing. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Bay Roof</b>	<b>Rubberized</b>		<b>Shingled</b>	
<b>Mansard (False)</b>	<b>Rubberized</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source



<b>Facade</b>	<b>Brick</b>	<b>Stretcher Bond</b>
Structure Component	Material	Feature
<b>Foundation</b>	<b>Concrete</b>	
<b>Walls</b>	<b>Brick</b>	

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>1-light</b>	<b>Wood</b>
<b>Clerestory</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1-light</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Metal/Glas</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Wood/Glass</b>

Notable Interior Plan(s) \_\_\_\_\_ Notable Interior Feature(s) \_\_\_\_\_

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s) _____
Subdivision: _____	
Ward/ANC: _____	
Zoning: _____	Designation Event(s) _____
Contributing: _____	
Survey(s) _____	Level(s) of Investigation _____
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0913\**  
 File: **634\_9th\_Street\_NE\_facade\_looking\_NW.JPG**  
 Date:: Photog:  
 Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 634\_9th\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 634\_9th\_Street\_NE\_rear\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

#### MISCELLANEOUS NOTES DATA

Notes:

#### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

#### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

#### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0838**

## BASICS DATA

ID Number: **0913-0838** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>636</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 636 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0838</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen rowhouses constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Row (1 of 19)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Row Building/Rectangular Bay**  
 Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete foundation with a coursed, rock-faced stone veneer, the façade (east elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of slate shingles with a metal cornice of scroll moldings and decorative modillions. An interior brick chimney pierces the roof. Projecting from the façade is a full-height bay capped by a front-gabled roof. The projecting bay features the same cornice found on the main block to include raking concrete molding and molded corner pendants. The façade includes a molded concrete sill course extending across the first-story and a molded metal architrave below the second-story openings. Window openings hold single and paired 1/1, double-hung, wood-sash and one-light vinyl awning windows. A wide, pressed metal lintel extends above the second-story openings of the projecting bay. The main entry is composed of a vestibule comprised of an outer double-leaf, wood-frame glass door with one-light transom. The inner door was not visible from the public right-of-way. The secondary door opening is located below and holds a single-leaf paneled wood door.

A two-story, two-bay ell is located on the rear (west) elevation of the main block. This brick structure has seven-course, American-bond brick coursing and is capped by a sloping roof. Fenestration consists of a 1/1, double-hung, wood-sash windows and a single-leaf wood door with lights and a one-light transom. All openings are topped by two-course, rowlock brick segmental arches. Wood-frame steps provide access to the rear entrance.

Site Notes:

**March 2010:** This two-story rowhouse is located on the west side of 9th Street, N.E. and is set back approximately fifteen feet from the brick sidewalk. The south (side) elevation of the dwelling is adjacent to 634 9th Street, N.E. The landscaped front yard features a small tree and a bed of English ivy. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is enclosed with wood fencing. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Bay Roof</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	



Structure Component	Material	Feature	Source
<b>Foundation</b>	<b>Concrete</b>		
<b>Walls</b>	<b>Brick</b>		
Materials Notes:			

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Awning</b>	<b>1-light</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Wood</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Wood/Glass</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**  
File: **636\_9th\_Street\_NE\_facade\_looking\_NW.JPG**  
Date:: Photog:  
Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 636\_9th\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 636\_9th\_Street\_NE\_rear\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

#### MISCELLANEOUS NOTES DATA

Notes:

#### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

#### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

#### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0837**

## BASICS DATA

ID Number: **0913-0837** Year Built: **1881** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>640</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Single Dwelling, 640 9th Street, N.E.</b>	<b>Common</b>
--	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0837</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1881</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Rear Addition</b>	<b>c. 1970</b>	<b>Site Visit/Map</b>			
----------------------	----------------	-----------------------	--	--	--

<b>Orig Construction</b>	<b>1881</b>	<b>Permit</b>			<b>1120 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Temple (Mary J.) et al.</b>
--------------------------	--------------	--------------------------------

<b>Price, W.</b>	<b>Builder</b>	<b>Price, W.</b>
------------------	----------------	------------------

Construction Notes:

One of eight dwellings constructed from the same permit (#0690) and one of two constructed on 9th Street, N.E.

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Attached (1 side)**  
 Relate to Street: **Front Yard w/ Setback**  
 Massing: **Vertical Box/flat front**  
 Footprint: **L Shape Add**

Cross Reference Notes:

Number Stories: **2**  
 Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

**Vernacular**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1881 by W. Price, this two-story, two-bay vernacular single-family dwelling was influenced by the Italianate style. The dwelling was one of eight similar dwellings constructed by Price from the same permit (#0690). The dwelling is constructed of seven-course, American-bond brick and is set on a solid brick foundation. The south (side) elevation of the dwelling is parged. A sloping roof caps the dwelling and is complemented by cornice composed of a dogtooth stringcourse, brick corbels, and a checkerboard brick stringcourse. An exterior-side chimney rises from the south elevation and is parged. The southernmost bay of the façade holds a single-leaf wood-frame glass door and a stained glass transom. A soldier brick segmental arch hood surmounts the transom. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows and have rowlock brick sills and soldier brick segmental arched hoods. The rear (west) elevation is parged and is pierced by a large opening that contains glass blocks. A one-story porch that was noted on the 1904, 1928, and 1960 Sanborn maps has been removed from the façade.

**A one-story addition extends from the southernmost bay of the rear elevation and was constructed c. 1970. The wood-frame addition is clad with Hardiplank siding and is set on a solid foundation. A shed roof caps the addition.**

Site Notes:

**March 2010:** This two-story dwelling is located on the west side of 9th Street, N.E. and is set back approximately forty feet from the brick sidewalk. The north (side) elevation of the dwelling is adjacent to 642 9th Street, N.E. The front yard is laid with brick and is obscured from the public right-of-way by a parged wall that is topped by a metal picket fence. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>			
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			



Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Full Glass</b>	<b>Wood/Glass</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b> <b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 640\_9th\_Street\_NE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 640\_9th\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 640\_9th\_Street\_NE\_rear\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:



---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/31/1881	0690	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0174**

## BASICS DATA

ID Number: **0913-0174** Year Built: **1881** Data Source: **Permit**

Number Extended Street Quad Type of Address

**642** **9th Street** **NE Current**

Name(s) Type of Name

**Single Dwelling, 642 9th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0174** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1881** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1881** **Permit** **1120 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Price, W.**

**Orig Construction** **Owner** **Temple (Mary J.) et al.**

Construction Notes:

**One of nine buildings constructed from the same permit (#0690) and one of two constructed on 9th Street, N.E.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Front Yard w/ Setback**

Massing: **Vertical Box/flat front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

**March 2010:** Constructed in 1881 by W. Price, this two-story, two-bay vernacular single-family dwelling was influenced by the Italianate style. The dwelling was one of eight similar dwellings constructed by Price from the same permit (#0690). The dwelling is constructed of seven-course, American-bond brick and is set on a solid brick foundation. A sloping roof caps the dwelling and is complemented by cornice composed of a dogtooth stringcourse, brick corbels, and a checkerboard brick stringcourse. The northernmost bay of the façade holds a single-leaf paneled wood door and a one-light transom. A soldier brick segmental arched hood surmounts the transom. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows and have wood sills and soldier brick segmental arched hoods. The rear (west) elevation is clad with T-111 siding and is pierced by large openings that triple one-light casement windows. A one-story porch that was noted on the 1904, 1928, and 1960 Sanborn maps has been removed from the facade.

Site Notes:

**March 2010:** This two-story single-family dwelling is located on the west side of 9th Street, N.E. and is set back approximately forty feet from the brick sidewalk. The dwelling is adjacent to 640 and 644 9th Street, N.E. The grassy front yard is edged along its southern boundary by a wood fence. A stone walkway leads from the primary entrance and ends at the sidewalk. The rear yard is enclosed with wood fencing.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>DbI-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:



**PHOTOS - DIGITIZED**

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 642\_9th\_Street\_NE\_facade\_looking\_NW.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 642\_9th\_Street\_NE\_facade\_looking\_SW.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 642\_9th\_Street\_NE\_rear\_looking\_SE.JPG

Date:: Photog:

Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

12/31/1881	0690	Build	
------------	------	-------	--

Permit Notes:



## BIBLIOGRAPHIC DATA

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

## SIGNIFICANCE DATA

---

Study Unit

---

Code	Criteria
------	----------

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0173**

## BASICS DATA

ID Number: **0913-0173** Year Built: **1906** Data Source: **Permit**

Number Extended Street Quad Type of Address

**644** **9th Street** **NE Current**

Name(s) Type of Name

**Single Dwelling, 644 9th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0173** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1906** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1906** **Permit** **3000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Atkinson, Frederick G.**

**Orig Construction** **Builder** **Atkinson, Frederick G.**

**Orig Construction** **Owner** **Atkinson, Susanna A.**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box/front porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **36**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1906 by Frederick G. Atkinson, this two-story, two-bay Queen Anne-style single-family dwelling was constructed from permit #2246. The dwelling is constructed of brick and is set on a solid concrete foundation; both are faced on the façade by pressed stretcher-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof with a projecting false pyramidal roof. Both are covered with slate shingles. A metal finial tops the false pyramidal roof, which is pierced by a shed dormer. The dormer is fenestrated with rectangular vents. A projecting cornice finishes the roof. An interior-side brick chimney rises from the south (side) elevation of the dwelling and has a parged corbeled cap. A single-leaf paneled wood door pierces the foundation. The southernmost bay of the first story holds a single-leaf wood-frame glass door with a one-light transom. The northernmost opening holds paired 1/1, double-hung, vinyl-sash windows. The second story openings contain 1/1, double-hung, vinyl-sash windows. All windows have concrete sills and lintels. A one-story, full-width porch spans the façade and is set on a brick pier foundation. The flat roof has overhanging eaves and is supported by brick posts. Turned wood balusters encircle the porch, which is accessed via steps in the southernmost end bay. The rear (west) elevation is pierced by 1/1, double-hung, vinyl-sash windows, which have two-course, rowlock brick segmental arches.

A two-story ell extends from the northernmost bay of the rear elevation and is original. The ell is constructed of American-bond brick and is set on a solid foundation. A sloping roof caps the ell and is pierced by an interior-side brick chimney on the south elevation. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf door. All openings have two-course, rowlock brick segmental arches and the windows also have wood sills. A one-story deck projects from the rear elevation and is highlighted by turned wood balusters.

Site Notes:

**March 2010:** This two-story single-family dwelling is located on the west side of 9th Street, N.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 642 and 646 9th Street, N.E. The front yard is landscaped with mature shrubs and is encircled by a metal bow and picket fence. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Bay Roof</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Pressed Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>1 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Full Glass</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)



Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **644\_9th\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **644\_9th\_Street\_NE\_facade\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **644\_9th\_Street\_NE\_rear\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Tuesday, June 25, 2013

ID\_Number: 0913-0173 Page 3



Notes:

--

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

03/05/1906	2246	Build	
------------	------	-------	--

Permit Notes:

--

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

--

### SIGNIFICANCE DATA

Study Unit

--

Code	Criteria
------	----------

--	--

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0836**

## BASICS DATA

ID Number: **0913-0836** Year Built: **1986** Data Source: **Permit**

Number	Extended	Street	Quad Type	Address
--------	----------	--------	-----------	---------

<b>646</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Single Dwelling, 646 9th Street, N.E.</b>	<b>Common</b>
--	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0836</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen dwellings constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached**  
Relate to Street: **Face on Setback Line**  
Massing: **Vertical Box/rectang bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete foundation with a coursed, rock-faced stone veneer, the façade (east elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of slate shingles with a metal cornice of scroll moldings and decorative modillions. Projecting from the façade is a full-height bay capped by a front-gabled roof. The projecting bay features the same cornice found on the main block to include raking concrete molding and molded corner pendants. The façade includes a molded concrete sill course extending across the first-story and a molded metal architrave below the second-story openings. Window openings hold single and paired 9/9, double-hung, wood-sash, paired 1/1, double-hung, vinyl-sash, paired one-light vinyl sliding windows, and one-light vinyl casement windows with one-light transoms. A wide, pressed metal lintel extends above the second-story openings of the projecting bay. The main entry is composed of a vestibule comprised of an outer double-leaf, wood-frame glass doors with a one-light transom. The inner door was not visible from the public right-of-way. The secondary door opening is located below and holds a single-leaf paneled wood door with lights.

A two-story, two-bay ell is located on the rear (west) elevation of the main block. The ell is constructed of brick and is set on a solid foundation. The first story of the rear elevation is parged. Fenestration consists of a 1/1, double-hung, vinyl-sash window, a 9/9, double-hung, wood-sash window and a single-leaf door with a one-light transom.

Site Notes:

**March 2010:** This two-story dwelling is located on the west side of 9th Street, N.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 644 and 648 9th Street, N.E. The front yard is landscaped with small shrubs and is encircled by a metal fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source



Foundation                      Concrete  
Walls                              Brick

Materials Notes:

--

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	9/9	Wood
Bay Windows	Rectangular	Casement	1-light	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	9/9 Double	Wood
Bay Windows	Rectangular	Sliding	1-light	Vinyl

Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Double	Full Glass	Wood/Glass

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

--

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b> <b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path:   **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**  
File:   **646\_9th\_Street\_NE\_facade\_looking\_NW.JPG**  
Date::                      Photog:  
Code::                      R:                      Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 646\_9th\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 646\_9th\_Street\_NE\_rear\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:



#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

#### MISCELLANEOUS NOTES DATA

Notes:

#### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

#### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

#### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0835**

## BASICS DATA

ID Number: **0913-0835** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>648</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 648 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0835</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2500 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of ten rowhouses constructed from the same permit (#0985).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 10)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Canted Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **48**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897, this two-story, two-bay single-family dwelling was one of 10 similar dwellings constructed by Melton & Watts from the same permit (#0985). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete foundation with a coursed, rock-faced stone veneer, the façade (east elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of rubber shingles with a metal cornice of scroll moldings and decorative modillions. An interior brick chimney pierces the roof. Projecting from the façade is a full-height canted bay. Extending higher than the main roof line, the projecting bay features one-light fixed wood clerestory windows and overhanging eaves replete with egg-and-dart and fleur-de-lis molding. Atop the projecting bay is a pyramidal roof of slate shingles adorned with a small metal finial. A molded concrete sill course extends across the first-story in harmony with a molded metal architrave which extends below the second-story openings. A single-leaf paneled door pierces the foundation of the façade. The southernmost bay of the first story holds double-leaf wood-frame multi-light doors with a one-light transom. Bead molding divides the door and transom. A three-course, rowlock brick segmental arch tops the transom. Window openings on the façade hold 1/1, double-hung, vinyl-sash. The foundation of the bay is pierced by one-light wood windows (possibly fixed). A three-course, rowlock brick segmental arch highlights all first story windows. The rear (west) elevation is fenestrated with a single-leaf paneled door and 1/1, double-hung, vinyl-sash windows, which have metal-clad sills.

A two-story ell extends from the southernmost bay of the rear elevation and is original. The ell is constructed of American-bond brick and is set on a solid foundation. A sloping roof caps the ell. An interior-side brick chimney rises from the south (side) elevation of the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows. The windows have metal-clad sills and all openings are topped by a two-course, rowlock brick segmental arch. A wood-frame pergola extends from the rear elevation of the ell.

Site Notes:

**March 2010:** This two-story rowhouse is located on the west side of 9th Street, N.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 646 and 650 9th Street, N.E. The front yard is landscaped with mature shrubs and is bounded by a low, concrete curb. A stone walkway leads from the primary entrance of the dwelling and ends at the sidewalk. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Rubberized		Shingled	
Mansard (False)	Rubberized		Shingled	
Sloped	Not Visible		Not Visible	



Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>1-light</b>	<b>Wood</b>
<b>Clerestory</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1-light</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unknown</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>		<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**  
**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**  
File: **648\_9th\_Street\_NE\_facade\_looking\_NW.JPG**  
Date:: Photog:  
Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 648\_9th\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 648\_9th\_Street\_NE\_rear\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

#### MISCELLANEOUS NOTES DATA

Notes:

#### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1897	0985	Build	

Permit Notes:

#### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

#### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0834**

## BASICS DATA

ID Number: **0913-0834** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>650</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 650 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0834</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2500 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of ten dwellings constructed from the same permit (#0985).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 10)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Rectangular Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **48**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897, this two-story, two-bay single-family dwelling was one of 10 similar dwellings constructed by Melton & Watts from the same permit (#0985). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete foundation with a rock-faced stone veneer, the façade (east elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of slate shingles with a metal cornice of scroll moldings and decorative modillions. Projecting from the façade is a full-height bay capped by a front-gabled roof of slate shingles. The projecting bay features the same cornice found on the main block, raking concrete molding, and molded concrete corner pendants. The façade includes a molded concrete sill course extending across the first-story which is offset by a molded metal architrave below the second-story openings. Single and paired window openings hold 1/1, double-hung, vinyl-sash on the facade. The foundation of the bay is pierced by paired one-light vinyl sliding windows. The first-story window openings have three-course, rowlock brick segmental arches. The second-story window opening on the main block has a rowlock brick segmental arch. A wide, pressed metal lintel extends above the second-story openings of the projecting bay. The main entry is composed of double-leaf multi-light wood doors, a one-light transom, and a three-course, rowlock brick segmental arch. Bead molding separates the doors and transom. The secondary door opening is located below and holds a single-leaf wood door. The rear (west) elevation is pierced by 1/1, double-hung, vinyl-sash windows, which are topped by two-course, rowlock brick segmental arches.

The two-story, two-bay rear ell has five-course, American-bond brick coursing and is capped by a sloping roof. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows with rowlock brick sills and two-course, rowlock brick segmental arches. A single-leaf multi-light wood door with a one-light transom is located on the west (rear) elevation of the ell. A two-course, rowlock brick segmental arch tops the transom.

Site Notes:

**March 2010:** This two-story rowhouse is located on the west side of 9th Street, N.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 648 and 652 9th Street, N.E. The landscaped front yard features mature shrubs and is encircled by a metal bow and picket fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is edged by wood fencing. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Bay Roof</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	



Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Sliding</b>	<b>1-light</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>		<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**  
**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**  
File: **650\_9th\_Street\_NE\_facade\_looking\_NW.JPG**  
Date:: Photog:  
Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 650\_9th\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 650\_9th\_Street\_NE\_rear\_looking\_E.JPG  
Date:: Photog:  
Code:: R: Fr:



#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

#### MISCELLANEOUS NOTES DATA

Notes:

#### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1897	0985	Build	

Permit Notes:

#### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

#### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0833**

## BASICS DATA

ID Number: **0913-0833** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>652</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 652 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0833</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2500 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of ten dwellings constructed from the same permit (#0985).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Row (1 of 10)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Row Building/Canted Bay**  
 Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **48**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897, this two-story, two-bay single-family dwelling was one of 10 similar dwellings constructed by Melton & Watts from the same permit (#0985). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete foundation with a coursed, rock-faced stone veneer, the façade (east elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of slate shingles with a metal cornice of scroll moldings and decorative modillions. An interior brick chimney pierces the roof. Projecting from the façade is a full-height canted bay. Extending higher than the main roof line, the projecting bay features one-light fixed wood clerestory windows and overhanging eaves replete with egg-and-dart and fleur-de-lis molding. Atop the projecting bay is a pyramidal roof of slate shingles adorned with a small metal finial. A molded concrete sill course extends across the first-story in harmony with a molded metal architrave which extends below the second-story openings. A single-leaf wood-frame glass door pierces the foundation of the façade. The southernmost bay of the first story holds a single-leaf paneled wood door with a one-light transom. Bead molding divides the door and transom. A three-course, rowlock brick segmental arch tops the transom. Window openings on the façade hold 1/1, double-hung, vinyl-sash. A three-course, rowlock brick segmental arch highlights all first story windows.

A two-story ell extends from the southernmost bay of the rear elevation and is original. The ell is constructed of American-bond brick and is set on a solid foundation. A sloping roof caps the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf multi-light wood door with a one-light transom. The windows have concrete sills and all openings are topped by a two-course, rowlock brick segmental arch.

Site Notes:

**March 2010:** This two-story rowhouse is located on the west side of 9th Street, N.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 650 and 654 9th Street, N.E. The front yard is bounded by a metal hairpin and picket fence. A concrete walkway leads from the primary entrance and ends at the sidewalk. The rear yard is edged by wood fencing. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Bay Roof</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	



Structure Component	Material	Feature	Source
<b>Foundation</b>	<b>Concrete</b>		
<b>Walls</b>	<b>Brick</b>		

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Clerestory</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1-light</b>	<b>Wood</b>

Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Full Glass</b>	<b>Wood/Glass</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**  
**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **652\_9th\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 652\_9th\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 652\_9th\_Street\_NE\_rear\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

#### MISCELLANEOUS NOTES DATA

Notes:

#### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1897	0985	Build	

Permit Notes:

#### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

#### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0832**

## BASICS DATA

ID Number: **0913-0832** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>654</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 654 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0832</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Multi-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Original</b>
-----------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Single-Family)</b>					<b>Current</b>
------------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2500 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of ten rowhouses constructed from the same permit (#0985).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 10)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Bldg (Rect. Bay)**  
Footprint: **L-Shaped**

Number Stories: **2 plus basement**  
Bays Wide: **2**

Height: **17**  
Width: **17**  
Depth/Length: **48**

SqFt:  
Volume:  
Lot Width  
Lot Depth/Length:  
Lot SqFt:  
Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897, this two-story, two-bay single-family dwelling was one of 10 similar dwellings constructed by Melton & Watts from the same permit (#0985). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete foundation with a rock-faced stone veneer, the façade (east elevation) of this brick structure has Roman brick, stretcher-bond coursing. A sloped roof is obscured by a false mansard of slate shingles with a metal cornice of scroll moldings and decorative modillions. Projecting from the façade is a full-height bay capped by a front-gabled roof of slate shingles. The projecting bay features the same cornice found on the main block, raking concrete molding, and molded concrete corner pendants. The façade includes a molded concrete sill course extending across the first-story which is offset by a molded metal architrave below the second-story openings. Single and paired window openings hold 1/1, double-hung, vinyl-sash on the facade. The foundation of the bay is pierced by paired one-light vinyl sliding windows. The first-story window openings have three-course, rowlock brick segmental arches. The second-story window opening on the main block has a rowlock brick segmental arch. A wide, pressed metal lintel extends above the second-story openings of the projecting bay. The main entry is composed of a single-leaf paneled wood door, a one-light transom, and a three-course, rowlock brick segmental arch. Bead molding separates the doors and transom. The secondary door opening is located below and holds a single-leaf wood door.

The two-story, two-bay rear ell has five-course, American-bond brick coursing and is capped by a sloping roof. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows with rowlock brick sills and two-course, rowlock brick segmental arches. A single-leaf paneled wood door with lights and a blind transom is located on the west (rear) elevation of the ell. A two-course, rowlock brick segmental arch tops the blind transom.

Site Notes:

**March 2010:** This two-story rowhouse is located on the west side of 9th Street, N.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 652 and 656 9th Street, N.E. The front yard is landscaped with mature shrubs and is bounded by a parged wall and a metal picket fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is edged by wood fencing. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Slate		Shingled	
Mansard (False)	Slate		Shingled	
Sloped	Not Visible		Not Visible	



Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Roman Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Sliding</b>	<b>1-light</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**  
**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**  
File: **654\_9th\_Street\_NE\_facade\_looking\_NW.JPG**  
Date:: Photog:  
Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 654\_9th\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 654\_9th\_Street\_NE\_rear\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

#### MISCELLANEOUS NOTES DATA

Notes:

#### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1897	0985	Build	

Permit Notes:

#### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

#### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0831**

## BASICS DATA

ID Number: **0913-0831** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>656</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
<b>827</b>		<b>G Street</b>	<b>NE</b>	<b>Alternate</b>

Name(s)	Type of Name
<b>Rowhouse, 656 9th Street, N.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>0913/0831</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Original</b>
<b>Residential (Multi-Family)</b>					<b>Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2500 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>

Construction Notes:

**One of ten rowhouses constructed from the same permit (#0985).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row Corner (1 of 10)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Hexagonal Bay**  
Footprint: **Rectangular (w/ side bays)**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **48**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897, this two-story, two-bay dwelling & store was one of 10 similar buildings constructed by Melton & Watts from the same permit (#0985). Following the design of architect B. Stanley Simmons, this Queen Anne-style building has a rectangular form with a two-story rear ell. Set on a solid concrete foundation with a rock-faced stone veneer, the façade (east elevation) of this brick structure has Roman brick, stretcher-bond coursing. A beltcourse encircles the dwelling between the first and second story window openings and features dentil molding. The roofing type of the building was not discernible from the public right-of-way. A molded metal cornice complements the roof. Projecting from the northeast corner of the façade is a full-height bay capped by an octagonal roof of slate shingles. The projecting bay features the same cornice found on the main block. The southernmost bay of the first story holds double-leaf multi-light wood doors with a one-light transom. The second story opening holds a 1/1, double-hung, vinyl-sash window. A pediment tops the window opening and is flanked by molded concrete pendants. The bay is fenestrated with 1/1, double-hung, vinyl-sash windows. All window openings on the façade have rowlock brick sills and the first story openings are topped by three-course, rowlock brick segmental arches. The north (side) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows and a single-leaf paneled wood door with leaded lights and a one-light sidelight. A blind segmental transom tops the door opening. All windows have rowlock brick sills. The first story openings are topped by three-course, rowlock brick segmental openings and the second story windows are topped by two-course, rowlock brick segmental openings. A false gable rises from the second story window openings of the easternmost bays and features a molded concrete raking cornice and molded concrete corner pendants. A circular vent is sited in the upper gable end. A three-sided rectangular bay projects from the north elevation and has the material treatment of the main block. Fenestration consists of paired 1/1, double-hung, vinyl-sash windows and glass blocks. The rear (west) elevation is fenestrated with double-leaf multi-light doors and 1/1, double-hung, vinyl-sash windows. All windows have rowlock brick sills.

Site Notes:

**March 2010:** This two-story rowhouse is located on the southwest corner of 9th Street, N.E. and G Street, N.E. and is set back approximately fifteen feet from the brick sidewalk. The south (side) elevation of the dwelling is adjacent to 654 9th Street, N.E. The front and side yards are laid with brick and are edged by a brick wall.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Bay Roof</b>	<b>Slate</b>		<b>Shingled</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Roman Brick</b>		<b>Stretcher Bond</b>	



Structure Component	Material	Feature	Source
<b>Foundation</b>	<b>Concrete</b>		
<b>Walls</b>	<b>Brick</b>		
Materials Notes:			

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>		<b>Wood/Glass</b>
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**  
File: **656\_9th\_Street\_NE\_facade\_looking\_NW.JPG**  
Date:: Photog:  
Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 656\_9th\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 656\_9th\_Street\_NE\_north\_elevation\_looking\_S.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 656\_9th\_Street\_NE\_north\_elevation\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 656\_9th\_Street\_NE\_rear\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

#### MISCELLANEOUS NOTES DATA

Notes:

--



## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1897	0985	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0829**

## BASICS DATA

ID Number: **0913-0829** Year Built: **1888** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>813</b>		<b>G Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-----------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Duplex, 813 G Street, N.E.</b>	<b>Common</b>
-----------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0829</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1888</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Rear Addition</b>	<b>c. 1970</b>	<b>Site Visit/Map</b>			
----------------------	----------------	-----------------------	--	--	--

<b>Orig Construction</b>	<b>1888</b>	<b>Permit</b>			<b>1000 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Fisher, A.J.</b>
--------------------------	----------------	---------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Temple, Edward</b>
--------------------------	--------------	-----------------------

Construction Notes:

**Constructed from the same permit as 815 G Street, N.E. (#0350).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Attached (1 side)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Vertical Box/front porch**  
 Footprint: **L Shape Add**

Cross Reference Notes:

Number Stories: **2**

Bays Wide:

Height:

Outbuilding Type

Contributing Status

Width: **14**

Depth/Length: **26**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1888 by A.J. Fisher, this two-story story duplex was influenced by the Queen Anne style and was constructed with 815 G Street, N.E. from the same permit (#0350). The duplex is constructed of brick and is set on a solid brick foundation; the façade (north elevation) and is constructed of American-bond brick. Paired brick string courses span the façade and bisect the second story opening. A sloping roof caps the dwelling and is fronted along the façade by a gabled parapet. The parapet is complemented by a corbeled brick cornice. An interior-brick chimney rises from the northeast corner of the dwelling and has a corbeled brick cap. The façade is fenestrated with a 35-light fixed wood window and paired 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins. A two-course, rowlock brick segmental arch, topped by a soldier brick segmental arch complements the second story opening. The west (side) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins and a single-leaf paneled wood door with lights. All openings are surmounted by a soldier brick segmental arch and the windows have metal-clad sills and are flanked by inoperable louvered shutters. A one-story, wraparound porch extends from the façade to the west elevation and is set on a solid brick foundation. The half-hipped roof of the porch is covered with standing-seam metal and is supported by brick posts set on brick piers. Decorative jig-sawn work highlights the porch. The rear (south) elevation is pierced by a 1/1, double-hung, vinyl-sash window with false 6/6 vinyl muntins and a two-course, rowlock brick sill.

A two-story ell extends from the easternmost bay of the rear elevation and is original. The ell is constructed of American-bond brick and is capped by a sloping roof. Visible fenestration consists of a 1/1, double-hung, vinyl-sash window with false 6/6 vinyl muntins, a one-light fixed window, and a single-leaf paneled wood door with lights. Most openings are topped by a two-course, rowlock brick segmental arch.

A one-story addition is located in the ell and was constructed c. 1970. The wood-frame addition is clad with T-111 siding and is set on a solid foundation. A shed roof, covered with asphalt shingles, caps the addition. A single-leaf metal door pierces the rear elevation.

Site Notes:

**March 2010:** This two-story duplex is located on the northwest corner of G Street, N.E. and Pickford Place, N.E. and is set back approximately ten feet from the brick sidewalk. The front yard is landscaped with mature shrubs and is encircled by a low brick retaining wall. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is edged with wood fencing.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	



Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>Multi-lite</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **813\_G\_Street\_NE\_facade\_looking\_SE.JPG**

Date:: Photog:

Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 813\_G\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 813\_G\_Street\_NE\_rear\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 813\_G\_Street\_NE\_west\_elevation\_looking\_NE  
.JPG  
Date:: Photog:  
Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
08/22/1888	0350	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------



Bibliographic Notes:

--

## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0830**

## BASICS DATA

ID Number: **0913-0830** Year Built: **1888** Data Source: **Permit**

Number Extended Street Quad Type of Address

**815** **G Street** **NE** **Current**

Name(s) Type of Name

**Duplex, 815 G Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0830** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1888** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1888** **Permit** **1000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Fisher, A.J.**

**Orig Construction** **Owner** **Temple, Edward**

Construction Notes:

**Constructed with 813 G Street, N.E. from the same permit (#0350).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Setback Line**

Massing: **Vertical Box**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide:

Height:

Width: **14**

Depth/Length: **26**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1888 by A.J. Fisher, this two-story duplex was influenced by the Queen Anne style and was constructed with 813 G Street, N.E. from the same permit (#0350). The duplex is constructed of brick and is set on a solid brick foundation; the façade (north elevation) is constructed of American-bond brick. Paired brick string courses span the façade and bisect the second story opening. A sloping roof caps the dwelling and is fronted along the façade by a gabled parapet. The parapet is complemented by a corbeled brick cornice. An interior-brick chimney rises from the northwest corner of the dwelling and has a corbeled brick cap. The façade is fenestrated with a 35-light fixed wood window and paired 6/6, double-hung, wood-sash windows. A gauged brick segmental arch complements the second story opening. The east (side) elevation is fenestrated with 6/6, double-hung, wood-sash windows and a single-leaf door. All openings are surmounted by a soldier brick segmental arch and the windows have rowlock brick sills. A one-story, wraparound porch has been removed from the façade and east elevations. The rear (south) elevation is pierced by one-light vinyl casement windows that rise the full height of the dwelling.

A two-story ell extends from the westernmost bay of the rear elevation and is original. The ell is constructed of American-bond brick and is capped by a sloping roof. Visible fenestration consists of a 4/4, double-hung, wood-sash window and a fixed multi-light window. These openings have been altered, though the soldier brick segmental arches still remain.

Site Notes:

**March 2010:** This two-story duplex is located on the south side of G Street, N.E. and is set back approximately ten feet from the brick sidewalk. The west (side) elevation of the dwelling is adjacent to 813 G Street, N.E. The front yard is landscaped with mature shrubs and is encircled by a low, brick retaining wall that is topped with metal milled point fencing. The rear yard is enclosed with wood fencing. An alley is located south of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

--

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>6/6 Double</b>	<b>Wood</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>Multi-lite</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

--

## PLAN/SURVEY/DESIGNATION DATA



Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\

File: 815\_G\_Street\_NE\_facade\_looking\_SW.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\

File: 815\_G\_Street\_NE\_north\_elevation.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\

File: 815\_G\_Street\_NE\_south\_elevation.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Tuesday, June 25, 2013

ID\_Number: 0913-0830 Page 3



Permit Issue Date	Number	Type	Remarks
08/22/1888	0350	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0144**

## BASICS DATA

ID Number: **0913-0144** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>810</b>		<b>F Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-----------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Duplex, 810 F Street, N.E.</b>	<b>Common</b>
-----------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0144</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Multi-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Original</b>
-----------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Single-Family)</b>					<b>Current</b>
------------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2000 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Weller, Frances R.</b>
--------------------------	------------------	---------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of six dwellings constructed from the same permit (#0983).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached (1 side)**  
Relate to Street: **Face on Setback Line**  
Massing: **Vertical Box/flat front**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **43**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by Melton & Watts, this two-story, three-bay Classical Revival-style single-family dwelling was constructed with six similar buildings from the same permit (#0983). Only four are still extant. The dwelling is constructed of American-bond brick and is set on a solid brick and stone foundation; the façade (south elevation) is faced with stretcher-bond brick. A sloping roof caps the dwelling and is highlighted by a prominent projecting molded cornice with dentil molding. A parapet rises from the façade and features wreath molding. A decorative rectangular panel is located above the second story openings. The easternmost bay of the façade holds a single-leaf paneled wood door with lights and a one-light semi-circular fanlight. A three-course, rowlock brick segmental arch with a keystone and imposts surmounts the fanlight. Poured concrete steps with metal hand rails provide access to the primary entrance. The first and second story window openings hold 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins, with the first story windows also having transoms. The foundation is pierced by one-light wood windows (possibly fixed). All openings have concrete sills and lintels. The west elevation is fenestrated with 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins and paired one-light sliding vinyl windows. The first story windows have rowlock brick sills and the second story openings have header brick sills; all are topped by two-course, rowlock brick segmental arches. The rear elevation is fenestrated with 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins.

A wood-frame deck, constructed c. 2005 is located on the roof of the building.

Site Notes:

**March 2010:** This two-story single-family dwelling is located on the north side of F Street, N.E. and is set back approximately thirty feet from the brick sidewalk. The east (side) elevation of the dwelling is adjacent to 812 F Street, N.E. The landscaped front yard features mature shrubs and is encircled by a metal milled point fence. A stone walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is bounded by wood fencing. An alley is located north of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick &amp; Stone</b>			
<b>Walls</b>	<b>Brick</b>			



Materials Notes:

--

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>1-light</b>	<b>Wood</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Pamels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

--

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 810\_F\_Street\_NE\_facade\_looking\_NE.JPG**  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 810\_F\_Street\_NE\_facade\_looking\_NW.JPG**  
Date:: Photog:  
Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 810\_F\_Street\_NE\_rear\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:



---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/28/1897	0983	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0143**

## BASICS DATA

ID Number: **0913-0143** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>812</b>		<b>F Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-----------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Duplex, 812 F Street, N.E.</b>	<b>Common</b>
-----------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0143</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Multi-Family)</b>					<b>Original</b>
-----------------------------------	--	--	--	--	-----------------

<b>Residential (Single-Family)</b>					<b>Current</b>
------------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2000 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Weller, Frances R.</b>
--------------------------	------------------	---------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**Originally one of six dwellings constructed from the same permit (#0983). Only four are extant.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached (1 side)**  
Relate to Street: **Face on Setback Line**  
Massing: **Vertical Box/flat front**  
Footprint: **Rectangular**

Number Stories: **2 plus basement**  
Bays Wide: **3**

Height:  
Width: **17**  
Depth/Length: **43**

SqFt:  
Volume:  
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by Melton & Watts, this two-story, three-bay Classical Revival-style single-family dwelling was constructed with six similar buildings from the same permit (#0983). Only four are still extant. The dwelling is constructed of American-bond brick and is set on a solid brick and stone foundation; the façade (south elevation) is faced with stretcher-bond brick. A sloping roof caps the dwelling and is highlighted by a prominent projecting molded cornice with dentil molding. A parapet rises from the façade and features wreath molding. A decorative rectangular panel is located above the second story openings. An interior-side chimney rises from the east (side) elevation and is parged. The easternmost bay of the façade holds a single-leaf paneled wood door and a one-light semi-circular fanlight. A three-course, rowlock brick segmental arch with a keystone and imposts surmounts the fanlight. Poured concrete steps provide access to the primary entrance. The first and second story window openings hold 1/1, double-hung, wood-sash. The foundation is pierced by one-light wood windows (possibly fixed). All openings have concrete sills and lintels. The rear elevation is fenestrated with 1/1, double-hung, wood-sash windows, which have rowlock brick sills and two-course, rowlock brick segmental arches. A single-leaf paneled wood door with lights pierces the rear elevation and has a stained glass transom.

Site Notes:

**March 2010:** This two-story single-family dwelling is located on the north side of F Street, N.E. and is set back approximately thirty feet from the brick sidewalk. The west (side) elevation of the dwelling is adjacent to 810 F Street, N.E. The landscaped front yard features mature shrubs and is encircled by a metal bow and picket fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. An alley is located north of the dwelling.

## NOTABLE FEATURES DATA

Component Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick &amp; Stone</b>			
<b>Walls</b>	<b>Brick</b>			



Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
Notable Interior Plan(s)			Notable Interior Feature(s)	

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 812\_F\_Street\_NE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 812\_F\_Street\_NE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 812\_F\_Street\_NE\_rear\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:



---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/28/1897	0983	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/24/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0172**

## BASICS DATA

ID Number: **0913-0172** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**617** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 617 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0172** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (west elevation) is faced with nine-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 619 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior brick chimney pierces the roof and has a corbeled brick cap. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash with false 6/6 vinyl muntins. Concrete sills and soldier brick segmental arches with rowlock brick caps finish each opening. The south (side) elevation is fenestrated with a single-leaf paneled wood door, which features a pedimented surround with fluted pilasters. Additional fenestration consists of 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins and a two-light fixed wood window that is two stories in height. All windows have two-course, rowlock brick segmental arches and sills.

Site Notes:

**March 2010:** This two-story duplex is located on the east side of Pickford Place, N.E. and fronts the concrete sidewalk. The north (side) elevation of the duplex is adjacent to 619 Pickford Place, N.E. The southern side yard is encircled by a wood fence. An alley is located south of the fence and wraps around to the east (rear) elevation of the duplex.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Tuesday, June 25, 2013

ID\_Number: 0913-0172 Page 2



Contributing:

Survey(s)

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

**Permit Research  
Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 617\_Pickford\_Place\_NE\_facade\_looking\_E.JPG

Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 617\_Pickford\_Place\_NE\_facade\_looking\_NE.JPG

Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:



## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/2/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0171**

## BASICS DATA

ID Number: **0913-0171** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**619** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 619 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0171** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Charles R.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

**Vernacular**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (west elevation) is faced with nine-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 617 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior brick chimney pierces the roof and has a corbeled brick cap. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash with false 6/6 vinyl muntins. Rowlock brick sills and soldier brick segmental arches with rowlock brick caps finish each opening. The north (side) elevation is fenestrated with a single-leaf door. Additional fenestration consists of 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins.

Site Notes:

**March 2010:** This two-story duplex is located on the east side of Pickford Place, N.E. and fronts the concrete sidewalk. The south (side) elevation of the duplex is adjacent to 617 Pickford Place, N.E. The northern side yard is encircled by a wood fence. An alley is located east of the building.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

**Tuesday, June 25, 2013**

**ID\_Number: 0913-0171 Page 2**



Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 619\_Pickford\_Place\_NE\_facade\_looking\_E.JP  
G

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 619\_Pickford\_Place\_NE\_facade\_looking\_SE.J  
PG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:



## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/2/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0170**

## BASICS DATA

ID Number: **0913-0170** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**623** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 623 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0170** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

**Vernacular**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (west elevation) is faced with nine-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 625 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior brick chimney pierces the roof and is parged. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Rowlock brick sills and soldier brick segmental arches with rowlock brick caps finish each opening. The south (side) elevation is fenestrated with a single-leaf door. Additional fenestration consists of 1/1, double-hung, vinyl-sash windows. All windows have two-course, rowlock brick segmental arches and sills.

A one-story, two-bay porch extends from the south elevation and is capped by a half-hipped roof. The roof is covered with metal and is supported by wood posts with sawn scroll work. A second story balcony extends from the easternmost bay of the south elevation and is set on posts. Wood steps provide access to this balcony, which is accessed from the interior via a single-leaf door.

Site Notes:

**March 2010:** This two-story duplex is located on the east side of Pickford Place, N.E. and fronts the concrete sidewalk. The north (side) elevation of the duplex is adjacent to 625 Pickford Place, N.E. The southern side yard is encircled by a wood fence. An alley is located east of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbi-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA



Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\

File: 623\_Pickford\_Place\_NE\_facade\_looking\_NE.J  
PG

Date::

Photog:

Code::

R:

Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\

File: 623\_Pickford\_Place\_NE\_facade\_looking\_SE.J  
PG

Date::

Photog:

Code::

R:

Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

--

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------



Bibliographic Notes:

--

## **SIGNIFICANCE DATA**

---

Study Unit

---

Code

Criteria

---

## **DATA PROCESSING EVENTS DATA**

---

Date	Individual	Action
4/2/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0169**

## BASICS DATA

ID Number: **0913-0169** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**625** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 625 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0169** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (west elevation) is faced with nine-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 623 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior brick chimney pierces the roof and has a corbeled brick cap. Multiple brick string courses span the façade. Window openings on the façade hold 6/6, double-hung, wood-sash. Rowlock brick sills and soldier brick segmental arches with rowlock brick caps finish each opening. The north (side) elevation is fenestrated with a single-leaf paneled wood door, flanked by fluted pilasters, in the westernmost bay and a single-leaf wood-frame glass door in the easternmost bay. A one-light fixed window, two-stories in height, pierces the north elevation. Additional fenestration consists of a double-hung, window. Several openings have been infilled with brick.

Site Notes:

**March 2010:** This two-story duplex is located on the east side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The south (side) elevation of the building is adjacent to 623 Pickford Place, N.E. The northern side yard is encircled by a metal chain-link fence. An alley is located east of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>6/6</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood/Glass</b>
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Tuesday, June 25, 2013

ID\_Number: 0913-0169 Page 2



Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 625\_Pickford\_Place\_NE\_facade\_looking\_NE.J  
PG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 625\_Pickford\_Place\_NE\_facade\_looking\_SE.J  
PG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------



Bibliographic Notes:

--

## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/2/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0168**

## BASICS DATA

ID Number: **0913-0168** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**629** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 629 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0168** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

**Vernacular**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (west elevation) is faced with nine-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 631 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior brick chimney pierces the roof and has a corbeled brick cap. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Soldier brick segmental arches with rowlock brick caps finish each opening. The first story windows have concrete sills and the second story windows have metal-clad sills. The south (side) elevation is parged and is fenestrated with a single-leaf wood door with lights and a stained glass transom and a single-leaf paneled metal door. Additional fenestration consists of 1/1, double-hung, vinyl-sash windows, which have concrete sills.

A one-story porch extends from the south elevation of the dwelling and has a flat roof that is supported by brick posts. Overhanging eaves finish the roof.

Site Notes:

**March 2010:** This two-story duplex is located on the east side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The north (side) elevation of the building is adjacent to 631 Pickford Place, N.E. The southern side yard is bounded by a fence. An alley is located east of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Metal</b>
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA



Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\

File: 629\_Pickford\_Place\_NE\_facade\_looking\_NE.J  
PG

Date::

Photog:

Code::

R:

Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\

File: 629\_Pickford\_Place\_NE\_facade\_looking\_SE.J  
PG

Date::

Photog:

Code::

R:

Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

--

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------



Bibliographic Notes:

--

## **SIGNIFICANCE DATA**

---

Study Unit

---

Code

Criteria

---

## **DATA PROCESSING EVENTS DATA**

---

Date	Individual	Action
4/2/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0167**

## BASICS DATA

ID Number: **0913-0167** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**631** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 631 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0167** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

March 2010: Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (west elevation) is faced with nine-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 629 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior brick chimney pierces the roof and has a corbeled brick cap. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Rowlock brick sills and soldier brick segmental arches with rowlock brick caps finish each opening. The north (side) elevation is pierced by a single-leaf multi-light wood door. The westernmost bay holds a single-leaf paneled wood door, which is flanked by fluted pilasters and features a segmental pediment. A one-story, one-bay porch shelters this door and has a shed roof with asphalt shingles. Square wood posts with jigsaw brackets support the roof. Additional fenestration consists 1/1, double-hung, vinyl-sash windows and a two-light fixed wood window that rises two stories in height.

Site Notes:

March 2010: This two-story duplex is located on the east side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The south (side) elevation is adjacent to 629 Pickford Place, N.E. The northern side yard is partially encircled by a wood fence. An alley is located east of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood/Glass</b>
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Tuesday, June 25, 2013

ID\_Number: 0913-0167 Page 2



Ward/ANC:  
Zoning:  
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 631\_Pickford\_Place\_NE\_facade\_looking\_NE.J  
PG

Date:: Photog:

Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 631\_Pickford\_Place\_NE\_facade\_looking\_SE.J  
PG

Date:: Photog:

Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------



Bibliographic Notes:

--

## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/2/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0166**

## BASICS DATA

ID Number: **0913-0166** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**635** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 635 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0166** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

March 2010: Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (west elevation) is faced with nine-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 637 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior brick chimney pierces the roof and has a corbeled brick cap. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Rowlock brick sills and soldier brick segmental arches with rowlock brick caps finish each opening. The south (side) elevation is pierced by a single-leaf paneled wood door. The door is flanked by fluted pilasters, which support a denticulated lintel. Additional fenestration consists double-hung windows and a two-light fixed wood window that rises two stories in height.

Site Notes:

March 2010: This two-story duplex is located on the east side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The north (side) elevation of the dwelling is adjacent to 637 Pickford Place, N.E. The southern side yard is encircled by a wood fence. A concrete walkway leads to the entrance on the south elevation. Planting beds, enclosed with brick retaining walls are located in the side yard. An alley is located east of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Tuesday, June 25, 2013

ID\_Number: 0913-0166 Page 2



Contributing:

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 635\_Pickford\_Place\_NE\_facade\_looking\_NE.J  
PG

Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 635\_Pickford\_Place\_NE\_facade\_looking\_SE.J  
PG

Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:



## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/2/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0165**

## BASICS DATA

ID Number: **0913-0165** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**637** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 637 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0165** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

March 2010: Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (west elevation) is faced with nine-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 635 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior brick chimney pierces the roof. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Concrete sills and soldier brick segmental arches with rowlock brick caps finish each opening. The north (side) elevation is pierced by two single-leaf paneled wood doors, which are topped by blind transoms and two-course, rowlock brick segmental arches. Poured concrete stoops provide access to these stoops. Additional fenestration consists of 1/1 double-hung windows, which have concrete sills and two-course, rowlock brick segmental arches.

Site Notes:

March 2010: This two-story duplex is located on the east side of Pickford Place, N.E. and directly fronts the sidewalk. The south (side) elevation is adjacent to 635 Pickford Place, N.E. The northern side yard is encircled by a milled point metal fence. Concrete walkways lead to the entries on this elevation. An alley is located east of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Tuesday, June 25, 2013

ID\_Number: 0913-0165 Page 2



Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 637\_Pickford\_Place\_NE\_facade\_looking\_NE.J  
PG

Date:: Photog:  
Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 637\_Pickford\_Place\_NE\_facade\_looking\_SE.J  
PG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------



Bibliographic Notes:

--

## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/2/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0164**

## BASICS DATA

ID Number: **0913-0164** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**641** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 641 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0164** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

**Vernacular**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (west elevation) is faced with nine-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 643 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Rowlock brick sills and soldier brick segmental arches with rowlock brick caps finish each opening. Visible fenestration on the south (side) elevation consists of 1/1, double-hung, vinyl-sash windows and a multi-light fixed wood window. All second story windows have two-course, rowlock brick segmental arches and concrete sills.

Site Notes:

**March 2010:** This two-story duplex is located on the east side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The north (side) elevation of the dwelling is adjacent to 643 Pickford Place, N.E. The southern side yard is encircled by a tall, wood fence. An alley is located east of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>DbI-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:



Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 641\_Pickford\_Place\_NE\_facade\_looking\_E.JP  
G

Date:: Photog:  
Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 641\_Pickford\_Place\_NE\_facade\_looking\_NE.J  
PG

Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:



## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/2/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0163**

## BASICS DATA

ID Number: **0913-0163** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**643** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 643 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0163** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

**Vernacular**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (west elevation) is faced with nine-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 641 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Rowlock brick sills and soldier brick segmental arches with rowlock brick caps finish each opening. Visible fenestration on the north (side) elevation consists of 1/1, double-hung, vinyl-sash windows, which have rowlock brick sills and two-course, rowlock brick segmental arches.

A one-story enclosed porch extends from the north elevation of the dwelling and was enclosed c. 1970. The wood-frame enclosed porch is clad with aluminum siding and is set on a solid parged foundation. A half-hipped roof caps the enclosed porch and is covered with asphalt shingles. Fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf paneled vinyl door with lights.

Site Notes:

**March 2010:** This two-story duplex is located on the east side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The south (side) elevation is adjacent to 641 Pickford Place, N.E. The northern side yard is partially encircled by a wood fence. An alley is located east of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Vinyl/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision

**Tuesday, June 25, 2013**

**ID\_Number: 0913-0163 Page 2**



Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0913\

File: 643\_Pickford\_Place\_NE\_facade\_looking\_NE.J  
PG

Date:: Photog:

Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0913\

File: 643\_Pickford\_Place\_NE\_facade\_looking\_SE.J  
PG

Date:: Photog:

Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

07/07/1897	0022	Build	
------------	------	-------	--

Permit Notes:

--

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------



Bibliographic Notes:

--

## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/2/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0162**

## BASICS DATA

ID Number: **0913-0162** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**647** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 647 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0162** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

**Vernacular**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (west elevation) is faced with ten-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 649 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash with 6/6 vinyl muntins. Inoperable paneled vinyl shutters flank each window. First story windows have rowlock brick sills and second story windows have header brick sills; all have soldier brick segmental arches with rowlock brick caps. Visible fenestration on the south (side) elevation consists of 1/1, double-hung, vinyl-sash windows, which have rowlock brick sills and two-course, rowlock brick segmental arches. Door openings also pierce the south elevation.

Site Notes:

**March 2010:** This two-story duplex is located on the east side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The north (side) elevation is adjacent to 649 Pickford Place, N.E. The southern side yard is encircled by a tall wood fence. An alley is located east of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

**Tuesday, June 25, 2013**

**ID\_Number: 0913-0162 Page 2**



Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 647\_Pickford\_Place\_NE\_facade\_looking\_NE.J  
PG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 647\_Pickford\_Place\_NE\_facade\_looking\_SE.J  
PG

Date:: Photog:

Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:



## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/2/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0161**

## BASICS DATA

ID Number: **0913-0161** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**649** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 649 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0161** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

March 2010: Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (west elevation) is faced with ten-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 647 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. Multiple brick string courses span the façade. An interior brick chimney pierces the roof and has a corbeled brick cap. Window openings on the façade hold 6/6, double-hung, wood-sash. First story windows have rowlock brick sills and second story windows have header brick sills; all have soldier brick segmental arches with rowlock brick caps. Visible fenestration on the north (side) elevation consists of a 6/6, double-hung, wood-sash window and a two-light fixed window that rises two stories in height. The westernmost bay holds a single-leaf paneled wood door, which is flanked by fluted pilasters and topped by a wood lintel. The easternmost bay also holds single-leaf paneled wood door. Several window openings have been infilled with brick.

Site Notes:

March 2010: This two-story duplex is located on the east side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The north (side) elevation of the dwelling is adjacent to 647 Pickford Place, N.E. The northern side yard is partially encircled by wood fencing. A brick walkway leads to an entrance on the north elevation. An alley is located east of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>6/6</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision

Tuesday, June 25, 2013

ID\_Number: 0913-0161 Page 2



Subdivision:  
Ward/ANC:  
Zoning:  
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research  
Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 649\_Pickford\_Place\_NE\_facade\_looking\_E.JP  
G

Date:: Photog:  
Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 649\_Pickford\_Place\_NE\_facade\_looking\_SE.J  
PG

Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------



Bibliographic Notes:

--

## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/2/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0800**

## BASICS DATA

ID Number: **0913-0800** Year Built: **1896** Data Source: **Permit**

Number Extended Street Quad Type of Address

**600** **9th Street** **NE Current**

Name(s) Type of Name

**Store, 600 9th Street, N.E.** **Historic**

**Multiple Dwelling, 600 9th Street, N.E.** **Current**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0800** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Commercial Building** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Religious** **1999** **Sanborn M** **Historic**

**Commercial** **1896** **Permit** **1999** **Sanborn M** **Original**

**Residential (Multi-Family)** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1896** **Permit** **4600 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **McGee, Inc.**

**Orig Construction** **Owner** **Pickford, Charles R.**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached end**  
Relate to Street: **Face on Line**  
Massing: **Row Building/Multiple Bays**  
Footprint: **Irregular**

Cross Reference Notes:

Number Stories: **3**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **19**

Depth/Length: **50**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Queen Anne

Exterior & Architectural Notes:

**March 2010:** This three-story store was designed by architect B. Stanley Simmons for owner Charles R. Pickford. This eclectic building, which now serves a multiple dwelling, was erected in 1896 by builder "McGee" (permit #1955). The building is two structural bays wide and sits on a solid brick and concrete foundation. A three-story rectangular bay projects from the south (side) elevation and has the same material treatment as the main block. The building is constructed of brick and is veneered with light-colored Roman bricks. A false mansard roof with polychrome slate shingles wraps around the facade (east elevation) and the south side elevation. The mansard and the projecting bay have an overhanging boxed cornice of metal that is ornamented with bezant molding and modillions with acanthus leaves. The southeast corner of the building is capped by a pyramidal hipped roof which is ornamented with polychrome slate shingles, a metal finial, and an overhanging boxed cornice decorated with anthemion molding and what appears to be leaf and dart molding. It also has a fluted concrete frieze that is trimmed with bead and reed molding. Oriel windows are located on the east and south elevation. They have half-hipped roofs of standing-seam metal with overhanging boxed cornices. They hold 1/1, double-hung, wood-sash windows over paneled spandrels. The outer edges of the oriel windows are ornamented with arabesque molding. Brick chimneys flank the pyramidal roof and have fluted concrete beltcourses and molded metal caps edged with anthemions. The openings on the northern bays of the first story facade have been altered. The original entry to the building appears to be located in the northernmost bay. This opening has a segmental brick arch and has been partially infilled and clad with vinyl siding. It now holds a 1/1, double-hung, wood-sash window with a one-light transom. The main entry is now located in the center bay of the facade. A one-story vestibule was constructed and projects from the main block. Clad with vinyl siding, the vestibule holds a replacement single-leaf paneled metal door with an oval leaded-glass light. The door is flanked by one-light/one-panel sidelights and is capped by a semicircular fanlight. The southernmost bay of the facade holds an elongated window opening that has been partially infilled with vinyl siding and a standard size 1/1, double-hung, wood-sash window with a one-light transom. A heavy rock-faced flat concrete lintel is located above the opening and wraps around the corner to the south elevation. An intermediate molded metal cornice is located above the first story on the facade and south elevation. It is edged on the top with a scrolled metal railing. The south side of the first story holds a single-leaf, wood-frame French door with a large one-light transom set in a segmental brick arch. A wood-frame projecting bay was constructed east of the entry on this south elevation and is clad with vinyl siding. It holds a band of 1/1, double-hung, wood-sash windows with one-light wood transoms capped by a band of one-light fixed or awning windows. The remainder of the building, including the projecting bay, is fenestrated with 1/1, double-hung, wood-sash windows with concrete lug sills. Openings on the first story have one-light transoms and segmental brick arches. Second-story window openings have segmental brick arches, while the third-story windows have jack brick arches. Molded metal beltcourses wrap around the building at the window sill level on the second and third stories and serve as a continuous sill.

A one-story, one-bay garage was constructed on the rear elevation ca. 1920. The garage, constructed of brick, has a flat roof. The vehicular opening has been enclosed and now holds a single-leaf paneled metal door with a semicircular light. A two-story wood deck is located on top of the flat roof and leads to a roof-top deck on the main block.

Site Notes:

**March 2010:** This dwelling is located on the west side of 9th Street, N.E. at the intersection of 9th and F Streets, N.E. It is set back approximately fifteen feet from the brick sidewalk. The north (side) elevation is adjacent to 602 9th Street, N.E. The front and side yard are planted with mature shrubs and enclosed by brick and milled point metal fencing. A brick walkway leads from the sidewalk to the main entrance, and concrete walkways lead from the sidewalk to the side entrances on the south (side) elevation.



## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False) Sloped</b>	<b>Slate Not Visible</b>	<b>Polychrome</b>	<b>Shingled Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Roman Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation Walls</b>	<b>Concrete &amp; Brick Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Wood</b>
<b>Facade</b>	<b>Segmental-Arched</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Wood</b>
<b>Oriel</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research Reconnaissance Survey</b>

## PHOTOS - DIGITIZED



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 600\_9th\_Street\_NE\_facade\_looking\_NW.JPG**  
Date:: Photog:  
Code:: R: Fr:

---



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 600\_9th\_Street\_NE\_facade\_looking\_SW.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 600\_9th\_Street\_NE\_rear\_looking\_S.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 600\_9th\_Street\_NE\_south\_elevation\_looking\_N.JPG**  
Date:: Photog:  
Code:: R: Fr:

---





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 600\_9th\_Street\_NE\_south\_elevation\_looking\_  
NE.JPG

Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 600\_9th\_Street\_NE\_south\_elevation\_looking\_  
NW.JPG

Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/29/1896	1955	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/14/2010	Barnes (JLB), Jeanne	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0801**

## BASICS DATA

ID Number: **0913-0801** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>800</b>		<b>F Street</b>	<b>NE</b>	<b>Current</b>
<b>802</b>		<b>F Street</b>	<b>NE</b>	<b>Alternate</b>

Name(s)	Type of Name
<b>Rowhouse, 800 F Street, N.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>0913/0801</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2500 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row Corner (1 of 10)**  
Relate to Street: **Face on Line**  
Massing: **Row Building/Multiple Bays**  
Footprint: **Irregular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **4**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **48**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**April 2010:** This two-story rowhouse was erected in 1897 by Melton & Watts. It was designed by architect B. Stanley Simmons for owner Charles R. Pickford. The Queen Anne-style dwelling is the end unit of a row of ten rowhouses. The building is four structural bays wide and two bays deep. It sits on a solid concrete and stone foundation and is constructed of brick faced with stretcher-bond brick. The building consists of a rectangular main block that is flanked by a two-and-a-half-story polygonal canted bay on the west and a two-story, rectangular projecting bay on the east. The main entry, a single-leaf paneled wood door with lights, is located on the facade (south elevation). The entry has a one-light transom, a segmental brick arch, and is reached by metal steps with a scrolled metal balustrade. The building is capped by a sloping roof (materials not visible). The center portion of the main block has a front gable, while the polygonal bay has a pyramidal hipped roof of asphalt shingles and the rectangular bay has a flat roof (materials not visible). Engaged columns and drop pendants ornament the front gable, which is pierced on the facade with a circular louvered vent. The pyramidal roof is ornamented with an overhanging boxed cornice with acanthus-leaf molding, ogee molding, and a rock-faced concrete frieze that serves as a continuous lintel for one-light clerestory windows in the upper story. The boxed cornice of the rectangular projecting bay is ornamented with acanthus-leaf molding, dentil molding, and leaf-and-dart ancons. A fluted stringcourse extends above the first-story window openings on the main block and canted bay. Window openings hold 1/1, double-hung, vinyl sash, some of which have segmental brick arches. A molded concrete stringcourse extends along the window sill level of the second story, doubling as a continuous sill. The second-story window openings of the rectangular bay have a continuous rock-faced concrete lintel, while the openings on the canted bay have a flat concrete lintel with drip molding. A one-story, one-bay addition was constructed on the first-story of the west elevation. This addition may have covered the original entry to the rowhouse. This addition is constructed of brick and has a flat roof. It now holds a large fixed vinyl window.

Site Notes:

**April 2010:** This building is located on the northeast corner of F Street, N.E. and 8th Street, N.E. The level grassy lot contains foundation plantings and mature trees and is enclosed with a metal bow and picket fence. A brick walkway leads from the main entry to the public brick sidewalk. The building, which is set back approximately ten feet from the sidewalk, is attached to 603 8th Street, N.E. on the north side.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	



Structure Component	Material	Feature	Source
<b>Foundation</b>	<b>Stone &amp; Concrete</b>		
<b>Walls</b>	<b>Brick</b>		

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Segmental-Arched</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panel(s)	Material
<b>Main Door</b>	<b>Arched (Segmental)</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Survey(s)

**Capitol Hill F & G Streets (2010)**

Historic District(s)

Designation Event(s)

Level(s) of Investigation

**Permit Research**

**Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **800-  
802\_F\_Street\_NE\_facade\_looking\_ENE.JPG**

Date::

Code::

Photog:

R:

Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 800-  
802\_F\_Street\_NE\_facade\_looking\_NE.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 800-802\_F\_Street\_NE\_side\_looking\_NW.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1897	0985	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/14/2010	Barnes (JLB), Jeanne	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0146**

## BASICS DATA

ID Number: **0913-0146** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>806</b>		<b>F Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-----------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Duplex, 806 F Street, N.E.</b>	<b>Common</b>
<b>Galatians Baptist Church</b>	<b>Current</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0146</b>			<b>Square/Lot</b>	<b>Permit</b>
<b>0913/0856</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Multi-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Original</b>
<b>Religious (Church)</b>					<b>Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2000 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Weller, Frances R.</b>
--------------------------	------------------	---------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Thomas H.</b>
--------------------------	--------------	----------------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached (1 side)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Bldg Flat-Fronted**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **43**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2010:** This two-story, three-bay duplex was constructed in 1897 and is now part of a five-bay, Classical Revival-style church. The building was constructed by Melton and Watts from the design of Francis R. Weller; it was one of six duplexes constructed from the same permit (#0983). The brick and stone structure sits on a solid brick and stone foundation that is veneered with rock-faced concrete on the façade (south elevation). The building is capped by a sloped roof that is highlighted by a molded metal parapet wall with posts and garland ornamentation. The roof is pierced by an interior-side brick chimney with a corbeled cap. A molded metal cornice with thin dentils finishes the roof. The façade is faced with stretcher-bond pressed brick. Openings on the façade at foundation level have concrete-lug lintels and have been boarded up with plywood. The main entryway is located in the eastern end bay on the first story and is shared with 808 8th Street. The opening holds a two-leaf metal-frame glass door leading to a vestibule with a single-leaf flush wood door with one light and a hallway. The entrance features a stone surround and a two-course rowlock brick elliptical arch with concrete or stone imposts and is accessed by concrete steps with turned metal hand rails. The façade is further fenestrated by 1/1, double-hung, vinyl-sash windows and concrete-lug lintels. All openings on the second story are highlighted by concrete sills. A decorative basketweave brick panel is located above the second story openings.

The west (side) elevation holds single-leaf paneled wood doors on the basement and first stories in the northernmost bay. The elevation is further fenestrated with 1/1, double-hung, vinyl-sash windows with rowlock brick or concrete sills and two-course rowlock brick segmental arches.

The main block of the rear (north) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows on the second story. A one-and-a-half-story concrete-block addition, formerly a garage, was constructed between ca. 1925 and ca. 1940. The exterior has been parged.

Site Notes:

**March 2010:** This building is located on the north side of F Street, N.E. at the intersection of F Street and Pickford Place, N.E. It is set back approximately fifteen feet from the brick sidewalk. The east (side) elevation is adjacent to 808 8th Street, N.E. The grassy front and side yard are enclosed by bow and picket metal fencing. A concrete walkway leads from the sidewalk to the main entrance. An alleyway is located at the rear of the building.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	



Structure Component	Material	Feature	Source
<b>Foundation</b>	<b>Brick &amp; Stone</b>		
<b>Walls</b>	<b>Brick &amp; Stone</b>		
Materials Notes:			

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>Boarded</b>	<b>Wood</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Pamels	Material
<b>First Floor</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Metal</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**  
File: **806\_F\_Street\_NE\_facade\_looking\_NE.JPG**  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 806\_F\_Street\_NE\_facade\_looking\_NW.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 806\_F\_Street\_NE\_rear\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/28/1897	0983	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0147**

## BASICS DATA

ID Number: **0913-0147** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**616** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 616 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0147** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

**Vernacular**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of five-course, American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (east elevation) is faced with nine-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 618 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Concrete sills and soldier brick segmental arches with rowlock brick caps finish each opening. The south (side) elevation is pierced by a single-leaf wood door with a one-light transom and a single-leaf wood-frame glass door with a one-light transom. Additional fenestration consists of 1/1, double-hung, vinyl-sash windows. All openings have two-course, rowlock brick segmental arches and the windows also feature concrete sills.

Site Notes:

**March 2010:** This two-story duplex is located on the west side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The north (side) elevation of the building is adjacent to 618 Pickford Place, N.E. The southern side yard is encircled by a wood privacy fence. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Full Glass</b>	<b>Wood</b>
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

**Tuesday, June 25, 2013**

**ID\_Number: 0913-0147 Page 2**



Contributing:

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 616\_Pickford\_Place\_NE\_facade\_looking\_NW.  
JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

### Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 616\_Pickford\_Place\_NE\_facade\_looking\_SW.  
JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:



## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/5/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0145**

## BASICS DATA

ID Number: **0913-0145** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>806</b>		<b>F Street</b>	<b>NE</b>	<b>Current</b>
<b>808</b>		<b>F Street</b>	<b>NE</b>	<b>Original</b>

Name(s)	Type of Name
<b>Duplex, 808 F Street, N.E.</b>	<b>Common</b>
<b>Galatians Baptist Church</b>	<b>Current</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>0913/0145</b>			<b>Square/Lot</b>	<b>Permit</b>
<b>0913/0856</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Duplex** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Multi-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Original</b>
<b>Religious (Church)</b>					<b>Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2000 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Weller, Frances R.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Thomas H.</b>

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached (1 side)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Flat Front**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **43**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2010:** This two-story, three-bay duplex was constructed in 1897 and is now part of a five-bay, Classical Revival-style church. The building was constructed by Melton and Watts from the design of Francis R. Weller; it was one of six duplexes constructed from the same permit (#0983). The brick and stone structure sits on a solid brick and stone foundation that is veneered with rock-faced concrete on the façade (south elevation). The building is capped by a sloped roof that is highlighted by a molded metal parapet wall with posts and garland ornamentation. The roof is pierced by an interior-side brick chimney with a corbeled cap. A molded metal cornice with thin dentils finishes the roof. The façade is faced with stretcher-bond pressed brick. Openings on the façade at foundation level have concrete-lug lintels and have been boarded up with plywood. The main entryway is located in the eastern end bay on the first story and is shared with 806 8th Street. The opening holds a two-leaf metal-frame glass door leading to a vestibule with a single-leaf flush wood door with one light and a hallway. The entrance features a stone surround and a two-course rowlock brick elliptical arch with concrete or stone impostes and is accessed by concrete steps with turned metal hand rails. The façade is further fenestrated by 1/1, double-hung, vinyl-sash windows and concrete-lug lintels. All openings on the second story are highlighted by concrete sills. A decorative basketweave brick panel is located above the second story openings.

Openings on the east (side) elevation hold 1/1, double-hung, vinyl-sash windows with concrete or rowlock brick sills and two-course rowlock brick segmental arches. An opening on the foundation level has been boarded up. A single-leaf flush wood door is located on the first story in the northernmost bay. This door is accessed via concrete steps with metal hand rails. Brick dentils complement the stepped parapet wall on this elevation.

The main block of the rear (north) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows on the second story. An asymmetrical, one-and-a-half-story concrete-block addition, formerly a garage, was constructed between ca. 1925 and ca. 1940. The exterior has been parged. A single-leaf opening is located on the northeast elevation, and the north elevation is pierced by clerestory window openings.

Site Notes:

**March 2010:** This building is located on the north side of F Street, N.E. at the intersection of F Street and Pickford Place, N.E. It is set back approximately fifteen feet from the brick sidewalk. The west (side) elevation is adjacent to 806 8th Street, N.E. The grassy front and side yard are enclosed by bow and picket metal fencing. A concrete walkway leads from the sidewalk to the main entrance. An alleyway is located at the rear of the building.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source



<b>Facade</b>	<b>Brick</b>	<b>Stretcher Bond</b>
Structure Component	Material	Feature
<b>Foundation</b>	<b>Brick &amp; Stone</b>	
<b>Walls</b>	<b>Brick &amp; Stone</b>	

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>Boarded</b>	<b>Wood</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Pamels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Metal</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **808\_F\_Street\_NE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 808\_F\_Street\_NE\_facade\_looking\_NW.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 808\_F\_Street\_NE\_rear\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/28/1897	0983	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0148**

## BASICS DATA

ID Number: **0913-0148** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**618** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 618 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0148** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

**Vernacular**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of five-course, American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (east elevation) is faced with nine-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 616 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, metal-sash. Rowlock brick sills and soldier brick segmental arches with rowlock brick caps finish each opening. The north (side) elevation is pierced by a single-leaf door with a one-light transom. Additional visible fenestration consists of 1/1, double-hung, metal-sash windows. All openings have two-course, rowlock brick segmental arches and the windows also feature rowlock brick sills.

Site Notes:

**March 2010:** This two-story duplex is located on the west side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The south (side) elevation of the building is adjacent to 616 Pickford Place, N.E. A tall, wood privacy fence encircles the northern side yard. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Metal</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

**Tuesday, June 25, 2013**

**ID\_Number: 0913-0148 Page 2**



Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

### PHOTOS - DIGITIZED

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 618\_Pickford\_Place\_NE\_facade\_looking\_NW.  
JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 618\_Pickford\_Place\_NE\_facade\_looking\_SW.  
JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:



## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/5/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0149**

## BASICS DATA

ID Number: **0913-0149** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**622** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 622 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0149** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

March 2010: Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of five-course, American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (east elevation) is faced with nine-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 624 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. Multiple brick string courses span the façade. Window openings on the façade hold 6/6, double-hung, wood-sash. Header brick sills and soldier brick segmental arches with rowlock brick caps finish each opening. The south (side) elevation is pierced by a single-leaf paneled wood door, which is flanked by fluted pilasters and topped by a molded lintel. Additional visible fenestration consists of 6/6, double-hung, wood-sash windows and a full-height fixed window. All window openings have two-course, rowlock brick segmental arches.

Site Notes:

March 2010: This two-story duplex is located on the west side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The north (side) elevation is adjacent to 624 Pickford Place, N.E. The southern side yard is encircled by a tall, wood privacy fence. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>6/6</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:



Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

### PHOTOS - DIGITIZED

Caption:

### Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 622\_Pickford\_Place\_NE\_facade\_looking\_NW.  
JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

### Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 622\_Pickford\_Place\_NE\_facade\_looking\_SW.  
JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:



## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/5/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0150**

## BASICS DATA

ID Number: **0913-0150** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**624** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 624 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0150** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

March 2010: Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of five-course, American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (east elevation) is faced with nine-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 622 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior brick chimney pierces the roof and has a corbeled brick cap. Multiple brick string courses span the façade. Window openings on the façade hold 6/6, double-hung, wood-sash. Rowlock brick sills and soldier brick segmental arches with rowlock brick caps finish each opening. The north (side) elevation is pierced by a single-leaf paneled wood door, which is flanked by fluted pilasters and topped by a front gabled pediment. Additional visible fenestration consists of a full-height fixed window.

Site Notes:

March 2010: This two-story duplex is located on the west side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The south (side) elevation of the dwelling is adjacent to 622 Pickford Place, N.E. The northern side yard is encircled by a tall, wood privacy fence. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>6/6</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:



Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 624\_Pickford\_Place\_NE\_facade\_looking\_NW.  
JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 624\_Pickford\_Place\_NE\_facade\_looking\_SW.  
JPG

Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:



## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/5/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0151**

## BASICS DATA

ID Number: **0913-0151** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**628** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 628 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0151** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

March 2010: Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of five-course, American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (east elevation) is faced with nine-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 630 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior brick chimney pierces the roof and has a corbeled brick cap. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Vinyl-clad sills and soldier brick segmental arches with rowlock brick caps finish each opening. The south (side) elevation is pierced by a single-leaf paneled wood door with lights, which is flanked by fluted pilasters with bulls-eye cornerblocks, in the easternmost bay and a single-leaf door in the westernmost bay. Both doors are topped by blind transoms. Additional visible fenestration consists of 1/1, double-hung, vinyl-sash windows, which have vinyl-clad sills and two-course, rowlock brick segmental arches. A one-story, two-bay porch shelters the easternmost bay of the south elevation. The half-hipped roof of the porch is covered with metal and is supported by square wood posts with jigsaw brackets.

Site Notes:

March 2010: This two-story duplex is located on the west side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The north (side) elevation of the building is adjacent to 630 Pickford Place, N.E. A metal chain link encircles the front half of the southern side yard, while a tall, wood privacy fence bounds the western half of the side yard. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA



Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **628\_Pickford\_Place\_NE\_facade\_looking\_NW.  
JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **628\_Pickford\_Place\_NE\_facade\_looking\_W.J  
PG**

Date:: Photog:

Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>07/07/1897</b>	<b>0022</b>	<b>Build</b>	

Permit Notes:

--

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------



Bibliographic Notes:

--

## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/5/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0152**

## BASICS DATA

ID Number: **0913-0152** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**630** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 630 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0152** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

March 2010: Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of brick and is set on a solid foundation composed of concrete and architectural brick. The façade (east elevation) is faced with nine-course, American-bond brick and the north (side) elevation is parged. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 628 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior parged chimney pierces the roof. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, wood-sash. Concrete sills and soldier brick segmental arches with rowlock brick caps finish each opening. The north (side) elevation is pierced by a single-leaf metal door with lights and a one-light transom. Additional visible fenestration consists of 1/1, double-hung, vinyl-sash windows and 2/2, double-hung, wood-sash windows.

Site Notes:

March 2010: This two-story duplex is located on the west side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The south (side) elevation of the building is adjacent to 628 Pickford Place, N.E. A metal chain-link fence encircles the eastern half of the northern side yard, while a tall, wood privacy fence bounds the western half. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Metal/Glas</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Tuesday, June 25, 2013

ID\_Number: 0913-0152 Page 2



Contributing:

Survey(s)

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

**Permit Research  
Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 630\_Pickford\_Place\_NE\_facade\_looking\_NW.  
JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 630\_Pickford\_Place\_NE\_facade\_looking\_SW.  
JPG

Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:



## SIGNIFICANCE DATA

---

Study Unit

---

Code	Criteria
------	----------

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/5/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0153**

## BASICS DATA

ID Number: **0913-0153** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**634** **Pickford Place** **NE Current**

Name(s) Type of Name

**Duplex, 634 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0153** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

**Vernacular**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of brick and is set on a solid foundation composed of concrete and architectural brick. The façade (east elevation) is faced with ten-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 636 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior brick chimney pierces the roof and has a plain cap. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Concrete sills and soldier brick segmental arches with rowlock brick caps finish each opening. The south (side) elevation is pierced by a single-leaf door and a one-light transom. Additional visible fenestration consists of 1/1, double-hung, vinyl-sash windows, which feature two-course, rowlock brick segmental arches.

Site Notes:

**March 2010:** This two-story duplex is located on the west side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The north (side) elevation is adjacent to 636 Pickford Place, N.E. A concrete walkway leads from the sidewalk and leads to an entrance located on the south (side) entrance. The southern side yard is encircled by a tall, wood privacy fence. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

**Tuesday, June 25, 2013**

**ID\_Number: 0913-0153 Page 2**



Contributing:

Survey(s)

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

**Permit Research  
Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 634\_Pickford\_Place\_NE\_facade\_looking\_NW.  
JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 634\_Pickford\_Place\_NE\_facade\_looking\_SW.  
JPG

Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:



## **SIGNIFICANCE DATA**

---

Study Unit

---

Code                      Criteria

---

## **DATA PROCESSING EVENTS DATA**

---

Date	Individual	Action
4/5/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0154**

## BASICS DATA

ID Number: **0913-0154** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**636** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 636 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0154** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi Coop)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

March 2010: Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (east elevation) is faced with ten-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 634 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior brick chimney pierces the roof and has a plain cap. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Header brick sills and soldier brick segmental arches with rowlock brick caps finish each opening. The north (side) elevation is pierced by two single-leaf paneled wood doors with one-light transoms. Additional visible fenestration consists of 1/1, double-hung, vinyl-sash windows. All openings have two-course, rowlock brick segmental arches. The windows have header brick sills.

Site Notes:

March 2010: This two-story duplex is located on the western side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The south (side) elevation of the dwelling is adjacent to 634 Pickford Place, N.E. The northern side yard is encircled by metal milled point fencing and wood fencing. An ally is located west of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Tuesday, June 25, 2013

ID\_Number: 0913-0154 Page 2



Contributing:

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

### PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 636\_Pickford\_Place\_NE\_facade\_looking\_NW.  
JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 636\_Pickford\_Place\_NE\_facade\_looking\_SW.  
JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:



## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/5/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0155**

## BASICS DATA

ID Number: **0913-0155** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**640** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 640 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0155** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

March 2010: Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of five-course, American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (east elevation) is faced with ten-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 642 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior brick chimney pierces the roof and has a corbeled brick cap. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Header brick sills on the first story and concrete sills on the second story, in addition to soldier brick segmental arches with rowlock brick caps finish each opening. The south (side) elevation is pierced by a single-leaf paneled wood door. The door is flanked by pilasters, which support a molded lintel. Additional visible fenestration consists of 1/1, double-hung, vinyl-sash windows and a one-light vinyl casement window over a one-light vinyl awning window. All window openings have two-course, rowlock brick segmental arches and header brick sills.

Site Notes:

March 2010: This two-story duplex is located on the west side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The north (side) elevation of the building is adjacent to 642 Pickford Place, N.E. The southern side yard is encircled by a tall, wood privacy fence. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbi-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:



Zoning:  
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 640\_Pickford\_Place\_NE\_facade\_looking\_NW.  
JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 640\_Pickford\_Place\_NE\_facade\_looking\_W.J  
PG

Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------



Bibliographic Notes:

--

## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/5/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0156**

## BASICS DATA

ID Number: **0913-0156** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**642** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 642 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0156** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

March 2010: Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of five-course, American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (east elevation) is faced with ten-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 640 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior brick chimney pierces the roof and has a corbeled brick cap. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash with false 6/6 vinyl muntins. Rowlock brick sills and soldier brick segmental arches with rowlock brick caps finish each opening. The north (side) elevation is pierced by a single-leaf door with lights. The door is flanked by fluted pilasters, which support lintel with dentil molding. Additional visible fenestration consists of 1/1, double-hung, vinyl-sash windows and a one-light vinyl window (possibly casement). All window openings have two-course, rowlock brick segmental arches and rowlock brick sills.

Site Notes:

March 2010: This two-story duplex is located on the western side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The south (side) elevation is adjacent to 640 Pickford Place, N.E. The northern side yard is encircled by a tall, wood privacy fence. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbi-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown w/Lights</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Tuesday, June 25, 2013

ID\_Number: 0913-0156 Page 2



Zoning:  
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 642\_Pickford\_Place\_NE\_facade\_looking\_NW.  
JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 642\_Pickford\_Place\_NE\_facade\_looking\_SW.  
JPG

Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------



Bibliographic Notes:

--

## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/5/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0157**

## BASICS DATA

ID Number: **0913-0157** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**646** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 646 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0157** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

March 2010: Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of five-course, American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (east elevation) is faced with ten-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 648 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior brick chimney pierces the roof and has a plain brick cap. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash with false 6/6 vinyl muntins. Concrete sills and soldier brick segmental arches with rowlock brick caps finish each opening. The south (side) elevation is pierced by a single-leaf paneled wood door. The door is flanked by pilasters and is topped by a molded door hood that is supported by brackets. Additional visible fenestration consists of double-leaf sliding glass doors and 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins. All window openings have a parged surround and concrete sills.

Site Notes:

March 2010: This two-story duplex is located on the western side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The north (side) elevation is adjacent to 648 Pickford Place, N.E. The southern side yard is encircled by a tall, wood privacy fence. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbi-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Vinyl</b>
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Tuesday, June 25, 2013

ID\_Number: 0913-0157 Page 2



Ward/ANC:  
Zoning:  
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 646\_Pickford\_Place\_NE\_facade\_looking\_SW.  
JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 646\_Pickford\_Place\_NE\_facade\_looking\_NW.  
JPG

Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/07/1897	0022	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------



Bibliographic Notes:

--

## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/5/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0158**

## BASICS DATA

ID Number: **0913-0158** Year Built: **1897** Data Source: **Permit**

Number Extended Street Quad Type of Address

**648** **Pickford Place** **NE** **Current**

Name(s) Type of Name

**Duplex, 648 Pickford Place, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0158** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1897** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1897** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-four duplexes constructed from the same permit (#0022).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **38**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

**Vernacular**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by Melton & Watts, this two-story, two-bay duplex was influenced by the Italianate style and is one of twenty-four duplexes constructed from the same permit (#0022). The duplex is constructed of five-course, American-bond brick and is set on a solid foundation composed of concrete and architectural brick. The façade (east elevation) is faced with ten-course, American-bond brick. A sloping roof caps the building and is fronted along the façade by a crowstep parapet that is shared with 646 Pickford Place, N.E. A molded cornice with corbeled brick complements the parapet. An interior brick chimney pierces the roof and has a plain brick cap. Multiple brick string courses span the façade. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Header brick sills and soldier brick segmental arches with rowlock brick caps finish each opening. The north (side) elevation is pierced by a single-leaf wood door. Additional visible fenestration consists of a single-leaf wood door and 1/1, double-hung, vinyl-sash windows, and a full-height window.

Site Notes:

**March 2010:** This two-story duplex is located on the western side of Pickford Place, N.E. and directly fronts the concrete sidewalk. The south (side) elevation is adjacent to 646 Pickford Place, N.E. A wood privacy fence encircles the northern side yard. An alley is located west of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood</b>
<b>Side Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

**Tuesday, June 25, 2013**

**ID\_Number: 0913-0158 Page 2**



Contributing:

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 648\_Pickford\_Place\_NE\_facade\_looking\_NW.  
JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 648\_Pickford\_Place\_NE\_side\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 648\_Pickford\_Place\_NE\_facade\_looking\_SW.  
JPG

Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Tuesday, June 25, 2013

ID\_Number: 0913-0158 Page 3



Permit Notes:

--

**BIBLIOGRAPHIC DATA**

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

--

**SIGNIFICANCE DATA**

---

Study Unit

---

Code	Criteria
------	----------

---

**DATA PROCESSING EVENTS DATA**

---

Date	Individual	Action
4/5/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0159**

## BASICS DATA

ID Number: **0913-0159** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>809</b>		<b>G Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-----------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Singlel Dwelling, 809 G Street, N.E.</b>	<b>Common</b>
---	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0159</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2000 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Weller, Frances R.</b>
--------------------------	------------------	---------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Thomas H.</b>
--------------------------	--------------	----------------------------

Construction Notes:

**One of six buildings constructed from the same permit (#0983). Only four are extant.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Attached (1 side)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Block**  
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **43**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by Melton & Watts, this two-story, three-bay Classical Revival-style single-family dwelling was constructed with six similar buildings from the same permit (#0983). Only four are still extant. The dwelling is constructed of five-course, American-bond brick and is set on a solid brick and stone foundation; the façade (north elevation) is faced with stretcher-bond brick. Concrete sill courses span the façade below the first and second story openings. A sloping roof caps the dwelling and is highlighted by a prominent projecting molded cornice with dentil molding. A parapet rises from the façade and features wreath molding. A decorative rectangular panel is located above the second story openings and is composed of basket weave brickwork. An interior-side brick chimney rises from the west (side) elevation and has a corbeled brick cap. The easternmost bay of the façade holds a single-leaf paneled wood door with lights and a one-light semi-circular fanlight. A three-course, rowlock brick semi-circular arch with a keystone and impost surmounts the fanlight. The first and second story window openings hold 1/1, double-hung, vinyl-sash windows. The foundation is pierced by one-light windows (possibly fixed). All openings have concrete sills and lintels. The west (side) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows. The windows have vinyl-clad sills and are topped by two-course, rowlock brick segmental arches. The rear elevation is fenestrated with a single-leaf paneled wood door with a one-light transom and 1/1, double-hung, vinyl-sash windows. All windows have vinyl-clad sills and two-course, rowlock brick segmental arches.

Site Notes:

**March 2010:** This two-story dwelling is located on the south side of G Street, N.E. and is set back approximately fifteen feet from the brick sidewalk. The east (side) elevation of the dwelling is adjacent to 811 G Street, N.E. The front yard is landscaped with mature shrubs and is encircled by metal bow and picket fencing. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk.

## NOTABLE FEATURES DATA

Component Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick &amp; Stone</b>			
<b>Walls</b>	<b>Brick</b>			



Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>1-light</b>	<b>Unknown</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Pamels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 809\_G\_Street\_NE\_facade\_looking\_S.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 809\_G\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 809\_G\_Street\_NE\_rear\_looking\_NNE.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/28/1897	0983	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
4/5/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0160**

## BASICS DATA

ID Number: **0913-0160** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>811</b>		<b>G Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-----------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Single Dwelling, 811 G Street, N.E.</b>	<b>Common</b>
--	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0160</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2000 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Weller, Frances R.</b>
--------------------------	------------------	---------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Thomas H.</b>
--------------------------	--------------	----------------------------

Construction Notes:

**One of six buildings constructed from the same permit (#0983). Only four are extant.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached (1 side)**  
Relate to Street: **Face on Setback Line**  
Massing: **Block**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **43**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by Melton & Watts, this two-story, three-bay Classical Revival-style single-family dwelling was constructed with six similar buildings from the same permit (#0983). Only four are still extant. The dwelling is constructed of five-course, American-bond brick and is set on a solid brick and stone foundation; the façade (north elevation) is faced with stretcher-bond brick. Brick sill courses span the façade below the first and second story openings. A sloping roof caps the dwelling and is highlighted by a prominent projecting molded cornice with dentil molding. A parapet rises from the façade and features wreath molding. A decorative rectangular panel is located above the second story openings and is composed of basket weave brickwork. An interior-side brick chimney rises from the east (side) elevation and has a corbeled brick cap. The westernmost bay of the façade holds a single-leaf wood door with three lights and a one-light semi-circular fanlight. A three-course, rowlock brick semi-circular arch with a keystone and impost surmounts the fanlight. The first and second story window openings hold 1/1, double-hung, vinyl-sash windows. The foundation is pierced by one-light vinyl windows (possibly fixed). All openings have concrete sills and lintels. The east elevation is fenestrated with 1/1, double-hung, vinyl-sash windows. The windows have concrete sills and are topped by two-course, rowlock brick segmental arches. The rear elevation is fenestrated with a single-leaf door with a diamond-shaped light and a one-light transom and 1/1, double-hung, vinyl-sash windows. All windows have concrete sills and two-course, rowlock brick segmental arches. A one-story, one-bay porch shelters the door opening and has a shed roof. The roof is covered with asphalt shingles and is supported by square wood posts.

Site Notes:

**March 2010:** This two-story dwelling is located on the south side of G Street, N.E. and is set back approximately fifteen feet from the brick sidewalk. The west (side) elevation of the dwelling is adjacent to 809 G Street, N.E. The grassy front yard is landscaped with mature shrubs and is encircled by a metal bow and picket fence. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. Metal chain-link fencing bounds the rear yard.

## NOTABLE FEATURES DATA

Component Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick &amp; Stone</b>			
<b>Walls</b>	<b>Brick</b>			



Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>1-light</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Pamels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood/Glass</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 811\_G\_Street\_NE\_facade\_looking\_S.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 811\_G\_Street\_NE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\

File: 811\_G\_Street\_NE\_rear\_looking\_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\

File: 811\_G\_Street\_NE\_side\_looking\_SW.JPG

Date:: Photog:

Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/28/1897	0983	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/5/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0828**

## BASICS DATA

ID Number: **0913-0828** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>653</b>		<b>8th Street</b>	<b>NE</b>	<b>Current</b>
<b>807</b>		<b>G Street</b>	<b>NE</b>	<b>Alternate</b>

Name(s)	Type of Name
<b>Dwelling/Store, 653 8th Street, N.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>0913/0828</b>			<b>Square/Lot</b>	<b>Current</b>
<b>0913/0115</b>			<b>Square/Lot</b>	<b>Historic</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Dwelling & Store** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential/Store</b>	<b>1897</b>	<b>Permit</b>			<b>Original</b>
<b>Residential (Multi-Family)</b>					<b>Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>3000 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Brant, Benjamin T.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Brant, Benjamin T.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Brant, Benjamin T.</b>

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Attached (1 side)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Block (irregular)**  
 Footprint: **Rectangular (irregular)**

Cross Reference Notes:

Number Stories: **3 plus basement**

Bays Wide:

Height:

Width: **19**

Depth/Length: **50**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** This three-story Queen Anne-style dwelling and store was constructed in 1897 by Benjamin T. Brant from permit #1480; it now serves as a multiple dwelling. The five-course American-bond brick structure is set on a solid concrete and brick foundation. A sloped roof caps the dwelling and is complemented on the façade (west elevation) and side by metal coping and a corbeled brick cornice. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows with concrete and wood sills and two-course rowlock brick segmental arches. A three-sided rectangular bay projects from the northwest corner of the dwelling and contains the main entrance. The bay shares the material treatment of the main block and holds a single-leaf paneled wood door with a semicircular transom and three-course rowlock brick semicircular arch on the first story. All other openings on the bay hold 1/1, double-hung, vinyl-sash windows with concrete or wood sills and two-course rowlock brick segmental arches. The north (side) elevation holds an interior brick chimney with a corbeled cap. The elevation has a three-sided rectangular projecting bay on the eastern end bay. This bay holds a single-leaf paneled wood door with a one-light transom on the first story, which is accessed by brick steps. All other openings on this elevation hold 1/1, double-hung, vinyl-sash windows with concrete or wood sills and two-course rowlock brick segmental arches. One-light windows pierced the foundation.

A one-story, one-bay brick garage was constructed ca. 1925 and extends from the rear (east) elevation of the building. The garage has a shed roof and is pierced on the north elevation by a roll-up paneled metal door. A two-story wood deck is located above the garage. The deck has a shed roof supported by square wood posts and is encircled by square wood balusters.

Site Notes:

**March 2010:** This building is located on the east side of 8th Street, N.E. at the intersection of 8th and G Streets, N.E. and is set back approximately fifteen feet from the brick sidewalk. The south (side) elevation is adjacent to 651 8th Street, N.E. The front yard wraps around to the side elevation and is landscaped with immature shrubs; it is bounded by a brick retaining wall with brick posts and milled point metal fencing. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk.

## NOTABLE FEATURES DATA

Component	Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source



Foundation Concrete & Brick  
Walls Brick

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b> <b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 653\_8th\_Street\_NE\_807\_G\_Street\_NE\_facade  
\_looking\_E.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 653\_8th\_Street\_NE\_807\_G\_Street\_NE\_facade  
\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 653\_8th\_Street\_NE\_807\_G\_Street\_NE\_rear\_lo  
oking\_NW.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 653\_8th\_Street\_NE\_807\_G\_Street\_NE\_side\_lo  
oking\_SW.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/08/1897	1480	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/16/2010	Litowitz (DDL), Dana	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0827**

## BASICS DATA

ID Number: **0913-0827** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>651</b>		<b>8th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Single Dwelling, 651 8th Street, N.E.</b>	<b>Common</b>
--	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0827</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

<b>0913/0114</b>			<b>Square/Lot</b>	<b>Historic</b>
------------------	--	--	-------------------	-----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2000 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Weller, Frances R.</b>
--------------------------	------------------	---------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Thomas H.</b>
--------------------------	--------------	----------------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached (1 side)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Bldg Flat-Fronted**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2010:** This two-story, three-bay Classical Revival-style single dwelling was constructed in 1897 by Melton and Watts. The dwelling, constructed from the design of Mr. Weller from permit # 0977, is constructed of brick and is set on a solid concrete and brick foundation that has a rock-faced veneer on the façade (west elevation). A sloping roof caps the building and is pierced by an interior-side brick chimney on the south elevation. The roof is highlighted by a brick parapet wall with metal end posts. Below the parapet is a molded metal cornice with metal dentils and a brick dentil course below. The façade is faced with stretcher-bond pressed brick and two-course brick sill courses span the façade below the first- and second-story window openings. A single-leaf paneled wood door with a semicircular transom and a three-course rowlock brick sill is located in the northernmost bay of the first story. This entry is accessed by concrete steps. All other openings hold 1/1, double-hung, vinyl-sash windows with 2/2 false muntins and concrete-lug sills.

The rear (east) elevation is fenestrated by 1/1, double-hung, vinyl-sash windows with wood sills and two-course rowlock brick segmental arches. A two-story, two-bay brick ell projects from the north bay of the rear. The ell is capped by a sloped roof and is fenestrated by a single-leaf door with a one-light transom in the northern end bay. All other openings on the ell hold one-light casement or 1/1, double-hung, vinyl-sash windows with wood or rowlock brick sills and two-course rowlock brick segmental arches.

Site Notes:

**March 2010:** This single dwelling is located on the east side of 8th Street, N.E. and is set back approximately fifteen feet from the brick sidewalk. The north (side) elevation is adjacent to 653 8th/ 807 G Street, N.E. The front yard is landscaped with mature shrubs and foundation plantings and is bounded by milled point metal fencing. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. A small yard enclosed by wood privacy fencing and chain link metal fencing is located at the rear of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			



Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
Notable Interior Plan(s)			Notable Interior Feature(s)	

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 651\_8th\_Street\_NE\_facade\_looking\_E.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 651\_8th\_Street\_NE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 651\_8th\_Street\_NE\_rear\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/23/1897	0977	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

---

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
4/16/2010	Litowitz (DDL), Dana	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0826**

## BASICS DATA

ID Number: **0913-0826** Year Built: **1881** Data Source: **Permit**

Number Extended Street Quad Type of Address

**647** **8th Street** **NE Current**

Name(s) Type of Name

**Duplex, 647 8th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0826** **Square/Lot** **Current**

**0913/0113** **Square/Lot** **Historic**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1881** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1881** **Permit** **1120 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Price, W.**

**Orig Construction** **Owner** **Temple (Mary J.) et al.**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

March 2010: Constructed in 1881 by W. Price, this two-story, two-bay vernacular duplex was influenced by the Italianate style. The dwelling is one of eight similar dwellings constructed by Price from the same permit (#0690). The building is constructed of seven-course, American-bond brick and is set on a solid brick foundation. A sloping roof caps the dwelling and is complemented on the façade (west elevation) by a parged parapet wall. The entire façade of the dwelling has been parged. The southern end bay of the façade holds a single-leaf paneled wood door with lights and a one-light transom. A concrete surround highlights the opening. The entrance is accessed by low wood decking that spans the façade and is encircled by wood balusters. All window openings on the façade hold 2/2, double-hung, wood-sash windows and have concrete sills and concrete, possibly painted faux concrete, surrounds or hoods. The foundation on the north (side) elevation has been parged. The rear (east) elevation has also been fully parged and is fenestrated with a single-leaf door with a one-light transom in the northernmost bay. The elevation is further fenestrated by 2/2 and 6/6, double-hung, wood-sash windows with concrete sills.

Site Notes:

March 2010: This duplex is located on the east side of 8th Street, N.E. and is set back approximately forty feet from the brick sidewalk. The south (side) elevation is adjacent to 645 8th Street, N.E. The front yard contains grass and mature trees and is bounded by chain link metal fencing. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. A small yard enclosed by wood privacy fencing and chain link metal fencing is located at the rear of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Parged</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>2/2</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/Area:

Tuesday, June 25, 2013

ID\_Number: 0913-0826 Page 2



ward/ANC:  
Zoning:  
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 647\_8th\_Street\_NE\_facade\_looking\_E.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 647\_8th\_Street\_NE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 647\_8th\_Street\_NE\_rear\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------



Permit Notes:

--

**BIBLIOGRAPHIC DATA**

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

--

**SIGNIFICANCE DATA**

---

Study Unit

--

Code	Criteria
------	----------

---

--

**DATA PROCESSING EVENTS DATA**

---

Date	Individual	Action
4/16/2010	Litowitz (DDL), Dana	Record Updated
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0825**

## BASICS DATA

ID Number: **0913-0825** Year Built: **1881** Data Source: **Permit**

Number Extended Street Quad Type of Address

**645** **8th Street** **NE Current**

Name(s) Type of Name

**Duplex, 645 8th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0825** **Square/Lot** **Current**

**0913/0112** **Square/Lot** **Historic**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Duplex** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1881** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1881** **Permit** **1120 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Price, W.**

**Orig Construction** **Owner** **Temple (Mary J.) et al.**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

March 2010: Constructed in 1881 by W. Price, this two-story, two-bay vernacular duplex was influenced by the Italianate style. The dwelling is one of eight similar dwellings constructed by Price from the same permit (#0690). The building is constructed of seven-course, American-bond brick and is set on a solid brick foundation. A sloping roof caps the dwelling and is complemented on the façade (west elevation) by a parged parapet wall. The entire façade of the dwelling has been parged. The southern end bay of the façade holds a single-leaf paneled wood door with lights and a one-light transom. A concrete surround highlights the opening. The entrance is accessed by low wood decking that spans the façade and is encircled by wood balusters. All window openings on the façade hold 2/2, double-hung, wood-sash windows and have concrete sills and concrete, possibly painted faux concrete, surrounds or hoods. The foundation on the north (side) elevation has been parged. The rear (east) elevation has also been fully parged and is fenestrated with a single-leaf paneled wood door with lights and a one-light transom in the southernmost bay. The elevation is further fenestrated by 1/1 and 6/1, double-hung, wood-sash windows with concrete sills.

Site Notes:

March 2010: This duplex is located on the east side of 8th Street, N.E. and is set back approximately forty feet from the brick sidewalk. The north (side) elevation is adjacent to 647 8th Street, N.E. The front yard contains grass and mature trees and is bounded by chain link metal fencing. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. A small yard enclosed by wood privacy fencing and chain link metal fencing is located at the rear of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Parged</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>2/2</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/Area:

Tuesday, June 25, 2013

ID\_Number: 0913-0825 Page 2



ward/ANC:  
Zoning:  
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 645\_8th\_Street\_NE\_facade\_looking\_E.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 645\_8th\_Street\_NE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 645\_8th\_Street\_NE\_rear\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------



Permit Notes:

--

**BIBLIOGRAPHIC DATA**

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

--

**SIGNIFICANCE DATA**

---

Study Unit

--

Code	Criteria
------	----------

---

**DATA PROCESSING EVENTS DATA**

---

Date	Individual	Action
4/16/2010	Litowitz (DDL), Dana	Record Updated
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0823**

## BASICS DATA

ID Number: **0913-0823** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>643</b>		<b>8th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Single Dwelling, 643 8th Street, N.E.</b>	<b>Common</b>
--	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0823</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

<b>0913/0110</b>			<b>Square/Lot</b>	<b>Historic</b>
------------------	--	--	-------------------	-----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2500 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row End (1 of 3)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Bldg (Rect. Bay)**  
Footprint: **L-Shaped**

Number Stories: **2 plus basement**  
Bays Wide: **2**

Height:  
Width: **17**  
Depth/Length: **48**

SqFt:  
Volume:  
Lot Width

Lot Depth/Length:  
Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897, this two-story, two-bay single-family rowhouse is one of ten similar dwellings constructed by Melton & Watts from the same permit (#0985). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling is set on a solid concrete foundation with a rock-faced stone veneer. The façade (west elevation) of this brick structure has stretcher-bond brick veneer. A sloped roof is obscured by a false mansard of slate shingles. A metal cornice has scrolled molding and decorative modillions. An interior brick chimney pierces the roof. The façade features a two-story projecting bay capped by a front-gabled roof of slate shingles. Supported architecturally by molded concrete corner pendants, a molded concrete balustrade extends through the front gable. A molded concrete sill course extends across the first-story and is offset by a molded metal architrave which extends below the second-story openings. Window openings on the façade hold single and paired 1/1, double-hung, vinyl-sash and one-light vinyl windows. The first-story window openings have three-course, rowlock brick segmental arches and wood panels below. The second-story window opening on the main block has a rowlock brick segmental arch. A wide, rock-faced concrete lintel extends above second-story openings of the projecting bay. Located in the northern bay of the first story, the main entry holds a single-leaf paneled wood door with a three-light sidelight and a one-light transom. The opening is highlighted by a three-course rowlock brick segmental arch and is accessed via metal steps with metal hand rails. The secondary door opening is located below grade and holds a single-leaf wood door. The foundation is further pierced by one-light fixed wood windows. The east (rear) elevation features a two-story, two-bay ell. This brick structure is capped by a sloped roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows with two-course rowlock brick segmental arches.

Site Notes:

**March 2010:** This end-unit rowhouse is located east of 8th Street, N.E. and is set back from the brick sidewalk approximately ten feet. The south (side) elevation is adjacent to 641 8th Street, N.E. and the north (side) elevation is adjacent to a grassy lot. The front yard contains plants and foundation plantings and is bounded by a milled point metal fence. A brick walkway extends from the sidewalk to the main and basement entrances. The property extends east to a narrow brick alley and the backyard is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	



Structure Component	Material	Feature	Source
<b>Foundation</b>	<b>Concrete</b>		
<b>Walls</b>	<b>Brick</b>		
Materials Notes:			

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1</b>	<b>Wood</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Pamels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**  
File: **643\_8th\_Street\_NE\_facade\_looking\_NE.JPG**  
Date:: Photog:  
Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 643\_8th\_Street\_NE\_facade\_looking\_SE(2).JP  
G

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 643\_8th\_Street\_NE\_rear\_looking\_NW.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1897	0985	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0822**

## BASICS DATA

ID Number: **0913-0822** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>641</b>	<b>-641B</b>	<b>8th Street</b>	<b>NE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 641 8th Street, N.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>0913/0822</b>			<b>Square/Lot</b>	<b>Current</b>
<b>0913/0109</b>			<b>Square/Lot</b>	<b>Historic</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Original</b>
<b>Residential (Multi-Family)</b>					<b>Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2500 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 3)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Canted Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2.5 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **48**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897, this two-and-a-half-story, two-bay rowhouse is one of ten similar dwellings constructed by Melton & Watts from the same permit (#0985). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling is set on a solid concrete foundation with a course, rock-faced stone veneer. The façade (west elevation) of this brick structure has stretcher coursing. A sloped roof is obscured by a false mansard of slate shingles. The heavy metal cornice has scrolled molding and decorative modillions. An interior brick chimney pierces the roof. The façade features a two-story, three-sided, canted projecting bay. Located above the overhanging eaves of the projecting bay is a pyramidal roof covered with slate shingles and capped by a metal finial. The bay has a boxed metal cornice with ornamental molding. The façade features a molded concrete sill course along the first-story window openings. The second-story window openings feature a molded metal architrave extending at sill level. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows and single-light clerestory windows. The first-story window openings have three-course, rowlock brick segmental arches. The second-story window opening on the main block has a rowlock brick segmental arch. The second-story window openings on the projecting bay have a wide lintel string course. The main entry comprises a vestibule with a single-leaf, paneled wood door with lights accessed by a double-leaf, metal security door. The exterior door has a single-light transom with a three-course rowlock brick segmental arch. The door is accessed by metal stairs with scrolling metal hand rails. A single-leaf wood French door pierces the foundation below the metal stairs. The foundation is further pierced by 1/1, double-hung, vinyl-sash and a one-light vinyl awning window with a rock-faced stone lintel.

The rear (east) elevation is fenestrated by 1/1, double-hung, vinyl-sash windows with two-course rowlock brick segmental arches. The rear elevation also features a two-story, two-bay ell. This brick structure has been parged and is capped by a shed roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows. A single-leaf door opening with single-light transom is located on the first story.

Site Notes:

**March 2010:** This rowhouse is located east of 8th Street, N.E. and is set back from the brick sidewalk approximately ten feet. The dwelling is adjacent to 639 and 643 8th Street, N.E. The front yard contains plants and foundation plantings and is bounded by a milled point metal fence. A concrete walkway extends from the sidewalk to the main and basement entrances. The property extends east to a narrow brick alley and the backyard is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	



Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Sliding</b>	<b>2 Lite</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Pamels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood/Glass</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 641-  
641B\_8th\_Street\_NE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 641-  
641B\_8th\_Street\_NE\_facade\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 641-  
641B\_8th\_Street\_NE\_rear\_looking\_NW.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1897	0985	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0821**

## BASICS DATA

ID Number: **0913-0821** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>639</b>	<b>-639B</b>	<b>8th Street</b>	<b>NE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 639 8th Street, N.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>0913/0821</b>			<b>Square/Lot</b>	<b>Current</b>
<b>0913/0108</b>			<b>Square/Lot</b>	<b>Historic</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Original</b>
<b>Residential (Multi-Family)</b>					<b>Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2500 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 3)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Bldg (Rect. Bay)**  
Footprint: **L-Shaped**

Number Stories: **2 plus basement**  
Bays Wide: **2**

Height: **17**  
Width: **48**  
Depth/Length: **48**

SqFt:  
Volume:  
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897, this two-story, two-bay single-family rowhouse is one of ten similar dwellings constructed by Melton & Watts from the same permit (#0985). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling is set on a solid concrete foundation with a course, rock-faced stone veneer. The façade (west elevation) of this brick structure is faced with stretcher-bond brick. The dwelling is capped by a sloped roof that is complemented by a molded metal cornice and brick corbelling. The façade features a molded concrete sill course extending across the first story and a molded metal architrave below the second-story openings. A two-story rectangular projecting bay is located on the southern bay of the façade. Window openings on the façade hold single and paired 1/1, double-hung, vinyl-sash with either two- or three-course, rowlock brick segmental arches. The second-story window openings have one-light transoms. The foundation is pierced by 1/1, double-hung, vinyl-sash windows with rock-faced stone linels. The main entry holds a double-leaf wood-frame glass door with a one-light transom and a three-course rowlock brick segmental arch. Bead molding separates the door from the transom. An interior entryway holds a single-leaf paneled wood door. This entry is accessed via metal steps with metal hand rails. The basement door opening below the metal steps holds a single-leaf, wood-frame glass door.

The rear (east) elevation is fenestrated by 1/1, double-hung, vinyl-sash windows with wood sills and two-course rowlock brick segmental arches. A two-story, two-bay brick ell is located on the rear elevation. This brick structure is capped by a sloped roof and pierced by 1/1, double-hung, vinyl-sash windows with rowlock brick sills and two-course, rowlock brick segmental arches.

Site Notes:

**March 2010:** This rowhouse is located east of 8th Street, N.E. and is set back from the brick sidewalk approximately ten feet. The dwelling is adjacent to 637 and 641 8th Street, N.E. The front yard contains brick retaining walls and is bounded by a milled point metal fence. A brick walkway extends from the sidewalk to the main and basement entrances. The property extends east to a narrow brick alley and the backyard is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Bluestone</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			



**Walls** **Brick**

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>DbI-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>DbI-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Full Glass</b>	<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Recessed</b>	<b>Paneled</b>	<b>Wood</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**  
File: **639-  
639B\_8th\_Street\_NE\_facade\_looking\_NE.JPG**  
Date:: Photog:  
Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 639-  
639B\_8th\_Street\_NE\_facade\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 639\_8th\_Street\_NE\_rear\_looking\_NW.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1897	0985	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0820**

## BASICS DATA

ID Number: **0913-0820** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>637</b>		<b>8th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 637 8th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0820</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

<b>0913/0107</b>			<b>Square/Lot</b>	<b>Historic</b>
------------------	--	--	-------------------	-----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>4250 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Hall, L.F.</b>
--------------------------	--------------	-------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Row (1 of 5)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Row Building/Canted Bay**  
 Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **3 plus basement**  
 Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this three-story, two-bay single-family rowhouse is one of five similar dwellings constructed by Melton & Watts from the same permit (#0024). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a rear ell. Set on a solid concrete foundation with a coursed, rock-faced stone veneer, the façade (west elevation) of this brick structure has stretcher-bond brick coursing that is partially parged. A sloped roof is obscured by a false mansard of slate shingles with a molded metal cornice. The mansard roof is pierced by a front-gabled pedimented wall dormer with slate shingles. The dormer highlights a 1/1, double-hung, vinyl-sash window. Projecting from the façade is a full-height canted bay. Extending higher than the main roof line, the projecting bay features a molded metal cornice with a hammered metal frieze below. Atop the projecting bay is a pyramidal roof of slate shingles adorned with a small metal finial. Molded metal architraves extend below the second- and third-story openings, and a string course of dentils runs below the architrave on the third story of the main block. Molded brick courses also span the projecting bay between the second- and third-story openings. A single-leaf paneled wood door is located in the northernmost bay on the foundation level. A double-leaf paneled wood door with lights pierces the first story in the northernmost bay. The entry is highlighted by a one-light transom and a rock-faced stone lintel with impostes. The door is accessed by brick steps with metal hand rails. The west elevation of the projecting bay holds a one-light fixed window on the first story. All other openings on the façade hold 1/1, double-hung, vinyl-sash windows. A molded concrete sill course is located below the openings on the first story. An opening on the second story of the main block is set in a round-headed opening with a three-course rowlock brick semicircular arch.

The rear (east) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows with one- and two-course rowlock brick segmental arches. A metal chimney is located on this elevation. A two-story brick hyphen connects the main block to a one-story brick ell, both original. The hyphen has a shed roof. The ell also has a shed roof and is fenestrated with 1/1, double-hung, vinyl-sash windows and a single-leaf door; all openings have two-course rowlock brick segmental arches. A wood deck with square wood balusters projects from the east elevation of the ell, and a patio with metal balusters is located on the roof of the ell.

Site Notes:

**March 2010:** This rowhouse is located east of 8th Street, N.E. and is set back from the brick sidewalk approximately ten feet. The dwelling is adjacent to 635 and 639 8th Street, N.E. The front yard contains small plants and is bounded by a metal picket fence. A brick walkway extends from the sidewalk to the main and basement entrances. The property extends east to a narrow brick alley and there is a small backyard.

## NOTABLE FEATURES DATA

Component	Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	



<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>Unknown</b>	<b>Unknown</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Paneled</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

## Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **637\_8th\_Street\_NE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 637\_8th\_Street\_NE\_facade\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 637\_8th\_Street\_NE\_rear\_looking\_W.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/06/1896	0024	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0819**

## BASICS DATA

ID Number: **0913-0819** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>635</b>		<b>8th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 635 8th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0819</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

<b>0913/0106</b>			<b>Square/Lot</b>	<b>Historic</b>
------------------	--	--	-------------------	-----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>4250 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Hall, L.F.</b>
--------------------------	--------------	-------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 5)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Bldg (Rect. Bay)**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **3 plus basement**  
Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this three-story, two-bay, single-family rowhouse is one of five similar dwellings constructed by Melton & Watts from the same permit (#0024). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a rear ell. Set on a solid concrete and brick foundation with a coursed, rock-faced stone veneer, the façade (west elevation) of this brick structure has Roman brick coursing. A sloped roof is obscured by a false mansard of slate shingles with a molded metal cornice. The mansard roof is pierced by a front-gabled pedimented wall dormer with slate shingles in the northernmost bay. The dormer highlights a 1/1, double-hung, vinyl-sash window. A pyramidal roof of slate shingles adorned with a small metal finial also pierces the mansard in the southern end bay. The roof has a complementary molded metal cornice and a hammered metal lintel course. Projecting from the façade is a two-story rectangular bay that features a flat roof with a wide hammered metal frieze. Molded metal architraves extend below the second- and third-story openings, and a dentil course runs below the architrave on the third story. A single-leaf paneled wood door is located in the northernmost bay on the foundation level. An opening in the northernmost bay of the first story holds a double-leaf wood-frame door with a one-light transom and a three-course rowlock brick segmental arch with molded brick accents. This exterior door leads to a recessed single-leaf paneled wood door. The entry is accessed by brick steps with metal hand rails. The second story of the northernmost bay holds a 1/1, double-hung, vinyl-sash window with a one-light semicircular transom. This opening is highlighted by a three-course rowlock brick semicircular arch. All other openings on the façade hold single or paired 1/1, double-hung, vinyl-sash windows. Openings on the first story have 6/6 or 9/9 false muntins, one-light transoms, concrete sills that merge with a concrete sill course, and three-course rowlock brick segmental arches. The foundation is pierced by 1/1, double-hung, vinyl-sash windows with splayed stone arches. On the third story, a single-leaf wood French door allows access to the roof of the projecting bay, which is encircled by metal balusters.

The rear (east) elevation is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows. All openings are highlighted by one- or two-course rowlock brick segmental arches. A two-story brick hyphen connects the main block to a one-story brick ell, both original. The hyphen has a shed roof. The ell also has a shed roof and the foundation has been parged. The east elevation is fenestrated with a 1/1, double-hung, vinyl-sash window with a metal-clad sill. A single-leaf door opening has been infilled with brick; both openings have two-course rowlock brick segmental arches. A wood deck with square wood posts and balusters is located atop the ell.

Site Notes:

**March 2010:** This rowhouse is located east of 8th Street, N.E. and is set back from the brick sidewalk approximately ten feet. The dwelling is adjacent to 633 and 637 8th Street, N.E. The dirt-filled front yard is bounded by a brick retaining wall. A brick walkway extends from the sidewalk to the main and basement entrances. The property extends east to a narrow brick alley and the backyard is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA



Roof Component	Material	Color	Treatment	Source
<b>Mansard (False) Sloped</b>	<b>Slate Not Visible</b>		<b>Shingled Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Roman Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation Walls</b>	<b>Concrete Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Recessed</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research  
Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **635\_8th\_Street\_NE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 635\_8th\_Street\_NE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 635\_8th\_Street\_NE\_rear\_looking\_NW(2).JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/06/1896	0024	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

---

Code	Criteria
------	----------

---



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0818**

## BASICS DATA

ID Number: **0913-0818** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>633</b>		<b>8th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 633 8th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0818</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

<b>0913/0105</b>			<b>Square/Lot</b>	<b>Historic</b>
------------------	--	--	-------------------	-----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>4250 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Hall, L.F.</b>
--------------------------	--------------	-------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 5)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Canted Bay**  
Footprint: **L-Shaped**

Number Stories: **3 plus basement**  
Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this three-story, two-bay single-family rowhouse is one of five similar dwellings constructed by Melton & Watts from the same permit (#0024). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a rear ell. Set on a solid concrete foundation with a coursed, rock-faced stone veneer, the façade (west elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of slate shingles with a molded metal cornice. The mansard roof is pierced by a front-gabled pedimented wall dormer with slate shingles. The dormer highlights a 1/1, double-hung, vinyl-sash window. Projecting from the façade is a full-height canted bay. Extending higher than the main roof line, the projecting bay features a molded metal cornice with a rock-faced frieze below. Atop the projecting bay is a pyramidal roof of slate shingles adorned with a small metal finial. Molded metal architraves extend below the second- and third-story openings, and a string course of dentils runs below the architrave on the third story of the main block. Molded brick courses also span the projecting bay between the second- and third-story openings. A single-leaf wood door with lights is located in the northernmost bay on the foundation level. A double-leaf wood-frame glass door pierces the first story in the northernmost bay. The entry is highlighted by a one-light transom and a rock-faced stone lintel with acanthus leaves that form a surround. The door is accessed by brick steps with metal hand rails. The west elevation of the projecting bay holds a one-light fixed window on the first story. All other openings on the façade hold 1/1, double-hung, vinyl-sash windows. An opening on the second story of the main block is set in a round-headed opening with a three-course rowlock brick semicircular arch.

The rear (east) elevation is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows. The elongated openings on the first story have one-light transoms. All openings are highlighted by one- or two-course rowlock brick segmental arches. A two-story brick hyphen connects the main block to a one-story brick ell, both original. The hyphen has a shed roof. The ell also has a shed roof and is fenestrated with 1/1, double-hung, vinyl-sash windows and a single-leaf paneled wood door with a one-light transom; all openings have two-course rowlock brick segmental arches. A wood deck with square wood balusters projects from the east elevation of the ell.

Site Notes:

**March 2010:** This rowhouse is located east of 8th Street, N.E. and is set back from the brick sidewalk approximately ten feet. The dwelling is adjacent to 631 and 635 8th Street, N.E. The front yard has been infilled with gravel and is enclosed by a milled point metal fence. A brick walkway extends from the sidewalk to the main and basement entrances. The property extends east to a narrow brick alley and the backyard is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Shingled	



<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood/Glass</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **633\_8th\_Street\_NE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 633\_8th\_Street\_NE\_facade\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 633\_8th\_Street\_NE\_rear\_looking\_NW.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/06/1896	0024	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0817**

## BASICS DATA

ID Number: **0913-0817** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>631</b>	<b>-631B</b>	<b>8th Street</b>	<b>NE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 631 8th Street, N.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>0913/0817</b>			<b>Square/Lot</b>	<b>Current</b>
<b>0913/0104</b>			<b>Square/Lot</b>	<b>Historic</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
<b>Residential (Multi-Family)</b>					<b>Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>4250 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Hall, L.F.</b>

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 5)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Bldg (Rect. Bay)**  
Footprint: **L-Shaped**

Number Stories: **3 plus basement**  
Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this three-story, two-bay, single-family rowhouse is one of five similar dwellings constructed by Melton & Watts from the same permit (#0024). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a rear ell. Set on a solid concrete and brick foundation with a coursed, rock-faced veneer, the façade (west elevation) of this brick structure has Roman brick coursing. A sloped roof is obscured by a false mansard of slate shingles with a molded metal cornice. The mansard roof is pierced by a front-gabled pedimented wall dormer with slate shingles in the northernmost bay. The dormer highlights a one-light vinyl casement window. A pyramidal roof of slate shingles adorned with a small metal finial also pierces the mansard in the southern end bay. The roof has a complementary molded metal cornice and a rock-faced lintel course. Projecting from the façade is a two-story rectangular bay that features a flat roof with a wide metal frieze. Molded metal architraves extend below the second- and third-story openings, and a metal string course runs below the architrave on the third story. A single-leaf paneled wood door is located in the northernmost bay on the foundation level. An opening in the northernmost bay of the first story has a three-course rowlock brick segmental arch with molded brick accents leads to a recessed single-leaf paneled wood door. The entry is accessed by metal steps with metal hand rails. The second story of the northernmost bay holds a two-leaf sliding vinyl window with a blind semicircular transom. This opening is highlighted by a three-course rowlock brick semicircular arch. All other openings on the façade hold single or triple wood casements. Openings on the first story have plain panels below and three-course rowlock brick segmental arches. On the third story, sliding metal-frame glass doors allow access to the roof of the projecting bay, which is encircled by metal balusters.

The rear (east) is fenestrated with double and triple wood awning windows. A two-story brick hyphen connects the main block to a one-story brick ell, both original. A one-story addition has been constructed on the roof of the ell; the entire rear elevation, including the main block, has been faced with German vinyl siding. The ell is fenestrated with single and triple wood awning windows and a single-leaf multi-light wood door. A wood deck is located atop the ell and is encircled by wood fencing.

Site Notes:

**March 2010:** This rowhouse is located east of 8th Street, N.E. and is set back from the brick sidewalk approximately ten feet. The dwelling is adjacent to 629 and 633 8th Street, N.E. The front yard has been paved with concrete and is enclosed by a brick retaining wall. A brick walkway extends from the sidewalk to the main and basement entrances. The property extends east to a narrow brick alley and the backyard is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Shingled	



<b>Sloped</b>	<b>Not Visible</b>	<b>Not Visible</b>		
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Roman Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Casement</b>	<b>1</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Sliding</b>	<b>2 Lite</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panel(s)	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
<b>Upper Story</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Metal</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**  
**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **631-  
631B\_8th\_Street\_NE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 631-  
631B\_8th\_Street\_NE\_facade\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 631\_8th\_Street\_NE\_rear\_looking\_NW.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/06/1896	0024	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0816**

## BASICS DATA

ID Number: **0913-0816** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>629</b>		<b>8th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 629 8th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0816</b>			<b>Square/Lot</b>	<b>Current</b>
<b>0913/0103</b>			<b>Square/Lot</b>	<b>Historic</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>4250 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Hall, L.F.</b>
--------------------------	--------------	-------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 5)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Canted Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **3 plus basement**  
Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this three-story, two-bay single-family rowhouse is one of five similar dwellings constructed by Melton & Watts from the same permit (#0024). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a rear ell. Set on a solid concrete foundation with a coursed, rock-faced stone veneer, the façade (west elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of slate shingles with a molded metal cornice. The mansard roof is pierced by a front-gabled pedimented wall dormer with slate shingles. The dormer highlights a 1/1, double-hung, vinyl-sash window. Projecting from the façade is a full-height canted bay. Extending higher than the main roof line, the projecting bay features a molded metal cornice with a rock-faced frieze below. Atop the projecting bay is a pyramidal roof of slate shingles adorned with a small metal finial. Molded metal architraves extend below the second- and third-story openings, and a string course of dentils runs below the architrave on the third story of the main block. Molded brick courses also span the projecting bay between the second- and third-story openings. A single-leaf metal-frame glass door is located in the northernmost bay on the foundation level. A double-leaf paneled wood door with lights pierces the first story of the façade in the northernmost bay. The entry is highlighted by a one-light transom and a rock-faced stone surround. Egg and reel molding divides the door and transom. The door is accessed by concrete steps with metal hand rails. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Openings on the first story have three-course rowlock brick segmental arches. Openings on the second story of the bay are highlighted by splayed brick lintels, and an opening on the second story of the main block is set in a round-headed opening with a three-course rowlock brick segmental arch. The foundation of the bay is pierced by a 1/1, double-hung, vinyl-sash window with a splayed stone lintel.

The rear (east) elevation is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows, some with false 6/6 muntins. A two-story brick hyphen connects the main block to a one-story brick ell, both original. The hyphen has a shed roof and the east elevation is faced with metal panels. The ell has a shed roof and is fenestrated with 1/1, double-hung, vinyl-sash windows with two-course rowlock brick segmental arches.

Site Notes:

**March 2010:** This rowhouse is located east of 8th Street, N.E. and is set back from the brick sidewalk approximately ten feet. The dwelling is adjacent to 627 and 631 8th Street, N.E. The front yard is planted with mature shrubs and foundation plantings and is enclosed by a metal bow and picket fence. A brick walkway extends from the sidewalk to the main and basement entrances. The property extends east to a narrow brick alley. The backyard is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Shingled	



<b>Sloped</b>	<b>Not Visible</b>	<b>Not Visible</b>
Wall Component	Material	Treatment
<b>Facade</b>	<b>Brick</b>	<b>Stretcher Bond</b>
Structure Component	Material	Source
<b>Foundation</b>	<b>Concrete</b>	
<b>Walls</b>	<b>Brick</b>	

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Full Glass</b>	<b>Metal</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Paneled</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 629\_8th\_Street\_NE\_facade\_looking\_NE.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 629\_8th\_Street\_NE\_facade\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 629\_8th\_Street\_NE\_rear\_looking\_NW.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/06/1896	0024	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0815**

## BASICS DATA

ID Number: **0913-0815** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>627</b>		<b>8th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Single Dwelling, 627 8th Street, N.E.</b>	<b>Common</b>
--	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0815</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

<b>0913/0102</b>			<b>Square/Lot</b>	<b>Historic</b>
------------------	--	--	-------------------	-----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>1800 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Armiger, George W. and John W.</b>	<b>Owner</b>	<b>Armiger, George W. and John W.</b>
---------------------------------------	--------------	---------------------------------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Woltz, Edward</b>
--------------------------	------------------	----------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Mennel, James</b>
--------------------------	----------------	----------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Bldg (Rect. Bay)**  
Footprint: **L-Shaped**

Number Stories: **2 plus basement**  
Bays Wide: **2**

Height:  
Width: **17**  
Depth/Length: **32**

SqFt:  
Volume:  
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897 by James Mennel, this two-story, two-bay Queen Anne-style single dwelling was influenced by the Italianate style. The dwelling was designed by Edward Woltz and was constructed from permit #0936. The dwelling is constructed of six-course, American-bond brick and is set on a solid concrete foundation. The façade (west elevation) is faced with pressed stretcher-bond brick. A sloping roof caps the dwelling and is complemented on the façade by a molded metal cornice, brick corbels, a molded brick string course, and a brick dentil string course. A four-course brick watertable is located above the foundation, which is pierced in the southern end bay by a single-leaf flush wood door. The foundation is also fenestrated with two-light sliding vinyl windows with stone sills and lintels. The southernmost bay on the first story holds a single-leaf paneled wood door with one light and a four-light wood transom with a stone lintel. The entrance is accessed by metal steps with gas pipe railings. Projecting from the façade is a full-height rectangular bay that features the same cornice found on the main block. All window openings on the façade hold replacement single or paired 1/1, double-hung, vinyl-sash windows and stone sills and lug lintels. Spandrel panels are located below the window openings.

The rear (west) elevation is fenestrated with a 1/1, double-hung, vinyl-sash windows with two-course rowlock brick segmental arches. A two-story, two-bay brick ell with a sloped roof projects from the southern bay of the rear elevation. The ell is fenestrated with 1/1, double-hung, vinyl-sash windows with header brick sills and two-course rowlock brick segmental arches.

Site Notes:

**March 2010:** This single dwelling is located east of 8th Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The dwelling is adjacent to 625 and 629 8th Street, N.E. The front yard is planted with mature shrubs and is enclosed by a metal fence. A brick walkway extends from the sidewalk to the main and basement entrances. The property extends east to a narrow brick alley. The backyard is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Pressed Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			



Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Sliding</b>	<b>2 Lite</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Pamels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 627\_8th\_Street\_NE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 627\_8th\_Street\_NE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 627\_8th\_Street\_NE\_rear\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/16/1897	0936	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

---

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0814**

## BASICS DATA

ID Number: **0913-0814** Year Built: **1881** Data Source: **Permit**

Number Extended Street Quad Type of Address

**625** **8th Street** **NE Current**

Name(s) Type of Name

**Single Dwelling, 625 8th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0814** **Square/Lot** **Current**

**0913/0101** **Square/Lot** **Historic**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1881** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1881** **Permit** **1120 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Price, W.**

**Orig Construction** **Owner** **Temple (Mary J.) et al.**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2010:** Constructed in 1881 by W. Price, this two-story, two-bay vernacular single-family rowhouse was influenced by the Italianate style. The dwelling is one of eight similar dwellings constructed by Price from the same permit (#0690). The dwelling is constructed of seven-course, American-bond brick and is set on a solid brick foundation. The façade (west elevation) is faced with stretcher-bond Roman brick. A sloping roof caps the dwelling and is complemented on the façade by a cornice composed of a dogtooth stringcourse, a molded metal architrave, a plain frieze, dentils, and a molded metal cornice. The southern end bay of the façade holds a single-leaf paneled wood door with a semicircular light and a one-light transom with a rusticated concrete-lug lintel. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows and have concrete sills and rusticated concrete-lug lintels. Three-course brick lintel courses span the façade below the window openings on both stories. The façade is pierced by a one-light window with a rusticated concrete-lug lintel.

The rear (west) elevation is fenestrated with a single-leaf wood door and 2/2, double-hung, wood-sash windows with wood sills and two-course rowlock brick segmental arches. A two-story, two-bay brick ell faced with stretcher-bond brick projects from the rear elevation. It is capped by a shed roof and is fenestrated by a single-leaf paneled wood door with a one-light transom and a soldier brick segmental arch. The ell is further fenestrated by 1/1, double-hung, vinyl-sash windows with concrete sills and soldier brick segmental arches. A wooden deck is located on the first story. It is encircled by square wood balusters.

Site Notes:

**March 2010:** This rowhouse is located east of 8th Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The dwelling is adjacent to 623 and 627 8th Street, N.E. The grassy front yard is planted with mature shrubs and is enclosed by a milled point metal fence. A brick walkway extends from the sidewalk to brick stairs at the main entrance. The property extends east to a narrow brick alley. The backyard is enclosed by metal chain link fencing.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Roman Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>1</b>	<b>Unknown</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:



## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\F&G Street - 2 to 11th**

**St\Database\Pictures\Square 0913\**

File: **625\_8th\_Street\_NE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\F&G Street - 2 to 11th**

**St\Database\Pictures\Square 0913\**

File: **625\_8th\_Street\_NE\_facade\_looking\_SE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\F&G Street - 2 to 11th**

**St\Database\Pictures\Square 0913\**

File: **625\_8th\_Street\_NE\_rear\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code

Roll

Frame(s)

Date

Photographer

Caption

## MISCELLANEOUS NOTES DATA

Notes:

--



## PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
12/31/1881	0690	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

## SIGNIFICANCE DATA

---

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0813**

## BASICS DATA

ID Number: **0913-0813** Year Built: **1898** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>623</b>		<b>8th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 623 8th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0813</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

<b>0913/0100</b>			<b>Square/Lot</b>	<b>Historic</b>
------------------	--	--	-------------------	-----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1898</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1898</b>	<b>Permit</b>			<b>2700 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Weller, M.C.</b>
--------------------------	------------------	---------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Thomas H.</b>
--------------------------	--------------	----------------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 3)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Bldg (Rect. Bay)**  
Footprint: **L-Shaped**

Number Stories: **2 plus basement**  
Bays Wide: **2**

Height: **17**  
Width: **17**  
Depth/Length: **30**

SqFt:  
Volume:  
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1898, this two-story, two-bay rowhouse is one of three similar rowhouses constructed by Melton and Watts from the same permit (#1004). Following the design of architect M.C. Weller, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete and brick foundation with a rock-faced concrete veneer, the façade (west elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of asphalt shingles with a metal cornice of scroll moldings and decorative modillions. An interior brick chimney pierces the roof. Projecting from the façade is a full-height rectangular bay capped by a front-gabled roof of asphalt shingles. The projecting bay features the same cornice found on the main block and a pressed metal frieze, raking concrete molding, and molded concrete corner pendants. Wood balusters are also located on the roof. The façade includes a molded metal architrave below the second-story openings. Single and paired window openings hold 1/1, double-hung, vinyl-sash. The first-story window openings have concrete-lug lintels; the opening on the west elevation of the projecting bay features a molded cap. A rock-faced concrete sill course extends below the first-story openings of the projecting bay. The second-story window opening on the main block has a rowlock brick segmental arch. The main entry in the northernmost bay holds a single-leaf, paneled wood door with a full-height two-light sidelight. The opening is highlighted by a one-light transom and concrete-lug lintel. The foundation is pierced by a single-leaf paneled wood door.

The rear (east) elevation is fenestrated by 1/1, double-hung, vinyl-sash windows with metal-clad sills and two-course rowlock brick segmental arches. The two-story, two-bay rear ell has six-course, American-bond brick coursing and is capped by a shed roof. The roof is pierced by an interior-side brick chimney on the south elevation. Fenestration consists of 1/1, double-hung, vinyl-sash windows with wood sills and two-course, rowlock brick segmental arches. A single-leaf paneled wood door with lights is located on the east (rear) elevation of the ell. The door opening includes a single-light transom and a two-course, rowlock brick segmental arch. A wooden deck with wood balusters projects from the rear elevation of the ell.

Site Notes:

**March 2010:** This rowhouse is located east of 8th Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The dwelling is adjacent to 621 and 625 8th Street, N.E. The front yard is planted with small shrubs and foundation plantings and is enclosed by a milled point metal fence. A brick walkway extends from the sidewalk to brick stairs at the main and basement entrances. The property extends east to a narrow brick alley. The backyard is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Asphalt		Shingled	



<b>Sloped</b>	<b>Not Visible</b>	<b>Not Visible</b>
Wall Component	Material	Color
<b>Facade</b>	<b>Brick &amp; Stone</b>	<b>Stretcher Bond</b>
Structure Component	Material	Feature
<b>Foundation</b>	<b>Concrete &amp; Brick</b>	
<b>Walls</b>	<b>Brick &amp; Stone</b>	

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>1</b>	<b>Unknown</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Pamels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **623\_8th\_Street\_NE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 623\_8th\_Street\_NE\_facade\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 623\_8th\_Street\_NE\_rear\_looking\_NW.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
01/06/1898	1004	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0812**

## BASICS DATA

ID Number: **0913-0812** Year Built: **1898** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>621</b>		<b>8th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 621 8th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0812</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

<b>0913/0099</b>			<b>Square/Lot</b>	<b>Historic</b>
------------------	--	--	-------------------	-----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1898</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1898</b>	<b>Permit</b>			<b>2700 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Weller, M.C.</b>
--------------------------	------------------	---------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Thomas H.</b>
--------------------------	--------------	----------------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 3)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Bldg (Rect. Bay)**  
Footprint: **L-Shaped**

Number Stories: **2 plus basement**  
Bays Wide: **2**

Height: **17**  
Width: **30**  
Depth/Length: **30**

SqFt:  
Volume:  
Lot Width

Lot Depth/Length:  
Lot SqFt:  
Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1898, this two-story, two-bay rowhouse is one of three similar rowhouses constructed by Melton and Watts from the same permit (#1004). Following the design of architect M.C. Weller, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete and brick foundation with a rock-faced concrete veneer, the façade (west elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of asphalt shingles with a metal cornice of scroll moldings and decorative modillions. An interior brick chimney pierces the roof. Projecting from the façade is a full-height rectangular bay capped by a front-gabled roof of asphalt shingles. The projecting bay features the same cornice found on the main block on the side elevations and a wide concrete cornice on the west elevation, raking concrete molding, and molded concrete corner pendants. Wood balusters are also located on the roof. The façade includes a molded metal architrave below the second-story openings. Single and paired window openings hold one-light vinyl casement windows with false six-light muntins. The first-story window openings have concrete-lug lintels; the opening on the west elevation of the projecting bay features a molded cap. A rock-faced concrete sill course extends below the first-story openings of the projecting bay. Second-story bay openings have concrete lintels. The second-story window opening on the main block has a rowlock brick segmental arch. The main entry in the northernmost bay holds a single-leaf, paneled wood door with a molded wood surround. The opening is highlighted by a one-light transom and concrete-lug lintel. Openings on the foundation hold one-light wood windows and have concrete-lug lintels.

The rear (east) elevation is fenestrated by 2/2, double-hung, wood-sash windows and 1/1, double-hung, vinyl-sash windows. All openings feature wood sills and two-course rowlock brick segmental arches. A two-story, two-bay rear ell has six-course, American-bond brick coursing and is capped by a shed roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows with false 6/6 muntins, concrete or rowlock brick sills, and two-course, rowlock brick segmental arches. A single-leaf wood-frame glass door is located on the east (rear) elevation of the ell. The door opening includes a single-light transom and a two-course, rowlock brick segmental arch. A wooden deck with wood balusters projects from the rear elevation of the ell.

Site Notes:

**March 2010:** This rowhouse is located east of 8th Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The dwelling is adjacent to 619 and 623 8th Street, N.E. The front yard is planted with small shrubs and foundation plantings and is partially bordered by a brick retaining wall. A brick walkway extends from the sidewalk to brick stairs at the main entrance. The property extends east to a narrow brick alley. The backyard is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------



<b>Mansard (False) Sloped</b>	<b>Asphalt Not Visible</b>		<b>Shingled Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Pressed Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick &amp; Stone</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>1</b>	<b>Wood</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>

Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **621\_8th\_Street\_NE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 621\_8th\_Street\_NE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 621\_8th\_Street\_NE\_rear\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
01/06/1898	1004	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

---

Code	Criteria
------	----------

---



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0811**

## BASICS DATA

ID Number: **0913-0811** Year Built: **1898** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>619</b>		<b>8th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 619 8th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0811</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

<b>0913/0098</b>			<b>Square/Lot</b>	<b>Historic</b>
------------------	--	--	-------------------	-----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1898</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1898</b>	<b>Permit</b>			<b>2700 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Weller, M.C.</b>
--------------------------	------------------	---------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Thomas H.</b>
--------------------------	--------------	----------------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 3)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Bldg (Rect. Bay)**  
Footprint: **L-Shaped**

Number Stories: **2 plus basement**  
Bays Wide: **2**

Height: **17**  
Width: **17**  
Depth/Length: **30**

SqFt:  
Volume:  
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1898, this two-story, two-bay rowhouse is one of three similar rowhouses constructed by Melton and Watts from the same permit (#1004). Following the design of architect M.C. Weller, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete and brick foundation with a rock-faced concrete veneer, the façade (west elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of asphalt shingles with a metal cornice of scroll moldings and decorative modillions. An interior brick chimney pierces the roof. Projecting from the façade is a full-height rectangular bay capped by a front-gabled roof of asphalt shingles. The projecting bay features the same cornice found on the main block, raking concrete molding, and molded concrete corner pendants. The façade includes a molded concrete sill course extending across the first-story, which is offset by a molded metal architrave below the second-story openings. Single and paired window openings hold 1/1, double-hung, vinyl-sash. The first-story window openings have concrete-lug lintels; the opening on the west elevation of the projecting bay features a molded cap. The second-story window opening on the main block has a rowlock brick segmental arch. A rock-faced concrete lintel extends above the second-story openings of the projecting bay. The main entry in the northernmost bay holds a single-leaf, paneled wood door with a molded wood surround. The opening is highlighted by a one-light transom and concrete-lug lintel. Openings on the foundation level have been covered by wood lattice and have concrete-lug sills.

The two-story, two-bay rear ell has seven-course, American-bond brick coursing and is capped by a shed roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills and two-course, rowlock brick segmental arches. A single-leaf, paneled metal door is located on the east (rear) elevation of the ell. The door opening includes a single-light transom and a two-course, rowlock brick segmental arch.

Site Notes:

**March 2010:** This rowhouse is located east of 8th Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The dwelling is adjacent to 617 and 621 8th Street, N.E. The front yard is planted with small shrubs and foundation plantings and is partially enclosed by a wood retaining wall. A brick walkway extends from the sidewalk to concrete stairs at the main entrance. The property extends east to a narrow brick alley. The backyard is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source



<b>Facade</b>	<b>Brick &amp; Stone</b>	<b>Stretcher Bond</b>
Structure Component	Material	Feature
<b>Foundation</b>	<b>Concrete &amp; Brick</b>	
<b>Walls</b>	<b>Brick &amp; Stone</b>	

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **619\_8th\_Street\_NE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 619\_8th\_Street\_NE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 619\_8th\_Street\_NE\_rear\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
01/06/1898	1004	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

---

Code	Criteria
------	----------

---



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0810**

## BASICS DATA

ID Number: **0913-0810** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>617</b>		<b>8th Street</b>	<b>NE</b>	<b>Permit</b>
------------	--	-------------------	-----------	---------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 617 8th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0810</b>			<b>Square/Lot</b>	<b>Current</b>
<b>0913/0097</b>			<b>Square/Lot</b>	<b>Historic</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>4250 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Lea, D.M.</b>
--------------------------	--------------	------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 5)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Canted Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **3 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this three-story, two-bay single-family rowhouse is one of five similar dwellings constructed by Melton & Watts from the same permit (#1961). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a rear ell. Set on a solid concrete and brick foundation with a coursed, rock-faced stone veneer, the façade (west elevation) of this brick structure has pressed stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of slate shingles with a molded metal cornice. The mansard roof is pierced by a front-gabled pedimented wall dormer with slate shingles. The dormer highlights a 1/1, double-hung, vinyl-sash window. Projecting from the façade is a full-height canted bay. Extending higher than the main roof line, the projecting bay features a molded metal cornice with a rock-faced lintel course below. Atop the projecting bay is a pyramidal roof of slate shingles adorned with a small metal finial. Molded metal architraves extend below the second- and third-story openings. A single-leaf metal door is located in the northernmost bay on the foundation level. A single-leaf wood-frame glass door pierces the first story of the façade in the northernmost bay. The entry is highlighted by wood surround and a rock-faced lintel. The door is accessed by concrete steps with metal hand rails. Window openings on the first story of the façade hold one-light, fixed windows, some with one-light transoms. These openings are highlighted by three-course rowlock brick segmental arches. The second and third stories are fenestrated with 1/1, double-hung, vinyl-sash. Openings on the second story of the bay are highlighted by splayed brick lintels, and an opening on the second story of the main block is set in a round-headed opening with a three-course rowlock brick semicircular arch. Molded brick string courses are located above the second story openings on the projecting bay, and a molded metal string course runs below the metal architrave on the third story of the main block. The foundation of the bay is pierced by two-light vinyl windows.

The rear (east) elevation is fenestrated with a single and paired 1/1, double-hung, vinyl-sash windows with concrete sills and two-course rowlock brick segmental arches. A single-leaf wood and glass door is located on the foundation level. A two-story brick hyphen connects the main block to a one-story brick ell, both original. These forms both have shed roofs. The ell is fenestrated with a single-light wood-frame glass door and paired casement windows, both with two-course rowlock brick segmental arches.

Site Notes:

**March 2010:** This rowhouse is located on the east side of 8th Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 615 and 619 8th Street, N.E. The small front yard is planted with mature shrubs and bounded by milled point metal fencing. A concrete walkway leads from the sidewalk and travels toward the primary and basement entrances. A small yard is located at the rear of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component

Material

Color

Treatment

Source



<b>Mansard (False) Sloped</b>	<b>Slate Not Visible</b>		<b>Shingled Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Metal</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **617\_8th\_Street\_NE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 617\_8th\_Street\_NE\_facade\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 617\_8th\_Street\_NE\_rear\_looking\_NW.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/30/1896	1961	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0809**

## BASICS DATA

ID Number: **0913-0809** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>615A</b>	<b>-615B</b>	<b>8th Street</b>	<b>NE</b>	<b>Current</b>
-------------	--------------	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 615 8th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0809</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

<b>0913/0096</b>			<b>Square/Lot</b>	<b>Historic</b>
------------------	--	--	-------------------	-----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>4250 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Lea, D.M.</b>
--------------------------	--------------	------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 5)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Bldg (Rect. Bay)**  
Footprint: **L-Shaped**

Number Stories: **3 plus basement**  
Bays Wide: **2**

Height: **17**  
Width: **17**  
Depth/Length: **32**

SqFt:  
Volume:  
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this three-story, two-bay, single-family rowhouse is one of five similar dwellings constructed by Melton & Watts from the same permit (#1961). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a rear ell. Set on a solid concrete and brick foundation with a coursed, rock-faced stone veneer, the façade (west elevation) of this brick structure has Roman brick coursing. A sloped roof is obscured by a false mansard of asphalt shingles with a molded metal cornice. The mansard roof is pierced by a front-gabled pedimented wall dormer with asphalt shingles in the northernmost bay. The dormer highlights a 1/1, double-hung, vinyl-sash window with false 6/6 muntins. A pyramidal roof of slate shingles also pierces the mansard in the southern end bay. The roof has a complementary molded metal cornice and a rock-faced lintel course. Projecting from the façade is a two-story rectangular bay that features a flat roof with a molded metal cornice and a wide lintel course below. A molded metal architrave extends below the second-story openings, and a concrete sill course runs below the first story openings. A single-leaf paneled door with lights is located in the northernmost bay on the foundation level. A two-leaf wood-frame glass door with a one-light transom and a three-course rowlock brick segmental arch leads to an interior single-leaf paneled wood door in the northernmost bay of the first story on the façade. The door is accessed by steps with metal hand rails. Window openings on the façade hold single or paired 1/1, double-hung, vinyl-sash with false 6/6 or 9/9 muntins. Openings on the first story have one-light transoms with false muntins and three-course rowlock brick segmental arches. An opening on the second story of the main block is set in a round-headed opening with a three-course rowlock brick semicircular arch and blind transom. On the third story, a two-leaf door with lights allow access to the roof of the projecting bay, which is encircled by turned metal balusters. The foundation of the bay is pierced by 1/1, double-hung, vinyl-sash windows with false 3/3 muntins and jack lintels.

The rear (east) is fenestrated with 1/1, double-hung, vinyl-sash windows with false 6/6 muntins and paired two-light sliding vinyl windows with six false muntins. A two-story brick hyphen connects the main block to a one-story brick ell, both original. The ell is fenestrated with 1/1, double-hung, vinyl-sash windows with false 9/9 muntins and two-course rowlock brick segmental arches. The southern end bay holds a single-leaf door with lights and a one-light transom with a two-course rowlock brick segmental arch. A one-story addition is located above the ell. This wood-frame structure is faced with German vinyl siding and is fenestrated with 1/1, double-hung, vinyl-sash windows with false 6/6 muntins. A wood deck sits atop the addition and is encircled by square wood posts and balusters.

Site Notes:

**March 2010:** This rowhouse is located on the east side of 8th Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 611 and 615 8th Street, N.E. The grassy front yard is bounded by milled point metal fencing with brick posts. A concrete walkway leads from the sidewalk and travels toward the primary and basement entrances. A small yard enclosed by wood privacy fencing is located at the rear of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA



Roof Component	Material	Color	Treatment	Source
<b>Mansard (False) Sloped</b>	<b>Asphalt Not Visible</b>		<b>Shingled Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Roman Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation Walls</b>	<b>Concrete &amp; Brick Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Metal/Glas</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Recessed</b>	<b>Paneled</b>	<b>Wood</b>
<b>Upper Story</b>	<b>Rectangular</b>	<b>Double</b>		<b>Unknown w/Lights</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research  
Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **615\_8th\_Street\_NE\_rear\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 615A-  
615B\_8th\_Street\_NE\_facade\_looking\_NE.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 615A-  
615B\_8th\_Street\_NE\_facade\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/30/1896	1961	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0808**

## BASICS DATA

ID Number: **0913-0808** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>613</b>		<b>8th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 613 8th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0808</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

<b>0913/0095</b>			<b>Square/Lot</b>	<b>Historic</b>
------------------	--	--	-------------------	-----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>4250 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Lea, D.M.</b>
--------------------------	--------------	------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 5)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Canted Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **3 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this three-story, two-bay single-family rowhouse is one of five similar dwellings constructed by Melton & Watts from the same permit (#1961). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a rear ell. Set on a solid concrete and brick foundation with a coursed, rock-faced stone veneer, the façade (west elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of slate shingles with a molded metal cornice. The mansard roof is pierced by a front-gabled pedimented wall dormer with slate shingles. The dormer highlights a 1/1, double-hung, vinyl-sash window. Projecting from the façade is a full-height canted bay. Extending higher than the main roof line, the projecting bay features a molded metal cornice with a rock-faced lintel course below. Atop the projecting bay is a pyramidal roof of slate shingles adorned with a small metal finial. Molded metal architraves extend below the second- and third-story openings. A single-leaf wood French door is located in the northernmost bay on the foundation level. A single-leaf paneled metal door pierces the first story of the façade in the northernmost bay. The entry is highlighted by a one-light transom and a rock-faced surround. The door is accessed by concrete steps with metal hand rails. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Openings on the first story have one-light transoms and three-course rowlock brick segmental arches. Openings on the second story of the bay are highlighted by splayed brick lintels, and an opening on the second story of the main block is set in a round-headed opening. The foundation of the bay is pierced by two-light vinyl sliding windows.

The rear (east) elevation is fenestrated with a single and paired 1/1, double-hung, vinyl-sash windows with concrete sills and two-course rowlock brick segmental arches. A two-story brick hyphen connects the main block to a one-story brick ell, both original. A third story has been added to the hyphen, which is faced with vinyl siding. The ell has a shed roof and is fenestrated with 1/1, double-hung, vinyl-sash windows with header brick sills and two-course rowlock brick segmental arches.

Site Notes:

**March 2010:** This rowhouse is located on the east side of 8th Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 611 and 615 8th Street, N.E. The grassy front yard is bounded by milled point metal fencing with brick posts. A concrete walkway leads from the sidewalk and travels toward the primary and basement entrances. A small yard enclosed by wood privacy fencing is located at the rear of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	



Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Sliding</b>	<b>2 Lite</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Pamels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood/Glass</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Metal/Glas</b>

Notable Interior Plan(s) \_\_\_\_\_ Notable Interior Feature(s) \_\_\_\_\_

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s) _____
Subdivision: _____	
Ward/ANC: _____	
Zoning: _____	Designation Event(s) _____
Contributing: _____	
Survey(s) _____	Level(s) of Investigation _____
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 613\_8th\_Street\_NE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 613\_8th\_Street\_NE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 613\_8th\_Street\_NE\_rear\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/30/1896	1961	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

---

Code	Criteria
------	----------

---



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0807**

## BASICS DATA

ID Number: **0913-0807** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>611</b>		<b>8th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 611 8th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0807</b>			<b>Square/Lot</b>	<b>Current</b>
<b>0913/0094</b>			<b>Square/Lot</b>	<b>Historic</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>4250 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Lea, D.M.</b>
--------------------------	--------------	------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Row (1 of 5)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Row Bldg (Rect. Bay)**  
 Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **3 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this three-story, two-bay, single-family rowhouse is one of five similar dwellings constructed by Melton & Watts from the same permit (#1961). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a rear ell. Set on a solid concrete and brick foundation with a coursed, rock-faced stone veneer, the façade (west elevation) of this brick structure has Roman brick coursing. A sloped roof is obscured by a false mansard of slate shingles with a molded metal cornice. The mansard roof is pierced by a front-gabled pedimented wall dormer with slate shingles in the northernmost bay. The dormer highlights a 1/1, double-hung, vinyl-sash window. A pyramidal roof of slate shingles adorned with a small metal finial also pierces the mansard in the southern end bay. The roof has a complementary molded metal cornice and a rock-faced lintel course. Projecting from the façade is a two-story rectangular bay that features a flat roof with a molded metal cornice and a rock-faced lintel course below. Molded metal architraves extend below the second- and third-story openings, and a metal string course runs below the architrave on the third story. A single-leaf paneled door with lights is located in the northernmost bay on the foundation level. A single-leaf paneled wood door pierces the first story of the façade in the northernmost bay. The entry is highlighted by a one-light transom and a three-course rowlock brick segmental arch. The door is accessed by brick steps with metal hand rails. Window openings on the façade hold single or paired 1/1, double-hung, vinyl-sash. Openings on the first story have one-light transoms and three-course rowlock brick segmental arches. An opening on the second story of the main block is set in a round-headed opening with a three-course rowlock brick semicircular arch. On the third story, a single-leaf wood door with lights allows access to the roof of the projecting bay. The foundation of the bay is pierced by one-light vinyl windows.

The rear (east) is fenestrated with 1/1, double-hung, vinyl-sash windows with one-course rowlock brick segmental arches. A two-story brick hyphen connects the main block to a one-story brick ell, both original. The hyphen has a shed roof and the ell has a shed roof that is pierced by an interior-side brick chimney. The ell is fenestrated with 1/1, double-hung, vinyl-sash windows with two-course rowlock brick segmental arches.

Site Notes:

**March 2010:** This rowhouse is located on the east side of 8th Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 609 and 613 8th Street, N.E. The front yard holds mature shrubs and trees and is bounded by milled point metal fencing with brick posts. A brick walkway leads from the sidewalk and travels toward the primary and basement entrances. A small yard enclosed by wood privacy fencing is located at the rear of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Shingled	



<b>Sloped</b>	<b>Not Visible</b>	<b>Not Visible</b>		
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Roman Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Pamels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
<b>Upper Story</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **611\_8th\_Street\_NE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 611\_8th\_Street\_NE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/30/1896	1961	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

---

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0806**

## BASICS DATA

ID Number: **0913-0806** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>609</b>		<b>8th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 609 8th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0806</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

<b>0913/0093</b>			<b>Square/Lot</b>	<b>Historic</b>
------------------	--	--	-------------------	-----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>4250 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
--------------------------	----------------	---------------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Lea, D.M.</b>
--------------------------	--------------	------------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 5)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Canted Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **3 plus basement**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this three-story, two-bay single-family rowhouse is one of five similar dwellings constructed by Melton & Watts from the same permit (#1961). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a rear ell. Set on a solid concrete and brick foundation with a coursed, rock-faced stone veneer, the façade (west elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of slate shingles with a molded metal cornice. The mansard roof is pierced by a front-gabled pedimented wall dormer with slate shingles. The dormer highlights a 1/1, double-hung, vinyl-sash window. Projecting from the façade is a full-height canted bay. Extending higher than the main roof line, the projecting bay features a molded metal cornice with a rock-faced lintel course below. Atop the projecting bay is a pyramidal roof of slate shingles adorned with a small metal finial. Molded metal architraves extend below the second- and third-story openings. A single-leaf wood door is located in the northernmost bay on the foundation level. A single-leaf wood French door pierces the first story of the façade in the northernmost bay. The entry is highlighted by a full-height, one-light sidelight, a one-light transom, and a rock-faced lug lintel with imposts. Egg and reel molding divides the door and transom. The door is accessed by brick steps with metal hand rails. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Openings on the first story have one-light transoms and three-course rowlock brick segmental arches. Openings on the second story of the bay are highlighted by splayed brick lintels, and an opening on the second story of the main block is set in a round-headed opening. The foundation of the bay is pierced by one-light vinyl awning windows.

The rear (east) elevation is partially parged and fenestrated with a single-leaf paneled door and 1/1, double-hung, vinyl-sash windows. A two-story brick hyphen connects the main block to a one-story brick ell, both original. The hyphen has a shed roof and the east elevation is faced with pressed stretcher-bond brick. The ell has a shed roof that is pierced by an interior-side brick chimney. The ell is fenestrated with 1/1, double-hung, vinyl-sash windows with two-course rowlock brick segmental arches.

Site Notes:

**March 2010:** This rowhouse is located on the east side of 8th Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 607 and 611 8th Street, N.E. The front yard holds sparse plantings and is bounded by bow and picket metal fencing. A brick walkway leads from the sidewalk and travels toward the primary and basement entrances. A small yard enclosed by wood privacy fencing is located at the rear of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	



Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete &amp; Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Awning</b>	<b>1</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Pamels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 609\_8th\_Street\_NE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 609\_8th\_Street\_NE\_facade\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 609\_8th\_Street\_NE\_rear\_looking\_NW.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/30/1896	1961	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0805**

## BASICS DATA

ID Number: **0913-0805** Year Built: **1898** Data Source: **Permit**

Number Extended Street Quad Type of Address

**607** **8th Street** **NE Current**

Name(s) Type of Name

**Single Dwelling, 607 8th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0805** **Square/Lot** **Current**

**0913/0092** **Square/Lot** **Historic**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1898** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1898** **Permit** **1900 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Melton & Watts**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide:

Height:

Width: **15**

Depth/Length: **29**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2010:** This two-story, three-bay Classical Revival-style single-family dwelling was constructed in 1898 by Melton and Watts (permit #1482). The dwelling is constructed of stretcher-bond brick and is set on a solid brick foundation. The façade (west elevation) is faced with pressed stretcher-bond brick. A sloping roof caps the dwelling and is complemented on the façade by an ogee-molded wood cornice with dentils. A parapet wall rises above the cornice and has posts and indented dentil molding. The northernmost bay on the first story holds a single-leaf paneled wood door with lights. This opening is highlighted by a one-light transom and a rusticated concrete lintel. The southern bay holds triple 9/9, double-hung, wood-sash windows. Recessed panels are located above and below the openings, and a molded wood architrave is located above the openings. The second story is fenestrated with 9/9, double-hung, wood-sash windows with concrete lintels. These openings have rusticated concrete sills that merge with the two-course brick sill course on the second story.

The rear (east) elevation holds a single-leaf wood door with lights with a one-light transom. The elevation is fenestrated with double-hung wood windows with two-course rowlock brick segmental arches. An enclosed porch is located on the second story. The porch is faced with vinyl siding and is capped by a shed roof. It is fenestrated with 1/1, double-hung, vinyl-sash windows.

Site Notes:

**March 2010:** This single dwelling is located on the east side of 8th Street, N.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 605.5 and 609 8th Street, N.E. The grassy front yard holds mature shrubs and foundation plantings and is bounded by bow and picket metal fencing. A brick walkway leads from the sidewalk and travels toward the primary entrance. A small yard enclosed by wood privacy fencing is located at the rear of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Pressed Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>9/9</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA



Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill F & G Streets (2010)**

Level(s) of Investigation

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\

File: 607\_8th\_Street\_NE\_facade\_looking\_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\

File: 607\_8th\_Street\_NE\_facade\_looking\_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\

File: 607\_8th\_Street\_NE\_rear\_looking\_NW.JPG

Date:: Photog:

Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA



Permit Issue Date	Number	Type	Remarks
04/19/1898	1482	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0804**

## BASICS DATA

ID Number: **0913-0804** Year Built: **1881** Data Source: **Permit**

Number Extended Street Quad Type of Address

**605.5** **8th Street** **NE Current**

Name(s) Type of Name

**Single Dwelling, 605.5 8th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0804** **Square/Lot** **Current**

**0913/0091** **Square/Lot** **Historic**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1881** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1881** **Permit** **1120 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Price, W.**

**Orig Construction** **Owner** **Temple (Mary J.) et al.**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

March 2010: Constructed in 1881 by W. Price, this two-story, two-bay vernacular single-family rowhouse was influenced by the Italianate style. The dwelling is one of eight similar dwellings constructed by Price from the same permit (#0690). The dwelling is constructed of seven-course, American-bond brick and is set on a solid brick foundation. A sloping roof caps the dwelling and is complemented on the façade (west elevation) by a cornice composed of a dogtooth stringcourse, brick corbels, and a checkerboard brick stringcourse. The northern end bay of the façade holds a single-leaf paneled wood door with lights and a wood surround with fluted pilasters capped by a swan's neck pediment. The entrance is accessed by brick steps. All window openings on the façade hold 6/6, double-hung, wood-sash windows and have rowlock brick sills and soldier brick segmental arched hoods. The rear (east) elevation is fenestrated with a single-leaf paneled wood door with lights and a one-light transom with a soldier brick lintel in the northernmost bay. The elevation is further fenestrated by 2/2 and 6/6, double-hung, wood-sash windows with concrete sills and one-course rowlock or soldier brick segmental arches.

Site Notes:

March 2010: This rowhouse is located on the east side of 8th Street, N.E. and is set back approximately thirty-five feet from the brick sidewalk. The dwelling is adjacent to 605 and 607 8th Street, N.E. The front yard contains grass and foundation plantings and is bounded by metal fencing with brick posts. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. A small yard enclosed by wood privacy fencing is located at the rear of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>6/6</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/District:

Tuesday, June 25, 2013

ID\_Number: 0913-0804 Page 2



ward/ANC:  
Zoning:  
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research  
Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 605.5\_8th\_Street\_NE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 605.5\_8th\_Street\_NE\_facade\_looking\_W.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 605.5\_8th\_Street\_NE\_rear\_looking\_W.JPG  
Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------



Permit Notes:

--

**BIBLIOGRAPHIC DATA**

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

--

**SIGNIFICANCE DATA**

---

Study Unit

--

Code	Criteria
------	----------

---

**DATA PROCESSING EVENTS DATA**

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0803**

## BASICS DATA

ID Number: **0913-0803** Year Built: **1881** Data Source: **Permit**

Number Extended Street Quad Type of Address

**605** **8th Street** **NE Current**

Name(s) Type of Name

**Single Dwelling, 605 8th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0803** **Square/Lot** **Current**

**0913/0090** **Square/Lot** **Historic**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1881** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1881** **Permit** **1120 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Price, W.**

**Orig Construction** **Owner** **Temple (Mary J.) et al.**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **4**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Vernacular

Exterior & Architectural Notes:

March 2010: Constructed in 1881 by W. Price, this two-story, four-bay vernacular single-family dwelling was influenced by the Italianate style. The building is one of eight similar dwellings constructed by Price from the same permit (#0690). The dwelling is constructed of seven-course, American-bond brick and is set on a solid brick foundation. A sloping roof caps the dwelling and is complemented on the façade (west elevation) by a cornice composed of a dogtooth stringcourse, brick corbels, and a checkerboard brick stringcourse. A central bay of the façade holds a single-leaf paneled wood door with a wood surround with fluted pilasters and capped by a swan's neck pediment. The entrance is accessed by brick steps. All window openings on the façade hold 6/6, double-hung, wood-sash windows and have rowlock brick sills and soldier brick segmental arched hoods. The rear (east) elevation is fenestrated with a single-leaf wood door with lights and a transom with a soldier brick segmental arch in the northernmost bay. The second story holds 1/1, double-hung, vinyl-sash windows with metal-clad sills and one-course rowlock brick segmental arches.

Site Notes:

March 2010: This single dwelling is located on the east side of 8th Street, N.E. and is set back approximately thirty-five feet from the brick sidewalk. The dwelling is adjacent to 603 and 605.5 8th Street, N.E. The front yard is landscaped with mature shrubs and trees and is bounded by metal fencing with brick posts. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. A small yard enclosed by wood privacy fencing is located at the rear of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>DbI-Hung</b>	<b>6/6</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:



Zoning:  
Contributing:  
  
Survey(s)  
**Capitol Hill F & G Streets (2010)**

Designation Event(s)  
  
Level(s) of Investigation  
**Permit Research**  
**Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 605\_8th\_Street\_NE\_facade\_looking\_E.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Undisplayable Image Format**

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 605\_8th\_Street\_NE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Undisplayable Image Format**

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 605\_8th\_Street\_NE\_rear\_looking\_W.JPG  
Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/31/1881	0690	Build	



Permit Notes:

--

### BIBLIOGRAPHIC DATA

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

--

### SIGNIFICANCE DATA

---

Study Unit

---

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0802**

## BASICS DATA

ID Number: **0913-0802** Year Built: **1897** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>603</b>	<b>-603B</b>	<b>8th Street</b>	<b>NE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Single Dwelling, 603 8th Street, N.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>0913/0802</b>			<b>Square/Lot</b>	<b>Current</b>
<b>0913/0089</b>			<b>Square/Lot</b>	<b>Historic</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1897</b>	<b>Permit</b>			<b>Original</b>
<b>Residential (Multi-Family)</b>					<b>Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1897</b>	<b>Permit</b>			<b>2500 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Melton &amp; Watts</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Attached**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Row Bldg (Rect. Bay)**  
 Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide:

Height:

Width: **17**

Depth/Length: **48**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1897, this two-story, two-bay single-family dwelling is one of ten similar dwellings constructed by Melton & Watts from the same permit (#0985). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling is set on a solid concrete foundation with a course, rock-faced stone veneer. The façade (west elevation) of this brick structure has been parged. The sloped roof is obscured by a false mansard roof of slate shingles with a molded metal cornice. The façade features a two-story projecting bay capped by a flat roof with brick parapet wall. The parapet wall has scroll molding, dentil molding, and corner pilasters. The façade features a molded concrete sill course extending across the first-story and a molded metal architrave below the second-story openings. Window openings on the façade hold single and paired 1/1, double-hung, vinyl-sash, some with false muntins, with either one- or three-course, rowlock brick segmental arches. The second-story window openings on the projecting bay have a wide lintel course of rock-faced concrete. The foundation is pierced by paired one-light vinyl sliding windows. The main entry holds a double-leaf paneled wood door with a one-light transom and a three-course rowlock brick segmental arch. This entry is accessed via metal steps with metal hand rails. The basement door opening holds a single-leaf, paneled metal door with lights. A two-story, two-bay ell is located on the east (rear) elevation. This brick structure is capped by a sloped roof and pierced by 1/1, double-hung, vinyl-sash windows with rowlock brick sills and two-course, rowlock brick segmental arches.

Site Notes:

**March 2010:** This single dwelling is located on the east side of 8th Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 800-802 F Street and 605 8th Street, N.E. The front yard is partially paved with brick and landscaped with mature shrubs; it is bounded by a milled point metal fence. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk.

## NOTABLE FEATURES DATA

Component Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			



Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Sliding</b>	<b>2 Lite</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Pamels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Metal/Glas</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**  
**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS**

**Databases\F&G Street - 2 to 11th**  
**St\Database\Pictures\Square 0913\**

File: **603-**

**603B\_8th\_Street\_NE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 603-  
603B\_8th\_Street\_NE\_rear\_looking\_SW.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 603\_8th\_Street\_NE\_facade\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1897	0985	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
4/15/2010	Litowitz (DDL), Dana	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Dayton (MSD), Maria	Record Created



# Resource All Data Report

**ID Number: 0913-0855**

## BASICS DATA

ID Number: **0913-0855** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>602</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 602 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0855</b>			<b>Square/Lot</b>	<b>Permit</b>
------------------	--	--	-------------------	---------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen buildings constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Row (1 of 19)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Row Building/Rectangular Bay**  
 Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**  
 Bays Wide: **2**  
 Height: **17**  
 Width: **17**  
 Depth/Length: **32**

Outbuilding Type

Contributing Status

SqFt:  
 Volume:  
 Lot Width  
 Lot Depth/Length:  
 Lot SqFt:  
 Acreage:  
 Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling is set on a solid concrete foundation with a rock-faced stone veneer. The façade (east elevation) of this brick structure is finished in Roman brick with stretcher coursing. A sloped roof is obscured by a false mansard of rubber shingles. A cornice with scrolled molding and decorative modillions completes the main roofline. An interior brick chimney pierces the roof. The façade features a two-story projecting bay capped by a flat roof with brick parapet wall. The parapet wall has scroll molding, crenellated ornamental molding, and corner pilasters with an acanthus ornamental plant motif. The façade features a rounded concrete sill course along the first-story window openings. The second-story window openings feature a molded metal architrave extending at sill level. The second-story window openings on the projecting bay also have a wide lintel course of rock-faced concrete. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows with 6/6 false muntins or 1/1, double-hung, vinyl-sash windows. The first-story window openings have three-course, rowlock brick segmental arches. This arch is replicated on the second story in the southern bay. The main entry is located in a recessed opening in the southern bay of the first story. A double-leaf, wood-frame glass door with one-light transom and single-light transom shelters a single-leaf, paneled wood door with single-light transom. A below-grade, secondary door opening is located below the metal stairs leading to the main entry. This opening holds a single-leaf, wood-frame glass door. The west (rear) elevation holds 1/1, double-hung, vinyl-sash windows set in segmental arches. A two-story, two-bay ell is located on the rear of the dwelling. The west (rear) elevation of the ell has been parged. Fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills and a single-leaf door opening with single-light transom.

Site Notes:

**March 2010:** This rowhouse is located west of 9th Street, N.E. and has a setback from the brick sidewalk of approximately fifteen feet. The raised front yard is enclosed by a hairpin and picket metal fence set on a concrete retaining wall. Mature trees and shrubs landscape the front yard. A brick walkway extends from the sidewalk to iron stairs. Concrete steps provide access to a secondary door opening located beneath the metal stairs. The backyard extends to the west. A wood deck has been constructed on the rear of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Roman Brick</b>		<b>Stretcher Bond</b>	



Structure Component	Material	Feature	Source
<b>Foundation</b>	<b>Concrete</b>		
<b>Walls</b>	<b>Brick</b>		

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>

Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Full Glass</b>	<b>Wood/Glass</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Wood/Glass</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Survey(s)

**Capitol Hill F & G Streets (2010)**

Historic District(s)

Designation Event(s)

Level(s) of Investigation

**Permit Research**

**Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0913\**

File: **602\_9th\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 602\_9th\_Street\_NE\_facade\_looking\_SW.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 602\_9th\_Street\_NE\_rear\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/31/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Weishar (P JW), Paul	Record Updated
3/19/2010	Weishar (P JW), Paul	Record Created



# Resource All Data Report

**ID Number: 0913-0854**

## BASICS DATA

ID Number: **0913-0854** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>604</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 604 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0854</b>			<b>Square/Lot</b>	<b>Permit</b>
------------------	--	--	-------------------	---------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Excellent**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen buildings constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 19)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Canted Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling is set on a solid concrete foundation with a rock-faced stone veneer. The façade (east elevation) of this brick structure has stretcher coursing. A sloped roof is obscured by a false mansard of slate shingles. The heavy metal cornice has scrolled molding and decorative modillions. An interior brick chimney pierces the roof. The façade features a two-story, three-sided projecting bay. Located above the overhanging eaves of the projecting bay is a pyramidal roof covered with slate shingles and capped by a metal finial. The façade features a rounded concrete sill course along the first-story window openings. The second-story window openings feature a molded metal architrave extending at sill level. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows, a single-light casement window, and single-light clerestory windows. The first-story window openings have three-course, rowlock brick segmental arches. The second-story window opening on the main block has a rowlock brick segmental arch. The second-story window openings on the projecting bay have a wide, rock-faced concrete lintel string course. The main entry comprises a vestibule with a single-leaf, paneled wood door and double-leaf, wood-frame glass door. Both doors have single-light transoms. The west (rear) elevation features a two-story, two-bay ell. This brick structure is capped by a shed roof with plain fascia board. Fenestration consists of 1/1, double-hung, vinyl-sash windows with rowlock brick sills and two-course, rowlock brick segmental arches. A single-leaf door opening with single-light transom also has a two-course, rowlock brick segmental arch.

Site Notes:

**March 2010:** This dwelling is located west of 9th Street, N.E. and has a setback of approximately fifteen feet from the brick sidewalk. The south (side) elevation is attached to 602 9th Street, N.E. while the north (side) elevation to 606 9th Street, N.E. The grassy front yard is enclosed by a bow and picket fence set on a molded concrete curb. A brick walkway extends from the sidewalk to an iron stair and deck. A secondary door opening is located beneath the stair. The property extends west to a narrow brick alley. Enclosed by a chain-link security fence, the backyard has been paved with flagstone. A metal staircase provides access to a first-story door opening.

## NOTABLE FEATURES DATA

Component Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Bay Roof</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	



Structure Component	Material	Feature	Source
<b>Foundation</b>	<b>Concrete</b>		
<b>Walls</b>	<b>Brick</b>		

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1-light</b>	<b>Unknown</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Casement</b>	<b>1-light</b>	<b>Unknown</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Unknown</b>
<b>Clerestory</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>1-light</b>	<b>Unknown</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Wood/Glass</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **604\_9th\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 604\_9th\_Street\_NE\_facade\_looking\_SW.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 604\_9th\_Street\_NE\_rear\_looking\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/31/2010	Dayton (MSD), Maria	Record Updated
3/24/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Weishar (PJW), Paul	Record Updated
3/19/2010	Weishar (PJW), Paul	Record Created



# Resource All Data Report

**ID Number: 0913-0848**

## BASICS DATA

ID Number: **0913-0848** Year Built: **1896** Data Source: **Permit**

Number Extended Street Quad Type of Address

**616** **9th Street** **NE Current**

Name(s) Type of Name

**Rowhouse, 616 9th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**0913/0848** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1896** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1896** **Permit** **2750 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Simmons, B. Stanley**

**Orig Construction** **Builder** **McGee, Inc.**

**Orig Construction** **Owner** **Pickford, Charles R.**

Construction Notes:

**One of nineteen rowhouses constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 19)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Oriel**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this vernacular dwelling is similar in style to 618 9th Street, N.E. These two dwellings are unique among the 19 dwellings constructed by McGee Inc from permit #1879. This dwelling has a rectangular form and a two-story rear ell. The dwelling is set on a solid concrete foundation and has a brick structure. The façade (east elevation) has multiple veneer materials. The foundation and first story have a coursed veneer of rock-faced stone. The top course of the stone veneer has rinceau molding. A wide band of concrete extends between the first and second stories. The second story has stretcher-bond coursing of Roman brick. The sloped roof is obscured by a brick parapet with metal coping. The north side of the parapet extends to form a brick column with corbeled brick pilasters. The basement is pierced by a six-light wood awning window, single-light vinyl awning window, and a single-leaf door opening. The southern bay of the first story holds a double-leaf, paneled wood door with single-light transom. The northern bay of the first story contains a single-light picture window topped by six-light awning windows. The first-story openings have concrete sills and rinceau-molded stone surrounds. The second story features a centrally placed oriel window with bands of acanthus, rinceau, egg-and-dart, and scrolled moldings in addition to molded architraves. A metal architrave extends across the façade and oriel to form a sill course for the paired, 1/1, double-hung, vinyl-sash windows with false muntins. The oriel is capped by a folded metal roof. This seven-course brick structure is capped by a shed roof and pierced by 1/1, double-hung, vinyl-sash windows with false muntins. The openings have concrete sills and two-course, rowlock brick segmental arches. A single-leaf, paneled wood door with four-light and single-light transom has also has a two-course, rowlock brick segmental arch.

Site Notes:

**March 2010:** This dwelling is located west of 9th Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The south (side) elevation is attached to 614 9th Street, N.E. and the north (side) elevation to 618 9th Street, N.E. The front yard is enclosed by a hairpin and picket metal fence. A mature tree dots the property. A concrete walkway extends from the sidewalk to concrete steps to the main entry. Concrete steps provide access to a secondary door located below grade. The property extends west to a narrow brick alley. The backyard is enclosed by a wood fence. Wood stairs lead to a small wood landing and access to the rear entry.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade (Lower)</b>	<b>Stone</b>		<b>Veneer</b>	
<b>Facade (Upper)</b>	<b>Roman Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>1 Flr Windows</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1-light</b>	<b>Unknown</b>
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Awning</b>	<b>1-light</b>	<b>Vinyl</b>
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Awning</b>	<b>6-light</b>	<b>Wood</b>
<b>Oriel</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Paneled</b>	<b>Wood</b>



Notable Interior Plan(s) \_\_\_\_\_

Notable Interior Feature(s) \_\_\_\_\_

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s) \_\_\_\_\_

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s) \_\_\_\_\_

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **616\_9th\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **616\_9th\_Street\_NE\_facade\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **616\_9th\_Street\_NE\_rear\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------



### MISCELLANEOUS NOTES DATA

---

Notes:

### PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

---

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

---

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/31/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	User (GU), Guest	Record Updated
3/19/2010	User (GU), Guest	Record Created



# Resource All Data Report

**ID Number: 0913-0853**

## BASICS DATA

ID Number: **0913-0853** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>606</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 606 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0853</b>			<b>Square/Lot</b>	<b>Permit</b>
------------------	--	--	-------------------	---------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Historic</b>
-----------------------------------	--	--	--	--	-----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen buildings constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 19)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Rectangular Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling is set on a solid concrete foundation with a rock-faced stone veneer. The façade (east elevation) of this brick structure has stretcher-bond brick veneer of Roman brick. A sloped roof is obscured by a false mansard of asphalt shingles. A metal cornice has scrolled molding and decorative modillions. An interior brick chimney pierces the roof. The façade features a two-story projecting bay capped by a front-gabled roof of asphalt shingles with metal finial. Supported architecturally by molded concrete corner pendants, a molded concrete balustrade extends through the front gable. A molded concrete sill course extends across the first-story and is offset by a molded metal architrave which extends below the second-story openings. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows. The first-story window openings have three-course, rowlock brick segmental arches. The second-story window opening on the main block has a rowlock brick segmental arch. A wide, rock-faced concrete lintel extends above second-story openings of the projecting bay. Located in the southern bay of the first story, the main entry holds a single-leaf wood door with lights. A metal awning shelters the door opening and obscures most of a three-course, rowlock brick segmental arch. The secondary door opening is located below grade and holds a single-leaf door. The west (rear) elevation features a two-story, two-bay ell. This brick structure has been clad in aluminum siding and is capped by a shed roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf wood door with single-light transom.

Site Notes:

**March 2010:** This dwelling is located west of 9th Street, N.E. and has a setback from the brick sidewalk of approximately fifteen feet. The south (side) elevation is attached to 604 9th Street, N.E. and the north (side) elevation to 608 9th Street, N.E. The level, grassy front yard is enclosed by a hairpin and picket metal fence. Mature shrubs line the dwelling's foundation and provide the only landscaping. A flagstone walkway extends from the sidewalk to an iron stair and deck providing access to the main entry. Concrete steps lead below the deck to a secondary door opening. The property extends west to a narrow brick alley. The backyard is enclosed by a chain-link security fence. Concrete steps provide access to a door opening on the rear of the dwelling.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Bay Roof</b>	<b>Asphalt</b>		<b>Shingled</b>	
<b>Mansard (False)</b>	<b>Asphalt</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source



Facade	Roman Brick	Stretcher Bond
Structure Component	Material	Feature
Foundation	Concrete	
Walls	Brick	

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl

Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single		Unknown
Main Door	Rectangular	Single		Wood/Glass

Notable Interior Plan(s) \_\_\_\_\_ Notable Interior Feature(s) \_\_\_\_\_

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s) _____
Subdivision: _____	
Ward/ANC: _____	
Zoning: _____	Designation Event(s) _____
Contributing: _____	
Survey(s) _____	Level(s) of Investigation _____
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 606\_9th\_Street\_NE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 606\_9th\_Street\_NE\_facade\_looking\_SW.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 606\_9th\_Street\_NE\_rear\_looking\_E.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/31/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Weishar (PJW), Paul	Record Updated
3/19/2010	Weishar (PJW), Paul	Record Created



# Resource All Data Report

**ID Number: 0913-0847**

## BASICS DATA

ID Number: **0913-0847** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>618</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 618 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0847</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen rowhouses constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 19)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Oriel**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this vernacular dwelling is similar in style to 616 9th Street, N.E. These two dwellings are unique among the 19 dwellings constructed by McGee Inc from permit #1879. This dwelling has a rectangular form and a two-story rear ell. The dwelling is set on a solid concrete foundation and has a brick structure. The first story of the façade (east elevation) has a coursed, rock-faced stone veneer accentuated by a rinceau-molded top course. The second story has a stretcher-bond brick veneer of Roman brick. A wide band of milled concrete extends between the first and second stories. A false mansard roof of asphalt shingles obscures a sloped roof. A prominent curvilinear brick parapet wall dominates the façade. The parapet has metal coping. Located along the south side of the elevation is a corbeled brick pilaster supporting a brick stack with molded overhanging eaves. The basement is pierced by single-light casement windows and a single-leaf door opening (not visible from the public right-of-way). The main entry is composed of a vestibule comprised of a single-leaf, paneled wood door and a double-leaf, metal-frame glass door. Paired 1/1, double-hung, vinyl-sash windows with false muntins flank the door opening to the north. The first-story openings have concrete sills and rinceau-molded stone surrounds. The second story features a centrally placed oriel window with bands of acanthus, rinceau, egg-and-dart, and scrolled moldings in addition to molded architraves. A metal architrave extends across the façade and oriel to form a sill course for the paired, 1/1, double-hung, vinyl-sash windows with false muntins. The oriel is capped by a folded metal roof. The west (rear) elevation features a two-story, two-bay ell. This seven-course brick structure is capped by a shed roof and pierced by 1/1, double-hung, vinyl-sash windows with concrete sills and two-course, rowlock brick segmental arches. The single-leaf French door with single-light transom has also has a two-course, rowlock brick segmental arch.

Site Notes:

**March 2010:** This dwelling is located west of 9th Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The south (side) elevation is attached to 616 9th Street, N.E. and the north (side) elevation to 620 9th Street, N.E. The front yard is enclosed by a hairpin and picket metal fence and includes mature shrubs and plantings. A concrete walkway extends from the sidewalk to stone-clad steps and the main entry. Concrete steps provide access to a secondary door located below grade. The property extends west to a narrow brick alley. The backyard is enclosed by a wood fence. Wood stairs lead to a small wood landing and access to the rear entry.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Asphalt</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source



<b>Facade (Lower)</b>	<b>Stone</b>	<b>Veneer</b>
<b>Facade (Upper)</b>	<b>Roman Brick</b>	<b>Stretcher Bond</b>
Structure Component	Material	Feature
<b>Foundation</b>	<b>Concrete</b>	
<b>Walls</b>	<b>Brick</b>	

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>1 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Casement</b>	<b>1-light</b>	<b>Unknown</b>
<b>Oriel</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Metal/Glas</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s) \_\_\_\_\_ Notable Interior Feature(s) \_\_\_\_\_

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s) _____
Subdivision: _____	
Ward/ANC: _____	
Zoning: _____	Designation Event(s) _____
Contributing: _____	
Survey(s) _____	Level(s) of Investigation _____
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **618\_9th\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: \_\_\_\_\_ Photog: \_\_\_\_\_

Code:: \_\_\_\_\_ R: \_\_\_\_\_ Fr: \_\_\_\_\_



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 618\_9th\_Street\_NE\_facade\_looking\_SW.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 618\_9th\_Street\_NE\_rear\_looking\_NE.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/31/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	User (GU), Guest	Record Updated
3/19/2010	User (GU), Guest	Record Created



# Resource All Data Report

**ID Number: 0913-0852**

## BASICS DATA

ID Number: **0913-0852** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>608</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 608 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0852</b>			<b>Square/Lot</b>	<b>Permit</b>
------------------	--	--	-------------------	---------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen buildings constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 19)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Canted Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling is set on a solid concrete foundation with a rock-faced stone veneer. The façade (east elevation) of this brick structure has stretcher coursing. A sloped roof is obscured by a false mansard of asphalt shingles. The metal cornice has scrolled molding and decorative modillions. An interior brick chimney pierces the roof. The façade features a two-story, projecting canted bay. Located above the overhanging eaves of the projecting bay is a pyramidal roof covered with slate shingles and capped by a metal finial. A molded concrete sill course extends across the first-story and is offset by a molded metal architrave which extends below the second-story openings. Window openings on the façade hold 1/1, double-hung, vinyl-sash and single-light clerestory windows. The first-story window openings have three-course, rowlock brick segmental arches. A wide, milled-faced concrete lintel extends above the second-story openings of the projecting bay. Located in the southern bay of the first story, the main entry holds a single-leaf wood door with lights. A metal awning shelters the door opening and obscures most of a three-course, rowlock brick segmental arch. The secondary door opening is located below grade and holds a single-leaf door. The west (rear) elevation features a two-story, two-bay ell. The west (rear) elevation of this brick structure has been parged. Fenestration includes 1/1, double-hung, vinyl-sash, two-light sliding, and a single-leaf, wood door. The door transom has been enclosed with wood.

A second-story window opening on the façade (east) elevation has been enclosed with brick. The rowlock brick segmental arch remains.

Site Notes:

**March 2010:** This dwelling is located west of 9th Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The south (side) elevation is attached to 606 9th Street, N.E. and the north (side) elevation to 610 9th Street, N.E. The level front yard is enclosed by a metal fence. A concrete walkway extends from the sidewalk to metal stairs and deck. Concrete steps located beneath the stairs provide access to a secondary door opening. The property extends west to a narrow brick alley. The backyard is enclosed by a chain-link security fence. A wood deck has been constructed on the first story of the rear elevation. A metal awning shelters the rear door opening.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Asphalt		Shingled	
Mansard (False)	Asphalt		Shingled	
Sloped	Not Visible		Not Visible	



Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Clerestory</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>16/6</b>	<b>Unknown</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **608\_9th\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 608\_9th\_Street\_NE\_facade\_looking\_SW.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 608\_9th\_Street\_NE\_rear\_looking\_NE.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/31/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Weishar (P JW), Paul	Record Updated
3/19/2010	Weishar (P JW), Paul	Record Created



# Resource All Data Report

**ID Number: 0913-0846**

## BASICS DATA

ID Number: **0913-0846** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>620</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 620 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0846</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen rowhouses constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 19)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Rectangular Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete foundation with a coursed, rock-faced stone veneer, the façade (east elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of slate shingles with a metal cornice of scroll moldings and decorative modillions. An interior brick chimney pierces the roof. Projecting from the façade is a full-height bay capped by a front-gabled roof of slate shingles. The projecting bay features the same cornice found on the main block to include raking concrete molding and molded corner pendants. The façade includes a molded concrete sill course extending across the first-story offset by a molded metal architrave below the second-story openings. Single and paired window openings hold 1/1, double-hung, vinyl-sash. The first-story window openings have three-course, rowlock brick segmental arches. The second-story window opening on the main block has a rowlock brick segmental arch. A wide, rock-faced concrete lintel extends above the second-story openings of the projecting bay. The main entry holds a single-leaf, paneled wood door with single-light transom. Coursed rock-faced stone surrounds the main entry. The secondary door opening is located below and holds a single-leaf wood door. The two-story, two-bay rear ell has seven-course, American-bond brick coursing and is capped by a shed roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills and two-course, rowlock brick segmental arches. A single-leaf wood door with single-light transom is located on the west (rear) elevation of the ell.

Site Notes:

**March 2010:** This dwelling is located west of 9th Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The south (side) elevation is attached to 618 9th Street, N.E. and the north (side) elevation to 622 9th Street, N.E. The front yard is enclosed by a chain-link fence set on concrete curbing. A concrete walkway extends from the sidewalk to a metal deck and the main entry. A metal awning shelters the main entry. Concrete steps provide access to a secondary door located below grade. The property extends west to a narrow brick alley. The backyard is enclosed by a chain-link fence. A metal porch has been affixed to the first story of the rear elevation. A metal awning shelters the first-story openings.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Bay Roof</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source



Facade	Brick	Stretcher Bond	
Structure Component	Material	Feature	Source
<b>Foundation</b>	<b>Concrete</b>		
<b>Walls</b>	<b>Brick</b>		

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>

Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s) \_\_\_\_\_ Notable Interior Feature(s) \_\_\_\_\_

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s) _____
Subdivision: _____	
Ward/ANC: _____	
Zoning: _____	Designation Event(s) _____
Contributing: _____	
Survey(s) _____	Level(s) of Investigation _____
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 620\_9th\_Street\_NE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 620\_9th\_Street\_NE\_facade\_looking\_SW.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 620\_9th\_Street\_NE\_rear\_looking\_NE.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/31/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	User (GU), Guest	Record Updated
3/19/2010	User (GU), Guest	Record Created



# Resource All Data Report

**ID Number: 0913-0851**

## BASICS DATA

ID Number: **0913-0851** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>610</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 610 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0851</b>			<b>Square/Lot</b>	<b>Permit</b>
------------------	--	--	-------------------	---------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen buildings constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Row (1 of 19)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Row Building/Rectangular Bay**  
 Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete foundation with a rock-faced stone veneer, the façade (east elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of tin shingles. A metal cornice has decorative modillions and a wide, plain frieze. An interior brick chimney pierces the roof. Projecting from the façade is a full-height bay. The bay has a brick parapet wall with crenelated molding and decorative pendants with acanthus molding. A molded concrete sill course extends across the first-story and is offset by a molded metal architrave which extends below the second-story openings. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows. The first-story window openings have three-course, rowlock brick segmental arches. The second-story window opening on the main block has a rowlock brick segmental arch. A wide, rock-faced concrete lintel extends above second-story openings of the projecting bay. Located in the southern bay of the first story, the main entry holds a single-leaf, paneled wood door with diamond-lights. A metal awning shelters the opening and obscures much of the three-course, rowlock brick segmental arch. The secondary door opening is located below grade and holds a single-leaf door. The two-story, two-bay rear ell has seven-course, American-bond brick coursing and is capped by a shed roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows with header sills and two-course, rowlock brick segmental arches. A single-leaf French door is located on the west (rear) elevation of the ell.

Site Notes:

**March 2010:** This dwelling is located west of 9th Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The south (side) elevation is attached to 608 9th Street, N.E. and the north (side) elevation to 612 9th Street, N.E. The level front yard is enclosed by a hairpin and picket metal fence. Mature shrubs dot the property. A brick walkway extends from the sidewalk to metal stairs and deck. Concrete steps located beneath the stairs provide access to a secondary door opening. The property extends west to a narrow brick alley. The backyard is enclosed by a chain-link security fence. A wood deck has been constructed on the first story of the rear elevation. A metal awning shelters the first-story openings.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Tin</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	



Structure Component	Material	Feature	Source
<b>Foundation</b>	<b>Concrete</b>		
<b>Walls</b>	<b>Brick</b>		
Materials Notes:			

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 610\_9th\_Street\_facade\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 610\_9th\_Street\_NE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 610\_9th\_Street\_NE\_rear\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

---

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

---

Code	Criteria
------	----------

---



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/31/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Weishar (P JW), Paul	Record Updated
3/19/2010	Weishar (P JW), Paul	Record Created



# Resource All Data Report

**ID Number: 0913-0845**

## BASICS DATA

ID Number: **0913-0845** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>622</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 622 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0845</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen rowhouses constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Row (1 of 19)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Row Building/Canted Bay**  
 Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete foundation, this brick structure is clad in Permastone. The sloped roof is obscured by a false mansard of asphalt shingles. A metal cornice has scroll moldings and decorative modillions. An interior brick chimney pierces the roof. Projecting from the façade is a full-height canted bay, also clad in Permastone. Extending higher than the main roof line, the projecting bay features clerestory windows and overhanging eaves replete with scrolled moldings. Atop the projecting bay is a pyramidal roof of asphalt shingles adorned with a metal globe. The façade features a molded concrete sill course extending across the first-story and a molded metal architrave below the second-story openings. Window openings on the façade hold 1/1, double-hung, vinyl-sash. The main entry holds a single-leaf, paneled wood door. The secondary door opening is located below and holds a single-leaf wood door. The west (rear) elevation of the dwelling has a two-story, two-bay ell. Fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills and two-course, rowlock brick segmental arches. A single-leaf wood door with square-light is located on the west (rear) elevation of the ell.

Site Notes:

**March 2010:** This dwelling is located west of 9th Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The south (side) elevation is attached to 620 9th Street, N.E. and the north (side) elevation to 624 9th Street, N.E. Mature shrubs line the brick sidewalk. The level front yard is covered with Astroturf and enclosed by a chain-link fence. Metal stairs and deck (both covered with Astroturf) provide access to the main entry. Concrete steps located beneath the stairs provide access to a secondary door opening. The property extends west to a narrow brick alley. The backyard is enclosed by a metal fence. A metal porch spans the width of the first story of the rear ell. This porch has concrete steps with metal railing, metal balusters, and a metal awning.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Bay Roof</b>	<b>Asphalt</b>		<b>Shingled</b>	
<b>Mansard (False)</b>	<b>Asbestos</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Permastone</b>		<b>Veneer</b>	
Structure Component	Material	Feature		Source



Foundation                      Concrete  
Walls                              Brick

Materials Notes:

--

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Clerestory</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>1-light</b>	<b>Unknown</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood:   **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path:   **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File:   **622\_9th\_Street\_NE\_facade\_looking\_NW.JPG**

Date::                      Photog:

Code::                      R:                      Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 622\_9th\_Street\_NE\_facade\_looking\_SW.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 622\_9th\_Street\_NE\_rear\_looking\_NE.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/31/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	User (GU), Guest	Record Updated
3/19/2010	User (GU), Guest	Record Created



# Resource All Data Report

**ID Number: 0913-0850**

## BASICS DATA

ID Number: **0913-0850** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>612</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 612 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0850</b>			<b>Square/Lot</b>	<b>Permit</b>
------------------	--	--	-------------------	---------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>			<b>Permit</b>	<b>Original</b>
------------------------------------	-------------	--	--	---------------	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen buildings constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 19)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Canted Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete foundation with a rock-faced stone veneer, the façade (east elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of slate shingles. A metal cornice has scroll moldings and decorative modillions. An interior brick chimney pierces the roof. Projecting from the façade is a full-height canted bay. Extending higher than the main roof line, the projecting bay features clerestory windows and overhanging eaves replete with scrolled moldings. Atop the projecting bay is a pyramidal roof of slate shingles adorned with a metal globe. A molded concrete sill course extends across the first-story and is offset by a molded metal architrave which extends below the second-story openings. Window openings on the façade hold 1/1, double-hung, vinyl-sash. A single-light vinyl-sash awning window pierces the foundation of the projecting bay. The first-story window openings have three-course, rowlock brick segmental arches. The second-story window opening on the main block has a rowlock brick segmental arch. A wide, milled-faced concrete lintel extends above the second-story openings of the projecting bay. The main entry comprises a vestibule with a single-leaf, paneled wood door and double-leaf, wood-frame glass door. Both doors have single-light transoms. The secondary door opening is located below and holds a single-leaf wood door. The two-story, two-bay rear ell has seven-course, American-bond brick coursing. A small percentage of the ell has been parged. A shed roof caps the ell. Fenestration consists of 1/1, double-hung, vinyl-sash windows with header sills and two-course, rowlock brick segmental arches. A single-leaf wood door is located on the west (rear) elevation of the ell. The door opening includes a single-light transom (covered with aluminum).

Site Notes:

**March 2010:** This dwelling is located west of 9th Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The south (side) elevation is attached to 610 9th Street, N.E. and the north (side) elevation to 614 9th Street, N.E. The level front yard is enclosed by decorative concrete block wall set between brick posts. A concrete walkway extends from the sidewalk to metal stairs and a deck sheltered by a metal awning. Concrete steps located beneath the stairs provide access to a secondary door opening. The property extends west to a narrow brick alley. The backyard is enclosed by a chain-link security fence. A wood deck has been constructed on the first story of the rear elevation.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Bay Roof</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	



Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Awning</b>	<b>1-light</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Clerestory</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>1-light</b>	<b>Unknown</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Double</b>	<b>Full Glass</b>	<b>Wood/Glass</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 612\_9th\_Street\_NE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 612\_9th\_Street\_NE\_facade\_looking\_SW.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 612\_9th\_Street\_NE\_rear\_looking\_NE.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/31/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Weishar (P JW), Paul	Record Updated
3/19/2010	Weishar (P JW), Paul	Record Created



# Resource All Data Report

**ID Number: 0913-0844**

## BASICS DATA

ID Number: **0913-0844** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>624</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 624 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0844</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen rowhouses constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Row (1 of 19)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Row Building/Rectangular Bay**  
 Footprint: **L-Shaped (irregular)**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling is set on a solid concrete foundation with a course, rock-faced stone veneer. The façade (east elevation) of this brick structure has stretcher-bond brick coursing. The sloped roof is obscured by a false mansard roof of slate shingles with a metal cornice of scrolled moldings and decorative modillions. An interior brick chimney pierces the roof. The façade features a two-story projecting bay capped by a flat roof with brick parapet wall. The parapet wall has scroll molding, crenellated ornamental molding, and corner pilasters with an acanthus ornamental plant motif. The façade features a molded concrete sill course extending across the first-story and a molded metal architrave below the second-story openings. Window openings on the façade hold 1/1, double-hung, vinyl-sash with either one- or three-course, rowlock brick segmental arches. The second-story window openings on the projecting bay have a wide lintel course of rock-faced concrete. Window openings on the façade hold 1/1, double-hung, vinyl-sash. The main entry is comprised of a vestibule composed of a single-leaf, paneled wood door and a single-leaf, metal-frame glass door; both with one-light transoms. The basement door opening holds a single-leaf, paneled wood door. A two-story, two-bay ell is located on the west (rear) elevation. This brick structure is capped by a shed roof and pierced by 1/1, double-hung, vinyl-sash windows. Window openings have concrete sills and two-course, rowlock brick segmental arches. A single-leaf, paneled wood door with lights is located on the west (rear) elevation of the ell.

Site Notes:

**March 2010:** This dwelling is located west of 9th Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The south (side) elevation is attached to 622 9th Street, N.E. and the north (side) elevation to 626 9th Street, N.E. The level front yard is enclosed by a chain-link fence set on a brick retaining wall. A concrete walkway extends from the sidewalk to concrete steps with metal railing to the main entry. Concrete steps located beneath the stairs provide access to a secondary door opening. The property extends west to a narrow brick alley. The backyard is enclosed by a metal fence. A metal porch spans the width of the first story of the rear ell. This porch has concrete steps with metal railing, metal balusters, and a metal awning.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Slate</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	



Structure Component	Material	Feature	Source
<b>Foundation</b>	<b>Concrete</b>		
<b>Walls</b>	<b>Brick</b>		
Materials Notes:			

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Full Glass</b>	<b>Metal/Glas</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**  
File: **624\_9th\_Street\_NE\_facade\_looking\_SW.JPG**  
Date:: Photog:  
Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 624\_9th\_Street\_NE\_facade\_looking\_W.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 624\_9th\_Street\_NE\_rear\_looking\_NE.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/31/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	User (GU), Guest	Record Updated
3/19/2010	User (GU), Guest	Record Created



# Resource All Data Report

**ID Number: 0913-0849**

## BASICS DATA

ID Number: **0913-0849** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>614</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 614 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0849</b>			<b>Square/Lot</b>	<b>Permit</b>
------------------	--	--	-------------------	---------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Original</b>
------------------------------------	-------------	---------------	--	--	-----------------

<b>Residential (Multi-Family)</b>					<b>Current</b>
-----------------------------------	--	--	--	--	----------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen buildings constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 19)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Rectangular Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide:

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete foundation with a rock-faced stone veneer, the façade (east elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of asphalt shingles with a metal cornice of scroll moldings and decorative modillions. An interior brick chimney pierces the roof. Projecting from the façade is a full-height bay capped by a front-gabled roof of asphalt shingles. The projecting bay features the same cornice found on the main block, raking concrete molding, and molded concrete corner pendants. The façade includes a molded concrete sill course extending across the first-story which is offset by a molded metal architrave below the second-story openings. Single and paired window openings hold 1/1, double-hung, vinyl-sash. The first-story window openings have three-course, rowlock brick segmental arches. The second-story window opening on the main block has a rowlock brick segmental arch. A wide, rock-faced concrete lintel extends above the second-story openings of the projecting bay. The main entry has been altered and enclosed to hold only a single-leaf, paneled wood door with light set in a fluted surround with bulls eye corner blocks. The secondary door opening is located below and holds a single-leaf, multi-light wood door. The two-story, two-bay rear ell has seven-course, American-bond brick coursing and is capped by a shed roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills and two-course, rowlock brick segmental arches. A single-leaf, paneled metal door with nine-lights is located on the west (rear) elevation of the ell. The door opening includes a single-light transom (enclosed with wood) and a two-course, rowlock brick segmental arch.

Site Notes:

**March 2010:** This dwelling is located west of 9th Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The south (side) elevation is attached to 612 9th Street, N.E. and the north (side) elevation to 614 9th Street, N.E. The front yard is partially enclosed by a hairpin and picket metal fence. A brick walkway extends from the sidewalk to metal stairs and a deck. Concrete steps located beneath the stairs provide access to a secondary door opening. The property extends west to a narrow brick alley. The backyard is enclosed by a chain-link security fence. A metal staircase provides access to the rear entry.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Bay Roof</b>	<b>Asphalt</b>		<b>Shingled</b>	
<b>Mansard (False)</b>	<b>Asphalt</b>		<b>Shingled</b>	
<b>Sloped</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source



Facade	Brick	Stretcher Bond
Structure Component	Material	Feature
Foundation	Concrete	
Walls	Brick	

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	10 Lite	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl

  

Door Location	Aperture Shape	Type	Panels	Material
Basement	Rectangular	Single		Wood/Glass
Main Door	Rectangular	Single	Paneled	Wood/Glass

  

Notable Interior Plan(s)	Notable Interior Feature(s)

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill F &amp; G Streets (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 614\_9th\_Street\_NE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 614\_9th\_Street\_NE\_facade\_looking\_SW.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 614\_9th\_Street\_NE\_rear\_looking\_NE.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/31/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	Weishar (PJW), Paul	Record Updated
3/19/2010	Weishar (PJW), Paul	Record Created



# Resource All Data Report

**ID Number: 0913-0843**

## BASICS DATA

ID Number: **0913-0843** Year Built: **1896** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>626</b>		<b>9th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	-------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Rowhouse, 626 9th Street, N.E.</b>	<b>Common</b>
---------------------------------------	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>0913/0843</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>1896</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Rear Addition</b>	<b>c. 1990</b>	<b>Site Visit/Map</b>			
----------------------	----------------	-----------------------	--	--	--

<b>Addition (Front)</b>	<b>c. 1990</b>	<b>Site Visit/Map</b>			
-------------------------	----------------	-----------------------	--	--	--

<b>Orig Construction</b>	<b>1896</b>	<b>Permit</b>			<b>2750 Permit</b>
--------------------------	-------------	---------------	--	--	--------------------

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

<b>Orig Construction</b>	<b>Architect</b>	<b>Simmons, B. Stanley</b>
--------------------------	------------------	----------------------------

<b>Orig Construction</b>	<b>Builder</b>	<b>McGee, Inc.</b>
--------------------------	----------------	--------------------

<b>Orig Construction</b>	<b>Owner</b>	<b>Pickford, Charles R.</b>
--------------------------	--------------	-----------------------------

Construction Notes:

**One of nineteen rowhouses constructed from the same permit (#1879).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 19)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Canted Bay**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Queen Anne**

Exterior & Architectural Notes:

**March 2010:** Constructed in 1896, this two-story, two-bay single-family dwelling was one of 19 similar dwellings constructed by McGee Inc. from the same permit (#1879). Following the design of architect B. Stanley Simmons, this Queen Anne-style dwelling has a rectangular form with a two-story rear ell. Set on a solid concrete foundation with a coursed, rock-faced stone veneer, the façade (east elevation) of this brick structure has stretcher-bond brick coursing. A sloped roof is obscured by a false mansard of asphalt shingles with a metal cornice of scroll moldings and decorative modillions. An interior brick chimney pierces the roof. Projecting from the façade is a full-height canted bay. Extending higher than the main roof line, the projecting bay features clerestory windows and overhanging eaves replete with scrolled moldings. Atop the projecting bay is a pyramidal roof of asphalt shingles adorned with a small metal globe. A molded concrete sill course extends across the first-story in harmony with a molded metal architrave which extends below the second-story openings. Window openings on the façade hold 1/1, double-hung, vinyl-sash. Jalousie window pierce the foundation of the projecting bay.

The main entry was not visible from the public right-of-way due to a façade addition. Based on its form and materials, this addition was completed c. 1990. The metal-frame addition encloses the area in front of the main opening located on the metal deck. The enclosure has jalousie windows and is capped by a metal awning. Metal awnings shelter the first-story window opening and span the width of the second story.

The west (rear) elevation of the main block has a two-story, two-bay ell. This seven-course, American-bond brick structure is capped by a shed roof and pierced by a 1/1, double-hung, vinyl-sash window. The first story of the west elevation of the ell has a full-width enclosed porch addition. Based on its form and materials, this metal-frame porch was constructed c. 1990. Jalousie windows and a metal awning complete the addition.

Site Notes:

**March 2010:** This dwelling is located west of 9th Street, N.E. and is set back from the brick sidewalk approximately fifteen feet. The south (side) elevation is attached to 624 9th Street, N.E. and the north (side) elevation to 628 9th Street, N.E. The level front yard is enclosed by a chain-link fence and includes immature shrubs. A brick walkway extends from the sidewalk the main entry. Concrete steps provide access to secondary door opening. The property extends west to a narrow brick alley. The backyard is enclosed by a chain-link security fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Bay Roof	Asphalt		Shingled	
Mansard (False)	Asphalt		Shingled	
Sloped	Not Visible		Not Visible	



Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Bay Windows</b>	<b>Rectangular</b>		<b>Multi-lite</b>	<b>Unknown</b>
<b>Bay Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Clerestory</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>1-light</b>	<b>Unknown</b>
<b>Porch/Enclosed</b>	<b>Rectangular</b>		<b>Multi-lite</b>	<b>Unknown</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill F & G Streets (2010)**

**Permit Research**

**Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

**Undisplayable Image Format**

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\**

File: **626\_9th\_Street\_NE\_facade\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 626\_9th\_Street\_NE\_facade\_looking\_SW.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\F&G Street - 2 to 11th  
St\Database\Pictures\Square 0913\  
File: 626\_9th\_Street\_NE\_rear\_looking\_NE.JPG

Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/18/1896	1879	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks
----------------	------	------	---------

Bibliographic Notes:

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



## DATA PROCESSING EVENTS DATA

---

Date	Individual	Action
3/31/2010	Dayton (MSD), Maria	Record Updated
3/19/2010	User (GU), Guest	Record Updated
3/19/2010	User (GU), Guest	Record Created



