ID	Num	her:	0960	-0053
	1 TUILL		U J U U	-0055

ID Number: 0960-00	53 Year Built	: 1876	Data Source:	Permit		
Number Extended S	treet		Quad Type of Ad	dress		
603 10	Oth Street		NE Current			
Name(s) Rowhouse, 603 10th Str	reet, N.E.	Type of N				
TaxCode1 TaxCode2	TaxCode3 Type	Explain				
0960/0053	Square/Lot	Current	<u> </u>			
STATUS/PURPOSE/U	ISE DATA					
Resource Type: Buildin	=		s Current: Extant			
Desig. Status: Historic Purpose: Rowho		Quali	-			
Purpose: Rowho	use	Cond	ition: Good			
Function/Use	Start	Source	Stop		Explain	
Residential (Single-Fam Residential (Multi-Famil		Permit			Original Current	
Nesidential (Maiti-1 anni	<i>y)</i>				Ourient	
CONSTRUCTION DAT	ГА					
Construction Event	Start So	urce S	Stop Source	Э	Cost Source	
Orig Construction	1876 Pe	rmit			2500 Permit	
Construction Event	Association		Asso	ciated Name	e	
Orig Construction	Owner		Farr	ham, E.D.		
Construction Notes:						
One of ten rowhouses of	constructed from the sa	me permit (#	1).			
PEOPLE/EVENTS DA	TA					
Racial Segregation Status	S:					
SETTING/SHAPE/SIZ	E DATA					
Surroundings: Ur	ban	Cro	oss Reference No	tes:		
	act					
	ow (1 of 10) ce on Setback Line					
	ow Building/Flat Front					
Footprint: Re	ectangular					
Number Stories:	2 plus basement					
Bays Wide:	3		_			
Height: Width:		Outbuilding	Туре	Cor	ntributing Status	
Depth/Length:						
SqFt:						
Volume:						
Lot Width Lot Depth/Length:		Outbuilding	Notes:			
Lot SqFt:		2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2				
Acreage:						
Has Driveway:					Į.	

Architectural Style(s)					
Italianate			_		
Exterior & Architectura	l Notes:				
rowhouses construction foundation. The faça located above the forwith modillions, dentelevation and has be first story holds a rephood with scrolled crailings provide accessindows and have controlled to the first story holds a rephood with scrolled controlled accessing the first story holds a rephood with scrolled controlled accessing the first story holds are sufficient to the first story holds a replacement to the first story holds are sufficient to	ted from the same per de (west elevation) is undation. A sloping ro til molding, end brack en partially parged. A placement, single-leaf onsoles surmounts th ess to the primary entroncrete sills and soldi	mit (#1). The dwelling faced with stretcher-bood caps the dwelling a ets and a frieze. An int single-leaf paneled do paneled wood door wie door opening, which ance. All window openier brick segmental arc	nate-style single-family ro- is constructed of brick ar- ond brick. A molded wate nd is highlighted by a pro- erior-side brick chimney is or pierces the foundation ith lights and a one-light to is flanked by wood pilas ings on the façade hold of thes. The rear (east) eleva- penings have concrete sil	ed is set on a set table spans the minent molder ises from the . The northern transom. A sinters. Cast iron /1, double-huition is fenestr	solid, raised he façade and is defected and the factorial cornice north (side) amost bay of the nple molded steps and ng, vinyl-sash ated with 1/1,
Site Notes:					
feet from the brick si by metal milled point	dewalk. The dwelling	is adjacent to 601 and valkway leads from the	of 10th Street, N.E. and is 605 10th Street, N.E. The primary entrance of the	grassy front y	ard is encircled
NOTABLE FEATUR	RES DATA				
Component	Feat	ure			
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment Street Part I	Source	
Facade	Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Unknown				
Walls	Brick				
Materials Notes:					
WINDOW/DOOR/IN	TERIOR DATA				
Window Location	Aperture Shape	Туре	Lights		Material
Facade	Rectangular	Dbl-Hung	1/1		Vinyl
Door Location	Aperture Shape	Туре	Pamels	;	Material
Basement	Rectangular	Single	Panele	d	Unknown
Main Door	Rectangular	Single	Panele	d	Wood/Glass
)		Notable Interior Featur	re(s)	
Notable Interior Plan(s		-			
Notable Interior Plan(s					
Notable Interior Plan(s					

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning:

Contributing

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 603_10th_Street_NE_facade_looking_E.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 603_10th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 603_10th_Street_NE_rear_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

05/12/1876 1 Build

Permit Notes:				
BIBLIOGRAPHIC DATA				
Short Citation	Type	Date	Remarks	
Bibliographic Notes:				
SIGNIFICANCE DATA				
Study Unit				
Code Criteria				
DATA PROCESSING EVENTS DATA	\			

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0053 Page 4

ID Number: 0960-0023

ID Number: 0960	-0023	Year Buil	t: 1876	Data	a Source: Permit		
Number Extended	Street			Quad	Type of Address		
605	10th Street			NE	Current		
Name(s)			Type of	Name			
Rowhouse, 605 10th	Street, N.E.		Comm	on	_		
TaxCode1 TaxCode	2 TaxCode3	Туре	Explair	n			
0960/0023		Square/Lot	Curre	nt			
STATUS/PURPOS	E/USE DATA	4					
Resource Type: Buil			Stat	us Curr	ent: Extant		
Desig. Status: Hist	toric		Qua	ality:			
Purpose: Row	vhouse		Con	dition:	Good		
Function/Use		Start	Source	Stop	Source	Explain	
Residential (Single-F		1876	Permit			Original	
Residential (Multi-Fa	imily)					Current	
CONSTRUCTION I	2474						
Construction Event		Start Sc	ource	Stop	Source	Cost Source	
Orig Construction			ermit	Otop	Course	2500 Permit	
Construction Event		Association			Associated Nar	me	
Orig Construction		Owner			Farnham, E.D.		
Construction Notes:							
One of ten rowhouse	es constructe	ed from the sa	ame permit ((#1).			
PEOPLE/EVENTS	DATA						
Racial Segregation St	atus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		С	ross Re	eference Notes:		1
Streetscape: Relate to Othr Bldgs:	Intact	11					
Relate to Street:	Face on Set						
Massing:	Row Buildin	g/Flat Front					
Footprint:	Rectangular	•					
Number Stories:	-	asement					
Bays Wide:	3		Outhuildin	a Tuna	0	antributing Status	
Height: Width:			Outbuildin Gazebo	ig Type	C	ontributing Status	
Depth/Length:			00.20.00				
SqFt:							
Volume:							
Lot Width Lot Depth/Length:			Outbuildin	na Notes	S:		
Lot SqFt:			March 20	10: A o	ne-story, one-bay gaz	zebo is located east of the	
Acreage:						0. The wood-frame gazebo tion and is capped by a	
Has Driveway:						vith square butt cedar	

Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/II Window Location Facade Door Location Basement Main Door	NTERIOR DATA Aperture Shape Rectangular Aperture Shape Rectangular Rectangular	Type Dbl-Hung Type Single Single	1/1 Pa Pa	hts mels neled	Material Vinyl Material Wood/Glass Wood/Glass	
Foundation Walls Materials Notes: WINDOW/DOOR/II Window Location Facade Door Location	Aperture Shape Rectangular Aperture Shape	Dbl-Hung Type	1 /1 Pa	mels	Vinyl Material	
Foundation Walls Materials Notes: WINDOW/DOOR/II Window Location Facade	NTERIOR DATA Aperture Shape Rectangular	Dbl-Hung	1/1		Vinyl	
Foundation Walls Materials Notes: WINDOW/DOOR/II	NTERIOR DATA Aperture Shape	•	<u>_</u>			
Foundation Walls Materials Notes:	NTERIOR DATA	Туре	Lig	hts	Material	
Foundation Valls Materials Notes:						
Foundation Walls	Brick					
Foundation Walls	Brick					
oundation	Brick					
· · · · · · · · · · · · · · · · · · ·	Unknown					
		Feature		Source		
		Factoria		0		
acade	Brick	30101	Stretcher Bond	Journe		
Vall Component	Material	Color	Treatment	Source		
Bloped	Not Visible	Coloi	Not Visible	Source		
EXTERIOR MATER Roof Component	Material	Color	Treatment	Source		
·						
OTABLE FEATU Component	Featu	ıre				
mature shrubs and s the primary entrance encircled by woof fe	-	rpin and picket fence	encircles the front ya	rd. A concrete wa	alkway leads from	
	o-story rowhouse is loo			-	•	
Site Notes:						
oundation. The nor ransom. A simple n bilasters. Poured co he façade hold 1/1, east) elevation is pa second story windo	the north (side) elevation thernmost bay of the find olded hood with scroll norete steps with meta double-hung, vinyl-sase arged and is fenestrate we are set in segmentation a wood post foundate.	rst story holds a single led consoles surmoun I hand rails provide ac th windows and have v d with 1/1, double-hun I openings. A one-stor	e-leaf paneled wood o ts the door opening, cess to the primary e wood sills and soldier g, vinyl-sash window	loor with lights a which is flanked entrance. All winc r brick segmenta s and double-lea	nd a one-light by fluted wood low openings on I arches. The rear f doors. The	
oundation. The faça nighlighted by a pro	cted from the same per ade (west elevation) is f minent molded cornice	faced with stretcher-bo with modillions, dent	ond brick. A sloping r il molding, end brack	oof caps the dwe ets and a frieze.	elling and is An interior brick	
	ar Notes. ucted in 1876, this two-	story, three-bay Italian	ate-style single-famil	y rowhouse is or	ne of ten	
March 2010: Constru	-I Maria					
Exterior & Architectur March 2010: Constru			_			
March 2010: Constru						

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Subdivision:

Interior Notes:

Historic District(s)

Tuesday, June 25, 2013 ID_Number: 0960-0023 Page 2

Ward/ANC:		
Zoning:	Designation Event(s)	
Contributing:		
Survey(s)	Level(s) of Investigation	
Capitol Hill F & G Streets (2010)	Permit Research	
	Reconnaissance Survey	

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 605_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 605_10th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0960\

File: 605_10th_Street_NE_rear_looking_W.JPG

Date:: Photog:

Code:: R: Fr:







PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

ID_Number: 0960-0023 Page 3

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

Permit Notes:	

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks	
Bibliographic Notes:				
Dibilographic Notes.				

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Created

ID Number: 0960-0024

ID Number: 0960	-0024	Year E	suilt: 1876	Dat	ta Source: P	ermit		
Number Extended	Street			Quad	d Type of Addres	SS		
607	10th Street			NE	Current			
007	Total Otrock							
Name(s)			Тур	e of Name				
Rowhouse, 607 10th	Street, N.E.		Cor	nmon				
TaxCode1 TaxCode	2 TaxCode3	3 Туре	Ex	plain				
0960/0024		Square/L		rrent				
STATUS/PURPOS	E/USE DAT	A						
Resource Type: Buil	lding		,	Status Cur	rent: Extant			
	oric			Quality:				
_	vhouse			Condition:	Fair			
Function/Use		Start	Source	Stop	Sou	rce	Explain	
Residential (Single-F	Family)	1876	Permit				Original	
Residential (Multi-Fa	ımily)						Current	
CONSTRUCTION	DATA							
Construction Event	(Start	Source	Stop	Source		Cost Source	
Orig Construction	•	1876	Permit				2500 Permit	
Construction Event		Associati	on		Associa	ted Na	me	
Orig Construction		Owner			Farnhar	n, E.D	· ·	
Construction Notes:								
One of ten rowhouse	as construct	ad from the	same nerr	nit (#1)				
One of ten rownous	es constructi	ed iroin the	Same pen	iiit (# i <i>)</i> .				
PEOPLE/EVENTS	DΔTΔ							
Racial Segregation St	atus:							
SETTING/SHAPE/S	SIZE DATA							
				O D	oforono Notos			
Surroundings:	Urban			Cross R	eference Notes:			٦
Streetscape:	Intact							
Relate to Othr Bldgs:								
Relate to Street:	Face on Set							
Massing:	Row Buildin		it					
Footprint:	Rectangula	r						
Number Stories:	2 plus	basement						
Bays Wide:	3							_
Height:			Outbu	ilding Type)	C	Contributing Status	
Width:							-	<u>-</u>
Depth/Length:								
SqFt:								
Volume:								
Lot Width								
Lot Depth/Length:			Outbu	ilding Note	es:			
Lot SqFt:			2 4.54		-			1
Acreage:								
Has Driveway:								

Architectural Style(s)					
Italianate			<u> </u>		
Exterior & Architectur	al Notes:				
rowhouses construction foundation. The faça located above the fowith modillions, denot the dwelling. A singular door removed. Cast iron shold 1/1, double-hur	ucted in 1876, this two- cted from the same per ide (west elevation) is undation. A sloping ro til molding, end brack ngle-leaf door pierces i with lights. The origina steps with hand rails p ng, vinyl-sash windows ted with 1/1, double-hu	mit (#1). The dwelling faced with stretcher-bo cof caps the dwelling a lets and a frieze. An interest foundation. The notal transom has been bo rovide access to the parameters and have wood sills as	is constructed of bric ond brick. A brick wat nd is highlighted by a erior brick chimney ri- orthernmost bay of the parded with plywood a rimary entrance. All w and soldier brick segn	k and is set on a ertable spans th prominent mole ses from the nore first story holds and the molded l indow openings nental arches. Ti	e solid, raised e façade and is ded wood cornice th (side) elevation s a single-leaf nood has been on the façade ne rear (east)
Site Notes:					
feet from the brick s landscaped with ma	o-story rowhouse is lo idewalk. The dwelling ture shrubs and is enc the dwelling and ends welling.	is adjacent to 605 and ircled by a metal bow a	609 10th Street, N.E. and picket fence. A co	The grassy front oncrete walkway	yard is leads from the
NOTABLE FEATU	RES DATA				
Component	Featu	ıre			
EXTERIOR MATER	RIALS DATA Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Unknown				
Walls	Brick				
Materials Notes:					
WINDOW/DOOR/II	NTERIOR DATA				
Window Location	Aperture Shape	Туре	Lig	hts	Material
Facade	Rectangular	Dbl-Hung	1/1		Vinyl
Door Location	Aperture Shape	Type	Par	mels	Material
Door Location Basement	Aperture Shape Rectangular	Type Single	Par	mels	Material Unknown

Notable Interior Feature(s)

Historic District(s)

Tuesday, June 25, 2013 ID_Number: 0960-0024 Page 2

Notable Interior Plan(s)

PLAN/SURVEY/DESIGNATION DATA

Capitol Hill

Interior Notes:

Neighborhood:

Subdivision: Ward/ANC:

Zoning:	Designation Event(s)
Contributing:	

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0960\

File: 607_10th_Street_NE_facade_looking_E.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 607_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 607_10th_Street_NE_rear_looking_W.JPG

Date:: Photog:

Code:: R: Fr:







PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

05/12/1876 1 Build

Permit Notes:						
BIBLIOGRAP	PHIC DATA					
Short Citation		Туре	Date	Remarks		
						-
Bibliographic No	otes:					
Bibliographic N	otes.					7
SIGNIFICANO	CE DATA					
Study Unit						
Code	Criteria				-	
DATA PROCI	ESSING EVENTS DATA					

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0024 Page 4

ID Number: 0960-0025

ID Number: 0960	-0025	Year Bu	ilt: 1876	Data	Source: Pern	nit	
Number Extended	Street			Quad T	ype of Address		
609	10th Street			NE C	Current		
Name(s)			Туре	of Name			
Rowhouse, 609 10th	Street, N.E.		Com			_	
TaxCode1 TaxCode	2 TaxCode3	в Туре	Expl	ain			
0960/0025		Square/Lo					
STATUS/PURPOS	E/USE DAT	A					
Resource Type: Buil	lding		S	atus Curre	nt: Extant		
•	toric			uality:			
Purpose: Rov	vhouse		С	ondition:	Good		
Function/Use		Start	Source	Stop	Source	Explain	
Residential (Single-F		1876	Permit			Original	
Residential (Multi-Fa	amily)					Current	
CONSTRUCTION							
Construction Event Orig Construction			ource ermit	Stop	Source	Cost Source 2500 Permit	
_	'						
Construction Event Orig Construction		Associatio Owner	n		Associated Farnham, E		
•		Owner			raiiiiaiii, E	. .	
Construction Notes:				4 (44)			
One of ten rowhouse	es constructe	ea from the s	same perm	t (#1).			
PEOPLE/EVENTS	ΠΑΤΑ						
Racial Segregation St	atus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Ref	erence Notes:		
Streetscape:	Intact						
Relate to Othr Bldgs:	Row (1 of 10	0)					
Relate to Street:	Face on Set						
Massing: Footprint:		ng/Flat Front -					
	Rectangula						
Number Stories:		pasement					
Bays Wide: Height:	3		Outhuik	ding Type		Contributing Status	
Width:			Outbuild	ing Type		Contributing Status	_
Depth/Length:							
SqFt:							
Volume:							
Lot Width			October 9	din n Nists			
Lot Depth/Length: Lot SqFt:			Outbuild	ding Notes:			
Acreage:							
Has Driveway:							

Architectural Style(s)					
Exterior & Architectura	ıl Notes:				
whouses construct nundation. The faça ighlighted by a pro- rick chimney rises to the foundation. The indicate and a one-light trans- tood pilasters. Meta içade hold 1/1, doul nundation is piercected with 1/1,	ted from the same per de (west elevation) is a minent molded wood of from the north (side) e northernmost bay of th om. A simple molded I steps with metal han ole-hung, vinyl-sash w I by 1/1, double-hung,	story, three-bay Italian mit (#1). The dwelling faced with stretcher-becornice with modillions levation of the dwellin le first story holds a si hood with scrolled cord rails provide access indows and have woo vinyl-sash windows with windows. The first reed.	is constructed of bond brick. A sloping, ed, dentil molding, ed, A single-leaf woongle-leaf paneled wasoles surmounts to the primary entrick sills and soldier to that false 6/6 vinyl m	rick and is set on proof caps the d and brackets and and door with a di rood door with a ane door opening ance. All window brick segmental untins. The rear	n a solid, raised lwelling and is a frieze. An interior lamond light pierces stained glass light y which is flanked by w openings on the arches. The
te Notes:	- 1110 1041144	<u> </u>			
feet from the brick si landscaped with mat primary entrance and	dewalk. The dwelling i ure shrubs and is enc	cated on the east side is adjacent to 607 and ircled by a metal bow a. The grassy rear yard the property.	611 10th Street, N.E and picket fence. A	i. The grassy fro concrete walkw	nt yard is ay leads from the
NOTABLE FEATUR	RES DATA				
omponent	Featu	ıre			
XTERIOR MATER	IALS DATA				
	Material	Color	Treatment	Source	
Roof Component	Material Not Visible	Color	Treatment Not Visible	Source	
Roof Component Sloped Wall Component		Color		Source	
Roof Component Bloped Vall Component Facade	Not Visible Material		Not Visible Treatment	Source	
Roof Component Sloped Wall Component Facade Structure Component Foundation	Not Visible Material Brick	Color	Not Visible Treatment	Source d	
Roof Component Sloped Vall Component Facade Structure Component Foundation Valls	Not Visible Material Brick Material Unknown	Color	Not Visible Treatment	Source d	
Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Not Visible Material Brick Material Unknown	Color	Not Visible Treatment	Source d	
Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Not Visible Material Brick Material Unknown Brick	Color	Not Visible Treatment	Source d	
Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Not Visible Material Brick Material Unknown Brick	Color	Not Visible Treatment Stretcher Bon	Source d	Material
Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Not Visible Material Brick Material Unknown Brick	Color Feature	Not Visible Treatment Stretcher Bon	Source d Source	Material Vinyl
Roof Component Sloped Vall Component Facade Structure Component Foundation Valls Materials Notes: VINDOW/DOOR/IN	Not Visible Material Brick Material Unknown Brick	Color Feature	Not Visible Treatment Stretcher Bon	Source d Source	

PLAN/SURVEY/DESIGNATION DATA

Rectangular

Neighborhood: Capitol Hill Historic District(s)

Single

Subdivision:

Main Door

Interior Notes:

Notable Interior Plan(s)

Paneled

Notable Interior Feature(s)

Wood/Glass

walu/AINC.
Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0960\

File: 609_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 609_10th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 609_10th_Street_NE_rear_looking_W.JPG

Date:: Photog:

Code:: R: Fr:







PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

Permit Notes:			

BIBLIOGRAPHIC DATA

Short Citation	Туре	Date	Remarks	
Bibliographic Notes:				

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action	
3/8/2010	Dayton (MSD), Maria	Record Updated	·
3/4/2010	Dayton (MSD), Maria	Record Updated	
3/4/2010	Dayton (MSD), Maria	Record Created	

ID Number: 0960-0026

ID Number: 0960	-0026	Year Built:	1876	Data	a Source: Permit		
Number Extended	Street			Quad	Type of Address		
611	10th Street				Current		
Name(s)			Туре с	of Name			
Rowhouse, 611 10th	Street, N.E.		Comm	non			
TaxCode1 TaxCode 0960/0026	2 TaxCode3	Type Square/Lot	Expla Curre				
STATUS/PURPOS	E/USE DATA						
Resource Type: Buil	lding		Sta	atus Curr	ent: Extant		
•	toric			ality:			
Purpose: Row	vhouse		Co	ndition:	Good		
Function/Use		Start	Source	Stop	Source	Explain	
Residential (Single-F		1876	Permit			Original	
Residential (Multi-Fa	imily)					Current	
CONSTRUCTION I	ΣΑΤ Δ						
Construction Event	Sta	art Sou	urce	Stop	Source	Cost Source	
Orig Construction	18		mit			2500 Permit	
Construction Event		Association			Associated Nar	me	
Orig Construction		Owner			Farnham, E.D.		
Construction Notes:							
One of ten rowhouse	es constructed	I from the sa	me permit	(#1).			
PEOPLE/EVENTS	DATA						
Racial Segregation St	atus:						
0 0							
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		(Cross Re	eference Notes:		
Streetscape:	Intact						
Relate to Othr Bldgs:	` ,						
Relate to Street: Massing:	Face on Setba						
Footprint:	Rectangular	yı ıat ı ront					
Number Stories:	2 plus ba	sement					
Bays Wide:	3	iscincin.					
Height:			Outbuildi	ng Type	C	ontributing Status	
Width:							
Depth/Length: SqFt:							
Volume:							
Lot Width							
Lot Depth/Length:			Outbuildi	ng Notes	s:		I
Lot SqFt: Acreage:							
Has Driveway:							
ilas biivoway.							

Architectural Style(s)					
Italianate					
Exterior & Architectura	al Notes:				
rowhouses constructed foundation. The faça located above the formodillions, dentil monorthernmost bay of hood with scrolled crails provide access windows and have colocks, 1/1, double-h	acted in 1876, this two- ted from the same per de (west elevation) is to undation. A sloping ro olding, end brackets ar the first story holds a consoles surmounts the to the primary entrance oncrete sills and solding, vinyl-sash windo th wood doors pierce to nental arches.	mit (#1). The dwelling faced with stretcher-book caps the dwelling and a frieze. A single-lessingle-leaf paneled woe door opening, which e. All window opening er brick segmental arows and 1/1, double-hu	is constructed of bricond brick. A brick wat not is highlighted by a fighted by a fighted by a fighted by wood pood door and a one-lighted by wood pays on the façade hold thes. The rear (east) early vinyl-sash windown.	k and is set on a ertable spans the prominent mold pierces the four ght transom. A si ilasters. Steps w 1/1, double-hung levation is fenesw with false 6/6	solid, raised e façade and is led cornice with ndation. The imple molded rith metal hand y, vinyl-sash trated with glass vinyl muntins.
Site Notes:					
mature shrubs and is	dewalk. The dwelling is encircled by a metal the sidewalk. The rea	bow and picket fence.	A brick walkway lead	s from the prima	ry entrance of the
NOTABLE FEATUR	RES DATA				
NOTABLE FEATUR	RES DATA Featu	ire			
_	Featu	ire			
Component EXTERIOR MATER	Featu	color	Treatment	Source	
Component	Featu		Treatment Not Visible	Source	
EXTERIOR MATER Roof Component Sloped	Featu RIALS DATA Material			Source Source	
EXTERIOR MATER Roof Component Sloped Wall Component	Featu RIALS DATA Material Not Visible	Color	Not Visible		
EXTERIOR MATER Roof Component Sloped Wall Component Facade	Featu RIALS DATA Material Not Visible Material	Color	Not Visible Treatment		
EXTERIOR MATER Roof Component	Feature RIALS DATA Material Not Visible Material Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation	Feature RIALS DATA Material Not Visible Material Brick Material Unknown	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Feature RIALS DATA Material Not Visible Material Brick Material Unknown	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Material Material Material Brick Material Unknown Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Material Material Brick Material Unknown Brick	Color	Not Visible Treatment	Source	Material

Window Location	Aperture Shape	Type	Lights	Material		
Facade	Rectangular	Dbl-Hung	1/1	Vinyl		
Door Location	Aperture Shape	Туре	Pamels	Material		
Basement	Rectangular	Single	Paneled	Wood		
Main Door	Rectangular	Single	Paneled	Wood		
Notable Interior Plan(s)			Notable Interior Feature(s)			

Interior Notes:		

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill
Subdivision:
Ward/ANC:
Historic District(s)

Historic District(s)

= . . . = ...

Zoning:	Designation Event(s)
Contributing:	

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Survey(s)

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0960\

File: 611_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:



St\Database\Pictures\Square 0960\

File: 611_10th_Street_NE_facdae_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 611_10th_Street_NE_rear_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

05/12/1876 1 Build

Permit Notes:				
BIBLIOGRAPHIC DATA				
Short Citation	Туре	Date	Remarks	
Bibliographic Notes:				
SIGNIFICANCE DATA				
Study Unit				
Code Criteria				
DATA PROCESSING EVENTS DATA	A			

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0026 Page 4

ID Number: 0960-0027

ID Number: 0960	-0027	Year Bu	uilt: 1876	Data	Source: Permi	t	
Number Extended	Street			Quad T	ype of Address		
613	10th Street			NE C	Current		
Name(s)			Туре	of Name			
Rowhouse, 613 10th	Street, N.E.			mon			
TaxCode1 TaxCode	2 TaxCode3	В Туре	Ехр	lain			
0960/0027		Square/L		rent			
STATUS/PURPOS	E/USE DAT	A					
Resource Type: Buil	ding		S	tatus Curre	nt: Extant		
•	oric			uality:			
Purpose: Rov	house		С	ondition:	Good		
Function/Use		Start	Source	Stop	Source	Explain	
Residential (Single-F		1876	Permit			Original	
Residential (Multi-Fa	ımily)					Current	
CONSTRUCTION			_				
Construction Event			Source Permit	Stop	Source	Cost Source 2500 Permit	
Orig Construction							
Construction Event		Associatio	on		Associated N		
Orig Construction		Owner			Farnham, E.	υ.	
Construction Notes:							
One of ten rowhouse	es constructe	ed from the	same perm	it (#1).			
PEOPLE/EVENTS	DATA						
Racial Segregation St	atus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Ref	erence Notes:		
Streetscape:	Intact			0.000.101			\neg
Relate to Othr Bldgs:	Row (1 of 1	0)					
Relate to Street:	Face on Set	back Line					
Massing:	Row Buildir		t				
Footprint:	Rectangula	ſ					
Number Stories:	2 plus l	pasement					
Bays Wide:	3		0 11 11			0	
Height: Width:			Outbuil	ding Type		Contributing Status	<u> </u>
Depth/Length:							
SqFt:							
Volume:							
Lot Width							
Lot Depth/Length:			Outbuil	ding Notes:			\neg
Lot SqFt:							
Acreage:							
Has Driveway:							

STYL	.E/E)	(TERI	OR	DATA

Architectural Style(s)

Italianate

Exterior & Architectural Notes:

March 2010: Constructed in 1876, this two-story, three-bay Italianate-style single-family rowhouse is one of ten rowhouses constructed from the same permit (#1). The dwelling is constructed of brick and is set on a solid, raised foundation. The façade (west elevation) is faced with stretcher-bond brick. A brick watertable spans the façade and is located above the foundation. A sloping roof caps the dwelling and is highlighted by a prominent molded wood cornice with modillions, dentil molding, end brackets and a frieze. A single-leaf wood door with a diamond light pierces the foundation. The northernmost bay of the first story holds a single-leaf paneled wood door. A Colonial Revival-style surround complements the door and is composed of pilasters and a molded pediment. Poured concrete steps with metal hand rails provide access to the primary entrance. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins and have rowlock brick sills and soldier brick segmental arches. The rear (east) elevation is fenestrated with 1/1, double-hung, wood-sash windows and double-leaf wood-frame glass doors. The windows feature rowlock brick sills and soldier brick segmental arches. A one-story, full-width wood-frame deck extends from the rear elevation of the dwelling and is complemented by square wood balusters.

Site Notes:

March 2010: This two-story rowhouse is located on the east side of 10th Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 611 and 615 10th Street, N.E. The grassy front yard is encircled by a metal bow and picket fence. A concrete walkway leads from the primary entrance and ends at the brick sidewalk. The rear yard is bounded by a wood fence. A concrete parking space and public alley are located east of the dwelling.

		۱B								

Component	Feature	
-----------	---------	--

EXTERIOR MATERIALS DATA

Material	Color	Treatment	Source	
Not Visible		Not Visible		
Material	Color	Treatment	Source	
Brick		Stretcher Bond		
Material	Feature		Source	
Unknown				
Brick				
_	Not Visible Material Brick Material Unknown	Not Visible Material Color Brick Material Feature Unknown	Not Visible Material Color Treatment Stretcher Bond Material Feature Unknown	Not Visible Material Color Treatment Source Brick Stretcher Bond Material Feature Source Unknown

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material			
Facade	Rectangular	Dbl-Hung	1/1	Vinyl			
Door Location	Aperture Shape	Туре	Pamels	Material			
Basement	Rectangular	Single		Wood/Glass			
Main Door	Rectangular	Single	Paneled	Wood			
Notable Interior Plan(s)			Notable Interior Feature(s)				

Interior Notes:	

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill
Subdivision:
Ward/ANC:
Historic District(s)

Tuesday, June 25, 2013 ID_Number: 0960-0027 Page 2

Zoning: Contributing:

Survey(s) Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research Reconnaissance Survey

Designation Event(s)

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 613_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 613_10th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 613_10th_Street_NE_rear_looking_W.JPG

Date:: Photog:

Code:: R: Fr:







PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

05/12/1876 1 Build

Permit Notes:				
BIBLIOGRAPHIC DATA				
Short Citation	Туре	Date	Remarks	
Bibliographic Notes:				
SIGNIFICANCE DATA				
Study Unit				
Code Criteria				
DATA PROCESSING EVENTS DAT	IA			

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0027 Page 4

ID Number: 0960-0028

ID Number: 0960	-0028	Year Built:	1876	Dat	a Source: Permit		
Number Extended	Street			Quad	Type of Address		
615	10th Street				Current		
Name(s)			Туре о	f Name			
Rowhouse, 615 10th	Street, N.E.		Comm	on			
TaxCode1 TaxCode 0960/0028	2 TaxCode3	Type Square/Lot	Explai Curre				
STATUS/PURPOS	E/USE DATA						
Resource Type: Buil	lding		Sta	tus Curi	ent: Extant		
•	toric			ality:			
Purpose: Rov	vhouse		Cor	ndition:	Good		
Function/Use		Start :	Source	Stop	Source	Explain	
Residential (Single-F		1876 I	Permit			Original	
Residential (Multi-Fa	imily)					Current	
CONSTRUCTION I	ΔΤΔ						
Construction Event	Sta	art Sou	ırce	Stop	Source	Cost Source	
Orig Construction	18		mit			2500 Permit	
Construction Event		Association			Associated Nan	ne	
Orig Construction		Owner			Farnham, E.D.		
Construction Notes:							
One of ten rowhouse	es constructed	from the sar	ne permit	(#1).			
PEOPLE/EVENTS	DATA						
Racial Segregation St	atus:						
0 0							
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		C	Cross Re	eference Notes:		
Streetscape:	Intact						
Relate to Othr Bldgs:	` ,						
Relate to Street: Massing:	Face on Setba						
Footprint:	Rectangular	71 10111 1 01011					
Number Stories:	2 plus ba	sement					
Bays Wide:	3		L				
Height:			Outbuildir	ng Type	Co	ontributing Status	
Width:							
Depth/Length: SqFt:							
Volume:							
Lot Width							
Lot Depth/Length:			Outbuildir	ng Note	S:		1
Lot SqFt: Acreage:							
Has Driveway:							
as 2say.							

Architectural Style(s)					
Italianate					
Exterior & Architectura	ıl Notes:				
rowhouses construction of the façand above the forwith modillions, dente eaf paneled wood do penings on the façand arches. And the porch is supported the fact and the fact archer end bay. The multi-light wood doon ave concrete sills.	ted from the same per de (west elevation) is to undation. A sloping ro til molding, end bracke af paneled wood door for. The entry is flanke de hold 6/6, double-hu one-story, full-width p ed by metal filigree po e rear (east) elevation rs with blind transoms an exterior-rear chimn	story, three-bay Italian mit (#1). The dwelling faced with stretcher-boof caps the dwelling a lets and a frieze. An interpretation pierces the foundation of by wood pilasters aroung, wood-sash windo orch spans the façadests. Metal balusters er is fenestrated with 6/6 s. All openings are top bey rises from the center	is constructed of briond brick. A brick wand is highlighted by erior-side brick chimn. The northernmost and topped by a panews, which have head and is set on a brick circle the porch whis, double-hung, wood ped by soldier bricker of the rear elevation.	ck and is set on a tertable spans the a prominent mole ney rises from the bay of the first set led blind transom der brick sills and the pier foundation the accessed vides as segmental arche	a solid, raised to façade and is ded wood cornice e north (side) tory holds a single-to. All window it soldier brick is a steps in the and single-leaf is and the windows
extends from the nor Site Notes:	thernmost bay and is	set on a square wood	post foundation.		
feet from the sidewal mature shrubs and s	k. The dwelling is adja mall trees and is encir	cated on the east side acent to 613 and 617 10 cled by a metal bow a public alley are locate	Oth Street, N.E. The o	rassy front yard e. The rear yard is	is landscaped with
NOTABLE FEATUR	DES DATA				
	Featu	ire			
Component	Featu	ire			
Component EXTERIOR MATER	Featu	Color	Treatment	Source	
EXTERIOR MATER Roof Component Sloped	Featu		Treatment Not Visible	Source	
EXTERIOR MATER Roof Component Sloped Wall Component	Featu NALS DATA Material Not Visible Material		Not Visible Treatment	Source Source	
EXTERIOR MATER Roof Component Sloped Wall Component	Featu IALS DATA Material Not Visible	Color	Not Visible		
Component EXTERIOR MATER Roof Component	Featu NALS DATA Material Not Visible Material	Color	Not Visible Treatment		
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation	Feature Featur	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Feature Featur	Color	Not Visible Treatment Stretcher Bond	Source	Material
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Unknown Brick	Color Color Feature	Not Visible Treatment Stretcher Bond	Source	Material
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/IN	Material Material Material Brick Material Unknown Brick TERIOR DATA Aperture Shape	Color Color Feature	Not Visible Treatment Stretcher Bond	Source	

Window Location	Aperture Shape	Туре	Lights	Material	
Facade	Rectangular	Dbl-Hung	6/6	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single	Paneled	Wood	
Main Door	Rectangular	Single	Paneled	Wood	
Notable Interior Plan	n(s)	1	Notable Interior Feature(s)		

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Subdivision:

Capitol Hill

Historic District(s)

Tuesday, June 25, 2013 ID_Number: 0960-0028 Page 2

Ward/ANC:		
Zoning:	Designation Event(s)	
Contributing:		
Survey(s)	Level(s) of Investigation	
Capitol Hill F & G Streets (2010)	Permit Research	
	Reconnaissance Survey	

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 615_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 615_10th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

File:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0960\ 615_10th_Street_NE_rear_looking_W.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

Permit Notes:			

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks	
Bibliographic Notes:				

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action	
3/8/2010	Dayton (MSD), Maria	Record Updated	
3/4/2010	Dayton (MSD), Maria	Record Updated	
3/4/2010	Dayton (MSD), Maria	Record Created	

ID Number: 0960-0029

Number Extended								
Name (s) Type of Name Name (s) Type of Name (s)	ID Number: 0960	-0029	Year Bu	uilt: 1876	Data	Source: Permit	t	
Name(s)	Number Extended	Street			Quad	Type of Address		
TaxCode1	617	10th Street			NE (Current		
TaxCode1	Name(s)			Туре	of Name			
Square/Lot Current		Street, N.E.						
Square/Lot Current	TaxCode1 TaxCode	2 TaxCode3	3 Type	Exp	lain			
Resource Type: Residential Historic Quality: Permit Good Permit Perm			,,					
Resource Type: Residential Historic Quality: Permit Good Permit Perm								
Desig. Slatus: Historic Rowhouse Rowhouse Source Store Source Explain	STATUS/PURPOS	E/USE DAT	A					
Purpose: Rowhouse Start Source Stop Source Explain	Resource Type: Buil	ding		S	tatus Curre	ent: Extant		
Residential (Single-Family)	=				-			
Residential (Single-Family) Residential (Multi-Family) Resolution Residential (Multi-Family) Residential (Multi-Family) Resolution Residential (Multi-Family) Resolution Residential (Multi-Family) Residential (Multi-Family) Resolution Residential (Multi-Family) Resolution Residential (Multi-Family) Residential (Multi-Family) Resolution Residential (Multi-Family) Resolution Residential (Multi-Family) Resolution Residential (Multi-Family) Resolution Residential (Multi-Family) Residential (Multi-Family) Resolution Residential (Multi-Family) Resolution Residential (Multi-Family) Residential (Multi-Family) Resolution Residential (Multi-Family) Residential (Multi-Family) Resolution Residential (Multi-Family) Residential (Multi-Family) Residential (Multi-Family) Residential (Multi-Family) Resolution Residential (Multi-Family) Residential (Mu	Purpose: Rov	house		С	ondition:	Good		
Residential (Multi-Family) CONSTRUCTION DATA Construction Event Start Source Stop Source Cost Source Orig Construction 1876 Permit 2500 Permit Construction Event Association Owner Farnham, E.D. Construction Notes Construction Notes Construction Notes Cone of ten rowhouses constructed from the same permit (#1). PEOPLE/EVENTS DATA Racial Segregation Status: SETTING/SHAPE/SIZE DATA Surroundings: Urban Cross Reference Notes: Relate to Othr Bidgs: Row (1 of 10) Relate to Street: Face on Setback Line Relate to Street: Face on Setback Line Relate to Street: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Vidith: Contributing Status Contributing Status	Function/Use		Start	Source	Stop	Source	Explain	
CONSTRUCTION DATA Construction Event Start Source Stop Source Cost Source Orig Construction 1876 Permit 2500 Permit Construction Event Association Associated Name Orig Construction Notes: One of ten rowhouses constructed from the same permit (#1). PEOPLE/EVENTS DATA Racial Segregation Status: SETTING/SHAPE/SIZE DATA Surroundings: Urban Cross Reference Notes: Streetscape: Intact Relate to Othr Bidgs: Row (1 of 10) Relate to Street: Face on Setback Line Massing: Row Building/Flat Front Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Outbuilding Type Contributing Status Coubuilding Notes: Outbuilding Notes: Outbuilding Notes: Outbuilding Notes:	· -		1876	Permit			_	
Construction Event Start Source Stop Source Cost Source Orig Construction 1876 Permit 2500 Permit Construction Event Association Associated Name Orig Construction Owner Farnham, E.D. Construction Notes: Cone of ten rowhouses constructed from the same permit (#1). PEOPLE/EVENTS DATA Racial Segregation Status: SETTING/SHAPE/SIZE DATA Surroundings: Urban Cross Reference Notes: Streetscape: Intact Relate to Othr Bidgs: Row (1 of 1 0) Relate to Street: Face on Setback Line Massing: Row Building/Flat Front Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Outbuilding Type Contributing Status Outbuilding Type Contributing Status Outbuilding Notes: Lot Width Lot Depth/Length: Cotty Contributing Notes: Lot Width Lot Depth/Length: Cotty Contributing Notes: Construction Nasociated Name Associated Name Farnham, E.D. Farnham, E.D. Associated Name Farnham, E.D. Fortham, E.D. Construction Notes: Cross Reference Notes:	Residential (Multi-Fa	ımily)					Current	
Construction Event Start Source Stop Source Cost Source Orig Construction 1876 Permit 2500 Permit Construction Event Association Associated Name Orig Construction Owner Farnham, E.D. Construction Notes: Cone of ten rowhouses constructed from the same permit (#1). PEOPLE/EVENTS DATA Racial Segregation Status: SETTING/SHAPE/SIZE DATA Surroundings: Urban Cross Reference Notes: Streetscape: Intact Relate to Othr Bidgs: Row (1 of 1 0) Relate to Street: Face on Setback Line Massing: Row Building/Flat Front Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Outbuilding Type Contributing Status Outbuilding Type Contributing Status Outbuilding Notes: Lot Width Lot Depth/Length: Cotty Contributing Notes: Lot Width Lot Depth/Length: Cotty Contributing Notes: Construction Nasociated Name Associated Name Farnham, E.D. Farnham, E.D. Associated Name Farnham, E.D. Fortham, E.D. Construction Notes: Cross Reference Notes:								
Orig Construction 1876 Permit 2500 Permit Construction Association Associated Name Orig Construction Owner Farnham, E.D. Construction Notes: One of ten rowhouses constructed from the same permit (#1). PEOPLE/EVENTS DATA Racial Segregation Status: SETTING/SHAPE/SIZE DATA Surroundings: Urban Cross Reference Notes: Streets Cape: Intact Relate to Other Bidgs: Row (1 of 10) Relate to Street: Row Building/Flat Front Face on Setback Line Massing: Row Building/Flat Front Rectangular Rectangular Contributing Status Number Stories: 2 plus basement Bays Wide: 3 Bays Wide: 3 Contributing Status Width: Under Contributing Status Update: Volume: Lot Width Outbuilding Notes: Lot SqFt: Contributing Status								
Construction Event Association Associated Name Orig Construction Owner Farnham, E.D. Construction Notes: One of ten rowhouses constructed from the same permit (#1). PEOPLE/EVENTS DATA Racial Segregation Status: SETTING/SHAPE/SIZE DATA Surroundings: Urban Cross Reference Notes: Streetscape: Intact Relate to Othr Bidgs: Row (1 of 10) Relate to Street: Face on Setback Line Massing: Row Building/Flat Front Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Width: Depth/Length: SqFt: Volume: Lot Width Lot Sqft: Acreage: Outbuilding Notes: Lot Sqft: Acreage:	-				Stop	Source		
Orig Construction Notes: One of ten rowhouses constructed from the same permit (#1). PEOPLE/EVENTS DATA Racial Segregation Status: SETTING/SHAPE/SIZE DATA Surroundings: Urban Cross Reference Notes: Streetscape: Intact Relate to Othr Bidgs: Row (1 of 10) Relate to Street: Face on Setback Line Massing: Row Building/Flat Front Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Vidth: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:	_							
Construction Notes: One of ten rowhouses constructed from the same permit (#1). PEOPLE/EVENTS DATA Racial Segregation Status: SETTING/SHAPE/SIZE DATA Surroundings: Urban Cross Reference Notes: Streetscape: Intact Relate to Othr Bidgs: Row (1 of 10) Relate to Street: Face on Setback Line Massing: Row Building/Flat Front Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Outbuilding Type Contributing Status Outbuilding Notes: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:	-			n				
Die of ten rowhouses constructed from the same permit (#1). PEOPLE/EVENTS DATA Racial Segregation Status: SETTING/SHAPE/SIZE DATA Surroundings: Urban Cross Reference Notes: Streetscape: Intact Relate to Othr Bidgs: Row (1 of 10) Relate to Street: Face on Setback Line Massing: Row Building/Flat Front Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Vidth: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:	•		Owner			Familiani, E.i	. .	
PEOPLE/EVENTS DATA Racial Segregation Status: SETTING/SHAPE/SIZE DATA Surroundings: Urban Cross Reference Notes: Streetscape: Intact Relate to Othr Bldgs: Row (1 of 10) Relate to Street: Face on Setback Line Massing: Row Building/Flat Front Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:					. (44)			
Racial Segregation Status: SETTING/SHAPE/SIZE DATA Surroundings: Urban Cross Reference Notes: Streetscape: Intact Relate to Othr Bldgs: Row (1 of 10) Relate to Street: Face on Setback Line Massing: Row Building/Flat Front Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:	One of ten rownous	es constructe	ea from the	same perm	It (#1).			
Racial Segregation Status: SETTING/SHAPE/SIZE DATA Surroundings: Urban Cross Reference Notes: Streetscape: Intact Relate to Othr Bldgs: Row (1 of 10) Relate to Street: Face on Setback Line Massing: Row Building/Flat Front Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:	PEODI E/EVENTS	ΠΑΤΑ						
SETTING/SHAPE/SIZE DATA Surroundings: Urban Cross Reference Notes: Streetscape: Intact Relate to Othr Bldgs: Row (1 of 10) Relate to Street: Face on Setback Line Massing: Row Building/Flat Front Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:								
Surroundings: Urban Cross Reference Notes: Streetscape: Intact Relate to Othr Bldgs: Row (1 of 10) Relate to Street: Face on Setback Line Massing: Row Building/Flat Front Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:	Racial Segregation St	atus:						
Streetscape: Intact Relate to Othr Bldgs: Row (1 of 10) Relate to Street: Face on Setback Line Massing: Row Building/Flat Front Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:	SETTING/SHAPE/S	SIZE DATA						
Streetscape: Intact Relate to Othr Bldgs: Row (1 of 10) Relate to Street: Face on Setback Line Massing: Row Building/Flat Front Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:	Surroundings:	Urban			Cross Ref	erence Notes:		
Relate to Street: Face on Setback Line Massing: Row Building/Flat Front Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:	•							
Massing: Row Building/Flat Front Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:	Relate to Othr Bldgs:	Row (1 of 1	0)					
Footprint: Rectangular Number Stories: 2 plus basement Bays Wide: 3 Height: Outbuilding Type Contributing Status Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:								
Number Stories: Bays Wide: Height: Outbuilding Type Contributing Status Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Contributing Status Outbuilding Type Contributing Status Outbuilding Notes:	-			t				
Bays Wide: Height: Outbuilding Type Contributing Status Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:		Rectangula	ſ					
Height: Outbuilding Type Contributing Status Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:			oasement					
Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:	-	3		Outhuile	dina Tuna		Contributing Status	
Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:				Outbuil	ung Type		Continuuting Status	_
Volume: Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:								
Lot Width Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage:	SqFt:							
Lot Depth/Length: Outbuilding Notes: Lot SqFt: Acreage: Outbuilding Notes:								
Lot SqFt: Acreage:				0	P			
Acreage:				Outbuil	aing Notes:			
	_							

Architectural Style(s)					
Italianate			<u> </u>		
Exterior & Architectura	al Notes:				
owhouses construction oundation. The faça ocated above the formodillions, dentil make dwelling. A single-leaf paneled with the formary entrance. Aland soldier brick seand double-leaf woo	ted from the same per de (west elevation) is undation. A sloping ro olding, end brackets a e-leaf wood door with vood door and a one-li is flanked by wood pi I window openings on gmental arches. The re d-frame glass doors.	mit (#1). The dwelling faced with stretcher-book caps the dwelling and a frieze. An interior lights pierces the four ght transom. A simple lasters. Poured concruthe façade hold 1/1, dear (east) elevation is fall window openings a	nate-style single-family is constructed of brick ond brick. A brick wat and is highlighted by a brick chimney rises findation. The northern e molded hood with scete steps with metal highlighted by sold enestrated with 1/1, do the surmounted by sold hernmost bay of the resurmounted of t	k and is set on a ertable spans the prominent mole om the north (simost bay of the forolled consoles and rails provided windows and buble-hung, viny dier brick segme	e solid, raised e façade and is led cornice with ide) elevation of irst story holds a surmounts the e access to the nave wood sills desath windows ental arches and
Site Notes:					
landscaped with ma walkway leads from	ture shrubs and found the primary entrance o od fence. A concrete p	ation plantings and is of the dwelling and en	619 10th Street, N.E. 7 encircled by a metal b ds at the sidewalk. Ma blic alley are located e	oow and picket fe ture trees dot the	ence. A concrete e rear yard, which
Component	Feat	ıre			
EXTERIOR MATER	RIALS DATA Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
acade	Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Unknown	. 55.10.5		2 - 0.00	
Walls	Brick				
Materials Notes:					
WINDOW/DOOR/IN	ITERIOR DATA				
WINDOW/DOOR/IN Window Location	Aperture Shape	Туре	Lig	hts	Material

Window Location	Aperture Shape	Туре	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single		Wood/Glass
Main Door	Rectangular	Single	Paneled	Wood
Notable Interior Plan	n(s)	ı	Notable Interior Feature(s)	

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **C** Subdivision:

Capitol Hill

Historic District(s)

Tuesday, June 25, 2013 ID_Number: 0960-0029 Page 2

Ward/ANC:		
Zoning:	Designation Event(s)	
Contributing:		
Survey(s)	Level(s) of Investigation	
Capitol Hill F & G Streets (2010)	Permit Research	
	Reconnaissance Survey	

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 617_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 617_10th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0960\

File: 617_10th_Street_NE_rear_looking_W.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

Tuesday, June 25, 2013 ID_Number: 0960-0029 Page 3

Permit Notes:			

BIBLIOGRAPHIC DATA

Short Citation	Туре	Date	Remarks	
Bibliographic Notes:				

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Created

ID Number: 0960-0030

ID Number: 0960	-0030 Year	Built: 1876	Data	Source: Permit		
Number Extended	Street		Quad T	ype of Address		
619	10th Street		NE C	urrent		
Name(s)		Туре	of Name			
Rowhouse, 619 10th	Street, N.E.	Com	mon	·		
TaxCode1 TaxCode	2 TaxCode3 Type	Expl	lain			
0960/0030	Square		rent			
STATUS/PURPOS	E/USE DATA					
Resource Type: Buil	=		tatus Currer	nt: Extant		
o .	oric		uality:	01		
Purpose: Rov	house	C	ondition:	Good		
Function/Use	Start	Source	Stop	Source	Explain	
Residential (Single-F	family) 1876	Permit			Historic/Current	
CONSTRUCTION I	ΣΑΤΑ					
Construction Event	Start	Source	Stop	Source	Cost Source	
Orig Construction	1876	Permit			2500 Permit	
Construction Event	Associa	ation		Associated Na	ıme	
Orig Construction	Owner			Farnham, E.D		
Construction Notes:						
	constructed from the	same permit	(#1).			
PEOPLE/EVENTS	DATA					
PEOPLE/EVENTS Racial Segregation St						
	atus:					
Racial Segregation St	atus:		Cross Refe	erence Notes:		
Racial Segregation St SETTING/SHAPE/S Surroundings: Streetscape:	atus: SIZE DATA Urban Intact		Cross Refe	erence Notes:		
Racial Segregation St SETTING/SHAPE/S Surroundings: Streetscape: Relate to Othr Bldgs:	SIZE DATA Urban Intact Row (1 of 10)		Cross Refe	erence Notes:		
Racial Segregation St SETTING/SHAPE/S Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street:	atus: SIZE DATA Urban Intact Row (1 of 10) Face on Setback Line		Cross Refe	erence Notes:		
Racial Segregation St SETTING/SHAPE/S Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing:	atus: BIZE DATA Urban Intact Row (1 of 10) Face on Setback Line Row Building/Flat Fro		Cross Refe	erence Notes:		
Racial Segregation St SETTING/SHAPE/S Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	atus: SIZE DATA Urban Intact Row (1 of 10) Face on Setback Line Row Building/Flat Fro	ont	Cross Refe	erence Notes:		
Racial Segregation St SETTING/SHAPE/S Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories:	atus: BIZE DATA Urban Intact Row (1 of 10) Face on Setback Line Row Building/Flat Fro	ont	Cross Refe	erence Notes:		
Racial Segregation St SETTING/SHAPE/S Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	atus: BIZE DATA Urban Intact Row (1 of 10) Face on Setback Line Row Building/Flat Fro Rectangular 2 plus basement	ont	Cross Refe		Contributing Status	
Racial Segregation St SETTING/SHAPE/S Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width:	atus: BIZE DATA Urban Intact Row (1 of 10) Face on Setback Line Row Building/Flat Fro Rectangular 2 plus basement	ont			Contributing Status	
Racial Segregation Standard Segregation	atus: BIZE DATA Urban Intact Row (1 of 10) Face on Setback Line Row Building/Flat Fro Rectangular 2 plus basement	ont			Contributing Status	
Racial Segregation St SETTING/SHAPE/S Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt:	atus: BIZE DATA Urban Intact Row (1 of 10) Face on Setback Line Row Building/Flat Fro Rectangular 2 plus basement	ont			Contributing Status	
Racial Segregation Standard Segregation	atus: BIZE DATA Urban Intact Row (1 of 10) Face on Setback Line Row Building/Flat Fro Rectangular 2 plus basement	ont			Contributing Status	
Racial Segregation St SETTING/SHAPE/S Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length:	atus: BIZE DATA Urban Intact Row (1 of 10) Face on Setback Line Row Building/Flat Fro Rectangular 2 plus basement	Outbuik			Contributing Status	
Racial Segregation Standard Segregation Standard Segregation Standard Segregation Standard Segregation Standard Segregation Standard Segregation Segre	atus: BIZE DATA Urban Intact Row (1 of 10) Face on Setback Line Row Building/Flat Fro Rectangular 2 plus basement	Outbuik	ding Type		Contributing Status	
Racial Segregation St SETTING/SHAPE/S Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length:	atus: BIZE DATA Urban Intact Row (1 of 10) Face on Setback Line Row Building/Flat Fro Rectangular 2 plus basement	Outbuik	ding Type		Contributing Status	

Architectural Style(s)					
Italianate			_		
Exterior & Architectur	al Notes:				
rowhouses construction foundation. The façallocated above the formodillions, dentil must be dwelling. The normolded hood with smetal hand rails prosash windows and I second story windo	ucted in 1876, this two- cted from the same per ade (west elevation) is oundation. A sloping ro- olding, end brackets all orthernmost bay of the crolled consoles surmivide access to the prinate soldier brick segn ws have header brick segn	mit (#1). The dwelling if faced with stretcher-bo of caps the dwelling and a frieze. An interior first story holds a sing ounts the door opening nary entrance. All wind nental arches. The first ills. The rear (east) ele	is constructed of brick ond brick. A brick wate nd is highlighted by a brick chimney rises frace	and is set on a crtable spans the prominent mold om the north (sind a one-light trwood pilasters. Agade hold 1/1, ce rowlock brick vith 1/1, double-	solid, raised e façade and is ed cornice with de) elevation of ansom. A simple Metal steps with louble-hung, vinyl- sills, while the hung, vinyl-sash
feet from the brick s by a wood picket fer sidewalk. The rear y dwelling.	o-story rowhouse is lo idewalk. The dwelling nce with brick posts. A ard is enclosed with a	is adjacent to 617 and brick walkway leads fr	621 10th Street, N.E. Trom the primary entrar	he grassy front ace of the dwelling	yard is encircled ng and ends at the
NOTABLE FEATU	RES DATA				
EXTERIOR MATE	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
M-II 0					
Wall Component	Material	Color	Treatment	Source	
Facade	Material Brick	Color	Treatment Stretcher Bond	Source	
<u>.</u>	Brick	Color		Source Source	
Facade	Brick				
Facade Structure Component	Brick Material				
Facade Structure Component Foundation	Brick Material Unknown				
Facade Structure Component Foundation Walls	Brick Material Unknown				
Facade Structure Component Foundation Walls	Brick Material Unknown Brick				
Facade Structure Component Foundation Walls Materials Notes:	Brick Material Unknown Brick			Source	Material
Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/II	Brick Material Unknown Brick	Feature	Stretcher Bond	Source	Material Vinyl
Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/III Window Location	Brick Material Unknown Brick NTERIOR DATA Aperture Shape	Feature	Stretcher Bond Light	Source	

Window Location	Aperture Shape	Type	Lights	Material	
Facade	Rectangular	Dbl-Hung	1/1	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single	Paneled	Unknown	
Notable Interior Plan(s)			Notable Interior Feature(s)		

PLAN/SURVEY/DESIGNATION DATA

Interior Notes:

Neighborhood: **Capitol Hill** Historic District(s) Subdivision: Ward/ANC:

Designation Event(s) Zoning: Contributing:

Capitol Hill F & G Streets (2010)

Permit Research Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 619_10th_Street_NE_facade_looking_E.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 619_10th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 619_10th_Street_NE_rear_looking_W.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

Remarks

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

05/12/1876 1 Build

Number Type

Permit Issue Date

Permit Notes:				
BIBLIOGRAPHIC DATA				
Short Citation	Туре	Date	Remarks	
Bibliographic Notes:				
SIGNIFICANCE DATA				
Study Unit				
Code Criteria				
DATA PROCESSING EVENTS DATA				
DATA PROCESSING EVENTS DATA				

Date	Individual	Action	
3/8/2010	Dayton (MSD), Maria	Record Updated	
3/4/2010	Dayton (MSD), Maria	Record Updated	
3/4/2010	Dayton (MSD), Maria	Record Created	

Tuesday, June 25, 2013 ID_Number: 0960-0030 Page 4

ID Number: 0960-0031

BASICS DATA

ID Number: 0960-0031	Year Built: 1876	Data Source: Permi	t	
Number Extended Street	(Quad Type of Address		
621 10th Street		NE Current		
Name(s)	Type of N	ame		
Rowhouse, 621 10th Street, N.E.	Common			
TaxCode1 TaxCode2 TaxCode3 Typ 0960/0031 Sq	pe Explain uare/Lot Current			
STATUS/PURPOSE/USE DATA				
Resource Type: Building	Status	Current: Extant		
Desig. Status: Historic	Quality			
Purpose: Rowhouse	Condit	ion: Good		
	art Source S	Stop Source	Explain	
Residential (Single-Family) 18	76 Permit		Original	
Residential (Multi-Family)			Current	
CONSTRUCTION DATA				
Construction Event Start	Source St	op Source	Cost Source	
Orig Construction 1876	Permit		2500 Permit	
Construction Event Ass	sociation	Associated N	ame	
Orig Construction Ow	vner	Farnham, E.	D.	
Construction Notes:				
One of ten rowhouses constructed fro	om the same permit (#1).		
PEOPLE/EVENTS DATA				
Racial Segregation Status:				
SETTING/SHAPE/SIZE DATA				
Surroundings: Urban	Cros	ss Reference Notes:		
Streetscape: Intact				
Relate to Othr Bldgs: Row (1 of 10)	Line			
Relate to Street: Face on Setback Massing: Row Building/Fla				
Footprint: Rectangular				
Number Stories: 2 plus baser	ment			
Bays Wide: 3				
Height:				
	Outbuilding ²	Гуре	Contributing Status	
Width:	Outbuilding ¹	Гуре	Contributing Status	
Width: Depth/Length:	Outbuilding	Гуре	Contributing Status	
Width:	Outbuilding	Гуре	Contributing Status	
Width: Depth/Length: SqFt: Volume: Lot Width			Contributing Status	
Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length:	Outbuilding Outbuilding		Contributing Status	
Width: Depth/Length: SqFt: Volume: Lot Width			Contributing Status	

Architectural Style(s)					
Italianate	-	-	_		
Exterior & Architectura	al Notes:				
owhouses constructoundation. The faça açade and is located wood cornice with make foundation. The isimple molded hood steps with metal hanof the façade hold 1/ The foundation is piedouble-hung, vinyl-s	teted in 1876, this two- ted from the same per de (west elevation) is f d above the foundation notillions, dentil moldi northernmost bay of th with scrolled console d rails provide access 1, double-hung, vinyl-serced by 6/6, double-hu ash windows and a sir d the windows also ha	mit (#1). The dwelling if faced with stretcher-both. A sloping roof caps in ing, end brackets and a ne first story holds a si is surmounts the door to the primary entrances sash windows and have ung, wood-sash windongle-leaf multi-light wo	is constructed of brice ond brick. A three-counte dwelling and is his frieze. A single-leaf ngle-leaf paneled wo opening, which is flace. All window opening soldier brick segmens. The rear (east) el	ck and is set on urse brick water ighlighted by a wood door with od door and a conked by wood pags on the first ental arches and evation is fenes	a solid, raised rtable spans the prominent molded in nine-lights pierces one-light transom. A bilasters. Metal and second stories d header brick sills. strated with 1/1,
ite Notes:					
by a wood picket fen sidewalk. The grassy	idewalk. The dwelling in ce with brick posts. A rear yard is bisected in alley is located east of the RES DATA	brick walkway leads fr by a concrete walkway	om the primary entra	nce of the dwel	ling and ends at the
Component	Featu	ILO			
EXTERIOR MATER	RIALS DATA Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Structure Component					
	Unknown				
Foundation	Unknown Brick				
Foundation Walls					
Foundation Walls Materials Notes:	Brick				
Foundation Walls Materials Notes:	Brick	Туре	Lig	yhts	Material
Foundation Walls Materials Notes: WINDOW/DOOR/IN	Brick	Type Dbl-Hung	Lig 6/6		Material Wood
Foundation Walls Materials Notes: WINDOW/DOOR/IN Window Location Basemt Windows	Brick ITERIOR DATA Aperture Shape	* '		5	
Foundation Walls Materials Notes: WINDOW/DOOR/IN Window Location	Brick ITERIOR DATA Aperture Shape Rectangular	Dbl-Hung	6/6 1/1	5	Wood

Window Location	Aperture Shape	Туре	Lights	Material
Basemt Windows	Rectangular	Dbl-Hung	6/6	Wood
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single		Wood/Glass
Main Door	Rectangular	Single	Paneled	Wood
Notable Interior Plan	(s)		Notable Interior Feature(s)	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Capitol Hill Neighborhood:

Historic District(s) Cubdivision.

Subulvision. Ward/ANC:		
Zoning:	Designation Event(s)	
Contributing:		
Survey(s)	Level(s) of Investigation	
Capitol Hill F & G Streets (2010)	Permit Research	
	Reconnaissance Survey	

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0960\

File: 621_10th_Street_NE_facade_looking_E.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 621_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 621_10th_Street_NE_rear_looking_W.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Туре		Remarks		
05/12/1876	1	Build				
Permit Notes:						
BIBLIOGRAPHIC DATA						
Short Citation			Туре	Date	Remarks	
Bibliographic Notes:						
SIGNIFICANCE DATA						
Study Unit						
Code Criteria						
DATA PROCESSING EVEN	ITS DAT	A				

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0031 Page 4

ID Number: 0960-0032

BASICS DATA

ID Number: 0960-0032 Year Built: 1876 Data Source: **Permit**

Quad Type of Address Number Extended Street

623 10th Street Current

Type of Name Name(s)

Rowhouse, 623 10th Street, N.E. Common

TaxCode1 TaxCode2 TaxCode3 Explain 0960/0032 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Historic Desig. Status: Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain Residential (Single-Family) 1876 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Addition pre 1928 Site

Visit/Map

2500 Permit **Orig Construction** 1876 **Permit**

Construction Event Associated Name Association

Chappel, L. Owner Chappel, L.

Construction Notes:

One of three rowhouses constructed from the same permit (#4).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID Number: 0960-0032 Page 1

Surroundings:	Urban	Cross Refe	rence Notes:		
Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Intact Row (1 of 3) Face on Setback Line Row Building/Flat Front Rectangle Ad				
Number Stories:	2 plus basement				
Bays Wide:	3				
Height: Width:		Outbuilding Type	C	contributing Status	
Depth/Length:					
SqFt:					
Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes:			
Lot SqFt: Acreage:					
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Italianate					
Exterior & Architectura	al Notes:				
of the dwelling. A sin story holds a single-consoles surmounts access to the primar 6/6 vinyl muntins an with a 1/1, double-husingle-leaf paneled rwindows also have a A second story encles Sanborn map. The waps the addition, we site Notes: March 2010: This tw	ngle-leaf paneled wood door wite the door opening, which is the door opening, which is ty entrance. All window oped have soldier brick segmenting, vinyl-sash window, a 1 metal door with lights. All open owlock brick sills.	or with lights pierces the lights and a one-list flanked by wood point on the façade intal arches and row the flanked by wood points are surmount the southernmost light vinyl siding one-light vinyl with on the east side of	s the foundation. The ight transom. A sinilasters. Brick step is hold 1/1, double-flock brick sills. The ight-sash window with the by soldier brick by soldier brick supported by swindows.	ises from the north (side) el he northernmost bay of the northernmost bay of the nple molded hood with folia is with metal hand rails proving, vinyl-sash windows we rear (east) elevation is fer ith false 6/6 vinyl muntins, aick segmental arches and the vation and is noted on the 19 square wood posts. A shed	first ted vide ith false estrated and a e
trees and shrubs and the dwelling and end	d is bounded by a metal mids at the sidewalk. The rear	lled point fence. A c	oncrete walkway le	The front yard features mat eads from the primary entral alley is located east of the d	nce of
NOTABLE FEATU					
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		American Bond		
Structure Component	Material	Feature		Source	
Foundation	Unknown				
Walls	Brick				

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single	Paneled	Wood/Glass
Main Door	Rectangular	Single	Paneled	Wood/Glass
Notable Interior Plan	n(s)		Notable Interior Feature(s)	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

ing: Designation Event(s)

Survey(s) Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 623_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0960\

File: 623_10th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:





Ca		

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 623_10th_Street_NE_rear_looking_W.JPG

Photog: Date::



Code:: Fr: **PHOTOS - B/W OR NON-DIGITIZED** Photo Code Roll Frame(s) Date Photographer Caption **MISCELLANEOUS NOTES DATA** Notes: **PERMIT DATA** Permit Issue Date Number Type Remarks 09/01/1876 4 Build Permit Notes: **BIBLIOGRAPHIC DATA Short Citation** Type Date Remarks Bibliographic Notes: SIGNIFICANCE DATA Study Unit Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Created

ID Number: 0960-0033

BASICS DATA

ID Number: 0960	-0033	Year E	Built: 18 7	76 Dat	ta Source:	Permit		
Number Extended	Street			Quad	d Type of Addre	ess		
625	10th Street			NE	Current			
Name(s)			Т	ype of Name				
Rowhouse, 625 10th	Street, N.E.		С	ommon				
TaxCode1 TaxCode	2 TaxCode3	Туре	E	Explain				
0960/0033		Square/l		Current				
STATUS/PURPOS	E/USE DAT	4						
Resource Type: Buil	_				rent: Extant			
•	oric			Quality:				
Purpose: Row	house			Condition:	Good			
Function/Use		Start	Sourc	e Stop	So	urce	Explain	
Residential (Single-F		1876	Perm	it			Original	
Residential (Multi-Fa	imily)						Current	
CONSTRUCTION I	7 4 7 4							
Construction Event		Start	Source	Stop	Source		Cost Source	
Orig Construction		876	Permit	Отор	Oddicc		2500 Permit	
Construction Event		Associati	on		Associa	ated Na	ma	
Orig Construction		Owner	OH		Chapp		ille	
•						,		
Construction Notes: One of three rowhou	ises construc	ted from t	he same	nermit (#4)				
				p =				
PEOPLE/EVENTS	DATA							
Racial Segregation St	atus:							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban			Cross R	eference Notes	S:		
Streetscape:	Intact]
Relate to Othr Bldgs:	Row (1 of 3)							
Relate to Street:	Face on Set							
Massing:	Row Buildin		nt					
Footprint:	Rectangular							
Number Stories:	_	pasement						
Bays Wide: Height:	3		Out	building Type		0	Contributing Status	
Width:			Outi	bulluling Type	7		onthibuting Status	=
Depth/Length:								
SqFt:								
Volume:								
Lot Width			O. 4	huildina Nata				
Lot Depth/Length: Lot SqFt:			Outi	building Note	:5.]
Acreage:								
Has Driveway:								

Architectural Ctula/-\					
Architectural Style(s) Italianate			_		
Exterior & Architectura	al Notos:				
rowhouses construc and is set on a solid, foundation. A sloping dentil molding, end k dwelling. A single-lea leaf paneled wood do opening, which is fla All window openings and header brick sille light transom. A one-	ted from the same per raised foundation. A to groof caps the dwelling rackets and a frieze. A far paneled wood door for and a one-light trainked by wood pilasters on the façade hold 1/s. The rear (east) eleva	story, three-bay Italian mit (#4). The dwelling three-course brick wat an and is highlighted ban interior-side brick opierces the foundation as metal steps with metal, double-hung, vinyl-stion is fenestrated wit-frame deck projects fe the deck.	is constructed of sever tertable spans the factor by a prominent molder thimney rises from the n. The northernmost be the dood with scrolled tetal hand rails provider sash windows and ha th sliding glass doors	en-course, Amerade and is located wood cornice to north (side) eleay of the first structure surmo e access to the power soldier brick. All openings ar	ican-bond brick and above the with modillions, vation of the bry holds a single- unts the door rimary entrance. segmental arches e topped by a one-
Site Notes:		<u> </u>			
feet from the brick si landscaped with mat	dewalk. The dwelling i ure shrubs and small	cated on the east side is adjacent to 623 and trees and is encircled sidewalk. The rear yar	627 10th Street, N.E. by a metal chain-link	The grassy front fence. A concret	yard is e walkway leads
NOTABLE FEATUR	RES DATA				
Component	Featu	ıre			
EXTERIOR MATER	IALS DATA		Treatment	Source	
EXTERIOR MATER		ure Color	Treatment Not Visible	Source	
EXTERIOR MATER Roof Component Sloped	NATA Material			Source Source	
EXTERIOR MATER Roof Component Sloped Wall Component	Material Not Visible	Color	Not Visible		
EXTERIOR MATER Roof Component Sloped Wall Component Facade	Material Not Visible Material	Color	Not Visible Treatment		
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component	Material Material Material Material Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation	Material Not Visible Material Brick Material	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Material Not Visible Material Brick Material Unknown	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls	Material Not Visible Material Brick Material Unknown	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Unknown Brick	Color	Not Visible Treatment	Source	
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes:	Material Not Visible Material Brick Material Unknown Brick	Color	Not Visible Treatment	Source	Material
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/IN	Material Not Visible Material Brick Material Unknown Brick	Color Color Feature	Not Visible Treatment American Bond	Source Source	Material Vinyl
EXTERIOR MATER Roof Component Sloped Wall Component Facade Structure Component Foundation Walls Materials Notes: WINDOW/DOOR/IN Window Location Facade Door Location	Material Not Visible Material Brick Material Unknown Brick	Color Color Feature	Not Visible Treatment American Bond Lig	Source Source	

Window Location	Aperture Shape	Туре	Lights	Material	
Facade	Rectangular	Dbl-Hung	1/1	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single	Paneled	Wood	
Main Door	Rectangular	Single	Paneled	Wood	
Notable Interior Plan	n(s)	1	Notable Interior Feature(s)		

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision: Mard/ANIC

Historic District(s)

vvaiu/Aivo.	
Zoning:	

Designation Event(s) Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 625_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 625_10th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Fr: Code:: R:

Caption:

C:\Users\CHRS\Documents\CHRS Path:

> Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 625_10th_Street_NE_rear_looking_W.JPG

Date:: Photog:

Fr: Code:: R:







PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

Permit Notes:			

BIBLIOGRAPHIC DATA

Short Citation	Type	Date	Remarks	
Bibliographic Notes:				

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action	
3/8/2010	Dayton (MSD), Maria	Record Updated	
3/4/2010	Dayton (MSD), Maria	Record Updated	
3/4/2010	Dayton (MSD), Maria	Record Created	

ID Number: 0960-0034

BASICS DATA

ID Number: 0960	-0034	Year I	Built: 1876	Data	Source: Permit	t	
Number Extended	Street			Quad T	ype of Address		
627	10th Street				urrent		
Name(s)			Тур	e of Name			
Rowhouse, 627 10th	Street, N.E.			nmon	_		
TaxCode1 TaxCode	2 TaxCode3	Type	Ex	olain			
0960/0034		Square/		rrent			
STATUS/PURPOS	E/USE DATA	١					
Resource Type: Buil	-			Status Currer	nt: Extant		
_	toric vhouse			Quality: Condition:	Good		
NOV	viiouse		·				
Function/Use	-amily)	Start 1876	Source Permit	Stop	Source	Explain	
Residential (Single-F Residential (Multi-Fa		10/0	Permit			Original Current	
(,						
CONSTRUCTION	DATA						
Construction Event	Si	tart	Source	Stop	Source	Cost Source	
Orig Construction	18	876	Permit			2500 Permit	
Construction Event		Associat	tion		Associated N	ame	
Orig Construction		Owner			Chappel, L.		
Construction Notes:							
One of three rowhou	ises construc	ted from t	the same pe	rmit (#4).			
PEOPLE/EVENTS	DATA						
Racial Segregation St							
radiai Gegregation G	atuo.						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Refe	erence Notes:		
Streetscape:	Intact						
Relate to Othr Bldgs:							
Relate to Street:	Face on Sett		4				
Massing: Footprint:	Row Building Rectangular	g/Fiat Fro	nτ				
Number Stories:		acamant					
Bays Wide:	2 plus b	asement					
Height:			Outbu	ilding Type		Contributing Status	
Width:							
Depth/Length:							
SqFt: Volume:							
Lot Width							
Lot Width Lot Depth/Length:			Outbu	ilding Notes:			
Lot Width Lot Depth/Length: Lot SqFt:			Outbu	ilding Notes:			
Lot Width Lot Depth/Length:			Outbu	ilding Notes:			

CTVI	/TEDI	$D\Delta T\Delta$

Architectural Style(s)

Italianate

Exterior & Architectural Notes:

March 2010: Constructed in 1876, this two-story, three-bay Italianate-style single-family rowhouse is one of three rowhouses constructed from the same permit (#4). The dwelling is constructed of seven-course, American-bond brick and is set on a solid, raised foundation. A three-course brick watertable spans the façade and is located above the foundation. A sloping roof caps the dwelling and is highlighted by a prominent molded wood cornice with modillions, dentil molding, end brackets and a frieze. A single-leaf door pierces the foundation. The northernmost bay of the first story holds a replacement, single-leaf paneled door with lights and a blind transom. A simple molded hood with scrolled consoles surmounts the door opening, which is flanked by wood pilasters. Metal steps with metal hand rails provide access to the primary entrance. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows and have soldier brick segmental arches and rowlock brick sills. The rear (east) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows and a single-leaf paneled wood door. A one-story wood-frame deck extends from the northernmost bay and is set on a square wood post foundation. Square wood balusters complement the deck.

Site Notes:

March 2010: This two-story rowhouse is located on the east side of 10th Street, N.E. and is set back approximately ten feet from the brick sidewalk. The south (side) elevation of the dwelling is adjacent to 625 10th Street, N.E. and an alley runs parallel to the north (side) elevation of the dwelling. The front yard is predominantly paved with concrete and is encircled by a metal chain-link fence. The grassy rear yard is landscaped with small trees and is bounded by metal chain-link fencing. An alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Unknown			
Walls	Brick			
Materials Notes:				
Materials Notes:				

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single		Unknown
Main Door	Rectangular	Single	Paneled	Unknown w/Lights
Notable Interior Plar	n(s)		Notable Interior Feature(s)	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)
Subdivision:

Ward/ANC:

Zoning:		
Contributing:		

Designation Event(s)

Survey(s)

Capitol Hill F & G Streets (2010)

Permit Research

Reconnaissance Survey

Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0960\

File: 627_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 627_10th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 627_10th_Street_NE_rear_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:







PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

09/01/1876 4 Build

Permit Notes:				
BIBLIOGRAPHIC DATA				
Short Citation	Type	Date	Remarks	
Bibliographic Notes:				
SIGNIFICANCE DATA				
Study Unit				
Code Criteria				
DATA BROCESSING EVENTS D				

Date	Individual	Action	
3/8/2010	Dayton (MSD), Maria	Record Updated	
3/4/2010	Dayton (MSD), Maria	Record Updated	
3/4/2010	Dayton (MSD), Maria	Record Created	

Tuesday, June 25, 2013 ID_Number: 0960-0034 Page 4

ID Number: 0960-0800

BASICS DATA

ID Number: 0960-0800 Year Built: 1890 Data Source: Permit

Number Extended Street Quad Type of Address

629 10th Street NE Current

Name(s) Type of Name

Single Dwelling, 629 10th Street, N.E. Common

 TaxCode1
 TaxCode2
 TaxCode3
 Type
 Explain

 0960/0800
 Square/Lot
 Permit

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1890 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Rear Addition c. 1960 Site Visit/Map

visiviviap

Orig Construction 1890 Permit 2000 Permit

 Construction Event
 Association
 Associated Name

 Orig Construction
 Owner
 Weschler, Charles

 Summerlott, Charles A.
 Builder
 Summerlott, Charles A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0960-0800 Page 1

Surroundings:	Urban	Cross Reference Notes:
Streetscape:	Intact	
Relate to Othr Bldgs:	Attached (1 side)	
Relate to Street:	Face on Setback Line	
Massing:	Vertical Box/rectang bay	
Footprint:	Rectangle Ad	
	_	
Number Stories:	2 plus basement	
Bays Wide:	2	Outh vilding Time
Height: Width:	4-	Outbuilding Type Contributing Status
Depth/Length:	17 40	Garage
SqFt:	40	
Volume:		
Lot Width		
Lot Depth/Length:		Outbuilding Notes:
Lot SqFt:		March 2010: A one-story, one-bay garage is located east of the
Acreage:		dwelling and was constructed c. 1925. The garage is
		constructed of five-course, American-bond brick and is set on
Has Driveway:		a solid brick foundation. A sloping roof caps the garage. The façade (east elevation) is pierced by a single opening that is
		covered by a roll-up corrugated metal door.
		, , ,
STYLE/EXTERIOR	ΠΔΤΔ	
Architectural Style(s)	DATA	
Queen Anne		
Italianate		
Exterior & Architectur		
		Summerlott, this two-story, two-bay Queen Anne-style single-family The dwelling is constructed of brick and is set on a solid brick
		with pressed stretcher-bond brick. A three course brick watertable is
1	` ,	s span the façade below the first and second story window openings,
	•	g courses. A sloping roof caps the dwelling and is highlighted by a
		interior-side chimney rises from the south (side) elevation of the dwelling the foundation of the dwelling. The northernmost bay of the first story
		ats and a one-light wood transom. A soldier brick segmental arch with
header cap surmour	nts the transom. Cast iron s	teps and railings provide access to the primary entrance. The second
		ash window. A three-sided, rectangular bay projects from the
		Ill height of the dwelling. The bay has the material treatment of the main vinyl-sash windows. All first and second story windows have concrete
		eader brick caps. The foundation window is topped by a two-course,
		sed brick panels divide the first and second stories. The south (side)
		vinyl-sash windows, which have concrete sills and two-course, rowlock on is pierced by sliding glass doros and a 1/1, double-hung, vinyl-sash
window.	nes. The real (east) elevation	in is pierced by similing glass doros and a 1/1, double-many, viriyi-sasii
		ear (east) elevation of the dwelling and is first noted on the 1904 Sanborn constructed c. 1960. The wood-frame porch is set on a solid foundation
		ory deck. The first story has been partially enclosed with T-111 siding.
	ers encircle the second sto	
Site Notes:		
	ngle-family dwelling is locat	ed on the east side of 10th Street, N.E. and is set back approximately five
		evation of the dwelling is adjacent to 631 10th Street, N.E. and a brick
		of the dwelling. The small grassy front yard directly abuts the brick
	e walkway leads from the proceed ocated east of the dwelling	rimary entrance and ends at the sidewalk. The rear yard is edged by wood
ionomy. An aney is i	Souted east of the aweiling	
NOTABLE FEATU	DEC DATA	
NOTABLE FEATU	NES DATA	
Component	Feature	

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		_
Wall Component	Material	Color	Treatment	Source	
Facade	Pressed Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Brick				-
Walls	Brick				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 FIr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single		Wood
Main Door	Rectangular	Single	Paneled	Wood/Glass
Notable Interior Plan	n(s)		Notable Interior Feature(s)	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Capitol Hill Neighborhood: Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s) Capitol Hill F & G Streets (2010) Level(s) of Investigation **Permit Research**

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0960\

File: 629_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 629_10th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 629_10th_Street_NE_rear_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

02/17/1890 1451 Build

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
3/8/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0800 Page 5

ID Number: 0960-0065

BASICS DATA

ID Number: 0960	-0065 Year B	uilt: 1892	Data	Source: Perr	nit	
Number Extended	Street		Quad	Type of Address		
631	10th Street		NE	Current		
Name(s)		Туре	of Name			
Single Dwelling, 631	10th Street, N.E.	Comi			_	
TaxCode1 TaxCode	2 TaxCode3 Type	Expla	ain			
0960/0065	Square/L				-	
	•					
STATUS/PURPOS	E/USE DATA					
Resource Type: Bui	lding	St	atus Curre	ent: Extant		
o .	toric	Qı	uality:			
Purpose: Roy	vhouse	Co	ondition:	Good		
Function/Use	Start	Source	Stop	Source	e Explain	
Residential (Single-I	amily) 1892	Permit			Original	
Residential (Multi-Fa	amily)				Current	
CONSTRUCTION						
Construction Event		Source	Stop	Source	Cost Source	
Orig Construction	1892 l	Permit			2000 Permit	
Construction Event	Association	n		Associated		
Orig Construction Orig Construction	Builder Owner			Hought, F. Hought, F.		
	Owner			Hought, F.		
Constructed with 63	2 40th Street N.E. from 1	ha aama na	:t /#00	16)		
Constructed with 03	3 10th Street, N.E. from t	ne same pe	11111t (#00	10).		
PEOPLE/EVENTS	DATA					
Racial Segregation S	tatus:					
SETTING/SHAPE/S	SIZE DATA					
Surroundings:	Urban		Cross Re	ference Notes:		
Streetscape:	Intact					
Relate to Othr Bldgs:						
Relate to Street: Massing:	Face on Setback Line Vertical Box/rectang ba	v				
Footprint:	L-Shaped	y				
Number Stories:	2 plus basement					
Bays Wide:	2 plus basement					
Height:		Outbuild	ling Type		Contributing Status	
Width:	23					<u> </u>
Depth/Length:	32					
SqFt: Volume:						
Lot Width						
Lot Depth/Length:		Outbuild	ling Notes	:		
Lot SqFt:						
Acreage:						
Has Driveway:						

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

March 2010: Constructed in 1892 by F.G. Hought, this two-story, two-bay Queen Anne-style single-family dwelling was constructed from the same permit (#0016) as 633 10th Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation; the façade (west elevation) is faced with pressed stretcher-bond brick. A sloping roof caps the dwelling and is highlighted by a molded cornice and a corbeled brick cornice. An interior chimney rises from the dwelling and is parged. A brick watertable spans the façade and is located above the foundation. Sill courses are located at the first and second stories. A string course, composed of nebule molding, spans the façade and is sited below the corbeled brick cornice. A single-leaf paneled metal door with a blind transom pierces the foundation. The northernmost bay of the first story holds a replacement, single-leaf paneled metal door with lights and a one-light wood transom. A soldier brick segmental arch with pearl molding surmounts the door opening, which is accessed via metal stairs. The second story opening holds a 1/1, double-hung, vinyl-sash window. A three-sided, rectangular bay extends from the southernmost bay of the façade and rises the full height of the dwelling. The bay has the same material treatment as the main block and is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows. All windows on the façade have concrete sills and the first and second story openings are topped by soldier brick segmental arches with pearl molding. The foundation openings are topped by rowlock brick segmental arches. The rear (east) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows.

A two-story ell extends from the northernmost bay of the rear elevation and is original. The ell is constructed of brick and is set on a solid foundation. A sloping roof caps the ell. Visible fenestration consists of a 1/1, double-hung, vinyl-sash window and a single-leaf door with lights and a one-light transom. The openings are topped by two-course, rowlock brick segmental arches and the window has a concrete sill. The second story openings have been infilled with brick. A one-story, full-width deck projects from the rear elevation and features square wood balusters.

Site Notes:

March 2010: This two-story dwelling is located on the east side of 10th Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 629 and 633 10th Street, N.E. The grassy front yard is encircled by a metal milled point fence. The rear yard is paved with concrete and accessed via swing-out metal chain-link gates. An alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component	onent Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			
Materials Notes:				

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single	Paneled	Metal	
Main Door	Rectangular	Single	Paneled	Metal/Glas	
Notable Interior Plan(s)			Notable Interior Feature(s)		

Tuesday, June 25, 2013 ID_Number: 0960-0065 Page 2

١	Inter	ior	N	otes

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Capitol Hill F & G Streets (2010)

Subdivision: Ward/ANC: Zoning:

Contributing:

Designation Event(s)

Historic District(s)

Survey(s)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 631_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 631_10th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 631_10th_Street_NE_rear_looking_W.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES	S DATA					
Notes:						
PERMIT DATA						
Permit Issue Date	Number Type		Remarks			
07/05/1892	0016 Build					
Permit Notes:						
BIBLIOGRAPHIC DATA						
Short Citation		Туре	Date	Remarks		
Bibliographic Notes:						<u></u>
SIGNIFICANCE DATA						
Study Unit						
Code Criteria					=	

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0065 Page 4

ID Number: 0960-0066

BASICS DATA

ID Number: 0960	9-0066 Year B	uilt: 1892	Data	Source: Permit		
Number Extended	Street		Ouad	Type of Address		
633	10th Street			Current		
Name(s)		Type	of Name			
Single Dwelling, 633	10th Street, N.E.	Comn				
TaxCode1 TaxCode 0960/0066	2 TaxCode3 Type Square/L	Expla ot Curre				
STATUS/PURPOS	E/USE DATA					
Resource Type: Bui	lding	Sta	atus Curre	nt: Extant		
o .	toric		ıality:			
Purpose: Res	idential	Co	ndition:	Good		
Function/Use	Start	Source	Stop	Source	Explain	
Residential (Single-I		Permit			Original Current	
Residential (Multi-Fa	amiiy)				Current	
CONSTRUCTION	DATA					
Construction Event		Source	Stop	Source	Cost Source	
Orig Construction	1892	Permit			2000 Permit	
Construction Event	Association	on		Associated Na	me	
Orig Construction Orig Construction	Builder Owner			Hought, F.G. Hought, F.G.		
	C IIII C			nought, no		
Constructed with 63	1 10th Street, N.E. from t	he same per	mit (#001	6).		
PEOPLE/EVENTS	DATA					
Racial Segregation S	tatus:					
SETTING/SHAPE/S	SIZE DATA					
Surroundings:	Urban		Cross Ref	erence Notes:		
Streetscape:	Intact					
Relate to Othr Bldgs:						
Relate to Street:	Face on Setback Line	.,				
Massing: Footprint:	Vertical Box/rectang ba L-Shaped	У				
Number Stories:	2 plus basement					
Bays Wide:	2 plus basement					
Height:		Outbuild	ing Type	C	Contributing Status	_
Width:	23					
Depth/Length: SqFt:	32					
Volume:						
Lot Width						
Lot Depth/Length:		Outbuild	ing Notes:			1
Lot SqFt: Acreage:						
Has Driveway:						

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

March 2010: Constructed in 1892 by F.G. Hought, this two-story, two-bay Queen Anne-style single-family dwelling was constructed from the same permit (#0016) as 631 10th Street, N.E. The dwelling is constructed of brick and is set on a solid, raised brick foundation; the facade (west elevation) is faced with pressed stretcher-bond brick. A sloping roof caps the dwelling and is highlighted by a molded cornice and a corbeled brick cornice. An interior-side brick chimney rises from the north (side) elevation of the dwelling. A brick watertable spans the facade and is located above the foundation. Sill courses are located at the first and second stories. A string course, composed of nebule molding, spans the façade and is sited below the corbeled brick cornice. A single-leaf paneled wood door with lights and a one-light transom pierce the foundation. The southernmost bay of the first story holds a replacement, single-leaf paneled metal door with lights and a one-light wood transom. A self-supporting metal awning shelters the entry, which is also surmounted by a soldier brick segmental arch with pearl molding. Metal steps provide access to the entry. The second story opening holds a 1/1, double-hung, vinyl-sash window. A three-sided, rectangular bay extends from the northernmost bay of the facade and rises the full height of the dwelling. The bay has the same material treatment as the main block and is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows. All windows on the façade have concrete sills and the first and second story openings are topped by soldier brick segmental arches with pearl molding. The foundation openings are topped by rowlock brick segmental arches. The rear (east) elevation is fenestrated with 2/2, double-hung, wood-sash windows.

A two-story ell extends from the southernmost bay of the rear elevation and is original. The parged ell is constructed of brick and is set on a solid foundation. A sloping roof caps the ell and is pierced by an interior brick chimney. Visible fenestration consists of a 1/1, double-hung, wood-sash window and a single-leaf paneled wood door with lights. The original transom opening is boarded. Wood steps provide access to the entry. The second story openings have been infilled with brick and are parged.

Site Notes:

March 2010: This two-story dwelling is located on the east side of 10th Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 631 and 635 10th Street, N.E. The front yard is landscaped with mature shrubs. The rear yard is enclosed with wood fencing. An alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component Fea	ature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			
Materials Notes:				

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single	Paneled	Wood/Glass	
Main Door	Rectangular	Single	Paneled	Metal	
Notable Interior Plan	n(s)		Notable Interior Feature(s)		

Tuesday, June 25, 2013 ID_Number: 0960-0066 Page 2

I	lr	١t	e	rio	or	Ν	lo	te	S

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Historic District(s)

Survey(s)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Capitol Hill F & G Streets (2010)

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 633_10th_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 633_10th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 633_10th_Street_NE_rear_looking_W.JPG

Date:: Photog:

Code:: R: Fr:





PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES	S DATA					
Notes:						
PERMIT DATA						
Permit Issue Date	Number Type		Remarks			
07/05/1892	0016 Build					-
Permit Notes:						
						J
BIBLIOGRAPHIC DATA						
Short Citation		Туре	Date	Remarks		
						=
Bibliographic Notes:						
						J
SIGNIFICANCE DATA						
Study Unit						
Code Criteria						

DATA PROCESSING EVENTS DATA

3/8/2010 Dayton (MSD), Maria Record Updated 3/4/2010 Dayton (MSD), Maria Record Updated 3/4/2010 Dayton (MSD), Maria Record Created	Date	Individual	Action
, , , , , , , , , , , , , , , , , , , ,	3/8/2010	Dayton (MSD), Maria	Record Updated
3/4/2010 Dayton (MSD), Maria Record Created	3/4/2010	Dayton (MSD), Maria	Record Updated
	3/4/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0066 Page 4

ID Number: 0960-0062

BASICS DATA

ID Number: 0960-0062 Year Built: 1910 Data Source: Permit

Number Extended Street Quad Type of Address

635 10th Street NE Current

Name(s) Type of Name

Rowhouse, 635 10th Street, N.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

0960/0062 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1910 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction c. 1960 Site

Visit/Map

Orig Construction 1910 Permit 2500 Permit

 Construction Event
 Association
 Associated Name

 Orig Construction
 Architect
 Wright & Hopkins

 Orig Construction
 Builder
 Wright & Hopkins

 Orig Construction
 Owner
 Wright & Hopkins

Construction Notes:

One of three rowhouses constructed from the same permit (#6682).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0960-0062 Page 1

Surroundings: Streetscape:	Urban Intact	Cross Refe	erence Notes:		
Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Row (1 of 3) Face on Setback Line Row Building/Front Porch Rectangular				
Number Stories: Bays Wide:	2 plus basement				
Height:	-	Outbuilding Type	Co	ontributing Status	
Width:	18	Garage			•
Depth/Length: SqFt: Volume: Lot Width	37				
Lot Depth/Length:		Outbuilding Notes:			1
Lot SqFt:			e-story, one-bay gara constructed c. 1925	age is located east of the	
Acreage:		Sanborn map, the	north (side) elevation	on of the garage is	
Has Driveway:		partially re-constr elevation is const roof caps the gara a roll-up paneled	ructed of American-	blocks. The south (side) bond brick. A sloping t elevation) is pierced by ning has also been	
STYLE/EXTERIOR	DATA				
Architectural Style(s) Classical Revival					
	al Natas:				
Exterior & Architecture March 2010: Constru	ai Notes: ucted in 1910 by Wright & H	opkins, this two-sto	orv. three-bay Classi	ical Revival-style single-far	nilv
is set on a solid con spans the first and s modillions. A single- single-leaf paneled v sash windows and h porch spans the faç- supported by battere A 1/1, double-hung, northernmost bay of windows. All window	three rowhouses constructed crete foundation; the façade second stories. A sloping rowhold pleaf paneled metal door piewood door and a one-light that the second is set on a stone for each of the rear elevation and is or wopenings on the rear elevation extends from the southern	e (west elevation) is of caps the dwellin rces the foundation ransom. All window is. Metal awnings s undation. The flat r on stone supports. the rear (east) elevatiginal. Visible fene ation have two-cou	s faced with Flemish g and is highlighted n. The southernmos or openings on the fathelter the second stoof of the porch has A metal awning projection. A three-sided, stration consists of rse, rowlock brick s	n-bond brick. A brick sill co I by a molded cornice with t bay of the first story hold acade hold 1/1, double-hun- tory openings. A one-story, s overhanging eaves and is jects from the facade of the canted bay projects from t 1/1, double-hung, vinyl-sas egmental arches and wood	s a g, vinyl- , two-bay s e porch. the sh
addition was construc	ucted on the footprint of an ted with T-111 siding and is	earlier addition tha	t is noted on the 19	28 Sanborn map. The wood	d-frame
Site Notes:	whouse is located on the ea	at aida of 10th Stra	ot N.E. and is set b	aak annravimataly fiya faat	from
the brick sidewalk. 1	The dwelling is adjacent to 6 ey is located east of the dwe	33 and 637 10th St			
NOTABLE FEATU	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	-
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	

Tuesday, June 25, 2013 ID_Number: 0960-0062 Page 2

Flemish Bond

Facade

Brick

Structure Component Material Feature Source

Foundation Concrete

Walls Brick

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
Facade	Rectangular	Dbl-Hung	1/1	Vinyl	
Door Location	Aperture Shape	Type	Pamels	Material	
Basement	Rectangular	Single	Paneled	Metal	
Main Door	Rectangular	Single	Paneled	Wood	
Notable Interior Plan(s)			Notable Interior Feature(s)		

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

ng: Designation Event(s)

Survey(s) Level(s) of Investigation

Capitol Hill F & G Streets (2010) Permit Research

Reconnaissance Survey

ID_Number: 0960-0062 Page 3

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 635_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:



Ca	- 4:	
ı.a	M	nn

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 635_10th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 635_10th_Street_NE_rear_looking_W.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption

MISCELLANEOUS NOTES DATA

Notes:

L			

PERMIT DATA

Permit Issue Date Number Type Remarks
05/26/1910 6682 Build

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0062 Page 5

ID Number: 0960-0063

BASICS DATA

ID Number: 0960-0063 Year Built: 1910 Data Source: **Permit**

Quad Type of Address Number Extended Street

637 10th Street Current

Type of Name Name(s)

Rowhouse, 637 10th Street, N.E. Common

TaxCode2 TaxCode3 Explain 0960/0063 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Condition: Rowhouse Good

Function/Use Start Source Stop Source Explain Residential (Single-Family) 1910 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Rear Addition c. 2008 Site

Visit/Map

Orig Construction 1910 **Permit** 2500 Permit

Associated Name Construction Event Association Orig Construction Architect Wright & Hopkins Builder Wright & Hopkins **Orig Construction Orig Construction** Owner Wright & Hopkins

Construction Notes:

One of three rowhouses constructed from the same permit (#6682).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID Number: 0960-0063 Page 1

Surroundings:	Urban	Cross Reference Notes:			
Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Intact Row (1 of 3) Face on Setback Line Row Building/Flat Front Rectangular				
Number Stories: Bays Wide: Height:	2 plus basement 3	Outbuilding Type	Co	ntributing Status	
Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length:	18 37	Outbuilding Notes			
Lot SqFt: Acreage: Has Driveway:		Culbuilding Notes	•		
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Classical Revival			_		
Exterior & Architectura	al Notes:				
modillions. A single- of the first story hole hold 1/1, double-hur full-width porch spa overhanging eaves a encircle the porch, v A two-story, full-wid addition is clad with fenestration consist	econd stories. A sloping re- leaf metal door and paired ds a single-leaf wood-frame ig, vinyl-sash windows with ns the façade and is set on and is supported by fluted a which is accessed via poure th addition is located on the Hardiplank siding and is set of a single-leaf wood-frame vinyl-sash windows with fa	sliding one-light was glass door and a in false 6/1 vinyl mu a brick pier found Tuscan columns the doncrete steps was erear (east) elevate on a solid found ne glass door with	vindows pierce the fo one-light transom. All antins and have concr ation. The half-hipped at are set on brick su with brick wing walls ion and was construct lation. A sloping roof a one-light transom a	undation. The southernmo I window openings on the rete sills and lintels. A one-diror of the porch has apports. Square wood baluin the southern end bay.	façade -story, sters ne
	o-story rowhouse is located		•	• •	
	idewalk. The dwelling is ad The rear yard is bounded b	-			anded
NOTABLE FEATU	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Flemish Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				

Tuesday, June 25, 2013 ID_Number: 0960-0063 Page 2

Walls

Brick

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material
Basemt Windows	Rectangular	Sliding	1/1	Vinyl
Facade	Rectangular	Dbl-Hung	1-light	Unknown
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single		Metal
Main Door	Rectangular	Single	Full Glass	Wood/Glass
Notable Interior Plan	(s)	1	Notable Interior Feature(s)	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision: Ward/ANC: Zoning: Contributing:

Survey(s)

Capitol Hill F & G Streets (2010)

Historic District(s)

Designation Event(s)

Level(s) of Investigation

Permit Research Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0960\

File: 637_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code::

R: Caption:

Fr:

Path: C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0960\

File: 637_10th_Street_NE_facade_looking_SE.JPG

Photog: Date::

Fr: Code:: R:





Ca		

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 637_10th_Street_NE_rear_looking_W.JPG

Date:: Photog:



Code:: Fr: **PHOTOS - B/W OR NON-DIGITIZED** Photo Code Roll Frame(s) Date Photographer Caption **MISCELLANEOUS NOTES DATA** Notes: **PERMIT DATA** Permit Issue Date Number Type Remarks 05/26/1910 6682 Build Permit Notes: **BIBLIOGRAPHIC DATA Short Citation** Type Date Remarks Bibliographic Notes: SIGNIFICANCE DATA Study Unit Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Created

ID Number: 0960-0064

BASICS DATA

ID Number: 0960-0064 Year Built: 1910 Data Source: Permit

Number Extended Street Quad Type of Address

639 10th Street NE Current

Name(s) Type of Name

Rowhouse, 639 10th Street, N.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

0960/0064 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1910 Permit Original Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1910 Permit 2500 Permit

 Construction Event
 Association
 Associated Name

 Orig Construction
 Architect
 Wright & Hopkins

 Orig Construction
 Builder
 Wright & Hopkins

 Orig Construction
 Owner
 Wright & Hopkins

Construction Notes:

One of three rowhouses constructed from the same permit (#6682).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0960-0064 Page 1

Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width	Urban Intact Row (1 of 3) Face on Setback Line Row Building/Front Porch Rectangular 2 plus basement 3 18 37	Cross Refe	erence Notes: Cont	ributing Status	
Lot Depth/Length:		Outbuilding Notes:			
Lot SqFt: Acreage:					
Has Driveway:					
Tido Diiveway.					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Classical Revival					
Exterior & Architectura				al Revival-style single-family	
topped by two-cours paneled wood door sash windows and h faced concrete block Tuscan wood colum poured concrete ste glass door with a on sided, canted bay pr of 1/1, double-hung, segmental arches ar	nave concrete sills and lintel it pier foundation. The half-h ns that are set on brick sup ps with rock-faced concrete e-light transom and 1/1, do ojects from the northernmo wood-sash windows. All wi	arches. The souther ansom. All windows. A one-story, two ipped roof of the p ports. Square wood block wing walls in able-hung, wood-sates bay of the rear e	ernmost bay of the firs openings on the faça -bay porch spans the orch has overhanging d balusters encircle th n the southern end ba ash windows pierce th levation and is origina	st story holds a single-leaf ade hold 1/1, double-hung, w façade and is set on a rock- geaves and is supported by the porch, which is accessed	via ree- sts
feet from the brick s	o-story rowhouse is located idewalk. The dwelling is adj all shrubs. The rear yard is o	acent to 637 and 64	11 10th Street, N.E. Th		ve
NOTABLE FEATU	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	_
Facade	Brick		Flemish Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				

Tuesday, June 25, 2013 ID_Number: 0960-0064 Page 2

Walls

Brick

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Basemt Windows	Rectangular	Fixed	1-light	Wood
Facade	Rectangular	Dbl-Hung	1/1	Wood
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single	Full Glass	Wood/Glass
Main Door	Rectangular	Single	Paneled	Wood/Glass
Notable Interior Plan	(s)		Notable Interior Feature(s)	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Subdivision: Ward/ANC: Zoning: Contributing:

Survey(s)

Capitol Hill F & G Streets (2010)

Historic District(s)

Designation Event(s)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 639_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0960\

File: 639_10th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:





Ca		

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 639_10th_Street_NE_rear_looking_W.JPG

Date:: Photog:



Code:: R: Fr: **PHOTOS - B/W OR NON-DIGITIZED** Photo Code Roll Frame(s) Date Photographer Caption **MISCELLANEOUS NOTES DATA** Notes: **PERMIT DATA** Permit Issue Date Number Type Remarks 05/26/1910 6682 Build Permit Notes: **BIBLIOGRAPHIC DATA Short Citation** Type Date Remarks Bibliographic Notes: SIGNIFICANCE DATA Study Unit Code Criteria

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Updated
3/4/2010	Dayton (MSD), Maria	Record Created

ID Number: 0960-0801

BASICS DATA

ID Number: 0960-0801 Year Built: c. 1905 Data Source: Site Visit/Map Quad Type of Address Number Extended Street 641 10th Street Current Type of Name Name(s) Single Dwelling, 641 10th Street, N.E. Common TaxCode1 TaxCode2 TaxCode3 Type Explain 0960/0801

STATUS/PURPOSE/USE DATA

Status Current: Extant Resource Type: Building

Square/Lot

Desig. Status: Historic Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain Residential (Single-Family) c. 1905 Site Visit/ Historic/Current

Current

CONSTRUCTION DATA

Construction Event Start Stop Cost Source Source Source

Rear Addition c. 1910 Site

Visit/Map

Orig Construction c. 1905 Site

Visit/Map

Construction Event **Associated Name** Association

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID Number: 0960-0801 Page 1

Surroundings:	Urban	Cross Re	ference Notes:		
Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Intact Attached (1 side) Face on Setback Line Vertical Box/Canted Bay L Shape Add				
Number Stories: Bays Wide:	2 2				
Height:	_	Outbuilding Type	С	ontributing Status	
Width: Depth/Length: SqFt: Volume:					
Lot Width Lot Depth/Length:		Outbuilding Notes			
Lot SqFt: Acreage:		Outsulaing Notes	•		
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)	PAIA				
Queen Anne			_		
Exterior & Architectur	al Notes:				
fenestrated with 1/1, The foundation oper A two-story ell exter parged and is set or fenestration consist are set in square-ed extends the length of	nings have been infilled wit nds from the southernmost n a solid foundation. An inte s of 6/6, double-hung, wood ged wood surrounds. A sin	indows. All windo h brick. bay of the rear (ea- erior brick chimney d-sash windows ar gle-leaf door pierc set on a solid foun	ws on the façade hands st) elevation and was pierces the sloping and a 1/1, double-hunces the rear elevation dation. The shed roc	ve concrete sills and stone I s constructed c. 1910. The e roof and is partially parged g, vinyl-sash window. All wi l. A one-story, two-bay porch of is covered with asphalt sh	II is . Visible ndows
feet from the brick s schoolyard is parall foundation planting entrance of the dwe	idewalk. The south (side) e el to the north (side) elevati s and is encircled by a meta	levation of the dwe on of the dwelling al hairpin and pick alk. The grassy rea	elling is adjacent to 6 . The front yard is lan et fence. A brick wall	d is set back approximately 639 10th Street, N.E. A concr ndscaped with mature shrub kway leads from the primary rood fencing and is bisected	ete os and
NOTABLE FEATU	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Unknown				-

Tuesday, June 25, 2013 ID_Number: 0960-0801 Page 2

Walls

Brick

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single	Paneled	Wood	

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

oning: Designation Event(s)

Survey(s) Level(s) of Investigation

Capitol Hill F & G Streets (2010) Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 641_10th_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 641_10th_Street_NE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:



\sim			
Ca	nı	חוי	n

Path: C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\ File: 641_10th_Street_NE_rear_looking_W.JPG Date:: Photog: Code:: R: Fr: **PHOTOS - B/W OR NON-DIGITIZED** Photo Code Date Photographer Caption Roll Frame(s) **MISCELLANEOUS NOTES DATA** Notes: **PERMIT DATA** Number Type Permit Issue Date Remarks Permit Notes: Missing Permit. **BIBLIOGRAPHIC DATA Short Citation** Type Date Remarks Bibliographic Notes: SIGNIFICANCE DATA Study Unit Criteria Code **DATA PROCESSING EVENTS DATA** Date Individual Action 3/8/2010 Dayton (MSD), Maria **Record Updated** 3/4/2010 Dayton (MSD), Maria **Record Updated** 3/4/2010 Dayton (MSD), Maria **Record Created**

Tuesday, June 25, 2013 ID_Number: 0960-0801 Page 4

ID Number: 0960-0051

BASICS DATA

ID Numbe	r: 0960-	0051	Year Built:	1892	Da	ta Source:	Permit
Number	Extended	Street			Quad	d Type of Ac	ldress
1004	-1004B	F Street			NE	Current	
1004		F Street			NE	Original	
Name(s)				Туре	of Name	:	
Rowhous	e, 1004 F St	reet, N.E.		Com	mon		
TaxCode1	TaxCode2	2 TaxCode3	Туре	Expla	ain		
0960/0051			Square/Lot	Curr	ent		

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1892 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source		
Orig Construction	1892	Permit			3166 Permit		
Construction Event	Asso	ciation		Associated	Name		
Orig Construction	Archi	tect		Clark, App	leton P., Jr.		
Orig Construction	Build	Builder		Williamson, Joseph B.			
Orig Construction	Owne	Owner		Buscher, J.H.			
Construction Notes:							
One of three rowhouses constructed from the same permit (#0369).							

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0960-0051 Page 1

Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Lot SqFt:	Urban Intact Row End (1 of 3) Face on Setback Line Row Building/Rectangular Rectangular 2 plus basement 2 18 30			ntributing Status					
Acreage:									
Has Driveway:									
STYLE/EXTERIOR	DATA								
Architectural Style(s)			=						
Queen Anne Italianate									
Exterior & Architectura	al Notas:								
The dwelling is conspressed stretcher-bostring courses are loflanked by stretcher openings and are linwith bead molding a topped by a two-couleaf paneled wood dithe cast iron stoop. 1/1, double-hung, virises the full height corners. Fenestratio the façade have gauhave concrete sills. and a single-leaf par concrete sill. A one-balusters encircle the	acced by the Italianate style and itructed of brick and is set of bond brick. A brick sill course ocated above the first and set bricks, is sited below the first and brick dentils. A single-lear rese, rowlock brick segments oor with lights and a painted brick shed roof of the porch is held to be a brick of the dwelling. The bay has n consists of 1/1, double-hunged brick jack arches. The first process of the first process of the dwelling of the sylvanian consists of 1/1, double-hunged brick jack arches. The first process of the dwelling of the sylvanian is neled door with lights and a story, full-width deck extending deck.	n a solid brick for a spans the façade cond story openings sloping roof caps af paneled metal cal arch. The reces d transom. A oness supported by soled, rectangular by the material treating, vinyl-sash wirst story opening parged and is fensix-light transom.	Indation; the façade of the beneath the second ongs. A string course, and the dwelling and is had been with leaded light sed westernmost bay story, one-bay porch quare wood posts. The ay extends from the of the main bloomdows. The foundations have gauged brick estrated with 1/1, do All windows are set	south elevation) is faced we story windows. Molded bri composed of fret molding re sited above the second ighlighted by a molded cores pierces the foundation are of the first story holds a significant to establish the entrance and it is escond story opening hose actions and second story opening hose and features chamfered in and second story opening segmental arches. All winduble-hung, vinyl-sash wind in segmental openings and	vith ick and story rnice nd is ingle- is set on ilds a ade and ags of ows ows				
Site Notes: March 2010: This rowhouse is located on the north side of F Street, N.E. and is set back approximately five feet from the brick sidewalk. The east (side) elevation of the dwelling is adjacent to 1006 F Street, N.E. The grassy front yard is landscaped with mature shrubs and is encircled by a metal picket fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is enclosed with wood fencing.									
NOTABLE FEATUR									
EXTERIOR MATER	Feature								
Roof Component	Material	Color	Treatment	Source					
Sloped	Not Visible		Not Visible						
Wall Component	Material	Color	Treatment	Source					

Tuesday, June 25, 2013 ID_Number: 0960-0051 Page 2

Stretcher Bond

Facade

Pressed Brick

Structure Componen		Feature	Source		
Foundation Walls	Brick Brick				
Materials Notes:	Brick				
Materials Notes.					
WINDOW/DOOR/I	NTERIOR DATA				
Window Location	Aperture Shape	Туре	Lights	Material	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single	Paneled	Metal/Glas	
Main Door	Rectangular	Single	Paneled	Wood/Glass	
Notable Interior Plan	(s)		Notable Interior Feature(s)		
Neighborhood: C	ESIGNATION DATA		Historic District(s)		
Subdivision: Ward/ANC: Zoning: Contributing:			Designation Event(s)		
Survey(s)			Level(s) of Investigation		
Capitol Hill F & G S	treets (2010)		Permit Research		
•	, ,		Reconnaissance Survey		
PHOTOS - DIGITI	ZED				
Caption:					
Databases	HRS\Documents\CHRS \F&G Street - 2 to 11th e\Pictures\Square 096				
	reet_NE_facade_lookir				
_					

Tuesday, June 25, 2013 ID_Number: 0960-0051 Page 3

Date::

Code::

Photog:

R:

Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\ File: 1004_F_Street_NE_facade_looking_NW.JPG Date:: Photog: Code:: R: Fr: Caption: Path: C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\ File: 1004_F_Street_NE_rear_looking_SW.JPG Date:: Photog: Code:: R: Fr: **PHOTOS - B/W OR NON-DIGITIZED** Photo Code Roll Date Photographer Frame(s) Caption **MISCELLANEOUS NOTES DATA** Notes: **PERMIT DATA** Permit Issue Date Number Type Remarks 08/15/1892 0369 Build Permit Notes: **BIBLIOGRAPHIC DATA Short Citation** Type Date Remarks Bibliographic Notes: SIGNIFICANCE DATA Study Unit Criteria Code

Tuesday, June 25, 2013 ID_Number: 0960-0051 Page 4

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/18/2010	Trieschmann (LVT), Laura	Record Updated
3/8/2010	Dayton (MSD), Maria	Record Updated
3/5/2010	Dayton (MSD), Maria	Record Updated
3/5/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0051 Page 5

ID Number: 0960-0050

BASICS DATA

ID Number: 0960-0050 Year Built: 1892 Data Source: Permit

Number Extended Street Quad Type of Address

1006 F Street NE Current

Name(s) Type of Name

Rowhouse, 1006 F Street, N.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

0960/0050 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1892 Permit Original

Residential (Multi-Family)

Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1892 Permit 3166 Permit

 Construction Event
 Association
 Associated Name

 Orig Construction
 Architect
 Clark, Appleton P., Jr.

 Orig Construction
 Builder
 Williamson, Joseph B.

Orig Construction Owner Buscher, J.H.

Construction Notes:

One of three rowhouses constructed from the same permit (#0369).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0960-0050 Page 1

Surroundings:	Urban		Cross Refere	nce Notes:				
Streetscape:	Intact	ĺ						
Relate to Othr Bldgs:	Row (1 of 3)							
•	` '							
Relate to Street:	Face on Setback Line	_						
Massing:	Row Building/Rectangular	вау						
Footprint:	Rectangular							
Number Stories:	2 plus basement							
Bays Wide:	2							
Height:		Outbuild	ing Type	1	Contributing Status	5		
Width:	18					_		
Depth/Length:	30							
SqFt:								
Volume:								
Lot Width								
		Outhuild	ina Notoo					
Lot Depth/Length:		Outbuild	ing Notes:					
Lot SqFt:								
Acreage:								
Has Driveway:								
STYLE/EXTERIOR	DATA							
Architectural Style(s)								
Queen Anne								
Italianate								
Exterior & Architectura	al Notes: ucted in 1892 by Joseph B. V	Villiame	n this two	story two-bay 0	uoon Anno-stylo	singla-family		<u> </u>
wood door and a on- provide access to th sided, rectangular be has the material trea vinyl-sash windows Permastone jack arc fenestrated with 1/1,	pierces the foundation. The e-light transom. A segmenta e door opening. The seconday extends from the eastern tment of the main block and a one-light fixed vinyl whes. The first story opening double-hung, vinyl-sash wick segmental arches. Two opening or the first story opening double-hung, vinyl-sash wick segmental arches. Two opening openital arches.	al arch of d story of most bay d feature vindow. T s have P ndows a	Permastone pening holds y of the façad s chamfered The foundati ermastone s nd a single-l	e tops the transo s a 1/1, double-h de and rises the corners. Fenes on and second segmental arche eaf paneled doo	om. Cast iron step lung, vinyl-sash w full height of the tration consists of story openings of s. The rear (north or. All windows ar	os and railing vindow. A the dwelling. The fall of 1/1, double the façade I of topped by	gs ree- he bay e-hung, have	
Site Notes:	sk segmental arches. Two op	Jennigs	on the mat a	tory mave been	iiiiiiea witii biick	•		ı
March 2010: This two from the brick sidew wood picket fence. I	o-story rowhouse is located ralk. The dwelling is adjacen The rear yard is bounded by	t to 1004	-1004B and					
NOTABLE FEATUR	RES DATA							
Component	Feature							
EXTERIOR MATER	RIALS DATA							
Roof Component	Material	Col	or	Treatment	Source			
Sloped	Not Visible			Not Visible				
Wall Component	Material	Col	or	Treatment	Source			
Facade	Permastone			Permastone				
Structure Component	Material	Fea	ture		Source			
Foundation	Brick							
Walls	Brick							
Materials Notes:								

Tuesday, June 25, 2013 ID_Number: 0960-0050 Page 2

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Fixed	1-light	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single	Paneled	Wood	
Main Door	Rectangular	Single	Paneled	Wood	
Notable Interior Plan	n(s)		Notable Interior Feature(s)		

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill
Subdivision:
Ward/ANC:
Zoning: Designation Event(s)

Contributing:

Survey(s)
Capitol Hill F & G Streets (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0960\

File: 1006_F_Street_NE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0960\

File: 1006_F_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Tuesday, June 25, 2013 ID_Number: 0960-0050 Page 3

3/5/2010

3/5/2010

Dayton (MSD), Maria

Dayton (MSD), Maria

Path: C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\ File: 1006_F_Street_NE_rear_looking_SW.JPG Date:: Photog: Code:: R: Fr: **PHOTOS - B/W OR NON-DIGITIZED** Photo Code Date Photographer Roll Frame(s) Caption **MISCELLANEOUS NOTES DATA** Notes: **PERMIT DATA** Permit Issue Date Number Type Remarks 08/15/1892 0369 Build Permit Notes: **BIBLIOGRAPHIC DATA Short Citation** Type Date Remarks Bibliographic Notes: SIGNIFICANCE DATA Study Unit Criteria Code **DATA PROCESSING EVENTS DATA** Date Individual Action 3/18/2010 Trieschmann (LVT), Laura **Record Updated** 3/8/2010 Dayton (MSD), Maria **Record Updated**

Record Updated

Record Created

ID Number: 0960-0049

BASICS DATA

ID Number: 0960-0049 Year Built: 1892 Data Source: Permit

Number Extended Street Quad Type of Address

1008 F Street NE Current

Name(s) Type of Name

Rowhouse, 1008 F Street, N.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

0960/0049 Square/Lot Permit

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Multi-Family) 1892 Permit Original

Residential (Multi-Family) 1892 Permit Original Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1892 Permit 3166 Permit 3166 Permit

Construction Event Association Associated Name

Orig Construction Architect Clark, Appleton P., Jr.

Orig Construction Builder Williamson, Joseph B.

Orig Construction Owner Buscher, J.H.

Construction Notes:

One of three rowhouses constructed from the same permit (#0369).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0960-0049 Page 1

Surroundings:	Urban		Cross Reference Notes:					
Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Intact Row (1 of 3) Face on Setback Line Row Building/Rectangular Rectangular	Вау						
Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Lot SqFt: Acreage:	2 plus basement 2 18 30		ding Type	Contrit	outing Status			
Has Driveway:								
STYLE/EXTERIOR	DATA							
Architectural Style(s)								
Queen Anne Italianate								
Exterior & Architectura	al Notes:							
The dwelling is conspressed stretcher-bestring courses are leflanked by stretcher openings and are limwith bead molding a a two-course, rowlordoor and a one-light opening holds a 1/1, of the façade and rischamfered corners. The foundation and gauged brick segme double-hung, vinyl-serving courses are limited to the segment of the segme	aced by the Italianate style a structed of brick and is set of brick and is set of brick and brick. A brick sill course bricks, is sited below the first and set bricks, is sited below the first and brick dentils. A single-leck brick segmental arch. The stransom. Cast iron steps and double-hung, vinyl-sash with set the full height of the dwe frenestration consists of 1/1 second story openings of the that arches. All windows has ash windows. All windows	n a solide spans to cond state story sloping af paneled western drailing. The double de façade ve conc	d brick found the façade be ory openings. De roof caps the ed metal doornmost bay of gs provide act three-sided, he bay has the hung, vinyle have gauge rete sills. The	ation; the façade (sou neath the second sto . A string course, cor corative panels are s dwelling and is high with lights pierces the the first story holds cess to the primary e rectangular bay exter material treatment of sash windows and on d brick jack arches. T rear (north) elevation	ath elevation) is faced wary windows. Molded bromposed of fret molding sited above the second lighted by a molded come foundation and is to a single-leaf paneled matrance. The second sinds from the easternment the main block and feelight fixed vinyl wind the first story openings in is fenestrated with 1/2.	with rick and story rnice pped by netal tory pst bay eatures lows.		
Site Notes: March 2010: This tw	o-story rowhouse is located	on the I	north side of	F Street N.F. and is s	set back approximately	five feet		
from the brick sidew metal hairpin and pi	valk. The dwelling is adjacen cket fence. A concrete walk nce edges the rear yard. A c	t to 1010 way lead	o and 1006 F	Street, N.E. The grass imary entrance of the	sy front yard is encircle dwelling and ends at t	d by a the		
NOTABLE FEATU	RES DATA							
Component	Feature							
EXTERIOR MATER	RIALS DATA							
Roof Component	Material	Co	lor	Treatment	Source			
Sloped	Not Visible			Not Visible				
Wall Component	Material	Co	lor	Treatment	Source			
Facade Structure Component	Pressed Brick	Eas	ituro	Stretcher Bond	Source			

Foundation

Brick

Walls Brick

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Туре Lights Material 2 Flr Windows **Dbl-Hung** 1/1 Vinyl Rectangular **Bay Windows** Rectangular **Dbl-Hung** Vinyl **Bay Windows** Rectangular 1-light Vinyl **Fixed** Type Pamels **Door Location** Aperture Shape Material Single Metal/Glas **Basement** Rectangular Paneled **Main Door** Rectangular Single **Paneled** Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision:
Ward/ANC:
Zoning:
Contributing:

Designation Event(s)

Survey(s) Level(s) of Investigation

Capitol Hill F & G Streets (2010) Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\ 1008_F_Street_NE_rear_looking_S.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

File:

Path: C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0960\

File: 1008_F_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

3/5/2010

3/5/2010

Dayton (MSD), Maria

Dayton (MSD), Maria

Path: C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\ File: 1008_F_Street_NE_facade_looking_NE.JPG Date:: Photog: Code:: R: Fr: **PHOTOS - B/W OR NON-DIGITIZED** Photo Code Date Photographer Roll Frame(s) Caption **MISCELLANEOUS NOTES DATA** Notes: **PERMIT DATA** Permit Issue Date Number Type Remarks 08/15/1892 0369 Build Permit Notes: **BIBLIOGRAPHIC DATA Short Citation** Type Date Remarks Bibliographic Notes: SIGNIFICANCE DATA Study Unit Criteria Code **DATA PROCESSING EVENTS DATA** Date Individual Action 3/18/2010 Trieschmann (LVT), Laura **Record Updated** 3/8/2010 Dayton (MSD), Maria **Record Updated**

Tuesday, June 25, 2013 ID_Number: 0960-0049 Page 4

Record Updated

Record Created

ID Number: 0960-0048

BASICS DATA

ID Numbe	r: 0960 -	0048	Year Built:	1892	Da	ta Source:	Permit
Number	Extended	Street			Qua	d Type of Ad	dress
1010	-1010.5	F Street			NE	Current	
1010		F Street			NE	Original	
Name(s)				Туре о	f Name)	
Rowhous	e, 1010 F St	reet, N.E.		Comm	on		
TaxCode1	TaxCode2	2 TaxCode3	Туре	Explai	in		
0960/0048	3		Square/Lot	Curre	nt		

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1892 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1892	Permit			2857 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Build	ler		Loveless, J	J.T.
Orig Construction	Own	er		Loveless, J	J.T.
Construction Notes:					
One of fourteen rowhous	es constructed	from the same	e permit (#2	608).	

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0960-0048 Page 1

Surroundings:	Urban		Cross Reference Notes:					
Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Intact Row (1 of 14) Face on Setback Line Row Building/Rectangular Rectangular	Вау						
Number Stories: Bays Wide:	2 plus basement 2					ı		
Height:		Outbuild	ding Type	Co	ntributing Status	-		
Width: Depth/Length:	17 32							
SqFt: Volume: Lot Width	32							
Lot Depth/Length:		Outbuild	ding Notes:			1		
Lot SqFt: Acreage:								
Has Driveway:								
Tido Diiveway.								
STYLE/EXTERIOR	DATA							
Architectural Style(s)								
Queen Anne								
Exterior & Architectura	al Notes:							
story openings. A th second story opening and second story op by a molded cornice building and has a p westernmost bay of lintel tops the transcholds a 1/1, double-lopening. A three-sid rises the full height roof of square butt a double-hung, vinyl-s with pearl molding a elevation is fenestra single-leaf paneled r the windows have vi	band of reed molding flank ree-course brick watertable gs. A string course, composenings and also bisects the and a corbeled brick cornic arged corbeled cap. A single the first story holds a single m. Cast iron steps and railing, vinyl-sash window. A ed, rectangular bay with chapt the dwelling. The bay has and fishscale slate shingles. The first and the foundation windows ted with 1/1, double-hung, whetal door with lights. All opnyl-clad sills. A one-story worst foundation. A solid wood	is locate sed of rea first stoce. An in eleaf pareleaf pareleaf pareleaf pareleaf pareleaf pareleaf pareleaf pareleaf pareleaf at the material second are high rinyl-sas penings prod-frar	ed above the eed molding, by openings. terior-rear braneled wood covide access to corners exterial treatmetops the roof story openin hlighted by so h windows, a are topped by me deck exterial treatmetops the roof story openin highted by so h windows, a are topped by me deck exterial treatmetops the roof story openin highted by so h windows, a are topped by me deck exterial treatmetops the roof story openin highted by so had a retopped by me deck exterial treatmetops had been deck exterial treatmetops	foundation. Sill company the façade A sloping roof calck chimney rises door pierces the floor with lights and the primary entry all arch with pearnds from the east of the main blows. Fenestration corgs are topped by soldier brick segments in two-course, rownds from the rear	ourses are sited below the and is located between the ps the dwelling and is high from the northwest corner oundation. The recessed da one-light transom. A stance. The second story op I molding surmounts the wernmost bay of the façade k and is capped by a pyrasists of single and paired soldier brick segmental arcental arches. The rear (norted wood door with lights, a lock brick segmental arches to the segmental	first and e first hlighted for of the tone ening vindow and midal 1/1, ches ch) and a es and		
March 2010: This two	o-story rowhouse is located alk. The dwelling is adjacen acircled by a metal bow and a of the dwelling.	nt to 100	8 and 1012 F	Street, N.E. The s	mall front yard is landscap	ed with		
NOTABLE FEATU	RES DATA							
Component	Feature							
EXTERIOR MATER	RIALS DATA							
Roof Component	Material	Co	lor	Treatment	Source			
Sloped	Not Visible			Not Visible				
Wall Component	Material	Co	lor	Treatment	Source			

Stretcher Bond

Facade

Pressed Brick

Structure Componer		Feature	Source	
Foundation Walls	Brick Brick			
	Brick			
Materials Notes:				
WINDOW/DOOR/	INTERIOR DATA			
Window Location	Aperture Shape	Туре	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single	Paneled	Wood
Main Door	Rectangular	Single	Paneled	Wood/Glass
Notable Interior Plar	n(s)		Notable Interior Feature(s)	
Interior Notes:				
PLAN/SURVEY/D	ESIGNATION DATA			
	Capitol Hill		Historic District(s)	
Subdivision:				
Ward/ANC:			B : " E ")	
Zoning:			Designation Event(s)	
Contributing:				
Survey(s)		_	Level(s) of Investigation	
Capitol Hill F & G S	Streets (2010)		Permit Research	
			Reconnaissance Survey	
PHOTOS - DIGITI	ZED			
Caption:				
-				
Databases	CHRS\Documents\CHRS \F&G Street - 2 to 11th			
File: 1010-	se\Pictures\Square 0960 Street_NE_rear_looking			
	_	_3.JFG		
Date::	Photog:	_		

Tuesday, June 25, 2013 ID_Number: 0960-0048 Page 3

Code::

R:

Fr:

Caption	ı:					
Path:	C:\Users\CHRS\D Databases\F&G S St\Database\Pictu	treet - 2 to 11th				
File:	1010-	NE_facade_looking	NW .IPG			
Date::	Photo	_	_1444.01 0			
Code::		R:	Fr:			
Caption	11					
Path:	C:\Users\CHRS\D					
	Databases\F&G S St\Database\Pictu					
File:	1010-	NE_facade_looking	N IPG			
Date::	Photo		_14.01 0			
Code::		R:	Fr:			
PHOTO	OS - B/W OR NON	I-DIGITIZED				
Photo C	Code Roll	Frame(s)	Date	Photographer	Caption	
MISCE	ELLANEOUS NOT	ES DATA				
Notes:						
PERMI	IT DATA					
Permit I	Issue Date	Number Type		Remarks		
06/06/18		2608 Build				
Permit N	Notes:					

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks

Bibliographic Notes:

SIGNIFICANCE DATA

Study Unit

Code Criteria

Tuesday, June 25, 2013 ID_Number: 0960-0048 Page 4

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/5/2010	Dayton (MSD), Maria	Record Updated
3/5/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0048 Page 5

Acreage:

Has Driveway:

ID Number: 0960-0047

BASICS DATA								
ID Number: 0960	-0047	Year Built	: 1892	Dat	a Source: F	Permit		
Number Extended	Street			Quad	Type of Addre	ss		
1012	F Street			NE	Current			
Name(s)			Type	of Name				
Rowhouse, 1012 F S	treet, N.E.		Com					
TayOndad TayOnda	0 T01-0	T	E	_•				
TaxCode1 TaxCode. 0960/0047	2 TaxCode3	Type	Expla Curr					
0900/0047		Square/Lot	Curr	ent				
STATUS/PURPOSI	E/USE DATA	1						
Resource Type: Buil	ding		St	atus Curi	rent: Extant			
Desig. Status: Hist	oric		Qı	uality:				
Purpose: Row	house		Co	ondition:	Good			
Function/Use		Start	Source	Stop	Sou	ırce	Explain	
Residential (Single-F	amily)	1892	Permit	Отор	000	ai o o	Original	
Residential (Multi-Fa							Current	
`	• ,							
CONSTRUCTION	DATA							
Construction Event		tart So	urce	Stop	Source		Cost Source	
Orig Construction			rmit	Ciop			2857 Permit	
•		A : - t :			A : -			
Construction Event		Association Builder			Associa Lovele :			
Orig Construction Orig Construction		Owner			Lovele	•		
_		OWING			LOVEIC	33, 0.1.		
Construction Notes:								
One of fourteen row	houses const	ructed from t	he same p	permit (#	2608).			
PEOPLE/EVENTS	DATA							
Racial Segregation St	atus.							
rtaciai ocgregation ot	atus.							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban			Cross Re	eference Notes	:		
Streetscape:	Intact							
Relate to Othr Bldgs:								
Relate to Street: Massing:	Face on Sett		r Dov					
Footprint:	Rectangular	g/Rectangula	Бау					
	_							
Number Stories:	_	asement						I
Bays Wide:	2		ماند طاعد دا			_	Nametrilla ation of Charles	
Height: Width:	47		Shed	ling Type			Contributing Status	
Depth/Length:	17 32		Silea					
SqFt:	JŁ							
Volume:								
Lot Width								
Lot Depth/Length:			Outbuild	ling Note	s:			
Lot SqFt:			March 2	2010: A c	ne-story, one-		efabricated shed is located	
Acreage:			north of	f the dwe	elling and was	constr	ructed c. 1990. The shed	Ì

(possibly clad with metal) is capped by a gable roof. The shed was obscured by tall privacy fencing.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

March 2010: Constructed in 1892 by J.T. Loveless, this two-story, two-bay Queen Anne-style single-family rowhouse is one of fourteen rowhouses constructed from the same permit (#2608). The dwelling is constructed of brick and is set on a solid and raised brick foundation; the façade (south elevation) is faced with pressed stretcher-bond brick. Recessed panels, containing a band of reed molding flanked by bands of bead molding, are located between the first and second story openings. A three-course brick watertable is located above the foundation. Sill courses are sited below the first and second story openings. A string course, composed of reed molding, spans the façade and is located between the first and second story openings and also bisects the first story openings. A sloping roof caps the dwelling and is highlighted by a molded cornice and a corbeled brick cornice. An interior-rear brick chimney rises from the northwest corner of the building and has a parged corbeled cap. A single-leaf paneled vinyl door with a one-light transom pierces the foundation. The recessed westernmost bay of the first story holds a single-leaf paneled door and a one-light transom. A stone lintel tops the transom. Cast iron steps and railings provide access to the primary entrance. The second story segmental opening holds a 1/1, double-hung, vinyl-sash window. A soldier brick segmental arch with pearl molding surmounts the window opening. A three-sided, rectangular bay with chamfered corners extends from the easternmost bay of the facade and rises the full height of the dwelling. The bay has the material treatment of the main block. A brick crowstep parapet rises from the bay and features decorative pearl molding. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. The first and second story openings are topped by soldier brick segmental arches with pearl molding and the foundation windows are highlighted by soldier brick segmental arches. The rear (north) elevation is parged and is fenestrated with 1/1, double-hung, vinyl-sash windows and a single-leaf paneled door with lights. All windows are set in segmental openings. A one-story, full-width wood-frame deck extends from the rear elevation of the dwelling and is set on a square wood post foundation. Horizontal wood boards form a balustrade and encircle the deck.

Site Notes:

March 2010: This two-story rowhouse is located on the north side of F Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 1010-1010.5 and 1014 F Street, N.E. The landscaped front yard features mature shrubs and small trees and is encircled by metal bow and picket fencing. The rear yard is edged by wood fencing. An alley is located north of the dwelling.

NOTABLE FEATURES DATA

Component	Feature	
-----------	---------	--

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Pressed Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Brick				
Walls	Brick				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
2 Flr Windows	Segmental-Arched	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single	Paneled	Vinyl	
Main Door	Rectangular	Single	Paneled	Unknown	
Notable Interior Plan	n(s)		Notable Interior Feature(s)		

Tuesday, June 25, 2013 ID_Number: 0960-0047 Page 2

Interior	Notes:			
PLAN/	/SURVEY/DESIGNATIO	ON DATA		
Neighbo Subdivi	orhood: Capitol Hill sion:	-		Historic District(s)
Ward/A Zoning: Contribu				Designation Event(s)
Survey((s)			Level(s) of Investigation
Capitol Hill F & G Streets (2010)				Permit Research Reconnaissance Survey
РНОТ	OS - DIGITIZED			
Caption	1:			
Path: File: Date:: Code::	C:\Users\CHRS\Docum Databases\F&G Street St\Database\Pictures\; 1012_F_Street_NE_fact Photog:	: - 2 to 11th Square 0960)\	
Caption):			
Path:	C:\Users\CHRS\Docum Databases\F&G Street St\Database\Pictures\	: - 2 to 11th Square 0960)\	
File:	1012_F_Street_NE_fac	:ade_lookin	g_NW.JPG	
Date:: Code::	Photog:	R:	Fr:	
Caption	1:			
Path: File:	C:\Users\CHRS\Docum Databases\F&G Street St\Database\Pictures\: 1012_F_Street_NE_rea	: - 2 to 11th Square 0960)\	
Date::	Photog:			

Tuesday, June 25, 2013 ID_Number: 0960-0047 Page 3

Code::

R:

Fr:

3/5/2010

Dayton (MSD), Maria

Path: C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\ File: 1012_F_Street_NE_shed_looking_SE.JPG Date:: Photog: Code:: R: Fr: **PHOTOS - B/W OR NON-DIGITIZED** Photo Code Date Photographer Caption Roll Frame(s) **MISCELLANEOUS NOTES DATA** Notes: **PERMIT DATA** Permit Issue Date Number Type Remarks 06/06/1892 2608 Build Permit Notes: **BIBLIOGRAPHIC DATA Short Citation** Type Date Remarks Bibliographic Notes: SIGNIFICANCE DATA Study Unit Criteria Code **DATA PROCESSING EVENTS DATA** Date Individual Action 3/8/2010 Dayton (MSD), Maria **Record Updated** 3/5/2010 Dayton (MSD), Maria **Record Updated**

Tuesday, June 25, 2013 ID_Number: 0960-0047 Page 4

Record Created

ID Number: 0960-0046

BASICS DATA

ID Number: 0960	-0046	Year I	Built: 1892	Data	a Source: Permit		
Number Extended	Street			Quad	Type of Address		
1014	F Street			NE	Current		
Name(s)			Тур	e of Name			
Rowhouse, 1014 F S	Street, N.E.			nmon			
TaxCode1 TaxCode	2 TaxCode3	Typo	Ev	alain			
0960/0046	z raxcoues	Type Square/		olain rrent			
0000/0010		oqua.o,					
STATUS/PURPOS	E/USE DATA	Δ.					
Resource Type: Buil	lding		(Status Curre	ent: Extant		
	toric		(Quality:			
Purpose: Rov	vhouse		(Condition:	Good		
Function/Use		Start	Source	Ston	Source	Evoloin	
Residential (Single-F	Family)	1892	Permit	Stop	Source	Explain Original	
Residential (Multi-Fa		.002	. 0			Current	
`	,						
CONSTRUCTION I	DATA						
Construction Event	5	Start	Source	Stop	Source	Cost Source	
Orig Construction	1	892	Permit	-		2857 Permit	
Construction Event		Associat	tion		Associated Na	ıme	
Orig Construction		Builder			Loveless, J.T	•	
Orig Construction		Owner			Loveless, J.T		
Construction Notes:							
One of fourteen row	houses cons	tructed fro	m the same	permit (#2	2608).		
PEOPLE/EVENTS	DATA						
Racial Segregation St	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Re	ference Notes:		
Streetscape:	Intact						
Relate to Othr Bldgs:	Row (1 of 14	-					
Relate to Street:	Face on Set		l D				
Massing: Footprint:	Row Buildin Rectangular		Jular Bay				
	•						
Number Stories:	-	pasement					
Bays Wide:	2		Outhui	ilding Type		Contributing Status	
Height: Width:	17		Outbu	Ilding Type		Contributing Status	
Depth/Length:	32						
SqFt:							
Volume:							
Lot Width							
Lot Depth/Length:			Outbui	Iding Notes	:		
Lot SqFt:							
Acreage:							
Has Driveway:							1

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

March 2010: Constructed in 1892 by J.T. Loveless, this two-story, two-bay Queen Anne-style single-family rowhouse is one of fourteen rowhouses constructed from the same permit (#2608). The dwelling is constructed of brick and is set on a solid and raised brick foundation; the facade (south elevation) is faced with pressed stretcher-bond brick. Recessed panels, containing a band of reed molding flanked by bands of bead molding, are located between the first and second story openings. A three-course brick watertable is located above the foundation. Sill courses are sited below the first and second story openings. A string course, composed of reed molding, spans the façade and is located between the first and second story openings. A sloping roof caps the dwelling and is highlighted by a molded cornice and a corbeled brick cornice. An interior-rear brick chimney rises from the northwest corner of the building and has a corbeled cap. A single-leaf paneled wood door with lights pierces the foundation. The recessed westernmost opening of the first story holds a single-leaf paneled metal door with lights and a one-light transom. The round-headed primary opening is highlighted by a soldier brick round-headed arch with stone imposts and keystone. Cast iron steps and railings provide access to the primary entrance. The second story opening holds a 1/1, double-hung, vinyl-sash window. A soldier brick segmental arch with pearl molding surmounts the window opening, which has a stone sill. A three-sided, rectangular bay with chamfered corners extends from the easternmost bay of the facade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a pyramidal roof of square butt and fishscale slate shingles. A finial tops the roof. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. The first and second story openings are topped by soldier brick segmental arches with pearl molding and the foundation windows are highlighted by soldier brick segmental arches. The rear (north) elevation is fenestrated with 1/1, doublehung, vinyl-sash windows and a single-leaf multi-light wood door with a one-light transom. All openings are topped by two-course, rowlock brick segmental arches and the windows have vinyl-clad sills. A one-story wood-frame deck extends from the rear elevation of the dwelling and is set on a square wood post foundation. Square wood balusters complement the roof.

Site Notes:

March 2010: This two-story rowhouse is located on the north side of F Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 1012 and 1016-1016B F Street, N.E. The front yard is landscaped with small trees and is encircled by metal bow and picket fencing. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is encircled by metal chain-link fencing. An alley is located north of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Pressed Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Brick				
Walls	Brick				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single	Paneled	Wood/Glass
Main Door	Rectangular	Single	Paneled	Metal/Glas

Tuesday, June 25, 2013 ID_Number: 0960-0046 Page 2

Notable Interior Plan(s)		Notable Interior Feature(s)			
latanian N	latas.				
Interior I	Notes:				
PLAN/S	SURVEY/DESIGNATION DATA				
Neighbo	-	Historic District(s)			
Subdivis Ward/Al					
Zoning:		Designation Event(s)			
Contribu	ting:				
Survey(s	s)	Level(s) of Investigation			
Capitol	Hill F & G Streets (2010)	Permit Research			
		Reconnaissance Survey			
РНОТО	OS - DIGITIZED				
Caption:					
Path:	C:\Users\CHRS\Documents\CHRS				
	Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\				
File:	1014_F_Street_NE_rear_looking_SE.JPG				
Date::	Photog:				
Code::	R: Fr:				
Caption:					
Path:	C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th				
	St\Database\Pictures\Square 0960\				
File:	1014_F_Street_NE_facade_looking_NW.JPG				
Date:: Code::	Photog: R: Fr:				
Caption:					
Сариоп.					
Path:	C:\Users\CHRS\Documents\CHRS				
ı allı.	Databases\F&G Street - 2 to 11th				
File:	St\Database\Pictures\Square 0960\ 1014_F_Street_NE_facade_looking_N.JPG				
Date::	Photog:				
Code::	R: Fr:				

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption	
MISCELLANEO	OUS NOTES	DATA				
Notes:						
PERMIT DATA						
Permit Issue Date	Э	Number Type		Remarks		
06/06/1892		2608 Build	<u> </u>			=
Permit Notes:						
BIBLIOGRAPH	IIC DATA					
Short Citation			Туре	Date Re	marks	_
Bibliographic Not	es:]
SIGNIFICANCE	E DATA					J
Study Unit						
Code C	Criteria					
DATA PROCES	SSING EVEN	ITS DATA				
Date	Individual		Action			
3/8/2010 3/5/2010 3/5/2010	Dayton (N	ISD), Maria ISD), Maria ISD), Maria	Record U Record U Record O	Ipdated		

Tuesday, June 25, 2013 ID_Number: 0960-0046 Page 4

ID Number: 0960-0045

BASICS DATA

ID Numbe	er: 0960 -	-0045	Year Built:	1892	Da	ta Source:	Permit
Number	Extended	Street			Qua	d Type of Ad	ldress
1016	-1016B	F Street			NE	Current	
1016		F Street			NE	Original	
Name(s)				Туре о	f Name)	
Rowhouse, 1016 F Street, N.E.			Comm	on			
TaxCode1	I TaxCode:	2 TaxCode3	Туре	Explai	n		
0960/004	5		Square/Lot	Curre	nt		

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1892 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source		
Orig Construction	1892	Permit			2857 Permit		
Construction Event	onstruction Event Association Associated Name			Name			
Orig Construction Builder			J.T.				
Orig Construction	Owner		Loveless, J.T.		J.T.		
Construction Notes:							
One of fourteen rowhouses constructed from the same permit (#2608).							

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0960-0045 Page 1

Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Lot SqFt:	Urban Intact Row (1 of 14) Face on Setback Line Row Building/Rectangular Rectangular 2 plus basement 2 17 32	Outbuilding T Shed Outbuilding N March 2010:	lotes: A one-story prefabricated	ontributing Status				
Acreage: Has Driveway:		the dwelling and is wood-frame construction. Constructed c. 1995, the shed is clad with vinyl-siding and is capped by a gable roof. The shed was obscured by a tall wood fence.						
STYLE/EXTERIOR	DATA							
Architectural Style(s)								
Queen Anne								
Exterior & Architectural Notes: March 2010: Constructed in 1892 by J.T. Loveless, this two-story, two-bay Queen Anne-style single-family rowhouse is one of fourteen rowhouses constructed from the same permit (#2608). The dwelling is constructed of brick and is set on a solid and raised brick foundation; the façade (south elevation) is faced with pressed stretcher-bond brick. Recessed panels, containing a band of reed molding flanked by bands of bead molding, are located between the first and second story openings. A string course, composed of reed molding, spans the façade and is located between the first and second story openings. A string course, composed of reed molding, spans the façade and is located between the first and second story openings. A sloping roof caps the dwelling and is highlighted by a molded cornice and a corbeled brick cornice. An interior-rear brick chimney rises from the northwest corner of the building and has a corbeled cap. A single-leaf paneled wood door with a blind transom pierces the foundation. The recessed westernmost opening of the first story holds a single-leaf paneled metal door and a one-light fanlight. The round-headed primary opening is highlighted by a soldier brick round-headed arch with stone imposts and keystone. Cast iron steps and railings provide access to the primary entrance. The second story opening holds a 1/1, double-hung, vinyl-sash window. A soldier brick segmental arch with pearl molding surmounts the window opening. A three-sided, rectangular bay with chamfered corners extends from the easternmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block. A brick crowstep parapet rises from the bay and features decorative pear molding. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. The first and second story openings are topped by soldier brick segmental arches with pearl molding and the foundation windows are highlighted by soldier brick segmental arches. The rear								
north of the dwelling.								
NOTABLE FEATU	RES DATA							
Component EXTERIOR MATER	Feature Plat S DATA							
LATERIOR WATER	NALS DATA							
Roof Component Sloped	Material Not Visible	Color	Treatment Not Visible	Source				
Wall Component	Material	Color	Treatment	Source				

Stretcher Bond

Facade

Pressed Brick

Structure Componer Foundation	t Material Brick	Feature	Source		
Foundation Walls	Brick				
	Brick				
Materials Notes:					
WINDOW/DOOR/	NTERIOR DATA				
Window Location	Aperture Shape	Туре	Lights	Material	
2 FIr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single	Paneled	Wood	
Main Door	Rectangular	Single	Paneled	Metal	
Notable Interior Plan	(s)		Notable Interior Feature(s)		
Interior Notes:					
PLAN/SURVEY/D	ESIGNATION DATA				
			Lliatoria Diatriat(a)		
Neighborhood: (Subdivision:	Capitol Hill		Historic District(s)		
Ward/ANC:					
Zoning:			Designation Event(s)		
Contributing:			Designation Event(s)		
Survey(s)			Level(s) of Investigation		
Capitol Hill F & G S	treets (2010)		Permit Research		
			Reconnaissance Survey		
PHOTOS - DIGITI	ZED				
Caption:					
	HRS\Documents\CHRS	;			
	\F&G Street - 2 to 11th	N			
	e\Pictures\Square 0960	Л			
File: 1016- 1016B F S	Street_NE_facade_look	ina NE.JPG			
ים ייסיייי	551iuouu6_iook				
Date::	Photog:				

Tuesday, June 25, 2013 ID_Number: 0960-0045 Page 3

Code::

R:

Fr:

\sim			
Ca	nt	\cap	n:
Οu	νι	ıv	

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 1016-

1016B_F_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 1016-

1016B_F_Street_NE_rear_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th

St\Database\Pictures\Square 0960\

File: 1016-

1016B_F_Street_NE_shed_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date Number Type Remarks

06/06/1892 2608 Build

Permit Notes:

BIBLIOGRAPHIC DATA

Short Citation	on	Type	Date	Remarks	
Bibliographi	ic Notes:				
SIGNIFICA	ANCE DATA				
Study Unit					
Code	Criteria				

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/5/2010	Dayton (MSD), Maria	Record Updated
3/5/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0045 Page 5

ID Number: 0960-0044

BASICS DATA

ID Number: 0960	-0044	Year Built	: 1892	Data	a Source:	Permit		
Number Extended	Street			Quad	Type of Addr	ess		
1018	F Street			NE	Current			
Name(s)			Туре	of Name				
Rowhouse, 1018 F S	treet, N.E.		Comr	non				
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	ain				
0960/0044		Square/Lot	Curr					
STATUS/PURPOS	E/USE DATA	ı						
Resource Type: Bui	_				rent: Extant			
_	toric			uality: ondition:	Cood			
ruipose. Rov	vhouse		C	mailion.	Good			
Function/Use		Start	Source	Stop	S	ource	Explain	
Residential (Single-I		1892	Permit				Original Current	
Residential (Multi-Fa	aminy)						Current	
CONSTRUCTION I	DATA							
Construction Event	St	art So	urce	Stop	Source		Cost Source	
Orig Construction	18	392 Pe	rmit				2857 Permit	
Construction Event		Association			Assoc	iated Nar	me	
Orig Construction		Builder			Lovel	ess, J.T.		
Orig Construction		Owner			Lovel	ess, J.T.		
Construction Notes:								
One of fourteen row	houses consti	ructed from t	he same p	permit (#	2608).			
PEOPLE/EVENTS	ΠΑΤΑ							
Racial Segregation St	iatus:							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban			Cross Re	eference Note	es:		
Streetscape:	Intact							
Relate to Othr Bldgs:								
Relate to Street:	Face on Seth							
Massing: Footprint:	Row Building Rectangular	g/Rectangula	г вау					
	_							
Number Stories:	2 plus ba	asement						
Bays Wide: Height:	2		Outbuild	ling Type		C	Contributing Status	
Width:	17		Outbuild	mig Typo			Charles Clared	
Depth/Length:	32							
SqFt:								
Volume:								
Lot Width			Outhout	lina Notes	o.			
Lot Depth/Length: Lot SqFt:			Julbuild	ling Notes	ъ.			
Acreage:								
Has Driveway:								

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

March 2010: Constructed in 1892 by J.T. Loveless, this two-story, two-bay Queen Anne-style single-family rowhouse is one of fourteen rowhouses constructed from the same permit (#2608). The dwelling is constructed of brick and is set on a solid and raised brick foundation; the facade (south elevation) is faced with pressed stretcher-bond brick. Recessed panels, containing a band of reed molding flanked by bands of bead molding, are located between the first and second story openings. A three-course brick watertable is located above the foundation. Sill courses are sited below the first and second story openings and a third bisects the first story windows. A string course, composed of reed molding, spans the façade and is located between the first and second story openings. A sloping roof caps the dwelling and is highlighted by a molded cornice and a corbeled brick cornice. An interior-rear parged chimney rises from the northwest corner of the building. A single-leaf paneled metal door pierces the foundation. The recessed westernmost opening of the first story holds a single-leaf paneled wood door. The outer entrance is composed of double-leaf wood-frame glass doors. A stone lintel tops the opening. Cast iron steps and railings provide access to the primary entrance. The second story opening holds a 1/1, double-hung, vinyl-sash window. A soldier brick segmental arch with pearl molding surmounts the window opening and a stone lintel finishes the window opening. A three-sided, rectangular bay with chamfered corners extends from the easternmost bay of the facade and rises the full height of the dwelling. The bay has the material treatment of the main block. A pyramidal roof, covered with slate shingles, caps the bay, which is also topped by a finial, caps the bay. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. The first and second story openings are topped by soldier brick segmental arches with pearl molding. The rear (north) elevation is parged and is fenestrated with 1/1, double-hung, vinyl-sash windows. The windows have sills. A one-story, full-width wood-frame deck extends from the rear elevation of the dwelling and is set on a square wood post foundation.

Site Notes

March 2010: This two-story rowhouse is located on the north side of F Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 1016-1016B and 1018 F Street, N.E. The front yard is landscaped with small trees and is bounded by a metal bow and picket fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. An alley is located north of the dwelling.

NOTABLE FEATURES DATA

Component	Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			
Materials Notes:				

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single	Paneled	Metal
Main Door	Rectangular	Double	Full Glass	Wood/Glass
Main Door	Rectangular	Single	Paneled	Wood
Notable Interior Plan(s)			Notable Interior Feature(s)	

Tuesday, June 25, 2013 ID_Number: 0960-0044 Page 2

Interior I	Notes:		
PLAN/S	SURVEY/DESIGNATION DATA		
Neighbo Subdivis Ward/Al Zoning:	sion:		Historic District(s) Designation Event(s)
Contribu	uting:		
Survey(s			Level(s) of Investigation
Capitol	Hill F & G Streets (2010)		Permit Research Reconnaissance Survey
РНОТО	OS - DIGITIZED		
Caption:			
Path:	C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\ 1018_F_Street_NE_facade_looking_	NE.JPG	
Date:: Code::	Photog:	Fr:	
Caption:	:		
Path:	C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\		
File:	1018_F_Street_NE_facade_looking_	NW.JPG	
Date:: Code::	Photog: R:	Fr:	
Caption:	C:\Users\CHRS\Documents\CHRS		
File:	Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\ 1018_F_Street_NE_rear_looking_SE	JPG	
Date::	Photog:	Fr:	

Tuesday, June 25, 2013 ID_Number: 0960-0044 Page 3

Photographer

Caption

PHOTOS - B/W OR NON-DIGITIZED

Roll

Frame(s)

Date

Photo Code

MISCELLANEOUS NOTES	S DATA					
Notes:						
PERMIT DATA						
Permit Issue Date	Number Type		Remarks			
06/06/1892	2608 Build					=
Permit Notes:						
						J
BIBLIOGRAPHIC DATA						
Short Citation		Туре	Date	Remarks		
		•				-
Bibliographic Notes:						
						J
SIGNIFICANCE DATA						
Study Unit						
Code Criteria						
					=	

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/5/2010	Dayton (MSD), Maria	Record Updated
3/5/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0044 Page 4

ID Number: 0960-0043

BASICS DATA

ID Numbe	er: 0960	-0043	Year Built:	1892	Da	ta Source:	Permit
Number	Extended	Street			Qua	d Type of Ad	dress
1020	-1020B	F Street			NE	Current	
1020		F Street			NE	Original	
Name(s)				Туре о	f Name)	
Rowhous	se, 1020 F S	treet, N.E.		Comm	on		
TaxCode1	I TaxCode:	2 TaxCode3	Туре	Explai	n		
0960/0043	3		Square/Lot	Curre	nt		

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain
Residential (Multi-Family) 1892 Permit Original
Residential (Single-Family) Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1892	Permit			2857 Permit
Construction Event	Asso	ciation		Associated	Name
Orig Construction	Build	der		Loveless, J	J.T.
Orig Construction	Owner		Loveless, J.T.		J.T.
Construction Notes:					

One of fourteen rowhouses constructed from the same permit (#2608).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0960-0043 Page 1

Surroundings:	Urban		Cross Refere	nce Notes:		
Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint:	Intact Row (1 of 14) Face on Setback Line Row Building/Rectangular Rectangular	Вау				
Number Stories:	2 plus basement					
Bays Wide:	2	Outhuile	ding Type	Con	tributing Status	
Height: Width:	17	Outbuild	ding Type	Con	tributing Status	
Depth/Length: SqFt: Volume: Lot Width	32					
Lot Depth/Length:		Outbuild	ding Notes:			
Lot SqFt:						
Acreage:						
Has Driveway:						
STYLE/EXTERIOR	DATA					
Architectural Style(s)						
Queen Anne						
Exterior & Architectura	al Notes:					
second story openin and second story op and is highlighted by northwest corner of the foundation. The and a one-light trans iron steps and railing sash window with a three-sided, rectangle height of the dwellin and features decorated the side bay opening fenestrated with 1/1, The windows have were windows have were and second story.	ree-course brick watertable gs. A string course, compo- lenings and a third string co y a molded cornice and a co the building and has a corb recessed westernmost oper som. Double-leaf paneled do gs provide access to the pri stone sill. A soldier brick se ular bay with chamfered cor g. The bay has the material tive pearl molding. Fenestra gs are topped by soldier bri double-hung, vinyl-sash. A yood sills. A one-story, full-v re wood post foundation.	sed of repurse bisorbeled belied caphing of the cors she mary enteres exteres the cors seems of the cors of	eed molding, sects the first cornice. o. A single-lea he first story lter the prima trance. The s I arch with pends from the tof the main sists of sing lental arches ngs are toppes	spans the façade a story openings. A An interior-rear briaf paneled metal do holds a single-leaf ary entrance and arrectond story opening e easternmost bay a block. A brick crole and paired 1/1, d with pearl molding d by two-course, ro	nd is located between the sloping roof caps the dwo ck chimney rises from the or with a blind transom p paneled metal door with let opped by a stone lintel. If you have a 1/1, double-hung of the façade and rises the with the window opening on the façade rises from buble-hung, vinyl-sash with the rear (north) elevation whock brick segmental and caps in the same could be window opening.	e first elling e ierces ights Cast ng, vinyl A ee full the bay indows. n is oches.
	o-story rowhouse is located	north o	f the dwelling	and is set back ap	proximately five feet fron	ı the
	dwelling is adjacent to 1018 acircled by a metal bow and					ed with
NOTABLE FEATUR	RES DATA					
Component	Feature					
EXTERIOR MATER	RIALS DATA					
Roof Component	Material	Co	olor	Treatment	Source	
Sloped	Not Visible			Not Visible		
Wall Component	Material	Со	olor	Treatment	Source	
Facade	Pressed Brick			Stretcher Bond		

Tuesday, June 25, 2013 ID_Number: 0960-0043 Page 2

Source

Feature

Structure Component

Material

Foundatio	n Brick				
Walls	Brick				
Materials N	Votes:				
WINDOW	//DOOR/INTERIOR DATA				
Window Lo	ocation Aperture Shape	Туре	Lights	Material	
2 FIr Wind		Dbl-Hung	1/1	Vinyl	
Bay Windo		Dbl-Hung	1/1	Vinyl	
Bay Windo	ows Rectangular	Dbl-Hung	1/1 Dou	uble Vinyl	
Door Locat	tion Aperture Shape	Туре	Pamels	Material	
Basement		Single	Panele	d Metal	
Main Door	=	Double	Panele	d Unknow	n
Main Door		Single	Panele	d Metal/Gl	as
Notable Int	terior Plan(s)		Notable Interior Feature	e(s)	
140(00)0 1111	onor rian(o)		- Hotable Interior Federal	0(0)	
Interior No	tes:				
PLAN/SU	RVEY/DESIGNATION DATA				
Neighborh	ood: Capitol Hill		Historic District(s)		
Subdivision	າ:				
Ward/ANC	:				
Zoning:			Designation Event(s)		
Contributin	g:				
Survey(s)			Level(s) of Investigation	n	
	II F & G Streets (2010)		Permit Research		
·	, ,		Reconnaissance Surv	vey	
PHOTOS	- DIGITIZED				
Caption:					
_	:\Users\CHRS\Documents\CHR	-			
	atabases\F&G Street - 2 to 11th t\Database\Pictures\Square 096				
	tiDatabaseiPicturesiSquare 096 020-	JU (
	020B_F_Street_NE_facade_loo	king_NE.JPG			

Tuesday, June 25, 2013 ID_Number: 0960-0043 Page 3

Date::

Code::

Photog:

Fr:

Caption	:						
Path:	C:\Users\CHRS\Do Databases\F&G St St\Database\Pictur	reet - 2 to 11th					
File:	1020-	IE_facade_looking_	NW.JPG				
Date::	Photo						
Code::		R:	Fr:				
Caption	:						
Path:	C:\Users\CHRS\Do	reet - 2 to 11th					
File:	St\Database\Pictur 1020-	res\Square 0960\ IE_rear_looking_SE	: IPG				
Date::	Photo						
Code::	FIIOLO	g. R:	Fr:				
РНОТО	OS - B/W OR NON	-DIGITIZED					
Photo C	code Roll	Frame(s)	Date	Photographer	Caption		
MISCE	LLANEOUS NOTE	ES DATA					
Notes:						_	
PERMI	T DATA						
Permit I	ssue Date	Number Type		Remarks			
06/06/18	892	2608 Build					
Permit N	Notes:						

DIDLINGDADUIC DATA

BIBLIOGRAPHIC DATA				
Short Citation	Туре	Date	Remarks	
Bibliographic Notes:				

SIGNIFICANCE DATA

Study Unit

Code Criteria

Tuesday, June 25, 2013 ID_Number: 0960-0043 Page 4

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/5/2010	Dayton (MSD), Maria	Record Updated
3/5/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0043 Page 5

ID Number: 0960-0042

BASICS DATA

ID Number: 0960-0042 Year Built: 1892 Data Source: Permit

Number Extended Street Quad Type of Address

600 11th Street NE Current

Name(s) Type of Name

Rowhouse, 600 11th Street, N.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

0960/0042 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1892 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Addition (Side) c. 1920 Site Visit/Map

Orig Construction 1892 Permit 2857 Permit 2857 Permit

Construction EventAssociationAssociated NameOrig ConstructionBuilderLoveless, J.T.Orig ConstructionOwnerLoveless, J.T.

Construction Notes:

One of fourteen rowhouses constructed from the same permit (#2608).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0960-0042 Page 1

Surroundings:	Urban	Cr	ross Reference Notes:	
Streetscape:	Intact			
Relate to Othr Bldgs	∷ Row (1 of 14)			
Relate to Street:	Face on Setback Line			
Massing:	Row Building/Rectangular	r Bay		
Footprint:	Rectangular			
Number Stories:	2 plus basement			
Bays Wide:	3			
Height:		Outbuilding	д Туре	Contributing Status
Width:	17			
Depth/Length:	32			
SqFt:				
Volume:				
Lot Width				
Lot Depth/Length:		Outbuilding	g Notes:	
Lot SqFt:				
Acreage:				
Has Driveway:				
STYLE/FXTERIO	R DATA			

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

March 2010: Constructed in 1892 by J.T. Loveless, this two-story, three-bay Queen Anne-style rowhouse is one of fourteen rowhouses constructed from the same permit. The dwelling is constructed of brick and is set on a solid and raised brick foundation; the façade (east elevation) is faced with pressed stretcher-bond brick. A four-course, stretcherbond brick watertable encircles the dwelling and is located above the foundation. Brick beltcourses are located beneath the first and second story window openings, between these openings, and bisecting the first story openings. Several of the beltcourses feature reed molding. The roofing type was obscured by a brick parapet, which features decorative checkerboard brick panels. A molded cornice and corbeled brick cornice finish the roof. An interior brick chimney rises from the northwest corner of the dwelling and has a corbeled brick cap. The central bay of the façade holds double-leaf paneled wood doors with lights and a one-light transom. Panels with reed molding and panels with bead molding flank the entry. A one-story, one-bay porch shelters the primary entrance. The flat roof of the porch has flared, overhanging eaves, which are supported by metal posts set on the stoop. Metal balusters encircle the roof of the porch, which serves as a second story deck for a single-leaf multi-light wood door. A single-leaf wood door with a diamond light pierces the foundation and is located below the porch. Three-sided, rectangular bays extend from the end bays of the façade and rise the full height of the dwelling. Each bay has chamfered corners with half-round brick molding and has the same material treatment as the main block. Pyramidal roofs with decorative slate shingles cap each bay. Finals top each roof. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows and paired one-light vinyl casement windows. One-light transoms top the central bay of the first story. All first and second story openings on the façade have soldier brick segmental arches with pearl molding. The foundation openings are topped by soldier brick segmental arches. All windows have stone sills. Decorative panels with bead molding are located between the first and second story of the central bay.

A three-sided, rectangular bay projects from the south (side) elevation and has the same material treatment as the bays on the façade. Fenestration is consistent with the façade.

The north (side) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows and a single-leaf multi-light wood door with a one-light transom. All openings are surmounted by two-course, rowlock brick segmental arches.

A one-story, full-width addition is located on the north elevation of the dwelling and was constructed c. 1920. The addition extends from the foundation of the dwelling and serves as a garage. The addition is constructed of brick and is set on a solid foundation. A flat roof caps the addition and supports a deck. The east elevation is fenestrated with a 1/1, double-hung, vinyl-sash window and a roll-up paneled metal door. The north elevation is fenestrated with one-light windows (possibly casement), which have concrete sills and two-course, rowlock brick segmental arches.

Site Notes

March 2010: This two-story rowhouse is located on the northwest corner of 11th Street, N.E. and F Street, N.E. and is set back approximately five feet from the brick sidewalk. The west (rear) elevation of the dwelling is adjacent to 1020-1020B F Street, N.E. The grassy front and side yards are encircled by metal hairpin and picket fencing. A concrete walkway leads from the primary entrance facing 11th Street, N.E. and ends at the brick sidewalk. An alley is located north of the dwelling.

NOTABLE FEATURES DATA

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Not Visible	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Pressed Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Brick				
Walls	Brick				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Rectangular	DoubleCase	1-light	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single		Wood/Glass
Main Door	Rectangular	Double	Paneled	Wood/Glass
Upper Story	Rectangular	Single		Wood/Glass
Notable Interior Plan	n(s)		Notable Interior Feature(s)	

nterior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	Capitol Hill	Historic District(s)	
Subdivision:			
Ward/ANC:			
Zoning:		Designation Event(s)	
Contributing:			
Survey(s)		Level(s) of Investigation	
Capitol Hill F &	G Streets (2010)	Permit Research	
		Reconnaissance Survey	

PHOTOS - DIGITIZED

Tuesday, June 25, 2013 ID_Number: 0960-0042 Page 3

Ca		

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 600_11th_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 600_11th_Street_NE_facade_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 600_11th_Street_NE_facade_looking_W.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

Permit Issue Date Number Type Remarks

06/06/1892 2608 Build

Permit Notes:

PERMIT DATA

BIBLIOGRAPHIC DATA

Short Citation Type Date Remarks



Bibliographic Notes:		
SIGNIFICANCE DATA		
Study Unit		
Code Criteria		

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/8/2010	Dayton (MSD), Maria	Record Created

ID Number: 0960-0041

BASICS DATA

ID Number: 0960-0041 Year Built: 1892 Data Source: Permit

Number Extended Street Quad Type of Address

612 11th Street NE Current

Name(s) Type of Name

Rowhouse, 612 11th Street, N.E. Common

 TaxCode1
 TaxCode2
 TaxCode3
 Type
 Explain

 0960/0041
 Square/Lot
 Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Renovated

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1892 Permit Original

Vacant Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction c. 2009 Site Visit/Map

Orig Construction 1892 Permit 2857 Permit

 Construction Event
 Association
 Associated Name

 Orig Construction
 Builder
 Loveless, J.T.

 Orig Construction
 Owner
 Loveless, J.T.

Construction Notes:

One of fourteen rowhouses constructed from the same permit (#2608).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0960-0041 Page 1

Surroundings:	Urban		Cross Refere	ence Notes:		
Streetscape:	Intact	ĺ				
Relate to Othr Bldgs:	Row (1 of 14)					
Relate to Street:	Face on Setback Line					
Massing:	Row Building/Rectangular	Bay				
Footprint:	Rectangular (w/ additions)					
Number Stories:	2 plus basement					
Bays Wide:	2					
Height:		Outbuild	ing Type		Contributing Status	_
Width:	17					
Depth/Length:	32					
SqFt:						
Volume:						
Lot Width						
Lot Depth/Length:		Outbuild	ing Notes:			ī
Lot SqFt:						
Acreage:						
Has Driveway:						
OTVI E/EVTEDIOD	DATA					
STYLE/EXTERIOR	DATA					
Architectural Style(s) Queen Anne						
	al Natao					
Exterior & Architectura		41.1-4			ne-style single-family rowho	
located between the and is highlighted by covered with plywood and a transom open hung, vinyl-sash wir opening, which also northernmost bay of block and is capped the roof. Fenestratio The first and second windows are highlig A two-story, full-wide wood-frame addition and features an over	first and second stories and a copy a molded cornice and a copy. The recessed southernming. A stone lintel surmount adow with false 6/6 vinyl mu has a stone sill. A three-sid the façade and rises the ful by a pyramidal roof. The roon consists of single and paid story openings are topped head by soldier brick segments and the side of the control of t	d bisect or beled by the training of the train	the first stor rick cornice ning of the fi nsom opening soldier brick ingular bay to of the dwelling ered with so double-hung er brick segues. est) elevation on a solid pa on. Fenestra	y window openi A single-leaf of the second is segmental archivith chamfered in the bay has uare butt and fing, vinyl-sash windered in the dwelling in the dwel	s the material treatment of the shscale slate shingles. A fini- dows with false 4/4 vinyl mu with pearl molding and the four grand was constructed c. 200 n. A sloping roof caps the adfining single-leaf wood-frame glas	dwelling n and is s door puble- window e main al tops ntins. undation 9. The dition
	n-story rowhouse is located	on the v	vest side of	11th Street N F	. and is set back approximate	ly five
feet from the brick s alley runs parallel to	idewalk. The north (side) ele	evation o	f the dwellir	g is adjacent to	614 11th Street, N.E. and a circled by metal chain-link fen	oncrete
NOTABLE FEATUR	RES DATA					
Component	Feature					
EXTERIOR MATER	RIALS DATA					
Roof Component	Material	Col	or	Treatment	Source	_
Bay Roof	Slate			Shingled		
Sloped	Not Visible			Not Visible		
Wall Component	Material	Col	or	Treatment	Source	

Tuesday, June 25, 2013 ID_Number: 0960-0041 Page 2

	Pressed Brick		Stretcher Bond	
Structure Componen	t Material	Feature	Source	
Foundation	Brick			
Walls	Brick			
Materials Notes:				
WINDOW/DOOR/I	NTERIOR DATA			
Window Location	Aperture Shape	Туре	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single		Boarded Up
Main Door	Rectangular	Single	Full Glass	Wood/Glass
Notable Interior Plan	(s)		Notable Interior Feature(s)	
	ESIGNATION DATA		Historic District(s)	
	ESIGNATION DATA		Historic District(s)	
Neighborhood: C				
Neighborhood: C Subdivision: Ward/ANC: Zoning:			Historic District(s) Designation Event(s)	
Neighborhood: C Subdivision: Ward/ANC:				
Neighborhood: C Subdivision: Ward/ANC: Zoning: Contributing: Survey(s)	apitol Hill			
Neighborhood: C Subdivision: Ward/ANC: Zoning: Contributing:	apitol Hill		Designation Event(s) Level(s) of Investigation Permit Research	
Neighborhood: C Subdivision: Ward/ANC: Zoning: Contributing: Survey(s)	apitol Hill		Designation Event(s) Level(s) of Investigation	
Neighborhood: C Subdivision: Ward/ANC: Zoning: Contributing: Survey(s)	treets (2010)		Designation Event(s) Level(s) of Investigation Permit Research	
Neighborhood: C Subdivision: Ward/ANC: Zoning: Contributing: Survey(s) Capitol Hill F & G S	treets (2010)		Designation Event(s) Level(s) of Investigation Permit Research	
Neighborhood: C Subdivision: Ward/ANC: Zoning: Contributing: Survey(s)	treets (2010)		Designation Event(s) Level(s) of Investigation Permit Research	
Neighborhood: C Subdivision: Ward/ANC: Zoning: Contributing: Survey(s) Capitol Hill F & G S	treets (2010)		Designation Event(s) Level(s) of Investigation Permit Research	
Neighborhood: C Subdivision: Ward/ANC: Zoning: Contributing: Survey(s) Capitol Hill F & G S	treets (2010)		Designation Event(s) Level(s) of Investigation Permit Research	

File: 612_11th_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Tuesday, June 25, 2013 ID_Number: 0960-0041 Page 3 Caption:

Undisplayable Image Format

Path:	C:\Users\CHRS Databases\F&0 St\Database\Pi	Street -	2 to 11th						
File:	612_11th_Stree			g_SW.JPG					
Date::	Pł	notog:							
Code::			R:	Fr:					
Caption	:								
					llne	dicalaya	abla Imac	no Forma	.4
Path:	C:\Users\CHRS Databases\F&0 St\Database\Pi	Street -	2 to 11th		One	uispiaya	able Imag	ge Forma	ıı
File:	612_11th_Stree			NE.JPG					
Date::	Pł	notog:	D.	F=:					
Code::			R:	Fr:					
РНОТ	OS - B/W OR N	ON-DIG	ITIZED						
Photo C	Code R	oll	Frame(s)	Date	Photograp	her	Caption		
MISCE	LLANEOUS N	OTES D	ATA						
Notes:									
PERM	IT DATA								
Permit 06/06/1	Issue Date	N	umber Type 2608 Build	l	Remarks				
Permit I	Notes:								
DIDI I	OCDADUIC DA	F.A.							
	OGRAPHIC DA	IA							
Short C	itation			Туре	Date	Remarks			
Biblioar	aphic Notes:								
	<u></u>								
SIGNII	FICANCE DATA	\							
Study L	Jnit								
Code	Criteria								
	Cillena						_		

Tuesday, June 25, 2013 ID_Number: 0960-0041 Page 4

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/8/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0041 Page 5

ID Number: 0960-0040

BASICS DATA							
ID Number: 0960	-0040	Year Bu	ilt: 1892	Data So	ource: Permit		
Number Extended	Street			Quad Typ	oe of Address		
614	11th Street			NE Cu	rrent		
Name(s)			Type	of Name			
Rowhouse, 614 11th	Street, N.E.						
TaxCode1 TaxCode	2 TaxCode3	Type	Expl	ain			
0960/0040		Square/Lo					
STATUS/PURPOS	E/USE DATA	\					
Resource Type: Buil	lding		S	atus Current	Extant		
Desig. Status: Hist	toric		Q	uality:			
Purpose: Rov	vhouse		C	ondition:	Good		
Function/Use		Start	Source	Stop	Source	Explain	
Residential (Single-F	amily)	1892	Permit			Original	
Residential (Multi-Fa	amily)					Current	
CONSTRUCTION I	DATA						
Construction Event			ource	Stop	Source	Cost Source	
Orig Construction	18	892 P	ermit			2857 Permit	
Construction Event		Association	n		Associated Na		
Orig Construction		Builder			Loveless, J.1		
Orig Construction		Owner			Loveless, J.1	•	
Construction Notes:							
One of fourteen row	houses const	ructed from	the same	permit (#260	8).		
PEOPLE/EVENTS	DATA						
Racial Segregation St	atus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Refer	ence Notes:		
Streetscape:	Intact			O1033 INCICIO	crice reces.		1
Relate to Othr Bldgs:	Row (1 of 14)					
Relate to Street:	Face on Sett						
Massing:	Row Building	g/Rectangul	lar Bay				
Footprint:	Rectangular						
Number Stories:	2 plus b	asement					
Bays Wide:	2						1
Height:			Outbuild	ding Type	I	Contributing Status	_
Width:	17		Shed				
Depth/Length:	32						
SqFt: Volume:							
Lot Width							
Lot Depth/Length:			Outbuild	ding Notes:			
Lot SqFt:			March 2	2010: A one-		hed is located west of the	
Acreage:						90. The shed is constructed	
Has Driveway:						oured concrete foundation. evered with asphalt	

shingles. Exposed rafter ends complement the porch.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

March 2010: Constructed in 1892 by J.T. Loveless, this two-story, two-bay Queen Anne-style single-family rowhouse is one of fourteen rowhouses constructed from the same permit (#2608). The dwelling is constructed of brick and is set on a solid and raised brick foundation; the facade (east elevation) is faced with pressed stretcher-bond brick. A four-course brick watertable is located above the foundation. Sill courses are sited below the first and second story openings. Brick string courses also are located between the first and second stories and bisect the first story window openings. A sloping roof caps the dwelling and is highlighted by a molded cornice and a corbeled brick cornice. An interior brick chimney pierces the roof. A single-leaf paneled metal door with lights pierces the foundation. The recessed southernmost opening of the first story holds a single-leaf paneled wood door with lights and a multi-light fanlight. A soldier brick round-headed arch with stone imposts and keystone surmount the transom. The second story opening holds a 1/1, double-hung, vinyl-sash window. A soldier brick round-headed arch with pearl molding tops the window opening, which also has a stone sill. A three-sided, rectangular bay with chamfered corners extends from the northernmost bay of the facade and rises the full height of the dwelling. The bay has the material treatment of the main block. A brick parapet rises from the bay and features a decorative brick panel with checkerboard brickwork. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. The first and second story openings are topped by soldier brick segmental arches with pearl molding and the foundation windows are highlighted by soldier brick segmental arches. The rear (west) elevation is parged and is fenestrated with 1/1, double-hung, vinyl-sash windows and two single-leaf metal doors. A one-story, full-width deck extends from the rear elevation and is set on a post foundation. Square wood balusters encircle the deck.

Site Notes:

March 2010: This two-story rowhouse is located on the west side of 11th Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 612 and 616 11th Street, N.E. The grassy front yard is landscaped with small trees and is encircled by a metal chain-link fence. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The grassy rear yard features mature trees. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		-
Wall Component	Material	Color	Treatment	Source	
Facade	Pressed Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Brick				
Walls	Brick				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single	Paneled	Metal/Glas	
Main Door	Rectangular	Single	Paneled	Wood/Glass	
Notable Interior Plar	n(s)		Notable Interior Feature(s)		

Tuesday, June 25, 2013 ID_Number: 0960-0040 Page 2

Interior	Notes:			
PLAN/	SURVEY/DESIGNATIO	N DATA		
Subdivi				Historic District(s)
Ward/A Zoning: Contrib				Designation Event(s)
Survey((s)			Level(s) of Investigation
Capitol	Hill F & G Streets (2010)			Permit Research Reconnaissance Survey
РНОТ	OS - DIGITIZED			
Caption	:			
				Undisplayable Image Format
Path:	C:\Users\CHRS\Docume Databases\F&G Street - St\Database\Pictures\Se	2 to 11th		
File:	614_11th_Street_NE_fa	cade_look	ing_NW.JPG	
Date:: Code::	Photog:	R:	Fr:	
Caption	:			
				Undisplayable Image Format
Path: File:	C:\Users\CHRS\Docume Databases\F&G Street - St\Database\Pictures\Se 614_11th_Street_NE_fa	2 to 11th quare 0960)\	
Date::	Photog:		<u></u>	
Code::		R:	Fr:	
Caption	ı:			

Undisplayable Image Format

Path:

File: Date::

Code::

C:\Users\CHRS\Documents\CHRS
Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0960\
614_11th_Street_NE_rear_looking_E.JPG

Photog:

R:

Fr:

Tuesday, June 25, 2013 ID_Number: 0960-0040 Page 3

Caption:

Path: C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\ File: 614_11th_Street_NE_shed_looking_NE.JPG Date:: Photog: Code:: R: Fr: **PHOTOS - B/W OR NON-DIGITIZED** Photo Code Date Photographer Caption Roll Frame(s) **MISCELLANEOUS NOTES DATA** Notes: **PERMIT DATA** Permit Issue Date Number Type Remarks 06/06/1892 2608 Build Permit Notes: **BIBLIOGRAPHIC DATA Short Citation** Type Date Remarks Bibliographic Notes: SIGNIFICANCE DATA Study Unit Criteria Code **DATA PROCESSING EVENTS DATA** Date Individual Action 3/8/2010 Dayton (MSD), Maria **Record Updated** 3/8/2010 Dayton (MSD), Maria **Record Created**

Tuesday, June 25, 2013 ID_Number: 0960-0040 Page 4

ID Number: 0960-0039

BASICS DATA							
ID Number: 0960	0-0039	Year B	uilt: 1892	Data	Source: Permit	:	
Number Extended	Street			Quad T	ype of Address		
616	11th Street			NE C	urrent		
Name(s)			Туре	e of Name			
Rowhouse, 616 11th	Street, N.E.		Con	nmon			
TaxCode1 TaxCode	2 TaxCode3	Туре	Exp	olain			
0960/0039		Square/L	ot Cu	rrent			
STATUS/PURPOS	E/USE DATA	\					
Resource Type: Bui	lding		5	Status Curre	nt: Extant		
o .	toric			Quality:			
Purpose: Rov	vhouse		(Condition:	Good		
Function/Use		Start	Source	Stop	Source	Explain	
Residential (Single-I		1892	Permit			Original	
Residential (Multi-Fa	amily)					Current	
CONSTRUCTION	DATA						
Construction Event		tart	Source	Stop	Source	Cost Source	
Orig Construction	18	392	Permit			2857 Permit	
Construction Event		Association	on		Associated Na	ame	
Orig Construction		Builder			Loveless, J.T		
Orig Construction		Owner			Loveless, J.T	Г.	
Construction Notes:							
One of fourteen row	houses const	ructed fron	n the same	permit (#26	608).		
PEOPLE/EVENTS	DATA						
Racial Segregation S	tatus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban			Cross Refe	erence Notes:		
Streetscape: Relate to Othr Bldgs:	Intact						
Relate to Street:	Face on Sett						
Massing:	Row Building		ılar Bav				
Footprint:	Rectangular	g-					
Number Stories:	2 plus b	asement					
Bays Wide:	2						
Height:			Outbui	lding Type		Contributing Status	

Width: 17

Garage

Depth/Length: 32

SqFt: Volume: Lot Width

Lot Depth/Length: Outbuilding Notes:

March 2010: This two-story, one-bay garage is located west of Lot SqFt: the dwelling and has been rehabilitated as a dwelling. The Acreage:

garage, constructed c. 1960, is composed of concrete blocks Has Driveway: and is set on a solid concrete block foundation. A flat roof

caps the garage. Fenestration consists of 1/1, double-hung, vinyl-sash windows and one-light fixed windows. The first story of the façade (west elevation) originally held the vehicular opening, but it has been partially infilled with T-111 siding. A single-leaf metal door pierces the T-111 siding.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

March 2010: Constructed in 1892 by J.T. Loveless, this two-story, two-bay Queen Anne-style single-family rowhouse is one of fourteen rowhouses constructed from the same permit (#2608). The dwelling is constructed of brick and is set on a solid and raised brick foundation; the façade (east elevation) is faced with pressed stretcher-bond brick. A four-course brick watertable is located above the foundation. Sill courses are sited below the first and second story openings. Brick string courses also are located between the first and second stories. A sloping roof caps the dwelling and is highlighted by a molded cornice and a corbeled brick cornice. An interior brick chimney pierces the roof and has a corbeled brick cap. A single-leaf paneled wood door with lights pierces the foundation and is topped by a one-light transom. The recessed southernmost opening of the first story holds a single-leaf paneled metal door and a one-light transom. A stone lintel surmounts the transom opening. The second story opening holds a 1/1, double-hung, vinyl-sash window. A soldier brick segmental arch with pearl molding tops the window opening, which also has a stone sill. A three-sided, rectangular bay with chamfered corners extends from the northernmost bay of the facade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a pyramidal roof. The roof is covered with square butt and fishscale slate shingles. A finial tops the roof. The frieze features a recessed panel composed of basketweave brick. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. The first and second story openings are topped by soldier brick segmental arches with pearl molding and the foundation windows are highlighted by soldier brick segmental arches. The rear (west) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows and a single-leaf paneled door with lights and a one-light transom. All openings have two-course, rowlock brick segmental arches.

Site Notes:

March 2010: This two-story rowhouse is located on the west side of 11th Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 614 and 618 11th Street, N.E. The front yard is bounded by a metal milled point fence. A brick archway provides an entry point from the public brick sidewalk to the front yard. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component Feature

Material

EXTERIOR MATERIALS DATA

Roof Component

Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Pressed Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Brick				
Walls	Brick				
Materials Notes:					

Color

WINDOW/DOOR/INTERIOR DATA

Basement	Rectangular	Single	Paneled	Wood/Glass	
Door Location	Aperture Shape	Туре	Pamels	Material	
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Window Location	Aperture Shape	Туре	Lights	Material	

Treatment

Source

Tuesday, June 25, 2013 ID_Number: 0960-0039 Page 2

Main Do	oor	Rectangular		Single	Paneled Metal
Notable	Interior Plan(s	s)			Notable Interior Feature(s)
	`	,			
Interior I	Notes:				
PLAN/	SURVEY/DE	SIGNATION	DATA		
Neighbo	orhood: Ca	pitol Hill			Historic District(s)
Subdivis					
Ward/Al					Designation Franks
Zoning: Contribu					Designation Event(s)
	-				
Survey(s		. (00.10)			Level(s) of Investigation
Capitol	Hill F & G Str	eets (2010)			Permit Research Reconnaissance Survey
PHOTO	OS - DIGITIZ	ED			
Caption	:				
					Undisplayable Image Format
Path:	C:\Users\CH	RS\Document	ts\CHRS		3g
i diii.	Databases\F	&G Street - 2	to 11th		
Ela.		\Pictures\Squ		. NW IDO	
File:	616_11tn_5t	reet_NE_faca	ae_iookinį	g_NW.JPG	
Date:: Code::		Photog:	R:	Fr:	
Caption					
Caption	•				
					Undisplayable Image Format
D-th	0.1111011	DOID			Ondisplayable image i ormat
Path:		RS\Document &G Street - 2			
		\Pictures\Squ			
File:	616_11th_St	reet_NE_faca	de_looking	g_SW.JPG	
Date:: Code::		Photog:	R:	Fr:	
			14.	11.	
Caption	:				
					Undisplayable Image Format
Path:		RS\Document			-
		&G Street - 2			
File:		\Pictures\Squ :reet_NE_rear_		NE.JPG	
Date::		Photog:		- -	
Code::		·-·- 9·	R:	Fr:	

Caption:

Undisplayable Image Format

Path:	Databases\	F&G Street	nents\CHRS : - 2 to 11th Square 0960\						
File:			NE_looking_E.J	PG					
Date::		Photog:							
Code::			R:	Fr:					
Caption	:								
Path:	Databases\	F&G Street	nents\CHRS : - 2 to 11th Square 0960\						
File:			NE_looking_NE.	JPG					
Date::		Photog:							
Code::			R:	Fr:					
Path: File: Date:: Code::	C:\Users\C Databases\ St\Databas	\F&G Street e\Pictures\	Square 0960\ NE_looking_SE.	JPG Fr:	Un	displaya	able Image	Format	
РНОТ	OS - B/W O	R NON-DIG	GITIZED						
Photo C	Code	Roll	Frame(s)	Date	Photograp	oher	Caption		
MISCE	LLANEOUS	S NOTES I	DATA						
Notes:									
PERM	IT DATA								
Permit I	ssue Date		Number Type		Remarks				
06/06/1	892		2608 Build						
Permit I	Notes:								
BIBLIC	OGRAPHIC	DATA							
Short C	itation			Туре	Date	Remarks			

Tuesday, June 25, 2013 ID_Number: 0960-0039 Page 4

Bibliographic	Notes:			
SIGNIFICA	NCE DATA			
Study Unit				
Code	Criteria			

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/8/2010	Dayton (MSD), Maria	Record Created

ID Number: 0960-0038

BASICS DATA								
ID Number: 0960	-0038	Year Built	1892	Data	a Source: P	ermit		
Number Extended	Street			Quad	Type of Addres	ss		
618	11th Street			NE	Current			
Name(s)			Type	of Name				
Rowhouse, 618 11th	Street, N.E.		Comn	non				
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	in				
0960/0038		Square/Lot	Curre					
STATUS/PURPOS	E/USE DATA	ı						
Resource Type: Buil	lding		Sta	atus Curre	ent: Extant			
3	toric		Qu	ality:				
Purpose: Rov	vhouse		Co	ndition:	Good			
Function/Use		Start	Source	Stop	Sou	rce	Explain	
Residential (Single-F	amily)	1892	Permit				Original	
Residential (Multi-Fa	ımily)						Current	
CONSTRUCTION								
Construction Event			ırce	Stop	Source		Cost Source 2857 Permit	<u>—</u>
Orig Construction	10		mit					
Construction Event		Association			Associat		me	
Orig Construction Orig Construction		Builder Owner			Loveles Loveles			
_		Owner			Loveles	3, 0.1.		
Construction Notes:	haaa aanat	atad fram ti		aum: 145	200)			
One of fourteen row	nouses consti	ructea from ti	ne same p	ermit (#2	2008).			
PEOPLE/EVENTS	DATA							
Racial Segregation St	atus:							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban		-	Cross Re	eference Notes:			
Streetscape:	Intact							
Relate to Othr Bldgs:	Row (1 of 14)							
Relate to Street:	Face on Setb		_					
Massing:	Row Building	g/Rectangulai	r Bay					
Footprint:	Rectangular							
Number Stories:	2 plus b	asement						
Bays Wide:	2		Outbuild	ina Tuna		C	antributing Status	
Height: Width:	17		Garage	ing Type			ontributing Status ontributing	
Depth/Length:	32		Garage			0.	ontributing	
SqFt:	*-							
Volume:								
Lot Width								
Lot Depth/Length:				ing Notes				
Lot SqFt:							s one-story, one-bay	
Acreage:			constru	s located cted of c	oncrete blocks	s and is	g. The garage is set on a solid concrete	

block foundation. A sloping roof caps the garage. The façade

Has Driveway:

(west elevation) is pierced by a roll-up paneled metal door.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

March 2010: Constructed in 1892 by J.T. Loveless, this two-story, two-bay Queen Anne-style single-family rowhouse is one of fourteen rowhouses constructed from the same permit (#2608). The dwelling is constructed of brick and is set on a solid and raised brick foundation; the facade (east elevation) is faced with pressed stretcher-bond brick. A four-course brick watertable is located above the foundation. Sill courses are sited below the first and second story openings. A string course spans the façade and is located between the first and second story openings. A sloping roof caps the dwelling and is highlighted by a molded cornice and a corbeled brick cornice. A single-leaf paneled wood door with lights pierces the foundation. The recessed southernmost opening of the first story holds a single-leaf paneled metal door with lights and a round-headed fanlight. The round-headed blind fanlight is highlighted by a soldier brick roundheaded arch with stone imposts and keystone. Cast iron steps and railings provide access to the primary entrance. The second story opening holds a 1/1, double-hung, vinyl-sash window. A soldier brick segmental arch with pearl molding surmounts the window opening. A three-sided, rectangular bay with chamfered corners extends from the northernmost bay of the facade and rises the full height of the dwelling. The bay has the material treatment of the main block. A brick crowstep parapet rises from the bay and features decorative pearl molding. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. The first and second story openings are topped by soldier brick segmental arches with pearl molding and the foundation windows are highlighted by soldier brick segmental arches. The rear (west) elevation is parged and is fenestrated with 1/1, double-hung, vinyl-sash windows and a sliding glass doors. All window openings are set in segmental openings. A one-story, full-width wood-frame deck extends from the rear elevation of the dwelling and is set on a square wood post foundation.

Site Notes:

March 2010: This two-story rowhouse is located on the west side of 11th Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 616 and 620 11th Street, N.E. The grassy front yard is enclosed with a metal chain-link fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is bounded by wood fencing. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Brick			
Materials Notes:				

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single	Paneled	Wood/Glass
Main Door	Rectangular	Single	Paneled	Metal/Glas
Notable Interior Plan	n(s)		Notable Interior Feature(s)	

Tuesday, June 25, 2013 ID_Number: 0960-0038 Page 2

nterior Notes:	
PLAN/SURVEY/DESIGNATION DATA	
Neighborhood: Capitol Hill Subdivision:	Historic District(s)
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill F & G Streets (2010)	Permit Research
	Reconnaissance Survey
DUOTOG DIGITIZED	
PHOTOS - DIGITIZED	
Caption:	
	He dieuleuskie lees ee Fermeri
	Undisplayable Image Format
Path: C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th	
St\Database\Pictures\Square 0960\	
File: 618_11th_Street_NE_facade_looking_NW.JPG	
Date:: Photog:	
Code:: R: Fr:	
Caption:	
	Undicalovable Image Formet
Dully All Journey	Undisplayable Image Format
Path: C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th	
St\Database\Pictures\Square 0960\ File: 618_11th_Street_NE_facade_looking_SW.JPG	
Date:: Photog:	
Code:: R: Fr:	
Caption:	
Path: C:\Users\CHRS\Documents\CHRS	
Databases\F&G Street - 2 to 11th	
St\Database\Pictures\Square 0960\ File: 618 11th Street NE garage looking SE.JPG	

Tuesday, June 25, 2013 ID_Number: 0960-0038 Page 3

Date::

Code::

Photog:

R:

Fr:

Undisplayable Image Format

Path:	Databases	CHRS\Docu s\F&G Stre se\Pictures	et - 2 to 11	th					
File:		Street_NE	-		E.JPG				
Date::		Photog:							
Code::			R:		Fr:				
РНОТО	OS - B/W C	R NON-D	IGITIZED)					
Photo C	ode	Roll	Fram	e(s)	Date	Photog	rapher	Caption	
MISCE	LLANEOU	S NOTES	DATA						
Notes:									
PERMI	T DATA								
Permit I	ssue Date		Number	Туре		Remarks			
06/06/18	892		2608	Build					
Permit N	Notes:								
BIBLIC	GRAPHIC	DATA							
Short Ci	itation				Туре	Date	Remarks		
Bibliogra	aphic Notes:								
	ICANCE D	DATA							
Study U	nit								
Code	Crite	eria						_	
DATA	PROCESS	ING EVEN	NTS DAT	Ą					
Date		Individual			Action				
4/26/20	10		DDL), Dan	a	Record	Updated			
3/8/2010	0	Dayton (N	/ISD), Mari	а	Record	Updated			
3/8/2010	0	Dayton (N	/ISD), Mari	а	Record	Created			

ID Number: 0960-0037

ID Number: 0960	-0037	Year Buil	t: 1892	Data	a Source:	Permit		
Number Extended	Street			Quad	Type of Addre	ess		
620	11th Street			NE	Current			
Name(s)			Туре	of Name				
Rowhouse, 620 11th	Street, N.E.		Com	mon				
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	ain				
0960/0037		Square/Lot						
STATUS/PURPOS	E/USE DATA							
Resource Type: Bui	_				ent: Extant			
_	toric			uality: ondition:	Cood			
ruipose. Rov	vhouse		C	maition.	Good			
Function/Use		Start	Source	Stop	So	urce	Explain	
Residential (Single-I		1892	Permit				Original Current	
Residential (Multi-Fa	aminy)						Current	
CONSTRUCTION I	DATA							
Construction Event	St	art So	urce	Stop	Source		Cost Source	
Orig Construction	18	92 P€	rmit				2857 Permit	
Construction Event		Association			Associ	ated Nar	me	
Orig Construction		Builder			Lovele	ss, J.T.		
Orig Construction		Owner			Lovele	ss, J.T.		
Construction Notes:								
One of fourteen row	houses consti	ructed from	he same p	permit (#2	2608).			
PEOPLE/EVENTS	ΠΑΤΑ							
Racial Segregation St	iatus:							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban			Cross Re	eference Notes	3:		
Streetscape:	Intact							
Relate to Othr Bldgs:								
Relate to Street:	Face on Seth		- B					
Massing: Footprint:	Row Building Rectangular	g/Rectangula	r Bay					
	_							
Number Stories: Bays Wide:	2 plus ba 2	asement						
Height:	2		Outbuild	ling Type		С	ontributing Status	
Width:	17			9 . , p =			Jim Jum g Clarad	
Depth/Length:	32							
SqFt:								
Volume:								
Lot Width Lot Depth/Length:			Outhuila	ling Notes	2.			
Lot SqFt:			Juibuilo	mig NOIES	J.			
Acreage:								
Has Driveway:								

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

March 2010: Constructed in 1892 by J.T. Loveless, this two-story, two-bay Queen Anne-style single-family rowhouse is one of fourteen rowhouses constructed from the same permit (#2608). The dwelling is constructed of brick and is set on a solid and raised brick foundation; the facade (east elevation) is faced with pressed stretcher-bond brick. A four-course brick watertable is located above the foundation. Sill courses are sited below the first and second story openings. A brick string course is also located between the first and second stories. A sloping roof caps the dwelling and is highlighted by a molded cornice and a corbeled brick cornice. A single-leaf paneled wood door with a blind transom pierces the foundation. The southernmost opening of the first story holds a single-leaf paneled wood door and a onelight transom. A stone lintel surmounts the transom opening. The second story opening holds a 1/1, double-hung, vinylsash window. A soldier brick segmental arch with pearl molding tops the window opening, which also has a stone sill. A three-sided, rectangular bay with chamfered corners extends from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a pyramidal roof. The roof is covered with square butt and fishscale slate shingles. A finial tops the roof. The frieze is complemented by a recessed panel of basketweave brickwork. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows. The first and second story openings are topped by soldier brick segmental arches with pearl molding and the foundation windows are highlighted by soldier brick segmental arches. The rear (west) elevation is fenestrated with 1/1, doublehung, vinyl-ash windows and sliding glass doors. The windows are topped by two-course, rowlock brick segmental arches and have rowlock brick sills. Several openings have been altered. A one-story, full-width wood-frame deck extends from the rear elevation of the dwelling and is encircled by square wood balusters.

Site Notes:

March 2010: This two-story rowhouse is located on the west side of 11th Street, N.E. and is set back approximately five feet from the brick sidewalk. The dwelling is adjacent to 620 and 624 11th Street, N.E. The front yard is bounded by a low, brick retaining wall, that is topped with English ivy. The rear yard is bounded by wood fencing. An asphalt-paved parking space and a public alley are located west of the dwelling.

NOTABLE FEATURES DATA

Component Fea	ture
---------------	------

EXTERIOR MATERIALS DATA

Material	Color	Treatment	Source
Slate		Shingled	
Not Visible		Not Visible	
Material	Color	Treatment	Source
Pressed Brick		Stretcher Bond	
Material	Feature		Source
Brick			
Brick			
	Slate Not Visible Material Pressed Brick Material Brick	Slate Not Visible Material Color Pressed Brick Material Feature Brick	Slate Not Visible Material Color Treatment Pressed Brick Stretcher Bond Material Feature Brick

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	ay Windows Rectangular Dbl-Hung		1/1 Double	Vinyl	
Door Location	Aperture Shape	Type	Pamels	Material	
Basement	Rectangular	Single	Paneled	Wood	
Main Door	Rectangular	Single	Paneled	Wood	
Notable Interior Plan	n(s)		Notable Interior Feature(s)		

Interior Notes:			

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Subdivision: Ward/ANC:

Zoning: Designation Event(s)

Contributing:

Survey(s) Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research Reconnaissance Survey

Historic District(s)

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 620_11th_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 620_11th_Street_NE_facade_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

File:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\ 620_11th_Street_NE_rear_looking_E.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:							
PERMIT DATA	A						
Permit Issue Da	te Number	Туре		Remarks			
06/06/1892	2608	Build					_
Permit Notes:							
BIBLIOGRAP	HIC DATA						
Short Citation			Туре	Date	Remarks		
Bibliographic No	otes:						_
CIONIFICANO	NE DATA						
SIGNIFICANO	EDATA						
Study Unit							
Code	Criteria					_	
DATA PROCE	ESSING EVENTS DAT	A					
Date	Individual		Action				
3/8/2010	Dayton (MSD), Mar	ia	Record Upda	ated			
3/8/2010	Dayton (MSD), Mar	ia	Record Crea	ted			

ID Number: 0960-0036

BASICS DATA

ID Number: 0960-0036 Year Built: 1892 Data Source: Permit

Number Extended Street Quad Type of Address

622 11th Street NE Current

Name(s) Type of Name

Rowhouse, 622 11th Street, N.E. Common

 TaxCode1
 TaxCode2
 TaxCode3
 Type
 Explain

 0960/0036
 Square/Lot
 Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Rowhouse Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1892 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Rear Addition c. 1965 Site Visit/Map

Orig Construction 1892 Permit 2857 Permit

 Construction Event
 Association
 Associated Name

 Orig Construction
 Builder
 Loveless, J.T.

Orig Construction Owner Loveless, J.T.

Construction Notes:

One of fourteen rowhouses constructed from the same permit (#2608).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: Streetscape:	Urban Intact		Cross Refere	nce Notes:		
Relate to Othr Bldgs: Relate to Street: Massing:	Row (1 of 14) Face on Setback Line Row Building/Rectangular	Rav				
Footprint:	Rectangular	Бау				
Number Stories:	2 plus basement					
Bays Wide: Height:	2	Outbuild	ding Type	(Contributing Status	
Width: Depth/Length:	17 32					
SqFt: Volume:						
Lot Width						
Lot Depth/Length:		Outbuild	ding Notes:			
Lot SqFt: Acreage:						
Has Driveway:						
STYLE/EXTERIOR	DATA					
Architectural Style(s)						
Queen Anne						
Exterior & Architectura					ne-style single-family rowhou	
string courses also a sloping roof caps the chimney pierces the opening of the first sarch with stone impovinyl-sash window. A stone sill. A three-signises the full height obay and features a double-hung, vinyl-second story openinhighlighted by soldie windows, a single-le segmental arches ar foundation. Square of the segmental single-le segmental arches ar foundation. Square of the segmental single-le segmental arches ar foundation. Square of the segmental single-le segmental arches ar foundation. Square of the segmental single-le segmental arches ar foundation is classification.	are located between the first e dwelling and is highlighte roof. A single-leaf metal do story holds a single-leaf pan ests and keystone surmound soldier brick round-headed ded, rectangular bay with chor the dwelling. The bay has eccorative brick panel with the grame topped by soldier brick segmental arches. The wood door, and single-lead concrete sills. A one-story wood balusters encircle the dwith horizontal siding and	t and set d by a m or with I eled doot t the blir d arch w amfered the mat ogtooth ansom o ck segm he rear af door. y, full-w deck. A	cond stories a colded cornical ights pierces or with lights and fanlight. The corners external treatments in the complements (west) elevation of the reced by a shed	and bisecting the and a corbelecthe foundation. and a blind fanline second story ding tops the winds from the main blenestration conthe central bay with pearl moldon is fenestrate a complemented ends from the relevation and roof.	at and second story openings the first story window opening of brick cornice. An interior bear the recessed southernmos ight. A soldier brick round-hopening holds a 1/1, double indow opening, which also horthernmost bay of the façactock. A brick parapet rises from the first story. The first arrived the first story. The first arrived with 1/1, double-hung, ving and the foundation wind double with 1/1, double-hung, ving a levation and is set on a lest story of the rear elevation. It was constructed c. 1965. The and is set back approximate	gs. A rick t eaded -hung, las a le and om the l, ld lows are lyl-sash ck post .
feet from the brick s mature shrubs and is and ends at the side	idewalk. The dwelling is adj s encircled by a metal milled	acent to d point f caped w	620 and 624 ence. A walky ith mature sh	11th Street, N.E. vay leads from t rubs and trees	and is set back approximate The front yard is landscape the primary entrance of the d and is bounded by wood fen	d with welling
NOTABLE FEATUR	RES DATA					
Component	Feature					
EXTERIOR MATER	RIALS DATA					
Roof Component	Material	Co	lor	Treatment	Source	
Sloped	Not Visible			Not Visible		
Wall Component	Material	Co	lor	Treatment	Source	

Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature	Source	
Foundation	Brick			 -
Walls	Brick			
Materials Notes:				
WINDOW/DOOR/IN	TERIOR DATA			
Window Location	Aperture Shape	Туре	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single		Metal/Glas
Main Door	Rectangular	Single	Paneled	Unknown w/Lights
Notable Interior Plan(s)		Notable Interior Feature(s)	
Interior Notes:				
PLAN/SURVEY/DE	SIGNATION DATA			
Neighborhood: Ca Subdivision:	SIGNATION DATA		Historic District(s)	
Neighborhood: Ca Subdivision: Ward/ANC:				
Neighborhood: Ca Subdivision:			Historic District(s) Designation Event(s)	
Neighborhood: Ca Subdivision: Ward/ANC: Zoning:				
Neighborhood: Ca Subdivision: Ward/ANC: Zoning: Contributing:	pitol Hill		Designation Event(s)	

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 622_11th_Street_NE_facade_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path:	C:\Users\CHRS\ Databases\F&G St\Database\Pic	Street -	2 to 11th						
File:	622_11th_Stree			_W.JPG					
Date::	Pho	otog:							
Code::			R:	Fr:					
Caption	:								
					اء ما ا	!:a.a.l.a	م مسلمان	- -	
D //		_			Und	ispiaya	able Image	e Format	
Path:	C:\Users\CHRS\ Databases\F&G	Street -	2 to 11th						
File:	St\Database\Pio			IDC					
Date::		tog:	ar_iooking_E	JPG					
Code::	1 11	nog.	R:	Fr:					
PHOTO	OS - B/W OR NO	N-DIGI	TIZED						
Photo C	Code Ro	oll	Frame(s)	Date	Photograph	er	Caption		
Notes:	ELLANEOUS NO	TES DA	ATA						
PERM	IT DATA								
Permit 06/06/1	Issue Date	Ni	umber Type 2608 Build		Remarks				_
Permit I	Notes:								7
BIBLIC	OGRAPHIC DAT	Α							
Short C	itation			Туре	Date	Remarks			_
Bibliogr	aphic Notes:								
SIGNII	FICANCE DATA								_
Study L									
Code	Criteria						_		

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/8/2010	Dayton (MSD), Maria	Record Created

ID Number: 0960-0035

ID Number: 0960	-0035	Year Built	: 1892	Data	a Source:	Permit		
Number Extended	Street			Quad	Type of Addr	ess		
624	11th Street			NE	Current			
Name(s)			Туре	of Name				
Rowhouse, 624 11th	Street, N.E.		Com	mon				
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	ain				
0960/0035		Square/Lot						
STATUS/PURPOS	E/USE DATA							
Resource Type: Buil	_				ent: Extant			
_	toric			uality: ondition:	Cood			
ruipose. Rov	vhouse		C	maillon.	Good			
Function/Use		Start	Source	Stop	Sc	ource	Explain	
Residential (Single-Residential (Multi-Fa		1892	Permit				Original Current	
Nesidential (Multi-1 a	aiiiiy)						Current	
CONSTRUCTION I	DATA							
Construction Event	St	art So	urce	Stop	Source		Cost Source	
Orig Construction	18	892 Pe	rmit				2857 Permit	
Construction Event		Association			Assoc	iated Nar	me	
Orig Construction		Builder				ess, J.T.		
Orig Construction		Owner			Lovele	ess, J.T.		
Construction Notes:								
One of fourteen row	houses consti	ucted from t	he same p	permit (#2	2608).			
PEOPLE/EVENTS	DATA							
Racial Segregation St								
Nacial Segregation St	iaius.							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban			Cross Re	eference Note	s:		
Streetscape:	Intact							l
Relate to Othr Bldgs:								l
Relate to Street:	Face on Seth		- D					l
Massing: Footprint:	Row Building Rectangular	g/Rectangula	r Bay					l
	_							l
Number Stories:	2 plus b	asement						
Bays Wide: Height:	2		Outhuild	ling Type		C	ontributing Status	
Width:	17		Outbuild	iiig Type			Onlinbuting Status	
Depth/Length:	32							
SqFt:								
Volume:								
Lot Width								
Lot Depth/Length:			Outbuild	ling Notes	S:			1
Lot SqFt:								1
Acreage:								1
Has Driveway:								

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

March 2010: Constructed in 1892 by J.T. Loveless, this two-story, two-bay Queen Anne-style single-family rowhouse is one of fourteen rowhouses constructed from the same permit (#2608). The dwelling is constructed of brick and is set on a solid and raised brick foundation; the facade (east elevation) is faced with pressed stretcher-bond brick. A four-course brick watertable is located above the foundation. Sill courses are sited below the first and second story openings. Brick string course are also located between the first and second stories and bisecting the first story openings. A sloping roof caps the dwelling and is highlighted by a molded cornice and a corbeled brick cornice. An interior-side brick chimney rises from the north (side) elevation and has a corbeled brick cap. A second interior brick chimney pierces the roof and is located near the rear (west) elevation. A single-leaf paneled door with lights and a one-light transom pierce the foundation. The recessed southernmost opening of the first story holds a single-leaf paneled wood door with leaded lights and a one-light transom. A stone lintel surmounts the transom opening. The second story opening holds a 1/1, double-hung, vinyl-sash window with false 6/6 vinyl muntins. A soldier brick segmental arch with pearl molding tops the window opening, which also has a stone sill. A three-sided, rectangular bay with chamfered corners extends from the northernmost bay of the facade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a pyramidal roof. The roof is covered with square butt and fishscale slate shingles. A finial tops the roof. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows with false 4/4 vinyl muntins and one-light fixed vinyl windows with false twenty-light vinyl muntins. The first and second story openings are topped by soldier brick segmental arches with pearl molding and the foundation windows are highlighted by soldier brick segmental arches. The rear (west) elevation is parged and scored to imitate stone. The rear is fenestrated with 1/1, double-hung, vinyl-sash windows with false 4/4 and 6/6 vinyl muntins and double-leaf paneled doors with lights. The windows are topped by two-course, rowlock brick segmental arches and have concrete sills.

Site Notes:

March 2010: This two-story rowhouse is located on the west side of 11th Street, N.E. and is set back approximately five feet from the brick sidewalk. The south (side) elevation of the dwelling is adjacent to 622 11th Street, N.E. The grassy front yard is bounded by a metal hairpin and picket fence. A brick walkway runs parallel to the north (side) elevation of the dwelling. The rear elevation is bounded by wood fencing. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
I	

EXTERIOR MATERIALS DATA

Material	Color	Treatment	Source	
Slate		Shingled		
Not Visible		Not Visible		
Material	Color	Treatment	Source	
Pressed Brick		Stretcher Bond		
Material	Feature		Source	
Brick				
Brick				
	Slate Not Visible Material Pressed Brick Material Brick	Slate Not Visible Material Color Pressed Brick Material Feature Brick	Slate Not Visible Material Pressed Brick Material Feature Brick Shingled Not Visible Not Visible Stretcher Bond	Slate Not Visible Material Color Treatment Source Pressed Brick Material Feature Source Stretcher Bond Material Feature

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material
2 FIr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Bay Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Bay Windows	Rectangular	Fixed	1-light	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single	Paneled	Unknown w/Lights
Main Door	Rectangular	Single	Paneled	Wood/Glass

Notable	Interior Plan(s)	Notable Interior Feature(s)
Interior	Notes:	
PLAN/	SURVEY/DESIGNATION DATA	
Neighbo		Historic District(s)
Subdivis Ward/A		
Zoning:		Designation Event(s)
Contribu	uting:	
Survey((s)	Level(s) of Investigation
	Hill F & G Streets (2010)	Permit Research
		Reconnaissance Survey
PHOTO	OS - DIGITIZED	
Caption	:	
		Undisplayable Image Format
Path:	C:\Users\CHRS\Documents\CHRS	onalopiayasio imago i ormat
ı aııı.	Databases\F&G Street - 2 to 11th	
File:	St\Database\Pictures\Square 0960\ 624_11th_Street_NE_facade_looking_NW.JPG	
Date::	Photog:	
Code::	R: Fr:	
Caption	:	
		Undisplayable Image Format
Path:	C:\Users\CHRS\Documents\CHRS	3
	Databases\F&G Street - 2 to 11th	
File:	St\Database\Pictures\Square 0960\ 624_11th_Street_NE_facade_looking_SW.JPG	
Date::	Photog:	
Code::	R: Fr:	
Caption	ı:	
		Undisplayable Image Format
Path:	C:\Users\CHRS\Documents\CHRS	Chaloplayable image i offilat
raill.	Databases\F&G Street - 2 to 11th	
T:1.	St\Database\Pictures\Square 0960\	
File:	624_11th_Street_NE_rear_looking_E.JPG	
Date::	Photog:	

Path:

Undisplayable Image Format

C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\ File: 624_11th_Street_NE_rear_looking_SE.JPG Date:: Photog: Code:: Fr: **PHOTOS - B/W OR NON-DIGITIZED** Photo Code Date Photographer Roll Frame(s) Caption **MISCELLANEOUS NOTES DATA** Notes: **PERMIT DATA** Permit Issue Date Number Type Remarks 06/06/1892 2608 Build Permit Notes: **BIBLIOGRAPHIC DATA Short Citation** Type Date Remarks Bibliographic Notes: **SIGNIFICANCE DATA** Study Unit Criteria Code **DATA PROCESSING EVENTS DATA** Date Individual Action 3/8/2010 Dayton (MSD), Maria **Record Updated** 3/8/2010 Dayton (MSD), Maria **Record Created**

ID Number: 0960-0018

ID Number: 0960	-0018 Year E	Built: c. 1970	Dat	a Source: DC Rea	al Property Database	
Number Extended	Street		Quad	Type of Address		
630	11th Street		NE	Current		
Name(s)		Туре	of Name			
Apartment Building,	630 11th Street, N.E.	Comn	non			
TaxCode1 TaxCode2	2 TaxCode3 Type	Expla	iin			
0960/0018	Square/					
STATUS/PURPOSE	E/USE DATA					
Resource Type: Buil	ding	Sta	atus Cur	rent: Extant		
0	Historic	Qu	ality:			
Purpose: Apa	rtment	Co	ndition:	Good		
Function/Use	Start	Source	Stop	Source	Explain	
Residential (Multi-Fa	mily) c. 1970	DC Real F	r		Historic/Current	
CONSTRUCTION D	DATA					
Construction Event	Start	Source	Stop	Source	Cost Source	
Orig Construction	с. 1970	DC Real Property				
		Database				
Construction Event	Associat	ion		Associated Na	ame	
Construction Notes:						
PEOPLE/EVENTS	DATA					
Racial Segregation St	atus:					
SETTING/SHAPE/S	SIZE DATA					
Surroundings:	Urban		Cross R	eference Notes:		
Streetscape:	Intact					
Relate to Othr Bldgs:						
Relate to Street:	Face on Setback Line					
Massing:	Block					
Footprint:	Rectangular					
Number Stories:	2 plus basement					
Bays Wide:	3	0 4 3 1			0 (11 (11 0)	
Height: Width:		Outbuild	ing Type		Contributing Status	_
Depth/Length:						
SqFt:						
Volume:						
Lot Width						
Lot Depth/Length:		Outbuild	ing Note	s:		_
Lot SqFt:						
Acreage:						
Has Driveway:						

STYLE/EXTERIOR Architectural Style(s)					
Modern					
Exterior & Architectura	al Notes:				
nd is faced with five lised. A flat roof ca evation) slightly pr indow and tripartite indows. All openin e central and soutl	acted c. 1970, this two-sto e-course, American-bond ps the building and is hig ojects from the primary e e windows composed of gs have concrete sills. Do hernmost bays. A single- h) and rear (west) elevati	brick. The building ghlighted with meta elevation. The façad a central one-light ecorative concrete leaf paneled metal	g is set on a solid, con I coping. The northern le is fenestrated with p fixed metal window an blocks are located abo door with lights pierce	crete block foun- most bay of the aired one-light n d flanking one-li ove the second s s the south (side	dation and is façade (east netal sliding ght sliding metal tory windows of
Site Notes:					
approximately ten fe mature trees and shi	p-story apartment building the from the brick sidewald tubs, as well as foundations parallel to the south (signers DATA	k. The free-standing on plantings. A met	g building is sited on a al hairpin and picket m	level, grassy lo netal fence encir	t that features cles the property.
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
lat	Not Visible		Not Visible		
Vall Component	Material	Color	Treatment	Source	
acade	Brick		American Bond		
Structure Component	Material	Feature		Source	
Foundation Walls	Concrete Block Concrete Block				
Materials Notes:					
WINDOW/DOOR/IN	ITERIOR DATA				
Window Location	Aperture Shape	Type	Ligh	nts	Material
	Rectangular	Sliding	1-li		Metal
acade	Tripartite	Fixed	1-li	ght	Metal
		Sliding	1-li	ght	Metal
acade	Tripartite	Ollullig			
Facade Facade Facade Door Location	Tripartite Aperture Shape	Туре	Par	nels	Material
Facade Facade	•	J		nels neled	Material Metal/Glas

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC:

Zoning: Designation Event(s)

Contributing:

Survey(s) Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th
St\Database\Pictures\Square 0960\

File: 630_11th_Street_NE_east_elevation.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 630_11th_Street_NE_north_elevation.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 630_11th_Street_NE_northeast_corner.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 630_11th_Street_NE_west_elevation.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLA	NEOUS NOTES DAT	ГА					
Notes:							
DEDMIT DA	T.					_	
PERMIT DA	MA						
Permit Issue	Date Nur	nber Type		Remarks			
Permit Notes	:						
DIDLIGOD/	ADUIC DATA						
DIDLIUGRA	APHIC DATA						
Short Citation	1	Т	·уре	Date	Remarks		
Bibliographic	Notes:						
SIGNIFICAL	NCE DATA						
Study Unit							
Code	Criteria						
DATA PRO	CESSING EVENTS	DATA					
-			A -4'				
Date	Individual		Action				

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/8/2010	Dayton (MSD), Maria	Record Created

ID Number: 0960-0068

ID Number: 0960	-0068	Year Built	1917	Data	Source: Permit	t	
Number Extended	Street			Quad T	ype of Address		
640	11th Street				urrent		
Name(s)			Type of				
Rowhouse, 640 11th	Street, N.E.		Commo	on			
TaxCode1 TaxCode	2 TaxCode3	Туре	Explair	1			
0960/0068		Square/Lot	Curren				
		•					
STATUS/PURPOSI	E/USE DATA	i.					
Resource Type: Buil	ding		Stati	us Currer	nt: Extant		
	oric		Qua	lity:			
Purpose: Apa	rtment		Con	dition:	Good		
-							
Function/Use			Source	Stop	Source	Explain	
Residential (Multi-Fa	ımily)	1917	Permit			Historic/Current	
CONSTRUCTION I	DATA						
Construction Event	St	art So	urce	Stop	Source	Cost Source	
Orig Construction	19)17 Pe	rmit			4000 Permit	
Construction Event		Association			Associated N	ama	
Orig Construction		Architect			Lepley, Mattl		
Orig Construction		Owner			Hill, William		
					,	-	
Construction Notes:							
Constructed with 642	2 11th Street,	N.E. from the	same perm	nit (#512 ⁻	1).		
PEOPLE/EVENTS	DATA						
Racial Segregation St	atus:						
SETTING/SHAPE/S	SIZE DATA						
Surroundings:	Urban		C	ross Refe	erence Notes:		
Streetscape:	Intact]
Relate to Othr Bldgs:		ide)					
Relate to Street:	Face on Setb						
Massing:	Block						
Footprint:	T Shape P						
Noveles and Otto de au	-						
Number Stories:	2						
Bays Wide:	5		Outhuildia	a T		Contribution Status	
Height: Width:	07		Outbuildin	g rype		Contributing Status	=
	27 50						
Depth/Length: SqFt:	50						
Volume:							
Lot Width							
Lot Depth/Length:			Outbuildin	a Notes:			
Lot SqFt:			Cathanan	g 110100.			
Acreage:							
Has Driveway:							
i ias Diiveway.			1				

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

March 2010: Constructed in 1917, this two-story, five-bay Colonial Revival-style apartment building was constructed from the same permit as 642 11th Street, N.E. The building is constructed of brick and is set on a solid concrete block foundation; the façade (east elevation) is faced with five-course, American-bond brick. A brick sill course spans the façade and is located below the second story window openings. Soldier brick string courses travel the façade above the first and second story openings and are flanked by string courses of rowlock brick. A sloping roof caps the building and is highlighted by a molded wood cornice and molded architrave. The central opening of the first story holds a single-leaf paneled wood door and a one-light transom. A square-edged wood surround complements the opening, which is topped by a gauged brick jack arch with concrete keystones. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins and have concrete sills. The rear (west) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins. These openings have concrete sills and two-course, rowlock brick segmental arches.

A two-story block extends from the center bay of the rear elevation and is original. The block is constructed of brick and is faced with irregular-coursed, American-bond brick. The block is set on a solid foundation and is capped by a sloping roof. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins and single-leaf doors with one-light transoms. The first story openings are topped by three-course, rowlock brick segmental arches and the second story openings are topped by two-course, rowlock brick segmental arches. The second story openings of the rear elevation have been altered and once held fenestration similar to the first story. A two-story, full-width porch has been removed.

Site Notes:

March 2010: This two-story apartment building is located on the west side of 11th Street, N.E. and is set back approximately ten feet from the brick sidewalk. The north (side) elevation of the dwelling is adjacent to 642 11th Street, N.E. The grassy front yard is landscaped with mature shrubs and foundation plantings and is encircled by a metal milled point fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is grassy and edged by metal chain-link fencing. An alley is located west of the dwelling.

NO	IABLE	FEAI	URES	DATA

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		American Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete Block				
Walls	Brick				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
Facade	Rectangular	Dbl-Hung	1/1	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single	Paneled	Wood	
Notable Interior Plan	n(s)		Notable Interior Feature(s)		

Interior Notes:			

PLAN/	SURVEY	/DESIGNATI	ON DATA			
Neighbo	orhood:	Capitol Hill			Historic District(s)	
Subdivis	sion:	-			· ·	
/ard/A						
oning:					Designation Event(s)	
ontribu	uting:					
urvey((s)				Level(s) of Investigation	on
apitol	Hill F & C	3 Streets (2010))		Permit Research	
					Reconnaissance Sur	rvey
НОТО	OS - DIG	ITIZED				
aption	1:					
					l la dia ala	veble leve ve Fermet
					undispia	yable Image Format
Path:		s\CHRS\Docur				
		base\Pictures\				
ile:			acade_looking	_NW.JPG		
Date::		Photog:				
Code::			R:	Fr:		
Caption	1:					
					Undispla	yable Image Format
Path:		s\CHRS\Docur				
		ses\F&G Street base\Pictures\				
ile:			acade_looking	_W.JPG		
Date::		Photog:		-		
Code::		i notog.	R:	Fr:		
antion	·-					
Caption						
					Undispla	yable Image Format
Path:	C:\llser	s\CHRS\Docur	nents\CHRS		2 	,
aut.	Databas	ses\F&G Street	- 2 to 11th			
		base\Pictures\	•			
File:	640_11t		ear_looking_S	E.JPG		
Date::		Photog:	_	_		
Code::			R:	Fr:		
нот/	OS - B/M	OR NON-DIG	SITIZED			
				Data	Dhoto	Continu
Photo C	oae	Roll	Frame(s)	Date	Photographer	Caption
VISCE	LLANEC	OUS NOTES I	DATA			
Notes:						
10103.						

PERMIT DATA					
Permit Issue Date	Number	Туре	Remarks		
05/24/1917		Build			
Permit Notes:					
BIBLIOGRAPHIC I	DATA				
Short Citation		Туре	Date	Remarks	
Bibliographic Notes:					
SIGNIFICANCE DA	ATA				
Study Unit					
Code Criter	ia				
DATA PROCESSIN	NG EVENTS DAT	Α			
Date I	ndividual	Actio	on		

Record Updated

Record Created

3/8/2010

3/8/2010

Dayton (MSD), Maria

Dayton (MSD), Maria

ID Number: 0960-0067

ID Number: 0960	-0067 Year Bu	ilt: 1917	Dat	a Source: Permit		
Number Extended	Street		Quad	Type of Address		
642	11th Street		NE	Current		
Name(s)		Type	of Name			
Apartment Building,	642 11th Street, N.E.	Comr				
TaxCode1 TaxCode 0960/0067	2 TaxCode3 Type Square/Lo	Expla ot Curre				
STATUS/PURPOS	E/USE DATA					
Resource Type: Buil	ding	Sta	atus Cur	rent: Extant		
Desig. Status: Hist	oric	Qι	ıality:			
Purpose: Apa	rtment	Co	ndition:	Good		
Function/Use	Start	Source	Stop	Source	Explain	
Residential (Multi-Fa		Permit			Historic/Current	
·						
CONSTRUCTION I	DATA					
Construction Event	Start S	Source	Stop	Source	Cost Source	
Orig Construction	1917 F	ermit			4000 Permit	
Construction Event	Associatio	n		Associated Na	me	
Orig Construction	Builder			Lepley, Matthe	ew G.	
Orig Construction	Owner			Hill, William A		
Construction Notes:						
	0 11th Street, N.E. from t	he same per	mit (#51	121).		
PEOPLE/EVENTS						
Racial Segregation St	atus:					
SETTING/SHAPE/S	SIZE DATA					
Surroundings:	Urban		Cross R	eference Notes:		
Streetscape:	Intact					1
Relate to Othr Bldgs:						
Relate to Street:	Face on Setback Line					
Massing:	Block					
Footprint:	T Shape P					
Number Stories:	2					
Bays Wide:	5	Ŀ				_
Height:		Outbuild	ing Type	e C	Contributing Status	_
Width:	27					
Depth/Length:	50					
SqFt:						
Volume:						
Lot Width		الدائد ماند ماند	ina Nat-	0.		
Lot Depth/Length: Lot SqFt:		Outbuild	ing ivote	ა.		7
Acreage:						
Has Driveway:						
Dirionay.						_

March 2010: Constructed in 1917, this two-story, five-bay Colonial Revival-style apartment building was constructed for the same permit as 640 11th Street, N.E. The building is constructed of brick and is set on a solid concrete block foundation; the façade least elevation) is faced with five-course, American-bond brick. A brick sill course spans the façade and is located below the second story window openings. Soldier brick string courses travel the façade above the façade and is located below the second story window openings. Soldier brick string courses travel the façade above the façade and is located below the second story window openings. Soldier brick string courses travel the façade above the façade and story openings and are flanked by string courses of rowlock brick. A sloping roof caps the building a singlified by a molded wood cornice and molded architrave. The central opening of the first story holds a single-lewood-frame door with leaded glass a one-light transom. A canopy shelters the primary entrance. All window openings the façade hold 1/1, double-hung, wood-sash windows and have concrete sills. The rear (west) elevation is fenestrated with 1/1, double-hung, winyl-sash windows. These openings have concrete sills and two-course, rowlock brick segment arches. A two-story block extends from the center bay of the rear elevation and is original. The block is constructed of brick at its faced with irregular-coursed, American-bond brick. The block is set on a solid foundation and is capped by a slopin toof. An interior-side brick chimney rises from the south (side) elevation of the dwelling and has a parged cap. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and single-leaf paneled wood doors with one-light transoms. The second story openings are topped by two-course, rowlock brick segmental arches. A two-story, full-wice porch projects from the rear elevation and is set on a square wood pier foundation. Each story is encircled by square wood balusters and is accessed by wood s	, , ,				
is faced with irregular-coursed, American-bond brick. The block is set on a solid foundation and is capped by a slopin roof. An interior-side brick chimney rises from the south (side) elevation of the dwelling and has a parged cap. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and single-leaf paneled wood doors with one-light transoms. The second story openings are topped by two-course, rowlock brick segmental arches. A two-story, full-wice porch projects from the rear elevation and is set on a square wood pier foundation. Each story is encircled by square wood balusters and is accessed by wood steps. Site Notes: March 2010: This two-story apartment building is located on the west side of 11th Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 640 and 644 11th Street, N.E. The grassy frogrard is landscaped with mature shrubs and is encircled by a metal milled point metal fence. The rear yard is paved wit concrete and serves as a parking area. An alley is located west of the dwelling. NOTABLE FEATURES DATA Component Feature EXTERIOR MATERIALS DATA Roof Component Material Color Treatment Source Not Visible Wall Component Material Color Treatment Source				<u> </u>	
the same permit as 640 11th Street, N.E. The building is constructed of brick and is set on a solid concrete block foundation; the façade (east elevation) is faced with five-course, American-bond brick. A brick sill course spans the façade and is located below the second story window openings. Soldier brick string courses travel the façade above tirist and second story openings and are flanked by string courses of rowlock brick. A sloping roof caps the building a is highlighted by a molded wood cornice and molded architrave. The central opening of the first story holds a single-lewood-frame door with leaded glass a one-light transom. A canopy shelters the primary entrance. All window openings the façade hold 1/1, double-hung, wood-sash windows and have concrete sills. The rear (west) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows. These openings have concrete sills and two-course, rowlock brick segment arches. A two-story block extends from the center bay of the rear elevation and is original. The block is constructed of brick at is faced with irregular-coursed, American-bond brick. The block is set on a solid foundation and is capped by a slopin roof. An interior-side brick chimney rises from the south (side) elevation of the dwelling and has a parged cap. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and single-leaf paneled wood doors with one-light transoms. The second story openings are topped by two-course, rowlock brick segmental arches. A two-story, full-wic porch projects from the rear elevation and is set on a square wood pier foundation. Each story is encircled by square wood balusters and is accessed by wood steps. Site Notes: March 2010: This two-story apartment building is located on the west side of 11th Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 640 and 644 11th Street, N.E. The grassy froy yard is landscaped with mature shrubs and is encircled by a metal milled point metal fence. The rear	exterior & Architectural	Notes:			
March 2010: This two-story apartment building is located on the west side of 11th Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 640 and 644 11th Street, N.E. The grassy frozen yard is landscaped with mature shrubs and is encircled by a metal milled point metal fence. The rear yard is paved with concrete and serves as a parking area. An alley is located west of the dwelling. NOTABLE FEATURES DATA EXTERIOR MATERIALS DATA Roof Component Material Color Treatment Source Sloped Not Visible Not Visible Wall Component Material Color Treatment Source	he same permit as 640 oundation; the façade açade and is located to irst and second story is highlighted by a mole wood-frame door with the façade hold 1/1, do with 1/1, double-hung,	11th Street, N.E. The based elevation) is face below the second story openings and are flank ded wood cornice and leaded glass a one-ligh uble-hung, wood-sash	building is constructed with five-course, window openings. ed by string course molded architrave. It transom. A canop windows and have	ted of brick and is set of American-bond brick. A Soldier brick string cou is of rowlock brick. A sl The central opening of by shelters the primary of concrete sills. The real	on a solid concrete block A brick sill course spans the urses travel the façade above the loping roof caps the building and the first story holds a single-leaf entrance. All window openings or r (west) elevation is fenestrated
EXTERIOR MATERIALS DATA Roof Component Material Color Treatment Source Sloped Not Visible Not Visible Wall Component Material Color Treatment Source	s faced with irregular- oof. An interior-side b enestration consists c ransoms. The second orch projects from th	coursed, American-bon rick chimney rises from of 1/1, double-hung, vin story openings are top e rear elevation and is	d brick. The block n the south (side) el yl-sash windows ar ped by two-course, set on a square wo	is set on a solid founda levation of the dwelling nd single-leaf paneled v rowlock brick segmen	ation and is capped by a sloping and has a parged cap. Visible wood doors with one-light tal arches. A two-story, full-width
March 2010: This two-story apartment building is located on the west side of 11th Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 640 and 644 11th Street, N.E. The grassy frozen yard is landscaped with mature shrubs and is encircled by a metal milled point metal fence. The rear yard is paved wit concrete and serves as a parking area. An alley is located west of the dwelling. NOTABLE FEATURES DATA Component Feature EXTERIOR MATERIALS DATA Roof Component Material Color Treatment Source Sloped Not Visible Not Visible Wall Component Material Color Treatment Source	Site Notes:				
EXTERIOR MATERIALS DATA Roof Component Material Color Treatment Source Sloped Not Visible Not Visible Wall Component Material Color Treatment Source		from the brick sidewall	k. The dwelling is a	diacent to 640 and 644	11th Street. N.E. The grassy front
EXTERIOR MATERIALS DATA Roof Component Material Color Treatment Source Sloped Not Visible Not Visible Wall Component Material Color Treatment Source	ard is landscaped wit concrete and serves as	h mature shrubs and is s a parking area. An alle	encircled by a met	al milled point metal fe	
Sloped Not Visible Not Visible Wall Component Material Color Treatment Source	ard is landscaped wit concrete and serves as	h mature shrubs and is s a parking area. An alle	encircled by a met	al milled point metal fe	
Wall Component Material Color Treatment Source	ard is landscaped with concrete and serves as NOTABLE FEATURE Component	h mature shrubs and is a parking area. An alles S DATA Feature	encircled by a met ey is located west o	al milled point metal fe f the dwelling.	nce. The rear yard is paved with
	ard is landscaped with concrete and serves as NOTABLE FEATURE Component EXTERIOR MATERIA Roof Component	h mature shrubs and is a parking area. An alles is a parking area. An alles is DATA Feature ALS DATA Material	encircled by a met ey is located west o	al milled point metal fer f the dwelling.	nce. The rear yard is paved with
Facade Brick American Bond	ard is landscaped with concrete and serves as NOTABLE FEATURE Component EXTERIOR MATERIA Roof Component	h mature shrubs and is a parking area. An alles is a parking area. An alles is DATA Feature ALS DATA Material	encircled by a met ey is located west o	al milled point metal fer f the dwelling.	nce. The rear yard is paved with
	NOTABLE FEATURE Component EXTERIOR MATERIA Roof Component	h mature shrubs and is a parking area. An alles is a parking area. An alles is DATA Feature ALS DATA Material Not Visible Material	encircled by a met ey is located west o	al milled point metal fer f the dwelling. Treatment Not Visible Treatment	Source
Structure Component Material Feature Source	ATTERIOR MATERIA Roof Component Sloped Vall Component	h mature shrubs and is a parking area. An alles is a parking area. An alles is DATA Feature ALS DATA Material Not Visible Material	encircled by a met ey is located west o	al milled point metal fer f the dwelling. Treatment Not Visible Treatment	Source
Foundation Concrete Block	ATTERIOR MATERIA Roof Component Sloped Vall Component Facade	h mature shrubs and is a parking area. An alles is a parki	cencircled by a meter is located west of the color color	al milled point metal fer f the dwelling. Treatment Not Visible Treatment	Source Source
Walls Brick	AND COMPONENT EXTERIOR MATERIA Roof Component Vall Component Facade Structure Component	h mature shrubs and is a parking area. An alles area. An	cencircled by a meter is located west of the color color	al milled point metal fer f the dwelling. Treatment Not Visible Treatment	Source Source

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
Facade	Rectangular	Dbl-Hung	1/1	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single	Full Glass	Wood/Glass	
Notable Interior Plan(s) Notable Interior Feature(s)					

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighbo Subdivis Ward/Al Zoning: Contribu	sion: NC:	Capitol Hill				Historic District(s) Designation Event(s))
Survey(s)					Level(s) of Investigat	tion
Capitol	Hill F & G	Streets (2010)			Permit Research	
						Reconnaissance Su	ırvey
РНОТО	OS - DIGI	TIZED					
Caption	:						
Dath	0.111.	NOUROLD				Undispla	ayable Image Format
Path:	Database	\CHRS\Docun es\F&G Street ase\Pictures\\$	- 2 to 11th				
File:		Street_NE_fac	-				
Date::		Photog:					
Code::			R:	Fr:			
Path: File: Date:: Code:: Caption	Database St\Datab 642_11th	\CHRS\Docun es\F&G Street ase\Pictures\\$ n_Street_NE_f Photog:	- 2 to 11th Square 0960\		G	Undispla	ayable Image Format
Path:		\CHRS\Docun	nents\CHRS			Undispla	ayable Image Format
		es\F&G Street ase\Pictures\\$					
File:		_Street_NE_r	•	E.JPG			
Date::		Photog:					
Code::			R:	Fr:			
РНОТО	OS - B/W	OR NON-DIO	SITIZED				
Photo C	ode	Roll	Frame(s)		ate	Photographer	Caption
		US NOTES [

PERMIT DATA							
Permit Issue Date	Number	Туре		Remarks			
05/24/1917	5121	Build					
Permit Notes:							\neg
BIBLIOGRAPHIC DATA							
Short Citation			Туре	Date	Remarks		_
Bibliographic Notes:							
SIGNIFICANCE DATA							
Study Unit							
Code Criteria						-	
DATA PROCESSING EVEN	ITS DAT	A					
Date Individual			Action				

Record Updated

Record Created

3/8/2010

3/8/2010

Dayton (MSD), Maria

Dayton (MSD), Maria

ID Number: 0960-0056

ID Number: 0960	-0056 Ye	ar Built: 18	3 98 Da	ta Source: Per	rmit	
Number Extended	Street		Qua	d Type of Address		
644	11th Street		NE	Current		
Name(s)			Type of Name	;		
Single Dwelling, 644	11th Street, N.E.		Common		<u>—</u>	
TaxCode1 TaxCode	2 TaxCode3 Type		Explain			
0960/0056	71	re/Lot	Current		_	
	•					
STATUS/PURPOS	E/USE DATA					
Resource Type: Buil	lding		Status Cur	rent: Extant		
Desig. Status: Hist	toric		Quality:			
Purpose: Res	idential		Condition:	Good		
Function/Use	Start	Sour	ce Stop	Sourc	e Explain	
Residential (Single-F	amily) 1898	Perr			Historic/Current	_
CONSTRUCTION I	DATA					
Construction Event	Start	Source	Stop	Source	Cost Source	
Orig Construction	1898	Permit			1400 Permit	
Construction Event	Asso	ciation		Associate	d Name	
Orig Construction	Build	er		Carr, S.		_
Orig Construction	Owne	er		Widman,	J.C.	
Construction Notes:						
Constructed with 64	6 11th Street, N.E. fr	om the sam	ne permit (#1	110).		
DEODI E/EVENTS	DATA					
PEOPLE/EVENTS						
Racial Segregation St	atus:					
CETTING/CHADE/	DIZE DATA					
SETTING/SHAPE/S	SIZE DATA					
Surroundings:	Urban		Cross R	eference Notes:		
Streetscape:	Intact					
Relate to Othr Bldgs: Relate to Street:	Attached Face on Setback Li	ne				
Massing:	Vertical Box/flat fro					
Footprint:	L-Shaped					
	-					
Number Stories:	2					
Bays Wide:	2	0	Ala: I al i as as Tours	_	Contribution Ctatus	
Height: Width:	40	00	tbuilding Type	•	Contributing Status	
	16					
Depth/Length: SqFt:	32					
Volume:						
Lot Width						
Lot Depth/Length:		Ou	tbuilding Note	es:		
Lot SqFt:				-		
Acreage:						
Has Driveway:						

STYLE/EXTERIOR DATA		
Architectural Style(s)		
Italianate		

March 2010: Constructed in 1898 by S. Carr, this two-story, two-bay Italianate-style single-family dwelling was constructed from the same permit (#1110) as 646 11th Street, N.E. The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (east elevation) is faced with pressed stretcher-bond brick. Brick sill courses span the façade beneath the first and second story window openings and a third string course is located above the second story openings. A sloping roof caps the dwelling and is highlighted by a molded metal cornice and a corbeled brick cornice. The northernmost bay of the façade holds a single-leaf paneled wood door and a one-light transom. A concrete lintel surmounts the transom. The façade is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows. All window openings have concrete sills and lintels. The rear (west) elevation is fenestrated with 1/1, double-hung, vinylsash windows, which have two-course, rowlock brick segmental arches and concrete sills.

A two-story ell extends from the northernmost bay of the rear elevation and is original to the dwelling. The ell is constructed of five-course, American-bond brick and is set on a solid foundation. A sloping roof caps the ell. An interiorside brick chimney rises from the south (side) elevation of the dwelling and has a parged cap. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf paneled door with lights and a blind transom. All openings are surmounted by two-course, rowlock brick segmental arches. The windows have concrete sills.

Site Notes:

March 2010: This two-story dwelling is located on the west side of 11th Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 642 and 646 11th Street, N.E. The front yard is landscaped with mature shrubs and is bounded by a metal bow and picket fence. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is grassy and features mature trees. Wood fencing edges the property. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Exterior & Architectural Notes:

|--|

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Pressed Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			
Materials Notes:				

WINDOW/DOOR/INTERIOR DATA

Notable Interior Plan	n(s)		Notable Interior Feature(s)		
Main Door	Rectangular	Single	Paneled	Wood	
Door Location	Aperture Shape	Туре	Pamels	Material	
Facade	Rectangular	Dbl-Hung	1/1 Double	Vinyl	
Facade	Rectangular	Dbl-Hung	1/1	Vinyl	
Window Location	Aperture Shape	Туре	Lights	Material	

Notable Interior Plan(s)	Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Subdivision: Ward/ANC: Zoning: Contributing: Survey(s)				Historic District(s) Designation Event(s) Level(s) of Investigation			
	Hill F & G Streets (2010	١		Permit Research	шоп		
Capitol	Tim T & O Officers (2010	,		Reconnaissance S	urvey		
PHOTO	OS - DIGITIZED						
Caption	e.			Undispla	ayable Image	Format	
Path: File: Date::	C:\Users\CHRS\Docum Databases\F&G Street St\Database\Pictures\S 644_11th_Street_NE_fa	- 2 to 11th Equare 0960\ acade_lookin	-	·	, 3		
Code:: Caption		R:	Fr:				
Path: File: Date:: Code::	C:\Users\CHRS\Docum Databases\F&G Street St\Database\Pictures\S 644_11th_Street_NE_fa	- 2 to 11th Square 0960\	g_ W.JPG Fr:	Undispla	ayable Image	Format	
Caption Path:	C:\Users\CHRS\Docum Databases\F&G Street St\Database\Pictures\S	- 2 to 11th Square 0960\		Undispla	ayable Image	Format	
File:	644_11th_Street_NE_r	ear_looking_	E.JPG				
Date:: Code::	Photog:	R:	Fr:				
PHOTO	OS - B/W OR NON-DIG	HTIZED					
Photo C		Frame(s)	Date	Photographer	Caption		
	ELLANEOUS NOTES D	· · · · · ·	23.0				
Notes:							
PERM	IT DATA						

Tuesday, June 25, 2013

ID_Number: 0960-0056 Page 3

Permit Issue	e Date	Number	Туре		Remarks			
02/09/1898			Build					-
Permit Note	s:							
BIBLIOGR	APHIC DATA							
Short Citation	on			Туре	Date	Remarks		_
Bibliographi								
Study Unit	ANCE DATA							
Code	Criteria						-	
DATA PRO	OCESSING EVE	NTS DAT	Ά					
Date	Individual			Action				
3/8/2010		MSD), Mar			Updated			
3/8/2010	Dayton (I	MSD), Mar	ia	Record	Created			

ID Number: 0960-0055

BASICS DATA

ID Number: 0960-0055 Year Built: 1898 Data Source: Permit

Number Extended Street Quad Type of Address

646 11th Street NE Current

Name(s) Type of Name

Single Dwelling, 646 11th Street, N.E. Common

 TaxCode1
 TaxCode2
 TaxCode3
 Type
 Explain

 0960/0055
 Square/Lot
 Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Residential Condition: Good

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1898 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Garage c. 1970 Site

Visit/Map

Orig Construction 1898 Permit 1400 Permit

 Construction Event
 Association
 Associated Name

 Orig Construction
 Builder
 Carr, S.

Orig Construction Owner Widman, J.C.

Construction Notes:

Constructed with 644 11th Street, N.E. from the same permit (#1110).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: Streetscape:	Urban Intact	Cross Ref	erence Notes:]
Relate to Othr Bldgs:	Attached				
Relate to Street:	Face on Setback Line Vertical Box/flat front				
Massing: Footprint:	L-Shaped				
Number Stories:	2				
Bays Wide:	2				i
Height:		Outbuilding Type	Contr	ibuting Status	
Width:	16	Garage			
Depth/Length:	32				
SqFt: Volume:					
Lot Width					
Lot Depth/Length:		Outbuilding Notes:			
Lot SqFt:			structed c. 1970, this or		
Acreage:			west of the dwelling ar The wood-frame garage		
Has Driveway:		vinyl siding and is	s set on a solid foundar	tion. A sloping roof	
			nd is covered with cor ation) is pierced by a ro		
		door.		,	
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Italianate					
Exterior & Architectura	al Notes: ucted in 1898 by S. Carr, thi	- 44 4 h-		familia dansilia a assa	
solid concrete found the façade beneath t story openings. A sle cornice. The norther lintel surmounts the	e same permit (#1110) as 64 lation; the façade (east elew he first and second story w oping roof caps the dwellin nmost bay of the façade ho transom. The façade is fen ave concrete sills and stone	ration) is faced with rindow openings ar g and is highlighte Ids a single-leaf pa estrated with single	pressed stretcher-bor ad a third string course d by a molded metal co neled metal door and a	nd brick. Brick sill cours is located above the se prnice and a corbeled br a one-light transom. A st	es span cond ick cone
constructed of five-o	ds from the northernmost l course, American-bond bric y rises from the south (side dows. All openings are sur	k and is set on a so) elevation of the d	olid foundation. A slopi welling. Visible fenestr	ng roof caps the ell. An ation consists of 1/1, do	uble-
Site Notes:					
feet from the brick s landscaped with fou	o-story rowhouse is located idewalk. The dwelling is ad ndation plantings and is bothe dwelling and ends at the	jacent to 644 and 6 ounded along the si	48 11th Street, N.E. The dewalk by a brick curb	e grassy front yard is . A brick walkway leads	from the
NOTABLE FEATU	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	_
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Pressed Brick		Stretcher Bond		_
Structure Component	Material	Feature		Source	

Foundation

Concrete

Walls Brick

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Type Window Location Aperture Shape Lights Material 1/1 Vinyl Facade Rectangular **Dbl-Hung Facade** Rectangular **Dbl-Hung** 1/1 Double Vinyl **Door Location** Aperture Shape Pamels Material Type Main Door Rectangular Single **Paneled** Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Zoning: Designation Event(s)

Survey(s) Level(s) of Investigation

Capitol Hill F & G Streets (2010) Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 646_11th_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 646_11th_Street_NE_facade_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path:

C:\Users\CHRS\Documents\CHRS

Undisplayable Image Format

		es\F&G Street ase\Pictures\	t - 2 to 11th Square 0960\						
File:	646_11th	_Street_NE_	garage_looking	_NE.JPG					
Date:: Code::		Photog:	R:	Fr:					
Caption	:								
Path:	Database	\CHRS\Docur	t - 2 to 11th		Und	displaya	able Image	e Format	
File:			Square 0960\ rear_looking_N	IE IBG					
Date::	040_1111	Photog:	rear_looking_iv	L.31 G					
Code::		Filolog.	R:	Fr:					
РНОТО	OS - B/W	OR NON-DI	GITIZED						
Photo C	Code	Roll	Frame(s)	Date	Photograp	her	Caption		
MISCE	LLANEO	US NOTES I	DATA						
Notes:									
PERMI	IT DATA								
Permit I	ssue Date		Number Type		Remarks				
02/09/1			1110 Build						-
Permit I	Notes:								
BIBLIC	OGRAPHI	C DATA							
Short C	itation			Туре	Date	Remarks			-
Bibliogr	aphic Note	e.							
	артно т тото	<u>. </u>							
SIGNIF	FICANCE	DATA							
Study U									
Code	Cr	iteria					_		

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/8/2010	Dayton (MSD), Maria	Record Created

ID Number: 0960-0054

ID Number: 0960	-0054 Ye	ar Built: 1910	Data	Source: Permit		
Number Extended	Street		Quad T	ype of Address		
648 -648A	11th Street		NE C	urrent		
Name(s)		Туре	of Name			
Multiple Dwelling, 64	18-648A 11th Street,	N.E. Com	mon			
TaxCode1 TaxCode	2 TaxCode3 Type	Expl	ain			
0960/0054		re/Lot Curi				
STATUS/PURPOS	E/USE DATA					
Resource Type: Buil	_		tatus Currer	nt: Extant		
Desig. Status: Hist			uality:	Oned		
Purpose: Res	idential	C	ondition:	Good		
Function/Use	Start	Source	Stop	Source	Explain	
Residential (Multi-Fa	mily) 1910	Permit			Historic/Current	
OONOTP!!OT!O!	NATA					
CONSTRUCTION I			Cton	0	Coat Course	
Orig Construction	Start 1910	Source Permit	Stop	Source	Cost Source 3500 Permit	
_						
Construction Event Ketcham & Carmody		ciation		Associated Na Ketcham & C		
Orig Construction	Arch			McNamara, T	•	
Orig Construction	Own			Thour, A.C.	nomus E.	
Construction Notes:				·		
Construction Notes.						
PEOPLE/EVENTS	DATA					
Racial Segregation St	atus:					
SETTING/SHAPE/S	SIZE DATA					
Surroundings:	Urban		Cross Refe	erence Notes:		
Streetscape:	Intact					
Relate to Othr Bldgs:	Attached					
Relate to Street:	Face on Setback Li					
Massing:	Vertical Box/Cante	d Bay				
Footprint:	L-Shaped					
Number Stories:	2 plus baseme	ent				
Bays Wide:	3					
Height:		Outbuild	ding Type	(Contributing Status	<u> </u>
Width:	22					
Depth/Length: SqFt:	27					
Volume:						
Lot Width						
Lot Depth/Length:		Outbuild	ding Notes:			
Lot SqFt:						
Acreage:						
Has Driveway:						

					ΓΔ

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

March 2010: Constructed in 1910 by Ketcham & Carmody, this two-story, three-bay Classical Revival-style multiple dwelling was constructed from permit #6589. The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (east elevation) is faced with stretcher-bond brick. Brick sill courses span the façade and are located beneath the first and second story window openings. A sloping roof caps the dwelling and is fronted along the façade by a molded cornice. A molded architrave is located above the second story openings. The end bays of the façade hold single-leaf paneled wood doors with transoms. The southernmost transom is composed of stained glass. The second story openings hold 1/1, double-hung, vinyl-sash windows. A three-sided, canted bay extends from the central bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is fenestrated with 1/1, double-hung, vinyl-sash windows and one-light fixed vinyl windows. The foundation is pierced by paired 1/1, double-hung, vinyl-sash windows. All windows on the façade have concrete sills and lintels.

A two-story ell extends from the northernmost bay of the rear (west) elevation and is original. The ell is constructed of brick and is set on a solid foundation. A sloping roof caps the ell. Visible fenestration consists of 1/1, double-hung, vinylsash windows and single-leaf wood-frame glass doors with one-light transoms. A two-story porch projects from the rear elevation of the ell and is wood-frame construction. The roof is supported by square wood posts.

Site Notes:

March 2010: This two-story multiple dwelling is located on the west side of 11th Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 646 and 652 11th Street, N.E. The grassy front yard is landscaped with mature shrubs. Twin concrete walkways lead from the end bays of the dwelling and terminate at the sidewalk. The rear yard is enclosed with metal chain-link fencing.

NOTABLE FEATURES DATA

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Stretcher Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				
Materials Notes:					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material	
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Dbl-Hung	1/1	Vinyl	
Bay Windows	Rectangular	Fixed	1-light	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single	Paneled	Wood	
Main Door	Rectangular	Single	Paneled	Wood	
Notable Interior Plan	u(s)		Notable Interior Feature(s)		

Interior Notes:			

Tuesday, June 25, 2013 ID_Number: 0960-0054 Page 2

PLAN/	SURVE	//DESIGNATION	ON DATA			
Neighbo Subdivis	sion:	Capitol Hill			Historic District(s)	
Ward/Al Zoning:	NC:				Designation Event(s)	
Contribu	uting:				Designation Event(s)	
Survey	۵)				Lovel(a) of Investigation	on
Survey(G Streets (2010	<u> </u>		Level(s) of Investigation	on
Capitoi	α ν	5 0110013 (2010	''		Reconnaissance Sur	rvey
РНОТО	OS - DIG	ITIZED				
Caption						
Caption	•					
					Undienla	yable Image Format
Dath	0.111	-\OUDO\D			Ulluispia	yable illiage i orillat
Path:		s\CHRS\Docun ses\F&G Street				
File.		base\Pictures\	-	OW IDO		
File: Date::	648_111		facade_looking_	SW.JPG		
Code::		Photog:	R:	Fr:		
Caption						
					Undianla	vahla Imaga Farmat
					Undispia	yable Image Format
Path:		s\CHRS\Docun ses\F&G Street				
	St\Data	base\Pictures\	Square 0960\			
File:	648_111		facade_looking_	_W.JPG		
Date:: Code::		Photog:	R:	Fr:		
				11.		
Caption	•					
					Undispla	yable Image Format
Path:		s\CHRS\Docun				
		base\Pictures\				
File:	648_111	h_Street_NE_r	rear_looking_NE	.JPG		
Date::		Photog:				
Code::			R:	Fr:		
РНОТО	DS - B/W	OR NON-DIG	GITIZED			
Photo C	ode	Roll	Frame(s)	Date	Photographer	Caption
MISCE	LLANE	OUS NOTES I	DATA			
Notes:						
. 10100.						

Tuesday, June 25, 2013 ID_Number: 0960-0054 Page 3

Permit Issue Date Number Type Remarks 05/23/1910 6589 Build Permit Notes: BIBLIOGRAPHIC DATA Short Citation Type Date Remarks Bibliographic Notes: SIGNIFICANCE DATA

DATA PROCESSING EVENTS DATA

Criteria

Study Unit

Code

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/8/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0054 Page 4

ID Number: 0960-0061

BASICS DATA

ID Number: 0960)-0061 Ye	ar Built: 1908	Dat	a Source: Permi	t	
Number Extended	Street		Quad	Type of Address		
652	11th Street		NE	Current		
Name(s)		Тур	e of Name			
Single Dwelling, 652	11th Street, N.E.	Co	mmon			
TaxCode1 TaxCode	2 TaxCode3 Type	Ex	plain			
0960/0061	Squa	re/Lot Cu	irrent			
STATUS/PURPOS	E/USE DATA					
Resource Type: Buil	_			rent: Extant		
•	toric		Quality:			
Purpose: Res	idential		Condition:	Good		
Function/Use	Start	Source	Stop	Source	Explain	
Residential (Single-F	Family) 1908	Permit			Historic/Current	
CONSTRUCTION I	DATA					
Construction Event	Start	Source	Stop	Source	Cost Source	
Orig Construction	1908	Permit			6250 Permit	
Construction Event	Asso	ciation		Associated N		
Orig Construction	Arch			Schneider, F		
Orig Construction	Build Own			Howenstein,		
Orig Construction	Own	21		Howenstein,	, п.к.	
Construction Notes:	0441.04 4.115.6					
Constructed with 65	8 11th Street, N.E. fr	om the same	permit (#38	383).		
PEOPLE/EVENTS	DATA					
Racial Segregation St	tatus:					
radiai eegregalion ee						
SETTING/SHAPE/S	SIZE DATA					
Surroundings:	Urban		Cross Re	eference Notes:		
Streetscape:	Intact					7
Relate to Othr Bldgs:						
Relate to Street:	Face on Setback Li					
Massing: Footprint:	Vertical Box/front p Rectangular	orcn				
Number Stories:	2 plus baseme	nt				
Bays Wide: Height:	3	Outhu	ilding Type		Contributing Status	
Width:			manig Typo		Ochanisating States	_
Depth/Length:						
SqFt:						
Volume:						
Lot Width		O. 41-	ildina Nete	٥.		
Lot Depth/Length: Lot SqFt:		Outbu	ilding Note	S .		٦
Acreage:						
Has Driveway:						

Classical Revival							
dwelling was constructions, American-bound brick. A slopin molded architrave such imney rises from the foundation. The flanked by sidelights highlights the transvinyl muntins and heavy of the façade and overhanging eaves.	al Notes: ucted in 1908 by H.R. Heructed from the same perion on the same perion of caps the dwelling pans the façade and is the north (side) elevation southernmost opening and topped by a semi-om. All window opening ave concrete sills and list is set on a brick pier and dentil molding capsessed via poured concrete.	ermit (#3883) as 658 11 a solid concrete founc g and is fronted along located above the secon and has a corbeled of the façade holds a elliptical spiderweb fags on the façade hold intels. A one-story, one foundation that has best the porch and is sup	th Street, N.E. The dation; the façade (of the façade by a moond story window of brick cap. A single-single-leaf paneled anlight. A two-cours 1/1, double-hung, vie-bay porch shelter pen infilled with wo ported by brick pos	dwelling is construent of the	ucted of five- aced with Flemish- modillions. A or-side brick with lights pierces oor entry is emi-elliptical arch with false 6/6 unce and central of with		
Site Notes:							
feet from the brick s	ro-story dwelling is loca sidewalk. The south (sid mature shrubs and is bo	e) elevation of the dwe	elling is adjacent to				
NOTABLE FEATU	RES DATA						
Component	Featu	re					
EXTERIOR MATER	RIALS DATA Material	Color	Treatment	Source			
Sloped	Not Visible		Not Visible				
Wall Component	Material	Color	Treatment	Source			
Facade	Brick		Flemish Bond				
Structure Component	Material	Feature		Source			
Foundation	Concrete						
Walls	Brick						
Materials Notes:							
WINDOW/DOOR/II	NTERIOR DATA						
Window Location	Aperture Shape	Туре	L	ights	Material		
Facade	Rectangular	Dbl-Hung	1	/1	Vinyl		
Door Location	Aperture Shape	Туре	F	Pamels	Material		
Basement Main Door	Rectangular Rectangular	Single Single		Paneled Paneled	Unknown w/Lights Wood		
Notable Interior Plan(s) Notable Interior Feature(s)							
Interior Notes:							
PLAN/SURVEY/DE	ESIGNATION DATA						
Neighborhood: Ca Subdivision:	apitol Hill		Historic District(s)			

STYLE/EXTERIOR DATA

Architectural Style(s)

Tuesday, June 25, 2013 ID_Number: 0960-0061 Page 2

wara/A	ANC:							
Zoning:	:			Designation Event(s)				
Contrib	Contributing:							
Survey(s)			Level(s) of Investigation					
Capitol	l Hill F & G Streets (2	2010)		Permit Resea Reconnaissa				
РНОТ	OS - DIGITIZED							
Caption	n:							
Path:	C:\Users\CHRS\Do	treet - 2 to 11th		Undi	splayable Image Fo	rmat		
File:	St\Database\Pictu 652_11th_STreet_ G	-						
Date::	Photo							
Code:: Caption		R:	Fr:					
Path: File: Date:: Code::	C:\Users\CHRS\Do Databases\F&G St St\Database\Pictu 652_11th_Street_N	treet - 2 to 11th res\Square 0960\ NE_facade_looki		Undi	splayable Image Fo	rmat		
РНОТ	OS - B/W OR NON	-DIGITIZED						
Photo C		Frame(s)	Date	Photographe	r Caption			
MISCE	ELLANEOUS NOTI	ES DATA						
Notes:								
PERM	IT DATA							
Permit 06/08/1	Issue Date	Number Type		Remarks				
Permit I	Notes:							
BIBLIC	OGRAPHIC DATA							
Short C	Citation		Туре	Date I	Remarks			

Tuesday, June 25, 2013 ID_Number: 0960-0061 Page 3

Bibliograph	nic Notes:				
SIGNIFIC	ANCE DATA				
Study Unit					
					
Code	Criteria				

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/8/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0061 Page 4

ID Number: 0960-0060

BASICS DATA

ID Number: 0960)-0060	Year Built	1908	Data	Source: F	ermit		
Number Extended	Street			Quad T	ype of Addres	ss		
658	11th Street			NE C	urrent			
Name(s)			Туре	of Name				
Single Dwelling, 658	3 11th Street, N	N.E.	Comr	non				
TaxCode1 TaxCode	2 TaxCode3	Type	Expla	ain				
0960/0060		Square/Lot	Curr	ent				
STATUS/PURPOS		<u> </u>						
Resource Type: Bui	_			atus Currer	nt: Extant			
3	toric sidential			uality: ondition:	Good			
raipooo. Res	nacitiai		00	manion.	0 000			
Function/Use		Start	Source	Stop	Sou	rce	Explain	
Residential (Single-I	Family)	1908	Permit				Historic/Current	
CONSTRUCTION	ΠΔΤΔ							
Construction Event		tart Soi	urce	Stop	Source		Cost Source	
Orig Construction			rmit				6250 Permit	
Construction Event		Association			Associa	ted Nar	me	
Orig Construction		Architect			Schnei			
Orig Construction		Builder			Howens	stein, H	I.R.	
Orig Construction		Owner			Howens	stein, H	I.R.	
Construction Notes:								
Constructed with 65	2 11th Street,	N.E. from the	same pe	rmit (#388	3).			
DEODI E/EVENTO	DATA							
PEOPLE/EVENTS								
Racial Segregation S	tatus:							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban			Cross Refe	erence Notes:			
Streetscape:	Intact]
Relate to Othr Bldgs:								
Relate to Street:	Face on Seth							
Massing:	Vertical Box/	front porch						
Footprint:	Rectangular							
Number Stories:	-	asement						
Bays Wide:	5		O. 41:1 al	:		0	antilla dia a Ctatua	
Height: Width:			Outbuild	ing Type			ontributing Status	_
Depth/Length:								
SqFt:								
Volume:								
Lot Width								
Lot Depth/Length:			Outbuild	ing Notes:				٦
Lot SqFt:								
Acreage:								
Has Driveway:								

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

March 2010: Constructed in 1908 by H.R. Howenstein, this two-story, five-bay Classical Revival-style single-family dwelling was constructed from the same permit (#3883) as 652 11th Street, N.E. The dwelling is constructed of five-course, American-bond brick and is set on a solid concrete foundation; the façade (east elevation) and north (side) elevations are faced with Flemish-bond brick. A sloping roof caps the dwelling and is fronted along the façade and north elevation by a brick parapet with a molded cornice and modillions. A molded architrave spans the façade and north elevation and is located above the second story window openings. The central bay of the first story holds a single-leaf paneled metal door and a one-light transom. Sidelights flank the door opening, which is sheltered by a one-story, one-bay porch, which is set on a brick pier foundation that has been infilled with glass blocks. The flat roof of the porch has overhanging eaves and dentil molding and is supported by metal posts. Metal balusters encircle the porch, which is accessed via brick steps in the central bay. The roof of the porch features decorative metal balusters. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows and feature concrete sills and lintels. The foundation is pierced by one-light vinyl windows (possibly awning). The north (side) elevation has fenestration that is consistent with the façade. The south (side) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows and a single-leaf wood-frame glass door. The window openings on the south elevation are topped by two-course, rowlock brick segmental arches.

A one-story addition extends from the foundation of the south elevation of the dwelling and is possibly original. The addition is constructed of brick and has a flat roof. The east elevation is pierced by a roll-up paneled metal door. The roof is obscured by a wood fence.

Site Notes:

March 2010: This single-family dwelling is located on the southwest corner of 11th Street, N.E. and G Street, N.E. and is set back approximately ten feet from the brick sidewalk. The rear (west) elevation of the dwelling is adjacent to 1029 G Street, N.E. The front yard is landscaped with mature shrubs and is encircled by a metal bow and picket fence on top of a brick retaining wall.

NOTABLE FEATURES DATA

|--|--|

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Flemish Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				
Materials Notes:					
iviateriais ivotes:					_

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
Basemt Windows Rectangular		Unknown	1-light	Vinyl	
Facade	Rectangular	Dbl-Hung	1/1	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single	Paneled	Metal	
Notable Interior Plan	(s)	N	Notable Interior Feature(s)		

Tuesday, June 25, 2013 ID_Number: 0960-0060 Page 2

Interior Notes:			

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Subdivision: Ward/ANC:

Zoning: Designation Event(s)

Contributing:

Survey(s) Level(s) of Investigation

Capitol Hill F & G Streets (2010)

Permit Research Reconnaissance Survey

Historic District(s)

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 658_11th_Street_NE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 658_11th_Street_NE_facade_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 658_11th_Street_NE_northeast_corner.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Tuesday, June 25, 2013 ID_Number: 0960-0060 Page 3

Notes:							
PERMIT DAT	ГА						
Permit Issue D	ate Number	Туре		Remarks			
06/08/1908	3883	Build					
Permit Notes:							
BIBLIOGRAF	PHIC DATA						
Short Citation			Гуре	Date	Remarks		
Bibliographic N	lotes:						
SIGNIFICAN	CE DATA						
Study Unit							
							
Code	Criteria					_	
DATA PROC	ESSING EVENTS DAT	A					
Date	Individual		Action				
3/8/2010	Dayton (MSD), Mar		Record Upda				
3/8/2010	Dayton (MSD), Mar	ia	Record Creat	ted			

ID Number: 0960-0057

BASICS DATA

ID Number: 0960	-0057	Year Built:	1924	Dat	a Source:	Permit		
Number Extended	Street			Quac	Type of Add	ress		
1025	G Street			NE	Current			
Name(s)			Туре	of Name				
Rowhouse, 1025 G S	Street, N.E.		Comn	non				
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	iin				
0960/0057		Square/Lot	Curre					
STATUS/PURPOS	E/USE DATA	ı						
Resource Type: Bui	_				rent: Extant			
_	toric vhouse			ality: ndition:	Good			
ruipose. Rov	viiouse		Co	nanion.	Good			
Function/Use			Source	Stop	S	ource	Explain	
Residential (Single-I	Family)	1924 F	Permit				Historic/Current	
CONSTRUCTION	DATA							
CONSTRUCTION I		art Sou	rco	Stop	Source		Cost Source	
Orig Construction		924 Peri		Зюр	Source		Cost Source	
Construction Event		Association			A 0000	ciated Nar	m o	
Orig Construction		Architect					ison & Co.	
Orig Construction		Owner			_	Baptist		
Porter, W.E.		Builder				r, W.E.		
Construction Notes:								
One of three rowhou	uses and a chu	ırch construct	ed from t	he sam	e permit (#38	382).		
PEOPLE/EVENTS	DATA							
Racial Segregation St	tatus:							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban		(Cross R	eference Note	es:		
Streetscape:	Intact							
Relate to Othr Bldgs:								
Relate to Street:	Face on Seth							
Massing: Footprint:		g/Front Porch						
	Rectangular							
Number Stories:	2 plus b	asement						
Bays Wide: Height:	3		Outbuildi	ina Tuno		_	Contributing Status	
Width:			Outbuildi	ing Type	,		John Duling Status	
Depth/Length:								
SqFt:								
Volume:								
Lot Width								
Lot Depth/Length:			Outbuildi	ing Note	s:			1
Lot SqFt:								
Acreage:								
Has Driveway:								l

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

March 2010: Constructed in 1924 by W.E. Porter, this two-story, three-bay Colonial Revival-style rowhouse is one of three rowhouses and a church constructed from the same permit (#3882). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (north elevation) is faced with Flemish-bond brick. A sloping roof caps the dwelling and is highlighted by a molded cornice with modillions. An interior-side brick chimney rises from the west (side) elevation of the dwelling and has a parged cap. A molded architrave spans the façade and is located above the second story window openings. A single-leaf paneled door with lights pierces the foundation of the façade. The easternmost bay of the first story holds a single-leaf paneled wood door. Sidelights flank the entry, which is topped by a semi-elliptical fanlight. A two-course, rowlock brick semi-elliptical arch highlights the fanlight. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows, which feature concrete sills and lintels. A one-story, one-bay porch is located on the façade and shelters the primary entrance and central bay. The porch is set on a brick pier foundation that is infilled with wood lattice and is capped by a flat roof supported by metal filigree posts. Overhanging eaves and dentil molding complement the roof. Metal balusters encircle the porch, which is accessed via poured concrete steps in the easternmost end bay. The rear (south) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows. These windows have two-course, rowlock brick segmental arches and sills.

A two-story, three-sided canted bay extends from the westernmost bay of the rear elevation and is original. The canted bay has the material treatment of the main block and is fenestrated with 1/1, double-hung, vinyl-sash windows. All windows have soldier brick flat arches.

Site Notes:

March 2010: This two-story rowhouse is located on the south side of G Street, N.E. and is set back approximately ten feet from the brick sidewalk. The east (side) elevation of the dwelling is adjacent to 1027 G Street, N.E. The raised front yard is bounded by a brick retaining wall. Poured concrete steps lead from the primary entrance of the dwelling and end at the sidewalk. The rear yard is bounded by metal chain-link fencing.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	
Facade	Brick		Flemish Bond		
Structure Component	Material	Feature		Source	
Foundation	Concrete				
Walls	Brick				
Materials Notes:					
Materialo Notos.					

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single	Paneled	Unknown w/Lights
Main Door	Rectangular	Single	Paneled	Wood
Notable Interior Plar	n(s)		Notable Interior Feature(s)	

Interior Notes:		

Tuesday, June 25, 2013 ID_Number: 0960-0057 Page 2

PLAN/	SURVE	//DESIGNATI	ON DATA			
Subdivis	Neighborhood: Capitol Hill Subdivision: Ward/ANC: Zoning: Contributing:		Historic District(s)			
Zoning:			Designation Event(s)			
Survoy	c)				Loyal(s) of Investigat	tion
Survey(3 Streets (2010	n)		Level(s) of Investigat Permit Research	lion
Oupitoi		5 011 CC15 (2011	·,		Reconnaissance Su	urvey
РНОТО	OS - DIG	ITIZED				
Caption	:					
					Undisnla	ayable Image Format
Path:	Databas	s\CHRS\Docur ses\F&G Street base\Pictures\	t - 2 to 11th		Ondiopic	ayabio iiilago i oriilat
File:		_Street_NE_fa		SE.JPG		
Date::		Photog:				
Code::			R:	Fr:		
Path: File: Date:: Code::	Databas St\Data 1025_G	s\CHRS\Docur ses\F&G Street base\Pictures\ _Street_NE_fa Photog:	t - 2 to 11th Square 0960\	_ SW.JPG Fr:	Undispla	ayable Image Format
Caption	:					
					Undispla	ayable Image Format
Path:	Databas St\Data	s\CHRS\Docur ses\F&G Street base\Pictures\	t - 2 to 11th Square 0960\			
File:	1025_G	_Street_NE_re	ar_looking_NI	E.JPG		
Date:: Code::		Photog:	R:	Fr:		
РНОТО	OS - B/W	OR NON-DI	GITIZED			
Photo C	ode	Roll	Frame(s)	Date	Photographer	Caption
MISCE	LLANE	DUS NOTES I	DATA			
Notes:						

Tuesday, June 25, 2013 ID_Number: 0960-0057 Page 3

PERMIT DATA							
Permit Issue Date	Number	Туре		Remarks			_
10/07/1924	3882	Build					
Permit Notes:							
BIBLIOGRAPHIC DATA							
Short Citation		Т	уре	Date	Remarks		_
Bibliographic Notes:							
SIGNIFICANCE DATA							
Study Unit							
Code Criteria							

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/8/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0057 Page 4

ID Number: 0960-0058

BASICS DATA

ID Number: 0960-0058 Year Built: 1924 Data Source: **Permit**

Quad Type of Address Number Extended Street

1027 **G** Street Current

Type of Name Name(s)

Rowhouse, 1027 G Street, N.E. Common

TaxCode2 TaxCode3 Explain 0960/0058 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Condition: Rowhouse Good

Function/Use Start Source Stop Source Explain Residential (Single-Family) 1924 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Cost Source Stop Source

Rear Addition c. 1950 Site

Visit/Map **Permit**

Construction Event Association

1924

Associated Name **Orig Construction Architect** Vaughn Ferguson & Co.

Orig Construction Builder Porter, W.E.

Israel Baptist Church **Orig Construction** Owner

Construction Notes:

Orig Construction

One of three rowhouses and a church constructed from the same permit (#3882).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID Number: 0960-0058 Page 1

Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width Lot Depth/Length: Lot SqFt: Acreage:	Urban Intact Row (1 of 3) Face on Setback Line Row Building/Front Porch Rectangular 2 plus basement 3	Outbuilding Type Outbuilding Notes:		ributing Status	
Has Driveway:					I
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Colonial Revival			_		
Exterior & Architectura	al Notes:				
(side) elevation of th openings. A single-le lintel. The easternmowhich is topped by a on the façade hold 1, porch is located on t foundation that is inf Overhanging eaves a poured concrete stel double-hung, vinyl-s A two-story, three-sic bay is parged and is segmental openings. A one-story addition addition is noted on addition is clad with	lighted by a molded cornice e dwelling. A molded archite af paneled metal door with ost bay of the first story hold one-light transom. A two-co/1, double-hung, vinyl-sash he façade and shelters the pilled with decorative concrete and dentil molding complements in the easternmost end bash windows. These windows ded canted bay extends from fenestrated with 1/1, doubled is located on the easternmost the 1928 Sanborn map, but aluminum siding. A shed round the start of the start of the start of the same and the same architecture.	rave spans the fag lights pierces the ds a single-leaf pa ourse, rowlock bri windows, which for primary entrance a ete block and is ca nent the roof. Meta ay. The rear (south ws are set in segment the westernmose-hung, vinyl-sash ost bay of the rear judging by the ma	rade and is located abordoundation of the façaneled metal door with ck arch highlights the eature concrete sills a and central bay. The proped by a flat roof supped by a flat r	ove the second story winder and is topped by a colights. Sidelights flank the transom. All window open dintels. A one-story, or orch is set on a brick pier oported by brick posts. The ported by brick posts and is fenestrated with 1/2 ion and is original. The content is a content in the content is and are set in the structed c. 1950. A woodstructed c. 1950.	dow encrete lie entry, lenings ne-bay ed via //1, lanted
Site Notes:	t	4141:	of O Street N.E. and		, ton foot
from the brick sidew	o-story rowhouse is located alk. The dwelling is adjacen s bounded along the sidewa	t to 1025 and 1029	G Street, N.E. The rai	sed front yard is landsca	ped with
NOTABLE FEATUR	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		

Tuesday, June 25, 2013 ID_Number: 0960-0058 Page 2

Treatment

Source

Color

Wall Component

Material

Facade	Brick	Flei	mish Bond
Structure Component	Material	Feature	Source
Foundation	Concrete		
Walls	Brick		
Materials Notes:			

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
Facade	Rectangular	Dbl-Hung	1/1	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Basement	Rectangular	Single	Paneled	Metal/Glas	
Main Door	Rectangular	Single	Paneled	Metal/Glas	
Notable Interior Plan	n(s)		Notable Interior Feature(s)		

Interior Notes:

DΙ	ΔN/	SHIP	/FV	/DFSIC	TAME	ION I	

Neighborhood: Capitol Hill Historic District(s)

Subdivision: Ward/ANC: Zoning: Contributing:

Designation Event(s)

Survey(s)

Capitol Hill F & G Streets (2010)

Level(s) of Investigation

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS

Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\

File: 1027_G_Street_NE_facade_looking_S.JPG

Date:: Photog:

Code:: R: Fr:

Tuesday, June 25, 2013 ID_Number: 0960-0058 Page 3

Caption:

Undisplayable Image Format

Path:	C:\Users\CHRS Databases\F&G St\Database\Pic	Street -	2 to 11th				
File:	1027_G_Street_	_NE_faca	ade_looking_	SE.JPG			
Date::	Ph	otog:					
Code::			R:	Fr:			
Caption	:						
					Undis	playable Imag	ge Format
Path:	C:\Users\CHRS Databases\F&G St\Database\Pic	Street -	2 to 11th				
File:	1027_G_Street_	_NE_rear	r_looking_NE	.JPG			
Date:: Code::	Ph	otog:	R:	Fr:			
	OS - B/W OR NO						
Photo C	ode R	oll	Frame(s)	Date	Photographer	Caption	
MISCE Notes:	LLANEOUS NO	OTES D	ATA				
PERMI	T DATA						
Permit I:	ssue Date	N	umber Type 3882 Build		Remarks		
Permit N	Notes:						
BIBLIC	GRAPHIC DAT	- A					
Short Ci	itation			Туре	Date Re	emarks	
Bibliogra	aphic Notes:						
SIGNIF	FICANCE DATA	ı					
Study U							
Code	Criteria						

Tuesday, June 25, 2013 ID_Number: 0960-0058 Page 4

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/8/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0058 Page 5

ID Number: 0960-0059

BASICS DATA

ID Number: 0960	-0059	Year Built:	1924	Dat	ta Source:	Permit		
Number Extended	Street			Quad	d Type of Add	ress		
1029	G Street			NE	Current			
Name(s)			Type	of Name	•			
Rowhouse, 1029 G S	Street, N.E.		Comr					
TaxCode1 TaxCode	2 TaxCode3	Туре	Expla	ain				
0960/0059	2 Taxoodoo	Square/Lot	Curr					
		•						
STATUS/PURPOS	E/USE DATA							
Resource Type: Bui	lding		St	atus Cur	rent: Extant			
Desig. Status: Hist	toric		Qı	uality:				
Purpose: Rov	vhouse		Co	ndition:	Good			
Function/Use		Start S	Source	Stop	5	Source	Explain	
Residential (Single-I	Family)	1924 I	Permit	•			Historic/Current	
CONSTRUCTION I	DATA							
Construction Event	St	art Sou	rce	Stop	Source		Cost Source	
Orig Construction	19	24 Per	mit					
Construction Event		Association			Asso	ciated Nar	me	
Orig Construction		Architect			Vaug	hn Fergu	ison & Co.	
Orig Construction		Builder				er, W.E.		
Orig Construction		Owner			Israe	I Baptist	Church	
Construction Notes:								
One of three rowhou	ises and a chu	rch construc	ted from	the sam	e permit (#3	882).		
DEODI E/EVENTO	DATA							
PEOPLE/EVENTS								
Racial Segregation St	tatus:							
0577110/011405/	0175 0 4 7 4							
SETTING/SHAPE/S	SIZE DATA							
Surroundings:	Urban			Cross R	eference Not	es:		-
Streetscape:	Intact							
Relate to Othr Bldgs: Relate to Street:	Face on Setb	ack Line						
Massing:	Row Building							
Footprint:	Rectangle Ad							
Number Stories:	2 plus ba	sement						
Bays Wide:	3	230ment	Į					
Height:			Outbuild	ing Type)	С	Contributing Status	
Width:								-
Depth/Length:								
SqFt:								
Volume: Lot Width								
Lot Viath Lot Depth/Length:			Outbuild	ina Note	es:			
Lot SqFt:			2 3.50110					
Acreage:								
Has Driveway:								

STYL		·vt			D 4 -	T A
5 I Y I	-/r	- X I	FKI	UK	114	1 4

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

March 2010: Constructed in 1924 by W.E. Porter, this two-story, three-bay Colonial Revival-style rowhouse is one of three rowhouses and a church constructed from the same permit (#3882). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (north elevation) is faced with Flemish-bond brick. A sloping roof caps the dwelling and is highlighted by a molded cornice with modillions. An interior-side brick chimney rises from the west (side) elevation of the dwelling. A molded architrave spans the façade and is located above the second story window openings. A single-leaf wood door pierces the foundation of the façade and is topped by a concrete lintel. The easternmost bay of the first story holds a single-leaf paneled metal door with lights. A paneled sidelight is sited west of the entry, which is topped by a one-light transom. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows, which feature concrete sills and lintels. A one-story, one-bay porch is located on the façade and shelters the primary entrance and central bay. The porch is set on a brick pier foundation that is infilled with glass blocks and is capped by a shed roof supported by brick posts. Overhanging eaves complement the roof. Metal balusters encircle the porch, which is accessed via poured concrete steps in the easternmost end bay. The rear (south) elevation is parged and is fenestrated with 1/1, double-hung, vinyl-sash windows. These windows are set in segmental openings.

A two-story, three-sided canted bay extends from the westernmost bay of the rear elevation and is original. The canted bay is parged and is fenestrated with 1/1, double-hung, vinyl-sash windows. All windows have sills and are set in segmental openings.

Site Notes

March 2010: This two-story rowhouse is located on the south side of G Street, N.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 1027 G Street, N.E. and 658 11th Street, N.E. The raised front yard is landscaped with mature shrubs and is bounded along the sidewalk by a brick retaining wall. Poured concrete steps provide access to the primary entrance.

NOTABLE FEATURES DATA

|--|

EXTERIOR MATERIALS DATA

Not Visible Freatment Source Flemish Bond
Flemish Bond
Course
Source
_

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Basement	Rectangular	Single		Wood
Main Door	Rectangular	Single	Paneled	Metal/Glas
Notable Interior Plar	n(s)		Notable Interior Feature(s)	

Interior Notes:		

Tuesday, June 25, 2013 ID_Number: 0960-0059 Page 2

PLAN/S	SURVEY/DESIGNA	TION DATA					
Neighbo	orhood: Capitol Hi	II		Historic District(s)			
Subdivis Ward/Al Zoning: Contribu	NC:			Designation Event(s)			
Survey(s	s)			Level(s) of Investigat	ion		
	Hill F & G Streets (20	010)		Permit Research	IOH		
оцро.		,		Reconnaissance Su	rvey		
РНОТО	OS - DIGITIZED						
Caption:							
Caption							
				Undispla	yable Imag	e Format	
Path:	C:\Users\CHRS\Doo Databases\F&G Str St\Database\Picture	eet - 2 to 11th es\Square 0960\		·			
File:	1029_G_Street_NE_		_SE.JPG				
Date:: Code::	Photog	: R:	Fr:				
Caption:							
Path: File: Date:: Code::	C:\Users\CHRS\Doc Databases\F&G Str St\Database\Picture 1029_G_Street_NE_ Photog	eet - 2 to 11th es\Square 0960\ _facade_looking	J_ SW.JPG Fr:	Undispla	yable Imag	e Format	
DUOTO	OS - B/W OR NON-	DICITIZED					
Photo C		Frame(s)	Date	Photographer	Caption		
MISCE	LLANEOUS NOTE	S DATA					
Notes:							
PERMI	T DATA						
Permit Is	ssue Date	Number Type)	Remarks			
10/07/19	924	3882 Buil	d				
Permit N	Notes:						
1							
BIBLIC	GRAPHIC DATA						
Short Ci	tation		Туре	Date Remark	(S		

Tuesday, June 25, 2013 ID_Number: 0960-0059 Page 3

Bibliograph	nic Notes:				
				_	
SIGNIFIC	ANCE DATA			 	
Study Unit		_			
Code	Criteria				

DATA PROCESSING EVENTS DATA

Date	Individual	Action
3/8/2010	Dayton (MSD), Maria	Record Updated
3/8/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0059 Page 4

ID Number: 0960-0804

BASICS DATA

ID Number: 0960-0804 Year Built: 1924 Data Source: **Permit** Quad Type of Address Number Extended Street 632 11th Street Current Type of Name Name(s) Church, 632 11th Street, N.E. Common **Israel Baptist Church** Historic Full Gospel Tabernacle Church Inter-Current Denominational TaxCode1 TaxCode2 TaxCode3 Type Explain 0960/0804 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Church Condition: Good

Function/Use Start Source Stop Source Explain

Religious (Church) 1924 Permit Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source	
Orig Construction	1924	Permit				
Construction Event	Association			Associated Name		
Orig Construction	Architect			Vaughn Ferguson & Co.		
Orig Construction	Builder			Porter, W.E.		
Orig Construction	Owner			Israel Bapt	ist Church	
Construction Notes:						

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0960-0804 Page 1

Surroundings: Streetscape: Relate to Othr Bldgs: Relate to Street: Massing: Footprint: Number Stories: Bays Wide: Height: Width: Depth/Length: SqFt: Volume: Lot Width	Urban Intact Detached Face on Setback Line Block T-Shaped 3 3 44 89	Cross Reference Notes: Outbuilding Type Contributing Status	
Lot Depth/Length:		Outbuilding Notes:	
Lot SqFt:			
Acreage:			
Has Driveway:			
STYLE/EXTERIOR	DATA		
Architectural Style(s)			
Gothic Revival			
Exterior & Architectura	al Notes:		
double-hung, wood- first story of the faça concrete keystones a setting as the door of rectangular, three-st treatment as the mai window with a rowlo vented openings wit gabled parapet walls The south (side) elev windows below fixe brick arches. The for elevation is fenestra western end bay of t that is accessed via The rear (west) eleva vinyl-sash windows located on this eleva rear elevation. The b	sash screened windows with the hold large two-leaf meta and soldier brick surrounds penings. A molded metal a ory bell tower rises from the notice by the hold. The tower has two ick brick sill and a soldier between two-course rowlock brick with metal coping and orn vation is fenestrated by five discreened windows. The openindation is pierced by triple ted in the same manner. A ten the elevation. The bay is femetal steps with hand rails attion has an exterior chimne with false 4/4 or 6/6 muntin thion. A two-story, three-siding has dogleg brick corners.	pointed arch openings with three 1/1, double-hung, wood-sash penings are highlighted by rowlock brick sills and two-course road 1/1, double-hung, vinyl-sash windows with false 4/4 muntins. two-story front-gabled bay with asphalt shingles projects from the estrated on the east elevation by a single-leaf metal door with o with a corbeled cap. The elevation is fenestrated with 1/1, doubles. The openings are highlighted by rowlock brick sills. Vents are ed canted bay with a half-hipped tin roof projects from the centers. A single-leaf flush metal door is located on the first story, and	on the s with the same gs. A al screened d-headed bed by screened by screened by screened by screened by screened by screened by by screened by
one-light wood wind the bay. Site Notes:	ows with a rowlock brick si	ill are located at the top of the bay. Vent panels are located on the	e sides of
the brick sidewalk. T wall and sign is bou main and secondary	he south (side) elevation is nded by a milled point meta	It side of 11th Street, N.E. and is set back approximately twenty to adjacent to a brick alley. A small grassy yard with a semicircular if fence and concrete stairs and walkways lead from the sidewal concrete parking area, and mechanical apparatus enclosed by cling.	r brick k to the
NOTABLE FEATU	RES DATA		
Component	Feature		

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source		
Gable	Asphalt		Shingled			
Wall Component	Material	Color	Treatment	Source		
Facade	Brick		American Bond			
Structure Componer	nt Material	Feature		Source		
Foundation	Unknown					
Walls	Brick					
Materials Notes:						
WINDOW/DOOR/I	INTERIOR DATA					
Window Location	Aperture Shape	Туре	Lig	hts	Material	
Facade	Pointed	Fixed	Sta	ained	Wood	
Facade	Rectangular	Dbl-Hung	1/1		Wood	
Facade	Rectangular	Fixed	1		Wood	
Door Location	Aperture Shape	Туре	Pa	mels	Material	
Main Door	Arched (Pointed)	Double			Metal/Glas	
Notable Interior Plan	(s)		Notable Interior Fe	eature(s)		
	ESIGNATION DATA		Historic District(s)			
Subdivision:	аркогт		Thotono Blothot(6)			
Ward/ANC:						
Zoning:			Designation Event(s)			
Contributing:						
Survey(s)			Level(s) of Investig	gation		
Capitol Hill F & G Streets (2010)		Permit Research Reconnaissance	Survey			
PHOTOS - DIGITI	7ED					
1 110103 - DIGITI	<u> </u>					
Caption:						
			Undien	lavahlo Ir	nage Format	
Databases	:HRS\Documents\CHRS \F&G Street - 2 to 11th :e\Pictures\Square 0960\		Olidisp	iayabie II	iiaye i Oilliat	
JUDalabas	ocii iciui esioqual e 03001					
	Street_NE_facade_looki	na NW.JPG				

Tuesday, June 25, 2013 ID_Number: 0960-0804 Page 3

Date::

Code::

Photog:

R:

Fr:

Caption:

Undisplayable Image Format

				0110110	., a.o.oa.go . c	
Path:	C:\Users\CHRS\Doo Databases\F&G Stro St\Database\Picture	eet - 2 to 11th				
File:	632_11th_Street_NE	-	g_SW.JPG			
Date:: Code::	Photog	: R:	Fr:			
Caption	:					
				Undispla	ayable Image Fo	ormat
Path:	C:\Users\CHRS\Doo					
	Databases\F&G Stro St\Database\Picture					
File:	632_11th_Street_NE	-	NE(2).JPG			
Date::	Photog	:				
Code::		R:	Fr:			
Caption	:					
				Undispla	ayable Image Fo	ormat
Path:	C:\Users\CHRS\Doo	cuments\CHRS				
	Databases\F&G Stre	eet - 2 to 11th				
File:	St\Database\Picture 632_11th_Street_NE	-	SE.JPG			
Date::	Photog	_				
Code::	3	R:	Fr:			
Caption	:					
				Undishla	ayable Image Fo	ormat
Doth	C:\Users\CHRS\Doo	oumanta\CUDS		Ondispie	iyabic iillage i c	riilat
Path:	Databases\F&G Stre					
Ella.	St\Database\Picture 632_11th_Street_NE	•	- IDO			
File: Date::			n.JPG			
Code::	Photog	R:	Fr:			
РНОТ	OS - B/W OR NON-I	DIGITIZED				
Photo C		Frame(s)	Date	Photographer	Caption	
1 11010 C	roue iton	Traine(3)	Date	Thotographici	Caption	
MISCE	LLANEOUS NOTES	S DATA				
		PAIA				
Notes:						

Tuesday, June 25, 2013

PERMIT DATA

Darmit lagua	Data	Number	Timo		Remarks			
Permit Issue	Date	Number			Remarks			
10/07/1924		3882	Build					
Permit Notes	3:							
BIBLIOGR	APHIC DATA							
Short Citatio	n			Туре	Date	Remarks		
Bibliographic	Notes:							
SIGNIFICA	NCE DATA							
Study Unit								
Code	Criteria						-	
DATA PRO	CESSING EVE	NTS DAT	A					
Date	Individual			Action				

Record Updated

Record Updated

Record Created

Tuesday, June 25, 2013

4/16/2010

3/18/2010 3/18/2010 Litowitz (DDL), Dana

Dayton (MSD), Maria

Dayton (MSD), Maria

ID Number: 0960-0802

BASICS DATA

ID Number: 0960	1-0802 Yes	ar Built: 1889	Data	Source: Sanbo	orn Map	
Number Extended	Street		Quad T	ype of Address		
651	10th Street		NE C	urrent		
Name(s)		Туре	of Name			
School, 651 10th Str		Com				
Madison Public Sch	ool	Histo	ric			
TaxCode1 TaxCode	2 TaxCode3 Type	Expl	ain			
0960/0802	Squa	re/Lot Curr	ent			
STATUS/PURPOS	F/USE DATA					
Resource Type: Buil		St	atus Curre	nt. Extant		
* *	toric		uality:			
Purpose: Sch	ool		ondition:	Good		
Function/Use	Start	Source	Stop	Source	Explain	
Educational	1889	Sanborn			Historic/Current	
CONSTRUCTION I	DATA					
Construction Event	Start	Source	Stop	Source	Cost Source	
Orig Construction	1889	Sanborn Ma	р			
Construction Event	Assoc	ciation		Associated N	lame	
Construction Notes:						
PEOPLE/EVENTS	DATA					
Racial Segregation St	tatus:					
SETTING/SHAPE/S	SIZE DATA					
Surroundings:	Urban		Cross Refe	erence Notes:		
Streetscape:	Intact]
Relate to Othr Bldgs:	Detached					
Relate to Street:	Face on Setback Li	ne				
Massing:	Block					
Footprint:	Rectangular					
Number Stories:	2 plus baseme	nt				
Bays Wide:	7	0 11 11			0 1 1 1 0 1	
Height: Width:		Outbuild	ding Type		Contributing Status	=
Depth/Length:						
SqFt:						
Volume:						
Lot Width						
Lot Depth/Length:		Outbuild	ding Notes:			7
Lot SqFt: Acreage:						
Has Driveway:						

STYLE/EXTERIOR DATA

Architectural Style(s)

Romanesque Revival

Exterior & Architectural Notes:

March 2010: Constructed in 1889, this two-story, seven-bay Romanesque Revival-style school has a rectangular form. The building is constructed of brick and is set on a solid, raised brick foundation; both are faced with stretcher-bond brick. A multi-course brick watertable encircles the building and is located above the foundation. Multiple brick sill courses encircle the building and several full-height brick pilasters ornament the façade, side, and rear elevations. The roofing type and materials were not discernible from the public right-of-way. A molded cornice with brick dentils complements the roof. An interior brick chimney pierces the roof and has a concrete cap. A three-sided, rectangular bay extends from the center of the façade (west elevation) and rises the full-height of the building. Sharing the material treatment of the main block the bay has a fourth story, which serves as a bell tower. The open-air bell tower is pierced by semicircular openings, which are complemented by semi-circular brick arches with molded imposts. A pyramidal roof caps the bell tower and is covered with slate shingles. The bay is fenestrated with double-leaf metal doors with lights. The opening was originally larger and has been enclosed with wood weatherboard siding. A metal awning shelters the primary entrance and is spanned by a metal lintel with rosettes. Additional fenestration consists of 6/6, double-hung, wood-sash windows, which have concrete sills and four-course, rowlock brick segmental arches. The building is fenestrated with 6/6, double-hung, wood-sash windows, paired one-light vinyl sliding windows, and paired two-light wood casement windows. All first and second story openings have concrete sills and four-course, rowlock brick segmental arches.

The north and south (side) elevations feature a centrally located projecting gable. The gabled roof features a molded cornice and corbeled brick and is delineated on the elevation by corbeled brick pilasters. A six-light wood semicircular window pierces the tympanum of each gable and has a three-course, rowlock brick semicircular arch. A full-height, rectangular bay projects from the rear (east) elevation and has the material treatment of the main block. A gabled roof caps the bay and has a corbeled cornice. Fenestration consists of a single-leaf door, 6/6, double-hung, wood-sash windows, and a six-light wood semi-circular window (possibly fixed) in the upper gable end. A metal awning shelters the door and is topped by a metal lintel with rosettes.

Site Notes:

March 2010: This two-story school is located on the southeast corner of G Street, N.E. and 10th Street, N.E. and is set back approximately five feet from the brick sidewalk. The free-standing building is sited on a level lot that features minimal landscaping. The rear yard is enclosed with metal chain-link fencing.

NOTABLE FEATURES DATA

Component	Feature
•	

EXTERIOR MATERIALS DATA

Color	Not Visible Treatment	Source
Color	Treatment	Source
	Stretcher Bond	
Feature		Source
	Feature	Feature

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Туре	Lights	Material	
Facade	Rectangular	Casement	2 Lite	Wood	
Facade	Rectangular	Dbl-Hung	6/6	Wood	
Facade	Rectangular	Sliding	2 Lite	Vinyl	
Door Location	Aperture Shape	Туре	Pamels	Material	
Main Door	Rectangular	Single		Metal/Glas	
Notable Interior Plan	n(e)	,	Jotable Interior Feature(s)		

Notable Interior Plan(s)

Notable Interior Feature(s)

Tuesday, June 25, 2013 ID_Number: 0960-0802 Page 2

Interior	Notes:	
PLAN/	SURVEY/DESIGNATION DATA	
Neighbo Subdivis Ward/A	sion:	Historic District(s)
Zoning: Contrib		Designation Event(s)
Survey(s)	Level(s) of Investigation
Capitol	Hill F & G Streets (2010)	Permit Research Reconnaissance Survey
РНОТ	OS - DIGITIZED	
Caption	:	
		Undisplayable Image Format
Path:	C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\	
File:	651_10th_Street_NE_facade_looking_NE.JPG	
Date:: Code::	Photog: R: Fr:	
Caption	<u> </u>	
		Undisplayable Image Format
Path:	C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\	
File:	651_10th_Street_NE_facade_looking_SE.JPG	
Date:: Code::	Photog: R: Fr:	
Caption	:	
		Undisplayable Image Format
Path:	C:\Users\CHRS\Documents\CHRS Databases\F&G Street - 2 to 11th St\Database\Pictures\Square 0960\	
File:	651_10th_Street_NE_north_elevation_looking _SW.JPG	

Tuesday, June 25, 2013 ID_Number: 0960-0802 Page 3

Date::

Code::

Photog:

R:

Fr:

Undisplayable Image Format

Path:	Database	CHRS\Docur s\F&G Street ise\Pictures\						
File:	651_10th JPG	_Street_NE_	SE_corner_lool	king_NW.				
Date::		Photog:						
Code::			R:	Fr:				
РНОТ	OS - B/W (OR NON-DI	GITIZED					
Photo C	Code	Roll	Frame(s)	Date	Photogr	apher	Caption	
MISCE	LLANEOU	JS NOTES I	DATA					
Notes:								
PERM	IT DATA							
Permit	ssue Date		Number Type		Remarks			
								-
Permit I	Notes:							
								J
BIBLIC	OGRAPHIC	DATA						
Short C	itation			Туре	Date	Remarks		_
Bibliogr	aphic Notes	:						1
	FICANCE	DATA						
Study L	Jnit							
Code	Crit	teria					_	
DATA	PROCESS	SING EVEN	TS DATA					
Date		Individual		Action				
4/14/20	10	Litowitz (D	DL), Dana	Record U	lpdated			
3/18/20		Dayton (MS		Record U				
3/18/20	10	Dayton (MS	SD), Maria	Record C	reated			

Tuesday, June 25, 2013 ID_Number: 0960-0802 Page 4

ID Number: 0960-0052

BASICS DATA

ID Number: 0960-0052 Year Built: 1876 Data Source: Permit

Number Extended Street Quad Type of Address

601 10th Street NE Current 1002 F Street NE Alternate

Name(s) Type of Name

Dwelling/Store, 601 10th Street, N.E. Common

 TaxCode1
 TaxCode2
 TaxCode3
 Type
 Explain

 0960/0806
 Square/Lot
 Current

 0960/0807
 Square/Lot
 Alternate

 0960/0052
 Square/Lot
 Historic

STATUS/PURPOSE/USE DATA

Resource Type: Building Status Current: Extant

Desig. Status: Historic Quality:

Purpose: Dwelling & Store Condition: Good

Function/Use Start Source Stop Source Explain

Dwelling & Store 1876 Permit Original

Residential (Multi-Family) Current

CONSTRUCTION DATA

 Construction Event
 Start
 Source
 Stop
 Source
 Cost Source

 Orig Construction
 1876
 Permit
 3500 Permit

 Construction Event
 Association
 Associated Name

 Orig Construction
 Owner
 Chappel, L.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Tuesday, June 25, 2013 ID_Number: 0960-0052 Page 1

Surroundings:	Urban	Cross Refer	ence Notes:		
Streetscape:	Intact				
Relate to Othr Bldgs:	Attached (1 side)				
Relate to Street:	Face on Setback Line				
Massing:	Row Bldg (Rect. Bay)				
Footprint:	Rectangular				
North an Ottoday	•				
Number Stories:	2				
Bays Wide:	3	O 4 11 T			
Height:		Outbuilding Type	Con	tributing Status	
Width:					
Depth/Length:					
SqFt:					
Volume:					
Lot Width		Outhuilding Nates			
Lot Septh/Length:		Outbuilding Notes:			
Lot SqFt:					
Acreage:					
Has Driveway:					
STYLE/EXTERIOR	DATA				
Architectural Style(s)					
Italianate					
Exterior & Architectura	al Notes:				
March 2010: This tw	o-story, three-bay Italianate-	style dwelling and s	tore was constructe	d in 1876 from permit #5.	Set on
	his brick building, now a mu			-	
	vation); the first story has b				
•	molded metal cornice and b	•	,		
	w openings, and molded bri with lights and a one-light ti				
•	it vinyl picture window with			-	
	with wood sills and splayed				3 ,
	f the façade and received th		,	-	
	nipped roof of asphalt shing	•		-	, vinyl-
	wood sills and splayed brick ry, one-bay porch spans the			_	ere is a
	orch with molded cornice th				10.15 u
	vation has a wood parapet v nd dentils. A single-leaf pan				
	her fenestrated by 1/1, doub		•		
	st) elevation is fenestrated b				
segmental arches or	n the second story.				
Site Notes:					
March 2010: This bu	ilding is located on the east	side of 10th Street,	N.E. at the intersect	ion of 10th and F Streets,	, N.E.
The building is set b	ack approximately ten feet f	from the brick sidew	alk. The grassy fron	t yard wraps around to th	e side
	d contains mature shrubs, to				
	alkway leads from the sidew by wood privacy fencing, and			-	_
building.	y mood prindly renoming, and	- u ou yu. u oo		,g	
NOTABLE FEATU	RES DATA				
Component	Feature				
EXTERIOR MATER	RIALS DATA				
Roof Component	Material	Color	Treatment	Source	
Sloped	Not Visible		Not Visible		
Wall Component	Material	Color	Treatment	Source	

Stretcher Bond

Facade

Brick

Structure Component	Material	Feature	Source	
Foundation Walls	Brick Brick	i catule	Source	
	Brick			
Materials Notes:				
WINDOW/DOOR/IN	TERIOR DATA			
Window Location	Aperture Shape	Туре	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Facade	Rectangular	Fixed	1	Vinyl
Door Location	Aperture Shape	Туре	Pamels	Material
Main Door	Rectangular	Single	Paneled	Wood/Glass
Notable Interior Plan(s)		Notable Interior Feature(s)	
\				
Interior Notes:				
interior Notes.				
DI ANICHDVEV/DE	CIONATION DATA			
PLAN/SURVEY/DE	SIGNATION DATA			
	pitol Hill		Historic District(s)	
Subdivision:				
Ward/ANC: Zoning:			Designation Event(s)	
Contributing:			Designation Event(s)	
-				
Survey(s)	. (22.42)		Level(s) of Investigation	
Capitol Hill F & G Str	eets (2010)		Permit Research	
			Reconnaissance Survey	
DUOTOG SIGITIT				
PHOTOS - DIGITIZ	EU			
Caption:				
			Undisplayable l	mage Format
Doth: C:\\\care\C\\	RS\Documents\CHRS			mago i orinat
	&G Street - 2 to 11th			
St\Database	\Pictures\Square 0960\			
File: 601_10th_St	reet_NE (2).JPG			
Date::	Photog:			

Tuesday, June 25, 2013 ID_Number: 0960-0052 Page 3

Code::

R:

Fr:

Caption:

Undisplayable Image Format

Path:	C:\Users\CHRS\D Databases\F&G S St\Database\Picto				
File:	601_10th_Street_	NE (3).JPG			
Date::	Phot	-	_		
Code::		R:	Fr:		
Caption	:			Undispla	yable Image Format
Path:		Street - 2 to 11th ures\Square 0960\			
File:	601_10th_Street_				
Date:: Code::	Phot	og: R:	Fr:		
Caption Path:	C:\Users\CHRS\D Databases\F&G S			Undispla	yable Image Format
File:	601_10th_Street_	NE.JPG			
Date::	Phot	=			
Code::		R:	Fr:		
РНОТО	OS - B/W OR NOI	N-DIGITIZED			
Photo C	Code Roll	Frame(s)	Date	Photographer	Caption
MISCE	LLANEOUS NOT	ES DATA			
Notes:					
PERMI	T DATA				
Permit I	ssue Date	Number Type	e	Remarks	
09/01/1	876	5 Buil	d		
Permit I	Notes:				
BIBLIC	GRAPHIC DATA	ı.			
Short C	itation		Туре	Date Remarks	3

Tuesday, June 25, 2013 ID_Number: 0960-0052 Page 4

Bibliograph	nic Notes:			_
				J
SIGNIFIC	ANCE DATA			
Study Unit				
Code	Criteria			

DATA PROCESSING EVENTS DATA

Date	Individual	Action
4/16/2010	Litowitz (DDL), Dana	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Updated
3/18/2010	Dayton (MSD), Maria	Record Created

Tuesday, June 25, 2013 ID_Number: 0960-0052 Page 5