

# Resource All Data Report

**ID Number: 4510-0151**

## BASICS DATA

ID Number: **4510-0151** Year Built: **ca. 1975** Data Source: **Site Visit/Map**

Number Extended Street Quad Type of Address

**1647 Benning Road NE Current**

Name(s) Type of Name

**Office Building, 1647 Benning Road, N.E. Common**

**Greater Northeast Medical Center, 1647 Benning Road, N.E. Current**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0151 Square/Lot Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Office Building** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Office ca. 1975 Site Visit/**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction c.a 1975 Permit**

Construction Event Association Associated Name

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Detached**

Relate to Street: **Face on Line**

Massing: **Horizontal Block**

Footprint: **Rectangular**

Number Stories: **3**

Bays Wide:

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Modern**

Exterior & Architectural Notes:

**March 2008:** This three-story office building was constructed ca. 1975 based on historic aerials. Set on a solid concrete foundation, this structure is capped by a flat roof. The façade (north elevation) is split into three architectural bays by narrow brick pilasters extending from the ground up above the roofline. These serve to give the wide building a verticality juxtaposed by the ribbons of fixed windows and cementitious exterior cladding. Door openings hold double-leaf, metal-frame glass doors with wide transoms. Of note, the recessed westernmost bay on the first story has a brick veneer and a single-leaf, flush metal door. Additional details were not provided by the volunteer surveyor.

Site Notes:

**March 2008:** This large office building is located south of Benning Road, N.E. and fronts the concrete sidewalk. A drive-through lane forms the western boundary of the property. A vehicular breezeway in the eastern end of the property provides access from Benning Road to an asphalt parking lot south of the building. The property extends south to an alley, however, this area was not surveyed or photographed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill - Rosedale**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\  
File: 1647\_BenningRdNE\_2.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\  
File: 1647\_BenningRdNE\_1.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0152**

## BASICS DATA

ID Number: **4510-0152** Year Built: **ca. 1975** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1653 Benning Road NE Current**

Name(s) Type of Name

**Laundromat, 1653 Benning Road, N.E. Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0152 Square/Lot Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Laundry** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Retail (Laundromat) ca. 1975 Site Visit/ Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction ca. 1975 Site Visit/Map**

Construction Event Association Associated Name

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Detached**

Relate to Street: **Parking Lot Setback**

Massing: **Vertical Box/flat front**

Footprint: **Rectangular**

Number Stories: **1**

Bays Wide:

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Modern**

Exterior & Architectural Notes:

**March 2008:** This detached commercial building was constructed ca. 1975 based on historic aerals. The one-story building has a rectangular form. Set on a solid concrete foundation, this concrete-block structure features ribbons of rock-faced and smooth-faced block. The skirt roof is covered with standing-seam metal and features deep overhanging eaves. Multiple metal ventilators and a large laundromat sign define the roofline. Fenestration consists of large fixed store windows and double-leaf, metal-frame glass doors.

**March 2008:** This tall metal sign was constructed ca. 1975. The boxed metal support is topped by a large oval sign.

Site Notes:

**March 2008:** This detached building is located on a corner lot southwest of the intersection of Benning Road, N.E. and 17th Street, N.E. The building is oriented to the north and has a setback of approximately fifty feet from the concrete sidewalk. An asphalt parking lot wraps the building. A large sign is located in front of the building. The lot extends south to an alley.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component

Material

Color

Treatment

Source

Wall Component

Material

Color

Treatment

Source

Structure Component

Material

Feature

Source

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location

Aperture Shape

Type

Lights

Material

Door Location

Aperture Shape

Type

Panels

Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill - Rosedale**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\  
File: 1653\_BenningRdNE\_1.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\  
File: 1653\_BenningRdNE\_2.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0826**

## BASICS DATA

ID Number: **4510-0826** Year Built: **ca.1990** Data Source: **Site Visit/Map**

Number Extended Street Quad Type of Address

**702 -706 17th Street NE Current**

Name(s) Type of Name

**Trailer, 702-706 17th Street, N.E. Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0826 Square/Lot Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Office** Condition: **Fair**

Function/Use Start Source Stop Source Explain

**Office ca. 1990 Site Visit/ Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction ca. 1990 Site Visit/Map**

Construction Event Association Associated Name

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Detached**

Relate to Street: **Parking Lot Setback**

Massing: **Horizontal Block**

Footprint: **Rectangular**

Number Stories: **1**

Bays Wide: **4**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Modern**

Exterior & Architectural Notes:

**March 2008:** This one-story, four-bay mobile trailer appears to have been constructed in the last half of the twentieth century. Placed on a channeled concrete block foundation, this metal-clad structure has a gable roof. Fenestration along the east elevation includes a single-leaf, flush metal door with light and two-light, metal-sash sliding windows. Wood steps provide access to the door opening. Additional details were not surveyed.

Site Notes:

**March 2008:** This property is located on the west side of 17th Street, N.E. The level, gravel lot is enclosed by a chain-link security fence. A mobile trailer is located towards the western end of the property.

**NOTABLE FEATURES DATA**

Component

Feature

**EXTERIOR MATERIALS DATA**

Roof Component

Material

Color

Treatment

Source

Wall Component

Material

Color

Treatment

Source

Structure Component

Material

Feature

Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location

Aperture Shape

Type

Lights

Material

Door Location

Aperture Shape

Type

Panels

Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill - Rosedale**

**Permit Research**

**Volunteer Reconnaissance Survey**

**PHOTOS - DIGITIZED**



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\17thStNE\

File: 702\_17thStNE\_1.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\17thStNE\

File: 702\_17thStNE\_2.JPG

Date:: Photog:

Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0820**

## BASICS DATA

ID Number: **4510-0820** Year Built: **ca. 2008** Data Source: **Site Visit/Map**

Number Extended Street Quad Type of Address

**1606** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Single Dwelling, 1606 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0820** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building**

Status Current: **Extant**

Desig. Status: **Not Historic**

Quality:

Purpose: **Residential**

Condition: **Not Applicable**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **2008** **Site Visit/** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **2008** **Site Visit/Map**

Construction Event Association Associated Name

Construction Notes:

**Under construction at time of survey, March 2008.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Cross Reference Notes:

Streetscape: **Intact**

Relate to Othr Bldgs: **Detached**

Relate to Street: **Front Yard w/ Setback**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Modern**

Exterior & Architectural Notes:

**March 2008: This two-story building was under construction during the 2008 on-site survey. Set on a solid concrete foundation, this wood-frame structure has a shed roof.**

Site Notes:

**March 2008: This building is located north of Gales Street, N.E. The building has a setback of approximately five feet from the concrete sidewalk. An alley forms the eastern boundary of the property. There is a narrow concrete walkway to the west and no backyard.**

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component

Material

Color

Treatment

Source

Wall Component

Material

Color

Treatment

Source

Structure Component

Material

Feature

Source

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location

Aperture Shape

Type

Lights

Material

Door Location

Aperture Shape

Type

Panels

Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill - Rosedale**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\  
File: 1606\_GalesStNE\_1.JPG  
Date:: Photog:  
Code:: R: Fr:



---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

---

### MISCELLANEOUS NOTES DATA

Notes:

---

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

---

Permit Notes:

---

### BIBLIOGRAPHIC DATA

---

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

---

---

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0831**

## BASICS DATA

ID Number: **4510-0831** Year Built: **ca. 1905** Data Source: **Maps**

Number Extended Street Quad Type of Address

**1608** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Single Dwelling, 1608 Gales Street, N.E.c** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0831** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **ca. 1905** **Site Visit/** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **ca. 1905** **Maps**

Construction Event Association Associated Name

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Detached**

Relate to Street: **Front Yard w/ Setback**

Massing: **Vertical Box/flat front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** This two-story, two-bay single-family dwelling was constructed, based on Baist maps, ca. 1905. The wood-frame structure is capped by a shed roof fronted by a prominent cornice with scrolled brackets and arched modillions. Two interior brick chimneys pierce the roof. The façade (south elevation) and east (side) elevation have been clad in vinyl siding. The west (side) elevation has a smooth parged exterior. Fenestration of the façade consists of a single-leaf, paneled wood door with oval light (replacement) and 1/1, double-hung, vinyl-sash windows with false muntins and inoperable louvered vinyl shutters. The side elevations are pierced by 1/1, double-hung, vinyl-sash windows. A one-story, one-bay porch that has been enclosed with a smooth parged exterior and is capped by a shed roof. A ca. 1990 vinyl-clad addition is located on the rear of the porch. The rear of the building was not surveyed by the volunteer surveyor.

Site Notes:

**March 2008:** This detached, single-family dwelling is located north of Gales Street, N.E. and has a setback of approximately ten feet from the concrete sidewalk. The level property is enclosed by a chain-link fence and includes a small grassy front yard. The lot extends north to an alley and includes a shed.

### NOTABLE FEATURES DATA

Component	Feature
-----------	---------

### EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill - Rosedale**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

---

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\  
File: 1608\_GalesStNE\_1.JPG  
Date:: Photog:  
Code:: R: Fr:



---

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

## MISCELLANEOUS NOTES DATA

---

Notes:

## PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

---

Permit Notes:

## BIBLIOGRAPHIC DATA

---

## SIGNIFICANCE DATA

---

Study Unit

Code	Criteria
------	----------

---

## DATA PROCESSING EVENTS DATA

---

# Resource All Data Report

**ID Number: 4510-0082**

## BASICS DATA

ID Number: **4510-0082** Year Built: **ca. 1880** Data Source: **Site Visit/Map**

Number Extended Street Quad Type of Address

**1601 Benning Road NE Current**

Name(s) Type of Name

**Dwelling & Store, 1601 Benning Road, N.E. Common**  
**China House Restaurant, 1601 Benning Road, N.E. Current**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0082 Square/Lot Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Dwelling & Store** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Dwelling & Store ] Sanborn M Historic**  
**Restaurant/Carry-out Site Visit/ Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction ca. 1880 Permit**  
**Addition 1928-1960 Sanborn Map**  
**Garage 1913-1916 Maps**

Construction Event Association Associated Name

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Detached**  
Relate to Street: **Sidewalk Abuts Facade**  
Massing: **Vertical Block (irregular)**  
Footprint: **Irregular**

Number Stories: **2**  
Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2008:** This two-story detached building was constructed at the end of the nineteenth century. Built as a store (first documented on the 1928 Sanborn Fire Insurance Company map), this building has an irregular form and has been subject to multiple additions and alterations. The building is composed of a two-story main block, a centrally located two-story brick addition, and a one-story garage at the southern end of the building. The wood-frame main block has a rough stuccoed exterior and a sloped roof obscured by a prominent molded wood cornice with dentils and angled brackets. Window openings hold 1/1, double-hung, vinyl-sash windows set in square-edge wood surrounds. Multiple openings have been enclosed and stuccoed. The façade (north elevation) has been altered with the installation of a projecting store front that extends across the façade and partially down the west (side) elevation. This wood-frame addition dates to the last decades of the twentieth century and has large fixed storefront windows. A metal sign adorns the roofline of the addition. The east (side) elevation has no openings.

Located in the middle of the building is a two-story brick addition constructed between 1928 and 1960. The building has a two-story block with a one-story segment extending southward with a raised porch set above. This addition has five-course, American-bond brick coursing and a flat roof with an ovolo-molded metal cornice. An interior-corner brick chimney is located in the southeast corner. Fenestration includes 6/6 and 1/1 double-hung, wood-sash windows with rowlock brick sills and soldier brick jack arches. Of note, the brick veneer extends one bay onto the main block. The southernmost bay of the west elevation of the main block continues the five-course, American-brick veneer and features a single-leaf, paneled wood door. The door is set in a Colonial Revival-style surround composed of fluted pilasters and an open pediment with a denticulated cornice. It is probable that when the two-story brick rear addition was constructed this singular side bay with door opening on the main block was altered. A one-story, full-width porch is located on the south (rear) elevation of the brick addition. Set on a solid brick foundation, this porch has a shed roof supported by brick posts and a brick balustrade. A one-story brick block extends on-grade from beneath the elevated rear porch to connect with the southernmost block of the building, the garage. A single-leaf, flush metal door is located on the west side of this segment.

The southernmost segment of this building is an attached one-story, one-bay garage. Constructed as a free-standing building between 1913 and 1916, this brick structure has five-course American-bond brick coursing and a flat roof. A roll-up metal security gate has been installed on the façade (west elevation).

Site Notes:

**March 2008:** This building is located on a corner lot southeast of the intersection of Benning Road, N.E. and 16th Street, N.E. and fronts the concrete sidewalk aside both avenues. An alley forms the southern boundary of the property. A vacant lot is located to the east.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill - Rosedale**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\**

File: **1601\_BenningRdNE\_1.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\

File: 1601\_BenningRdNE\_2.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\

File: 1601\_BenningRdNE\_3.JPG

Date:: Photog:

Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0149**

## BASICS DATA

ID Number: **4510-0149** Year Built: **1966** Data Source: **Cornerstone**

Number Extended Street Quad Type of Address

**1611 Benning Road NE Current**

Name(s) Type of Name

**Church, 1611 Benning Road, N.E. Common**  
**Trinidad Baptist Church Current**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0149 Square/Lot Current**

**4510/0085 Square/Lot Historic**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Religious Structure** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Religious (Church) 1966 Cornersto Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction 1966 Cornerstone**

Construction Event Association Associated Name

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Detached**

Relate to Street: **Front Yard w/ Setback**

Massing: **Vertical Block (irregular)**

Footprint: **Rectangular (irregular)**

Number Stories: **2 plus basement**

Bays Wide: **4**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Modern**

Exterior & Architectural Notes:

**March 2008:** The cornerstone for Trinidad Baptist Church was laid on October 15, 1966, and the church building was dedicated on January 29, 1967. The Modern building has a rectangular form and is set on a solid concrete foundation. The masonry structure is veneered with stretcher-bond brick and capped by a flat roof with metal coping.

The façade (north elevation) is dominated by a irregular pentagonal-shaped projection with a large concrete cross integrated into the design. Concrete coping lines the projection. The main entry consists of paired, double-leaf, flush metal doors. Large panels of stretcher brick and two large black panels complete the Moderne design. Flanking this projection are vertical bays composed of 1/1, double-hung, vinyl-sash windows with concrete sills and large soldier brick spandrels flanked by brick pilasters. An elevated brick deck with a brick balustrade fronts the church.

The west (side) elevation has multi-light metal-sash windows with concrete sills. One window opening has been infilled with decorative concrete block. A double-leaf, flush metal door is located in the northernmost bay. The brick pilasters found on the façade are repeated on the west elevation, albeit with wider window openings.

The south (rear) elevation appears to have a brick chimney and brick appendage with a roofline much lower than that of the main block. Additional details were not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** The Trinidad Baptist Church is located on the south side of Benning Road, N.E. and has a setback of approximately twenty feet. The level, grassy front yard, split by wide concrete steps leading up to the main entry, is enclosed by a milled point metal fence and includes mature shrubs. A concrete walkway provides access from the sidewalk to a handicap lift attached to the side of the front porch. A concrete walkway extends down the western side of the property, which is lined by a chain-link security fence. The property extends south to an alley. The backyard was not surveyed or photographed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill - Rosedale**

Level(s) of Investigation

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\

File: 1611\_BenningRdNE\_1.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\

File: 1611\_BenningRdNE\_2.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

## BIBLIOGRAPHIC DATA

## **SIGNIFICANCE DATA**

---

Study Unit

---

Code

Criteria

---

## **DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 4510-0058**

## BASICS DATA

ID Number: **4510-0058** Year Built: **1943** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1615 Benning Road NE Current**

Name(s) Type of Name

**Apartment Building, 1615 Benning Road, N.E. Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0058 Square/Lot Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Apartment Building** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family) 1943 Permit Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction 1943 Permit 12000 Permit**

Construction Event Association Associated Name

**Orig Construction Architect Santmyers, George T.**

**Orig Construction Builder Werksman, A.**

**Orig Construction Owner Werksman, A.**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Semi-Detached**

Relate to Street: **Front Yard w/ Setback**

Massing: **Vertical Box/flat front**

Footprint: **U-Shaped (irregular)**

Number Stories: **3 plus basement**

Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

March 2008: This three-story-plus-basement, three-bay apartment building was constructed in 1943 by owner/builder Abner Werksman. Designed by architect George T. Santmyers, this Modern building has a rectangular form with a large recessed bay along the east (side) elevation. The building has a split-level side hall plan. Set on a solid concrete foundation, this masonry structure is faced with five-course, American-bond brick. A flat roof is obscured by a brick parapet replete with concrete coping and plain brick panels across the façade (north elevation). A chimney was not surveyed. Located in the western bay of the façade, the main entry holds a single-leaf, flush metal door pierced by two small windows. A wide concrete surround with square-edged profile is replete with a plain entablature and a molded cornice supporting a shallow pediment. Window openings contain fixed and casement metal sash with rowlock brick sills and concrete lug lintels. The raised basement openings include a soldier brick lintel string. The west (side) elevation has six-course, American-bond brick coursing and no openings. The south (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

March 2008: This semi-detached building is located south of Benning Road, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The concrete front is enclosed by a milled point metal fence. The west (side) elevation fronts the property line. The property extends south to an alley, however, the backyard was not surveyed or photographed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component

Material

Color

Treatment

Source

Wall Component

Material

Color

Treatment

Source

Structure Component

Material

Feature

Source

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location

Aperture Shape

Type

Lights

Material

Door Location

Aperture Shape

Type

Panels

Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\**

File: **1615\_BenningRdNE\_1.JPG**

Date:: Photog:

Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>03/19/1943</b>	<b>259304</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0829**

## BASICS DATA

ID Number: **4510-0829** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1617 Benning Road NE Current**

Name(s) Type of Name

**Single Dwelling, 1617 Benning Road, N.E. Original**

**The Jackson Building, 1617 Benning Road, N.E. Current**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0829 Square/Lot Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family) 1925 Permit Original**

**Religious Site Visit/ Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction 1925 Permit**

Construction Event Association Associated Name

**Orig Construction Architect Santmyers, George T.**

**Orig Construction Builder Wignall, John**

**Orig Construction Owner Hess, Fred G.**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs:  
Relate to Street:  
Massing:  
Footprint:

Cross Reference Notes:

Number Stories:

Bays Wide:

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Type

Contributing Status

**Security Stand**

Outbuilding Notes:

**March 2008: This security stand is located adjacent to the dwelling in the parking lot. Set on metal stilts, this metal-frame structure is capped by a flat roof and has large fixed windows.**

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

**Craftsman**

Exterior & Architectural Notes:

**March 2008: Constructed in 1925 by John Wignall for Fred G. Hess, this single-family dwelling was built under permit (#507). Designed by architect George T. Santmyers, this Classical Revival-style dwelling exhibits stylistic influences of the Craftsman and has a rectangular form. Originally constructed as a single-family dwelling, this building has been repurposed to function as office space and now is known as "The Jackson Building". Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond brick. The sloped roof is fronted by a slate-shingled false mansard set between brick firewalls. Twin six-light wood-sash awning windows pierce a shed-roofed false dormer with overhanging eaves. An interior-brick chimney is located along the east elevation. The façade (north elevation) has a single-leaf door opening located in the western bay of the first story (not visible). Window openings on the second story hold 1/1, double-hung, vinyl sash with concrete sills and soldier brick jack arches.**

**The one-story, two-bay porch that extends across the façade has been partially enclosed with vinyl siding. Set on a brick pier foundation, the porch has a flat roof supported by brick posts. A below-grade door opening (not visible) is sheltered by the deck of the porch.**

**Fenestration of the east (side) elevation is limited to four basement window openings with concrete sills and segmental arches.**

**A two-story porch is located on the rear of the dwelling. Enclosed with asbestos shingles, this porch is capped by a shed roof. Additional details were not provided by the volunteer surveyor.**

**March 2008: This metal sign stands approximately ten feet high and appears to have been installed ca. 2000. A metal pole supports a rectangular-boxed metal sign.**

Site Notes:

**March 2008: This semi-detached building is located south of Benning Road, N.E. and has a setback of approximately twenty feet from the concrete sidewalk. The grassy front yard is enclosed by a hairpin metal fence and includes concrete steps up to the front porch as well as down to a below-grade door opening. A tall sign is located in the front yard. An asphalt parking lot forms the eastern half of the property. A guard stand is located within the lot. The property extends south to an alley and includes a secondary dwelling. The backyard was not surveyed or photographed by the volunteer surveyor.**

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component

Material

Color

Treatment

Source

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
-----------------------------------	----------------------

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)
----------------------

Survey(s)	Level(s) of Investigation
-----------	---------------------------

**Capitol Hill - Rosedale**

**Permit Research**

**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\**

File: **1617\_BenningRdNE\_1.JPG**

Date:: Photog:

Code:: R: Fr:




Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\  
File: 1617\_BenningRdNE\_2.JPG

Date:: Photog:

Code:: R: Fr:




Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\  
File: 1617\_BenningRdNE\_3.JPG

Date:: Photog:

Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

07/16/1925	507	Build	
------------	-----	-------	--

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0066**

## BASICS DATA

ID Number: **4510-0066** Year Built: **1937** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1631 Benning Road NE Current**

Name(s) Type of Name

**Dwelling & Store, 1631 Benning Road, N.E. Common**  
**Thompson's Auto and Plate Glass Company, Current**  
**1631 Benning, N.E.**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0066 Square/Lot Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Dwelling & Store** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Dwelling & Store 1937 Permit Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Addition (Rear) ca. 1950 Site Visit/Map**

**Orig Construction 1937 Permit 5000 Permit**

Construction Event Association Associated Name

**Orig Construction Architect Honey, W.B.**

**Orig Construction Builder Smirolodo, Anthony**

**Orig Construction Owner Smirolodo, Anthony**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached (1 side)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Vertical Box/flat front**  
Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **20**

Depth/Length: **36**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2008:** This two-story, three-bay multi-purpose building was constructed in 1937 by owner/builder Anthony Smirolido. Designed by architect W.B. Honey, this Classical Revival-style building has a rectangular form. Set on a solid brick foundation, this brick structure is faced with six-course, American-bond brick coursing. A sloped roof is obscured by a stepped brick parapet with concrete coping across the façade (north elevation). Single-leaf, wood-frame glass doors are located in the outer bays of the façade and include single-light transoms. A three-light fixed storefront window with concrete sill graces the middle bay. A soldier brick lintel string completes the first story openings. The second story is pierced by three, 1/1, double-hung, vinyl-sash windows with concrete sills. A metal sign wraps the façade and east (side) elevation just beneath the second-story sills. The east elevation has no openings.

A large addition, constructed ca. 1950, is located on the rear of the building. Two stories in height, the addition drops down to one story as it extends south. According to Sanborn Fire Insurance Company maps the addition has a concrete block structure. The addition has a smooth parged exterior with areas of failure revealing a brick veneer (possibly structural). Fenestration includes three small openings along the east elevation. Additional details were not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This building is located south of Benning Road, N.E. and has a setback of approximately five feet from the concrete sidewalk. A concrete patio extends between the building and the sidewalk. A large asphalt parking lot forms the eastern boundary of the property. The lot extends south to an alley. The backyard is enclosed by a privacy fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:



## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s) \_\_\_\_\_ Notable Interior Feature(s) \_\_\_\_\_

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s) \_\_\_\_\_  
Subdivision: \_\_\_\_\_  
Ward/ANC: \_\_\_\_\_  
Zoning: \_\_\_\_\_  
Contributing: \_\_\_\_\_  
Designation Event(s) \_\_\_\_\_  
Survey(s) \_\_\_\_\_  
Level(s) of Investigation \_\_\_\_\_  
**Capitol Hill - Rosedale** **Permit Research**  
**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\  
File: 1631\_BenningRdNE\_1.JPG  
Date:: Photog:  
Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
01/28/1937	199082	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

---

## SIGNIFICANCE DATA

---

Study Unit

---

Code

Criteria

---

## DATA PROCESSING EVENTS DATA

---

# Resource All Data Report

**ID Number: 4510-0150**

## BASICS DATA

ID Number: **4510-0150** Year Built: **ca. 1980-2002** Data Source: **Site Visit/Map**

Number	Extended	Street	Quad Type of Address
<b>1635</b>	<b>-1639</b>	<b>Benning Road</b>	<b>NE Current</b>

Name(s)	Type of Name
<b>Restaurant, 1635-1639 Benning Road, N.E.</b>	<b>Common</b>
<b>McDonald's Restaurant</b>	<b>Current</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>4510/0150</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Not Historic** Quality:  
Purpose: **Restaurant** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Restaurant/Carry-out</b>	<b>1980-2002</b>	<b>Site Visit/</b>			<b>Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>ca. 1980-2002</b>	<b>Permit</b>			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Detached**  
Relate to Street: **Paved Setback**  
Massing: **Irregular**  
Footprint: **Rectangular (irregular)**

Number Stories: **2**

Bays Wide:

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type	Contributing Status
------------------	---------------------

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Modern**

Exterior & Architectural Notes:

**March 2008:** This McDonald's commercial building was constructed between 1980 and 2002. The building consists of a two-story main block and a one-story rear block. The concrete-block structure is faced in brick and capped by flat roofs. The two-story main block features single- and double-leaf metal-frame glass doors and large fixed metal storefront windows. The second story features tall fixed metal sash with curved ceilings. The northeast corner of the main block features a bubble skylight and a McDonald's sign affixed to the façade.

The one-story rear block has a single-leaf, flush metal doors. Additional details were not surveyed or photographed by the volunteer surveyor.

**March 2008:** This tall metal sign appears to have been installed at the same time as the building. The McDonald's arch is located on the top of the sign.

Site Notes:

**March 2008:** This commercial building is located on the south side of Benning Road, N.E. and has a setback of approximately ten feet from the concrete sidewalk. The front of the property is covered with concrete and includes a tall sign. A large asphalt parking lot is located to the west and south of the building. A drive-through lane is located east of the building.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\

File: 1635\_BenningRdNE\_1.JPG

Date:: Photog:

Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0099**

## BASICS DATA

ID Number: **4510-0099** Year Built: **1886** Data Source: **Permit**

Number Extended Street Quad Type of Address

**725** **16th Street** **NE** **Current**

Name(s) Type of Name

**Single Dwelling, 725 16th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0099** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1886** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1886** **Permit** **800 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Lewis, J. H.**

**Orig Construction** **Owner** **Lewis, W.F.**

Construction Notes:

**One of two buildings constructed from permit (#0640), only one still extant.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Detached**

Relate to Street: **Front Yard w/ Setback**

Massing: **Vertical Box/front porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**September 2009:** Based on a building permit (#0640), this two-story, two-bay single-family dwelling was constructed in 1886 by J.H. Lewis for W.F. Lewis. Exhibiting stylistic influences of the Italianate style, this wood-frame structure is set on a solid parged foundation and has been clad in vinyl siding. Capped by a sloped roof with an interior brick chimney, the façade (west elevation) features a prominent molded metal boxed cornice with scrolled modillions, dentils, and scrolled brackets. Located in the southern bay of the façade, the main entry holds a single-leaf, paneled wood door with semi-circular light (replacement) sheltered by a one-story, one-bay porch. The porch has a solid brick-veneered foundation and an asphalt-shingled half-hipped roof supported by brick columns. Metal balusters enclose the porch and extend down the brick steps. Window openings on the façade contain 1/1, double-hung, vinyl sash set in narrow vinyl surrounds. The north (side) elevation has four window openings with 1/1, double-hung, vinyl sash. Of note is the one-story integral porch with a brick support located in the southeast corner of the dwelling. The east (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**September 2009:** This detached single-family dwelling is located on the east side of 16th Street, N.E. and has a setback of approximately ten feet from the concrete sidewalk. The level lot is bounded by a chain-link fence and includes a grassy front lawn marked by mature foundation plantings. Brick steps extend off the sidewalk and up to the front porch. North of the property is a vacant lot with a concrete parking pad. A wooden privacy fence encloses the backyard, which extends east to an alley.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	Capitol Hill	Historic District(s)
---------------	--------------	----------------------

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)
----------------------

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\**  
File: **725\_16thStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\**  
File: **725\_16thStNE\_2.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>09/06/1886</b>	<b>0640</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------





# Resource All Data Report

**ID Number: 4510-0097**

## BASICS DATA

ID Number: **4510-0097** Year Built: **ca. 1886** Data Source: **Maps and Permit Information**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>723</b>		<b>16th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	--------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Single Dwelling, 723 16th Street, N.E.</b>	<b>Common</b>
---	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>4510/0097</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>ca. 1886</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-----------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Addition (Rear)</b>	<b>ca. 1950</b>	<b>Site Visit/Map</b>			
------------------------	-----------------	-----------------------	--	--	--

<b>Garage</b>	<b>ca. 1915</b>	<b>Site Visit/Map</b>			
---------------	-----------------	-----------------------	--	--	--

<b>Orig Construction</b>	<b>ca. 1886</b>	<b>Permit</b>			
--------------------------	-----------------	---------------	--	--	--

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis.

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Detached**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Vertical Box/front porch**  
Footprint: **Rectangular**

Number Stories: **2**  
Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

**Garage**

Outbuilding Notes:

**March 2008: This one-story, two-bay garage dates to ca. 1915 based on Sanborn Fire Insurance Company maps. The brick structure is capped by a shed roof. The façade (east elevation) has a roll-up, paneled metal garage door (replacement) in the northern bay. The southern half of the façade has a vehicular opening and a door opening, both of which have been enclosed and parged.**

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2008: Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis. Set on a solid foundation, this wood-frame structure has been reclad in German vinyl siding. The sloped roof has an interior brick chimney and is fronted by a prominent molded cornice with paired scrolled brackets and scrolled modillions. Located in the northern bay of the façade (west elevation), the single-leaf main entry holds a paneled wood door with a blind transom. Window openings on the façade contain 1/1, double-hung, vinyl sash with inoperable louvered vinyl shutters. A porch shelters the first story. Set on a concrete slab, this porch has a flat roof with overhanging eaves supported by brick posts. The south (side elevation) has no openings. The north (side) elevation was not photographed or surveyed by the volunteer surveyor. The east (rear) elevation has been enclosed with German vinyl siding. Additional details were not surveyed.**

**A one-story, full-width addition is located on the rear of the dwelling constructed in the middle of the twentieth century. Clad in German vinyl siding, the addition has a sloped roof and a single-leaf, flush metal door.**

Site Notes:

**March 2008: This single-family dwelling is located on the east side of 16th Street, N.E> and has a setback of approximately ten feet from the sidewalk. The front porch extends to within three feet of the sidewalk. The level property is enclosed by a chain-link fence and has a grassy side yard with shrubs. The rear of the property extends east to an alley and includes a garage.**

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

--

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

--

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
-----------------------------------	----------------------

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill - Rosedale**

**Permit Research**

**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\  
File: 723\_16th\_Street\_NE\_rear\_and\_garage\_lookin  
g\_NW.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\  
File: 723\_16thStNE\_1.JPG

Date:: Photog:

Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

--

---

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

--

---

**BIBLIOGRAPHIC DATA**

---

---

**SIGNIFICANCE DATA**

---

Study Unit

Code	Criteria
------	----------

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 4510-0096**

## BASICS DATA

ID Number: **4510-0096** Year Built: **ca. 1886** Data Source: **Maps and Permit Information**

Number Extended Street Quad Type of Address

**721** **16th Street** **NE** **Current**

Name(s) Type of Name

**Single Dwelling, 721 16th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0096** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **ca. 1886** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Addition (Rear)** **ca. 2000** **Site Visit/Map**

**Orig Construction** **ca. 1886** **Permit**

Construction Event Association Associated Name

Construction Notes:

Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis.

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Detached**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Vertical Box/front porch**  
Footprint: **Rectangular**

Number Stories: **2**  
Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2008:** Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis. Set on a solid foundation, this wood-frame structure has a stuccoed exterior. The sloped roof is fronted by a prominent molded cornice with scrolled brackets and modillions. Located in the northern bay of the façade (west elevation), the main entry holds a single-leaf, paneled wood door sheltered by a one-story, one-bay porch. Set on a concrete slab, the porch has a half-hipped asphalt roof supported by wood posts with square wood balusters. Window openings contain 1/1, double-hung, vinyl sash. The south (side) elevation has no openings. The north (side) elevation was not surveyed by the volunteer surveyor.

The east (rear) elevation has been obscured by a full-width, three-story addition. Constructed ca. 2000 (does not appear on 1999 Sanborn Fire Insurance Company map), this large addition is composed of a parged two-story block with a third story clad in German vinyl siding. The addition is set on a solid concrete block foundation. The first and second stories feature single-leaf, paneled doors with semi-circular lights, a double-leaf French door, and 1/1, double-hung, vinyl-sash windows with false muntins. Quoins, wide strings, and projecting surrounds juxtapose the smooth parged exterior. The third story is capped by an asymmetrical gabled roof with a closed gable facing east. Fenestration consists of a single-leaf, wood-frame glass door and 1/1, double-hung, vinyl-sash windows. An ocular window pierces the projecting gable end. A wood balcony extends across the third story of the east elevation.

Site Notes:

**March 2008:** This dwelling is located on the east side of 16th Street, N.E. and has a setback of approximately ten feet from the sidewalk. The level, grassy front yard is enclosed with a chain-link fence. An asphalt alley (known earlier as Rosedale Alley or Graceland Court) forms the southern boundary of the lot. The property extends east and is bounded by a narrow alley.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
-----------------------------------	----------------------

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill - Rosedale**

**Permit Research**

**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\  
File: 721\_16thStNE\_1.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\  
File: 721\_16thStNE\_2.JPG**

Date:: Photog:

Code:: R: Fr:





Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\  
File: 721\_16thStNE\_3.JPG  
Date:: Photog:  
Code:: R: Fr:



---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

---

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code Criteria

### DATA PROCESSING EVENTS DATA

---

# Resource All Data Report

**ID Number: 4510-0832**

## BASICS DATA

ID Number: **4510-0832** Year Built: **ca. 1886** Data Source: **Maps and Permit Information**

Number Extended Street Quad Type of Address

**719** **16th Street** **NE** **Current**

Name(s) Type of Name

**Single Dwelling, 719 16th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0832** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **ca. 1886** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **ca.1886** **Permit**

Construction Event Association Associated Name

Construction Notes:

**Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Detached**

Relate to Street: **Front Yard w/ Setback**

Massing: **Vertical Box/front porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2008:** Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis. Set on a solid foundation, this wood-frame structure has a parged exterior. The sloped roof has an interior brick chimney and is fronted by a prominent molded cornice with scrolled brackets, modillions, and dentils. Located in the northern bay of the façade (west elevation), the main entry holds a single-leaf, paneled wood door. A one-story, one-bay porch shelters the opening. Set on a concrete slab, the porch has a half-hipped asphalt-shingled roof supported by wood posts. The porch features decorative spindlework and is partially enclosed with lattice. Window openings on the façade contain 1/1, double-hung, vinyl sash set in square wood surrounds. The north (side) elevation has two window openings with 1/1, double-hung, vinyl sash. The south (side) elevation was not surveyed or photographed by the volunteer surveyor. The east (rear) elevation was not surveyed or photographed, though a one-story enclosed porch is visible from 16th Street. Enclosed with vinyl siding, the porch has a shed roof. No additional details were provided by the volunteer surveyor.

Site Notes:

**March 2008:** This single-family dwelling is located east of 16th Street, N.E. and has a setback of approximately ten feet from the concrete sidewalk. The level, grassy front lawn is enclosed by a chain-link fence and includes a large tree in the southwest corner. Extending east to an alley, the backyard is enclosed by a chain-link fence. The building fronts an alley to the north, which was known earlier as Roseland Alley or Graceland Court.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component

Material

Color

Treatment

Source

Wall Component

Material

Color

Treatment

Source

Structure Component

Material

Feature

Source

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location

Aperture Shape

Type

Lights

Material

Door Location

Aperture Shape

Type

Panels

Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
Capitol Hill - Rosedale

Level(s) of Investigation  
Permit Research  
Volunteer Reconnaissance Survey

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\  
File: 719\_16thStNE\_1.JPG  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0811**

## BASICS DATA

ID Number: **4510-0811** Year Built: **ca. 1886** Data Source: **Maps and Permit Information**

Number Extended Street Quad Type of Address

**717** **16th Street** **NE** **Current**

Name(s) Type of Name

**Twin Dwelling, 717 16th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0811** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **ca. 1886** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **ca. 1886** **Permit**

Construction Event Association Associated Name

Construction Notes:

**Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached Twin (1 of 2)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Vertical Box/front porch**  
Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2008:** Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis. Set on a solid foundation, this wood-frame structure has been reclad in German vinyl siding. The sloped roof is fronted by a molded cornice with scrolled brackets and modillions. Located in the northern bay of the façade (west elevation), the main entry holds a single-leaf, paneled wood door (replacement). Window openings contain 1/1, double-hung, vinyl sash with false muntins. All openings have vinyl-clad surrounds. A porch shelters the first story. The asphalt-shingled half-hipped roof is supported by metal filigree posts. The north (side) elevation has three window openings (not surveyed). The east (rear) elevation was not photographed or surveyed by the volunteer surveyor. However, there does appear to be a one-story appendage clad in German vinyl siding. According to Sanborn Fire Insurance Company maps, this section dates to before 1916 and may be original to the dwelling.

Site Notes:

**March 2008:** This twin dwelling is located on the east side of 16th Street, N.E. and has a setback of approximately ten feet from the sidewalk. A picket fence encloses the property, which features a mature tree in the southwest corner. A narrow side yard is located along the north of the building. An alley forms the eastern boundary of the property.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	<b>Capitol Hill</b>	Historic District(s)
Subdivision:		
Ward/ANC:		
Zoning:		Designation Event(s)
Contributing:		
Survey(s)		Level(s) of Investigation

**PHOTOS - DIGITIZED**

---

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\  
File: 717\_16thStNE\_1.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\  
File: 717\_16thStNE\_2.JPG  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

Code Criteria

**DATA PROCESSING EVENTS DATA**

---





# Resource All Data Report

**ID Number: 4510-0810**

## BASICS DATA

ID Number: **4510-0810** Year Built: **ca. 1886** Data Source: **Permit**

Number Extended Street Quad Type of Address

**715** **16th Street** **NE** **Current**

Name(s) Type of Name

**Twin Dwelling, 715 16th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0810** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **ca. 1886** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **ca. 1886** **Permit**

Construction Event Association Associated Name

Construction Notes:

**Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached Twin (1 of 2)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Vertical Box/front porch**  
Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis. Set on a solid foundation, this wood-frame structure has been reclad in German vinyl siding. The sloped roof is fronted by a molded cornice with scrolled brackets and modillions. Located in the southern bay of the façade (west elevation), the main entry holds a single-leaf, paneled wood door (replacement). Window openings contain 1/1, double-hung, vinyl sash with inoperable, louvered vinyl shutters. A one-story, two-bay porch is located on the façade. The porch has an asphalt-shingled half-hipped roof with spindlework supported by chamfered wood posts with decorative brackets. The south (side) elevation has two window openings (not surveyed). The east (rear) elevation was not photographed or surveyed by the volunteer surveyor. However, there does appear to be a one-story appendage clad in vinyl siding. According to Sanborn Fire Insurance Company maps, this section dates to before 1916 and may be original to the dwelling.

Site Notes:

**March 2008:** This twin dwelling is located east of 16th Street, N.E. and has a setback of approximately ten feet from the concrete sidewalk. The property is enclosed by a combination of wood picket, hairpin metal, and chain-link fencing. The property extends east to an alley.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	Capitol Hill	Historic District(s)
Subdivision:		
Ward/ANC:		
Zoning:		Designation Event(s)
Contributing:		
Survey(s)		Level(s) of Investigation

**PHOTOS - DIGITIZED**

---

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\  
File: 715\_16thStNE\_1.JPG  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

---

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit 

Code	Criteria
------	----------

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 4510-0809**

## BASICS DATA

ID Number: **4510-0809** Year Built: **ca. 1886** Data Source: **Maps and Permit Information**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>713</b>		<b>16th Street</b>	<b>NE</b>	<b>Current</b>
------------	--	--------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Twin Dwelling, 713 16th Street, N.E.</b>	<b>Common</b>
---	---------------

TaxCode1	TaxCode2	TaxCode3	Type	Explain
----------	----------	----------	------	---------

<b>4510/0809</b>			<b>Square/Lot</b>	<b>Current</b>
------------------	--	--	-------------------	----------------

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
--------------	-------	--------	------	--------	---------

<b>Residential (Single-Family)</b>	<b>ca. 1886</b>	<b>Permit</b>			<b>Historic/Current</b>
------------------------------------	-----------------	---------------	--	--	-------------------------

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
--------------------	-------	--------	------	--------	-------------

<b>Orig Construction</b>	<b>ca. 1886</b>	<b>Permit</b>			
<b>Addition (Rear)</b>		<b>Site Visit/Map</b>			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis.

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached Twin (1 of 2)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Vertical Box/front porch**  
Footprint: **Rectangular (w/ additions)**

Number Stories: **2**  
Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2008:** Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis. Set on a solid foundation, this wood-frame structure has been reclad in lapped vinyl siding. The sloped roof is fronted by a molded cornice with scrolled brackets and modillions. Located in the northern bay of the façade (west elevation), the main entry holds a single-leaf, paneled wood door (replacement). A one-story, one-bay porch shelters the door opening. The porch has an asphalt-shingled half-hipped roof with spindlework supported by wood posts. Window openings contain 1/1, double-hung, vinyl sash. The north (side) elevation has two window openings. The east (rear) elevation was not photographed or surveyed by the volunteer surveyor. However, there is a one-story appendage clad in vinyl siding visible from 16th Street. According to Sanborn Fire Insurance Company maps, this section dates to before 1916 and may be original to the dwelling. A one-story, shed-roofed addition is located at the back of the dwelling. Clad in vinyl siding, the addition has no fenestration on the north (side) elevation. No further details were visible from the public right-of-way.

Site Notes:

**March 2008:** This twin dwelling is located on the east side of 16th Street, N.E. and has a setback of approximately ten feet from the concrete sidewalk. The narrow front yard is enclosed by a hairpin metal fence and includes mature shrubs. A concrete walkway extends down the north side of the building. Extending east to an alley, the backyard is enclosed with a chain-link fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s) \_\_\_\_\_ Notable Interior Feature(s) \_\_\_\_\_

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s) \_\_\_\_\_  
Subdivision: \_\_\_\_\_  
Ward/ANC: \_\_\_\_\_  
Zoning: \_\_\_\_\_  
Contributing: \_\_\_\_\_  
Designation Event(s) \_\_\_\_\_  
Survey(s) \_\_\_\_\_ Level(s) of Investigation \_\_\_\_\_  
**Capitol Hill - Rosedale** **Permit Research**  
**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\**  
File: **713\_16thStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\**  
File: **713\_16thStNE\_2.JPG**  
Date:: Photog:  
Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

### PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

---

Permit Notes:

--

### BIBLIOGRAPHIC DATA

---

### SIGNIFICANCE DATA

---

Study Unit \_\_\_\_\_

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

---

# Resource All Data Report

**ID Number: 4510-0808**

## BASICS DATA

ID Number: **4510-0808** Year Built: **ca. 1886** Data Source: **Maps and Permit Information**

Number Extended Street Quad Type of Address

**711** **16th Street** **NE** **Current**

Name(s) Type of Name

**Twin Dwelling, 711 16th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0808** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **ca. 1886** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **ca. 1886** **Permit**

Construction Event Association Associated Name

Construction Notes:

**Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached Twin (1 of 2)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Vertical Box/front porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2008:** Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis. Set on a solid foundation, this wood-frame structure has been reclad in lapped vinyl siding. The sloped roof is fronted by a molded cornice with scrolled brackets and modillions. Located in the southern bay of the façade (west elevation), the main entry holds a single-leaf, paneled wood door (replacement). A one-story, one-bay porch shelters the door opening. The porch has an asphalt-shingled roof with spindlework supported by wood posts. Window openings contain 1/1, double-hung, vinyl sash. The north (south) elevation and east (rear) elevation were not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This twin dwelling is located on the east side of 16th Street, N.E. and has a setback of approximately ten feet from the concrete sidewalk. The narrow front yard, enclosed by a milled point metal fence, includes a mature flowering tree. A concrete walkway extends south of the dwelling, providing access through a wooden privacy fence to the backyard. An alley forms the eastern boundary of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill - Rosedale**

**Permit Research**

**PHOTOS - DIGITIZED**

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\  
File: 711\_16thStNE\_1.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\  
File: 711\_16thStNE\_2.JPG  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

**BIBLIOGRAPHIC DATA****SIGNIFICANCE DATA**

Study Unit

Code Criteria

**DATA PROCESSING EVENTS DATA**

# Resource All Data Report

**ID Number: 4510-0807**

## BASICS DATA

ID Number: **4510-0807** Year Built: **ca. 1886** Data Source: **Maps and Permit Information**

Number Extended Street Quad Type of Address

**709** **16th Street** **NE** **Current**

Name(s) Type of Name

**Twin Dwelling, 709 16th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0807** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **ca. 1886** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **ca. 1886** **Permit**

Construction Event Association Associated Name

Construction Notes:

**Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached Twin (1 of 2)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Vertical Box/front porch**  
Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2008:** Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis. Set on a solid foundation, this wood-frame structure has been reclad in lapped vinyl siding. The sloped roof is fronted by an asphalt-shingled pent roof with a molded cornice, scrolled brackets, and dentils. Located in the northern bay of the façade (west elevation), the main entry holds a single-leaf wood door (replacement) with a T-111-clad transom. Window openings contain 1/1, double-hung, vinyl sash. Window openings contain 1/1, double-hung, vinyl sash. A one-story, one-bay porch shelters the first-story openings. Set on a concrete slab, this porch has a flat roof with a molded metal cornice supported by brick posts. The north (side) elevation has two window openings and a single-leaf door opening. The east (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This twin dwelling is located on the east side of 16th Street, N.E. and has a setback of approximately ten feet from the concrete sidewalk. The narrow front lawn is enclosed by a chain-link fence and includes a rock walkway leading to the wooden privacy fence that lines the side yard (north of dwelling). The rear of the property was not surveyed or photographed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	<b>Capitol Hill</b>	Historic District(s)
Subdivision:		
Ward/ANC:		
Zoning:		Designation Event(s)
Contributing:		
Survey(s)		Level(s) of Investigation

**PHOTOS - DIGITIZED**

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\  
File: 709\_16thStNE\_1.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\  
File: 709\_16thStNE\_2.jpg  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

**BIBLIOGRAPHIC DATA****SIGNIFICANCE DATA**

Study Unit

Code	Criteria
------	----------

**DATA PROCESSING EVENTS DATA**



# Resource All Data Report

**ID Number: 4510-0806**

## BASICS DATA

ID Number: **4510-0806** Year Built: **ca. 1886** Data Source: **Maps and Permit Information**

Number Extended Street Quad Type of Address

**707** **16th Street** **NE** **Current**

Name(s) Type of Name

**Twin Dwelling, 707 16th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510-0806** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **ca. 1886** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **ca. 1886** **Permit**

Construction Event Association Associated Name

Construction Notes:

**Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached Twin (1 of 2)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Vertical Box/front porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

March 2008: Although no building permit was identified in the District of Columbia building permit database, this dwelling closely resembles the others on the east side of the 700 Block of 16th Street, N.E., dating it to ca. 1886 with a probable owner/builder being either W.F. Lewis or J.H. Lewis. Set on a solid foundation, this wood-frame structure has a smooth parged exterior. The sloped roof is fronted by a molded cornice with scrolled brackets. Located in the southern bay of the façade (west elevation), the main entry holds a single-leaf wood door (replacement). Window openings contain 1/1, double-hung, vinyl sash. A one-story, one-bay porch shelters the first-story openings. Set on a concrete slab, this porch has a flat roof supported by brick posts with a honeycomb-brick balustrade. The south (side) and east (rear) elevation was not surveyed by the volunteer surveyor.

Site Notes:

March 2008: This twin dwelling is located on the east side of 16th Street, N.E. and has a setback of approximately ten feet from the concrete sidewalk. The narrow front lawn is enclosed by a hairpin metal fence and includes mature trees and shrubs. A concrete walkway provides access to the front porch. A narrow side yard is located south of the building. The rear extends east to an alley but was not surveyed or photographed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill - Rosedale**

**Permit Research**



**PHOTOS - DIGITIZED**

---

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\  
File: 707\_16thStNE\_1.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\  
File: 707\_16thStNE\_2.JPG  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

Code Criteria

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 4510-0804**

## BASICS DATA

ID Number: **4510-0804** Year Built: **1886** Data Source: **Permit**

Number Extended Street Quad Type of Address

**703** **16th Street** **NE** **Current**

Name(s) Type of Name

**Twin Dwelling, 703 16th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0804** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1886** **Permit**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1886** **Permit** **800 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Lewis, W.F.**

**Orig Construction** **Owner** **Lewis, W.F.**

Construction Notes:

**One of three buildings constructed from permit (#0898), one of two still extant.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached Twin (1 of 2)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Vertical Box/rectang bay**

Footprint: **Rectangular (w/ additions)**

Number Stories: **2**

Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**March 2008:** This two-story, three-bay twin dwelling was constructed in 1886 by owner/builder W.F. Lewis and is one of three similar builders erected under the same permit (#0898). Only two are extant. Set on a solid brick foundation, this wood-frame structure has been clad in aluminum siding. The sloped roof is fronted by a false mansard of slate shingles with a boxed metal cornice. Located in the southern bay of the façade (west elevation), the main entry holds a single-leaf door with transom set beneath a one-story, one-bay porch. Set on a brick stoop, the porch has an asphalt-shingled shed roof supported by metal filigree posts. Dominating the façade is a full-height projecting bay north of the main entry. Clad in aluminum siding, the projection is capped by a slate-shingled pyramidal roof with a metal finial. Window openings on the façade contain 1/1, double-hung, vinyl sash set in vinyl-clad surrounds. The south (side) elevation has 1/1, double-hung, vinyl-sash windows.

The rear of the dwelling features a two-story, one-bay projection to the south. Part of the original design, this appendage has been clad in a combination of aluminum and vinyl siding. Capped by a shed roof, fenestration includes a single-leaf, paneled wood door with transom and a 1/1, double-hung, vinyl-sash window located on the west elevation.

The east (rear) elevation of the dwelling was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This dwelling is located on the east side of 16th Street, N.E. and has a setback of approximately ten feet from the concrete sidewalk. The front yard is enclosed with a milled point metal fence. Brick steps provide access up to the main entry. A narrow concrete walk skirts the building to the south, providing access to a secondary side door opening. The property extends east to an alley. A large, level grassy vacant lot is located to the south.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning: Contributing:  Survey(s) <b>Capitol Hill - Rosedale</b>	Designation Event(s)   Level(s) of Investigation <b>Permit Research</b> <b>Volunteer Reconnaissance Survey</b>
---	---

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
 Databases\Rosedale - 15 to 19th  
 St\Database\Pictures\Square 4510\16thStNE\  
 File: 703\_16thStNE\_1.JPG  
 Date:: Photog:  
 Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/04/1886	0898	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0805**

## BASICS DATA

ID Number: **4510-0805** Year Built: **1886** Data Source: **Permit**

Number Extended Street Quad Type of Address

**705** **16th Street** **NE** **Current**

Name(s) Type of Name

**Twin Dwelling, 705 16th Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0805** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1886** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1886** **Permit** **800 Permit**

Construction Event Association Associated Name

**Orig Construction** **Builder** **Lewis, W.F.**

**Orig Construction** **Owner** **Lewis, W.F.**

Construction Notes:

**One of three buildings constructed from permit (#0898), one of two still extant.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached Twin (1 of 2)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Vertical Box/front porch**

Footprint: **Rectangular (w/ additions)**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** This two-story, two-bay twin dwelling was constructed in 1886 by owner/builder W.F. Lewis and is one of three similar builders erected under the same permit (#0898). Only two are extant. Set on a solid brick foundation, this wood-frame structure has a smooth parged exterior. The sloped roof is obscured by a plain pent set above a molded metal cornice with scrolled brackets. Located in the northern bay of the façade (west elevation), the main entry holds a single-leaf, flush wood door with diamond light and a blind transom set above. South of the main entry is a 2/2, double-hung, wood-sash window. A one-story porch shelters the first story. Set on a solid foundation faced with brick, the porch has an asphalt-shingled shed roof with a molded metal cornice. Tapered parged columns are set atop brick piers with a honeycomb brick balustrade extending between. The second story is fenestrated with 1/1, double-hung, vinyl-sash windows. The north (side) and east (rear) elevations were not photographed or surveyed by the volunteer surveyor.

A second-story appendage is located at the rear of the north (side) elevation. An original feature, this feature is supported by metal posts, has a parged exterior, and is capped by a shed roof. One bay wide, fenestration includes 1/1, double-hung, vinyl-sash windows.

Site Notes:

**March 2008:** This dwelling is located on the east side of 16th Street, N.E. and has a setback of approximately ten feet from the concrete sidewalk. The front yard has a small grassy yard and is enclosed with a hairpin metal fence. A narrow concrete walkway skirts the building to the north, providing access to the backyard. The lot extends east to an alley.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\**  
File: **705\_16thStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\16thStNE\**  
File: **705\_16thStNE\_2.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/04/1886</b>	<b>0898</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------





# Resource All Data Report

**ID Number: 4510-0143**

## BASICS DATA

ID Number: **4510-0143** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1612** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1612 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0143** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

March 2008: Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a pedimented brick parapet featuring a molded metal cornice with dentils. A blank concrete field with rowlock brick surround completes the parapet. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door (replacement) with a single-light transom. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. Additional fenestration includes a two-light, vinyl-sash sliding basement window. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation with honeycomb brick infill, this porch has a flat roof with overhanging eaves and a narrow molded metal cornice. Brick posts support the roof with metal balusters extending between. The west (side) and north (rear) elevations were not surveyed or photographed by the volunteer surveyor.

Site Notes:

March 2008: This semi-detached dwelling is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard is enclosed by a chain-link fence. Concrete steps provide access up to the front porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material
Notable Interior Plan(s)			Notable Interior Feature(s)	

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	Capitol Hill	Historic District(s)
Subdivision:		
Ward/ANC:		
Zoning:		Designation Event(s)
Contributing:		

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1612\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0142**

## BASICS DATA

ID Number: **4510-0142** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1614** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1614 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0142** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a stepped brick parapet featuring a molded metal cornice with dentils. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door (replacement) with a single-light transom. Window openings contain 1/1, double-hung, vinyl sash with false muntins and concrete sills. Soldier brick lintel strings complete the first and second story openings. Additional fenestration includes a single-leaf, multi-light wood door with access to the basement. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation with decorative concrete block infill, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with metal balusters extending between. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard is enclosed by a chain-link fence. Concrete steps provide access up to the front porch while stone pavers lead to a below-grade door opening. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1614\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0141**

## BASICS DATA

ID Number: **4510-0141** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1616** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1616 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0141** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular (w/ additions)**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a gabled brick parapet featuring a molded metal cornice with dentils. A blank concrete field with rowlock brick surround completes the parapet. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door with a single-light transom. Window openings contain 1/1, double-hung, vinyl sash with false muntins and concrete sills. Soldier brick lintel strings complete the first and second story openings. Additional fenestration includes paired 4-light vinyl-sash sliding basement windows. A one-story, one-bay porch shelters the main entry and one window opening. Set on a concrete pier foundation, this porch has a flat roof with overhanging eaves and a molded metal cornice. Paneled wood posts set on paneled piers support the roof and adjoining roof-top balustrade. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard includes a concrete walkway. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	Capitol Hill	Historic District(s)
Subdivision:		
Ward/ANC:		
Zoning:		Designation Event(s)
Contributing:		



Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1616\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0140**

## BASICS DATA

ID Number: **4510-0140** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1618** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1618 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0140** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a stepped brick parapet featuring a molded metal cornice with dentils. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door with a single-light transom. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation with decorative concrete block infill which extends up to form a balustrade, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level front yard is enclosed by a chain-link fence. A stone paver walkway with brick accents provides access up to the front porch steps. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**PHOTOS - DIGITIZED**

---

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\  
File: 1618\_GalesStNE\_1.JPG  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
10/08/1924	3568	Build	

---

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

Code	Criteria
------	----------

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 4510-0127**

## BASICS DATA

ID Number: **4510-0127** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1644** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1644 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0127** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a gabled brick parapet featuring a molded metal cornice with dentils. A concrete panel with rowlock brick surround completes the parapet. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door with lights and a single-light transom. Window openings contain 6/1, double-hung, wood sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with metal balusters extending between. East of the porch a below-grade door opening holds a single-leaf, paneled wood door with nine lights set in a square wood surround. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard is enclosed by a chain-link fence and includes mature shrubs and small trees. Concrete steps provide access up to the front porch. A secondary walkway provides access down to a below-grade door opening east of the porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	Capitol Hill	Historic District(s)
---------------	--------------	----------------------

Subdivision:

Ward/ANC:

Zoning:

Contributor:

Designation Event(s)
----------------------

Contributing:

Survey(s)

**Capitol Hill - Rosedale**

Level(s) of Investigation

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\  
File: 1644\_GalesStNE\_1.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/08/1924	3568	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0139**

## BASICS DATA

ID Number: **4510-0139** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1620** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1620 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0139** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

March 2008: Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a gabled brick parapet featuring a molded metal cornice with dentils. A blank concrete panel with a rowlock brick surround completes the parapet. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf door (not visible). Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. Additional fenestration includes a basement window (not surveyed). A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation with brick infill, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with metal balusters extending between. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

March 2008: This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level front yard is enclosed by a chain-link fence and includes immature plantings. Concrete steps provide access up to the front porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1620\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0800**

## BASICS DATA

ID Number: **4510-0800** Year Built: **ca.1903-1907** Data Source: **Maps**

Number Extended Street Quad Type of Address

**1610** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Single Dwelling, 1610 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0800** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **ca. 1903-19 Site Visit/** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **ca. 1903-1907** **Maps**

Construction Event Association Associated Name

Construction Notes:

**Incorrectly listed on permit (# 1607). Appears on Baist Maps between 1903 and 1907.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Detached**

Relate to Street: **Front Yard w/ Setback**

Massing: **Vertical Box/flat front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**

Exterior & Architectural Notes:

**March 2008:** This two-story, two-bay single-family dwelling has stylistic influences of the Italianate style. Although an accurate building permit for this building could not be located, based on Baist maps from 1903 and 1907, this wood-frame structure was constructed ca. 1905. Set on a solid foundation, the dwelling has been clad in vinyl siding. The sloped roof is fronted by a molded metal boxed cornice with scrolled modillions set between slightly larger brackets. Located in the eastern bay of the façade (south elevation), the main entry holds a single-leaf, paneled metal door with oval light (replacement) set in a plain, wide vinyl-clad surround. Window openings on the façade contain 1/1, double-hung, vinyl sash with 6/6 false muntins flanked by inoperable louvered vinyl shutters. The east (side) elevation has 1/1, double-hung, vinyl-sash windows. The west (side) and north (rear) elevations were not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This detached, single-family dwelling is located north of Gales Street, N.E. and has a setback of approximately ten feet from the concrete sidewalk. The level lot is enclosed by a chain-link fence and includes a small grassy front yard. A concrete walkway lines the east side of the building. The backyard extends north to an alley.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill - Rosedale**

**Permit Research**

**PHOTOS - DIGITIZED**

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\  
File: 1610\_GalesStNE\_1.JPG  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

**BIBLIOGRAPHIC DATA****SIGNIFICANCE DATA**

Study Unit

Code	Criteria
------	----------

**DATA PROCESSING EVENTS DATA**

# Resource All Data Report

**ID Number: 4510-0138**

## BASICS DATA

ID Number: **4510-0138** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1622** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1622 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0138** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular (w/ additions)**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a stepped brick parapet featuring a molded metal cornice with dentils. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door with a single-light transom. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation with decorative concrete block infill, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with metal balusters extending between. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard is enclosed by a chain-link fence and includes mature shrubs and foundation plantings. Concrete steps provide access up to the front porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1622\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA



# Resource All Data Report

**ID Number: 4510-0137**

## BASICS DATA

ID Number: **4510-0137** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1624** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1624 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0137** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a gabled brick parapet featuring a molded metal cornice with dentils. A blank concrete panel with rowlock brick surround completes the parapet. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, flush wood door with lights and a single-light transom. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. A single-light vinyl awning window pierces the basement. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation with decorative concrete block infill, this porch has a flat roof with overhanging eaves and a metal cornice. Brick posts support the roof with metal balusters extending between. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard is enclosed by a chain-link fence. Concrete steps provide access up to the front porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1624\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0136**

## BASICS DATA

ID Number: **4510-0136** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1626** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1626 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510-0136** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 22)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a stepped brick parapet featuring a molded metal cornice with dentils. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf wood door with a single-light transom. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. A single-light vinyl awning window pierces the basement. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with metal balusters extending between. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard is enclosed by a chain-link fence. Concrete steps provide access up to the front porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**PHOTOS - DIGITIZED**

---

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\  
File: 1626\_GalesStNE\_1.JPG  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
10/08/1924	3568	Build	

---

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

Code Criteria

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 4510-0135**

## BASICS DATA

ID Number: **4510-0135** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1628** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1628 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0135** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

March 2008: Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a gabled brick parapet featuring a molded metal cornice with dentils. A concrete panel with rowlock brick surround completes the parapet. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door with twelve lights and a single-light transom. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with metal balusters extending between. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

March 2008: This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard is enclosed by a wooden picket fence. Concrete steps provide access up to the front porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:



Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1628\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0134**

## BASICS DATA

ID Number: **4510-0134** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1630** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1630 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0134** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Res Multi/Commcl/Movie Theater** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a stepped brick parapet featuring a molded metal cornice with dentils. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door with oval light (replacement) and a single-light transom. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. A below-grade door opening is located in the eastern bay and contains a single-leaf, paneled wood door with semi-circular light (not original). A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation infilled with brick and pierced by two-light vinyl sliding windows, the porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with metal balusters extending between. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level front yard is enclosed by a chain-link fence. Concrete steps provide access up to the front porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material
Notable Interior Plan(s)			Notable Interior Feature(s)	

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	Capitol Hill	Historic District(s)
Subdivision:		
Ward/ANC:		
Zoning:		Designation Event(s)
Contributing:		

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1630\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0133**

## BASICS DATA

ID Number: **4510-0133** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1632** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1632 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0133** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multifamily/Misc)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a gabled brick parapet featuring a molded metal cornice with dentils. A blank concrete field with rowlock brick surround completes the parapet. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door with a single-light transom. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. Additional fenestration includes a multi-light basement window set in a narrow, square-edge wood surround. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation with brick infill, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with metal balusters extending between. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level front yard is enclosed by a chain-link fence and dotted with flowers. Concrete steps provide access up to the front porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	Capitol Hill	Historic District(s)
---------------	--------------	----------------------

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)
----------------------

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1632\_GalesStNE\_1.JPG**

Date:: Photog:

Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0132**

## BASICS DATA

ID Number: **4510-0132** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1634** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1634 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0132** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

March 2008: Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a stepped brick parapet featuring a molded metal cornice with dentils. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door with semi-circular light (replacement) and a blind transom. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with square wood balusters extending between. The porch has a wood deck. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

March 2008: This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard features a wooden handicap ramp off the sidewalk up to the front porch. Concrete steps also access the porch from the sidewalk. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1634\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0131**

## BASICS DATA

ID Number: **4510-0131** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1636** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1636 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0131** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a gabled brick parapet featuring a molded metal cornice with dentils. A blank concrete panel with a rowlock brick surround completes the parapet. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door (replacement) with a frosted transom. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. Additional fenestration includes a single-light, vinyl-sash awning basement window. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with metal balusters extending between. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard is enclosed by a chain-link fence. Concrete steps provide access up to the front porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1636\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0130**

## BASICS DATA

ID Number: **4510-0130** Year Built: **1924** Data Source:

Number Extended Street Quad Type of Address

**1638** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1638 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0130** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a stepped brick parapet featuring a molded metal cornice with dentils. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door with semi-circular light (replacement) and a single-light transom. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. Additional fenestration consists of a two-light, metal-sash awning window. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation with decorative concrete block infill, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with metal balusters extending between. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard is enclosed by a chain-link fence. Brick steps provide access up to the front porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	Capitol Hill	Historic District(s)
---------------	--------------	----------------------

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)
----------------------

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1638\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA



# Resource All Data Report

**ID Number: 4510-0129**

## BASICS DATA

ID Number: **4510-0129** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1640** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1640 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0129** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a gabled brick parapet featuring a molded metal cornice with dentils. A blank concrete panel with rowlock brick surround completes the parapet. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, flush wood door with a single-light transom. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation with lattice infill, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with a wood balustrade located on the sides of the porch. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard is enclosed by a chain-link fence and includes mature shrubs and plantings. Concrete steps provide access up to the front porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	Capitol Hill	Historic District(s)
Subdivision:		
Ward/ANC:		
Zoning:		Designation Event(s)
Contributing:		

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1640\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0122**

## BASICS DATA

ID Number: **4510-0122** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1654** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1654 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0122** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a stepped brick parapet complete with a molded metal cornice and dentils. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, flush wood door with lights and a transom covered with plywood. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the openings. A one-story porch extends across the façade. Set on a brick pier foundation with decorative concrete block infill, the porch has metal balusters extending between brick piers. The roof has been removed and the porch elongated from its original configuration. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard is enclosed by a chain-link fence. Concrete steps provide access up to the front porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**PHOTOS - DIGITIZED**

---

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\  
File: 1654\_GalesStNE\_1.JPG  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
10/08/1924	3568	Build	

---

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

Code	Criteria
------	----------

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 4510-0128**

## BASICS DATA

ID Number: **4510-0128** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1642** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1642 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0128** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

March 2008: Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a stepped brick parapet featuring a molded metal cornice with dentils. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door with lights (replacement) and a single-light transom. Window openings contain 6/1 wood and 1/1 vinyl double-hung sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. A below-grade door opening (not surveyed) is located in the eastern end of the façade. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation infilled with concrete, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with metal balusters extending between. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

March 2008: This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The front of the property is enclosed by a chain-link fence. Concrete steps provide access up to the front porch. A second concrete walkway provides access to a below-grade door opening. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:



Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1642\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0126**

## BASICS DATA

ID Number: **4510-0126** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1646** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1646 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0126** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

March 2008: Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a stepped brick parapet complete with a molded metal cornice and dentils. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door (replacement) with a single-light transom. Window openings contain 6/1, double-hung, wood sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation with decorative concrete block infill, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with metal balusters extending between. Additional fenestration consists of a basement window east of the porch. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

March 2008: This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard is enclosed by a chain-link fence. Concrete steps provide access up to the front porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1646\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0125**

## BASICS DATA

ID Number: **4510-0125** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1648** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1648 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0125** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a gabled brick parapet complete with a molded metal cornice and dentils. A concrete panel with rowlock brick surround completes the parapet. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door with lights and a single-light transom. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation with decorative concrete block infill, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with cross-braced metal railing extending between. A below-grade single-leaf paneled wood door is located east of the porch. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard is enclosed by a milled point metal fence and includes mature shrubs. Concrete steps provide access up to the front porch. A concrete walkway provides access to a below-grade door opening east of the porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1648\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0124**

## BASICS DATA

ID Number: **4510-0124** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1650** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1650 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0124** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a stepped brick parapet complete with a molded metal cornice and dentils. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door with twelve lights and a single-light transom. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the first and second story openings. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation infilled with parged concrete block, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with metal balusters extending between. Additional fenestration consists of a six-light wood-sash basement window east of the porch. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**March 2008:** This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard is partially enclosed by a milled point metal fence. Concrete steps provide access up to the front porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1650\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 4510-0123**

## BASICS DATA

ID Number: **4510-0123** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1652** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1652 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0123** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

March 2008: Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a gabled brick parapet complete with a molded metal cornice and dentils. A concrete panel with rowlock brick surround completes the parapet. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, paneled wood door with a single-light transom. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the openings. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation with decorative concrete block infill, this porch has a flat roof with overhanging eaves. Brick posts support the roof with metal balusters extending between. The north (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

March 2008: This rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The level, grassy front yard is enclosed by a milled point metal fence. Concrete steps provide access up to the front porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1652\_GalesStNE\_1.JPG**  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1652\_GalesStNE\_2.JPG**  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



# Resource All Data Report

**ID Number: 4510-0822**

## BASICS DATA

ID Number: **4510-0822** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1656** **Gales Street** **NE** **Current**

Name(s) Type of Name

**Rowhouse, 1656 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0822** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4347 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howenstein, H. R.**

**Orig Construction** **Builder** **Howenstein, H. R.**

**Orig Construction** **Owner** **Howenstein, H. R.**

Construction Notes:

**One of twenty-three buildings constructed from permit (#3568).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 23)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Classical Revival

Exterior & Architectural Notes:

March 2008: Constructed in 1924 by owner/architect/builder H.R. Howenstein, this two-story, three-bay Classical Revival-style semi-detached rowhouse was one of 23 similar buildings erected under the same permit (#3568). Set on a solid concrete foundation, this brick structure is faced with five-course, American-bond coursing. A sloped roof caps the rowhouse and is fronted by a gabled brick parapet complete with a molded metal cornice and dentils. A concrete panel with rowlock brick surround completes the parapet. A chimney was not visible from the public right-of-way. Located in the western bay of the façade (south elevation), the main entry holds a single-leaf, flush wood door with an altered single-light transom. Window openings contain 1/1, double-hung, vinyl sash with concrete sills. Soldier brick lintel strings complete the openings. A one-story, one-bay porch shelters the main entry and one window opening. Set on a brick pier foundation with lattice infill, this porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts support the roof with metal balusters extending between. The north (rear) elevation was not surveyed or photographed by the volunteer

Site Notes:

March 2008: This semi-detached rowhouse is located on the north side of Gales Street, N.E. and has a setback of approximately fifteen feet from the concrete sidewalk. A gap of approximately five inches separates the building from 1660 Gales Street, N.E. The level, grassy front yard is enclosed by a chain-link fence and includes immature plantings. Concrete steps provide access up to the front porch. The rear of the property was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	Capitol Hill	Historic District(s)
---------------	--------------	----------------------

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)
----------------------



Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1656\_GalesStNE\_1.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\**  
File: **1656\_GalesStNE\_2.JPG**

Date:: Photog:

Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>10/08/1924</b>	<b>3568</b>	<b>Build</b>	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



# Resource All Data Report

**ID Number: 4510-0825**

## BASICS DATA

ID Number: **4510-0825** Year Built: **1949** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1660** **Gales Street** **NE Current**  
**1658 -1660** **Gales Street** **NE Original**

Name(s) Type of Name

**Duplex, 1658-1660 Gales Street, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0825** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1949** **Permit** **Original**  
**Residential (Single-Family)** **D.C. Real** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1949** **Permit**

Construction Event Association Associated Name

**Orig Construction** **Owner** **Cory Construction Company**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Vertical Box/flat front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

**March 2008:** This two-story, three-bay duplex was not positively identified in the District of Columbia building permit database. However, a permit, which lists the building as non-extant, does exist and appears based on map research to incorrectly list the building's condition. Based on this permit (#A-214), this building was constructed in 1949 for the Cory Construction Company. Set on a solid concrete foundation, this masonry structure has a six-course, American-bond brick veneer. The building is capped by a flat roof obscured by a brick parapet with a simple metal coping. Fenestration of the façade (south elevation) consists of a single-leaf, paneled wood door with semi-circular light (replacement) and 1/1, double-hung, vinyl-sash windows with false muntins and header sills. Soldier brick flat arches complete each opening. A door opening, located in the middle bay of the façade, has been partially enclosed with T-111 and a window installed. Fenestration of the east (side) elevation consists of 1/1, double-hung, vinyl-sash windows with false muntins and header sills. The north (rear) elevation has 1/1, double-hung, vinyl-sash windows with false muntins and header sills. Single-leaf, paneled doors with lights are located on the first and second stories. A metal stair provides access to the second story door opening.

Site Notes:

**March 2008:** This detached building is located on a corner lot northwest of the intersection of Gales Street, N.E. and 17th Street, N.E. The building has a setback of approximately fifteen feet (typical) from the concrete sidewalk along Gales Street. The level, grassy lot is enclosed by a chain-link fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component

Material

Color

Treatment

Source

Wall Component

Material

Color

Treatment

Source

Structure Component

Material

Feature

Source

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location

Aperture Shape

Type

Lights

Material

Door Location

Aperture Shape

Type

Panels

Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Capitol Hill - Rosedale

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\

File: 1660\_GalesStNE\_1.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square 4510\GalesStNE\

File: 1660\_GalesStNE\_2.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

09/15/1949	A-214	Build	
------------	-------	-------	--

Permit Notes:

Incorrectly lists building as not extant.

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



# Resource All Data Report

**ID Number: 4510-0064**

## BASICS DATA

ID Number: **4510-0064** Year Built: **ca. 1908** Data Source: **D.C. Real Property**

Number Extended Street Quad Type of Address

**1627 Benning Road NE Current**

Name(s) Type of Name

**Single Dwelling, 1627 Benning Road, N.E. Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0064 Square/Lot Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family) ca. 1908 D.C. Real Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Addition (Rear) ca. 2000 Site Visit/Map**

**Orig Construction ca. 1908 D.C. Real Property**

Construction Event Association Associated Name

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Vertical Box/flat front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

**February 2008:** A building permit for this dwelling could not be positively identified in the District of Columbia's building permit database. However, a permit (#0139) notes that it could be associated with this property, stating, "probably 1627 or 1629". This permit, issued July 7, 1888, lists the building's owner as doctor W.R. Frisby and the builder as George L. Ammon. Conversely, the permit also documents the building as no longer be extant.

This two-story, three-bay single-family dwelling was constructed as a twin in the late nineteenth century. Set on a solid foundation, this wood-frame structure has been clad in vinyl siding. A sloped roof is fronted by a molded cornice with thin dentils and scrolled decorative brackets. Located in the west bay of the façade (north elevation), the main entry holds a single-leaf, wood-frame glass door with a transom blinded by asphalt paper. Window openings contain 1/1, double-hung, vinyl sash with narrow wood sills. All openings have vinyl-clad surrounds topped by vinyl ogee-molded entablatures. A wide band between the first and second story openings is clad in sheet metal, corroborating documentation by the Sanborn Fire Insurance Company of an original full-width porch.

The west (side) elevation is clad in weatherboard siding and has no fenestration.

A two-story concrete-block addition is located on the rear of the main block. Based on its form and materials, this addition dates to ca. 2000. Capped by a shed roof, the west (side) elevation of the addition has no exterior finish. The south (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This dwelling is located on the south side of Benning Road, N.E. and has a setback of approximately thirty feet from the concrete sidewalk. The level, grassy front yard is partially enclosed by a chain-link security fence. A concrete walkway extends off the sidewalk to the main entry. The property extends south to an alley, however, the backyard was not surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA



Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill - Rosedale**

Level(s) of Investigation

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\

File: 1627\_BenningRdNE\_1.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\

File: 1627\_BenningRdNE\_2.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

## BIBLIOGRAPHIC DATA

## **SIGNIFICANCE DATA**

---

Study Unit

---

Code

Criteria

---

## **DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 4510-0065**

## BASICS DATA

ID Number: **4510-0065** Year Built: **ca. 1990** Data Source: **Sanborn Map**

Number Extended Street Quad Type of Address

**1629** **Benning Road** **NE** **Current**

Name(s) Type of Name

**Office Building, 1629 Benning Road, N.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**4510/0065** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Office Building** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Office** **ca. 1990** **Sanborn M** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **ca. 1990** **Permit**

Construction Event Association Associated Name

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Sidewalk Abuts Facade**

Massing: **Vertical Box/flat front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide:

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Modern**

Exterior & Architectural Notes:

**February 2008:** A building permit for this dwelling could not be positively identified in the District of Columbia's building permit database. However, a permit (#0139) notes that it could be associated with this property, stating, "probably 1627 or 1629". This permit, issued July 7, 1888, lists the building's owner as doctor W.R. Frisby and the builder as George L. Ammon. Conversely, the permit also documents the building as no longer extant, which based on current photographs, appears valid.

Based on Sanborn Fire Insurance Company maps, this building appears to have a construction date of ca. 1990. If the original block is extant, it is no longer evident due to alterations and additions. The façade (north elevation) of this concrete-block structure features two brick-veneered skirt walls extending out to front the sidewalk. These walls flank a bank of elongated fixed windows with an arched ceiling. Two single-leaf, metal-frame glass doors provide access to the front of the building. Above the first story openings are large metal signs. The west and east (side) elevations of the building have a brick veneer north of the faces of the adjacent buildings, leaving the bulk of the side elevations with no exterior finish. Fenestration of the west elevation includes a bubble window. The south (rear) elevation was not photographed or surveyed by the volunteer surveyor.

Site Notes:

**February 2008:** This building is located on the south side of Benning Road, N.E. and fronts the concrete sidewalk. The narrow lot extends south to an alley. The backyard was not photographed or surveyed by the volunteer surveyor.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill - Rosedale**

Level(s) of Investigation  
**Permit Research  
Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\Rosedale - 15 to 19th  
St\Database\Pictures\Square  
4510\BenningRdNE\

File: 1629\_BenningRdNE\_1.JPG

Date:: Photog:

Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

