

Resource All Data Report

ID Number: 1058-0079

BASICS DATA

ID Number: **1058-0079** Year Built: **c. 1980** Data Source: **Observation**

Number Extended Street Quad Type of Address

1408 **A Street** **SE Current**

Name(s) Type of Name

Apartment Building, 1408 A Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0079 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multi-Family) **c. 1980** **Site Visit/** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **c. 1980** **Observation**

Construction Event Association Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Freestanding**

Relate to Street: **Front Yard w/ Setback**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **3**

Bays Wide: **5**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

April 2010: Constructed c. 1980, this three-story, five-bay Modern apartment building is of masonry construction. The building is faced with six-course, American-bond brick and is set on a solid foundation. A flat roof caps the building and is pierced by interior brick chimneys on the north and south (side) elevations. The central bay of the façade (west elevation) projects from the façade and is pierced by single-leaf metal-frame glass door with sidelights and a tripartite transom. Additional fenestration on the façade consists of single and paired 1/1, double-hung, vinyl-sash windows, which feature rowlock brick sills. The south and north (side) elevations have fenestration that is consistent with the façade.

Site Notes:

April 2010: This three-story apartment building is located on the north side of A Street, S.E. and is set back approximately ten feet from the brick sidewalk. The building is oriented towards the west. The grassy yard is landscaped with foundation plantings. An alley is located north of the building.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1058\
 File: 26_14th_Street_1408_A_Street_SE_looking_N
 W.JPG
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1058\
 File: 1408_A_Street_SE_side_looking_S.JPG
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1058\
 File: 26_14th_Street_1408_A_Street_SE_looking_S
 W.JPG
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1058\
 File: 1408_A_Street_SE_facade_looking_NW.JPG
 Date:: Photog:
 Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0085

BASICS DATA

ID Number: **1058-0085** Year Built: **1935** Data Source: **Permit**

Number Extended Street Quad Type of Address

1412 **A Street** **SE Current**

Name(s) Type of Name

Apartment Building, 1412 A Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0085 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multi-Family) **1935** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1935** **Permit** **10000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Giles, Lewis W.**

Orig Construction **Builder** **Burns, J.A.**

Orig Construction **Owner** **Burns, J.A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Detached**
Relate to Street: **Face on Setback Line**
Massing: **Block**
Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **38**

Depth/Length: **48**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Garage

Contributing Status

Non-Contributing

Outbuilding Notes:

April 2010: A four-car garage is located north of the building and was constructed c. 1990. The garage is constructed of concrete blocks and is set on a solid concrete block foundation; both are faced with stretcher-bond brick. A sloping roof caps the garage. The façade (north elevation) is pierced

by four vehicular openings; each holds a roll-up paneled metal door. A one-story, two-bay garage is located on the south elevation of the c. 1990 garage and was constructed c. 1980. The garage is constructed of concrete blocks and is set on a solid concrete block foundation; both are faced with stretcher-bond brick. A sloping roof caps the garage. The east elevation is pierced by two openings. The southernmost bay holds a roll-up metal door and the northernmost opening holds a swing-up door of T-111 siding.

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1935 by J.A. Burns, this two-story, three-bay Colonial Revival-style apartment building is of masonry construction. The building is constructed of brick and is faced with six-course, American-bond brick on the façade (south elevation). Set on a solid brick and tile foundation, the dwelling is capped by a sloping roof. A false mansard roof fronts the façade and is covered with metal shingles. Hipped dormers project from the false mansard roof over the end bays of the dwelling. Each dormer has a roof covered with metal shingles and is pierced by a six-light wood window (possibly fixed). A central gable rises from the false mansard roof and has a roof covered with metal shingles. An exterior-rear brick chimney rises from the north elevation and has a parged cap. The central bay of the façade holds a single-leaf paneled metal door with lights. A one-story, one-bay porch shelters the primary entrance and is set on a brick pier foundation that has been infilled with brick. The half-hipped roof of the porch has overhanging eaves and is supported by metal balusters. Poured concrete steps provide access to the porch. The façade is fenestrated with a eight-light wood casement window, paired 6/6, double-hung, wood-sash windows, and tripartite windows composed of a central 6/6, double-hung, wood-sash window and flanking 4/4, double-hung, wood-sash windows. All window openings have concrete sills and soldier brick flat arches. The east and west (side) elevations are fenestrated with 4/4, double-hung, wood-sash windows and single and paired 6/6, double-hung, wood-sash windows. All windows have concrete sills. The rear (north) elevation is pierced by a single-leaf door with lights and 6/6, double-hung, wood-sash windows.

A two-story, full-width garage spans the rear elevation and is wood-frame construction. The porch is capped by a sloping roof that is supported by square wood posts. Square wood balusters encircle the second story of the porch.

Site Notes:

April 2010: This two-story, three-bay apartment building is located on the north side of A Street, S.E. and is set back approximately ten feet from the brick sidewalk. An alley runs parallel to the east (side) elevation of the dwelling. The grassy front and side yards are landscaped with mature shrubs and foundation plantings and are bounded by a metal bow and picket fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is enclosed by a wood fence.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source

Wall Component	Material	Color	Treatment	Source

Structure Component	Material	Feature	Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material

Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s) _____

Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s) _____

Survey(s) _____

Level(s) of Investigation _____

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **1412_A_Street_SE_facade_looking_N.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **1412_A_Street_SE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **1412_A_Street_SE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1412_A_Street_SE_rear_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1412_A_Street_SE_garage_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1412_A_Street_SE_garage_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1412_A_Street_SE_garage_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1412_A_Street_SE_garage_looking_W.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/15/1935	180308	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0804

BASICS DATA

ID Number: **1058-0804** Year Built: **1931** Data Source: **Permit**

Number Extended Street Quad Type of Address

1414 **A Street** **SE Current**

Name(s) Type of Name

Multiple Dwelling, 1414 A Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0804 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multi-Family) **1931** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1931** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Giles, Lewis W.**

Orig Construction **Builder** **Nolan, Thomas W.**

Orig Construction **Owner** **Nolan, Thomas W.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Detached**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Flat Front**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **20**

Depth/Length: **60**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1931 by Thomas W. Nolan, this two-story, two-bay building contained multiple flats. The building is constructed of brick and is faced with six-course, American-bond brick on the façade (south elevation). Set on a solid brick foundation, the building is capped by a sloping roof. A molded architrave spans the façade and is located above the second story soldier brick string course. The easternmost bay of the façade holds double-leaf wood doors with lights, which is topped by a soldier brick flat arch. A metal awning shelters the primary entrance. Additional fenestration on the façade consists of single and paired 1/1, double-hung, vinyl-sash windows. All windows have concrete sills and soldier brick flat arches. The west (side) elevation is pierced by single and paired 1/1, double-hung, vinyl-sash windows and glass block windows. All openings have concrete sills. The rear (north) elevation is fenestrated with single-leaf doors and 1/1, double-hung, vinyl-sash windows.

A two-story, full-width porch spans the rear elevation and is wood-frame construction. The sloping roof of the porch is supported by square wood posts.

Site Notes:

April 2010: This two-story building is located on the north side of A Street, S.E. and is set back approximately ten feet from the brick sidewalk. The east (side) elevation of the dwelling is adjacent to 1416 A Street, S.E. An alley runs parallel to the west (side) elevation of the dwelling. The grassy front yard is landscaped with mature shrubs and foundation plantings and is encircled by a retaining wall topped by a metal bow and picket fence. The grassy rear yard is enclosed by concrete block walls and a metal milled point fence. An alley is located north of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1414_A_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1414_A_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1414_A_Street_SE_rear_looking_S.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

[Empty text box]

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/17/1931	141788	Build	

Permit Notes:

[Empty text box]

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0803

BASICS DATA

ID Number: **1058-0803** Year Built: **c. 1885** Data Source: **Maps**

Number	Extended	Street	Quad	Type of Address
1416		A Street	SE	Current

Name(s)	Type of Name
Single Dwelling, 1416 A Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1058/0803			Square/Lot	Current
1058/0004			Square/Lot	Historic

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	c. 1885	Site Visit/			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Rear Addition	c. 1915	Maps			
Orig Construction	c. 1885	Maps			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Detached**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Flat Front**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**

Height:	Outbuilding Type	Contributing Status
	Garage	Non-Contributing

Width:
Depth/Length:
SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

April 2010: Constructed c. 1990, this one-story, one-bay garage is located north of the dwelling. The garage is constructed of concrete blocks and is set on a solid concrete block foundation. A sloping roof caps the building. The façade (north elevation) is pierced by a roll-up paneled metal door.

STYLE/EXTERIOR DATA

Architectural Style(s)

Vernacular
Italianate

Exterior & Architectural Notes:

April 2010: Constructed c. 1885, this two-story, two-bay vernacular single-family dwelling was influenced by the Italianate style. The dwelling is constructed of brick and is faced with seven-course, American-bond brick on the façade (south elevation). Set on a solid foundation, a sloping roof caps the building. A molded metal cornice and brick corbels highlight the roof. The westernmost bay of the façade holds a single-leaf paneled wood door and a stained glass transom. A soldier brick segmental arch surmounts the transom. The window openings on the façade hold 1/1, double-hung, vinyl-sash. Each window has a vinyl-clad sill and a soldier brick segmental arch. A one-story, full-width porch spans the façade and is set on a solid foundation. The sloping roof of the porch is supported by metal filigree post. Metal balusters finish the porch. The rear (north) elevation is parged. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows.

A one-story addition is located on the rear elevation of the dwelling and was constructed c. 1915. The addition is parged.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the north side of A Street, S.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is sited between 1414 and 1418 A Street, S.E. The grassy front yard is planted with a few mature shrubs and is encircled by metal bow and picket fence. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is enclosed by a concrete block wall. An alley is located north of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1416_A_Street_SE_facade_looking_N.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1416_A_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1416_A_Street_SE_rear_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1416_A_Street_SE_garage_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

The permit for this dwelling was not found.
--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0802

BASICS DATA

ID Number: **1058-0802** Year Built: **1893** Data Source: **Permit**

Number Extended Street Quad Type of Address

1418 **A Street** **SE Current**

Name(s) Type of Name

Single Dwelling, 1418 A Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0802 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1893** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1893** **Permit** **1500 Permit**

Construction Event Association Associated Name

Burns, F.G. **Owner** **Burns, F.G.**

Orig Construction **Builder** **Mandley & Bro.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached (1 side)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **14**

Depth/Length: **35**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type Contributing Status

Garage **Contributing**

Outbuilding Notes:

April 2010: A one-story, one-bay garage is located north of the dwelling and was constructed c. 1940. The wood-frame garage is clad with vinyl siding and is capped by a sloping roof. Double-leaf wood doors pierce the façade (north elevation).

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1893 by William H. Mandley & Brothers, this two-story vernacular single-family dwelling has been altered since its construction. The dwelling is constructed of brick and is set on a solid brick and concrete foundation. A sloping roof caps the dwelling. The easternmost bay of the façade holds a single-leaf paneled wood door with lights. The westernmost bay of the first story holds a tripartite window composed of triple one-light wood casement windows flanked by 2/2, double-hung, wood-sash windows. The second story of the façade is pierced by a single-leaf wood-frame door with jalousie lights and fixed single-light wood windows and one-light wood casement windows. A two-story, full-width porch spans the façade. Brick posts support the second level of the porch, which is capped by a pent roof covered with asphalt shingles. Square wood posts support the pent roof.

A two-story ell extends from the easternmost bay of the rear elevation and is parged. A two-story addition (used as a residence) is located on the rear of the ell and is wood-frame construction. The addition is clad with T-111 siding and is capped by a front-gabled roof. A two-story porch projects from the west (side) elevation of the addition and has a shed roof that is supported by square wood posts. Visible fenestration consists of double-hung sash windows. The first story of the addition was not visible from the public right-of-way.

Site Notes:

April 2010: This two-story single-family dwelling is located on the north side of A Street, S.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 1416 and 1420 A Street, S.E. The grassy front yard is landscaped with mature shrubs and foundation plantings. The yard is bounded by a brick retaining wall topped by a metal milled point fence. The rear yard is enclosed by a fence. An alley is located north of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Pannels Material

Notable Interior Plan(s) Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Ward/ANC:

Zonina: Designation Event(s)

Contributing:
Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1418_A_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1418_A_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1418_A_Street_SE_rear_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1418_A_Street_SE_garage.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/06/1893	1965	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0801

BASICS DATA

ID Number: **1058-0801** Year Built: **1885** Data Source: **Permit**

Number Extended Street Quad Type of Address

1420 **A Street** **SE Current**

Name(s) Type of Name

Single Dwelling, 1420 A Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0801 **Square/Lot** **Current**

1058/0003 **Square/Lot** **Historic**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1885** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1885** **Permit** **275 Permit**

Construction Event Association Associated Name

Burns, Mrs. **Owner** **Burns, Mrs.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached (1 side)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Front Porch**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **16**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type Contributing Status

Shed **Non-Contributing**

Outbuilding Notes:

April 2010: A one-story, one-bay prefabricated shed is located north of the dwelling and was constructed c. 1980. The shed is clad with corrugated metal and is capped by a gambrel roof of corrugated metal.

STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate
Vernacular

Exterior & Architectural Notes:

April 2010: Constructed in 1885 for owner Mrs. Burns, this two-story three-bay vernacular single-family dwelling was influenced by the Italianate style. The dwelling is constructed of brick and is faced with American-bond brick on the façade (south elevation). Set on a solid foundation, the dwelling is capped by a sloping roof. A molded metal cornice with brick corbels complements the roof. The easternmost bay of the façade holds a single-leaf paneled wood door and a stained glass transom. A soldier brick segmental arch surmounts the transom. All window openings on the façade hold 6/6, double-hung, wood-sash and have metal-clad wood sills and soldier brick segmental arches. Louvered shutters flank the window openings. A one-story, full-width porch spans the façade and is set on a brick foundation. The shed roof of the porch is supported by wood posts. Wood balusters complete the porch.

A one-story ell extends from the eastern bay of the rear (north) elevation. A second story addition was constructed on the brick ell and extends the full width of the rear elevation of the main block. The wood-frame addition is clad with German vinyl siding and is capped by a sloping roof. Visible fenestration consists of a single-leaf paneled metal door with lights and 1/1, double-hung, metal-sash window. A second story deck projects from the rear elevation of the addition and is set on square wood posts.

Site Notes:

April 2010: This two-story single-family dwelling is located on the north side of A Street, S.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 1418 A Street, S.E. The landscaped front yard is planted with mature shrubs and foundation plantings and is encircled by a metal bow and picket fence. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard features several brick walkways. An alley is located north of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Pannels Material

Notable Interior Plan(s) Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill Historic District(s)
Subdivision:

Ward/ANC:
Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1420_A_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1420_A_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1420_A_Street_SE_rear_looking_S.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1420_A_Street_SE_shed_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/12/1885	1735.5	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0075

BASICS DATA

ID Number: **1058-0075** Year Built: **1921** Data Source: **Permit**

Number Extended Street Quad Type of Address

1422 **A Street** **SE Current**

Name(s) Type of Name

Single Dwelling, 1422 A Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0075 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1921** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1921** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Speiden & Speiden**

Orig Construction **Builder** **Kenyon, J. T.**

Orig Construction **Owner** **Kenyon, J. T.**

Construction Notes:

One of two dwellings constructed from the same permit (#3541).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached (1 side)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1921 by J.T. Kenyon, this two-story, three-bay Classical Revival-style single-family dwelling is one of two dwellings constructed from the same permit (#3541). The dwelling is constructed of brick and the façade (south elevation) is faced with five-course, American-bond brick. Set on a solid concrete foundation, a sloping roof caps the dwelling. A molded metal architrave complements the roof and features egg and dart molding. An interior-side brick chimney rises from the west (side) elevation of the dwelling and has been parged. The easternmost bay of the façade holds a single-leaf multi-light wood door. The window openings on the façade hold 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins. All windows have concrete sills and soldier brick flat arches. A one-story, full-width porch spans the façade and is set on a brick pier foundation that has been infilled with a single-leaf paneled metal door with lights and a 1/1, double-hung, vinyl-sash window. The flat roof of the porch has overhanging eaves and is supported by brick posts set on brick piers. Square wood balusters encircle the porch, which is accessed via poured concrete with brick wing walls in the easternmost end bay. The rear (north) elevation is pierced by 1/1, double-hung, vinyl-sash windows, which have two-course, rowlock brick segmental arches.

A two-story brick ell extends from the easternmost bay of the rear elevation and is capped by a sloping roof. An enclosed porch extends from the rear elevation of the ell and is clad with German vinyl siding. Visible fenestration consist of a single-leaf paneled door with lights, a 1/1, double-hung, vinyl-sash window, and 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins.

A one-story, full-width screened porch extends from the rear elevation of the ell and was constructed c. 1995. The wood-frame porch is capped by a shed roof of asphalt shingles.

Site Notes:

April 2010: This two-story single-family dwelling is located on the north side of A Street, S.E. and is set back approximately ten feet from the brick sidewalk. The east (side) elevation of the dwelling is adjacent to 1424 A Street, S.E. The landscaped front yard is planted with mature shrubs and is bounded by a low, stone retaining wall. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is enclosed by a wood fence. An alley is located north of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s) _____
Subdivision: _____
Ward/ANC: _____
Zoning: Designation Event(s) _____
Contributing: _____
Survey(s) Level(s) of Investigation _____
Capitol Hill Southeast Phase II (2010) **Permit Research**
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1422_A_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1422_A_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1422_A_Street_SE_rear_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
11/03/1921	3541	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0074

BASICS DATA

ID Number: **1058-0074** Year Built: **1921** Data Source: **Permit**

Number Extended Street Quad Type of Address

1424 **A Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1424 A Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0074 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1921** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1921** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Speiden & Speiden**

Orig Construction **Builder** **Kenyon, J. T.**

Orig Construction **Owner** **Kenyon, J. T.**

Construction Notes:

One of two rowhouses constructed from the same permit (#3541).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **17**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1921 by J.T. Kenyon, this two-story, three-bay Classical Revival-style single-family dwelling is one of two dwellings constructed from the same permit (#3541). The dwelling is constructed of brick and the façade (south elevation) is faced with five-course, American-bond brick. Set on a solid concrete foundation, a sloping roof caps the dwelling. A molded metal architrave complements the roof and features egg and dart molding. The westernmost bay of the façade holds a single-leaf paneled wood door. The window openings on the façade hold 6/6, double-hung, wood-sash windows. All windows have wood sills and soldier brick flat arches. The foundation is pierced by a 6/6, double-hung, wood-sash window and a single-leaf door. A one-story, full-width porch spans the façade and is set on a brick pier foundation. The flat roof of the porch has overhanging eaves and is supported by brick posts set on brick piers. Metal balusters encircle the porch, which is accessed via poured concrete with brick wing walls in the westernmost end bay. The rear (north) elevation is pierced by 6/1, double-hung, wood-sash windows, which have two-course, rowlock brick segmental arches.

A two-story brick ell extends from the westernmost bay of the rear elevation and is capped by a sloping roof. An enclosed porch extends from the rear elevation of the ell and is clad with aluminum siding. Visible fenestration consist of a single-leaf wood door with lights and a single-light transom and 4/1, double-hung, wood-sash windows.

Site Notes:

April 2010: This two-story single-family dwelling is located on the north side of A Street, S.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 1422 and 1428 A Street, S.E. The landscaped front yard is planted with mature shrubs and plantings and is bounded by a stone retaining wall. Poured concrete steps lead from the primary entrance of the dwelling and end at the sidewalk. The rear yard features mature shrubs and plants and is bounded by a wood fence. An alley is located north of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:
Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1424_A_Street_SE_facade_looking_N.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1424_A_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1424_A_Street_SE_rear_looking_S.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
11/03/1921	3541	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0077

BASICS DATA

ID Number: **1058-0077** Year Built: **1930** Data Source: **Permit**

Number Extended Street Quad Type of Address

1428 **A Street** **SE Current**

Name(s) Type of Name

Multiple Dwelling, 1428 A Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0077 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multi-Family) **1930** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1930** **Permit** **6000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Hill, Bishop**

Orig Construction **Builder** **Hill Co.**

Orig Construction **Owner** **Hill, William A.**

Construction Notes:

One of two buildings constructed from the same permit (#137704).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Flat Front**
Footprint: **T-Shaped**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **5**

Height:

Width: **27**

Depth/Length: **54**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type

Shed

Contributing Status

Non-Contributing

Outbuilding Notes:

April 2010: A one-story, one-bay shed is located north of the dwelling and was constructed c. 2000. The shed is clad with standing-seam metal and is capped by a front-gabled roof; also of standing-seam metal.

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

April 2010: Constructed in 1930 by William A. Hill & Company, this two-story, four-bay Modern multiple dwelling is one of two buildings constructed from the same permit (#137704). The dwelling is constructed of brick and is faced with six-course, American-bond brick on the façade (south elevation). Set on a solid brick foundation, the dwelling is capped by a sloping roof that is finished with coping. The central bay holds a single-leaf paneled wood door with lights. The door is flanked by 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins. These three openings are topped by a soldier brick flat arch and have a brick surround that projects from the façade. An ornamental brick panel, composed of chevrons, is located above the door opening. All other window openings on the façade hold 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins. All windows have rowlock brick sills and soldier brick flat arches. The rear (north) elevation is pierced by 1/1, double-hung, vinyl-sash windows, which feature concrete sills and two-course, rowlock brick segmental arches.

A two-story wing extends from center of the rear elevation and is constructed of brick. A sloping roof caps the wing. Visible fenestration consists of a single-leaf wood door, three single-leaf paneled wood doors with lights, and 1/1, double-hung, vinyl-sash windows. All doors are topped by one-light transoms and all openings have two-course, rowlock brick segmental arches. A two-story, full-width porch extends from the rear elevation of the wing. The sloping roof is supported by square wood posts. Wood steps provide access to the second story of the porch.

Site Notes:

April 2010: This two-story multiple dwelling is located on the north side of A Street, S.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 1424 and 1430 A Street, S.E. The grassy front yard features mature shrubs and is bounded by a metal chain-link fence. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is grassy and features mature shrubs. A metal chain-link fence encloses the rear yard. An alley is located north of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **1428_A_Street_SE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **1428_A_Street_SE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **1428_A_Street_SE_rear_looking_S.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0076

BASICS DATA

ID Number: **1058-0076** Year Built: **1930** Data Source: **Permit**

Number Extended Street Quad Type of Address

1430 **A Street** **SE Current**

Name(s) Type of Name

Multiple Dwelling, 1430 A Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0076 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multi-Family) **1930** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1930** **Permit** **6000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Hill, Bishop**

Orig Construction **Builder** **Hill Co.**

Orig Construction **Owner** **Hill, William A.**

Construction Notes:

One of two buildings constructed from the same permit (#137704).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **T-Shaped**

Number Stories: **2**

Bays Wide: **5**

Height:

Width: **27**

Depth/Length: **54**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

April 2010: Constructed in 1930 by William A. Hill & Company, this two-story, five-bay Modern multiple dwelling is one of two buildings constructed from the same permit (#137704). The dwelling is constructed of brick and is faced with six-course, American-bond brick on the façade (south elevation). Set on a solid brick foundation, the dwelling is capped by a sloping roof that is finished with coping. The central bay holds a single-leaf paneled wood door with lights. The door is flanked by 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins. These three openings are topped by a soldier brick flat arch and have a brick surround that projects from the façade. An ornamental brick panel, composed of chevrons, is located above the door opening. All other window openings on the façade hold 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins. All windows have rowlock brick sills and soldier brick flat arches. The rear (north) elevation is pierced by 1/1, double-hung, vinyl-sash windows, which feature concrete sills and two-course, rowlock brick segmental arches.

A two-story wing extends from center of the rear elevation and is constructed of brick. A sloping roof caps the wing. Visible fenestration consists of four single-leaf paneled wood doors and 1/1, double-hung, vinyl-sash windows. All doors are topped by one-light transoms and all openings have two-course, rowlock brick segmental arches. A two-story, full-width porch extends from the rear elevation of the wing. The sloping roof is supported by square wood posts. Wood steps provide access to the second story of the porch.

Site Notes:

April 2010: This two-story multiple dwelling is located on the north side of A Street, S.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 1428 and 1432 A Street, S.E. The grassy front yard is landscaped with mature shrubs and trees and is enclosed by a metal chain-link fence. A walkway leads from the primary entrance of the building and ends at the sidewalk. The rear yard is also landscaped with mature shrubs and trees and is enclosed by a fence.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **1430_A_Street_SE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **1430_A_Street_SE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **1430_A_Street_SE_rear_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0061

BASICS DATA

ID Number: **1058-0061** Year Built: **1912** Data Source: **Permit**

Number Extended Street Quad Type of Address

1432 **A Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1432 A Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0061 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1912** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1912** **Permit** **2500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Hunter & Bell**

Orig Construction **Builder** **Forbes & Nalley**

Orig Construction **Owner** **Townshend, Aaron R.**

Construction Notes:

One of three rowhouses constructed from the same permit (#3477).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 3)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1912 by Forbes & Nalley, this two-story, three-bay Classical Revival-style single-family dwelling is one of three similar dwellings constructed from the same permit (#3477). The dwelling is constructed of brick and is faced with five-course, American-bond brick on the façade (south elevation). A brick string course spans the façade and is sited above the second story openings. Set on a solid concrete foundation, the dwelling is capped by a sloping roof. A molded wood cornice finishes the roof. The westernmost bay of the façade holds a single-leaf paneled metal door with lights and a single-light transom. A two-course, rowlock brick segmental arch surmounts the transom. All first and second story window openings hold 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins and feature concrete sills and two-course, rowlock brick sills with keystones. The foundation of the façade is pierced by a single-leaf paneled metal door with lights and a single-light fixed wood window. Both openings have two-course, rowlock brick segmental arches. The rear (north) elevation is fenestrated with 6/6, double-hung, wood-sash windows, which have two-course, rowlock brick segmental arches.

Site Notes:

April 2010: This two-story single-family dwelling is located on the north side of A Street, S.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 1430 and 1434 A Street, S.E. The front yard features ornamental plantings of mature shrubs and small trees. A stone retaining wall topped by a metal milled point fence encircles the front yard.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**
File: **1432_A_Street_SE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**
File: **1432_A_Street_SE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
02/08/1912	3477	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0060

BASICS DATA

ID Number: **1058-0060** Year Built: **1912** Data Source: **Permit**

Number Extended Street Quad Type of Address

1434 **A Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1434 A Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0060 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1912** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1912** **Permit** **2500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Hunter & Bell**

Orig Construction **Builder** **Forbes & Nalley**

Orig Construction **Owner** **Townshend, Aaron R.**

Construction Notes:

One of three rowhouses constructed from the same permit (#3477).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 3)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Flat Front**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1912 by Forbes & Nalley, this two-story, three-bay Classical Revival-style single-family dwelling is one of three similar dwellings constructed from the same permit (#3477). The dwelling is constructed of brick and is faced with five-course, American-bond brick on the façade (south elevation). A brick string course spans the façade and is sited above the second story openings. Set on a solid concrete foundation, the dwelling is capped by a sloping roof. A molded metal cornice finishes the roof. The westernmost bay of the façade holds a single-leaf paneled wood door and a single-light transom. A two-course, rowlock brick segmental arch surmounts the transom. Brick steps with metal hand rails provide access to the primary entrance. The façade is fenestrated with 6/1 and 6/6, double-hung, wood-sash windows and feature concrete sills. The first story windows have two-course, rowlock brick segmental arches and the second story windows have concrete lintels. The foundation of the façade is pierced by a single-leaf paneled wood door and a 1/1, double-hung, wood-sash window. Both openings have two-course, rowlock brick segmental arches. The rear (north) elevation was not visible from the public right-of-way.

Site Notes:

April 2010: This two-story single-family dwelling is located on the north side of A Street, S.E. and is set back approximately ten feet from the brick sidewalk. The dwelling is adjacent to 1432 and 1436 A Street, S.E. The front yard is landscaped with mature shrubs and foundation plantings and is bounded by a brick retaining wall. A brick walkway leads from the sidewalk and ends at the front door.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 1434_A_Street_SE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 1434_A_Street_SE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
02/08/1912	3477	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0059

BASICS DATA

ID Number: **1058-0059** Year Built: **1912** Data Source: **Permit**

Number Extended Street Quad Type of Address

1436 **A Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1436 A Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0059 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multifamily/Misc) **1912** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1912** **Permit** **2500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Hunter & Bell**

Orig Construction **Builder** **Forbes & Nalley**

Orig Construction **Owner** **Townshend, Aaron R.**

Construction Notes:

One of three rowhouses constructed from the same permit (#3477).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 3)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1912 by Forbes & Nalley, this two-story, three-bay Classical Revival-style single-family dwelling is one of three similar dwellings constructed from the same permit (#3477). The dwelling is constructed of brick and is faced with five-course, American-bond brick on the façade (south elevation). A brick string course spans the façade and east (side) elevations and is sited above the second story openings. Set on a solid concrete foundation, the dwelling is capped by a sloping roof. A molded metal cornice finishes the roof. The westernmost bay of the façade holds a single-leaf paneled wood door and a single-light transom. A two-course, rowlock brick segmental arch surmounts the transom. Brick steps with metal hand rails provide access to the primary entrance. The façade is fenestrated with 6/6, double-hung, wood-sash windows and feature concrete sills. All windows (except the first story of the central bay) have concrete jack arches. The central bay of the first story has a two-course, rowlock brick segmental arch. The foundation of the façade is pierced by 1/1, double-hung, vinyl-sash windows. Both openings have two-course, rowlock brick segmental arches. The east (side) elevation is fenestrated with 6/6, double-hung, wood-sash windows and 1/1, double-hung, vinyl-sash windows. A two-story rectangular bay projects from the east elevation and has a material treatment consistent with the façade. Fenestration is also consistent with the façade. Several openings have been infilled with brick. The rear (north) elevation is pierced by double-leaf doors, a 6/6, double-hung, wood-sash window, and a 1/1, double-hung, vinyl-sash window.

Site Notes:

April 2010: This two-story single-family dwelling is located on the northwest corner of A Street, S.E. and 15th Street, S.E. and is set back approximately ten feet from the brick sidewalk. The west (side) elevation of the dwelling is adjacent to 1434 A Street, S.E. The grassy front yard is landscaped with mature trees and shrubs and is bounded by a metal milled point fence. The rear yard is obscured by a wood fence.

NOTABLE FEATURES DATA

Component _____ Feature _____

EXTERIOR MATERIALS DATA

Roof Component _____ Material _____ Color _____ Treatment _____ Source _____

Wall Component _____ Material _____ Color _____ Treatment _____ Source _____

Structure Component _____ Material _____ Feature _____ Source _____

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location _____ Aperture Shape _____ Type _____ Lights _____ Material _____

Door Location _____ Aperture Shape _____ Type _____ Panels _____ Material _____

Notable Interior Plan(s) _____

Notable Interior Feature(s) _____

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\

File: 1436_A_Street_SE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\

File: 1436_A_Street_SE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\

File: 1436_A_Street_SE_rear_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\

File: 1436_A_Street_SE_side_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 1436_A_Street_SE_rear_looking_WSW.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
02/08/1912	3477	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0058

BASICS DATA

ID Number: **1058-0058** Year Built: **1912** Data Source: **Permit**

Number Extended Street Quad Type of Address

27 **15th Street** **SE Current**

Name(s) Type of Name

Single Dwelling, 27 15th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0058 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1912** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1912** **Permit** **2500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Hunter & Bell**

Orig Construction **Builder** **Forbes & Nalley**

Orig Construction **Owner** **Townsend, Aaron R.**

Construction Notes:

One of two dwellings constructed from the same permit (#3476).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached (1 side)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Row Building/Flat Front**
Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **15**

Depth/Length: **20**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1912 by Forbes & Nalley, this two-story, three-bay Classical Revival-style single-family dwelling is one of two dwellings constructed from the same permit (#3476). The dwelling is constructed of brick and is faced with five-course, American-bond brick on the façade (east elevation). A brick string course spans the façade and is located above the second story window openings. Set on a solid concrete foundation, the dwelling is capped by a sloping roof. A molded metal cornice finishes the roof. The foundation of the façade is pierced by two single-leaf paneled wood doors with lights, which are flanked by 2/2, double-hung, wood-sash windows. The façade is fenestrated with 6/6, double-hung, wood-sash windows, which feature concrete sills and lintels.

A two-story brick ell extends from the northernmost bay of the rear elevation of the dwelling. A sloping roof caps the ell. An interior brick chimney rises from the southwest corner of the ell. Visible fenestration consists of 6/6, double-hung, wood-sash windows and a single-leaf door. Two-course, rowlock brick segmental arches top each opening.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the west side of 15th Street, S.E. and is set back approximately twenty feet from the brick sidewalk. The north (side) elevation of the dwelling is adjacent to 25 15th Street, S.E. The grassy front yard is landscaped with mature shrubs and is bisected by a brick walkway. The rear yard is enclosed with a metal chain-link fence.

NOTABLE FEATURES DATA

Component _____ Feature _____

EXTERIOR MATERIALS DATA

Roof Component _____ Material _____ Color _____ Treatment _____ Source _____

Wall Component _____ Material _____ Color _____ Treatment _____ Source _____

Structure Component _____ Material _____ Feature _____ Source _____

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location _____ Aperture Shape _____ Type _____ Lights _____ Material _____

Door Location _____ Aperture Shape _____ Type _____ Pannels _____ Material _____

Notable Interior Plan(s) _____

Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s) _____

Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 27_15th_Street_SE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 27_15th_Street_SE_facade_looking_SW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 27_15th_Street_SE_rear_looking_SE.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
02/08/1912	3476	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0057

BASICS DATA

ID Number: **1058-0057** Year Built: **1912** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
25		15th Street	SE	Current

Name(s)	Type of Name
Single Dwelling, 25 15th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1058/0057			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1912	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1912	Permit			2500 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Hunter & Bell
Orig Construction	Builder	Forbes & Nalley
Orig Construction	Owner	Townsend, Aaron R.

Construction Notes:

One of two dwellings constructed from the same permit (#3476).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Front Yard w/ Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **15**

Depth/Length: **20**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type	Contributing Status
------------------	---------------------

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1912 by Forbes & Nalley, this two-story, three-bay Classical Revival-style single-family dwelling is one of two dwellings constructed from the same permit (#3476). The dwelling is constructed of brick and is faced with five-course, American-bond brick on the façade (east elevation). A brick string course spans the façade and is located above the second story window openings. Set on a solid concrete foundation, the dwelling is capped by a sloping roof. A molded metal cornice finishes the roof. The southernmost bay of the façade holds a single-leaf paneled wood door. The original transom has been infilled with brick. The window openings on the façade hold 1/1, double-hung, vinyl-sash windows, which feature concrete sills and concrete jack arches. The foundation is pierced by a one-light fixed vinyl window. A one-story, one-bay porch shelters the primary entrance of the dwelling and is set on a brick pier foundation that is infilled with decorative concrete blocks. The flat roof of the porch has overhanging eaves and is supported by metal filigree posts. Metal balusters encircle the porch, which is accessed via steps in the southern end bay.

A two-story brick ell extends from the southernmost bay of the rear elevation of the dwelling. A sloping roof caps the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows. Two-course, rowlock brick segmental arches top each opening.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the west side of 15th Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 23 and 27 15th Street, S.E. The grassy front yard is landscaped with foundation plantings and is bounded by a brick retaining wall topped by a metal milled point fence. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is obscured by fencing.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source

Wall Component	Material	Color	Treatment	Source

Structure Component	Material	Feature	Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material

Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:
Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\

File: 25_15th_Street_SE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\

File: 25_15th_Street_SE_facade_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\

File: 25_15th_Street_SE_rear_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
02/08/1912	3476	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0056

BASICS DATA

ID Number: **1058-0056** Year Built: **1909** Data Source: **Permit**

Number Extended Street Quad Type of Address

23 **15th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 23 15th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0056 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1909** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1909** **Permit** **2500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Lewis, John H.**

Orig Construction **Builder** **Lewis, John H.**

Talbert, G.W. **Owner** **Talbert, G.W.**

Construction Notes:

One of three rowhouses constructed from the same permit (#2782).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 3)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Front Porch**
Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1909 by John H. Lewis, this two-story, three-bay Classical Revival-style single-family dwelling is one of three similar dwellings constructed from the same permit (#2782). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (east elevation) is faced with five-course, American-bond brick. Brick string courses span the façade and are located below and above the second story window openings. A sloping roof caps the dwelling and is highlighted by a molded metal cornice. An exterior brick chimney rises from the rear (west) elevation and has a parged cap. The northernmost bay of the façade holds a single-leaf paneled wood door with lights and a single-light wood transom. Other openings on the façade hold 1/1, double-hung, vinyl-sash windows, which feature concrete sills and lintels. A one-story, two-bay porch extends from the façade and is set on a brick pier foundation that has been infilled with vertical wood boards. The flat roof of the porch has overhanging eaves with dentils and is supported by metal filigree posts. Metal balusters encircle the porch, which is accessed via poured concrete steps in the northern end bay.

A two-story, full-width addition is located on the rear (west) elevation of the dwelling and was constructed c. 2005. The wood-frame addition is clad with German vinyl siding and is capped by a sloping roof. Visible fenestration consists of double-leaf wood-frame glass doors (topped by a single-light transom) and 1/1, double-hung, vinyl-sash windows.

Site Notes:

April 2010: This two-story single-family dwelling is located on the west side of 15th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 21 and 25 15th Street, S.E. The small front yard is landscaped with mature shrubs and foundation plantings. The rear yard is enclosed by a wood fence.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Designation Level(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 23_15th_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 23_15th_Street_SE_facade_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 23_15th_Street_SE_rear_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/26/1909	2782	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0055

BASICS DATA

ID Number: **1058-0055** Year Built: **1909** Data Source: **Permit**

Number Extended Street Quad Type of Address

21 **15th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 21 15th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0055 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1909** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1909** **Permit** **2500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Lewis, John H.**

Orig Construction **Builder** **Lewis, John H.**

Orig Construction **Owner** **Talbert, G.W.**

Construction Notes:

One of three rowhouses constructed from the same permit (#2782).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 3)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Front Porch**
Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Garage

Contributing Status

Non-Contributing

Outbuilding Notes:

April 2010: Constructed c. 1990, this one-story, one-bay garage is located west of the dwelling. The garage is clad with corrugated metal and is capped by a sloping roof; also covered with corrugated metal. The façade (west elevation) is pierced by a roll-up paneled metal door.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1909 by John H. Lewis, this two-story, three-bay Classical Revival-style single-family dwelling is one of three similar dwellings constructed from the same permit (#2782). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (east elevation) is faced with five-course, American-bond brick. Brick string courses span the façade and are located below and above the second story window openings. A sloping roof caps the dwelling and is highlighted by a molded metal cornice. An exterior brick chimney rises from the rear (west) elevation and has a parged cap. The northernmost bay of the façade holds a replacement single-leaf paneled wood door with lights and a single-light wood transom and sidelight. Other openings on the façade hold 1/1, double-hung, vinyl-sash windows, which feature concrete sills and lintels. The foundation of the façade features a single-leaf paneled wood door with lights and a projecting oriel window. The oriel is capped by a shed roof and is fenestrated with one-light vinyl casement windows. A one-story, one-bay porch shelters the primary entrance and is set on a brick pier foundation. The shed roof of the porch is covered with asphalt shingles and is supported by metal filigree posts. Metal balusters encircle the porch, which is accessed via stone steps. The rear (west) elevation features a two-story integrated porch in the southern bay. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and single-leaf doors. All openings have two-course, rowlock brick sills.

Site Notes:

April 2010: This two-story single-family dwelling is located on the west side of 15th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 19 and 23 15th Street, S.E. The small front yard features planters and is bounded by a brick retaining wall. The rear yard is bounded by a wood fence. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning: Designation Event(s)
 Contributing: _____
 Survey(s) Level(s) of Investigation
Capitol Hill Southeast Phase II (2010) **Permit Research**
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1058\
 File: 21_15th_Street_SE_facade_looking_NW.JPG
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1058\
 File: 21_15thStreet_SE_facade_looking_SW.JPG
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1058\
 File: 21_15th_Street_SE_garage_looking_E.JPG
 Date:: Photog:
 Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/26/1909	2782	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0054

BASICS DATA

ID Number: **1058-0054** Year Built: **1909** Data Source: **Permit**

Number Extended Street Quad Type of Address

19 **15th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 19 15th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0054 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **2782** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1909** **Permit** **2500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Lewis, John H.**

Orig Construction **Builder** **Lewis, John H.**

Orig Construction **Owner** **Talbert, G.W.**

Construction Notes:

One of three rowhouses constructed from the same permit (#2782).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 3)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Front Porch**
Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1909 by John H. Lewis, this two-story, three-bay Classical Revival-style single-family dwelling is one of three similar dwellings constructed from the same permit (#2782). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (east elevation) is faced with Permastone. A sloping roof caps the dwelling and is highlighted by a molded metal cornice. An exterior brick chimney rises from the rear (west) elevation and has a parged cap. The northernmost bay of the façade holds double-leaf wood-frame glass doors and a single-light wood transom and sidelight. Other openings on the façade hold 1/1, double-hung, vinyl-sash windows. The foundation of the façade features a single-leaf wood-frame glass door. A one-story, one-bay porch shelters the primary entrance and central bay of the facade and is set on a brick pier foundation that has been infilled with glass blocks. The flat roof of the porch has overhanging eaves and is supported by brick posts set on brick piers. Metal balusters encircle the porch, which is accessed via poured concrete steps in the northern end bay.

A two-story addition with a contemporaneous one-story wing is located on the rear (west) elevation of the dwelling. The addition is parged and each section has a sloping roof. Visible fenestration consists of double-leaf wood-frame doors with single-light transoms and 1/1, double-hung, vinyl-sash windows. A wood deck extends from the rear elevation of the one-story wing.

Site Notes:

April 2010: This two-story single-family dwelling is located on the west side of 15th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 17 and 21 15th Street, S.E. The grassy front yard is bounded by a stone retaining wall. A concrete walkway leads to a basement level entrance. The rear yard is enclosed by a wood fence. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:
Contributing:

Designation Event(s) _____

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 19_15th_Street_SE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 19_15th_Street_SE_facade_looking_SW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 19_15th_Street_SE_rear_looking_SE.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/26/1909	2782	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0049

BASICS DATA

ID Number: **1058-0049** Year Built: **1896** Data Source: **Permit**

Number Extended Street Quad Type of Address

17 **15th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 17 15th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0049 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1896** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1896** **Permit** **1600 Permit**

Construction Event Association Associated Name

Caldwell & Miller **Owner** **Caldwell & Miller**

Orig Construction **Builder** **Caldwell, M.P.**

Construction Notes:

One of four rowhouses constructed from the same permit (#0724).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

April 2010: Constructed in 1896 by M.P. Caldwell, this two-story, two-bay Queen Anne-style single-family dwelling is one of four similar dwellings constructed from the same permit (#0724). The dwelling is constructed of brick and is set on a solid brick foundation; the façade (east elevation) is faced with seven-course, American-bond brick. Brick string courses span the façade and are located below the first and second story openings and above the second story openings. A sloping roof caps the dwelling and is highlighted by a molded metal cornice with brick corbels and dentils. The northernmost bay of the façade holds a single-leaf paneled wood door with a single-light wood transom. A three-course, rowlock brick segmental arch surmounts the transom. The southernmost bay holds a bowed oriel window, which is supported by brackets. A half-hipped roof of standing-seam metal caps the window and is covered with standing-seam metal. The oriel is composed of one-light vinyl casement windows. The second story openings hold 1/1, double-hung, vinyl-sash windows and have concrete sills and three-course, rowlock brick segmental arches. The rear (west) elevation is parged and is pierced by 1/1, double-hung, vinyl-sash windows, which have rowlock brick sills.

A two-story ell extends from the northernmost bay of the rear elevation and is parged. A sloping roof caps the ell. Two interior-side parged chimneys rise from the north (side) elevation. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows.

Site Notes:

April 2010: This two-story single-family dwelling is located on the west side of 15th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 15 and 19 15th Street, S.E. The grassy front yard is landscaped with mature shrubs and foundation plantings and is bounded by a metal milled point fence. A concrete walkway leads from the primary entrance and leads to the sidewalk. The rear yard is obscured by wood fencing. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:
Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 17_15th_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 17_15th_Street_SE_facade_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 17_15th_Street_SE_rear_looking_E.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/08/1896	0724	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0048

BASICS DATA

ID Number: **1058-0048** Year Built: **1896** Data Source: **Permit**

Number Extended Street Quad Type of Address

15 **15th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 15 15th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0048 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1896** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1896** **Permit** **1600 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Caldwell, M.P.**

Orig Construction **Owner** **Caldwell & Miller**

Construction Notes:

One of four rowhouses constructed from the same permit (#0724).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

April 2010: Constructed in 1896 by M.P. Caldwell, this two-story, two-bay Queen Anne-style single-family dwelling is one of four similar dwellings constructed from the same permit (#0724). The dwelling is constructed of brick and is set on a solid brick foundation; the façade (east elevation) is faced with seven-course, American-bond brick. Brick string courses span the façade and are located below the first and second story openings and above the second story openings. A sloping roof caps the dwelling and is highlighted by a molded metal cornice with brick corbels and dentils. The central bay of the façade holds double-leaf wood doors. The window openings on the façade hold one-light wood casement windows, which have concrete sills.

A two-story brick ell extends from the southernmost bay of the rear elevation. A sloping roof caps the ell. An interior brick chimney rises from the northwest corner of the ell. Visible fenestration consists of a single-leaf door and 6/6, double-hung, wood-sash windows, which feature rowlock brick sills.

Site Notes:

April 2010: This two-story single-family dwelling is located on the west side of 15th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 13 and 17 15th Street, S.E. The front yard is landscaped with mature shrubs and foundation plantings and is encircled by a metal milled point fence. A concrete walkway leads from the primary entrance and ends at the sidewalk. The rear yard is enclosed by a wood fence. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component _____ Feature _____

EXTERIOR MATERIALS DATA

Roof Component _____ Material _____ Color _____ Treatment _____ Source _____

Wall Component _____ Material _____ Color _____ Treatment _____ Source _____

Structure Component _____ Material _____ Feature _____ Source _____

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location _____ Aperture Shape _____ Type _____ Lights _____ Material _____

Door Location _____ Aperture Shape _____ Type _____ Panels _____ Material _____

Notable Interior Plan(s) _____

Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s) _____

Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 15_15th_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 15_15th_Street_SE_facade_looking_W.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 15_15th_Street_SE_rear_looking_E.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/08/1896	0724	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0047

BASICS DATA

ID Number: **1058-0047** Year Built: **1896** Data Source: **Permit**

Number Extended Street Quad Type of Address

13 **15th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 13 15th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0047 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1896** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1896** **Permit** **1600 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Caldwell, M.P.**

Orig Construction **Owner** **Caldwell & Miller**

Construction Notes:

One of four rowhouses constructed from the same permit (#0724).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

April 2010: Constructed in 1896 by M.P. Caldwell, this two-story, two-bay Queen Anne-style single-family dwelling is one of four similar dwellings constructed from the same permit (#0724). The dwelling is constructed of brick and is set on a solid brick foundation; the façade (east elevation) is faced with seven-course, American-bond brick. Brick string courses span the façade and are located below the first and second story openings and above the second story openings. A sloping roof caps the dwelling and is highlighted by a molded metal cornice with brick corbels and dentils. The northernmost bay of the façade holds a single-leaf paneled wood door. The original transom has been infilled with brick, however, the three-course, rowlock brick segmental arch remains. A one-story projecting bay extends from the southernmost bay of the first story. The bay is constructed of brick and is fenestrated with triple 1/1, double-hung, wood-sash windows. A flat roof caps the bay and extends across the façade and shelters the primary entrance. The second story openings have 1/1, double-hung, wood-sash windows with concrete sills and three-course, rowlock brick segmental arches. The rear (west) elevation is pierced by 1/1, double-hung, vinyl-sash windows and have two-course, rowlock brick segmental arches.

A two-story brick ell extends from the northernmost bay of the rear elevation. A sloping roof caps the ell. An interior brick chimney rises from the southwest corner of the ell. A two-story enclosed porch extends from the rear elevation of the ell and is wood-frame construction clad with aluminum siding. A sloping roof caps the enclosed porch. Visible fenestration consists of 1/1, double-hung, wood-sash windows.

Site Notes:

April 2010: This two-story single-family dwelling is located on the west side of 15th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 11 and 15 15th Street, S.E. A pebble walkway leads from the primary entrance of the dwelling and ends at the sidewalk. A metal milled point fence encircles the front yard. The rear yard is bounded by a wood fence. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **13_15th_Street_SE_facade_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **13_15th_Street_SE_facade_looking_W.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **13_15th_Street_SE_rear_looking_E.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0046

BASICS DATA

ID Number: **1058-0046** Year Built: **1896** Data Source: **Permit**

Number Extended Street Quad Type of Address

11 **15th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 11 15th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0046 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1896** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1896** **Permit** **1600 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Caldwell, M.P.**

Orig Construction **Owner** **Caldwell & Miller**

Construction Notes:

One of four rowhouses constructed from the same permit (#0724).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

April 2010: Constructed in 1896 by M.P. Caldwell, this two-story, two-bay Queen Anne-style single-family dwelling is one of four similar dwellings constructed from the same permit (#0724). The dwelling is constructed of brick and is set on a solid brick foundation; the façade (east elevation) is faced with seven-course, American-bond brick. Brick string courses span the façade and are located below the first and second story openings and above the second story openings. A sloping roof caps the dwelling and is highlighted by a molded metal cornice with brick corbels and dentils. The southernmost bay of the façade holds a single-leaf wood-frame glass door with a three-course, rowlock brick segmental arch. A one-story projecting bay extends from the northernmost bay of the first story. The bay is constructed of brick and is fenestrated with a one-light fixed wood window. A flat roof caps the bay and extends across the façade and shelters the primary entrance. The second story openings have 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A two-story parged brick ell extends from the southernmost bay of the rear elevation. A sloping roof caps the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows, which have rowlock brick sills.

Site Notes:

April 2010: This two-story single-family dwelling is located on the west side of 15th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 7 and 13 15th Street, S.E. The front yard laid with stone and is landscaped with mature shrubs and foundation plantings and is encircled by a brick retaining wall topped by a metal milled point fence. The rear yard is enclosed by a wood fence. An alley is located west of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Pannels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Contributing.

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**
File: **11_15th_Street_SE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**
File: **11_15th_Street_SE_facade_looking_SW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**
File: **11_15th_Street_SE_rear_looking_E.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/08/1896	0724	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0053

BASICS DATA

ID Number: **1058-0053** Year Built: **1901** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
7		15th Street	SE	Current

Name(s)	Type of Name
Multiple Dwelling, 7 15th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1058/0053			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Multi-Family)	1901	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1901	Permit			4000 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Simmons, B. Stanley
Orig Construction	Builder	Galloway & Son
Orig Construction	Owner	Phillips, S.L.

Construction Notes:

One of four dwellings constructed from the same permit (#1618).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached (1 side)**
Relate to Street: **Face on Setback Line**
Massing: **Row Bldg (Rect. Bay)**
Footprint: **Rectangular**

Number Stories: **3 plus basement**

Bays Wide: **2**

Height:

Width: **19**

Depth/Length: **50**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Romanesque Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1901 by Galloway & Son, this three-story, two-bay Romanesque Revival-style multi-family dwelling is one of four similar dwellings constructed from the same permit (#1618). The dwelling is constructed of brick and is faced with stretcher-bond brick on the façade (east elevation). The north (side) elevation of the dwelling is parged. Multiple ornamental stringcourses spans the façade. Set on a solid concrete foundation, the dwelling is capped by a sloping roof. A molded metal cornice with brick corbels complements the roof. An exterior-side parged chimney rises from the north and south elevations. The southernmost bay of the façade holds a single-leaf paneled wood door and a semicircular transom. A three-course, rowlock brick semicircular arch with molded brick cap and concrete imposts surmounts the transom. The second story opening holds a 1/1, double-hung, wood-sash window and the third story round-headed opening also holds a 1/1, double-hung, wood-sash window. A three-sided, rectangular bay extends from the northernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is fenestrated with 1/1, double-hung, wood-sash windows. The central bay of the first story is a round-headed window and features an elaborate molded brick surround. All first and second story openings have concrete sills and lintels. The third story openings have a molded architrave for a sill and a three-course, rowlock brick round-headed arch. The north elevation is fenestrated with 1/1, double-hung, wood-sash windows with wood sills. The rear (west) elevation is parged and is fenestrated with 1/1, double-hung, wood-sash windows with wood sills. A three-story, canted bay window extends from the northern bay of the rear elevation and is wood-frame construction. The bay is clad with vinyl siding and is fenestrated with 1/1, double-hung, wood-sash windows.

Site Notes:

April 2010: This three-story multi-family dwelling is located on the west side of 15th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The south (side) elevation of the dwelling is adjacent to 11 15th Street, S.E. The raised front yard is landscaped with mature shrubs and is bounded by a concrete retaining wall. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is enclosed by a fence.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **7_15th_Street_SE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **7_15th_Street_SE_facade_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **7_15th_Street_SE_rear_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0052

BASICS DATA

ID Number: **1058-0052** Year Built: **1901** Data Source: **Permit**

Number Extended Street Quad Type of Address

1447 **East Capitol Street** **SE** **Current**

Name(s) Type of Name

Multiple Dwelling, 1447 East Capitol Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0052 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multi-Family) **1901** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1901** **Permit** **4000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Simmons, B. Stanley**

Orig Construction **Builder** **Galloway & Son**

Orig Construction **Owner** **Phillips, S.L.**

Construction Notes:

One of four buildings constructed from the same permit (#1618).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 4)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Bldg (Rect. Bay)**

Footprint: **Rectangular**

Number Stories: **3 plus basement**

Bays Wide: **2**

Height:

Width: **19**

Depth/Length: **50**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Romanesque Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1901 by Galloway & Son, this three-story, two-bay Romanesque Revival-style multi-family dwelling is one of four similar dwellings constructed from the same permit (#1618). The dwelling is constructed of brick and is faced with stretcher-bond brick on the façade (north elevation). Multiple ornamental stringcourses spans the façade. Set on a solid concrete foundation, the dwelling is capped by a sloping roof. A molded metal cornice with brick corbels complements the roof. A three-sided, rectangular bay extends from the easternmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block. The recessed westernmost bay of the façade holds a single-leaf paneled wood door and a single-light transom. The door is set within an integrated porch formed by a large round-headed opening with a multi-course, rowlock brick semicircular arch. All window openings on the façade hold 1/1, double-hung wood-sash windows, although the third story windows have round-headed sash. The first and second story openings have concrete sills and the first story windows have concrete jack arches and the second story windows have concrete lug lintels. The third story openings are topped by three-course, rowlock brick semicircular arches. The foundation is pierced by paired one-light vinyl windows. The east (side) elevation has fenestration that is consistent with the façade. A three-sided, bay projects from the east elevation and has the same material treatment as the main block. A three-sided, canted oriel window projects from second and third story of the rear (south) elevation of the dwelling. The wood-frame oriel is clad with vinyl siding and is fenestrated with 1/1, double-hung, wood-sash windows.

Site Notes:

April 2010: This three-story multi-family dwelling is located on the southwest corner of East Capitol Street, S.E. and 15th Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling was constructed on a separate lot although it appears as one building with 1445 East Capitol Street, S.E. The front yard is landscaped with mature plantings and is encircled by a brick retaining wall.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source

Wall Component	Material	Color	Treatment	Source

Structure Component	Material	Feature	Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Pannels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:
Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1445-
1447_East_Capitol_Street_SE_E_elevation.JP
G

Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1445-
1447_East_Capitol_Street_SE_facade_looking
_SW.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1447_East_Capitol_Street_SE_facade_looking
_SE.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 1447_East_Capitol_Street_SE_facade_looking
_SW.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/04/1901	1618	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0051

BASICS DATA

ID Number: **1058-0051** Year Built: **1901** Data Source: **Permit**

Number Extended Street Quad Type of Address

1445 East Capitol Street SE Current

Name(s) Type of Name

Multiple Dwelling, 1445 East Capitol Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0051 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multi-Family) 1901 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1901 Permit 4000 Permit

Construction Event Association Associated Name

Orig Construction Architect Simmons, B. Stanley

Orig Construction Builder Galloway & Son

Orig Construction Owner Phillips, S.L.

Construction Notes:

One of four buildings constructed from the same permit (#1618).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 3)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Bldg (Rect. Bay)**

Footprint: **C-Shaped**

Number Stories: **3 plus basement**

Bays Wide: **2**

Height:

Width: **19**

Depth/Length: **50**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Romanesque Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1901 by Galloway & Son, this three-story, two-bay Romanesque Revival-style multi-family dwelling is one of four similar dwellings constructed from the same permit (#1618). The dwelling is constructed of brick and is faced with stretcher-bond brick on the façade (north elevation). Multiple ornamental stringcourses spans the façade. Set on a solid concrete foundation, the dwelling is capped by a sloping roof. A molded metal cornice with brick corbels complements the roof. A three-sided, rectangular bay extends from the westernmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block. The recessed easternmost bay of the façade holds a single-leaf paneled wood door and a single-light transom. The door is set within an integrated porch formed by a large round-headed opening with a multi-course, rowlock brick semicircular arch. All window openings on the façade hold 1/1, double-hung wood-sash windows, although the third story windows have round-headed sash. The first and second story openings have concrete sills and the first story windows have concrete jack arches and the second story windows have concrete lug lintels. The third story openings are topped by three-course, rowlock brick semicircular arches. The foundation is pierced by paired one-light vinyl windows. A three-sided, canted oriel window projects from second and third story of the rear (south) elevation of the dwelling. The wood-frame oriel is clad with vinyl siding and is fenestrated with 1/1, double-hung, wood-sash windows.

Site Notes:

April 2010: This three-story multi-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling was constructed on a separate lot although it appears as one building with 1447 East Capitol Street, S.E. The front yard is landscaped with mature plantings and is encircled by a brick retaining wall.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Designation Level(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\

File: 1445_East_Capitol_Street_SE_facade_looking
_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\

File: 1445_East_Capitol_Street_SE_facade_looking
_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\

File: 1445-
1447_East_Capitol_Street_SE_facade_looking
_SE.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0045

BASICS DATA

ID Number: **1058-0045** Year Built: **1906** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1441		East Capitol Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1441 East Capitol Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1058/0045			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1906	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1906	Permit			3333 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Allard, William C.
Orig Construction	Builder	Bray, Martin H.
Orig Construction	Owner	Bray, Martin H.

Construction Notes:

One of three rowhouses constructed from the same permit (#1963).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 3)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Row Bldg (Polygonal Bay)**
Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **37**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

April 2010: Constructed in 1906 by Martin H. Bray, this two-story, two-bay Queen Anne-style single-family dwelling is one of three similar rowhouses constructed from the same permit (#1963). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (north elevation) is faced with stretcher-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof with a flared overhanging eave. The false mansard is covered with slate shingles and is complemented by a molded metal cornice with block modillions and dentil molding. A three-sided, canted bay projects from the easternmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a pyramidal roof of slate shingles. A multi-light frieze window pierces the bay. The westernmost bay of the façade holds a single-leaf wood-frame glass door and a single-light wood transom. A rock-faced concrete lintel surmounts the transom. Stone steps with brick wing walls provide access to the primary entrance. Window fenestration of the façade consists of 1/1, double-hung, wood-sash windows. All windows have rock-faced concrete sills and lintels. The rear (south) elevation is fenestrated with 1/1, double-hung, wood-sash windows.

A two-story brick ell extends from the easternmost bay of the rear elevation and is original. The ell is capped by a sloping roof and is set on a solid foundation. An exterior-side brick chimney rises from the west (side) elevation. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows, which have concrete sills and two-course, rowlock brick segmental arches.

A two-story enclosed porch extends from the rear elevation of the ell and is wood-frame construction. The enclosed porch is clad with asbestos siding and is capped by a sloping roof. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf door with a single-light transom.

Site Notes:

April 2010: This two-story single-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1439 and 1443 East Capitol Street, S.E. The grassy front yard is landscaped with mature trees and shrubs, as well as foundation plantings. A stone walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is enclosed by a wood fence.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s) _____
Subdivision: _____
Ward/ANC: _____
Zoning: _____ Designation Event(s) _____
Contributing: _____

Survey(s) _____ Level(s) of Investigation _____
Capitol Hill Southeast Phase II (2010) **Permit Research**
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase**
I\Database\Pictures\Square 1058
File: **1441_East_Capitol_Street_SE_facade_looking**
_S.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase**
I\Database\Pictures\Square 1058
File: **1441_East_Capitol_Street_SE_facade_looking**
_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase**
I\Database\Pictures\Square 1058
File: **1441_East_Capitol_Street_SE_rear_looking_N**
E.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/10/1906	1963	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0044

BASICS DATA

ID Number: **1058-0044** Year Built: **1906** Data Source: **Permit**

Number Extended Street Quad Type of Address

1439 East Capitol Street SE Current

Name(s) Type of Name

Rowhouse, 1439 East Capitol Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0044 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1906 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1906 Permit 3333 Permit

Construction Event Association Associated Name

Orig Construction Architect Allard, William C.

Orig Construction Builder Bray, Martin H.

Orig Construction Owner Bray, Martin H.

Construction Notes:

One of three rowhouses constructed from the same permit (#1963).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 3)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Bldg (Polygonal Bay)**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **37**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

April 2010: Constructed in 1906 by Martin H. Bray, this two-story, two-bay Queen Anne-style single-family dwelling is one of three similar rowhouses constructed from the same permit (#1963). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (north elevation) is faced with stretcher-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof with a flared overhanging eave. The false mansard is covered with slate shingles and is complemented by a molded metal cornice with block modillions and dentil molding. A three-sided, canted bay projects from the easternmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a pyramidal roof of slate shingles. A multi-light frieze window pierces the bay. The westernmost bay of the façade holds a single-leaf wood-frame glass door and a single-light wood transom. A rock-faced concrete lintel surmounts the transom. Steps with brick wing walls provide access to the primary entrance. Window fenestration of the façade consists of 1/1, double-hung, vinyl-sash windows. All windows have rock-faced concrete sills and lintels. The rear (south) elevation is fenestrated with 1/1, double-hung, wood-sash windows.

A two-story brick ell extends from the westernmost bay of the rear elevation and is original. The ell is capped by a sloping roof and is set on a solid foundation. An exterior-side brick chimney rises from the east (side) elevation. Visible fenestration consists of two single-leaf multi-light wood doors and 1/1, double-hung, vinyl-sash windows, which have concrete sills and two-course, rowlock brick segmental arches.

A two-story porch extends from the rear elevation of the dwelling and is wood-frame construction. The sloping roof of the porch is supported by square wood posts. Square wood balusters encircle each level of the porch.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1437 and 1441 East Capitol Street, S.E. The front yard is landscaped with mature shrubs and small trees and is bounded by a stone retaining wall. The rear yard is enclosed by a wood fence. An alley is located south of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s) _____
Subdivision: _____
Ward/ANC: _____
Zoning: _____ Designation Event(s) _____
Contributing: _____

Survey(s) _____ Level(s) of Investigation _____
Capitol Hill Southeast Phase II (2010) **Permit Research**
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1439_East_Capitol_Street_SE_facade_looking
_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1439_East_Capitol_Street_SE_facade_looking
_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1439_East_Capitol_Street_SE_rear_looking_N
E.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/10/1906		Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0043

BASICS DATA

ID Number: **1058-0043** Year Built: **1906** Data Source: **Permit**

Number Extended Street Quad Type of Address

1437 **East Capitol Street** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1437 East Capitol Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0043 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1906** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1906** **Permit** **3333 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Allard, William C.**

Orig Construction **Builder** **Bray, Martin H.**

Orig Construction **Owner** **Bray, M. H.**

Construction Notes:

One of three rowhouses constructed from the same permit (#1963).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 3)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Bldg (Polygonal Bay)**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **37**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

April 2010: Constructed in 1906 by Martin H. Bray, this two-story, two-bay Queen Anne-style single-family dwelling is one of three similar rowhouses constructed from the same permit (#1963). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (north elevation) is faced with stretcher-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof with a flared overhanging eave. The false mansard is covered with slate shingles and is complemented by a molded metal cornice with block modillions and dentil molding. A three-sided, canted bay projects from the easternmost bay of the façade and rises the full height of the dwelling. The bay has the material treatment of the main block and is capped by a pyramidal roof of slate shingles. A multi-light frieze window pierces the bay. The westernmost bay of the façade holds a single-leaf wood-frame glass door and a single-light wood transom. A rock-faced concrete lintel surmounts the transom. Steps with brick wing walls provide access to the primary entrance. Window fenestration of the façade consists of 1/1, double-hung, vinyl-sash windows. All windows have rock-faced concrete sills and lintels. The rear (south) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows and have sills and two and three-course, rowlock brick segmental arches.

A two-story brick ell extends from the easternmost bay of the rear elevation and is original. The ell is capped by a sloping roof and is set on a solid foundation. An exterior-side brick chimney rises from the west (side) elevation. Visible fenestration consists of two single-leaf paneled wood doors with lights and 1/1, double-hung, vinyl-sash windows, which have concrete sills and two-course, rowlock brick segmental arches.

A two-story porch extends from the rear elevation of the dwelling and is wood-frame construction. The sloping roof of the porch is supported by square wood posts. Bamboo balusters encircle each level of the porch.

Site Notes:

April 2010: This two-story single-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1435 and 1439 East Capitol Street, S.E. The front yard is landscaped with mature shrubs and small trees. A walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is paved with concrete and is enclosed by a wood fence. An alley is located south of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s) _____
Subdivision: _____
Ward/ANC: _____
Zoning: _____ Designation Event(s) _____
Contributing: _____
Survey(s) _____ Level(s) of Investigation _____
Capitol Hill Southeast Phase II (2010) **Permit Research**
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1437_East_Capitol_Street_SE_facade_looking
_S.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1437_East_Capitol_Street_SE_facade_looking
_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1437_East_Capitol_Street_SE_rear_looking_N
E.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/10/1906	1963	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0064

BASICS DATA

ID Number: **1058-0064** Year Built: **1913** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1435		East Capitol Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1435 East Capitol Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1058/0064			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1913	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1913	Permit			2500 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Talbott, W.R.
Orig Construction	Builder	Howenstein, H.R.
Orig Construction	Owner	Howenstein, H.R.

Construction Notes:

One of three rowhouses constructed from the same permit (#3398).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 3)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Flat Front**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **18**

Depth/Length: **34**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type	Contributing Status
------------------	---------------------

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1913 by H.R. Howenstein, this two-story, three-bay Classical Revival-style single-family dwelling is one of three similar rowhouses constructed from the same permit (#3398). The dwelling is constructed of brick and is set on a solid brick foundation; the façade (north elevation) is faced with Flemish-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard is covered with slate shingles and is pierced by two pedimented dormers. Each door is fenestrated by a ten-light wood window (possibly fixed). A molded metal cornice with block modillions finishes the roof. The westernmost bay of the façade holds a single-leaf paneled wood door and a stained glass transom. Metal stairs provide access to the primary entrance. The other openings on the façade hold 1/1, double-hung, vinyl-sash windows and have concrete sills and lintels. The foundation of the façade is pierced by a single-leaf multi-light wood door and 1/1, double-hung, vinyl-sash windows. The rear (south elevation) is fenestrated with 1/1, double-hung, vinyl-sash windows, which have two-course, rowlock brick segmental arches and concrete sills.

A two-story brick ell extends from the westernmost bay of the rear elevation and is original. The ell is capped by a sloping roof. A two-story enclosed porch is located on the rear elevation of the ell. The wood-frame porch is clad with vinyl siding and is capped by a sloping roof. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf paneled metal door.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1433 and 1437 East Capitol Street, S.E. The grassy front yard is landscaped with mature shrubs and small trees and is bounded by a stone retaining wall. A concrete walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is enclosed by a wood fence. An alley is located south of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058**

File: **1435_East_Capitol_Street_SE_facade_looking
_S.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058**

File: **1435_East_Capitol_Street_SE_facade_looking
_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058**

File: **1435_East_Capitol_Street_SE_rear_looking_N
W.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
01/22/1913	3398	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0063

BASICS DATA

ID Number: **1058-0063** Year Built: **1913** Data Source: **Permit**

Number Extended Street Quad Type of Address

1433 East Capitol Street SE Current

Name(s) Type of Name

Rowhouse, 1433 East Capitol Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0063 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1913 Permit Historic

Residential (Multi-Family) Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1913 Permit 2500 Permit

Construction Event Association Associated Name

Orig Construction Architect Talbott, W.R.

Orig Construction Builder Howenstein, H.R.

Orig Construction Owner Howenstein, H.R.

Construction Notes:

One of three rowhouses constructed from the same permit (#3398).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row (1 of 3)**
 Relate to Street: **Front Yard w/ Setback**
 Massing: **Row Building/Front Porch**
 Footprint: **L-Shaped**

Cross Reference Notes:



Number Stories: **2 plus basement**
 Bays Wide: **3**
 Height: **18**
 Width: **34**
 Depth/Length: **3**

Outbuilding Type	Contributing Status
Garage	Contributing

SqFt:
 Volume:
 Lot Width
 Lot Depth/Length:
 Lot SqFt:
 Acreage:
 Has Driveway:

Outbuilding Notes:

April 2010: A one-story, two-bay garage is located south of the dwelling and was constructed c. 1940. The garage is constructed of five-course, American-bond brick and is capped by a shed roof. A corbeled brick cornice complements the roof. The façade (south elevation) is fenestrated by a roll-up paneled metal door and a single-leaf door.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1913 by H.R. Howenstein, this two-story, three-bay Classical Revival-style single-family dwelling is one of three similar rowhouses constructed from the same permit (#3398). The dwelling is constructed of brick and is set on a solid brick foundation; the façade (north elevation) is faced with Flemish-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard is covered with slate shingles and is pierced by two pedimented dormers. Each door is fenestrated by a one-light wood window (possibly fixed). A molded metal cornice with block modillions finishes the roof. The easternmost bay of the façade holds a single-leaf wood-frame glass door and a one-light wood transom. The other openings on the façade hold 1/1, double-hung, wood-sash windows and have concrete sills and lintels. The foundation of the façade is pierced by 1/1, double-hung, wood-sash windows and a single-leaf door. A one-story, full-width porch spans the façade and is set on a pier foundation. The flat roof of the porch has overhanging eaves with modillions and is supported by Tuscan wood columns. Turned wood balusters encircle the porch, which is accessed via brick steps with brick wing walls in the eastern end bay.

A two-story brick ell extends from the easternmost bay of the rear elevation and is original. The ell is capped by a sloping roof. A two-story enclosed porch is located on the rear elevation of the ell and is wood-frame construction clad with vinyl siding. A sloping roof caps the enclosed porch. Visible fenestration consists of one-light vinyl casement windows, 1/1, double-hung, wood-sash windows and a single-leaf, wood-frame glass door with a single-light transom.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1431 and 1435 East Capitol Street, S.E. The front yard is landscaped with mature shrubs and plantings. The rear yard is enclosed by a wood fence. An alley is located south of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s) _____ Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s) _____

Survey(s) _____

Level(s) of Investigation _____

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 1433_East_Capitol_Street_SE_facade_looking
 _S.JPG**

Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 1433_East_Capitol_Street_SE_rear_looking_N
 W.JPG**

Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 1433_East_Capitol_Street_SE_garage.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
01/22/1913	3398	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0062

BASICS DATA

ID Number: **1058-0062** Year Built: **1913** Data Source: **Permit**

Number Extended Street Quad Type of Address

1431 East Capitol Street SE Current

Name(s) Type of Name

Rowhouse, 1431 East Capitol Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0062 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1913 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1913 Permit 2500 Permit

Construction Event Association Associated Name

Orig Construction Architect Talbott, W.R.

Orig Construction Builder Howenstein, H.R.

Orig Construction Owner Howenstein, H.R.

Construction Notes:

One of three rowhouses constructed from the same permit (#3398).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 3)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **18**

Depth/Length: **34**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type

Garage

Contributing Status

Contributing

Outbuilding Notes:

April 2010: This one-story, one-bay garage is located south of the dwelling and was constructed c. 1925. The garage is constructed of brick and is capped by a sloping roof. A roll-up paneled metal door pierces the façade (south elevation).

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1913 by H.R. Howenstein, this two-story, three-bay Classical Revival-style single-family dwelling is one of three similar rowhouses constructed from the same permit (#3398). The dwelling is constructed of brick and is set on a solid brick foundation; the façade (north elevation) is faced with Flemish-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard is covered with slate shingles and is pierced by two pedimented dormers. Each door is fenestrated by a ten-light wood window (possibly fixed). A molded metal cornice with block modillions finishes the roof. The westernmost bay of the façade holds a replacement, single-leaf paneled metal door with an oval light and a single-light wood transom. A concrete lintel surmounts the transom. The other openings on the façade hold 1/1, double-hung, vinyl-sash windows and have concrete sills and lintels. A one-story, full-width porch spans the façade and is set on a brick pier foundation. The flat roof of the porch has overhanging eaves with modillions and is supported by brick posts set on brick piers. Metal balusters encircle the porch, which is accessed via metal steps in the western end bay.

A two-story brick ell extends from the westernmost bay of the rear elevation and is original. The ell is capped by a sloping roof and features an interior-side brick chimney rising from the west elevation. The chimney has a parged cap. A two-story enclosed porch is located on the rear elevation of the ell. The wood-frame porch is clad with vinyl siding and is capped by a sloping roof. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows. A one-story porch is located on the rear elevation of the enclosed porch and was not visible from the public right-of-way.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1433A-1433B and 1429 East Capitol Street, S.E. The grassy front yard is landscaped with mature shrubs and plantings. A walkway leads from the primary entrance of the dwelling and ends at the sidewalk. An alley is located south of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058**

File: **1431_East_Capitol_Street_SE_facade_looking
_SE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058**

File: **1431_East_Capitol_Street_SE_facade_looking
_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058**

File: **1431_East_Capitol_Street_SE_garage_looking
_N.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 1431_East_Capitol_Street_SE_rear_looking_N
E.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
01/22/1913	3398	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0067

BASICS DATA

ID Number: **1058-0067** Year Built: **1913** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1429		East Capitol Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1429 East Capitol Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1058/0067			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1913	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1913	Permit			2500 Permit

Construction Event	Association	Associated Name
Abbott, J.E.	Owner	Abbott, J.E.
Orig Construction	Architect	Abbott, W.H.
Orig Construction	Builder	Abbott, W.H.

Construction Notes:

One of three rowhouses constructed from the same permit (#2656).


PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 3)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:



Number Stories: **2**
Bays Wide: **3**
Height:
Width: **16**
Depth/Length: **32**

Outbuilding Type	Contributing Status
Garage	Contributing

SqFt:
Volume:
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

April 2010: This one-story, one-bay garage is located south of the dwelling and was constructed c. 1925. The garage is constructed of five-course, American-bond brick and is capped by a sloping roof. The façade (south elevation) is pierced by a roll-up paneled metal door.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1913 by W.H. Abbott, this two-story, three-bay Classical Revival-style single-family dwelling is one of three similar rowhouses constructed from the same permit (#2656). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (north elevation) is faced with five-course, American-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard is covered with slate shingles and is pierced by a pedimented dormer. The dormer is fenestrated by paired diamond-light wood windows (possibly casement). The molded metal cornice is finished with block modillions. The easternmost bay of the façade holds a single-leaf, wood door with a single-light. A concrete lintel surmounts the door opening. Additional openings hold 1/1, double-hung, vinyl-sash windows. All windows have concrete sills and lintels. A one-story, full-width porch spans the façade and is set on a pier foundation. The flat roof of the porch has overhanging eaves and is supported by fluted wood columns. Square wood balusters encircled the porch, which is accessed via steps in the eastern end bay. The rear (south) elevation was not visible from the public right-of-way.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1427 and 1431 East Capitol Street, S.E. The grassy front yard is landscaped with mature trees and shrubs, as well as foundation plantings. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. An alley is located south of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1429_East_Capitol_Street_SE_facade_looking
_S.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1429_East_Capitol_Street_SE_facade_looking
_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1429_East_Capitol_Street_SE_garage.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/18/1913	2656	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0066

BASICS DATA

ID Number: **1058-0066** Year Built: **1913** Data Source: **Permit**

Number Extended Street Quad Type of Address

1427 **East Capitol Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1427 East Capitol Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0066 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1913** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1913** **Permit** **2500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Abbott, W.H.**

Orig Construction **Builder** **Abbott, W.H.**

Orig Construction **Owner** **Abbott, J.E.**

Construction Notes:

One of three rowhouses constructed from the same permit (#2656).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 3)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **16**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Garage

Contributing Status

Contributing

Outbuilding Notes:

April 2010: A one-story, one-bay garage is located south of the dwelling and was constructed c. 1925. The garage is sited between the garages for 1425 and 1429 East Capitol Street, S.E. The garage is constructed of brick and is capped by a sloping roof. The roof is complemented by a corbeled brick

cornice. The façade (south elevation) is pierced by a roll-up metal door, which is surmounted by a metal lintel.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1913 by W.H. Abbott, this two-story, three-bay Classical Revival-style single-family dwelling is one of three similar rowhouses constructed from the same permit (#2656). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (north elevation) is faced with stretcher-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard is covered with slate shingles and is pierced by a pedimented dormer. The dormer is fenestrated by paired diamond-light wood windows (possibly casement). The molded metal cornice is finished with block modillions. The westernmost bay of the façade holds a single-leaf door. The transom has been infilled. A concrete lintel surmounts the door opening. Additional openings hold 1/1, double-hung, wood-sash windows. All windows have concrete sills and lintels. A one-story, full-width porch spans the façade and is set on a brick pier foundation that is infilled with honeycomb brickwork. The flat roof of the porch has overhanging eaves and is supported by brick posts set on brick piers. Metal balusters encircled the porch, which is accessed via steps in the western end bay.

A two-story ell extends from the westernmost bay of the rear elevation and is constructed of five-course, American-bond brick. A sloping roof caps the ell. Visible fenestration consists of a single-leaf door and 2/2, double-hung, wood-sash windows, which have wood sills and two-course, rowlock brick segmental arches.

A one-story, two-bay porch projects from the rear elevation of the ell. The porch has a shed roof that is supported by metal filigree posts.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1425 and 1429 East Capitol Street, S.E. The grassy front yard is landscaped with mature shrubs and trees. The rear yard is enclosed by a fence. An alley is located south of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Pannels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s) _____
Subdivision: _____
Ward/ANC: _____
Zoning: _____ Designation Event(s) _____
Contributing: _____

Survey(s) _____ Level(s) of Investigation _____
Capitol Hill Southeast Phase II (2010) **Permit Research**
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**
File: **1427_East_Capitol_Street_SE_facade_looking
_SE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**
File: **1427_East_Capitol_Street_SE_facade_looking
_SW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**
File: **1427_East_Capitol_Street_SE_garage_looking
_NE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 1427_East_Capitol_Street_SE_rear_looking_N
E.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/18/1913	2656	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0065

BASICS DATA

ID Number: **1058-0065** Year Built: **1913** Data Source: **Permit**

Number Extended Street Quad Type of Address

1425 East Capitol Street SE Current

Name(s) Type of Name

Rowhouse, 1425 East Capitol Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0065 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1913 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1913 Permit 2500 Permit

Construction Event Association Associated Name

Orig Construction Architect Abbott, W.H.

Orig Construction Builder Abbott, W.H.

Orig Construction Owner Abbott, J.E.

Construction Notes:

One of three rowhouses constructed from the same permit (#2656).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row End (1 of 3)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Row Building/Front Porch**
Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **16**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Garage

Contributing Status

Contributing

Outbuilding Notes:

April 2010: A one-story, one-bay garage is located south of the dwelling and was constructed c. 1925. The garage is constructed of five-course, American-bond brick and is capped by a sloping roof. A corbeled brick cornice finishes the roof. The façade (south elevation) is pierced by a roll-up paneled

metal door.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1913 by W.H. Abbott, this two-story, three-bay Classical Revival-style single-family dwelling is one of three similar rowhouses constructed from the same permit (#2656). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (north elevation) is faced with stretcher-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. The false mansard is covered with slate shingles and is pierced by a pedimented dormer. The dormer is fenestrated by paired louvered ventes. The molded metal cornice is finished with block modillions. An interior-side brick chimney rises from the west elevation and has a parged cap. The easternmost bay of the façade holds a single-leaf, paneled metal door with lights and a single-light transom. A concrete lintel surmounts the door opening. Additional openings hold 1/1, double-hung, vinyl-sash windows. All windows have concrete sills and lintels. A one-story, full-width porch spans the façade and is set on a pier foundation. The flat roof of the porch has overhanging eaves and is supported by brick posts. Square wood balusters encircled the porch, which is accessed via steps in the eastern end bay. The west (side) elevation is fenestrated by 1/1, double-hung, vinyl-sash windows and have concrete sills and two-course, rowlock brick segmental arches. The rear (south) elevation is pierced by 1/1, double-hung, vinyl-sash windows; these windows have concrete sills and two-course, rowlock brick segmental arches.

A one-story, full-width enclosed porch is located on the south elevation. The wood-frame enclosed porch is clad with German vinyl siding and is capped by a sloping roof. Visible fenestration consists of a single-leaf, paneled metal door with lights and paired one-light vinyl sliding windows.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The east (side) elevation of the dwelling is adjacent to 1427 East Capitol Street, S.E. An asphalt-paved alley runs parallel to the west (side) elevation of the dwelling. The front yard of the dwelling is landscaped with mature shrubs and foundation plantings and is enclosed by a brick retaining wall with a metal milled point fence. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is enclosed by a wood fence. An alley is located south of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s) _____
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s) _____
Contributing:	
Survey(s) _____	Level(s) of Investigation _____
Capitol Hill Southeast Phase II (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1425_East_Capitol_Street_SE_facade_looking
_S.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1425_East_Capitol_Street_SE_facade_looking
_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1425_East_Capitol_Street_SE_rear_looking_N
E.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 1425_East_Capitol_Street_SE_garage.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/18/1913	2656	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0807

BASICS DATA

ID Number: **1058-0807** Year Built: **1889** Data Source: **Permit**

Number Extended Street Quad Type of Address

1423 **East Capitol Street** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1423 East Capitol Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0807 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1889** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1889** **Permit** **800 Permit**

Construction Event Association Associated Name

Mayle, William **Owner** **Mayle, William**

Orig Construction **Builder** **Waters, C.G.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **15**

Depth/Length: **40**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Exterior & Architectural Notes:

April 2010: Constructed in 1889 by C.G. Waters, this two-story, two-bay Italianate-style single-family dwelling is constructed of seven-course, American-bond brick. Set on a brick foundation, the dwelling is capped by a sloping roof. A molded cornice with brick corbels complements the roof. A brick string course spans the façade and is located above the second story windows. The westernmost bay of the façade (north elevation) holds a single-leaf paneled wood door. A pedimented door surround highlights the opening, which is flanked by fluted pilasters. All other openings on the façade hold 1/1, double-hung, vinyl-sash windows and have concrete sills and soldier brick segmental arches. The east (side) elevation has fenestration that is consistent with the façade and each opening features a rowlock brick sill and soldier brick segmental arch. The rear (south) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows and a single-leaf paneled door with lights and a single-light transom. The windows have concrete sills and brick segmental arches.

A two-story, full-width porch extends from the rear elevation of the dwelling and is capped by a sloping roof. Square wood posts support each level of the porch.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The west (side) elevation of the dwelling is adjacent to 1421 East Capitol Street, S.E. and an asphalt-paved alley runs parallel to the east (side) elevation of the dwelling. The front yard is landscaped by mature shrubs and foundation plantings. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is enclosed by a wood fence. An alley is located south of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Pannels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Contributing.

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1423_East_Capitol_Street_SE_facade_looking
_S.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1423_East_Capitol_Street_SE_facade_looking
_SW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1423_East_Capitol_Street_SE_rear_looking_N
W.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/09/1889	1948	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0809

BASICS DATA

ID Number: **1058-0809** Year Built: **1904** Data Source: **Permit**

Number Extended Street Quad Type of Address

1421 East Capitol Street SE Current

Name(s) Type of Name

Multiple Dwelling, 1421 East Capitol Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0809 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multi-Family) 1904 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1904 Permit 3000 Permit

Construction Event Association Associated Name

Orig Construction Builder Langley, Charles A.

Orig Construction Owner Langley, Charles A.

Construction Notes:

One of two dwellings constructed from the same permit (#1210).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Front Yard w/ Setback**
Massing: **Row Building/Flat Front**
Footprint: **C-Shaped**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **62**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

April 2010: Constructed by Charles A. Langley in 1904, this two-story, two-bay Queen Anne-style multi-family dwelling is one of two dwellings constructed from the same permit (#1210). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (north elevation) is faced with stretcher-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a molded metal cornice with brick corbelling. A parapet rises from the façade. An interior chimney rises from the dwelling and is constructed of brick. The easternmost bay of the façade is deeply recessed and is pierced by a single-leaf paneled wood door. A four-course, rowlock brick segmental arch surmounts the opening of the bay. Brick steps with metal hand rails provide access to the primary entrance. The window openings on the façade hold 9/9, double-hung, wood-sash and feature concrete sills and four-course, rowlock brick segmental arches. The rear (south) elevation is fenestrated with a single-leaf wood door with lights and a single-light transom, a single-leaf multi-light wood door with a single-light transom, and 6/6, double-hung, wood-sash windows. All openings are topped by two-course, rowlock brick segmental arches.

Site Notes:

April 2010: This two-story, multi-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1419 and 1423 East Capitol Street, S.E. The front yard is landscaped with mature shrubs, plantings, and foundation plantings. A brick walkway leads from the primary entrance of the dwelling and ends at the concrete sidewalk. The rear yard is enclosed by a fence. An alley is located south of the dwelling.

NOTABLE FEATURES DATA

Component _____ Feature _____

EXTERIOR MATERIALS DATA

Roof Component _____ Material _____ Color _____ Treatment _____ Source _____

Wall Component _____ Material _____ Color _____ Treatment _____ Source _____

Structure Component _____ Material _____ Feature _____ Source _____

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location _____ Aperture Shape _____ Type _____ Lights _____ Material _____

Door Location _____ Aperture Shape _____ Type _____ Panels _____ Material _____

Notable Interior Plan(s) _____

Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s) _____

Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1421_East_Capitol_Street_SE_facade_looking
_S.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1421_East_Capitol_Street_SE_facade_looking
_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1421_East_Capitol_Street_SE_rear_looking_N
W.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/01/1904	1210	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0808

BASICS DATA

ID Number: **1058-0808** Year Built: **1904** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1419		East Capitol Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1419 East Capitol Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1058/0808			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Multi-Family)	1904	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1904	Permit			3000 Permit

Construction Event	Association	Associated Name
Orig Construction	Builder	Langley, Charles A.
Orig Construction	Owner	Langley, Charles A.

Construction Notes:

One of two dwellings constructed from the same permit (#1210).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Front Yard w/ Setback**
Massing: **Row Building/Flat Front**
Footprint: **C-Shaped**

Cross Reference Notes:

Number Stories: **2**

Bays Wide:

Height:

Width: **16**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type	Contributing Status
------------------	---------------------

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

April 2010: Constructed by Charles A. Langley in 1904, this two-story, two-bay Queen Anne-style multi-family dwelling is one of two dwellings constructed from the same permit (#1210). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (north elevation) is faced with stretcher-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a molded metal cornice with brick corbelling. A parapet rises from the façade. The westernmost bay of the façade is pierced by two single-leaf paneled wood doors with lights. A four-course, rowlock brick segmental arch surmounts the opening of the bay. The window openings on the façade hold 1/1, double-hung, vinyl-sash and feature concrete sills and four-course, rowlock brick segmental arches. The rear (south) elevation is fenestrated with single-leaf doors and 1/1, double-hung, vinyl-sash windows.

A two-story, full-width wood-frame porch extends from the rear elevation of the dwelling. The sloping roof of the porch is supported by square wood posts.

Site Notes:

April 2010: This two-story, multi-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1417 and 1421 East Capitol Street, S.E. The front yard is landscaped with mature shrubs and foundation plantings. The rear yard is enclosed by a wood fence. An alley is located south of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1419_East_Capitol_Street_SE_facade_looking
_SE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1419_East_Capitol_Street_SE_facade_looking
_SW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1419_East_Capitol_Street_SE_rear_looking_N
.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/01/1904	1210	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0070

BASICS DATA

ID Number: **1058-0070** Year Built: **1918** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1417		East Capitol Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1417 East Capitol Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1058/0070			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1918	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1918	Permit			2500 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Howser, W. Edgar
Orig Construction	Builder	Howenstein, H.R.
Orig Construction	Owner	Howenstein, H.R.

Construction Notes:

One of three rowhouses constructed from the same permit (#2495).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 3)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Row Building/Front Porch**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **18**

Depth/Length: **33**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type	Contributing Status
------------------	---------------------

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1918 by H.R. Howenstein, this two-story, three-bay Classical Revival-style single-family dwelling is one of three similar rowhouses constructed from the same permit (#2495). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (north elevation) is faced with five-course, American-bond brick. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. Slate shingles cover the false mansard roof. A pedimented dormer pierces the false mansard roof and is fenestrated with a ten-light wood window (possibly fixed). A molded metal cornice finishes the false mansard roof. An exterior brick chimney rises from the rear (south) elevation and has been painted. The easternmost bay of the façade holds a single-leaf paneled metal door with lights and a single-light transom. Window openings hold double-hung, wood-sash with a multi-light upper sash. All windows have concrete sills. A single-leaf door and a single-light vinyl awning window pierce the foundation. A one-story, one-bay porch projects from the façade and is set on a brick pier foundation. The flat roof of the porch has overhanging eaves and is supported by metal balusters set on brick piers. Square wood balusters encircle the porch, which is accessed via wood steps in the eastern end bay.

A two-story enclosed porch is located on the rear elevation and extends its full width. The wood-frame porch is clad with aluminum siding and is capped by a sloping roof. Visible fenestration consists of paired 1/1, double-hung, vinyl-sash windows.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1415 and 1419 East Capitol Street, S.E. The landscaped front yard is planted with mature shrubs and plantings. A walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is enclosed by a wood fence. An alley is located south of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **1417_East_Capitol_Street_SE_facade_looking
_SE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **1417_East_Capitol_Street_SE_facade_looking
_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **1417_East_Capitol_Street_SE_rear_looking_N
E.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/23/1918	2495	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0069

BASICS DATA

ID Number: **1058-0069** Year Built: **1918** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1415		East Capitol Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1415 East Capitol Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1058/0069			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1918	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1918	Permit			2500 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Howser, W. Edgar
Orig Construction	Builder	Howenstein, H.R.
Orig Construction	Owner	Howenstein, H.R.

Construction Notes:

One of three rowhouses constructed from the same permit (#2495).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 3)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Row Building/Front Porch**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**
Bays Wide: **3**
Height: **18**
Width: **33**
Depth/Length: **33**
SqFt:
Volume:
Lot Width

Outbuilding Type	Contributing Status
------------------	---------------------

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1918 by H.R. Howenstein, this two-story, three-bay Classical Revival-style single-family dwelling is one of three similar rowhouses constructed from the same permit (#2495). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (north elevation) is faced with five-course, American-bond brick. A string course composed of basketweave-bond brick spans the façade and is sited above the second story windows. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. Slate shingles cover the false mansard roof. A pedimented dormer pierces the false mansard roof and is fenestrated with a ten-light wood window (possibly fixed). A molded metal cornice finishes the false mansard roof. An exterior brick chimney rises from the rear (south) elevation and has been painted. The easternmost bay of the façade holds a single-leaf wood door with a diamond light and a single-light transom. Window openings hold 1/1, double-hung, vinyl-sash. All windows have concrete sills. A single-leaf door pierces the foundation. A one-story, one-bay porch projects from the façade and is set on a brick pier foundation. The flat roof of the porch has overhanging eaves and is supported by metal filigree posts set on brick piers. Metal balusters encircle the porch, which is accessed via poured concrete steps in the eastern end bay.

A two-story enclosed porch is located on the rear elevation and extends its full width. The wood-frame porch is clad with asbestos shingles and is capped by a sloping roof. Visible fenestration consists of a single-leaf door, a single-leaf wood door with a single-light, and 1/1, double-hung, vinyl-sash windows.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1413 and 1417 East Capitol Street, S.E. The grassy front yard is landscaped with mature shrubs and foundation plantings. The rear yard is enclosed by a wood fence and features mature shrubs. An alley is located south of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:
Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1415_East_Capitol_Street_SE_facade_looking
_S.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1415_East_Capitol_Street_SE_facade_looking
_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1415_East_Capitol_Street_SE_rear_looking_N
.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/23/1918	2495	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0068

BASICS DATA

ID Number: **1058-0068** Year Built: **1918** Data Source: **Permit**

Number Extended Street Quad Type of Address

1413 East Capitol Street SE Current

Name(s) Type of Name

Rowhouse, 1413 East Capitol Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0068 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1918 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1918 Permit 2500 Permit

Construction Event Association Associated Name

Orig Construction Architect Howser, W. Edgar

Orig Construction Builder Howenstein, H.R.

Orig Construction Owner Howenstein, H.R.

Construction Notes:

One of three rowhouses constructed from the same permit (#2495).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 3)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Row Building/Front Porch**
Footprint: **Rectangular**

Number Stories: **2**

Bays Wide:

Height:

Width: **18**

Depth/Length: **33**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Garage

Shed

Contributing Status

Non-Contributing

Non-Contributing

Outbuilding Notes:

April 2010: A one-story, one-bay garage, constructed c. 1970, is located south of the dwelling. The wood-frame garage is clad with vinyl siding and is capped by a hipped roof. The roof is covered with asphalt shingles and features wide, overhanging eaves. The façade (south elevation) is pierced by a roll-up

paneled metal door.

April 2010: A one-story, one-bay shed is located south of the dwelling and was constructed c. 1980. The wood-frame shed is clad with T-111 siding and is capped by a shed roof of asphalt shingles. Overhanging eaves and exposed rafter ends complement the roof. The shed is set on a wood post foundation.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1918 by H.R. Howenstein, this two-story, three-bay Classical Revival-style single-family dwelling is one of three similar rowhouses constructed from the same permit (#2495). The dwelling is constructed of brick and is set on a solid concrete foundation; the façade (north elevation) is faced with five-course, American-bond brick. A string course composed of basketweave-bond brick spans the façade and is sited above the second story windows. A sloping roof caps the dwelling and is fronted along the façade by a false mansard roof. Slate shingles cover the false mansard roof. A pedimented dormer pierces the false mansard roof and is fenestrated with a ten-light wood window (possibly fixed). A molded metal cornice finishes the false mansard roof. An exterior brick chimney rises from the rear (south) elevation and has been painted. The easternmost bay of the façade holds a single-leaf wood door with lights and a single-light transom. Window openings hold 1/1, double-hung, vinyl-sash. All windows have concrete sills. A one-story, one-bay porch projects from the façade and is set on a brick pier foundation. The flat roof of the porch has overhanging eaves and is supported by metal filigree posts set on brick piers. Metal balusters encircle the porch, which is accessed via poured concrete steps in the eastern end bay.

A two-story enclosed porch is located on the rear elevation and extends its full width. The wood-frame porch is clad with aluminum shingles and is capped by a sloping roof. Visible fenestration consists of fixed wood windows.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1415 East Capitol Street, S.E. and 1409 East Capitol Street, S.E. The front yard is landscaped with mature trees and shrubs, as well as foundation plantings. A wood fence encircles the rear yard. An alley is located south of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s) _____
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s) _____
Contributing:	
Survey(s) _____	Level(s) of Investigation _____
Capitol Hill Southeast Phase II (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1413_East_Capitol_Street_SE_facade_looking
_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1413_East_Capitol_Street_SE_facade_looking
_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1413_East_Capitol_Street_SE_rear.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1058\
 File: 1413_East_Capitol_Street_SE_garage.JPG
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1058\
 File: 1413_East_Capitol_Street_SE_shed.JPG
 Date:: Photog:
 Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/23/1918	2495	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0026

BASICS DATA

ID Number: **1058-0026** Year Built: **1886** Data Source: **Permit**

Number Extended Street Quad Type of Address

1409 East Capitol Street SE Current

Name(s) Type of Name

Single Dwelling, 1409 East Capitol Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0026 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1886 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1886 Permit 600 Permit

Construction Event Association Associated Name

Havens & Gillette Owner Havens & Gillette

Orig Construction Builder Trott, C.V.

Construction Notes:

One of two dwellings constructed from the same permit (#1494). Only one dwelling exists today.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **14**

Depth/Length: **26**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Vernacular

Exterior & Architectural Notes:

April 2010: Constructed in 1886 by C.V. Trott, this two-story, two-bay vernacular single-family dwelling is set on a solid brick foundation. The wood-frame dwelling is clad with Permastone on the first story and with aluminum siding on the second story. A sloping roof caps the dwelling and is finished by a molded wood cornice with a scrolled bracket. Fenestration consists of 1/1, double-hung, wood-sash windows. Second story windows are flanked by louvered shutters.

A one-story, one-bay addition is located on the east (side) elevation of the dwelling and was constructed c. 1925. The wood-frame addition shares the material treatment of the main block. The easternmost bay holds a single-leaf paneled wood door with lights. A second story addition was added c. 1970 and also shares the material treatment of the main block's second story. A one-story, full-width porch spans the façade of the dwelling and has a flat roof. The roof is supported by square wood posts set on brick piers.

A two-story brick ell extends from the westernmost bay of the rear (south) elevation and is faced with seven-course, American-bond brick. A sloping roof caps the ell, which is pierced by 1/1, double-hung, vinyl-sash windows. All windows have rowlock brick sills. The first story opening originally held a single-leaf door.

A two-story addition is located on the east elevation of the ell. The first story is constructed of brick and the second story has been parged. Visible fenestration consists of a single-leaf paneled metal door with lights and a 1/1, double-hung, vinyl-sash window with a header brick sill.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately thirty feet from the concrete sidewalk. The dwelling is adjacent to 1407 and 1413 East Capitol Street, S.E. The landscaped front yard features mature shrubs and foundation plantings. A curvilinear brick walkway leads from the primary entrance and ends at the sidewalk. The rear yard features a concrete-paved parking space. An alley is located south of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s) Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**
Subdivision:
Ward/ANC:
Zoning:
Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Historic District(s)

Designation Event(s)

Level(s) of Investigation
Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 1409_East_Capitol_Street_SE_facade_looking
_S.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 1409_East_Capitol_Street_SE_facade_looking
_SW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 1409_East_Capitol_Street_SE_rear_looking_N
W.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/06/1886	1494	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0025

BASICS DATA

ID Number: **1058-0025** Year Built: **c. 2007** Data Source: **DC Real Property**

Number	Extended	Street	Quad Type	Address
1407		East Capitol Street	SE	Current

Name(s)	Type of Name
Single Dwelling, 1407 East Capitol Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1058/0025			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	c. 2007	DC Real Pr			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	c. 2007	DC Real Property			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Raised Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **Rectangular**

Number Stories: **3 plus basement**
Bays Wide: **3**

Height:	Outbuilding Type	Contributing Status
---------	------------------	---------------------

Width:
Depth/Length:
SqFt:

Volume:
Lot Width

Lot Depth/Length:
Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

April 2010: Constructed c. 2007, this three-story, three-bay Modern multi-family dwelling is set on a solid foundation. The façade (north elevation) is faced with stretcher-bond brick and the east (side) elevation is clad with vinyl siding. Soldier brick string courses span the façade and bisect the second and third story window openings. A sloping roof caps the building and is flanked by parapet walls. A corbeled brick cornice complements the roof. The easternmost bay holds a single-leaf paneled metal door with lights and a stained glass transom. A soldier brick jack arch with a central keystone surmounts the transom. All window other openings on the façade hold 1/1, double-hung, vinyl-sash windows with false 9/9 vinyl muntins. All windows have rowlock brick sills and soldier brick jack arches with a central keystone. A single-leaf paneled metal door with lights pierces the foundation of the façade. A one-story, one-bay porch shelters the primary entrance and central bay and is set on a brick pier foundation that has been infilled with glass blocks. The flat roof of the porch has overhanging eaves and is supported by fluted columns set on brick piers. Metal balusters encircle the porch, which is accessed via poured concrete steps in the eastern end bay. The rear (south) elevation is fenestrated by a single-leaf paneled metal door and single and triple 1/1, double-hung, vinyl-sash windows. All windows have rowlock brick sills.

Site Notes:

April 2010: This three-story, multi-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1405 and 1409 East Capitol Street, S.E. The grassy front yard is landscape with mature shrubs. A concrete walkway leads from the sidewalk and ends at the front porch of the dwelling. A metal milled point fence lines the western edge of the property. The rear yard is paved with concrete and is enclosed by a wood fence.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s) _____
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation _____
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1407_East_Capitol_Street_SE_facade_looking
_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1407_East_Capitol_Street_SE_facade_looking
_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1407_East_Capitol_Street_SE_rear_looking_N
W.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0031

BASICS DATA

ID Number: **1058-0031** Year Built: **1939** Data Source: **Permit**

Number Extended Street Quad Type of Address

1405 East Capitol Street SE Current

Name(s) Type of Name

Multiple Dwelling, 1405 East Capitol Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0031 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multi-Family) 1939 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1939 Permit 7500 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Marshal, C.H.

Orig Construction Owner Marshal, C.H.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Front Yard w/ Setback**
Massing: **Row Building/Flat Front**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **34**

Depth/Length: **35**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern
Art Deco

Exterior & Architectural Notes:

April 2010: Constructed in 1939 by C.H. Marshal, this two-story, three-bay Modern multi-family dwelling has detailing associated with the Art Deco style. The building is constructed of concrete blocks and is set on a solid concrete block foundation; the façade (north elevation) is faced with six-course, American-bond brick. A large exterior-rear brick chimney rises from the south (rear) elevation and pierces the overhanging eave. Decorative soldier brick string courses span the façade and are located above the foundation and second story window openings. A sloping roof caps the building and is complemented by metal coping. The central bay of the façade holds a single-leaf, wood-frame glass door. A molded concrete surround with Art Deco detailing highlights the door opening. Poured concrete steps with metal balusters provide access to the primary entrance. Additional openings on the façade hold single and paired 1/1, double-hung, metal-sash windows with rowlock brick sills. The first story openings have soldier brick flat arches. The rear elevation is fenestrated by single-leaf, metal-frame glass doors with one-light metal transoms and single and paired 1/1, double-hung, metal-sash windows. A two-story, full-width deck spans the rear elevation of the dwelling. Square wood balusters complete each level.

Site Notes:

April 2010: This two-story, multi-family dwelling is located on the south side of East Capitol Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The building is adjacent to 1401 and 1407 East Capitol Street, S.E. The grassy yard is landscaped with mature shrubs and foundation plantings. A walkway leads from the primary entrance of the dwelling and ends at the sidewalk. A wood fence encloses the rear yard of the building.

NOTABLE FEATURES DATA

Component _____ Feature _____

EXTERIOR MATERIALS DATA

Roof Component _____ Material _____ Color _____ Treatment _____ Source _____

Wall Component _____ Material _____ Color _____ Treatment _____ Source _____

Structure Component _____ Material _____ Feature _____ Source _____

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location _____ Aperture Shape _____ Type _____ Lights _____ Material _____

Door Location _____ Aperture Shape _____ Type _____ Panels _____ Material _____

Notable Interior Plan(s) _____

Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s) _____

Contributing:

Survey(s)

Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1405_East_Capitol_Street_SE_facade_looking
_S.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1405_East_Capitol_Street_SE_facade_looking
_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 1405_East_Capitol_Street_SE_rear_looking_N
W.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
05/18/1939	222998	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0813

BASICS DATA

ID Number: **1058-0813** Year Built: **1900** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1401		East Capitol Street	SE	Current

Name(s)	Type of Name
Multiple Dwelling, 1401 East Capitol Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1058/0813			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Multi-Family)	1900	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1900	Permit			6000 Permit

Construction Event	Association	Associated Name
Hill, Nora M.	Owner	Hill, Nora M.
Orig Construction	Architect	Campbell, H.A.
Orig Construction	Builder	Watts & Taylor

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached (1 side)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Block**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **3**
Height: **38**
Width: **51**
Depth/Length: **51**

Outbuilding Type	Contributing Status
------------------	---------------------

SqFt:
Volume:
Lot Width:

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

April 2010: Constructed in 1900 by Watts & Taylor, this two-story, three-bay Classical Revival-style apartment building is set on a solid concrete foundation. The building is constructed of brick and is faced on the façade (north elevation) by stretcher-bond brick. A molded architrave spans the façade and is located above the second story window openings. A sloping roof caps the building and is highlighted by a molded metal cornice with scrolled modillions. The central bay of the façade holds double-leaf paneled metal doors with lights and a single-light fanlight. Brick steps with brick wing walls provide access to the entrance. The second story opening holds a 1/1, double-hung, wood-sash window. Three-sided, canted bays extend from the eastern and western end bays of the façade and each rises the full height of the building. Each bay shares the material treatment of the main block and fenestrated with 1/1, double-hung, wood-sash windows. All windows on the façade have concrete sills and rock-faced concrete lintels. The west (side) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows, which have concrete sills and soldier brick segmental arches. A two-story, rectangular bay projects from the west elevation and shares the material treatment of the main block. Visible fenestration on the rear (south) elevation consists of 1/1, double-hung, wood-sash windows with concrete sills and two-course, rowlock brick segmental arches.

Site Notes:

April 2010: This two-story apartment building is located on the southeast corner of East Capitol Street, S.E. and 14th Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The east (side) elevation of the building is adjacent to 1405 East Capitol Street, S.E. The grassy front yard is landscaped with mature shrubs, trees, and foundation plantings. A concrete walkway leads from the primary entrance of the dwelling and ends at the concrete sidewalk. A metal milled point fence encircles the property.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Designation Level(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\

File: 1401_East_Capitol_Street_SE_facade_looking
_S.JPG

Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\

File: 1401_East_Capitol_Street_SE_NW_corner.JP
G

Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\

File: 1401_East_Capitol_Street_SE_SW_corner.JP
G

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/09/1900	0580	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0028

BASICS DATA

ID Number: **1058-0028** Year Built: **c. 1869-1873** Data Source: **Tax Assessment**

Number	Extended	Street	Quad	Type of Address
2		14th Street	SE	Current

Name(s)	Type of Name
Single Dwelling, 2 14th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1058/0028			Square/Lot	Current
1058/0011			Square/Lot	Historic

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Multi-Family)	c. 1869-187	Tax Asses			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	c. 1869-1873	Tax Assessment			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

Constructed at the same time as 4 14th Street, S.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached (1 side)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type	Contributing Status
------------------	---------------------

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Vernacular

Exterior & Architectural Notes:

April 2010: Constructed c. 1869-1873, this two-story, two-bay vernacular single-family dwelling was influenced by the Italianate style. The wood-frame dwelling is clad with vinyl siding and is set on a solid foundation. A sloping roof caps the dwelling and is fronted along the façade (west elevation) by a molded wood cornice with scrolled modillions. The northernmost bay of the façade holds a single-leaf paneled metal door. Additional openings on the façade hold paired one-light vinyl sliding windows and 1/1, double-hung, vinyl-sash windows. A one-story, full-width porch spans the façade and is set on a concrete foundation. The flat roof of the porch has overhanging eaves and is supported by brick posts set on brick piers. Brick steps in the northern end bay provide access to the porch.

A one-story addition is located on the rear (east) elevation and extends from the southern bay. The wood-frame addition is clad with vinyl siding and is capped by a sloping roof. A wide, overhanging eave complements the roof. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows with false 8/1 vinyl muntins.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the east side of 14th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The south (side) elevation of the dwelling is adjacent to 4 14th Street, S.E. The landscaped front yard features mature shrubs and foundation plantings and is bounded by a retaining wall topped by a metal fence. A brick walkway leads from the sidewalk and ends at the front porch of the dwelling. A wood fence encloses the rear yard of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s) Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Ward/ANC:

Zoning: Designation Event(s)

Contributor:

Continuing.

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey
Tax Assessment**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 2_14th_Street_SE_facade_looking_E.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 2_14th_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 2_14th_Street_SE_rear_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

Tax assessment records of the District of Columbia show that, in 1864, the property was owned by Donald M. Cathran and was valued at \$86. In 1869, the property had the same owner and was valued at \$173. The property was not individually assessed in 1869-1871, but in 1872-73, it had the same owner and was valued at \$216. From this data, we can estimate that the dwelling was constructed between 1869 and 1873.

General Assessment, 1864. (Vol. 10 of 18) Corporation of Washington. Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C.

General Assessment, 1869. Corporation of Washington. (Vol. 12. of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C.

General Assessment, 1869-1871. Corporation of Washington. (Vol. 13 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C.

General Assessment, 1872-1873. Corporation of Washington. (Vol. 14 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C.

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

No permit was found for this dwelling, but it is similar in design to the neighboring dwelling at 4 14th Street, S.E.

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0027

BASICS DATA

ID Number: **1058-0027** Year Built: **c. 1869-1873** Data Source: **Tax Assessment**

Number	Extended	Street	Quad	Type of Address
4		14th Street	SE	Current

Name(s)	Type of Name
Single Dwelling, 4 14th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1058/0027			Square/Lot	Current
1058/0011			Square/Lot	Historic

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	c. 1869-187	Tax Asses			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	c. 1869-1873	Tax Assessment			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

Constructed at the same time as 2 14th Street, S.E.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Flat Front**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**

Height:	Outbuilding Type	Contributing Status
---------	------------------	---------------------

Width:
Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Vernacular

Exterior & Architectural Notes:

April 2010: Constructed c. 1869-1873, this two-story, two-bay vernacular single-family dwelling was influenced by the Italianate style. The wood-frame dwelling is clad with vinyl siding and is set on a solid foundation. A sloping roof caps the dwelling and is fronted along the façade (west elevation) by a molded wood cornice with scrolled modillions. The southernmost bay of the façade holds a single-leaf paneled wood door. Additional openings on the façade hold 1/1, double-hung, vinyl-sash windows. The rear (east) elevation is pierced by 1/1, double-hung, vinyl-sash windows.

Constructed c. 1930, a one-story, one-bay addition extends from the northernmost bay of the rear elevation. The wood-frame addition is clad with vinyl siding and is capped by a sloping roof. Metal sheets cover the roof. A single-leaf multi-light wood door fenestrates the bay.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the east side of 14th Street, S.E. and is set back approximately ten feet from the sidewalk. The dwelling is adjacent to 2 and 6 14th Street, S.E. The sloping front yard is heavily landscaped with English ivy and mature shrubs. A metal picket fence encircles the front yard. A wood fence encloses the rear yard. An alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s) Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Ward/ANC:

Zoning: Designation Event(s)

Contributing:

Survey(s) Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 4_14th_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 4_14th_Street_SE_facade_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 4_14th_Street_SE_rear_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

Tax assessment records of the District of Columbia show that, in 1864, the property was owned by Donald M. Cathran and was valued at \$86. In 1869, the property had the same owner and was valued at \$173. The property was not individually assessed in 1869-1871, but in 1872-73, it had the same owner and was valued at \$216. From this data, we can estimate that the dwelling was constructed between 1869 and 1873.

General Assessment, 1864. (Vol. 10 of 18) Corporation of Washington. Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C.

General Assessment, 1869. Corporation of Washington. (Vol. 12. of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C.

General Assessment, 1869-1871. Corporation of Washington. (Vol. 13 of 18) Records of Government of the District of Columbia, Record Group 351 (Entry 46), National Archives Building, Washington, D.C.

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

No permit was found for this dwelling. It is similar in style to the neighboring dwelling at 2 14th Street, S.E.

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0037

BASICS DATA

ID Number: **1058-0037** Year Built: **1886** Data Source: **Permit**

Number Extended Street Quad Type of Address

6 **14th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 6 14th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0037 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1886** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1886** **Permit** **500 Permit**

Construction Event Association Associated Name

Fitzhugh, M.B. Mrs. **Owner** **Fitzhugh, M.B. Mrs.**

Orig Construction **Builder** **Rodgers, W.L.**

Construction Notes:

One of eight rowhouses constructed from the same permit (#1870), of which only four are extant.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **26**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Vernacular

Exterior & Architectural Notes:

April 2010: Constructed in 1886 by W.L. Rodgers, this two-story, two-bay vernacular single-family dwelling was influenced by the Italianate style. The dwelling was originally one of eight similar dwellings constructed from the same permit (#1870), but in 2010 only four are extant. The wood-frame dwelling is clad with vinyl siding and is set on a solid brick foundation. A sloping roof caps the dwelling and is highlighted by a molded wood cornice with modillions and scrolled brackets. The northernmost bay of the façade (west elevation) holds a single-leaf paneled wood door with lights. Additional openings on the façade hold single and paired 6/6, double-hung, wood-sash windows. The second story openings have molded lintels and are flanked by inoperable paneled shutters. A one-story, two-bay porch spans the façade and is set on a solid foundation. Square wood posts support the second story, which serves as a deck. Square wood balusters encircle each level of the porch. Visible fenestration on the rear (east) elevation consists of 6/6, double-hung, wood-sash windows.

Site Notes:

April 2010: This two-story single-family dwelling is located on the east side of 14th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 4 and 8 14th Street, S.E. The landscaped front yard features mature shrubs and foundation plantings and is encircled by a brick retaining wall topped by a metal fence. A stone walkway leads from the primary entrance of the dwelling and ends at the sidewalk. A wood fence encircles the rear yard. An alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 6_14th_Street_SE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 6_14th_Street_SE_facade_looking_SE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 6_14th_Street_SE_rear_looking_W.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/15/1886	1870	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0036

BASICS DATA

ID Number: **1058-0036** Year Built: **1886** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
8		14th Street	SE	Current

Name(s)	Type of Name
Rowhouse, 8 14th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1058/0036			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1886	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1886	Permit			500 Permit

Construction Event	Association	Associated Name
Orig Construction	Builder	Rodgers, W.L.
Orig Construction	Owner	Fitzhugh, M.B. Mrs.

Construction Notes:

One of eight rowhouses constructed from the same permit (#1870), of which only four are extant.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 4)**
Relate to Street: **Face on Setback Line**
Massing: **Row Building/Front Porch**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**
Height:
Width: **13**
Depth/Length: **26**

Outbuilding Type	Contributing Status
------------------	---------------------

SqFt:
Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Vernacular

Exterior & Architectural Notes:

April 2010: Constructed in 1886 by W.L. Rodgers, this two-story, two-bay vernacular single-family dwelling was influenced by the Italianate style. The dwelling was originally one of eight similar dwellings constructed from the same permit (#1870), but in 2010 only four are extant. The wood-frame dwelling is clad with wood siding and is set on a solid brick foundation. A sloping roof caps the dwelling and is highlighted by a molded wood cornice. The southernmost bay of the façade (west elevation) holds a single-leaf wood-frame glass door. Additional openings on the façade hold single-leaf wood-frame glass doors and a one-light fixed wood window. A one-story, one-bay porch spans the façade and is set on a solid foundation. The flat roof of the porch is supported by metal filigree posts. Metal balusters encircle the porch, which is accessed via steps in the southern end bay.

A two-story enclosed porch is located on the rear elevation of the dwelling. The wood-frame enclosed porch is clad with T-111 siding and is capped by a sloping roof. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the east side of 14th Street, S.E. and is set back approximately ten feet from the sidewalk. The dwelling is adjacent to 6 and 10 14th Street, S.E. The front yard is landscaped with mature shrubs and trees and is bounded by a brick retaining wall. A wood fence encloses the rear yard of the property. An alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 8_14th_Street_SE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 8_14th_Street_SE_facade_looking_SE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1058\
File: 8_14th_Street_SE_rear_looking_W.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/15/1886	1870	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0035

BASICS DATA

ID Number: **1058-0035** Year Built: **1886** Data Source: **Permit**

Number Extended Street Quad Type of Address

10 **14th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 10 14th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0035 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1886** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1886** **Permit** **500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Rodgers, W.L.**

Orig Construction **Builder** **Fitzhugh, M.B. Mrs.**

Construction Notes:

One of eight rowhouses constructed from the same permit (#1870), of which only four are extant.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **26**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Vernacular

Exterior & Architectural Notes:

April 2010: Constructed in 1886 by W.L. Rodgers, this two-story, two-bay vernacular single-family dwelling was influenced by the Italianate style. The dwelling was originally one of eight similar dwellings constructed from the same permit (#1870), but in 2010 only four are extant. The wood-frame dwelling is clad with Hardiplank siding and is set on a solid brick foundation. A sloping roof caps the dwelling and is highlighted by a molded wood cornice with scrolled end brackets. The northernmost bay of the façade (west elevation) holds a single-leaf paneled wood door with lights and a single-light transom. Additional openings on the façade hold 1/1, double-hung, wood-sash windows. A one-story, full-width porch spans the façade and is set on a solid brick foundation. Chamfered square wood posts with wood spindlework support the flat roof of the porch. Wood balusters encircle the porch, which is accessed via steps in the northern end bay. Visible fenestration on the rear (east) elevation consists of 1/1, double-hung, vinyl-sash windows.

A one-story, one-bay addition extends from the northern bay of the rear elevation. The wood-frame addition is clad with Hardiplank siding and is capped by a sloping roof. An interior brick chimney pierces the roof. An additional one-story addition projects from the rear addition and was not visible from the public right-of-way.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the east side of 4th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 8 and 12 4th Street, S.E. The sloping front yard is landscaped with mature shrubs and is encircled by a metal fence. A wood fence encloses the rear yard of the property. An alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Contributing.

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 10_14th_Street_SE_facade_looking_E.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 10_14th_Street_SE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 10_14th_Street_SE_rear_looking_W.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/15/1886	1870	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0034

BASICS DATA

ID Number: **1058-0034** Year Built: **1886** Data Source: **Permit**

Number Extended Street Quad Type of Address

12 **14th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 12 14th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0034 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1886** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1886** **Permit** **500 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Rodgers, W.L.**

Orig Construction **Owner** **Fitzhugh, M.B. Mrs.**

Construction Notes:

One of eight rowhouses constructed from the same permit (#1870), of which only four are extant.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **26**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Vernacular

Exterior & Architectural Notes:

April 2010: Constructed in 1886 by W.L. Rodgers, this two-story, two-bay vernacular single-family dwelling was influenced by the Italianate style. The dwelling was originally one of eight similar dwellings constructed from the same permit (#1870), but in 2010 only four are extant. The wood-frame dwelling is clad with Hardiplank siding and is set on a solid brick foundation. A sloping roof caps the dwelling and is highlighted by a molded wood cornice with scrolled modillions, end brackets, and dentils. The northernmost bay of the façade (west elevation) holds a single-leaf paneled wood door and a single-light transom. Additional openings on the façade hold 6/6, double-hung, wood-sash windows. Molded lintel hoods accent the second story openings. A one-story, full-width porch spans the façade and is set on a solid brick foundation. Turned wood posts with wood spindlework support the flat roof of the porch. Wood balusters encircle the porch, which is accessed via steps in the northern end bay. Visible fenestration on the rear (east) elevation consists of 6/6, double-hung, wood-sash windows.

A two-story, one-bay ell extends from the northern bay of the rear elevation. The wood-frame addition is clad with German vinyl siding and is capped by a sloping roof. Visible fenestration consists of 6/6, double-hung, wood-sash windows.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the east side of 14th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 10 and 14 14th Street, S.E. The sloping front yard is landscaped with mature shrubs, trees, and foundation plantings. A brick walkway leads from the sidewalk and ends at the front porch of the dwelling. The rear yard is landscaped with mature shrubs and trees and is encircled by a wood fence. An alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:
Contributing:

Designation Event(s) _____

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 12_14th_Street_SE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 12_14th_Street_SE_facade_looking_SE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 12_14th_Street_SE_rear_looking_W.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/15/1886	1870	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0081

BASICS DATA

ID Number: **1058-0081** Year Built: **1891** Data Source: **Permit**

Number Extended Street Quad Type of Address

14 **14th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 14 14th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0081 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multifamily/Misc) **1891** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit** **1000 Permit**

Construction Event Association Associated Name

Kelley, W.E.S. Mrs. **Owner** **Kelley, W.E.S. Mrs.**

Orig Construction **Builder** **Mandley, W.H.**

Construction Notes:

One of four rowhouses constructed from the same permit (#0023).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Bldg (Rect. Bay)**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

April 2010: Constructed in 1891 by William H. Mandley, this two-story, two-bay Queen Anne-style single-family dwelling is one of four similar dwellings constructed from the same permit (#0023). The dwelling is constructed of brick and is set on a solid brick foundation; the façade (west elevation) is faced with American-bond brick. A two-course, brick string course spans the façade and is located between the first and second stories. A sloping roof caps the dwelling and is fronted along the façade by a molded metal cornice with brick corbelling and dentils. The southernmost bay of the façade holds a single-leaf wood-frame glass door and a single-light wood transom. A rowlock brick segmental arch with pearl molding surmounts the transom. A three-sided, rectangular bay extends from the northern bay of the façade and rises the full height of the building. The bay has the material treatment of the main block and features a brick watertable. All window openings on the façade hold 2/2, double-hung, wood-sash, which have concrete sills and rowlock brick segmental arches with pearl molding. Visible fenestration on the rear (east) elevation consists of 6/6, double-hung, wood-sash windows.

An ell extends from the southern bay of the rear elevation and is parged. An interior chimney rises from the rear elevation of the ell. The ell was not visible from the public right-of-way.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the east side of 14th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 12 and 16 14th Street, S.E. The sloping front yard is landscaped with mature shrubs. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard features mature trees and is encircled by a wood fence. An alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:
Contributing:

Designation Event(s) _____

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 14_14th_Street_SE_facade_looking_E.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 14_14th_Street_SE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 14_14th_Street_SE_rear_looking_W.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/06/1891	0023	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0082

BASICS DATA

ID Number: **1058-0082** Year Built: **1891** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
16		14th Street	SE	Current

Name(s)	Type of Name
Rowhouse, 16 14th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1058/0082			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1891	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1891	Permit			1000 Permit

Construction Event	Association	Associated Name
Orig Construction	Builder	Mandley, W.H.
Orig Construction	Owner	Kelley, W.E.S. Mrs.

Construction Notes:

One of four rowhouses constructed from the same permit (#0023).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 4)**
Relate to Street: **Face on Setback Line**
Massing: **Row Bldg (Rect. Bay)**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type	Contributing Status
------------------	---------------------

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

April 2010: Constructed in 1891 by William H. Mandley, this two-story, two-bay Queen Anne-style single-family dwelling is one of four similar dwellings constructed from the same permit (#0023). The dwelling is constructed of brick and is set on a solid brick foundation; the façade (west elevation) is faced with American-bond brick. A two-course, brick string course spans the façade and is located between the first and second stories. A sloping roof caps the dwelling and is fronted along the façade by a molded metal cornice with brick corbelling and dentils. The southernmost bay of the façade holds a single-leaf, paneled wood door with lights and a single-light wood transom. A rowlock brick segmental arch with pearl molding surmounts the transom. A three-sided, rectangular bay extends from the northern bay of the façade and rises the full height of the building. The bay has the material treatment of the main block and features a brick watertable. All window openings on the façade hold 1/1, double-hung, vinyl-sash, which have concrete sills and rowlock brick segmental arches with pearl molding. Visible fenestration on the rear (east) elevation consists of double-hung windows.

An ell extends from the northern bay of the rear elevation and is parged. An interior chimney rises from the rear elevation of the ell. Visible fenestration consists of double-hung windows and a single-leaf paneled door with lights and a single-light transom.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the east side of 14th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 14 and 18 14th Street, S.E. The front yard features mature shrubs. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard features mature trees and is enclosed by a wood fence. An alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:
Contributing:

Designation Event(s) _____

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 16_14th_Street_SE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 16_14th_Street_SE_facade_looking_SE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 16_14th_Street_SE_rear_looking_W.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/06/1891	0023	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0083

BASICS DATA

ID Number: **1058-0083** Year Built: **1891** Data Source: **Permit**

Number Extended Street Quad Type of Address

18 **14th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 18 14th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0083 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit** **1000 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Mandley, W.H.**

Orig Construction **Owner** **Kelley, W.E.S. Mrs.**

Construction Notes:

One of four rowhouses constructed from the same permit (#0023).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Bldg (Rect. Bay)**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Non-Contributing

Outbuilding Notes:

April 2010: This one-story, one-bay wood pergola is located east of the dwelling. It was constructed c. 2000. Wood cross beams are supported by wood posts and brackets.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

April 2010: Constructed in 1891 by William H. Mandley, this two-story, two-bay Queen Anne-style single-family dwelling is one of four similar dwellings constructed from the same permit (#0023). The dwelling is constructed of brick and is set on a solid brick foundation; the façade (west elevation) is faced with American-bond brick. A two-course, brick string course spans the façade and is located between the first and second stories. A sloping roof caps the dwelling and is fronted along the façade by a molded metal cornice with brick corbelling and dentils. The southernmost bay of the façade holds a single-leaf, wood-frame glass door and a single-light wood transom. A shed-roofed awning shelters the primary entrance of the dwelling. A rowlock brick segmental arch with pearl molding surmounts the transom. A three-sided, rectangular bay extends from the northern bay of the façade and rises the full height of the building. The bay has the material treatment of the main block and features a brick watertable. All window openings on the façade hold 1/1, double-hung, vinyl-sash, which have concrete sills and rowlock brick segmental arches with pearl molding. Visible fenestration on the rear (east) elevation consists of 1/1, double-hung, vinyl-sash windows.

An ell extends from the southern bay of the rear elevation and is parged. An interior chimney rises from the rear elevation of the ell. Visible fenestration consists of 1/1, double-hung, vinyl-sash windows, which have concrete sills.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the east side of 14th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 16 and 20 14th Street, S.E. The landscaped front yard is planted with mature shrubs and plantings and is encircled by a metal fence. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. A wood fence encircles the rear yard of the property, where a wood-frame pergola is sited. An alley is located east of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 18_14th_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 18_14th_Street_SE_facade_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 18_14th_Street_SE_pergola_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 18_14th_Street_SE_rear_looking_W.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/06/1891	0023	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0084

BASICS DATA

ID Number: **1058-0084** Year Built: **1891** Data Source: **Permit**

Number Extended Street Quad Type of Address

20 **14th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 20 14th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1058/0084 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1891** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1891** **Permit** **1000 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Mandley, W.H.**

Orig Construction **Owner** **Kelley, W.E.S. Mrs.**

Construction Notes:

One of four rowhouses constructed from the same permit (#0023).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 4)**

Relate to Street: **Face on Setback Line**

Massing: **Row Bldg (Rect. Bay)**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Shed

Contributing Status

Non-Contributing

Outbuilding Notes:

April 2010: A one-story, one-bay shed is located east of the dwelling and was constructed c. 1980. The wood-frame shed is clad with plywood and is capped by a sloping roof of asphalt shingles. Fenestration was not visible from the public right-of-way.

STYLE/EXTERIOR DATA

Architectural Style(s)

Queen Anne

Exterior & Architectural Notes:

April 2010: Constructed in 1891 by William H. Mandley, this two-story, two-bay Queen Anne-style single-family dwelling is one of four similar dwellings constructed from the same permit (#0023). The dwelling is constructed of brick and is set on a solid brick foundation; the façade (west elevation) is faced with American-bond brick. A two-course, brick string course spans the façade and is located between the first and second stories. A sloping roof caps the dwelling and is fronted along the façade by a molded metal cornice with brick corbelling and dentils. The southernmost bay of the façade holds a single-leaf, paneled wood door and a single-light wood transom. A rowlock brick segmental arch with pearl molding surmounts the transom. A three-sided, rectangular bay extends from the northern bay of the façade and rises the full height of the building. The bay has the material treatment of the main block and features a brick watertable. All window openings on the façade hold 2/2, double-hung, wood-sash, which have concrete sills and rowlock brick segmental arches with pearl molding. The south elevation of the dwelling is parged. Visible fenestration on the rear (east) elevation consists of 6/6, double-hung, wood-sash windows.

An ell extends from the northern bay of the rear elevation and is parged. An interior chimney rises from the rear elevation of the ell. Visible fenestration consists of 6/6, double-hung, wood-sash windows, which have concrete sills.

A one-story addition is located in the ell and was constructed c. 1970. The wood-frame addition is clad with Hardieplank siding and is capped by a sloping roof. There is no visible fenestration.

Site Notes:

April 2010: This two-story, single-family dwelling is located on the east side of 14th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The north (side) elevation of the dwelling is adjacent to 18 14th Street, S.E. The sloping front yard is landscaped with mature shrubs and is partially bounded by a metal chain-link fence. A brick walkway leads from the primary entrance of the dwelling and ends at the sidewalk. The rear yard is enclosed by a wood fence.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **20_14th_Street_SE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **20_14th_Street_SE_facade_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **20_14th_Street_SE_rear_looking_NW.JPG.JP
G**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058**

File: **20_14th_Street_SE_shed.JPG.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
07/06/1891	0023	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1058-0080

BASICS DATA

ID Number: **1058-0080** Year Built: **c. 1980** Data Source: **Site Visit/Map**

Number	Extended	Street	Quad	Type of Address
26		14th Street	SE	Current

Name(s)	Type of Name
Apartment Building, 26 14th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1058/0080			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Not Historic** Quality:
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Multi-Family)	c. 1980	Site Visit/			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	c. 1980	Site Visit/Map			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Detached**
Relate to Street: **Front Yard w/ Setback**
Massing: **Block**
Footprint: **Rectangular**

Number Stories: **3**
Bays Wide: **5**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

April 2010: Constructed c. 1980, this three-story, five-bay Modern apartment building is of masonry construction and is similar to 1408 A Street, S.E. The building is faced with six-course, American-bond brick and is set on a solid foundation. Brick beltcourses encircle the building at the first, second, and third story sill level. A flat roof caps the building and is pierced by interior brick chimneys on the east and west (side) elevations. The central bay of the façade (south elevation) projects from the façade and is pierced by single-leaf wood-frame glass door with a surround composed of T-111 siding. Additional fenestration on the façade consists of single and paired 1/1, double-hung, vinyl-sash windows, which feature rowlock brick sills. The east and west (side) elevations have fenestration that is consistent with the façade.

Site Notes:

April 2010: This three-story apartment building is located at the northwest corner of 14th Street, S.E. and A Street, S.E. and is set back from the brick sidewalk approximately forty feet. The freestanding building is oriented towards A Street, S.E. though it has a 14th Street, S.E. address. The building is set on a level grassy lot that is bounded by a brick retaining wall topped by a metal chain-link fence. Foundation plantings landscape the property. A concrete walkway leads from the primary entrance of the building and exits onto the 14th Street, S.E. sidewalk.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill Southeast Phase II (2010)	Permit Research Reconnaissance Survey

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 26_14th_Street_SE_facade_looking_N.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 26_14th_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 26_14th_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 26_14th_Street_1408_A_Street_SE_looking_N
W.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 26_14th_Street_1408_A_Street_SE_looking_S
W.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1058\
File: 26_14th_Street_SE_side_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA
