

# Resource All Data Report

**ID Number: 1064-0815**

## BASICS DATA

ID Number: **1064-0815** Year Built: **1901** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1413** **G Street** **SE** **Current**

Name(s) Type of Name

**Single Dwelling, 1413 G Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1064/0815** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1901** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1901** **Permit** **2400 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Plager, W.S.**

**Orig Construction** **Builder** **Sourwine, F.D.**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-five rowhouses constructed from the same permit (#1124), of which thirteen are extant. It is the only rowhouse from this permit constructed on G Street, S.E. that is still standing.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **16**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Colonial Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1901 by F.D. Sourwine from the design of W.S. Plager, this two-story, three-bay, Colonial Revival-style, single-family brick rowhouse is one of thirteen similar rowhouses constructed from the same permit (#1124). This dwelling is constructed of brick and is set on a solid concrete foundation; the façade (southeast elevation) has been faced with stretcher-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a prominent molded architrave with dentils, a brick parapet wall, and a molded cornice set between brick firewalls finish the roof. Stone string courses span the façade of the first and second story windows and are located beneath the window openings. Also, stone string courses span the façade at lintel level on the foundation and second stories. Square billet panels span the façade above the second story. The basement has been converted into livable space and the foundation is pierced with a single-leaf door in the western bay. Steps lead down to this opening. The eastern bay of the first story holds a single-leaf door and a storm door and is topped with a rectangular one-light transom. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows. A one-story, one-bay concrete porch spans the façade on the first story and is set on a stone pier foundation. The flat roof of the porch has molded, overhanging eaves and is supported by Tuscan wood columns. Turned wood balusters complete the porch. The west (side) elevation is faced with five-course American-bond brick. The foundation is pierced by two one-light windows (possibly fixed) with concrete-lug sills and two-course rowlock brick arches in the central bays. This elevation is also fenestrated with three 1/1, double-hung, vinyl-sash windows with concrete-lug sills and two-course rowlock brick arches on the first and second stories. An interior brick chimney rises from the center of the elevation. The foundation and a portion of the first story of the rear (south) elevation were obscured by the rear fence. The rear elevation is faced with five-course American-bond brick. The western bay of the elevation holds a single-leaf wood-frame glass door. A two-course, rowlock brick segmental arch highlights the opening. All other openings hold 1/1, double-hung, vinyl-sash windows with concrete lug sills and are topped by two-course, rowlock brick segmental arches. A wood deck with wood balusters extends from the rear elevation.

Site Notes:

**March 2008:** This rowhouse is located on the south side of G Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 1415 G Street, S.E. and abuts a paved walkway to the west. The rowhouse is fronted by raised, grassy front yard with immature shrubs and plants. Poured concrete steps lead from the primary entrance to the concrete sidewalk. A masonry retaining wall lines the front of the property and runs parallel to the sidewalk. A small backyard is located at the rear of the property and is enclosed by a metal and wood privacy fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**  
File: **1413G1\_SW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**  
File: **1413G2\_S.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**  
File: **1413G3\_SE.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

8/16/2013

DC HPO Survey - Southeast Phase II

ID\_Number: 1064-0815 Page 3

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
02/14/1901	1124	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1064-0034**

## BASICS DATA

ID Number: **1064-0034** Year Built: **1901** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1415** **G Street** **SE** **Current**

Name(s) Type of Name

**Single Dwelling, 1415 G Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1064/0034** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1901** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1901** **Permit** **1500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Plager, W.S.**

**Orig Construction** **Builder** **Pickford, W.E.**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **16**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Colonial Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1901 by W.E. Pickford from the design of W.S. Plager, this two-story, three-bay, Colonial Revival-style, semi-detached, single-family brick dwelling was constructed from permit #1491. This dwelling is constructed of brick and is set on a solid concrete foundation; the façade (southeast elevation) has been faced with stretcher-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a prominent molded architrave with dentils, a brick parapet wall, and a molded cornice set between brick firewalls finish the roof. Stone string courses span the façade of the first and second story windows and are located beneath the window openings. Also, a stone string course spans the façade at lintel level on the second story. Square billet panels span the façade above the second story. The western bay of the first story holds a single-leaf paneled door with a leaded glass oval and is topped with a rectangular transom. The door also has a soldier-brick lintel. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows. A one-story, one-bay concrete porch spans the façade on the first story and is set on a stone pier foundation with stone infill. The flat roof of the porch has molded, overhanging eaves and is supported by Tuscan wood columns. Turned wood balusters complete the porch. The east (side) elevation is faced with five-course American-bond brick. The foundation was obscured by the rear fence, but the elevation is fenestrated with three 1/1, double-hung, vinyl-sash windows with concrete-lug sills and two-course rowlock brick arches on the first and second stories. An interior brick chimney rises from the center of the elevation. The foundation and a portion of the first story of the rear (south) elevation were obscured by the rear fence. The rear elevation is faced with five-course American-bond brick. The western bay of the elevation holds a single-leaf door. A two-course, rowlock brick segmental arch highlights the opening. All other openings hold 1/1, double-hung, vinyl-sash windows with wood sills. The window in the western bay on the second story is topped with a two-course, rowlock brick segmental arch. A wood deck with wood balusters extends from the rear elevation.

Site Notes:

**March 2008:** This rowhouse is located on the south side of G Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 1413 G Street, S.E. The rowhouse is fronted by raised, grassy front yard dotted with plants. Poured concrete steps with metal hand rails lead from the primary entrance to the concrete sidewalk. A concrete walkway also runs along the side (east elevation) of the house to steps leading down to the concrete sidewalk. A masonry retaining wall lines the front of the property and runs parallel to the sidewalk. A small backyard is located at the rear of the property and is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unkown w/Lights</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

---

## PLAN/SURVEY/DESIGNATION DATA

---

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

---

## PHOTOS - DIGITIZED

---

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\  
File: 1415G1\_S.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\  
File: 1415G2\_S.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\  
File: 1415G3\_S.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\

File: 1415G4\_SW.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\

File: 1415G5\_NW.JPG

Date:: Photog:

Code:: R: Fr:



#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

#### MISCELLANEOUS NOTES DATA

Notes:

#### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

04/18/1901	1491	Build	
------------	------	-------	--

Permit Notes:

#### BIBLIOGRAPHIC DATA

#### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

#### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1064-0816**

## BASICS DATA

ID Number: **1064-0816** Year Built: **1901** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1412** **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1412 Potomac Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1064/0816** **Square/Lot** **Current**

**1064/0014** **Square/Lot** **Historic**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1901** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1901** **Permit** **2400 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Plager, W.S.**

**Orig Construction** **Builder** **Sourwine, F.D.**

**Orig Construction** **Owner** **Pickford, W.E.**

Construction Notes:

One of twenty-five rowhouses constructed from the same permit (#1124), of which thirteen are extant. One of twelve consecutive rowhouses constructed along Potomac Avenue, S.E.

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row End (1 of 12)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Front Porch**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **3**

Height:

Outbuilding Type

Contributing Status

Width: **16**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Colonial Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1901 by F.D. Sourwine from the design of W.S. Plager, this two-story, three-bay, Colonial Revival-style, single-family brick rowhouse is one of thirteen similar rowhouses constructed from the same permit (#1124). This dwelling is constructed of brick and is set on a solid concrete foundation; the façade (southeast elevation) has been faced with stretcher-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a molded cornice with dentils, brick end brackets, and a molded architrave finish the roof. Stone string courses span the façade of the first and second story windows and are located beneath the window openings. Also, a stone string course spans the façade at lintel level on the second story. Decorative panels with pateras span the façade above the second story. The southwest bay of the first story holds a single-leaf paneled wood door and storm door and is topped with a rectangular one-light transom. All window openings on the façade hold 6/6, double-hung, wood-sash windows. A one-story, two-bay porch extends across the façade and is set on a stone pier foundation that has been infilled with stone. The roof of the porch (possibly flat) has overhanging eaves and is supported by square wood posts. Metal balusters and poured concrete steps with stone wing walls in the southwest end bay complete the porch. The southwest (side) elevation is faced with stretcher-bond brick. The foundation and a portion of the first story of the rear (northwest) elevation were obscured by the rear fence. A two-story ell extends from the southwest bay of the rear elevation and is original to the main block. The rear elevation of the ell is faced with five-course American-bond brick that has been painted. The northeast bay of the ell holds a single-leaf wood door with lights and a metal storm door topped by a rectangular one-light transom. A two-course, rowlock brick segmental arch highlights the opening. The southwest bay holds a 6/6, double-hung, wood-sash window, also topped by a two-course, rowlock brick segmental arch. The windows on the second story have been replaced by a three-sided canted oriel window. The central opening holds a one-light fixed vinyl window and the flanking openings contain 1/1, double-hung, vinyl-sash windows. An original rowlock brick segmental arch can be seen in the southwest bay of the second story.

Site Notes:

**March 2008:** This end-unit rowhouse is located on the northwest side of Potomac Avenue, S.E. and is set back approximately thirty feet from the concrete sidewalk. The dwelling is adjacent to 1414 Potomac Avenue, S.E. and is fronted by a raised, grassy front yard. A metal fence encloses the property on the southeast border, while mature shrubs form barriers on the northeast and southwest boundaries. A concrete walkway leads from the primary entrance and terminates with steps leading down to the concrete sidewalk. A retaining wall, constructed of brick, lines the front of the property and runs parallel to the sidewalk. A small backyard, enclosed by a stretcher-bond brick wall, is located at the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	

Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>6/6</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s) \_\_\_\_\_ Notable Interior Feature(s) \_\_\_\_\_

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s) _____
Subdivision: _____	
Ward/ANC: _____	
Zoning: _____	Designation Event(s) _____
Contributing: _____	
Survey(s) _____	Level(s) of Investigation _____
<b>Capitol Hill Southeast Phase I (2009/2010)</b>	<b>Permit Research</b>
	<b>Volunteer Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**  
File: **1412Potomac1\_NW.JPG**

Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\

File: 1412Potomac2\_N.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\

File: 1412Potomac3\_SE.JPG

Date:: Photog:

Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
02/14/1901	1124	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1064-0809**

## BASICS DATA

ID Number: **1064-0809** Year Built: **1901** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1414** **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1414 Potomac Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1064/0809** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1901** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1901** **Permit** **2400 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Plager, W.S.**

**Orig Construction** **Builder** **Sourwine, F.D.**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-five rowhouses constructed from the same permit (#1124), of which thirteen are extant. One of twelve consecutive rowhouses constructed along Potomac Avenue, S.E.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 12)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **16**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

March 2008: Constructed in 1901 by F.D. Sourwine from the design of W.S. Plager, this two-story, three-bay, Colonial Revival-style, single-family brick rowhouse is one of thirteen similar rowhouses constructed from the same permit (#1124). This dwelling is constructed of brick and is set on a solid concrete foundation; the façade (southeast elevation) has been faced with stretcher-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a molded cornice with dentils, brick end brackets, and a molded architrave set between brick firewalls finish the roof. Stone string courses span the façade of the first and second story windows and are located beneath the window openings. Also, stone string courses span the façade at lintel level on the first and second stories. Decorative panels with interlace details span the façade above the second story. The southwest bay of the first story holds a single-leaf paneled door and metal security door and is topped with a rectangular one-light transom. The door opening is highlighted by a stone string course beneath. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows. The windows on the first story have metal grilles. Poured concrete steps with wing walls in the southwest bay complete the façade. The foundation and a portion of the first story of the rear (northwest) elevation were obscured by the rear fence. A two-story ell extends from the southwest bay of the rear elevation and is original to the main block. The rear elevation is faced with five-course American-bond brick that has been painted. The northeast bay of the ell holds a single-leaf paneled wood door and a metal storm door topped by a rectangular one-light transom. A two-course, rowlock brick segmental arch highlights the opening. All other openings on the rear elevation hold 1/1, double-hung, vinyl-sash windows, which are also topped by two-course, rowlock brick segmental arches. The windows on the first story have metal grilles.

Site Notes:

March 2008: This rowhouse is located on the northwest side of Potomac Avenue, S.E. and is set back approximately thirty feet from the concrete sidewalk. The dwelling is adjacent to 1412 Potomac Avenue, S.E. and 1416 Potomac Avenue, S.E. The rowhouse is fronted by a raised, grassy front yard with mature shrubs, foundation plantings, and plants. Wood planting walls divide the yard and mature shrubs form barriers on the northeast and southwest boundaries. A concrete walkway leads from the primary entrance and terminates with steps leading down to the concrete sidewalk. A retaining wall, constructed of stone, lines the front of the property and runs parallel to the sidewalk. A small backyard, enclosed by a stretcher-bond brick wall and a wood privacy fence, is located at the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\  
File: 1414Potomac1\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\  
File: 1414Potomac2\_SE.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

<b>02/14/1901</b>	<b>1124</b>	<b>Build</b>	
-------------------	-------------	--------------	--

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

---

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 1064-0811**

## BASICS DATA

ID Number: **1064-0811** Year Built: **1901** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1416** **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse,1416 Potomac Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1064/0811** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1901** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1901** **Permit** **2400 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Plager, W.S.**

**Orig Construction** **Builder** **Sourwine, F.D.**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-five rowhouses constructed from the same permit (#1124), of which thirteen are extant. One of twelve consecutive rowhouses constructed along Potomac Avenue, S.E.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 12)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **16**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1901 by F.D. Sourwine from the design of W.S. Plager, this two-story, three-bay, Colonial Revival-style, single-family brick rowhouse is one of thirteen similar rowhouses constructed from the same permit (#1124). This dwelling is constructed of brick and is set on a solid concrete foundation; the façade (southeast elevation) has been faced with stretcher-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a prominent molded architrave with dentils, a brick parapet wall, and a molded cornice set between brick firewalls finish the roof. Stone string courses span the façade of the first and second story windows and are located beneath the window openings. Also, stone string courses span the façade at lintel level on the second story. Decorative inset panels with beads span the façade above the second story. The southwest bay of the first story holds a single-leaf paneled wood door and metal security door and is topped with a rectangular one-light transom. The door opening is highlighted by a stone string course beneath. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows. The windows on the first story have metal grilles. A one-story, two-bay porch extends across the façade and is set on a stone pier foundation. The roof of the porch (possibly flat) has overhanging eaves and is supported by metal filigree posts. Metal balusters and poured concrete steps with stone wing walls in the southwest end bay complete the porch. The foundation and a portion of the first story of the rear (northwest) elevation were obscured by the rear fence. A two-story ell extends from the southwest bay of the rear elevation and is original to the main block. The rear ell is faced with five-course American-bond brick. The northeast bay of the ell holds a single-leaf wood-frame glass door and a metal storm door topped by a rectangular one-light transom. A two-course, rowlock brick segmental arch highlights the opening. All other openings on the rear ell hold 1/1, double-hung, vinyl-sash windows, which are also topped by two-course, rowlock brick segmental arches. The window on the first story has a metal grille.

Site Notes:

**March 2008:** This rowhouse is located on the northwest side of Potomac Avenue, S.E. and is set back approximately thirty feet from the concrete sidewalk. The dwelling is adjacent to 1414 Potomac Avenue, S.E. and 1418 Potomac Avenue, S.E. The rowhouse is fronted by a raised, grassy front yard with mature shrubs. A metal picket fence borders the yard. A concrete walkway lined with a low brick wall leads from the primary entrance and terminates with steps leading down to the concrete sidewalk. A retaining wall, constructed of stone, lines the front of the property and runs parallel to the sidewalk. A small backyard, enclosed by a wood privacy fence, is located at the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			
<b>Walls</b>	<b>Concrete</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**  
File: **1416Potomac1\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**  
File: **1416Potomac2\_SE.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>02/14/1901</b>	<b>1124</b>	<b>Build</b>	

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

---

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 1064-0813**

## BASICS DATA

ID Number: **1064-0813** Year Built: **1901** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1418** **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1418 Potomac Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1064/0813** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1901** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1901** **Permit** **2400 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Plager, W.S.**

**Orig Construction** **Builder** **Sourwine, F.D.**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-five rowhouses constructed from the same permit (#1124), of which thirteen are extant. One of twelve consecutive rowhouses constructed along Potomac Avenue, S.E.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 12)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **16**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Colonial Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1901 by F.D. Sourwine from the design of W.S. Plager, this two-story, three-bay, Colonial Revival-style, single-family brick rowhouse is one of thirteen similar rowhouses constructed from the same permit (#1124). This dwelling is constructed of brick and is set on a solid concrete foundation; the façade (southeast elevation) has been faced with stretcher-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a prominent molded architrave with dentils, a brick parapet wall, and a molded cornice set between brick firewalls finish the roof. Stone string courses span the façade of the first and second story windows and are located beneath the window openings. Also, stone string courses span the façade at lintel level on the second story. Decorative panels with pateras span the façade above the second story. The southwest bay of the first story holds a single-leaf door and metal security door and is topped with a rectangular one-light transom. The door opening is highlighted by a concrete lintel and stone string course at lintel level. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows. The windows on the first story have metal grilles. A one-story, one-bay porch extends across the façade and is set on a brick pier foundation. The roof of the porch (possibly flat) has overhanging eaves and is supported by square brick posts. Metal balusters and poured concrete steps in the southwest end bay complete the porch. The foundation and a portion of the first story of the rear (northwest) elevation were obscured by the rear fence. A two-story ell extends from the southwest bay of the rear elevation and is original to the main block. The rear ell is faced with five-course American-bond brick. The northeast bay of the ell holds a single-leaf paneled door with an inset half-circle light and a storm door topped by a blind transom. A two-course, rowlock brick segmental arch highlights the opening. All other openings on the rear ell hold 1/1, double-hung, vinyl-sash windows, which are also topped by two-course, rowlock brick segmental arches. The window on the first story has a metal grille.

Site Notes:

**March 2008:** This rowhouse is located on the northwest side of Potomac Avenue, S.E. and is set back approximately thirty feet from the concrete sidewalk. The dwelling is adjacent to 1416 Potomac Avenue, S.E. and 1420 Potomac Avenue, S.E. The rowhouse is fronted by a raised, grassy front yard with mature shrubs. A concrete walkway leads from the primary entrance and terminates with steps leading down to the concrete sidewalk. A retaining wall, constructed of stone, lines the front of the property and runs parallel to the sidewalk. A small backyard, enclosed by a wood privacy fence, is located at the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\  
File: 1418Potomac1\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\  
File: 1418Potomac2\_E.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

<b>02/14/1901</b>	<b>1124</b>	<b>Build</b>	
-------------------	-------------	--------------	--

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

---

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 1064-0029**

## BASICS DATA

ID Number: **1064-0029** Year Built: **1901** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1420** **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1420 Potomac Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1064/0029** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1901** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1901** **Permit** **2400 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Plager, W.S.**

**Orig Construction** **Builder** **Sourwine, F.D.**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-five rowhouses constructed from the same permit (#1124), of which thirteen are extant. One of twelve consecutive rowhouses constructed along Potomac Avenue, S.E.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 12)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **16**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Colonial Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1901 by F.D. Sourwine from the design of W.S. Plager, this two-story, three-bay, Colonial Revival-style, single-family brick rowhouse is one of thirteen similar rowhouses constructed from the same permit (#1124). This dwelling is constructed of brick and is set on a solid concrete foundation; the façade (southeast elevation) has been faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a prominent molded architrave with dentils, a brick parapet wall, and a molded cornice set between brick firewalls finish the roof. Stone string courses span the façade of the first and second story windows and are located beneath the window openings. Also, stone string courses span the façade at lintel level on the foundation level, first, and second stories. Decorative panels with an interlace motif span the façade above the second story. The foundation is pierced by two 1/1, double-hung vinyl-sash windows with metal grilles in the northeastern bays. The southwest bay of the first story holds a single-leaf paneled wood door and is topped with a rectangular one-light transom. The door opening is highlighted by a wood surround and entablature. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows. The windows on the first story have metal grilles. Brick steps with metal hand rails in the southwest end bay complete the facade. The foundation and a portion of the first story of the rear (northwest) elevation were obscured by the rear fence. A two-story ell extends from the southwest bay of the rear elevation and is original to the main block. The rear ell is faced with five-course American-bond brick that has been painted. The northeast bay of the ell holds a single-leaf door topped by a one-light transom. A two-course, rowlock brick segmental arch highlights the opening. An opening in the southwest bay of the first story of the rear ell holds a 1/1, double-hung window which also has a two-course, rowlock brick segmental arch. The window on the first story has a metal grille. On the second story, the northeast opening holds a 1/1, double-hung, vinyl-sash window and the southwest opening holds a multi-light wood-frame glass door with a one-light transom. The door is highlighted by a two-course rowlock brick segmental arch. A one-story, two-bay, wood porch spans the façade on the second story and is supported by square wood posts. The porch has turned wood balusters and a slightly pitched roof. The northeast (side) elevation of the rear ell is faced in stucco. Openings on this elevation hold 1/1, double-hung, vinyl-sash windows set in segmental openings with concrete-lug sills in the first and second stories.

Site Notes:

**March 2008:** This rowhouse is located on the northwest side of Potomac Avenue, S.E. and is set back approximately thirty feet from the concrete sidewalk. The dwelling is adjacent to 1418 Potomac Avenue, S.E. and 1422 Potomac Avenue, S.E. The rowhouse is fronted by a raised, grassy front yard with mature shrubs. A concrete walkway leads from the primary entrance and terminates with steps leading down to the concrete sidewalk. A retaining wall, constructed of stone, lines the front of the property and runs parallel to the sidewalk. A small backyard, enclosed by a wood privacy fence, is located at the rear of the property.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Basemt Windows	Rectangular	Unknown	Unknown	Unknown
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Pamels	Material
Main Door	Rectangular	Single	Paneled	Unknown

Notable Interior Plan(s) \_\_\_\_\_

Notable Interior Feature(s) \_\_\_\_\_

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s) \_\_\_\_\_

Designation Event(s) \_\_\_\_\_

Survey(s) \_\_\_\_\_

Level(s) of Investigation \_\_\_\_\_

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**

File: **1420Potomac1\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**

File: **1420Potomac2\_S.JPG**

Date:: Photog:

Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
02/14/1901	1124	Build	

Permit Notes:

--

---

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

Study Unit

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

# Resource All Data Report

**ID Number: 1064-0009**

## BASICS DATA

ID Number: **1064-0009** Year Built: **1901** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1422** **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1422 Potomac Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1064/0009** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1901** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1901** **Permit** **2400 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Plager, W.S.**

**Orig Construction** **Builder** **Sourwine, F.D.**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-five rowhouses constructed from the same permit (#1124), of which thirteen are extant. One of twelve consecutive rowhouses constructed along Potomac Avenue, S.E.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 12)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **16**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

March 2008: Constructed in 1901 by F.D. Sourwine from the design of W.S. Plager, this two-story, three-bay, Colonial Revival-style, single-family brick rowhouse is one of thirteen similar rowhouses constructed from the same permit (#1124). This dwelling is constructed of brick and is set on a solid concrete foundation; the façade (southeast elevation) has been faced with stretcher-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a prominent molded architrave with dentils, a brick parapet wall, and a molded cornice set between brick firewalls finish the roof. Stone string courses span the façade of the first and second story windows and are located beneath the window openings. Also, a stone string course spans the façade at lintel level on the second story. Inset decorative panels with beads span the façade above the second story. The southwest bay of the first story holds a single-leaf paneled wood door and storm door and is topped with a rectangular one-light transom. The door opening is highlighted by a concrete lintel and stone string course at lintel level. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows. A one-story, one-bay porch extends across the façade and is set on a stone pier foundation. The roof of the porch (possibly flat) is supported by metal filigree posts. Metal balusters and poured concrete steps with stone wing walls in the southwest end bay complete the porch. A two-story ell extends from the southwest bay of the rear (northwest) elevation and is original to the main block. The rear ell is faced with five-course American-bond brick. The northeast bay of the ell holds a single-leaf paneled wood door with lights and a storm door topped by a one-light transom. A two-course, rowlock brick segmental arch highlights the opening. All other openings on the rear ell hold 1/1, double-hung, wood-sash windows, which are also topped by two-course, rowlock brick segmental arches. The window on the second story has a concrete-lug sill. A one-story concrete porch spans the first story of the rear ell. The foundation was obscured and was not identifiable. A wood half-wall encloses the porch. The slightly pitched roof of the porch is clad in asphalt tile and is supported by wood posts. Concrete steps in the northeast end bay complete the northwest elevation of the ell. The northeast elevation has the same material treatment and has two openings consistent with those on the northwest elevation.

Site Notes:

March 2008: This rowhouse is located on the northwest side of Potomac Avenue, S.E. and is set back approximately thirty feet from the concrete sidewalk. The dwelling is adjacent to 1420 Potomac Avenue, S.E. and 1424 Potomac Avenue, S.E. The rowhouse is fronted by a raised, grassy front yard with mature shrubs and plants. Low wood planting walls divide the yard. A concrete walkway leads from the primary entrance and terminates with steps leading down to the concrete sidewalk. A retaining wall, constructed of stone and brick, lines the front of the property and runs parallel to the sidewalk. A small backyard, enclosed by a metal chain-link fence, is located at the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill Southeast Phase I (2009/2010)</b>	<b>Permit Research</b>
	<b>Volunteer Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\  
File: 1422Potomac1\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\  
File: 1422Potomac2\_S.JPG  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

--

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
02/14/1901	1124		build

Permit Notes:

--

## **BIBLIOGRAPHIC DATA**

---

## **SIGNIFICANCE DATA**

---

Study Unit

--

Code

Criteria

--

## **DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 1064-0008**

## BASICS DATA

ID Number: **1064-0008** Year Built: **1901** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1424** **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1424 Potomac Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1064/0008** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1901** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1901** **Permit** **2400 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Plager, W.S.**

**Orig Construction** **Builder** **Sourwine, F.D.**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-five rowhouses constructed from the same permit (#1124), of which thirteen are extant. One of twelve consecutive rowhouses constructed along Potomac Avenue, S.E.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 12)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **16**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Colonial Revival

Exterior & Architectural Notes:

March 2008: Constructed in 1901 by F.D. Sourwine from the design of W.S. Plager, this two-story, three-bay, Colonial Revival-style, single-family brick rowhouse is one of thirteen similar rowhouses constructed from the same permit (#1124). This dwelling is constructed of brick and is set on a solid concrete foundation; the façade (southeast elevation) has been faced with stretcher-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a prominent molded architrave with dentils, a brick parapet wall, and a molded cornice set between brick firewalls finish the roof. Stone string courses span the façade of the first and second story windows and are located beneath the window openings. Also, stone string courses span the façade at lintel level on the first and second stories. Decorative panels with pateras span the façade above the second story. The southwest bay of the first story holds a single-leaf paneled door with an inset half-circle light and is topped with a rectangular one-light transom. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows. A brick deck spans southeastern half of the first story. The deck is supported by brick piers. Metal balusters and brick steps with metal hand rails in the southwest end bay complete the facade. The rear (northwest) elevation is faced in five-course American-bond brick that has been painted. A two-story ell extends from the southwest bay of the rear elevation—this is original to the main block and has the same material treatment. The northeast bay of the ell holds a single-leaf door with a storm door and is topped by a one-light transom. A two-course, rowlock brick segmental arch highlights the opening. All other openings on the rear elevation holds 1/1, double-hung, vinyl-sash windows with two-course, rowlock brick segmental arches. The windows on the second story have concrete-lug sills. A wood deck spans the southwest elevation of the ell and is supported by wood posts. The foundation is pierced by a single-leaf paneled door in the main block.

Site Notes:

March 2008: This rowhouse is located on the northwest side of Potomac Avenue, S.E. and is set back approximately thirty feet from the concrete sidewalk. The dwelling is adjacent to 1422 Potomac Avenue, S.E. and 1426 Potomac Avenue, S.E. The rowhouse is fronted by a raised, grassy front yard with mature shrubs. A brick walkway leads from the primary entrance and terminates with steps leading down to the concrete sidewalk. A retaining wall, constructed of stone and brick, lines the front of the property and runs parallel to the sidewalk. A concrete-paved driveway, enclosed by a wood privacy fence, is located at the rear of the property.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Unkown w/Lights

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\  
File: 1424Potomac1\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\  
File: 1424Potomac2\_S.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>02/14/1901</b>	<b>1124</b>	<b>Build</b>	

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

---

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 1064-0007**

## BASICS DATA

ID Number: **1064-0007** Year Built: **1901** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1426** **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1426 Potomac Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1064/0007** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1901** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1901** **Permit** **2400 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Plager, W.S.**

**Orig Construction** **Builder** **Sourwine, F.D.**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-five rowhouses constructed from the same permit (#1124), of which thirteen are extant. One of twelve consecutive rowhouses constructed along Potomac Avenue, S.E.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 12)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **16**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1901 by F.D. Sourwine from the design of W.S. Plager, this two-story, three-bay, Colonial Revival-style, single-family brick rowhouse is one of thirteen similar rowhouses constructed from the same permit (#1124). This dwelling is constructed of brick and is set on a solid concrete foundation; the façade (southeast elevation) has been faced with stretcher-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a prominent molded architrave with dentils, a brick parapet wall, and a molded cornice set between brick firewalls finish the roof. Stone string courses span the façade of the first and second story windows and are located beneath the window openings. Also, stone string courses span the façade at lintel level on the first and second stories. Decorative panels with interlace details span the façade above the second story. The foundation is pierced with a window with a metal grille in the northeast bay. The southwest bay of the first story holds a single-leaf door with a metal security door and is topped with a rectangular one-light transom. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows. The windows on the first story are covered with metal grilles. A wood deck spans southeastern half of the first story. Wood steps with hand rails in the southwest end bay complete the facade. The foundation and a portion of the first story of the rear (northwest) elevation were obscured by the rear fence. A two-story ell extends from the southwest bay of the rear elevation and is original to the main block. The rear ell is faced with five-course American-bond brick that has been painted. The northeast bay of the ell holds a single-leaf multi-light door with a storm door topped by a blind transom. A two-course, rowlock brick segmental arch highlights the opening. An opening in the southwest bay of the first story holds a 1/1, double-hung, vinyl-sash window with a metal grille and a blind transom. This opening is topped by a two-course, rowlock brick segmental arch. The second story is fenestrated with a 1/1, double-hung, vinyl-sash window with a two-course, rowlock brick segmental arch.

Site Notes:

**March 2008:** This rowhouse is located on the northwest side of Potomac Avenue, S.E. and is set back approximately thirty feet from the concrete sidewalk. The dwelling is adjacent to 1424 Potomac Avenue, S.E. and 1428 Potomac Avenue, S.E. The rowhouse is fronted by a raised, grassy front yard with mature shrubs and foundation plantings. A brick walkway leads from the primary entrance and terminates with steps leading down to the concrete sidewalk. A retaining wall, constructed of brick, lines the front of the property and runs parallel to the sidewalk. A small backyard, enclosed by a wood privacy fence, is located at the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>Unknown</b>	<b>Unknown</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Pamels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\  
File: 1426Potomac1\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\  
File: 1426Potomac2\_SE.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>02/14/1901</b>	<b>1124</b>	<b>Build</b>	

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

---

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 1064-0006**

## BASICS DATA

ID Number: **1064-0006** Year Built: **1901** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1428** **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1428 Potomac Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1064/0006** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1901** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1901** **Permit** **2400 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Plager, W.S.**

**Orig Construction** **Builder** **Sourwine, F.D.**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-five rowhouses constructed from the same permit (#1124), of which thirteen are extant. One of twelve consecutive rowhouses constructed along Potomac Avenue, S.E.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 12)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **16**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

March 2008: Constructed in 1901 by F.D. Sourwine from the design of W.S. Plager, this two-story, three-bay, Colonial Revival-style, single-family brick rowhouse is one of thirteen similar rowhouses constructed from the same permit (#1124). This dwelling is constructed of brick and is set on a solid concrete foundation; the façade (southeast elevation) has been faced with permastone. The roofing type and material were not visible from the public right-of-way, but a prominent molded architrave with dentils, a brick parapet wall, and a molded cornice set between brick firewalls finish the roof. The southwest bay of the first story holds a single-leaf paneled wood door with an inset half-circle light and is topped with a rectangular one-light transom. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows and have stone sills and flat segmental permastone arches with keystones. A wood trellis spans southeastern half of the first story. Concrete steps in the southwest end bay complete the facade. The foundation and a portion of the first story of the rear (northwest) elevation were obscured by the rear fence. A two-story ell extends from the southwest bay of the rear elevation and is original to the main block. The rear ell is faced with weatherboard. The northeast bay of the ell holds a single-leaf door with a storm door topped by a rectangular one-light transom. Other openings hold 1/1, double-hung, vinyl-sash windows.

Site Notes:

March 2008: This rowhouse is located on the northwest side of Potomac Avenue, S.E. and is set back approximately thirty feet from the concrete sidewalk. The dwelling is adjacent to 1426 Potomac Avenue, S.E. and 1430 Potomac Avenue, S.E. The rowhouse is fronted by a raised, grassy front yard with mature shrubs and plants. A concrete walkway leads from the primary entrance and terminates with steps leading down to the concrete sidewalk. A retaining wall, constructed of brick, lines the front of the property and runs parallel to the sidewalk. A metal chain-link fence runs alongside the concrete walkway and encloses the front yard. A small backyard, enclosed by a wood privacy fence, is located at the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Permastone			
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Full Glass	Unkown w/Lights

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**  
File: **1428Potomac1\_N.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**  
File: **1428Potomac2\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**  
File: **1428Potomac3\_S.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

8/16/2013

DC HPO Survey - Southeast Phase II

ID\_Number: 1064-0006 Page 3

Permit Issue Date	Number	Type	Remarks
02/14/1901	1124	Build	

Permit Notes:

#### **BIBLIOGRAPHIC DATA**

#### **SIGNIFICANCE DATA**

Study Unit

Code	Criteria

#### **DATA PROCESSING EVENTS DATA**

# Resource All Data Report

**ID Number: 1064-0005**

## BASICS DATA

ID Number: **1064-0005** Year Built: **1901** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1430** **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1430 Potomac Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1064/0005** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1901** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1901** **Permit** **2400 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Plager, W.S.**

**Orig Construction** **Builder** **Sourwine, F.D.**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-five rowhouses constructed from the same permit (#1124), of which thirteen are extant. One of twelve consecutive rowhouses constructed along Potomac Avenue, S.E.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 12)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **16**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1901 by F.D. Sourwine from the design of W.S. Plager, this two-story, three-bay, Colonial Revival-style, single-family brick rowhouse is one of thirteen similar rowhouses constructed from the same permit (#1124). This dwelling is constructed of brick and is set on a solid concrete foundation; the façade (southeast elevation) has been faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a prominent molded architrave with dentils, a brick parapet wall, and a molded cornice set between brick firewalls finish the roof. Stone string courses span the façade of the first and second story windows and are located beneath the window openings. Also, stone string courses span the façade at lintel level on the foundation level, first, and second stories. Decorative panels with pateras span the façade above the second story. The foundation is pierced with two multi-light windows in the northeast bay. The southwest bay of the first story holds a single-leaf door with a storm door and is topped with a rectangular three-light transom. All window openings on the façade hold 6/6, double-hung, wood-sash windows. Brick steps with metal hand rails in the southwest bay complete the façade. The foundation and a portion of the first story of the rear (northwest) elevation were obscured by the rear fence. A two-story ell extends from the southwest bay of the rear elevation and is original to the main block. The rear ell is faced with five-course American-bond brick. The northeast bay of the ell holds a single-leaf door with a storm door topped by a rectangular one-light transom. A two-course, rowlock brick segmental arch highlights the opening. An opening in the southwest bay of the first story holds a 1/1, double-hung, vinyl-sash window. This opening is topped by a two-course, rowlock brick segmental arch. The second story has a single-leaf door and storm door with a two-course, rowlock brick segmental arch in the southwest end bay. A metal deck with metal balusters spans the second story and is supported by metal posts. Metal stairs and hand rails provide access from the backyard to the second story. Two openings with two-course rowlock brick arches are visible on the northeast elevation of the rear ell. The main block of the rear elevation is also faced in five-course American-bond brick. It is fenestrated with 6/6, double-hung sash windows with two-course rowlock brick arches on both stories.

Site Notes:

**March 2008:** This rowhouse is located on the northwest side of Potomac Avenue, S.E. and is set back approximately thirty feet from the concrete sidewalk. The dwelling is adjacent to 1428 Potomac Avenue, S.E. and 1432 Potomac Avenue, S.E. The rowhouse is fronted by a raised, grassy front yard with immature shrubs and trees. A brick walkway leads from the primary entrance and terminates with steps leading down to the concrete sidewalk. A retaining wall, constructed of brick, lines the front of the property and runs parallel to the sidewalk. A small backyard, enclosed by a metal privacy fence, is located at the rear of the property.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>Unknown</b>	<b>Unknown</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>6/6</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Pamels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**

File: **1430Potomac1\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**

File: **1430Potomac2\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**

File: **1430Potomac3\_S.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

#### MISCELLANEOUS NOTES DATA

---

Notes:

--

#### PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
02/14/1901	1124	Build	

Permit Notes:

--

#### BIBLIOGRAPHIC DATA

---

#### SIGNIFICANCE DATA

---

Study Unit \_\_\_\_\_

Code	Criteria

#### DATA PROCESSING EVENTS DATA

---

# Resource All Data Report

**ID Number: 1064-0800**

## BASICS DATA

ID Number: **1064-0800** Year Built: **1901** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1432** **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1432 Potomac Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1064/0800** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1901** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1901** **Permit** **2400 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Plager, W.S.**

**Orig Construction** **Builder** **Sourwine, F.D.**

**Orig Construction** **Owner** **Pickford, Thomas H.**

Construction Notes:

**One of twenty-five rowhouses constructed from the same permit (#1124), of which thirteen are extant. One of twelve consecutive rowhouses constructed along Potomac Avenue, S.E.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 12)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **16**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

**March 2008:** Constructed in 1901 by F.D. Sourwine from the design of W.S. Plager, this two-story, three-bay, Colonial Revival-style, single-family brick rowhouse is one of thirteen similar rowhouses constructed from the same permit (#1124). This dwelling is constructed of brick and is set on a solid concrete foundation; the façade (southeast elevation) has been faced with stretcher-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a prominent molded architrave with dentils, a brick parapet wall, and a molded cornice set between brick firewalls finish the roof. Stone string courses span the façade of the first and second story windows and are located beneath the window openings. Also, stone string courses span the façade at lintel level on the foundation, first, and second stories. Inset decorative panels with beads span the façade above the second story. The foundation is pierced with two windows in the northeast bay. The southwest bay of the first story holds a single-leaf paneled wood door with an inset half-circle light and is topped with a rectangular one-light transom. All window openings on the façade hold 1/1, double-hung, vinyl-sash windows. Metal steps with metal hand rails in the southwest end bay complete the façade. The foundation and a portion of the first story of the rear (northwest) elevation were obscured by the rear fence. A two-story ell extends from the southwest bay of the rear elevation and is original to the main block. The rear ell is faced with five-course American-bond brick that has been painted. The northeast bay of the ell holds a single-leaf multi-light door topped by a blind transom. A two-course, rowlock brick segmental arch highlights the opening. An opening in the southwest bay of the first story holds a 1/1, double-hung, vinyl-sash window. This opening is topped by a two-course, rowlock brick segmental arch. The second story opening holds a 1/1, double-hung, vinyl-sash window with a concrete sill and a two-course, rowlock brick segmental arch in the southwest end bay. A wood deck with wood balusters spans the first story of the ell. The main block of the rear elevation is also faced in five-course American-bond brick that has been painted. It is fenestrated with 1/1, double-hung, vinyl-sash windows with two-course rowlock brick arches on both stories.

Site Notes:

**March 2008:** This rowhouse is located on the northwest side of Potomac Avenue, S.E. and is set back approximately thirty feet from the concrete sidewalk. The dwelling is adjacent to 1430 Potomac Avenue, S.E. and 1434 Potomac Avenue, S.E. The rowhouse is fronted by a gently sloping, grassy front yard with mature shrubs and foundation plantings. A concrete walkway leads from the primary entrance and terminates with steps leading down to the concrete sidewalk. A concrete curb lines the front of the property and runs parallel to the sidewalk. A small backyard, enclosed by a wood privacy fence, is located at the rear of the property.

## NOTABLE FEATURES DATA

Component Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>Unknown</b>	<b>Unknown</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**  
File: **1432Potomac1\_NW.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**  
File: **1432Potomac2\_S.JPG**

Date:: Photog:

Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

--

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

02/14/1901	1124	Build	
------------	------	-------	--

Permit Notes:

--

## **BIBLIOGRAPHIC DATA**

---

## **SIGNIFICANCE DATA**

---

Study Unit

--

Code

Criteria

--

## **DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 1064-0028**

## BASICS DATA

ID Number: **1064-0028** Year Built: **1901** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1434		Potomac Avenue	SE	Current
1434	-1436	Potomac Avenue	SE	Historic
1434		Potomac Avenue	SE	Original

Name(s)	Type of Name
Dwelling/Store, 1434 Potomac Avenue, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1064/0028			Square/Lot	Current

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Dwelling/Store** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Dwelling & Store	1901	Permit			Original
Residential (Multi-Family)					Current

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1901	Permit			2400 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Plager, W.S.
Orig Construction	Builder	Sourwine, F.D.
Orig Construction	Owner	Pickford, Thomas H.

Construction Notes:

One of twenty-five rowhouses constructed from the same permit (#1124), of which thirteen are extant. One of twelve consecutive rowhouses constructed along Potomac Avenue, S.E.

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Attached (1 side)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Vertical Block (irregular)**  
 Footprint: **Irregular**

Cross Reference Notes:

Number Stories: **3**

Bays Wide: **4**

Height:

Outbuilding Type

Contributing Status

Width: **16**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Colonial Revival**

**Second Empire**

Exterior & Architectural Notes:

**March 2008:** Constructed in 1901 by F.D. Sourwine from the design of W.S. Plager, this three-story, four-bay, Colonial Revival-style multiple dwelling with influences of the Second Empire style is one of twenty-five similar rowhouses constructed from the same permit (#1124). The building was originally constructed as a dwelling and store. This building is constructed of brick and is set on a solid concrete foundation. The dwelling is faced with stretcher-bond brick that has been painted. An asphalt-shingled mansard roof caps the building and is pierced by pedimented dormers. Each dormer is fenestrated with a 1/1, double-hung, vinyl-sash window. Stone beltcourses encircle the dwelling and are located below and above the first and second story window openings. A stone watertable is sited above the foundation. Paired beltcourses span the façade and wrap to the northeast (side) elevation and are located above the second story windows. These beltcourses are composed of recessed square panels with pellet molding. All window openings which pierce the building have been decreased in size and now hold smaller window-sash. The central bay of the façade (southeast elevation) holds a single-leaf door, which is sheltered by a canopy. A brick stoop with metal balusters and brick steps provides access to the door. All openings on the façade hold 1/1, double-hung, vinyl-sash windows. Several windows on the façade have been infilled with brick. A three-sided, rectangular bay rises the full height of the façade and extends from the southwestern bay. Sharing the same material treatment as the main block, the bay is capped by a three-sided, canted mansard roof. The bay features fenestration that is consistent with the façade. Additional asymmetrical four-light windows sit between the first and second stories and the second and third stories in the southwestern end bay.

A one-story, one-bay addition projects from the façade and is located northeast of the primary entrance. The wood-frame addition is clad with T-111 siding and is capped by a front-gabled roof that is covered with asphalt shingles. Openings on the southeastern and southwestern elevations of the projecting bays hold one-light fixed windows.

The east elevation of the structure shares the same material treatment and fenestration as the façade. Two additional four-light fixed windows pierce the elevation between the first and second stories and second and third stories in the northern end bay. The windows on the first story have metal grilles. The stone string course running below the first story windows runs only below the window openings themselves.

The north elevation shares the same material treatment as the other elevations. The foundation was obscured by the rear fence. The mansard roof is pierced with a gabled dormer, which holds a 1/1, double-hung, vinyl-sash window. Fenestration consists of 1/1, double-hung, vinyl-sash windows and multi-light windows. Several original window openings have been infilled with brick.

The west elevation of the building has the same material treatment as the façade but has no stone or decorative square panel beltcourses. The window on the first story has a metal grille.

The northwest elevation of the structure was obscured by the rear fence. This elevation is faced with stretcher-bond brick that has been painted. The first, second, and third stories hold single-leaf, wood-frame glass doors with one-light sidelights and metal security doors and grilles. Each story has a wood deck with wood balusters supported by square wood posts. The third story opening is highlighted by a wood entablature.

Site Notes:

**March 2008:** This multiple dwelling is located on the northwest side of Potomac Avenue, S.E. and is set back approximately thirty feet from the concrete sidewalk. The dwelling is adjacent to 1432 Potomac Avenue, S.E. The building is fronted by a flat, grassy front yard dotted with mature trees and small foundation plantings. A brick walkway leads from the primary entrance to the concrete sidewalk. A concrete curb lines the front and sides of the property and runs parallel to the sidewalk. A small backyard, enclosed by a wood privacy fence, is located at the rear of the property.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard</b>	<b>Asphalt</b>		<b>Shingled</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>4</b>	<b>Unknown</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill Southeast Phase I (2009/2010)</b>	<b>Permit Research</b>
	<b>Volunteer Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**  
File: **1434Potomac3\_NW.JPG**

Date:: Photog:  
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**  
File: **1434Potomac1\_NW.JPG**

Date:: Photog:  
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**  
File: **1434Potomac2\_W.JPG**

Date:: Photog:  
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**  
File: **1434Potomac4\_S.JPG**


Date:: Photog:  
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\**  
File: **1434Potomac5\_S.JPG**

Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1064\

File: 1434Potomac6\_SE.JPG

Date:: Photog:

Code:: R: Fr:



---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
02/14/1901	1124	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

---

