

Resource All Data Report

ID Number: 1074-0039

BASICS DATA

ID Number: **1074-0039** Year Built: **1911** Data Source: **Permit**

Number Extended Street Quad Type of Address

1502 **D Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1502 D Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0039 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1911** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1911** **Permit** **2000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Volland, Edward O.**

Orig Construction **Builder** **Volland, C.D.**

Orig Construction **Owner** **Nesline, George**

Construction Notes:

One of four rowhouses constructed from the same permit (#1872).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 4)**

Relate to Street: **Raised Front Yard/Setback**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **15**

Depth/Length: **44**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: This single-family rowhouse was constructed in 1911 by C.D. Volland. This two-story, three-bay dwelling reflects the Classical Revival style and is one of four similar rowhouses constructed from the same permit (#1872). The brick house sits on a solid concrete foundation and has five-course, American-bond brickwork. The sloping roof (materials not visible) is ornamented with a molded metal cornice set between corbeled brick firewalls above a corbeled brick string. Fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete lug sills and rock-faced lintels. The main entry, a single-leaf, paneled metal door with lights and single-light transom, is located in the easternmost bay. A one-story, two-bay porch is located on the façade. Set on a solid brick foundation, this porch has a flat roof with overhanging eaves and a metal cornice. Metal filigree posts with metal balusters complete the porch. The north (rear) elevation was not visible from the public right-of-way.

Site Notes:

September 2010: This single-family dwelling sits on the north side of D Street, S.E. on a level lot covered with brick and enclosed with a picket and milled point metal fence. The west (side) elevation is adjacent to 1500 D Street, S.E. while the east (side) elevation is to 1504 D Street, S.E. The house is set back approximately fifteen feet from the public sidewalk. The backyard extends north, but was not visible from the public right-of-way.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s) Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s) Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1502_D_Street_SE_facade_looking_NE.jpg
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1502_D_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/10/1911	1872	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0038

BASICS DATA

ID Number: **1074-0038** Year Built: **1911** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1504		D Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1504 D Street, S.E.	Current

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0038			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1911	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1911	Permit			2000 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Volland, Edward O.
Orig Construction	Builder	Volland, C.D.
Orig Construction	Owner	Nesline, George

Construction Notes:

One of four rowhouses constructed from the same permit (#1872).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 4)**
Relate to Street: **Raised Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **3**
Height:
Width: **15**
Depth/Length: **44**

Outbuilding Type	Contributing Status
------------------	---------------------

SqFt:
Volume:
Lot Width:

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: This single-family rowhouse was constructed in 1911 by C.D. Volland. This two-story, three-bay dwelling reflects the Classical Revival style and is one of four similar rowhouses constructed from the same permit (#1872). The brick house sits on a solid concrete foundation and has five-course, American-bond brickwork. The sloping roof (materials not visible) is ornamented with a molded metal cornice set between corbeled brick firewalls above a corbeled brick string. Fenestration consists of 1/1, double-hung, wood-sash windows with concrete lug sills and rock-faced lintels. Located in the easternmost bay of the façade, the main entry holds a single-leaf, paneled wood door and single-light transom. The door has stylistic influences of the Queen Anne style. A one-story, two-bay porch is located on the façade. Capped by a flat roof, the porch has a molded metal cornice and is supported by metal filigree posts. The north (rear) elevation was not visible from the public right-of-way.

Site Notes:

September 2010: This single-family dwelling sits on the north side of D Street, S.E. and has a setback from the public sidewalk of approximately fifteen feet. The west (side) elevation is adjacent to 1502 D Street, S.E. while the east (side) elevation is to 1506 D Street, S.E. Landscaped with immature shrubs and trees, the front yard is enclosed with a milled point and hairpin metal fence. Brick steps link the front porch with the sidewalk. The backyard extends north, but was not visible from the public right-of-way.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1504_D_Street_SE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1504_D_Street_SE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/10/1911	1872	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0037

BASICS DATA

ID Number: **1074-0037** Year Built: **1911** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1506		D Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1506 D Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0037			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1911	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1911	Permit			2000 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Volland, Edward O.
Orig Construction	Builder	Volland, C.D.
Orig Construction	Owner	Nesline, George

Construction Notes:

One of four rowhouses constructed from the same permit (#1872).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 4)**
Relate to Street: **Raised Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **3**
Height:
Width: **15**
Depth/Length: **44**
SqFt:

Outbuilding Type	Contributing Status
------------------	---------------------

Volume:
Lot Width:
Lot Depth/Length:
Lot SqFt:
Acreage:
Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: This single-family rowhouse was constructed in 1911 by C.D. Volland. This two-story, three-bay dwelling reflects the Classical Revival style and is one of four similar rowhouses constructed from the same permit (#1872). The brick house sits on a solid concrete foundation and has five-course, American-bond brickwork. The sloping roof (materials not visible) is ornamented with a molded metal cornice set between corbeled brick firewalls above a corbeled brick string. Fenestration consists of 1/1, double-hung, wood-sash windows with concrete lug sills and rock-faced lintels. Located in the easternmost bay of the façade, the main entry holds a single-leaf, paneled metal door with a semi-circular light. A single-light transom is also set in the narrow, square-edge wood door surround. A one-story, one-bay porch, set on a brick pier foundation, shelters the central and eastern bays of the first story. The flat roof has overhanging eaves and is supported by brick posts. The backyard extends north, but was not visible from the public right-of-way.

Site Notes:

September 2010: This single-family dwelling sits on the north side of D Street, S.E. and has a setback from the public sidewalk of approximately fifteen feet. The west (side) elevation is adjacent to 1504 D Street, S.E. while the east (side) elevation is to 1508 D Street, S.E. Heavily landscaped, the front yard is covered with mature shrubs and plantings. A brick walkway extends from the front porch down steps to the sidewalk, which is lined with a brick retaining wall. The backyard extends north, but was not visible from the public right-of-way.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **1506_D_Street_SE_facade_looking_N.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **1506_D_Street_SE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/10/1911	1872	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0036

BASICS DATA

ID Number: **1074-0036** Year Built: **1911** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1508		D Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1508 D Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0036			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1911	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1911	Permit			2000 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Volland, Edward O.
Orig Construction	Builder	Volland, C.D.
Orig Construction	Owner	Nesline, George

Construction Notes:

One of four rowhouses constructed from the same permit (#1872).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 4)**
Relate to Street: **Raised Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **3**
Height:
Width: **15**
Depth/Length: **44**

Outbuilding Type	Contributing Status
------------------	---------------------

SqFt:
Volume:
Lot Width:

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: This single-family rowhouse was constructed in 1911 by C.D. Volland. This two-story, three-bay dwelling reflects the Classical Revival style and is one of four similar rowhouses constructed from the same permit (#1872). The brick house sits on a solid concrete foundation and has five-course, American-bond brickwork. The sloping roof (materials not visible) is ornamented with a molded metal cornice set between corbeled brick firewalls above a corbeled brick string. Fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete lug sills and rock-faced lintels. Located in the easternmost bay of the façade, the main entry holds a single-leaf, paneled wood door with semi-circular light surmounted by a single-light transom. A one-story, one-bay porch, set on a brick pier foundation, shelters the central and eastern bays of the first story. The flat roof has overhanging eaves with a molded metal cornice and is supported by metal filigree posts set on brick piers. The backyard extends north, but was not visible from the public right-of-way.

Site Notes:

September 2010: This single-family dwelling sits on the north side of D Street, S.E. and has a setback from the public sidewalk of approximately fifteen feet. The west (side) elevation is adjacent to 1506 D Street, S.E. while the east (side) elevation is to 1510 D Street, S.E. Concrete covers the front of the property, which is enclosed with a metal chain-link fence. Concrete steps lead down from the front porch. The backyard extends north, but was not visible from the public right-of-way.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1508_D_Street_SE_facade_looking_N.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1508_D_Street_SE_facade_looking_NE.jpg**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1508_D_Street_SE_rear_looking_SW.jpg**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/10/1911	1872	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0815

BASICS DATA

ID Number: **1074-0815** Year Built: **1894** Data Source: **Permit**

Number Extended Street Quad Type of Address

1510 **D Street** **SE Current**

Name(s) Type of Name

Single Dwelling, 1510 D Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0815 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1894** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1894** **Permit** **600 Permit**

Construction Event Association Associated Name

Kolb, E.L. **Builder** **Kolb, E.L.**

Orig Construction **Owner** **Dietz, Charles**

Construction Notes:

One of two dwellings constructed from the same permit (#1658).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Raised Front Yard/Setback**

Massing: **Vertical Box/front porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **15**

Depth/Length: **27**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Italianate

Exterior & Architectural Notes:

September 2010: This two-story, two-bay, single-family rowhouse was constructed in 1894 by E.L. Kolb. This twin building reflects the Classical Revival style with influences of the Italianate and is one of two constructed from the same permit (#1698). Set on a solid brick and concrete foundation, this brick structure has seven-course, American-bond brickwork. A sloped roof (materials not visible) caps the dwelling and is pierced by an interior brick chimney with plain cap. A prominent corbeled brick cornice adorns the façade (south elevation). Fenestration of the façade consists of 1/1, double-hung, vinyl-sash windows with concrete sills and soldier brick segmental arches with header drip molding. Located in the western bay, the main entry holds a single-leaf, wood-frame glass door with single-light transom. The opening has a narrow, square-edge wood surround and a segmental arch. A one-story, one-bay porch shelters the first story. Set on a solid foundation, the porch has a flat roof with overhanging eaves supported by Tuscan columns. Square wood balusters compliment the porch, which has a stone-clad deck.

A two-story, full-width addition has been constructed on the north (rear) elevation. Based on its form and materials, as well as Sanborn Fire Insurance Company maps, it appears that this addition was constructed c. 1980. Clad in beaded vinyl siding, the addition is capped by a shed roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows and single-leaf, wood-frame glass doors.

Site Notes:

September 2010: This single-family dwelling sits on the north side of D Street, S.E. and has a setback from the public sidewalk of approximately ten feet. The west (side) elevation is adjacent to 1508 D Street, S.E. while the east (side) elevation is to 1512 D Street, S.E. The small, grassy front yard has mature shrubs and is enclosed with a hairpin and point metal fence. Stone pavers link the front porch with the sidewalk. The backyard extends north to an alley and is enclosed with a wooden privacy fence. A second-story wood deck has been constructed on the rear of the dwelling.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1510_D_Street_SE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1510_D_Street_SE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1510_D_Street_SE_rear_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0816

BASICS DATA

ID Number: **1074-0816** Year Built: **1894** Data Source: **Permit**

Number Extended Street Quad Type of Address

1512 **D Street** **SE Current**

Name(s) Type of Name

Single Dwelling, 1512 D Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0816 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1894** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1894** **Permit** **600 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Kolb, E.L.**

Orig Construction **Owner** **Dietz, Charles**

Construction Notes:

One of two dwellings constructed from the same permit (#1658).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Raised Front Yard/Setback**

Massing: **Vertical Box/front porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **15**

Depth/Length: **27**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Italianate

Exterior & Architectural Notes:

September 2010: This two-story, two-bay, single-family rowhouse was constructed in 1894 by E.L. Kolb. This twin building reflects the Classical Revival style with influences of the Italianate and is one of two constructed from the same permit (#1698). Set on a solid brick and concrete foundation, this brick structure has seven-course, American-bond brickwork. A sloped roof (materials not visible) caps the dwelling and is pierced by an interior brick chimney with plain cap. A prominent corbeled brick cornice adorns the façade (south elevation). Fenestration of the façade consists of 1/1, double-hung, vinyl-sash windows with concrete sills and soldier brick segmental arches with header drip molding. Inoperable louvered vinyl shutters flank each window opening. Located in the western bay, the main entry holds a single-leaf, paneled wood door with semi-circular light. A blank transom and segmental arch complete the opening. A one-story, one-bay porch shelters the first story. Set on a solid foundation, the porch has a flat roof with overhanging eaves supported by Tuscan columns. Set on-grade, the concrete porch deck has no balustrade.

A two-story, full-width addition has been constructed on the north (rear) elevation. Based on its form and materials, as well as Sanborn Fire Insurance Company maps, it appears that this addition was constructed c. 1980. Clad in beaded vinyl siding, the addition is capped by a shed roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows and single-leaf, paneled metal door with semi-circular light.

Site Notes:

September 2010: This single-family dwelling sits on the north side of D Street, S.E. and has a setback from the public sidewalk of approximately ten feet. The west (side) elevation is adjacent to 1510 D Street, S.E. while the east (side) elevation is to 1514 D Street, S.E. The small, grassy front yard has mature shrubs and is enclosed with a bow and picket metal fence. A concrete walkway extends from the front porch to the sidewalk. Poured concrete covers the backyard, which is enclosed with a wooden privacy fence and extends north to an alley.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1512_D_Street_SE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1512_D_Street_SE_rear_looking_S.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1512_D_Street_SE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0802

BASICS DATA

ID Number: **1074-0802** Year Built: **1890** Data Source: **Permit**

Number Extended Street Quad Type of Address

1514 **D Street** **SE Current**

Name(s) Type of Name

Single Dwelling, 1514 D Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0802 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1890** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1894** **Permit** **400 Permit**

Construction Event Association Associated Name

Orig Construction **Owner** **Brooker, W.H.**
Peebles, O. **Builder** **Peebles, O.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Front Yard/Setback**
Massing: **Vertical Box/flat front**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **14**

Depth/Length: **26**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Exterior & Architectural Notes:

September 2010: This two-story, two-bay, single-family, Italianate-style dwelling was constructed in 1890 by O. Peebles. Set on a solid brick foundation, this wood-frame structure has been clad in vinyl siding. A sloped roof caps the dwelling and features a molded metal cornice with scrolled modillions set between end brackets. An interior brick chimney with plain cap pierces the roofline. Located in the western bay, the main entry holds a single-leaf, paneled wood door flanked by fluted pilasters with a plain frieze and molded cap. Window openings hold 1/1, double-hung, vinyl-sash windows with inoperable, louvered vinyl shutters. The north (rear) elevation has a two-story, full-width addition, which based on its form and materials, appears to have been constructed c. 1990. Clad in vinyl siding and capped by a shed roof, the addition has 1/1, double-hung, vinyl-sash windows and sliding-glass doors with single-light transoms. A two-story, wood-frame porch with a shed roof and square balusters highlights the rear of the dwelling.

Site Notes:

September 2010: Located north of D Street, S.E., this single-family rowhouse has a setback from the public sidewalk of approximately fifteen feet. The dwelling is adjacent to 1512 and 1516 D Street, S.E. The landscaped front yard has a manicured lawn, mature trees and shrubs, as well as foundation plantings. A bow and point metal fence encloses the yard. A brick walkway extends from the main entry to the sidewalk. The backyard extends north to an alley and is enclosed with a wooden privacy fence.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1514_D_Street_SE_facade_looking_.jpg
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1514_D_Street_SE_facade_looking_N.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1514_D_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1514_D_Street_SE_rear_looking_N.jpg
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
11/17/1890	1198	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0801

BASICS DATA

ID Number: **1074-0801** Year Built: **1893** Data Source: **Permit**

Number Extended Street Quad Type of Address

1516 **D Street** **SE Current**

Name(s) Type of Name

Single Dwelling, 1516 D Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0801 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1893** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1893** **Permit** **600 Permit**

Construction Event Association Associated Name

Baines, George W. **Builder** **Baines, George W.**

Orig Construction **Owner** **Baines, Hannah, Mrs.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Freestanding**
Relate to Street: **Front Yard/Setback**
Massing: **Vertical Box/front porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **12**

Depth/Length: **28**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Altered

Exterior & Architectural Notes:

September 2010: Constructed in 1893, this two-story, three-bay, single-family dwelling is reflective of multiple architectural styles. However, due to restoration efforts, the original architectural scheme is no longer evident. Set on a brick and concrete foundation, this brick structure has a stucco exterior. A shed roof caps the dwelling and features a tall parapet along the façade (south elevation). The parapet has an ogee-molded metal cornice set above a wide plain frieze. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows with 6/6 false muntins. Concrete sills and keystone arches complete each opening. The single-leaf main entry, located in the western bay, holds a paneled wood door with lights and a single-light transom. A one-story, three-bay porch spans the width of the façade. Set on a concrete deck, the porch has a half-hipped roof of terra cotta tiles with overhanging eaves. Tuscan columns support the roof while square wood balusters enclose the sides of the porch. Fenestration of the east (side) elevation consists of 1/1, double-hung, vinyl-sash windows. The north (rear) elevation has a two-story, two-bay original block. Stuccoed, this appendage has 2/2, double-hung, wood-sash windows and single-leaf, paneled wood doors set in square-edge wood surrounds. A two-story, full-width porch extends off the rear of the appendage. Capped by a shed roof, this porch has wood post supports. Additional details were not visible from the public right-of-way.

Site Notes:

September 2010: Located north of D Street, S.E., this semi-detached dwelling has a setback from the sidewalk of approximately fifteen feet. The west (side) elevation is attached to 1514 D Street, S.E. The landscaped front yard has mature and immature shrubs and plantings. A picket metal fence encloses the front yard, which has a concrete walkway extending off the front porch down to the sidewalk. A wooden privacy fence encloses the side and back yards.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Contributing.

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1516_D_Street_SE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1516_D_Street_SE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1516_D_Street_SE_rear_looking_SE.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
11/09/1893	0756	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0800

BASICS DATA

ID Number: **1074-0800** Year Built: **c. 2000** Data Source: **Site Visit/Map**

Number	Extended	Street	Quad	Type of Address
1518		D Street	SE	Current

Name(s)	Type of Name
Single Dwelling, 1518 D Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0800			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Not Historic** Quality:
Purpose: **Residential** Condition: **Excellent**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	c. 2000	Site Visit/			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	c. 2000	Site Visit/Map			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached (1 side)**
Relate to Street: **Front Yard/Setback**
Massing: **Vertical Block**
Footprint: **Rectangular**

Number Stories: **3**
Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2010: Based on its form and materials, this dwelling was constructed c. 2000 and replaced an earlier single-family rowhouse. Set on a solid foundation, this structure is clad in German vinyl siding and capped by a shed roof. Window openings hold 1/1, double-hung, vinyl-sash windows. The main entry, located in the eastern bay, holds a single-leaf, wood-frame glass door with single-light transom set in a plain wood surround. The façade (south elevation) features a two-story, two-sided canted bay. The third story, setback approximately three feet, has a balcony set above the canted bay. With metal railing, the balcony is accessed via sliding glass doors topped by a large transom. East of the balcony is a large two-light, sliding vinyl-sash window. The north (rear) elevation features a centrally located chimney stack. Window openings, which hold 1/1, double-hung, vinyl-sash windows, flank the stack on all three levels.

Site Notes:

September 2010: Located north of D Street, S.E., this semi-detached dwelling has a setback of approximately fifteen feet from the sidewalk. The east (side) elevation is attached to 1522 D Street, S.E. The small front yard has immature shrubs and trees, as well as a concrete walkway lined with brick extending from the main entry to the sidewalk. A milled point metal fence encloses the front yard. A wooden privacy fence encloses the side and back yards. Mature shrubs and Crepe Myrtles sprout from the backyard.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
-----------------------------------	----------------------

Subdivision:	
--------------	--

Ward/ANC:	
-----------	--

Zoning:	Designation Event(s)
---------	----------------------

Contributing:	
---------------	--

Survey(s)	Level(s) of Investigation
-----------	---------------------------

Capitol Hill Southeast Phase II (2010)	Permit Research
-----------------------------------------------	------------------------

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1518_D_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1518_D_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1518_D_Street_SE_rear_looking_S.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0053

BASICS DATA

ID Number: **1074-0053** Year Built: **1912** Data Source: **Permit**

Number Extended Street Quad Type of Address

1522 **D Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1522 D Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0053 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1912** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1912** **Permit** **2150 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of thirteen rowhouses constructed from the same permit (#5853).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 13)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **12**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1912 by Harry A. Kite, this two-story, two-bay, Classical Revival-style single-family rowhouse was one of thirteen constructed from the same permit (#5853). Set on a solid concrete foundation, this brick structure has been clad in Permastone. A sloped roof caps the dwelling and features a molded metal cornice set between molded end brackets. An interior brick chimney pierces the roof. The façade (south elevation) has 1/1, double-hung, vinyl-sash windows with concrete sills and Permastone keystone arches. A single-leaf, paneled wood door with lights is located in the eastern bay. The door is accompanied by a single-light wood transom and topped by a Permastone keystone arch. A one-story, full-width porch is set on a concrete slab. The flat roof has overhanging eaves with a metal cornice of pressed dentils. Permastone-clad supports include metal balusters. Fenestration of the north (rear) elevation consists of 1/1, double-hung, vinyl-sash windows with two-course, rowlock brick segmental arches.

A two-story, one-bay ell is located on the rear of the dwelling. The ell has a brick exterior and shed roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills and two-course, rowlock brick segmental arches.

Site Notes:

September 2010: This single family rowhouse is located north of D Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The west (side) elevation is adjacent to 1518 D Street, S.E. and the east (side) elevation to 1524 D Street, S.E. Enclosed with a metal bow and point fence, the front yard has a mature tree and immature plantings. A concrete walkway extends from the front porch to the sidewalk. The backyard, enclosed with a wooden privacy fence, extends north to an alley.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1522_D_Street_SE_facade_looking_N.jpg
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1522_D_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1522_D_Street_SE_rear_looking_N.jpg
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

[Empty text box]

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/11/1912	5853	Build	

Permit Notes:

[Empty text box]

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0052

BASICS DATA

ID Number: **1074-0052** Year Built: **1912** Data Source: **Permit**

Number Extended Street Quad Type of Address

1524 **D Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1524 D Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0052 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1912** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1912** **Permit** **2153 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of thirteen rowhouses constructed from the same permit (#5853).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 13)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **12**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Shed

Outbuilding Notes:

September 2010: This one-story, one-bay shed was constructed c. 2000 and has a rubber structure/cladding, and gable roof.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1912 by Harry A. Kite, this two-story, two-bay, Classical Revival-style single-family rowhouse was one of thirteen constructed from the same permit (#5853). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and features a molded metal cornice set between molded end brackets. An interior brick chimney pierces the roof. The façade (south elevation) has 1/1, double-hung, vinyl-sash windows with concrete lug sills and lintels. A two-course brick sill string highlights the second-story openings. A single-leaf, paneled wood door is located in the eastern bay. The door is accompanied by a single-light wood transom and concrete lug lintel. A one-story, full-width porch is set on a concrete slab. The flat roof has overhanging eaves and is supported by a Permastone-clad post and a wood post. Decorative metal balusters extend between the wood post and a brick pier. Fenestration of the north (rear) elevation consists of 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A two-story, one-bay ell is located on the rear of the dwelling. This brick structure is capped by a shed roof and has a single-leaf, multi-light door located on the second story. The opening has a blank transom and three-course, rowlock brick segmental arch. Additional details were not visible from the public right-of-way.

Site Notes:

September 2010: This single family rowhouse is located north of D Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The west (side) elevation is adjacent to 1522 D Street, S.E. and the east (side) elevation to 1526 D Street, S.E. Enclosed with a metal bow and point fence, the front yard has immature plantings and shrubs. A concrete walkway extends from the front porch to the sidewalk. The backyard, enclosed with a wooden privacy fence, extends north to an alley. A shed is located in the backyard.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\

File: 1524_D_Street_SE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\

File: 1524_D_Street_SE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\

File: 1524_D_Street_SE_rear_looking_S.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\

File: 1524_D_Street_SE_shed_looking_S.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/11/1912	5853	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0051

BASICS DATA

ID Number: **1074-0051** Year Built: **1912** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1526		D Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1526 D Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0051			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1912	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1912	Permit			2150 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Landvoigt, A. E.
Orig Construction	Builder	Kite, Harry A.
Orig Construction	Owner	Kite, Harry A.

Construction Notes:

One of thirteen rowhouses constructed from the same permit (#5853).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 13)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**
Height:
Width: **12**
Depth/Length: **42**

Outbuilding Type	Contributing Status
Shed	

SqFt:
Volume:
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

September 2010: This one-story, one-bay prefabricated shed, based on its form and materials, appears to have been constructed c. 2000. The wood-frame is clad in Hardieplank siding and capped by an asymmetrical side-gabled roof of asphalt shingles. Double-leaf, paneled wood doors are located

on the north elevation.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1912 by Harry A. Kite, this two-story, two-bay, Classical Revival-style single-family rowhouse was one of thirteen constructed from the same permit (#5853). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and features a molded metal cornice set between molded end brackets. An interior brick chimney pierces the roof. The façade (south elevation) has 1/1, double-hung, vinyl-sash windows with concrete lug sills and lintels. A two-course brick sill string highlights the second-story openings. A single-leaf, paneled wood door is located in the eastern bay. The door is accompanied by a single-light wood transom and concrete lug lintel. A one-story, full-width porch is set on a concrete slab. The flat roof has overhanging eaves and is supported by a PermaStone-clad post and a wood post. Decorative metal balusters extend between the wood post and a brick pier. Fenestration of the north (rear) elevation consists of 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A two-story, one-bay brick ell is located on the rear of the rowhouse. Capped by a shed roof, the ell has 1/1, double-hung, vinyl-sash windows and a single-leaf, wood-frame glass door. The first story has paired window and door while the second story is a single window. Each opening has a concrete sill and three-course, rowlock brick segmental arch.

Site Notes:

September 2010: This single family rowhouse is located north of D Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The west (side) elevation is adjacent to 1524 D Street, S.E. and the east (side) elevation to 1530 D Street, S.E. Enclosed with a metal bow and point fence, the front yard has a mature tree and immature plantings. A concrete walkway extends from the front porch to the sidewalk. The backyard, enclosed with a wooden privacy fence, extends north to an alley. A shed is located in the backyard.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s) Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1526_D_Street_SE_facade_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1526_D_Street_SE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1526_D_Street_SE_rear_and_shed_looking_S.
JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/11/1912	5853	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0050

BASICS DATA

ID Number: **1074-0050** Year Built: **1912** Data Source: **Permit**

Number Extended Street Quad Type of Address

1528 **D Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1528 D Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0050 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1912** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1912** **Permit** **2150 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of thirteen rowhouses constructed from the same permit (#5853).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 13)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **12**

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1912 by Harry A. Kite, this two-story, two-bay, Classical Revival-style single-family rowhouse was one of thirteen constructed from the same permit (#5853). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and features a molded metal cornice set between molded end brackets. An interior brick chimney pierces the roof. The façade (south elevation) has 1/1, double-hung, vinyl-sash windows with concrete lug sills and lintels. A two-course brick sill string highlights the second-story openings. Inoperable louvered vinyl shutters flank each window opening. A single-leaf, paneled wood door is located in the western bay. The door is accompanied by a single-light wood transom and concrete lug lintel. A one-story, full-width porch is set on a concrete slab. The flat roof has overhanging eaves and is supported by Tuscan columns set on the concrete slab deck. Fenestration of the north (rear) elevation was not visible from the public right-of-way.

A two-story, one-bay brick ell is located on the rear of the rowhouse. Capped by a shed roof, the ell has 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A one-story, one-bay enclosed porch is located on the rear of the ell. Enclosed with brick, this appendage has a shed roof and includes a wide opening on the north elevation with a two-course, rowlock brick segmental arch. The opening has a door (not visible) with a transom and a large fixed window.

Site Notes:

September 2010: This single family rowhouse is located north of D Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The west (side) elevation is adjacent to 1526 D Street, S.E. and the east (side) elevation to 1532 D Street, S.E. Enclosed with a metal bow and point fence, the front yard is overgrown with trees and shrubs. A concrete walkway extends from the front porch to the sidewalk. The backyard, enclosed with a wooden privacy fence, extends north to an alley.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1528_D_Street_SE_facade_looking_NE
(2).JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1528_D_Street_SE_facade_looking_NE.jpg**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1528_D_Street_SE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1528_D_Street_SE_rear_looking_SW.jpg**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/11/1912	5853	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0049

BASICS DATA

ID Number: **1074-0049** Year Built: **1912** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1530		D Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1530 D Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0049			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1912	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1912	Permit			2153 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Landvoight, A.E.
Orig Construction	Builder	Kite, Harry A.
Orig Construction	Owner	Kite, Harry A.

Construction Notes:

One of thirteen rowhouses constructed from the same permit (#5853).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 13)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**
Height: **12**
Width: **42**
Depth/Length: **42**
SqFt:
Volume:
Lot Width

Outbuilding Type	Contributing Status
------------------	---------------------

Lot Depth/Length:
Lot SqFt:
Acreage:
Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1912 by Harry A. Kite, this two-story, two-bay, Classical Revival-style single-family rowhouse was one of thirteen constructed from the same permit (#5853). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and features a molded metal cornice set between molded end brackets. An interior brick chimney pierces the roof. The façade (south elevation) has 1/1, double-hung, vinyl-sash windows with concrete lug sills and lintels. A two-course brick sill string highlights the second-story openings. A single-leaf, paneled wood door with semi-circular light is located in the eastern bay. The door is accompanied by a single-light wood transom and concrete lug lintel. A one-story, full-width porch set on a concrete slab shelters the first story. The flat roof has overhanging eaves and is supported by a Tuscan columns. Fenestration of the north (rear) elevation consists of 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A two-story, one-bay brick ell is located on the rear of the rowhouse. Capped by a shed roof, the ell has a 1/1, double-hung, vinyl-sash window with a concrete sill and three-course, rowlock brick segmental arch.

A one-story, one-bay porch is located on the rear of the ell. This original feature has been enclosed with German vinyl siding and capped by a shed roof. Fenestration was not visible from the public right-of-way.

Site Notes:

September 2010: This single family rowhouse is located north of D Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The west (side) elevation is adjacent to 1528 D Street, S.E. and the east (side) elevation to 1532 D Street, S.E. Enclosed with a metal bow and point fence, the front yard has a concrete walkway extending from the front porch to the sidewalk. The backyard, enclosed with a wooden privacy fence, extends north to an alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:
Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1530_D_Street_SE_facade_looking_N.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1530_D_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1530_D_Street_SE_rear_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/11/1912	5853	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0048

BASICS DATA

ID Number: **1074-0048** Year Built: **1912** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1532		D Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1532 D Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0048			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1912	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1912	Permit			2150 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Landvoight, A.E.
Orig Construction	Builder	Kite, Harry A.
Orig Construction	Owner	Kite, Harry A.

Construction Notes:

One of thirteen rowhouses constructed from the same permit (#5853).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 13)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**
Height: **12**
Width: **42**
Depth/Length: **42**
SqFt:
Volume:
Lot Width

Outbuilding Type	Contributing Status
------------------	---------------------

Lot Depth/Length:
Lot SqFt:
Acreage:
Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1912 by Harry A. Kite, this two-story, two-bay, Classical Revival-style single-family rowhouse was one of thirteen constructed from the same permit (#5853). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and features a molded metal cornice set between molded end brackets. An interior brick chimney pierces the roof. The façade (south elevation) has 1/1, double-hung, vinyl-sash windows with concrete lug sills and lintels. A two-course brick sill string highlights the second-story openings. A single-leaf, wood-frame glass door set in a narrow, square-edge wood surround is located in the western bay. The door is accompanied by a single-light wood transom and concrete lug lintel. A one-story, full-width porch set on a concrete slab shelters the first story. The flat roof has overhanging eaves and is supported by a Tuscan columns. Fenestration of the north (rear) elevation consists of a single-leaf, paneled wood door with lights and a 1/1, double-hung, vinyl-sash window with a concrete sill and three-course, rowlock brick segmental arch.

A two-story, one-bay brick ell is located on the rear of the rowhouse. This brick appendage has a shed roof and 1/1, double-hung, vinyl-sash windows with concrete sills. The second-story opening features a three-course, rowlock brick segmental arch.

Site Notes:

September 2010: This single family rowhouse is located north of D Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The west (side) elevation is adjacent to 1530 D Street, S.E. and the east (side) elevation to 1534 D Street, S.E. Enclosed with a metal bow and point fence, the landscaped front yard has a brick walkway extending from the front porch to the sidewalk. The backyard, partially enclosed with a metal chain-link fence, extends north to an alley.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:
Contributing:

Designation Event(s) _____

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1532_D_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1532_D_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1532_D_Street_SE_rear_looking_S.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/11/1912	5853	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0047

BASICS DATA

ID Number: **1074-0047** Year Built: **1912** Data Source: **Permit**

Number Extended Street Quad Type of Address

1534 **D Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1534 D Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0047 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1912** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1912** **Permit** **2150 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of thirteen rowhouses constructed from the same permit (#5853).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 13)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **12**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Shed

Outbuilding Notes:

September 2010: This one-story, one-bay prefabricated shed, based on its materials, appears to have been constructed c. 1970. The metal structure is clad in vertical metal sheets and capped by a front-gabled roof of corrugated metal.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1912 by Harry A. Kite, this two-story, two-bay, Classical Revival-style single-family rowhouse was one of thirteen constructed from the same permit (#5853). Set on a solid concrete foundation, this brick structure prominently features its Flemish-bond brickwork. A sloped roof caps the dwelling and features a molded metal cornice set between molded end brackets. An interior brick chimney pierces the roof. The façade (south elevation) has 1/1, double-hung, vinyl-sash windows with concrete lug sills and lintels. A two-course brick sill string highlights the second-story openings. A single-leaf, paneled wood door with lights is located in the eastern bay. The door is accompanied by a single-light wood transom and concrete lug lintel. A one-story, full-width porch set on a concrete slab shelters the first story. The flat roof has overhanging eaves and is supported by a Tuscan columns. Metal balusters complete the porch. Fenestration of the north (rear) elevation consists of 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A two-story, one-bay brick ell is located on the rear of the rowhouse and capped by a shed roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills and a single-leaf, flush wood door with diamond light. Each opening has a three-course, rowlock brick segmental arch.

Site Notes:

September 2010: This single family rowhouse is located north of D Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The west (side) elevation is adjacent to 1532 D Street, S.E. and the east (side) elevation to 1536 D Street, S.E. Enclosed with a metal bow and point fence, the front yard has a manicured lawn with mature shrubs. A concrete walkway extends from the front porch to the sidewalk. The backyard, enclosed with a metal chain-link fence, extends north to an alley and includes a shed and brick parking pad.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Pannels Material

Notable Interior Plan(s) Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Ward/ANC:

Transfer Date:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\

File: 1534_D_Street_SE_facade_looking_NE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\

File: 1534_D_Street_SE_facade_looking_NW.jpg

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\

File: 1534_D_Street_SE_rear_looking_N.jpg

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/11/1912	5853	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0046

BASICS DATA

ID Number: **1074-0046** Year Built: **1912** Data Source: **Permit**

Number Extended Street Quad Type of Address

1536 D Street SE Current

Name(s) Type of Name

Rowhouse, 1536 D Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0046 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1912 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1912 Permit 2153 Permit

Construction Event Association Associated Name

Orig Construction Architect Landvoigt, A. E.

Orig Construction Builder Kite, Harry A.

Orig Construction Owner Kite, Harry A.

Construction Notes:

One of thirteen rowhouses constructed from the same permit (#5853).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 13)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **12**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1912 by Harry A. Kite, this two-story, two-bay, Classical Revival-style single-family rowhouse was one of thirteen constructed from the same permit (#5853). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and features a molded metal cornice set between molded end brackets. An interior brick chimney with parged cap pierces the roof. The façade (south elevation) has 1/1, double-hung, vinyl-sash windows with concrete lug sills and lintels. A two-course brick sill string highlights the second-story openings. A single-leaf, paneled wood door with semi-circular light is located in the western bay. Set in a narrow, square-edge wood surround, the door is accompanied by a single-light transom and concrete lug lintel. A one-story, full-width porch set on a concrete slab shelters the first story. Supported by Tuscan columns, the flat roof has overhanging eaves and a metal gutter system. Fenestration of the north (rear) elevation consists of 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A two-story, one-bay brick ell is located on the rear of the rowhouse. This brick appendage has a shed roof and a single-leaf door with lights and 1/1, double-hung, vinyl-sash windows. Each opening has a concrete sill and a three-course, rowlock brick segmental arch.

Site Notes:

September 2010: This single family rowhouse is located north of D Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The west (side) elevation is adjacent to 1534 D Street, S.E. and the east (side) elevation to 1538 D Street, S.E. Enclosed with a metal bow and point fence, the landscaped front yard has mature and immature shrubs and plantings. A concrete walkway extends from the front porch to the sidewalk. The backyard, partially enclosed with a metal chain-link fence, extends north to an alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:
Contributing:

Designation Event(s) _____

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **1536_D_Street_SE_facade_looking_N.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **1536_D_Street_SE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **1536_D_Street_SE_rear_looking_SE.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/11/1912	5853	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0045

BASICS DATA

ID Number: **1074-0045** Year Built: **1912** Data Source: **Permit**

Number Extended Street Quad Type of Address

1538 D Street SE Current

Name(s) Type of Name

Rowhouse, 1538 D Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0045 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1912 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1912 Permit 2150 Permit

Construction Event Association Associated Name

Orig Construction Architect Landvoight, A.E.

Orig Construction Builder Kite, Harry A.

Orig Construction Owner Kite, Harry A.

Construction Notes:

One of thirteen rowhouses constructed from the same permit (#5853).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 13)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **12**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1912 by Harry A. Kite, this two-story, two-bay, Classical Revival-style single-family rowhouse was one of thirteen constructed from the same permit (#5853). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and features a molded metal cornice set between molded end brackets. An interior brick chimney with parged cap pierces the roof. The façade (south elevation) has 1/1, double-hung, vinyl-sash windows with concrete lug sills and lintels. A two-course brick sill string highlights the second-story openings. A single-leaf, paneled wood door is located in the eastern bay. Set in a narrow, square-edge wood surround, the door is accompanied by a single-light transom and concrete lug lintel. A one-story, full-width porch set on a concrete slab shelters the first story. Supported by Tuscan columns, the flat roof has overhanging eaves. Twisted metal balusters complete the porch. Fenestration of the north (rear) elevation consists of 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A two-story, one-bay brick ell is located on the rear of the rowhouse. This brick appendage has a shed roof and is pierced by 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A one-story, one-bay enclosed porch is located on the north (rear) elevation of the ell. This original porch has been enclosed with vinyl siding. A shed roof of asphalt shingles with overhanging eaves caps the porch. Window openings are covered with plywood yet retain square-edge wood surrounds. A single-leaf door opening (door not visible) is located on the east (side) elevation of the enclosed porch.

Site Notes:

September 2010: This single family rowhouse is located north of D Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The west (side) elevation is adjacent to 1536 D Street, S.E. and the east (side) elevation to 1538 D Street, S.E. Enclosed with a metal bow and point fence, the grassy front yard has mature shrubs. A concrete walkway extends from the front porch to the sidewalk. The backyard, enclosed with a metal chain-link fence, extends north to an alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**
Subdivision:
Ward/ANC:
Zoning:
Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Historic District(s)

Designation Event(s)

Level(s) of Investigation
Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1538_D_Street_SE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1538_D_Street_SE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1538_D_Street_SE_rear_looking_S.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/11/1912	5853	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0044

BASICS DATA

ID Number: **1074-0044** Year Built: **1912** Data Source: **Permit**

Number Extended Street Quad Type of Address

1540 **D Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1540 D Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0044 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1912** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1912** **Permit** **2150 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoight, A.E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of thirteen rowhouses constructed from the same permit (#5853).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 13)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **12**

Depth/Length: **42**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1912 by Harry A. Kite, this two-story, two-bay, Classical Revival-style single-family rowhouse was one of thirteen constructed from the same permit (#5853). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and features a molded metal cornice set between molded end brackets. An interior brick chimney with parged cap pierces the roof. The façade (south elevation) has 1/1, double-hung, vinyl-sash windows with concrete lug sills and lintels. A two-course brick sill string highlights the second-story openings. A single-leaf, paneled wood door is located in the western bay. Set in a narrow, square-edge wood surround, the door is accompanied by a single-light transom and concrete lug lintel. A one-story, full-width porch set on a concrete slab shelters the first story. Supported by Tuscan columns, the flat roof has overhanging eaves. Fenestration of the north (rear) elevation consists of 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A two-story, one-bay brick ell is located on the rear of the rowhouse. This brick appendage has a shed roof and is pierced by 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches.

Site Notes:

September 2010: This single family rowhouse is located north of D Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The west (side) elevation is adjacent to 1538 D Street, S.E. and the east (side) elevation to 1542 D Street, S.E. Enclosed with a metal bow and point fence, the front yard has been improved with mature shrubs, plantings, and flowers. A concrete walkway extends from the front porch to the sidewalk. The backyard, enclosed with a tall wooden privacy fence fence, extends north to an alley.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Pannels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Designation Level(s)

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1540_D_Street_SE_facade_looking_N.jpg
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1540_D_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1540_D_Street_SE_rear_looking_SE.jpg
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/11/1912	5853	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0043

BASICS DATA

ID Number: **1074-0043** Year Built: **1912** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1542		D Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1542 D Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0043			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1912	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1912	Permit			2153 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Landvoigt, A. E.
Orig Construction	Builder	Kite, Harry A.
Orig Construction	Owner	Kite, Harry A.

Construction Notes:

One of thirteen rowhouses constructed from the same permit (#5853).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 13)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**
Height:
Width: **12**
Depth/Length: **42**
SqFt:

Outbuilding Type	Contributing Status
------------------	---------------------

Volume:
Lot Width:
Lot Depth/Length:
Lot SqFt:
Acreage:
Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1912 by Harry A. Kite, this two-story, two-bay, Classical Revival-style single-family rowhouse was one of thirteen constructed from the same permit (#5853). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and features a molded metal cornice set between molded end brackets. An interior brick chimney with parged cap pierces the roof. The façade (south elevation) has 6/6, double-hung, wood-sash windows with concrete lug sills and lintels. A two-course brick sill string highlights the second-story openings. A single-leaf, paneled wood door is located in the eastern bay. Set in a narrow, square-edge wood surround, the door is accompanied by a single-light transom and concrete lug lintel. A one-story, full-width porch set on a concrete slab shelters the first story. The flat roof has overhanging eaves and is supported by brick posts. Metal balusters extends between the posts and a brick pier with concrete cap. Fenestration of the north (rear) elevation consists of 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A two-story, one-bay brick ell is located on the rear of the rowhouse. This appendage has a shed roof and is pierced by 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches.

Site Notes:

September 2010: This single family rowhouse is located north of D Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The west (side) elevation is adjacent to 1540 D Street, S.E. and the east (side) elevation to 1544 D Street, S.E. Enclosed with a metal bow and point fence, the grassy front yard has mature shrubs. A concrete walkway extends from the front porch to the sidewalk. The backyard, enclosed with a wooden privacy fence, extends north to an alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Designation Level(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1542_D_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1542_D_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1542_D_Street_SE_rear_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/11/1912	5853	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0042

BASICS DATA

ID Number: **1074-0042** Year Built: **1912** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1544		D Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1544 D Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0042			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1912	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1912	Permit			2150 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Landvoigt, A. E.
Orig Construction	Builder	Kite, Harry A.
Orig Construction	Owner	Kite, Harry A.

Construction Notes:

One of thirteen rowhouses constructed from the same permit (#5853).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 13)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**

Height:	Outbuilding Type	Contributing Status
---------	------------------	---------------------

Width:
Depth/Length:
SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1912 by Harry A. Kite, this two-story, two-bay, Classical Revival-style single-family rowhouse was one of thirteen constructed from the same permit (#5853). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and features a molded metal cornice set between molded end brackets. An interior brick chimney with parged cap pierces the roof. The façade (south elevation) has 1/1, double-hung, vinyl-sash windows with concrete lug sills and lintels. A two-course brick sill string highlights the second-story openings. A single-leaf, paneled wood door with semi-circular light is located in the western bay. Set in a narrow, square-edge wood surround, the door is accompanied by a single-light transom and concrete lug lintel. A one-story, full-width porch set on a concrete slab shelters the first story. The flat roof has overhanging eaves and is supported by brick posts. Twisted metal balusters extends between the posts and a brick pier with concrete cap. Lattice encloses the western end of the porch. Fenestration of the north (rear) elevation consists of 2/2, double-hung, wood-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A two-story, one-bay brick ell is located on the rear of the rowhouse. This appendage has a shed roof and is pierced by 1/1, double-hung, wood-sash windows with concrete sills and three-course, rowlock brick segmental arches.

Site Notes:

September 2010: This single family rowhouse is located north of D Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The west (side) elevation is adjacent to 1542 D Street, S.E. and the east (side) elevation to 1546 D Street, S.E. Enclosed with a metal bow and point fence, the front yard has been covered with mulch. Immature shrubs and plantings dot the yard. A concrete walkway extends from the front porch to the sidewalk. The backyard, enclosed with a wooden privacy fence, extends north to an alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:
Contributing:

Designation Event(s) _____

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **1500_D_Street_SE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **1544_D_Street_SE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **1544_D_Street_SE_rear_looking_SE.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/11/1912	5853	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0041

BASICS DATA

ID Number: **1074-0041** Year Built: **1912** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1546		D Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1546 D Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0041			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1912	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1912	Permit			2150 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Landvoight, A.E.
Orig Construction	Builder	Kite, Harry A.
Orig Construction	Owner	Kite, Harry A.

Construction Notes:

One of thirteen rowhouses constructed from the same permit (#5853).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row End (1 of 13)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **Rectangular (w/ side bays)**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**
Height:
Width: **12**
Depth/Length: **42**
SqFt:

Outbuilding Type	Contributing Status
------------------	---------------------

Volume:
Lot Width:
Lot Depth/Length:
Lot SqFt:
Acreage:
Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1912 by Harry A. Kite, this two-story, two-bay, Classical Revival-style single-family rowhouse was one of thirteen constructed from the same permit (#5853). This semi-detached dwelling is unique with its canted corner and projecting side bays. Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof is obscured by a heavy, molded metal cornice with scrolled brackets. Two, interior parged chimneys with corbeled brick caps pierce the roof. Window openings hold 1/1, double-hung, vinyl-sash windows with concrete lug sills and lintels. A two-course, brick sill string accents the second-story openings. The main entry, located in the canted southeast corner, holds a single-leaf, paneled wood door with oval light. Set in a Colonial Revival-style surround composed of fluted pilasters and a plain entablature, the opening is sheltered by a one-story, one-bay porch. Set on a brick stoop, the porch has a front-gabled roof of asphalt shingles supported by thin Tuscan columns. The south elevation has a projecting three-sided bay window with 1/1, double-hung, vinyl-sash windows flanking a picture window. This non-original window has a brick-veneered base. The east (side) elevation has two, two-story projecting bays. The north (rear) elevation has a single-leaf, paneled wood door with lights located on the first story. This opening has a wood surround composed of plain pilasters, frieze, and blocked entablature. A 1/1, double-hung, vinyl-sash window pierces the second story. This window is smaller than the original opening, as evidenced by the concrete sill approximately one foot below the current window. A second, second-story window openings has been enclosed with brick.

Site Notes:

September 2010: This single-family rowhouse is located on a corner lot northwest of the intersection of D Street, S.E. and 16th Street, S.E. The west (side) elevation is adjacent to 1544 D Street, S.E. With a setback of approximately fifteen feet from the public concrete sidewalk, the front yard has been covered with concrete squares. A milled point security fence encloses the front yard and extends down the 16th Street sidewalk. Mature shrubs and a mature tree anchor the northeast corner of the property. The small backyard has been covered with brick and is enclosed with a milled point metal security fence.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1546_D_Street_SE_facade_looking_N.jpg**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1546_D_Street_SE_rear_looking_SE (1).JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1546_D_Street_SE_rear_looking_SE (2).JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1546_D_Street_SE_rear_looking_SE.jpg**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 1546_D_Street_SE_rear_looking_SW.JPG
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 1546_D_Street_SE_Southeast_corner.JPG
 Date:: Photog:
 Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/11/1912	5853	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0062

BASICS DATA

ID Number: **1074-0062** Year Built: **1914** Data Source: **Permit**

Number	Extended	Street	Quad Type	of Address
309		16th Street	SE	Current

Name(s)	Type of Name
Rowhouse, 309 16th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0062			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Multifamily/Misc)	1914	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1914	Permit			2500 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Landvoigt, A. E.
Orig Construction	Builder	Kite, Harry A.
Orig Construction	Owner	Kite, Harry A.

Construction Notes:

One of eight similar rowhouses constructed from the same permit (#2110).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row End (1 of 8)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
Bays Wide:
Height:
Width: **13**
Depth/Length: **40**
SqFt:

Outbuilding Type	Contributing Status
------------------	---------------------

Volume:
Lot Width
Lot Depth/Length:
Lot SqFt:
Acreage:
Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1914 by Harry A. Kite, this two-story, two-bay single-family rowhouse is one of eight constructed from the same permit (#2110). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof features an ogee-molded metal cornice supported by decorative end brackets. A thin, molded metal string extends just below the cornice. An interior brick chimney with parged cap pierces the roof. Window openings on the façade (east elevation) have 1/1, double-hung, vinyl-sash windows with concrete lug sills and lintels.

The original one-story, full-width front porch has been enclosed with brick. A single-leaf, paneled wood door with two lights and a 1/1, double-hung, vinyl-sash window pierce the enclosed porch. The porch retains its flat roof and overhanging eaves.

Fenestration of the north (side) elevation consists of 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches. The west (rear) elevation has 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches. An original door opening has been infilled with a single-leaf, paneled metal door with lights. The transom has been infilled with brick, however, the three-course, rowlock brick segmental arch remains.

Site Notes:

September 2010: This semi-detached single-family rowhouse is located west of 16th Street, S.E. and has a setback of approximately twenty feet from the public sidewalk. The south (side) elevation is adjacent to 311 16th Street, S.E. while a narrow alley fronts the north (side) elevation. The front yard has a brick walkway extending from the front of the dwelling to the sidewalk. The backyard extends west to an alley and includes a concrete parking pad.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:
Contributing:

Designation Event(s) _____

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **309_16th_Street_SE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **309_16th_Street_SE_facade_looking_SW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **309_16th_Street_SE_rear_looking_E.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
11/09/1914	2110	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0063

BASICS DATA

ID Number: **1074-0063** Year Built: **1914** Data Source: **Permit**

Number Extended Street Quad Type of Address

311 **16th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 311 16th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0063 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1914** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Rear Addition **c. 1980** **Site Visit/Map**

Orig Construction **1914** **Permit** **2500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of eight similar rowhouses constructed from the same permit (#2110).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row (1 of 8)**
 Relate to Street: **Front Yard/Setback**
 Massing: **Row Building/Front Porch**
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
 Bays Wide: **2**
 Height: **13**
 Width: **13**
 Depth/Length: **40**

Outbuilding Type Contributing Status

SqFt:
 Volume:
 Lot Width
 Lot Depth/Length:
 Lot SqFt:
 Acreage:
 Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1914 by Harry A. Kite, this two-story, two-bay single-family rowhouse is one of eight constructed from the same permit (#2110). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof features an ogee-molded metal cornice supported by decorative end brackets. A thin, molded metal string extends just below the cornice. An interior brick chimney with parged cap pierces the roof. Window openings on the façade (east elevation) have 1/1, double-hung, vinyl-sash windows. The first story window opening is paired and has a rowlock brick sill. The two second-story openings have concrete sills and lug lintels. The main entry, located in the northern bay, holds a single-leaf, paneled wood door with semi-circular light. Set in a narrow, square-edge wood surround, the door is accompanied by a single-light transom. A one-story, full-width porch on the façade has a flat roof with overhanging eaves. Tuscan columns set on the concrete slab deck support the roof. Fenestration of the west (rear) elevation consists of 1/1, double-hung, vinyl-sash windows.

A two-story, one-bay ell is located on the rear of the dwelling. Clad in aluminum siding and capped by a shed roof, the ell has 1/1, double-hung, vinyl-sash windows. Metal awnings shelter the openings.

A one-story addition is located on the rear of the ell. Based on its form and materials, it appears that this addition was constructed c. 1980. Clad in aluminum siding, the addition is capped by a double-sloped shed roof of metal sheets. Fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf, paneled wood door.

Site Notes:

September 2010: This single-family rowhouse is located west of 16th Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The house is adjacent to 309 and 313 16th Street, S.E. The grassy front yard has mature shrubs and is enclosed with a bow and point metal fence. A concrete walkway extends from the front porch to the sidewalk. The backyard, covered with concrete, is enclosed with a metal chain-link fence. A mature tree is located in the southwest corner.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Pannels Material

Notable Interior Plan(s) _____

Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s) _____

Contributing:

Survey(s) _____

Level(s) of Investigation _____

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**

File: **311_16th_Street_SE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**

File: **311_16th_Street_SE_facade_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074\
File: 311_16th_Street_SE_rear_looking_E.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
11/09/1914	2110	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0064

BASICS DATA

ID Number: **1074-0064** Year Built: **1914** Data Source: **Permit**

Number Extended Street Quad Type of Address

313 **16th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 313 16th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0064 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1914** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Rear Addition **c. 1970** **Site Visit/Map**

Orig Construction **1914** **Permit** **2500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of eight similar rowhouses constructed from the same permit (#2110).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row (1 of 8)**
 Relate to Street: **Front Yard/Setback**
 Massing: **Row Building/Front Porch**
 Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
 Bays Wide: **2**
 Height: **13**
 Width: **13**
 Depth/Length: **40**
 SqFt:
 Volume:
 Lot Width
 Lot Depth/Length:
 Lot SqFt:
 Acreage:
 Has Driveway:

Outbuilding Type	Contributing Status
------------------	---------------------

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1914 by Harry A. Kite, this two-story, two-bay single-family rowhouse is one of eight constructed from the same permit (#2110). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof features an ogee-molded metal cornice supported by decorative end brackets. A thin, molded metal string extends just below the cornice. An interior brick chimney with parged cap pierces the roof. Located in the southern bay of the first story, the main entry holds a single-leaf, flush wood door with single-light transom. Window openings have 1/1, double-hung, vinyl-sash windows with concrete sills and lug lintels. Inoperable, louvered vinyl shutters flank each opening. A one-story, full-width porch highlights the façade. With its flat roof, overhanging eaves, and molded metal cornice, the porch features Tuscan columns with square balusters. A wood post with newel is located along the front of the porch. The west (rear) elevation of the dwelling has 1/1, double-hung, wood-sash windows with wood sills and three-course, rowlock brick segmental arches.

A two-story, one-bay brick ell is located on the rear of the dwelling. Fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills.

A one-story, one-bay addition is located on the rear of the ell. Based on its form and materials, as well as Sanborn Fire Insurance Company maps, this addition was constructed c. 1970 and may have originally been a porch. Now clad in aluminum siding and capped by a shed roof, the addition has two-light, vinyl-sash sliding windows and a single-leaf, flush wood door accessed via concrete steps.

Site Notes:

September 2010: This single-family rowhouse is located west of 16th Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The house is adjacent to 311 and 315 16th Street, S.E. The grassy front yard has mature shrubs and is enclosed with a bow and point metal fence. A concrete walkway extends from the front porch to the sidewalk. The backyard is enclosed with a metal chain-link fence. A wooden security fence fronts the alley west of the property.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature		Source
---------------------	----------	---------	--	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s) Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **313_16th_Street_SE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **313_16th_Street_SE_facade_looking_SW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074\
File: 313_16th_Street_SE_rear_looking_E.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
11/09/1914	2110	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0065

BASICS DATA

ID Number: **1074-0065** Year Built: **1914** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
315		16th Street	SE	Current

Name(s)	Type of Name
Rowhouse, 315 16th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0065			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1914	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1914	Permit			2500 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Landvoight, A.E.
Orig Construction	Builder	Kite, Harry A.
Orig Construction	Owner	Kite, Harry A.

Construction Notes:

One of eight rowhouses constructed from the same permit (#2110).


PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 8)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:



Number Stories: **2**
Bays Wide: **2**
Height:
Width: **13**
Depth/Length: **40**

Outbuilding Type	Contributing Status
Garage	

SqFt:
Volume:
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

September 2010: Constructed c. 1940, this metal-frame structure is clad in pressed metal sheets. A shed roof of asphalt shingles caps the building. The façade (west elevation) has a large opening, now with a double-leaf, plywood door with metal strap hinges.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1914 by Harry A. Kite, this two-story, two-bay single-family rowhouse is one of eight constructed from the same permit (#2110). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof features an ogee-molded metal cornice supported by decorative end brackets. A thin, molded metal string extends just below the cornice. An interior brick chimney with parged cap pierces the roof. Located in the northern bay of the first story, the main entry holds a single-leaf, paneled wood door with single-light transom. Window openings have 1/1, double-hung, vinyl-sash windows with concrete sills and lug lintels. A one-story, full-width porch dominates the façade. With its flat roof, overhanging eaves, and molded metal cornice, the porch has Tuscan columns. The porch has been screened and the baluster closed with T1-11 siding. The west (rear) elevation of the dwelling has 1/1, double-hung, wood-sash windows with wood sills and three-course, rowlock brick segmental arches.

A two-story, one-bay brick ell is located on the rear of the dwelling. Fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills.

A one-story, two-bay addition is located on the rear of the dwelling. Clad in vinyl siding, the addition has a shed roof of asphalt shingles. Fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf, flush metal door with light.

Site Notes:

September 2010: This single-family rowhouse is located west of 16th Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The house is adjacent to 313 and 317 16th Street, S.E. The front yard has mature shrubs and is enclosed with a bow and point metal fence. A concrete walkway extends from the front porch to the sidewalk. Enclosed with a wooden privacy fence, the backyard has a garage fronting the rear alley.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research

Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **315_16th_Street_SE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **315_16th_Street_SE_facade_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **315_16th_Street_SE_garage_looking_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **315_16th_Street_SE_rear_looking_E.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code Roll Frame(s) Date Photographer Caption

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
11/09/1914	2110	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0066

BASICS DATA

ID Number: **1074-0066** Year Built: **1914** Data Source: **Permit**

Number Extended Street Quad Type of Address

317 **16th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 317 16th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0066 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1914** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1914** **Permit** **2500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of eight rowhouses constructed from the same permit (#2110).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 8)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **40**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1914 by Harry A. Kite, this two-story, two-bay single-family rowhouse is one of eight constructed from the same permit (#2110). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof features an ogee-molded metal cornice supported by decorative end brackets. A thin, molded metal string extends just below the cornice. An interior brick chimney pierces the roof. Located in the southern bay of the first story, the main entry holds a single-leaf, paneled wood door with single-light transom. Window openings have 1/1, double-hung, vinyl-sash windows with concrete sills and lug lintels. A full-width porch shelters the first story of the façade. Set on a concrete slab, the porch has a flat roof with overhanging eaves supported by Tuscan columns. Square wood balusters complete the porch. The west (rear) elevation has a 1/1, double-hung, vinyl-sash window with a concrete sill and three-course, rowlock brick segmental arch located in the second story.

A two-story, one-bay ell with Flemish-bond brickwork is located on the rear of the dwelling. Capped by a shed roof, the ell has 1/1, double-hung, vinyl-sash windows and a single-leaf, paneled wood door. Openings have concrete sills and three-course, rowlock brick segmental arches.

Site Notes:

September 2010: This single-family rowhouse is located west of 16th Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The house is adjacent to 315 and 319 16th Street, S.E. The front yard has mature shrubs and is partially enclosed with a bow and point metal fence. A concrete walkway extends from the front porch to the sidewalk. The level, grassy backyard extends west to an alley. A wooden privacy fence extends along the northern bounds of the backyard. A brick and concrete walkway winds from the rear entry to the alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Designation Level(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 317_16th_Street_SE_facade_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 317_16th_Street_SE_facade_looking_W.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 317_16th_Street_SE_rear_looking_E.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
11/09/1914	2110	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0067

BASICS DATA

ID Number: **1074-0067** Year Built: **1914** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
319		16th Street	SE	Current

Name(s)	Type of Name
Rowhouse, 319 16th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0067			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1914	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1914	Permit			2500 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Landvoigt, A. E.
Orig Construction	Builder	Kite, Harry A.
Orig Construction	Owner	Kite, Harry A.

Construction Notes:

One of eight rowhouses constructed from the same permit (#2110).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 8)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**
Height:
Width: **13**
Depth/Length: **40**
SqFt:

Outbuilding Type	Contributing Status
------------------	---------------------

Volume:
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1914 by Harry A. Kite, this two-story, two-bay single-family rowhouse is one of eight constructed from the same permit (#2110). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof features an ogee-molded metal cornice supported by decorative end brackets. A thin, molded metal string extends just below the cornice. An interior brick chimney with plain cap pierces the roof. Located in the northern bay of the first story, the main entry holds a single-leaf, paneled wood door with two lights and a single-light transom. Window openings have 1/1, double-hung, vinyl-sash windows with concrete sills and lug lintels. A full-width porch shelters the first story of the façade. Set on a concrete slab, the porch has a flat roof with overhanging eaves supported by Tuscan columns. Twisted metal balusters complete the porch. The west (rear) elevation has 1/1, double-hung, vinyl-sash windows with a concrete sills and three-course, rowlock brick segmental arches.

A two-story, one-bay ell with Flemish-bond brickwork is located on the rear of the dwelling. Capped by a shed roof, the ell has a 1/1, double-hung, vinyl-sash window with a concrete sill and three-course, rowlock brick segmental arch.

A one-story, two-bay porch is located on the rear of the ell. This original feature has been enlarged slightly and enclosed with Hardieplank and capped by a shed roof of standing seam metal. Fenestration consists of a single-leaf, paneled wood door with semi-circular light and a wide, 1/1, double-hung, vinyl-sash window.

Site Notes:

September 2010: This single-family rowhouse is located west of 16th Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The house is adjacent to 317 and 321 16th Street, S.E. The front yard has mature shrubs and is partially enclosed with a bow and point metal fence. A concrete walkway with metal railing extends from the front porch to the sidewalk. The level, grassy backyard extends west to an alley. A metal chain-link fence extends along the southern boundary of the backyard. A brick walkway extends from the rear entry to a concrete parking pad.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **319_16th_Street_SE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **319_16th_Street_SE_facade_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **319_16th_Street_SE_rear_looking_E.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0068

BASICS DATA

ID Number: **1074-0068** Year Built: **1914** Data Source: **Permit**

Number Extended Street Quad Type of Address

321 **16th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 321 16th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0068 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1914** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1914** **Permit** **2500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of eight rowhouses constructed from the same permit (#2110).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 8)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **40**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1914 by Harry A. Kite, this two-story, two-bay single-family rowhouse is one of eight constructed from the same permit (#2110). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof features an ogee-molded metal cornice supported by decorative end brackets. A thin, molded metal string extends just below the cornice. An interior parged chimney pierces the roof. Located in the southern bay of the first story, the main entry holds a single-leaf, paneled wood door with lights and a single-light transom. Window openings have 1/1, double-hung, vinyl-sash windows with concrete sills and lug lintels. Inoperable louvered vinyl shutters flank each window opening. A full-width porch shelters the first story of the façade. Set on a concrete slab, the porch has a flat roof with overhanging eaves supported by a Tuscan column and a brick post. Twisted metal balusters complete the porch. The west (rear) elevation has 1/1, double-hung, vinyl-sash windows with a concrete sills and three-course, rowlock brick segmental arches.

A two-story, one-bay ell with Flemish-bond brickwork is located on the rear of the dwelling. Capped by a shed roof, the ell is pierced by 1/1, double-hung, vinyl-sash windows and a single-leaf, paneled wood door with semi-circular light. All openings have concrete sills and three-course, rowlock brick segmental arches. A one-story wood deck has been constructed on the rear of the ell.

Site Notes:

September 2010: This single-family rowhouse is located west of 16th Street, S.E. and has a setback from the sidewalk of approximately twenty feet. The house is adjacent to 319 and 323 16th Street, S.E. The front yard has mature shrubs and is partially enclosed with a bow and point metal fence. A brick retaining wall is located aside the sidewalk. A brick walkway with concrete steps links the front porch with the sidewalk. The level, grassy backyard extends west to an alley and is enclosed with a metal chain-link fence.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:
Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 321_16th_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 321_16th_Street_SE_facade_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 321_16th_Street_SE_rear_looking_ESE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
11/09/1914	2110	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0069

BASICS DATA

ID Number: **1074-0069** Year Built: **1914** Data Source: **Permit**

Number Extended Street Quad Type of Address

323 **16th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 323 16th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0069 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1914** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Rear Addition **c. 2000** **Site Visit/Map**

Orig Construction **1914** **Permit** **2500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of eight rowhouses constructed from the same permit (#2110).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row (1 of 8)**
 Relate to Street: **Front Yard/Setback**
 Massing: **Row Building/Front Porch**
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
 Bays Wide: **2**
 Height: **13**
 Width: **13**
 Depth/Length: **40**
 SqFt:
 Volume:
 Lot Width
 Lot Depth/Length:
 Lot SqFt:
 Acreage:
 Has Driveway:

Outbuilding Type Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1914 by Harry A. Kite, this two-story, two-bay single-family rowhouse is one of eight constructed from the same permit (#2110). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof features an ogee-molded metal cornice supported by decorative end brackets. A thin, molded metal string extends just below the cornice. An interior parged chimney pierces the roof. Located in the southern bay of the first story, the main entry holds a single-leaf, paneled wood door with semi-circular light and a single-light transom. Window openings have 1/1, double-hung, vinyl-sash windows with concrete sills and lug lintels. Inoperable louvered vinyl shutters flank each window opening. A full-width porch shelters the first story of the façade. Set on a concrete slab, the porch has a flat roof with overhanging eaves supported by brick posts. The original balustrade has been removed in favor of one composed of decorative concrete block. The southern end of the porch has a closed balustrade of brick. The west (rear) elevation has 1/1, double-hung, vinyl-sash windows with a concrete sills and three-course, rowlock brick segmental arches.

The south (side) elevation holds 1/1, double-hung, vinyl-sash windows with header sills and three-course, rowlock brick segmental arches.

The west (rear) elevation has a two-story, full-width addition, which based on its form, materials, and Sanborn Fire Insurance Company maps, appears to have been constructed c. 1990. The addition has a stretcher-bond brick veneer and a shed roof. Fenestration consists of two-light, vinyl-sash sliding windows with inoperable louvered shutters. A single-leaf, paneled wood door with semi-circular light is located on the west (rear) elevation.

Site Notes:

September 2010: Located at the end of a row, this semi-detached rowhouse on the west side of 16th Street, S.E. has a setback of approximately twenty feet from the concrete public sidewalk. The north (side) elevation is adjacent to 321 16th Street, S.E. while a brick and concrete alley fronts the south (side) elevation. The raised front yard is lined with brick retaining walls adorned with milled point fencing or decorative concrete blocks. A milled point and hoop metal fence lines the northern side of the front yard. Mature shrubs and a brick walkway define the front yard. Extending west, the deep backyard has a tall concrete-block security wall along the southern edge of the property. Accessed via a brick walkway, a concrete parking pad is located at the end of the grassy backyard.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
-----------------------------------	----------------------

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\

File: 323_16th_Street_SE_facade_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\

File: 323_16th_Street_SE_facade_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074\

File: 323_16th_Street_SE_rear_looking_E.JPG

Date: Photog:

Code: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
11/09/1914	2110	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0078

BASICS DATA

ID Number: **1074-0078** Year Built: **1915** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
325		16th Street	SE	Current

Name(s)	Type of Name
Rowhouse, 325 16th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0078			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1915	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1915	Permit			1500 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Landvoight, A.E.
Orig Construction	Builder	Kite, Harry A.
Orig Construction	Owner	Kite, Harry A.

Construction Notes:

One of seven rowhouses constructed from the same permit (#5272).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row End (1 of 7)**
Relate to Street: **Raised Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **3**
Height:
Width: **15**
Depth/Length: **40**
SqFt:

Outbuilding Type	Contributing Status
------------------	---------------------

Volume:
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

August 2010: Constructed in 1915 by Harry A. Kite, this two-story, three-bay Classical Revival-style single-family rowhouse is one of seven similar dwellings constructed from the same permit (#5272). The dwelling is constructed of brick and is faced with Flemish-bond brick. Set on a solid concrete foundation, the dwelling is capped by a sloping roof with an interior-side brick chimney along the north elevation. The façade (east elevation) features a molded metal cornice set on scrolled end brackets connected with a thin molded string. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows with concrete lug sills. There are no lintels. Located in the southern bay of the façade, the main entry holds a single-leaf, wood-frame glass door set in a surround composed of pilasters and a splayed entablature. A one-story, full-width porch dominates the façade. Set on a brick pier foundation with a wood deck, the porch has a flat roof with overhanging eaves supported by thin Tuscan columns. Square wood balusters complete the porch. Fenestration of the north (side) elevation includes 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches. The west (rear) elevation has 1/1, double-hung, vinyl-sash windows with wood sills. A single-leaf door with blind transom is located in the southern bay of the first story. All openings have three-course, rowlock brick segmental arches.

Site Notes:

August 2010: Located west of 16th Street, S.E., this semi-detached rowhouse has a setback from the concrete sidewalk of approximately twenty feet. The south (side) elevation is adjacent to 327 16th Street, S.E. while a concrete and brick alley fronts the north (side) elevation. Improved with a manicured lawn, mature trees and shrubs, the front yard is enclosed with a milled point metal fence. A concrete walkway links the front porch with the sidewalk. The backyard extends west to an alley and is enclosed with a wooden privacy fence. A wood deck has been constructed on the first story of the rear of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:
Contributing:

Designation Event(s) _____

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **325_16th_Street_SE_facade_looking_SW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **325_16th_Street_SE_facade_looking_W.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **325_16th_Street_SE_rear_looking_ESE.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/15/1915	5272	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0079

BASICS DATA

ID Number: **1074-0079** Year Built: **1915** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
327		16th Street	SE	Current

Name(s)	Type of Name
Rowhouse, 327 16th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0079			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1915	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1915	Permit			1500 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Landvoight, A.E.
Orig Construction	Builder	Kite, Harry A.
Orig Construction	Owner	Kite, Harry A.

Construction Notes:

One of seven rowhouses constructed from the same permit (#5722).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 7)**
Relate to Street: **Raised Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:



Number Stories: **2**
Bays Wide: **3**
Height: **15**
Width: **40**
Depth/Length: **40**

Outbuilding Type	Contributing Status
Shed	

SqFt:
Volume:
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

September 2010: This one-story, one-bay prefabricated shed has a rubber structure, cladding, and front-gabled roof. Additional details were not visible from the public right-of-way.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

August 2010: Constructed in 1915 by Harry A. Kite, this two-story, three-bay Classical Revival-style single-family rowhouse is one of seven similar dwellings constructed from the same permit (#5272). The dwelling is constructed of brick and is faced with Flemish-bond brick. Set on a solid concrete foundation, the dwelling is capped by a sloping roof with an interior brick chimney. The façade (east elevation) features a molded metal cornice set on scrolled end brackets connected with a thin molded string. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows with concrete lug sills. There are no lintels. Located in the southern bay of the façade, the main entry holds a single-leaf, paneled wood door with single-light transom. A one-story, full-width porch dominates the façade. The porch has a flat roof with overhanging eaves supported by Tuscan columns and a wood post. Square wood balusters complete the porch. Fenestration of the west (rear) elevation consists of 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A two-story brick ell is located on the rear of the dwelling. The ell has tripled 1/1, double-hung, vinyl-sash windows with concrete sills.

Site Notes:

August 2010: Located west of 16th Street, S.E., this rowhouse is set back from the concrete sidewalk approximately twenty feet. The dwelling is adjacent to 325 and 329 16th Street, S.E. The front yard is enclosed with a metal chain-link fence and bow and picket metal fence. Primarily covered with rock, the front yard includes mature foundation plantings. A concrete walkway extends from the front porch to the sidewalk. The backyard extends west to an alley and is enclosed with a wooden privacy fence. A shed is located in the backyard.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Designation Level(s)

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **327_16th_Street_SE_facade_looking_SW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **327_16th_Street_SE_facade_looking_W.jpg**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **327_16th_Street_SE_rear_looking_E.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **327_16th_Street_SE_shed_looking_SE.jpg**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/15/1915	5722	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0080

BASICS DATA

ID Number: **1074-0080** Year Built: **1915** Data Source: **Permit**

Number Extended Street Quad Type of Address

329 **16th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 329 16th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0080 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1915** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1915** **Permit** **1500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of seven rowhouses constructed from the same permit (#5722).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 7)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **15**

Depth/Length: **40**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

August 2010: Constructed in 1915 by Harry A. Kite, this two-story, three-bay Classical Revival-style single-family rowhouse is one of seven similar dwellings constructed from the same permit (#5272). The dwelling is constructed of brick and is faced with pressed Flemish-bond brick. Set on a solid concrete foundation, the dwelling is capped by a sloping roof with an interior brick chimney. The façade (east elevation) features a molded metal cornice set on scrolled end brackets connected with a thin molded string. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows with concrete lug sills. There are no lintels. Located in the northern bay of the façade, the main entry holds a single-leaf, paneled wood door with a blank transom. A one-story, full-width porch highlights the front of the rowhouse. The porch has a flat roof with overhanging eaves supported by Tuscan columns. Square wood balusters complete the porch. Fenestration of the west (rear) elevation consists of 1/1, double-hung, wood-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A two-story, one-bay rear ell has been parged along the west (rear) elevation. An exterior-side brick chimney rises along the south elevation. Fenestration consists of 1/1, double-hung, wood-sash windows with concrete sills.

A one-story, two-bay porch is located on the rear of the ell. This original feature has been enclosed with T1-11 siding and is capped by a shed roof of asphalt sheets. Fenestration consists of 6/6, double-hung, wood-sash windows and a single-leaf wood door.

Site Notes:

August 2010: Located west of 16th Street, S.E., this rowhouse is set back from the concrete sidewalk approximately twenty feet. The dwelling is adjacent to 327 and 331 16th Street, S.E. Landscaped with immature shrubs and foundation plantings, the front yard is enclosed with a bow and picket metal fence. A concrete walkway extends from the front porch to the sidewalk. The backyard extends west to an alley and is enclosed with a wooden privacy fence.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **329_16th_Street_SE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **329_16th_Street_SE_facade_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **329_16th_Street_SE_rear_looking_NE.jpg**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0081

BASICS DATA

ID Number: **1074-0081** Year Built: **1915** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
331		16th Street	SE	Current

Name(s)	Type of Name
Rowhouse, 331 16th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0081			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1915	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1915	Permit			1500 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Landvoigt, A. E.
Orig Construction	Builder	Kite, Harry A.
Orig Construction	Owner	Kite, Harry A.

Construction Notes:

One of seven rowhouses constructed from the same permit (#5272).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 7)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **3**
Height: **15**
Width: **40**
Depth/Length: **40**

Outbuilding Type	Contributing Status
------------------	---------------------

SqFt:
Volume:
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

August 2010: Constructed in 1915 by Harry A. Kite, this two-story, three-bay Classical Revival-style single-family rowhouse is one of seven similar dwellings constructed from the same permit (#5272). The dwelling is constructed of brick and has been faced with Permastone. Set on a solid concrete foundation, the dwelling is capped by a sloping roof. The façade (east elevation) features a molded metal cornice set on scrolled end brackets. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows with 6/6 false muntins and concrete lug sills. Faux Permastone keystone arches complete each opening. Located in the southern bay of the façade, the main entry holds a single-leaf, paneled wood door with lights. A blank transom surmounts the door. A one-story, three-bay porch spans the width of the façade. The porch has a flat roof with overhanging eaves supported by wood posts and a Tuscan column. Square wood balusters complete the porch. Fenestration of the west (rear) elevation consists of 1/1, double-hung, wood-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A two-story, one-bay brick ell is located on the rear of the dwelling. Capped by a shed roof, an exterior-side brick chimney rises along the north elevation. Fenestration consists of 1/1, double-hung, vinyl-sash windows with 6/6 false muntins. Concrete sills and three-course, rowlock brick segmental arches complete each opening.

A one-story, two-bay porch is located on the rear of the ell. This original feature has been enclosed with T1-11 siding and is capped by a shed roof of asphalt shingles. Wide metal flashing has been fixed to the rear of the ell. Fenestration consists of 1/1, double-hung, vinyl-sash windows with 6/6 false muntins and a single-leaf, paneled door with lights.

Site Notes:

August 2010: Located west of 16th Street, S.E., this rowhouse is set back from the concrete sidewalk approximately twenty feet. The dwelling is adjacent to 329 and 333 16th Street, S.E. Landscaped with shrubs, flowers, and foundation plantings, the front yard is enclosed with a milled point metal fence. A concrete walkway extends from the front porch to the sidewalk. The backyard extends west to an alley and is partially enclosed with a wooden privacy fence. A wooden deck abuts the rear of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**

File: **331_16th_Street_SE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**

File: **331_16th_Street_SE_facade_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**

File: **331_16th_Street_SE_rear_looking_E.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/15/1915	5272	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0082

BASICS DATA

ID Number: **1074-0082** Year Built: **1915** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
333		16th Street	SE	Current

Name(s)	Type of Name
Rowhouse, 333 16th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0082			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1915	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1915	Permit			1500 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Landvoigt, A. E.
Orig Construction	Builder	Kite, Harry A.
Orig Construction	Owner	Kite, Harry A.

Construction Notes:

One of seven rowhouses constructed from the same permit (#5272).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 7)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:



Number Stories: **2**
Bays Wide: **3**
Height: **15**
Width: **40**
Depth/Length: **40**
SqFt:
Volume:
Lot Width

Outbuilding Type	Contributing Status
Shed	

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

September 2010: This one-story, three-bay prefabricated shed was constructed c. 2005. German vinyl siding clads the shed while a shed roof of asphalt shingles caps it. Fenestration consists of 1/1, double-hung, vinyl-sash windows with false 4/4 muntins and a single-leaf, German vinyl-siding-clad door.

Inoperable louvered shutters finish each window opening.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

August 2010: Constructed in 1915 by Harry A. Kite, this two-story, three-bay Classical Revival-style single-family rowhouse is one of seven similar dwellings constructed from the same permit (#5272). The dwelling is constructed of brick and has a Flemish-bond brick veneer. Set on a solid concrete foundation, the dwelling is capped by a sloping roof. The façade (east elevation) features a molded metal cornice set on scrolled end brackets connected by a thin, molded concrete string. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows with concrete lug sills. Located in the northern bay of the façade, the main entry holds a single-leaf, paneled wood door with a single-light transom. A one-story, three-bay porch spans the width of the façade. The porch has a flat roof with overhanging eaves supported by wood posts with square wood balusters set between. Fenestration of the west (rear) elevation consists of 1/1, double-hung, wood-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A two-story, one-bay brick ell is located on the rear of the dwelling. Capped by a shed roof, an exterior-side brick chimney rises along the south elevation. Fenestration consists of 1/1, double-hung, vinyl-sash windows with 6/6 false muntins. Concrete sills complete each opening.

A one-story, two-bay porch is located on the rear of the ell. This original feature has been enclosed with T1-11 siding and is capped by a shed roof of asphalt shingles. Fenestration consists of 1/1, double-hung, vinyl-sash windows with 6/6 false muntins and a single-leaf door.

Site Notes:

August 2010: Located west of 16th Street, S.E., this rowhouse is set back from the concrete sidewalk approximately twenty feet. The dwelling is adjacent to 331 and 335 16th Street, S.E. Landscaped with shrubs and foundation plantings, the front yard is enclosed with a bow and point metal fence. A concrete walkway extends from the front porch to the sidewalk. The backyard extends west to an alley and is enclosed with a wooden privacy fence. A shed is located in the backyard.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**

File: **333_16th_Street_SE_facade_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**

File: **333_16th_Street_SE_facade_looking_W.jpg**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**

File: **333_16th_Street_SE_rear_looking_SE (1).JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**

File: **333_16th_Street_SE_shed_looking_SE.jpg**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/15/1915	5272	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0083

BASICS DATA

ID Number: **1074-0083** Year Built: **1915** Data Source: **Permit**

Number Extended Street Quad Type of Address

335 **16th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 335 16th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0083 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1915** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Rear Addition **c. 1990** **Site Visit/Map**

Orig Construction **1915** **Permit** **1500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of seven rowhouses constructed from the same permit (#5272).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row (1 of 7)**
 Relate to Street: **Front Yard/Setback**
 Massing: **Row Building/Flat Front**
 Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
 Bays Wide: **3**
 Height: **15**
 Width: **15**
 Depth/Length: **40**

Outbuilding Type _____ Contributing Status _____

SqFt:
 Volume:
 Lot Width
 Lot Depth/Length:
 Lot SqFt:
 Acreage:
 Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

August 2010: Constructed in 1915 by Harry A. Kite, this two-story, three-bay Classical Revival-style single-family rowhouse is one of seven similar dwellings constructed from the same permit (#5272). The dwelling is constructed of brick and has a Flemish-bond brick veneer. Set on a solid concrete foundation, the dwelling is capped by a sloping roof. The façade (east elevation) features a molded metal cornice set on scrolled end brackets connected by a thin, molded concrete string. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows with concrete lug sills. Located in the southern bay of the façade, the main entry holds a single-leaf, paneled wood door with a blank transom. Based on Sanborn Fire Insurance Company maps and physical evidence, the roof of the front porch has been removed. A concrete deck extends across the façade and includes a metal balustrade.

A two-story, full-width addition is located on the west (rear) elevation of the rowhouse. Based on its form, materials, and Sanborn Fire Insurance Company maps, this addition appears to have been constructed c. 1990. Clad in German vinyl siding, the addition is capped by a shed roof. Window openings hold 1/1, double-hung, vinyl-sash windows. A single-leaf, paneled metal door with semi-circular light is located in the southern bay of the first story.

Site Notes:

August 2010: Located west of 16th Street, S.E., this rowhouse is set back from the concrete sidewalk approximately twenty feet. The dwelling is adjacent to 333 and 337 16th Street, S.E. Landscaped with shrubs and foundation plantings, the front yard is enclosed with a milled point metal fence. A brick walkway and steps link the main entry to the sidewalk. The backyard extends west to an alley and is enclosed with a wooden privacy fence. A brick parking pad abuts the alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
-----------------------------------	----------------------

Subdivision:	
--------------	--

Ward/ANC:	
-----------	--

Zoning:	Designation Event(s)
---------	----------------------

Contributing:	
---------------	--

Survey(s)	Level(s) of Investigation
-----------	---------------------------

Capitol Hill Southeast Phase II (2010)	Permit Research Reconnaissance Survey
-----------------------------------------------	--------------------------------------------------------

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **335_16th_Street_SE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**
File: **335_16th_Street_SE_facade_looking_SW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074\

File: 335_16th_Street_SE_rear_looking_E.JPG

Date: Photog:

Code: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/15/1915	5272	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0084

BASICS DATA

ID Number: **1074-0084** Year Built: **1915** Data Source: **Permit**

Number Extended Street Quad Type of Address

337 **16th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 337 16th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0084 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1915** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1915** **Permit** **1500 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of seven rowhouses constructed from the same permit (#5272).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 7)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **15**

Depth/Length: **40**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

August 2010: Constructed in 1915 by Harry A. Kite, this two-story, three-bay Classical Revival-style single-family rowhouse is one of seven similar dwellings constructed from the same permit (#5272). The dwelling is constructed of brick and has a Flemish-bond brick veneer. Set on a solid concrete foundation, the dwelling is capped by a sloping roof. An exterior-rear brick chimney with a corbeled cap rises from the west (rear) elevation. An interior-side brick chimney rises from the south (side) elevation. The façade (east elevation) features a molded metal cornice set on scrolled end brackets connected by a thin, molded concrete string. Window openings on the façade hold 1/1, double-hung, vinyl-sash windows with concrete lug sills. Located in the northern bay, the main entry holds a single-leaf, paneled wood door set in a narrow, square-edge wood surround. A blank transom surmounts the door. A full-width porch spans the width of the façade. Set on a concrete slab, the porch has a flat roof with overhanging eaves supported by metal filigree posts. Twisted metal balusters complete the porch. Fenestration of the south (side) elevation consists of 1/1, double-hung, vinyl-sash windows with metal-clad sills and three-course, rowlock brick segmental arches. The west (rear) elevation has 1/1, double-hung, vinyl-sash windows with concrete sills and three-course, rowlock brick segmental arches.

A one-story, full-width porch is located on the rear of the dwelling. This original feature has been enclosed with vinyl siding and is capped by a shed roof of asphalt shingles. Fenestration consists of 1/1, double-hung, vinyl-sash windows.

Site Notes:

September 2010: This semi-detached rowhouse is located west of 16th Street, S.E. and has a setback of approximately twenty feet from the public sidewalk. The north (side) elevation is adjacent to 335 16th Street, S.E. A narrow brick alley forms the southern boundary of the property. The raised, level front yard has mature trees and shrubs. A concrete walkway and steps link the front porch to the sidewalk. Enclosed by a wooden privacy fence, the backyard extends west to an alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:
Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 337_16th_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 337_16th_Street_SE_facade_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 337_16th_Street_SE_facade_looking_W.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 337_16th_Street_SE_rear_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/15/1915	5272	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0093

BASICS DATA

ID Number: **1074-0093** Year Built: **1958** Data Source: **Sanborn Map**

Number	Extended	Street	Quad	Type of Address
308		15th Street	SE	Current

Name(s)	Type of Name
Commercial Building, 308 15th Street, S.E.	Common
Board of Childcare Daycare Center	Current

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0093			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Commercial Building** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Commercial	1958	Sanborn M			Historic
Day Care Center		Site Visit/			Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1958	Sanborn Map			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Freestanding**
Relate to Street: **Face on Setback Line**
Massing: **Vertical Block**
Footprint: **L-Shaped**

Number Stories: **2**
Bays Wide: **4**

Height:
Width:

Depth/Length:
SqFt:

Volume:
Lot Width

Lot Depth/Length:
Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2010: Constructed in 1958, this two-story concrete-block building has an L-shaped form. Set on a solid foundation, this building is capped by a flat roof. A stretcher-bond brick veneer dresses the façade (west elevation). The north (side) elevation has been parged. The façade has 1/1, double-hung, metal-sash windows with rowlock brick sills and soldier brick jack arches. The main entry, located in a wide integral porch in the north end of the façade, holds a double-leaf, metal-frame glass door with single-light transom. A soldier brick jack arch completes the opening. A secondary door opening (single-leaf, metal-frame glass door) is located in a narrow integral porch south of the main entry. The north and south (side) elevations have no fenestration. The east (rear) elevation has 1/1, double-hung, vinyl-sash windows with rowlock brick sills. The southern block of the building has no roof. This design feature allows for an outdoor playground. Multiple door openings on the rear of the building hold single-leaf, flush metal doors.

Site Notes:

September 2010: The Board of Childcare Day Care Center is located east of 15th Street, S.E. and fronts the wide concrete sidewalk along the street. Planting beds with mature trees and shrubs are integrated into the sidewalk. A brick alley forms the southern boundary of the lot, while an alley forms the eastern boundary. A narrow asphalt alley forms the northern boundary.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Pannels Material

Notable Interior Plan(s) Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Ward/ANC:

Zoning: Designation Event(s)

Contributing:

Survey(s) Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 308_15th_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 308_15th_Street_SE_facade_looking_NE_2.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 308_15th_Street_SE_facade_looking_SE
(4).JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 308_15th_Street_SE_facade_looking_SE
(7).JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\

File: 308_15th_Street_SE_facade_looking_SE.jpg

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\

File: 308_15th_Street_SE_rear_looking_W.jpg

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0021

BASICS DATA

ID Number: **1074-0021** Year Built: **1904** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
300		15th Street	SE	Current

Name(s)	Type of Name
Rowhouse, 300 15th Street, S.E.	Common
Ian's Hair Studio	Current

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0021			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1904	Permit			Original
Dwelling & Store					Historic
Residential/Professional		Site Visit/			Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1904	Permit			1800 Permit

Construction Event	Association	Associated Name
Orig Construction	Builder	Burgess & Parsons
Orig Construction	Owner	Fritag, H.C.

Construction Notes:

One of ten rowhouses constructed from the same permit (#1413).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row End (1 of 10)**
 Relate to Street: **Front Yard/Setback**
 Massing: **Row Building/Flat Front**
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
 Bays Wide: **5**
 Height: **16**
 Width: **20**
 Depth/Length: **20**
 SqFt:
 Volume:
 Lot Width
 Lot Depth/Length:
 Lot SqFt:
 Acreage:
 Has Driveway:

Outbuilding Type _____ Contributing Status _____

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1904 by Burgess + Parsons, this single-family rowhouse is one of ten built under the same permit (#1413). Reflective of the Classical Revival style, this two-story, five-bay dwelling is set on a solid concrete foundation. The brick structure is faced with stretcher-bond brick along the west (façade) and north elevations. The south elevation has five-course, American-bond brickwork. A three-course string wraps the building at the sill plate. A sloped roof is obscured by a towering parapet. Composed of a corbeled brick table surmounted by an ovolo-molded metal cornice, the parapet extends across the façade and west elevation. The main entry, located in the second bay, holds a single-leaf wood door with decorative panels. Set in a narrow, square-edge wood surround, the opening has a stained glass transom and a soldier brick segmental arch with header brick drip molding. A large metal awning shelters the opening. Window openings on the façade hold 6/6, double-hung, wood sash. A two-course, rowlock brick sill string and soldier brick segmental arch with rowlock brick drip molding adorn each opening. Window openings on the north elevation are similar, though they are paired. The south elevation has a recessed opening with a two-course, rowlock brick segmental arch. A single-leaf, paneled wood door with four lights is accessed via brick steps. The second story has a 6/6, double-hung, wood-sash window with a rowlock brick sill and two-course, rowlock brick segmental arch.

Site Notes:

September 2010: Located on a corner lot southeast of the intersection of 15th Street, S.E. and C Street, S.E., this semi-detached rowhouse has a setback of approximately twenty feet from the brick sidewalk. The level, grassy yard extends along both streets and includes mature foundation plantings. A milled point metal fence with brick posts lines the yard. A brick walkway extends from the main entry west to 15th Street. A concrete and asphalt parking pad is located in the southern end of the property.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s) _____ Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s) _____

Survey(s) _____

Level(s) of Investigation _____

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **300_15th_Street_SE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **300_15th_Street_SE_facade_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 300_15th_Street_SE_facade_looking_NE.JPG
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 300_15th_Street_SE_side_looking_S.JPG
 Date:: Photog:
 Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/01/1904	1413	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0022

BASICS DATA

ID Number: **1074-0022** Year Built: **1904** Data Source: **Permit**

Number Extended Street Quad Type of Address

1503 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1503 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0022 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1904** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1904** **Permit** **1800 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Burgess & Parsons**

Orig Construction **Owner** **Fritag, H.C.**

Construction Notes:

One of ten rowhouses constructed from the same permit (#1413).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 10)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **20**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1904 by Burgess + Parsons, this two-story, two-bay Classical Revival-style rowhouse was one of ten constructed from the same permit (#1413). Set on a solid concrete foundation, this brick structure is faced with stretcher-bond brick across the façade (north elevation). Brick sill strings span the first and second stories. The sloped roof has a parapet composed of a brick corbeled table and an ovolo-molded metal cornice. The main entry, located in the western bay, holds a single-leaf, paneled wood door with lights. Set in a narrow, square-edge wood surround, the door is surmounted by a single-light transom. East of the door opening is a large, fixed window with a concrete sill. Single and paired 1/1, double-hung, vinyl-sash windows with 6/1 false muntins pierce the second story and include concrete sills. All of the façade openings feature soldier brick segmental arches with header brick drip molding. The south (rear) elevation was not visible from the public right-of-way.

Site Notes:

September 2010: This rowhouse is located south of C Street, S.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The building is adjacent to 300 15th Street, S.E. and the east (side) elevation to 1905 C Street, S.E. The level, grassy front yard has immature plantings and is enclosed with a bow and picket metal fence. A concrete walkway extends from the front stoop to the sidewalk. The rear of the property was not visible from the public right-of-way.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1503_C_Street_SE_facade_looking_N.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1503_C_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/01/1904	1413	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0023

BASICS DATA

ID Number: **1074-0023** Year Built: **1904** Data Source: **Permit**

Number Extended Street Quad Type of Address

1505 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1505 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0023 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1904** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1904** **Permit** **1800 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Burgess & Parsons**

Orig Construction **Owner** **Fritag, H.C.**

Construction Notes:

One of ten rowhouses constructed from the same permit (#1413).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 10)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **20**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1904 by Burgess + Parsons, this two-story, two-bay Classical Revival-style rowhouse was one of ten constructed from the same permit (#1413). Set on a solid concrete foundation, this brick structure is faced with stretcher-bond brick across the façade (north elevation). Brick sill strings span the first and second stories. The sloped roof has a parapet composed of a brick corbeled table and an ovolo-molded metal cornice. The main entry, located in the eastern bay, holds a single-leaf, Craftsman-style wood door with lights. Set in a narrow, square-edge wood surround, the door is surmounted by a stained glass transom. Window openings, single and paired, hold 1/1, double-hung, vinyl sash with concrete sills. All of the façade openings feature soldier brick segmental arches with header brick drip molding. The south (rear) elevation was not visible from the public right-of-way.

Site Notes:

September 2010: This rowhouse is located south of C Street, S.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The building is adjacent to 1503 and 1507 C Street, S.E. The level, grassy front yard has immature plantings and is enclosed with a bow and picket metal fence. A concrete walkway extends from the front stoop to the sidewalk. The rear of the property was not visible from the public right-of-way.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation

Permit Research

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 1505_C_Street_SE_facade_looking_S.jpg
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 1505_C_Street_SE_facade_looking_SE.JPG
 Date:: Photog:
 Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/01/1904	1413	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0024

BASICS DATA

ID Number: **1074-0024** Year Built: **1904** Data Source: **Permit**

Number Extended Street Quad Type of Address

1507 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1507 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0024 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1904** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1904** **Permit** **1800 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Burgess & Parsons**

Orig Construction **Owner** **Fritag, H.C.**

Construction Notes:

One of ten rowhouses constructed from the same permit (#1413).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 10)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **20**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1904 by Burgess + Parsons, this two-story, two-bay Classical Revival-style rowhouse was one of ten constructed from the same permit (#1413). Set on a solid concrete foundation, this brick structure is faced with stretcher-bond brick across the façade (north elevation). Brick sill strings span the first and second stories. The sloped roof has a parapet composed of a brick corbeled table and an ovolo-molded metal cornice. The main entry, located in the western bay, holds a single-leaf, paneled metal door with semi-circular light. Set in a narrow, square-edge wood surround, the door is surmounted by a single-light transom. Window openings, single and paired, hold 1/1, double-hung, vinyl sash with concrete sills. All of the façade openings feature soldier brick segmental arches with header brick drip molding. The south (rear) elevation was not visible from the public right-of-way.

Site Notes:

September 2010: This rowhouse is located south of C Street, S.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The building is adjacent to 1505 and 1509 C Street, S.E. The level, grassy front yard is enclosed with a bow and picket metal fence. A concrete walkway extends from the front stoop to the sidewalk. The rear of the property was not visible from the public right-of-way.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill Southeast Phase II (2010)	Permit Research

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 1507_C_Street_SE_facade_looking_SE.JPG
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 1507_C_Street_SE_facade_looking_SW.JPG
 Date:: Photog:
 Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/01/1904	1413	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0025

BASICS DATA

ID Number: **1074-0025** Year Built: **1904** Data Source: **Permit**

Number Extended Street Quad Type of Address

1509 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1509 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0025 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1904** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1904** **Permit** **1800 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Burgess & Parsons**

Orig Construction **Owner** **Fritag, H.C.**

Construction Notes:

One of ten rowhouses constructed from the same permit (#1413).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 10)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Flat Front**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **20**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1904 by Burgess + Parsons, this two-story, two-bay Classical Revival-style rowhouse was one of ten constructed from the same permit (#1413). Set on a solid concrete foundation, this brick structure is faced with stretcher-bond brick across the façade (north elevation). Brick sill strings span the first and second stories. The sloped roof has a parapet composed of a brick corbeled table and an ovolo-molded metal cornice. The main entry, located in the eastern bay, holds a single-leaf, wood-frame glass door. Set in a narrow, square-edge wood surround, the door is surmounted by a single-light transom. Window openings, single and paired, hold 1/1, double-hung, vinyl sash with 9/9 false muntins and concrete sills. All of the façade openings have soldier brick segmental arches with header brick drip molding.

The south (rear) elevation has a two-story, one-bay ell. Faced with five-course, American-bond brickwork, the ell is capped by a shed roof with an interior-corner brick chimney. Fenestration consists of 1/1, double-hung, vinyl-sash windows with 9/9 false muntins, concrete sills, and two-course, rowlock brick segmental arches.

Site Notes:

September 2010: This rowhouse is located south of C Street, S.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The building is adjacent to 1505 and 1509 C Street, S.E. The level, grassy front yard has immature foundation plantings and is enclosed with a bow and picket metal fence. A brick walkway extends from the front stoop to the sidewalk. The backyard was not visible from the public right-of-way.

NOTABLE FEATURES DATA

Component _____ Feature _____

EXTERIOR MATERIALS DATA

Roof Component _____ Material _____ Color _____ Treatment _____ Source _____

Wall Component _____ Material _____ Color _____ Treatment _____ Source _____

Structure Component _____ Material _____ Feature _____ Source _____

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location _____ Aperture Shape _____ Type _____ Lights _____ Material _____

Door Location _____ Aperture Shape _____ Type _____ Panels _____ Material _____

Notable Interior Plan(s) _____

Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s) _____

Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1509_C_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1509_C_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1509_C_Street_SE_rear_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/01/1904	1413	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0026

BASICS DATA

ID Number: **1074-0026** Year Built: **1904** Data Source: **Permit**

Number Extended Street Quad Type of Address

1511 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1511 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0026 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1904** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1904** **Permit** **1800 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Burgess & Parsons**

Orig Construction **Owner** **Fritag, H.C.**

Construction Notes:

One of ten rowhouses constructed from the same permit (#1413).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 10)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **20**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1904 by Burgess + Parsons, this two-story, two-bay Classical Revival-style rowhouse was one of ten constructed from the same permit (#1413). Set on a solid concrete foundation, this brick structure is faced with stretcher-bond brick across the façade (north elevation). Brick sill strings span the first and second stories. The sloped roof has a parapet composed of a brick corbeled table and an ovolo-molded metal cornice. The main entry, located in the western bay, holds a single-leaf, paneled wood door. Set in a narrow, square-edge wood surround, the door is surmounted by a single-light transom. Window openings, single and paired, hold 1/1, double-hung, vinyl sash with 6/6 false muntins and concrete sills. All of the façade openings have soldier brick segmental arches with header brick drip molding.

The south (rear) elevation has a two-story, one-bay ell. Faced with five-course, American-bond brickwork, the ell is capped by a shed roof with an interior-corner brick chimney. Fenestration consists of 1/1, double-hung, vinyl-sash windows with 9/9 false muntins, concrete sills, and two-course, rowlock brick segmental arches.

Site Notes:

September 2010: This rowhouse is located south of C Street, S.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The building is adjacent to 1509 and 1513 C Street, S.E. The level, grassy front yard has immature foundation plantings and is enclosed with a bow and picket metal fence. A brick walkway extends from the front stoop to the sidewalk. The backyard stretches south to an alley.

NOTABLE FEATURES DATA

Component _____ Feature _____

EXTERIOR MATERIALS DATA

Roof Component _____ Material _____ Color _____ Treatment _____ Source _____

Wall Component _____ Material _____ Color _____ Treatment _____ Source _____

Structure Component _____ Material _____ Feature _____ Source _____

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location _____ Aperture Shape _____ Type _____ Lights _____ Material _____

Door Location _____ Aperture Shape _____ Type _____ Panels _____ Material _____

Notable Interior Plan(s) _____

Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s) _____

Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1511_C_Street_SE_facade_looking_S.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1511_C_Street_SE_facade_looking_SW.jpg
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/01/1904	1413	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0027

BASICS DATA

ID Number: **1074-0027** Year Built: **1904** Data Source: **Permit**

Number Extended Street Quad Type of Address

1513 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1513 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0027 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1904** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1904** **Permit** **1800 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Burgess & Parsons**

Orig Construction **Owner** **Fritag, H.C.**

Construction Notes:

One of ten rowhouses constructed from the same permit (#1413).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 10)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Flat Front**
Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **20**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Garage

Outbuilding Notes:

September 2010: This one-story, one-bay garage, based on its form and materials, was originally constructed c. 1920 but has been extensively rehabilitated. The sidewalls are parged, while the façade (south elevation) has been infilled with stretcher-bond brick. A single-leaf, flush metal door pierces the south elevation. A shed roof caps the garage.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1904 by Burgess + Parsons, this two-story, two-bay Classical Revival-style rowhouse was one of ten constructed from the same permit (#1413). Set on a solid concrete foundation, this brick structure is faced with stretcher-bond brick across the façade (north elevation). Brick sill strings span the first and second stories. The sloped roof has a parapet composed of a brick corbeled table and an ovolo-molded metal cornice. The main entry, located in the eastern bay, holds a single-leaf, multi-light wood door. Set in a narrow, square-edge wood surround, the door is surmounted by a stained glass transom. Window openings, single and paired, hold 1/1, double-hung, vinyl sash with concrete sills. All of the façade openings boast soldier brick segmental arches with header brick drip molding. Fenestration of the south (rear) elevation of the main block was not visible from the public right-of-way.

The south (rear) elevation has a two-story, one-bay ell. The five-course, American-bond brick appendage has been parged along the south (rear) elevation. The ell is capped by a shed roof with an interior-corner brick chimney. Fenestration consists of 1/1, double-hung, vinyl-sash windows with parged concrete sills and segmental arches.

Site Notes:

September 2010: This rowhouse is located south of C Street, S.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The building is adjacent to 1511 and 1515 C Street, S.E. The level, grassy front yard has immature foundation plantings and is enclosed with a bow and picket metal fence. A concrete walkway extends from the front stoop to the sidewalk. The backyard stretches south and includes a garage fronting the alley.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Pannels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributor:

Contributing:

Survey(s)

Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1513_C_Street_SE_facade_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1513_C_Street_SE_facade_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1513_C_Street_SE_garage_looking_NE.jpg
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1513_C_Street_SE_garage_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074\
File: 1513_C_Street_SE_rear_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/01/1904	1413	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0028

BASICS DATA

ID Number: **1074-0028** Year Built: **1904** Data Source: **Permit**

Number Extended Street Quad Type of Address

1515 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1515 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0028 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1904** **Permit** **Historic**

Residential (Multi-Family) **Site Visit/** **Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Rear Addition **c. 2000** **Site Visit/Map**

Orig Construction **1904** **Permit** **1800 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Burgess & Parsons**

Orig Construction **Owner** **Fritag, H.C.**

Construction Notes:

One of ten rowhouses constructed from the same permit (#1413).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row (1 of 10)**
 Relate to Street: **Front Yard/Setback**
 Massing: **Row Building/Flat Front**
 Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
 Bays Wide: **2**
 Height: **16**
 Width: **16**
 Depth/Length: **20**

Outbuilding Type Contributing Status

SqFt:
 Volume:
 Lot Width
 Lot Depth/Length:
 Lot SqFt:
 Acreage:
 Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1904 by Burgess + Parsons, this two-story, two-bay Classical Revival-style rowhouse was one of ten constructed from the same permit (#1413). Set on a solid concrete foundation, this brick structure is faced with stretcher-bond brick across the façade (north elevation). Brick sill strings span the first and second stories. The sloped roof has a parapet composed of a brick corbeled table and an ovolo-molded metal cornice. The main entry, located in the western bay, holds a single-leaf, multi-light wood door. Set in a narrow, square-edge wood surround, the door is surmounted by a single-light transom. Window openings, single and paired, hold 1/1, double-hung, vinyl sash with concrete sills. All of the façade openings boast soldier brick segmental arches with header brick drip molding and scrolled spandrels. Fenestration of the south (rear) elevation of the main block was not visible from the public right-of-way.

A two-story, one-bay addition is located on the rear of the dwelling. Based on its form and materials, this addition was constructed c. 2000. Clad in German vinyl siding or parged, the addition is capped by a shed roof with an overhanging eave. Fenestration consists of a double-leaf, sliding-glass door and 1/1, double-hung, vinyl-sash windows.

Site Notes:

September 2010: This rowhouse is located south of C Street, S.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The building is adjacent to 1513 and 1517 C Street, S.E. The level, front yard has been covered with brick pavers and is enclosed with a bow and milled point metal fence. A brick walkway extends from the front stoop to the sidewalk. The backyard stretches south to an alley and is enclosed with a wooden privacy fence. A metal roll-up garage door has been added to the rear of the property.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s) _____ Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s) _____

Survey(s) _____

Level(s) of Investigation _____

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1515_C_Street_SE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1515_C_Street_SE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 1515_C_Street_SE_rear_looking_NW (1).JPG
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 1515_C_Street_SE_rear_looking_NW.jpg
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 1515_C_Street_SE_rear_looking_SE.JPG
 Date:: Photog:
 Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/01/1904	1413	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0029

BASICS DATA

ID Number: **1074-0029** Year Built: **1904** Data Source: **Permit**

Number Extended Street Quad Type of Address

1517 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1517 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0029 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1904** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1904** **Permit** **1800 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Burgess & Parsons**

Orig Construction **Owner** **Fritag, H.C.**

Construction Notes:

One of ten rowhouses constructed from the same permit (#1413).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 10)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **20**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1904 by Burgess + Parsons, this two-story, two-bay Classical Revival-style rowhouse was one of ten constructed from the same permit (#1413). Set on a solid concrete foundation, this brick structure is faced with stretcher-bond brick across the façade (north elevation). Brick sill strings span the first and second stories. The sloped roof has a parapet composed of a brick corbeled table and an ovolo-molded metal cornice. The main entry, located in the eastern bay, holds a single-leaf, paneled wood door. Set in a narrow, square-edge wood surround, the door is surmounted by a blank transom. Window openings, single and paired, hold 1/1, double-hung, vinyl sash with concrete sills. All of the façade openings boast soldier brick segmental arches with header brick drip molding. Fenestration of the south (rear) elevation consists of a narrow, 1/1, double-hung, vinyl-sash window with concrete sill and two-course, rowlock brick segmental arch located on the second story.

A two-story, one-bay ell dominates the rear of the dwelling. Three-bays deep, this ell has five-course, American-bond brick work and is capped by a shed roof. An interior brick chimney pierces the roof. Window openings have 1/1, double-hung, vinyl-sash windows with concrete sills and two-course, rowlock brick segmental arches.

A one-story, four-bay porch spans the rear of the ell. This original feature is set on a pier foundation and is capped by a shed roof of asphalt shingles. Enclosed with vinyl siding, the porch is now pierced with 1/1, double-hung, vinyl-sash windows and a single-leaf, paneled wood door accessed via wood steps.

Site Notes:

September 2010: This rowhouse is located south of C Street, S.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The building is adjacent to 1515 and 1519 C Street, S.E. The level, grassy front yard has flower beds and mature shrubs, all enclosed with a bow and picket metal fence. A concrete walkway extends from the brick stoop to the sidewalk. The grassy backyard stretches south to an alley and is enclosed with metal and wood fencing.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1517_C_Street_SE_facade_looking_S.jpg**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1517_C_Street_SE_facade_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1517_C_Street_SE_rear_looking_NW.jpg**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0030

BASICS DATA

ID Number: **1074-0030** Year Built: **1904** Data Source: **Permit**

Number Extended Street Quad Type of Address

1519 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1519 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0030 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1904** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1904** **Permit** **1800 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Burgess & Parsons**

Orig Construction **Owner** **Fritag, H.C.**

Construction Notes:

One of ten rowhouses constructed from the same permit (#1413).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 10)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **20**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1904 by Burgess + Parsons, this two-story, two-bay Classical Revival-style rowhouse was one of ten constructed from the same permit (#1413). Set on a solid concrete foundation, this brick structure is faced with stretcher-bond brick across the façade (north elevation). Brick sill strings span the first and second stories. The sloped roof has a parapet composed of a brick corbeled table and an ovolo-molded metal cornice. The main entry, located in the western bay, holds a single-leaf, paneled wood door. Set in a narrow, square-edge wood surround, the door is surmounted by a recessed single-light transom. Window openings, single and paired, hold 1/1, double-hung, vinyl sash with concrete sills. All of the façade openings boast soldier brick segmental arches with header brick drip molding. Fenestration of the south (rear) elevation consists of a narrow, 1/1, double-hung, vinyl-sash window with concrete sill and two-course, rowlock brick segmental arch located on the second story.

A two-story, one-bay ell is located on the rear of the dwelling. Three-bays deep, this ell has five-course, American-bond brick work and is capped by a shed roof. An interior brick chimney pierces the roof. Window openings have 1/1, double-hung, vinyl-sash windows with concrete sills and two-course, rowlock brick segmental arches. A single-leaf, wood-frame glass door is located on the south (rear) elevation of the ell. Accessed via wood steps, this opening has a deteriorated Colonial Revival-style surround composed of fluted pilasters. The transom opening, along with other window openings, has been enclosed with brick.

Site Notes:

September 2010: This end-unit rowhouse is located south of C Street, S.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The building is adjacent to 1517 and 1521 C Street, S.E. The level front yard has been covered with mulch and has immature plants. A bow and picket metal fence encloses the front yard. A concrete walkway extends from the stoop to the sidewalk. The backyard extends south to an alley and includes a concrete parking pad and brick walkway.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1519_C_Street_SE_facade_looking_SE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1519_C_Street_SE_facade_looking_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**

File: **1519_C_Street_SE_rear_looking_N.jpg**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0033

BASICS DATA

ID Number: **1074-0033** Year Built: **1910** Data Source: **Permit**

Number Extended Street Quad Type of Address

1521 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1521 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0033 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1910** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Rear Addition **c. 2000** **Site Visit/Map**

Orig Construction **1910** **Permit** **3333 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Schneider, Ferd. T.**

Orig Construction **Builder** **Burgess & Parsons**

Orig Construction **Owner** **Holton, W.L.**

Construction Notes:

One of three rowhouses constructed from the same permit (#7202).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row End (1 of 3)**
 Relate to Street: **Front Yard/Setback**
 Massing: **Row Building/Front Porch**
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
 Bays Wide: **3**
 Height: **18**
 Width: **18**
 Depth/Length: **33**

Outbuilding Type Contributing Status

SqFt:
 Volume:
 Lot Width
 Lot Depth/Length:
 Lot SqFt:
 Acreage:
 Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1910 by Burgess and Parsons, this two-story, three-bay Classical Revival-style rowhouse is one of three constructed from the same permit (#7202). Set on a raised foundation, this brick structure is faced with Flemish-bond brick. A sloped roof caps the dwelling and is fronted by an ogee-molded metal cornice with scrolled brackets. A narrow molded concrete string is located above the second-story openings. No chimney stacks were visible from the public right-of-way. The main entry, located in the western bay, holds a single-leaf, paneled wood door set in a narrow, square-edge wood surround. A tall, single-light sidelight and single-light transom complete the opening. Window openings contain 1/1, double-hung, vinyl-sash windows with concrete sills. The raised basement contains a single-leaf, paneled wood door with lights and a 1/1, double-hung, vinyl-sash window. All façade openings have concrete lug lintels. A one-story, full-width porch dominates the front of the dwelling. Set on a brick pier foundation, the porch has a flat roof with overhanging eaves and a molded cornice. Brick supports and twisted metal balusters complete the porch.

The south (rear) elevation has a two-story, full-width addition, which based on its form and materials appears to have been constructed c. 2000. Clad in vinyl siding and capped by a shed roof with an overhanging eave, the addition has 1/1, double-hung, vinyl-sash windows. A double-leaf, wood-frame glass door is centrally located on the first story of the south (rear) elevation and provides access to the deck.

Site Notes:

September 2010: This end-unit rowhouse is located south of C Street, S.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The building is adjacent to 1519 and 1523 C Street, S.E. The front yard is landscaped with immature shrubs and enclosed with a milled point metal fence. Concrete steps provide access from the brick walkway to the front porch. Concrete steps lead down to a below-grade door opening underneath the porch. The backyard extends south to an alley and is enclosed with a wooden privacy fence with metal, roll-up garage door. A wood deck has been added to the rear of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**

File: **1521_C_Street_SE_facade_looking_N.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074**

File: **1521_C_Street_SE_facade_looking_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 1521_C_Street_SE_rear_looking_NW (1).JPG
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 1521_C_Street_SE_rear_looking_NW.jpg
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 1521_C_Street_SE_rear_looking_SE.JPG
 Date:: Photog:
 Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/21/1910	7202	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0034

BASICS DATA

ID Number: **1074-0034** Year Built: **1910** Data Source: **Permit**

Number Extended Street Quad Type of Address

1523 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1523 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0034 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1910** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1910** **Permit** **3333 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Schneider, Ferd. T.**

Orig Construction **Builder** **Burgess & Parsons**

Orig Construction **Owner** **Holton, W.L.**

Construction Notes:

One of three rowhouses constructed from the same permit (#7202).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 3)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **18**

Depth/Length: **33**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1910 by Burgess and Parsons, this two-story, three-bay Classical Revival-style rowhouse is one of three constructed from the same permit (#7202). Set on a raised foundation, this brick structure is faced with Flemish-bond brick. A sloped roof caps the dwelling and is fronted by an ogee-molded metal cornice with scrolled brackets. A narrow molded concrete string is located above the second-story openings. An interior-rear brick chimney with a parged cap pierces the roof. The main entry, located in the western bay, holds a single-leaf, paneled door with semi-circular light set in a narrow, square-edge wood surround. A tall, single-light sidelight and single-light transom complete the opening. Window openings contain 1/1, double-hung, vinyl-sash windows with concrete sills. The raised basement contains a single-leaf door opening (not visible). All façade openings have concrete lug lintels. A one-story, two-bay porch spans the width of the first story. Set on a brick pier foundation with honeycomb brick infill, the porch has a flat roof feature overhanging eaves, a molded metal cornice, and pressed metal dentils. Metal filigree posts support the roof. The south (rear) elevation is faced with five-course, American-bond brick and features a full-height, three-sided canted bay. Window openings have 1/1, double-hung, vinyl-sash windows with concrete lug sills and two-course, rowlock brick segmental arches. A double-leaf, French door is located in the western bay of the first story.

Site Notes:

September 2010: This single-family rowhouse is located south of C Street, S.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The building is adjacent to 1521 and 1525 C Street, S.E. The raised front yard has stone retaining walls. Concrete steps provide access from the concrete walkway to the front porch. Concrete steps lead down to a door opening underneath the porch. A metal chain-link fence encloses the front yard. The backyard extends south to an alley and is partially enclosed with a wooden privacy fence. A mature tree is located in proximity to the rear of the building. A concrete parking pad is located in the rear of the property.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:
Contributing:

Designation Event(s) _____

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1523_C_Street_SE_facade_looking_S.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1523_C_Street_SE_facade_looking_SW.jpg
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1523_C_Street_SE_rear_looking_N.jpg
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/21/1910	7202	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0035

BASICS DATA

ID Number: **1074-0035** Year Built: **1910** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1525		C Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1525 C Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0035			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1910	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1910	Permit			3333 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Schneider, Ferd. T.
Orig Construction	Builder	Burgess & Parsons
Orig Construction	Owner	Holton, W.L.

Construction Notes:

One of three rowhouses constructed from the same permit (#7202).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row End (1 of 3)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **3**
Height:
Width: **18**
Depth/Length: **33**
SqFt:

Outbuilding Type	Contributing Status
------------------	---------------------

Volume:
Lot Width:
Lot Depth/Length:
Lot SqFt:
Acreage:
Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1910 by Burgess and Parsons, this two-story, three-bay Classical Revival-style rowhouse is one of three constructed from the same permit (#7202). Set on a raised foundation, this brick structure is faced with Flemish-bond brick. A sloped roof caps the dwelling and is fronted by an ogee-molded metal cornice with scrolled brackets. A narrow molded concrete string is located above the second-story openings. An interior-rear brick chimney with a parged cap pierces the roof. The main entry, located in the western bay, holds a single-leaf, flush wood door with light set in a narrow, square-edge wood surround. A tall, single-light sidelight and single-light transom complete the opening. Window openings contain 1/1, double-hung, vinyl-sash windows with concrete sills. The raised basement contains a single-leaf, flush wood door. All facade openings have concrete lug lintels. A one-story shelters the first story. Set on a brick pier foundation with honeycomb brick infill, the porch has a flat roof with overhanging eaves and a molded metal cornice. Brick posts set on brick piers support the roof. The south (rear) elevation is faced with five-course, American-bond brick and features a full-height, three-sided canted bay. Window openings hold 1/1, double-hung, vinyl-sash windows with concrete sills and two-course, rowlock brick segmental arches. A multi-light wood door is located in the western bay of the first story.

Site Notes:

September 2010: This single-family rowhouse is located south of C Street, S.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The building is adjacent to 1523 and 1527 C Street, S.E. The raised front yard has brick retaining walls and immature plantings. A mature trees provides shade. Concrete steps provide access from the concrete walkway to the front porch. Concrete steps lead down to a door opening underneath the porch. A metal chain-link fence encloses the front yard. The backyard extends south to an alley and is enclosed with a wooden privacy fence.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)

Contributing:

Designation Level(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1525_C_Street_SE_facade_looking_S.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1525_C_Street_SE_facade_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1525_C_Street_SE_rear_looking_N.jpg
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
06/21/1910	7202	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0054

BASICS DATA

ID Number: **1074-0054** Year Built: **1914** Data Source: **Permit**

Number Extended Street Quad Type of Address

1527 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1527 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0054 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1914** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1914** **Permit** **1750 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of eight rowhouses constructed from the same permit (#3642).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row End (1 of 8)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **40**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type Contributing Status

Shed

Outbuilding Notes:

September 2010: This one-story prefabricated shed was constructed c. 2007. The frame structure is clad in T1-11 siding and capped by a shed roof of asphalt shingles. Paired single-light, vinyl-sash sliding windows pierce the shed.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1914 by Harry A. Kite, this two-story, two-bay Classical Revival-style rowhouse was one of eight constructed under the same permit (#3642). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and is fronted by a molded metal cornice with molded end brackets. A narrow molded concrete string extends beneath the cornice. An exterior-rear brick chimney rises from the south (rear) elevation.

The façade (north elevation) has been extensively altered. The second story has 1/1, double-hung, vinyl-sash windows with false 6/6 muntins and concrete lug sills. The first story has a full-width enclosed porch. Enclosed with fixed window a double-leaf, wood-frame glass door, the porch has a flat roof with molded metal cornice.

The south (rear) elevation has 1/1, double-hung, vinyl-sash windows with false 6/6 muntins, concrete sills, and two-course, rowlock brick segmental arches.

Site Notes:

September 2010: This single-family rowhouse is located south of C Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The building is adjacent to 1525 and 1529 C Street, S.E. The front yard is enclosed with a metal chain-link fence. A mature trees provides shade. A concrete walkway extends from the front porch to the sidewalk. The backyard extends south to an alley and is enclosed with a wooden privacy fence. A shed is located in the backyard.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1527_C_Street_SE_facade_looking_N.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1527_C_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1527_C_Street_SE_rear_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1527_C_Street_SE_rear_looking_N.jpg
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074\
File: 1527_C_Street_SE_shed_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1914	3642	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0055

BASICS DATA

ID Number: **1074-0055** Year Built: **1914** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1529		C Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1529 C Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0055			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1914	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1914	Permit			1750 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Landvoigt, A. E.
Orig Construction	Builder	Kite, Harry A.
Orig Construction	Owner	Kite, Harry A.

Construction Notes:

One of eight rowhouses constructed from the same permit (#3642).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 8)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Front Porch**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**
Height:
Width: **13**
Depth/Length: **40**
SqFt:

Outbuilding Type	Contributing Status
------------------	---------------------

Volume:
Lot Width:
Lot Depth/Length:
Lot SqFt:
Acreage:
Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1914 by Harry A. Kite, this two-story, two-bay Classical Revival-style rowhouse was one of eight constructed under the same permit (#3642). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and is fronted by a molded metal cornice with molded end brackets. A narrow molded concrete string extends beneath the cornice. An exterior-rear brick chimney rises from the south (rear) elevation. The main entry, located in the western bay, holds a single-leaf, paneled wood door with lights. Set in a narrow, square-edge wood surround, the opening includes a single-light transom. Window openings have 1/1, double-hung, vinyl-sash windows with 6/6 false muntins and concrete sills. Concrete lug lintels accompany each façade opening. A two-story, one-bay ell is located on the rear of the dwelling. Faced with five-course, American-bond brick, the ell has a shed roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows with false 6/6 muntins. Each opening has a concrete sill and two-course, rowlock brick segmental arch.

A one-story, two-bay porch is located on the rear of the ell. This original feature has been enclosed with vinyl siding and is capped by a shed roof. A single-leaf door (not visible) and a four-light, vinyl-sash window pierce the porch.

Based on physical evidence as well as Sanborn Fire Insurance Company maps, a one-story, full-width porch has been removed from the façade.

Site Notes:

September 2010: This single-family rowhouse is located south of C Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The building is adjacent to 1527 and 1531 C Street, S.E. The grassy front yard has immature plantings and a concrete walkway extending from the front porch to the sidewalk. The backyard extends south to an alley and is enclosed with a concrete block wall.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source

Wall Component	Material	Color	Treatment	Source

Structure Component	Material	Feature	Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Pannels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:
Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074\

File: 1529_C_Street_SE_facade_looking_S.jpg

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074\

File: 1529_C_Street_SE_rear_looking_N.jpg

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

03/16/1914	3642	Build	
------------	------	-------	--

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

Resource All Data Report

ID Number: 1074-0056

BASICS DATA

ID Number: **1074-0056** Year Built: **1914** Data Source: **Permit**

Number Extended Street Quad Type of Address

1531 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1531 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0056 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1914** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1914** **Permit** **1750 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of eight rowhouses constructed from the same permit (#3642).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 8)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Flat Front**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **40**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1914 by Harry A. Kite, this two-story, two-bay Classical Revival-style rowhouse was one of eight constructed under the same permit (#3642). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and is fronted by a molded metal cornice with molded end brackets. A narrow molded concrete string extends beneath the cornice. An exterior-rear brick chimney rises from the south (rear) elevation. The main entry, located in the western bay, holds a single-leaf, paneled wood door with lights. Set in a narrow, square-edge wood surround, the opening includes a single-light transom. Window openings have 1/1, double-hung, vinyl-sash windows with 6/6 false muntins and concrete sills. Concrete lug lintels accompany each façade opening. The south (rear) elevation has a single-leaf, paneled wood door and a 1/1, double-hung, vinyl-sash window with 8/8 false muntins. Each opening has a concrete sill and three-course, rowlock brick segmental arch.

A two-story, one-bay ell is located on the rear of the dwelling. Faced with five-course, American-bond brick, the ell has a shed roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows with false 6/6 muntins. Each opening has a concrete sill and three-course, rowlock brick segmental arch.

Based on physical evidence as well as Sanborn Fire Insurance Company maps, a one-story, full-width porch has been removed from the façade.

Site Notes:

September 2010: This single-family rowhouse is located south of C Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The building is adjacent to 1527 and 1531 C Street, S.E. The grassy front yard has immature foundation plantings and mature Crepe Myrtles. A concrete walkway extends from the main entry to the sidewalk. The backyard extends south to an alley and is enclosed with wooden privacy fence.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:
Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1531_C_Street_SE_facade_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1531_C_Street_SE_facade_looking_SW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1531_C_Street_SE_rear_looking_N.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1914	3642	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0057

BASICS DATA

ID Number: **1074-0057** Year Built: **1914** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1533		C Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1533 C Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0057			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1914	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1914	Permit			1750 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Landvoigt, A. E.
Orig Construction	Builder	Kite, Harry A.
Orig Construction	Owner	Kite, Harry A.

Construction Notes:

One of eight rowhouses constructed from the same permit (#3642).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 8)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Flat Front**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**
Height:
Width: **13**
Depth/Length: **30**
SqFt:

Outbuilding Type	Contributing Status
------------------	---------------------

Volume:
Lot Width
Lot Depth/Length:
Lot SqFt:
Acreage:
Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1914 by Harry A. Kite, this two-story, two-bay Classical Revival-style rowhouse was one of eight constructed under the same permit (#3642). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and is fronted by a molded metal cornice with molded end brackets. A narrow molded concrete string extends beneath the cornice. An exterior-rear brick chimney rises from the south (rear) elevation. The main entry, located in the western bay, holds a single-leaf, paneled wood door. Set in a narrow, square-edge wood surround, the opening includes a single-light transom. Window openings have 6/6, double-hung, wood-sash windows and concrete sills. Concrete lug lintels accompany each façade opening. The south (rear) elevation has a single-leaf, multi-light wood door and a 8/8, double-hung, wood-sash window.

A two-story, one-bay ell is located on the rear of the dwelling. The ell has been parged and is capped by a shed roof. Fenestration consists of 6/6, double-hung, wood-sash windows with wood sills and segmental arches. Each opening has a concrete sill and three-course, rowlock brick segmental arch.

Based on physical evidence as well as Sanborn Fire Insurance Company maps, a one-story, full-width porch has been removed from the façade.

Site Notes:

September 2010: This single-family rowhouse is located south of C Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The building is adjacent to 1531 and 1535 C Street, S.E. The front yard has immature shrubs and a mature tree, and is enclosed with a hoop and point metal fence. A brick walkway extends from the main entry to the sidewalk. The backyard extends south to an alley and is enclosed with wooden privacy fence. Mature trees dot the backyard.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:
Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1533_C_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1533_C_Street_SE_facade_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1533_C_Street_SE_rear_looking_S.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1914	3642	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0058

BASICS DATA

ID Number: **1074-0058** Year Built: **1914** Data Source: **Permit**

Number Extended Street Quad Type of Address

1535 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1535 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0058 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1914** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1914** **Permit** **1750 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of eight rowhouses constructed from the same permit (#3642).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 8)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1914 by Harry A. Kite, this two-story, two-bay Classical Revival-style rowhouse was one of eight constructed under the same permit (#3642). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and is fronted by a molded metal cornice with molded end brackets. A narrow molded concrete string extends beneath the cornice. An exterior-rear brick chimney rises from the south (rear) elevation. The main entry, located in the western bay, holds a single-leaf, paneled wood door. Set in a narrow, square-edge wood surround, the opening includes a single-light transom. Window openings have 1/1, double-hung, vinyl-sash windows and concrete sills. Concrete lug lintels accompany each façade opening. The south (rear) elevation was not visible from the public right-of-way.

A two-story, one-bay ell is located on the rear of the dwelling. Fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf door with three-course, rowlock brick segmental arches.

Based on physical evidence as well as Sanborn Fire Insurance Company maps, a one-story, full-width porch has been removed from the façade.

Site Notes:

September 2010: This single-family rowhouse is located south of C Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The building is adjacent to 1533 and 1537 C Street, S.E. The front yard has immature plantings and is enclosed with a hoop and picket metal fence. A brick walkway extends from the main entry to the sidewalk. The backyard extends south to an alley and is enclosed with wooden privacy fence.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Designation Level(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\

File: 1535_C_Street_SE_facade_looking_SE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\

File: 1535_C_Street_SE_facade_looking_SW.jpg

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

[Empty text box]

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1914	3642	Build	

Permit Notes:

[Empty text box]

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

Resource All Data Report

ID Number: 1074-0059

BASICS DATA

ID Number: **1074-0059** Year Built: **1914** Data Source: **Permit**

Number Extended Street Quad Type of Address

1537 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1537 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0059 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Fair**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1914** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1914** **Permit** **1750 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of eight rowhouses constructed from the same permit (#3642).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 8)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1914 by Harry A. Kite, this two-story, two-bay Classical Revival-style rowhouse was one of eight constructed under the same permit (#3642). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and is fronted by a molded metal cornice with molded end brackets. An exterior-rear brick chimney rises from the south (rear) elevation. A narrow molded concrete string extends beneath the cornice. The main entry, located in the western bay, holds a single-leaf, paneled wood door. Set in a narrow, square-edge wood surround, the opening includes a single-light transom. Window openings have 6/6, double-hung, wood-sash windows and concrete sills. Concrete lug lintels accompany each façade opening. The south (rear) elevation has 1/1, double-hung, vinyl-sash windows with concrete sills. A single-leaf, paneled wood door with four lights is located in the eastern bay and includes a single-light transom. All rear openings have three-course, rowlock brick segmental arches.

Based on physical evidence as well as Sanborn Fire Insurance Company maps, a one-story, full-width porch has been removed from the façade.

Site Notes:

September 2010: This single-family rowhouse is located south of C Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The building is adjacent to 1535 and 1539 C Street, S.E. The front yard is covered with brick pavers and is enclosed with a hoop and point metal fence. The backyard extends south to an alley and is enclosed with wooden privacy fence. Mature trees dot the backyard.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1537_C_Street_SE_facade_looking_S.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1537_C_Street_SE_facade_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 1537_C_Street_SE_rear_looking_N.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1914	3642	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0060

BASICS DATA

ID Number: **1074-0060** Year Built: **1914** Data Source: **Permit**

Number Extended Street Quad Type of Address

1539 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1539 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0060 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1914** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1914** **Permit** **1750 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of eight rowhouses constructed from the same permit (#3642).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 8)**

Relate to Street: **Front Yard/Setback**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1914 by Harry A. Kite, this two-story, two-bay Classical Revival-style rowhouse was one of eight constructed under the same permit (#3642). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and is fronted by a molded metal cornice with molded end brackets. An exterior-rear brick chimney rises from the south (rear) elevation. A narrow molded concrete string extends beneath the cornice. The main entry, located in the western bay, holds a single-leaf, paneled wood door. Set in a narrow, square-edge wood surround, the opening includes a single-light transom. Window openings have 6/6, double-hung, wood-sash windows and concrete sills. Concrete lug lintels accompany each façade opening. The south (rear) elevation has 1/1, double-hung, vinyl-sash windows with concrete sills. Additional details were not visible from the public right-of-way.

Based on physical evidence as well as Sanborn Fire Insurance Company maps, a one-story, full-width porch has been removed from the façade.

Site Notes:

September 2010: This single-family rowhouse is located south of C Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The building is adjacent to 1537 and 1541 C Street, S.E. The front yard has mature trees and shrubs and is enclosed with a metal fence. The backyard extends south to an alley and is enclosed with wooden privacy fence. Mature trees dot the backyard.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Pannels Material

Notable Interior Plan(s) Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Ward/ANC:

Zoning: Designation Event(s)

Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1539_C_Street_SE_facade_looking_N.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1539_C_Street_SE_facade_looking_NE.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1539_C_Street_SE_rear_looking_S.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1914	3642	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0061

BASICS DATA

ID Number: **1074-0061** Year Built: **1914** Data Source: **Permit**

Number Extended Street Quad Type of Address

1541 **C Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1541 C Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0061 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1914** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1914** **Permit** **1750 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Landvoigt, A. E.**

Orig Construction **Builder** **Kite, Harry A.**

Orig Construction **Owner** **Kite, Harry A.**

Construction Notes:

One of eight rowhouses constructed from the same permit (#3642).

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row End (1 of 8)**
Relate to Street: **Front Yard/Setback**
Massing: **Row Building/Flat Front**
Footprint: **Rectangular (w/ side bays)**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type Contributing Status

Shed

Outbuilding Notes:

September 2010: Constructed c. 2000, this one-story, one-bay concrete-block structure is capped by a she roof of standing-seam metal. Additional details were not visible from the public right-of-way.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

September 2010: Constructed in 1914 by Harry A. Kite, this two-story, two-bay Classical Revival-style rowhouse was one of eight constructed under the same permit (#3642). Set on a solid concrete foundation, this brick structure has Flemish-bond brickwork. A sloped roof caps the dwelling and is fronted by an elegant molded metal cornice with molded end brackets. A narrow molded concrete string extends beneath the cornice. This roofline is carried down the east (side) elevation. The façade (north elevation) has a single-leaf, paneled wood door located in the eastern bay. Set in a narrow, square-edge wood surround, the door has a blank transom with an ogee-molded lintel. Window openings on the façade and east elevation contain 1/1, double-hung, vinyl-sash windows with concrete sills. The east elevation features two, full-height projecting rectangular bays. The south (rear) elevation has 1/1, double-hung, vinyl-sash windows with rowlock brick sills. A single-leaf, paneled wood door with four-light and a single-light transom is located in the western bay. All rear openings have three-course, rowlock brick segmental arches.

Site Notes:

September 2010: Located on a corner lot southwest of the intersection of C Street, S.E. and 16th Street, S.E., this semi-detached rowhouse has a setback of approximately twenty feet from the concrete sidewalk. The west (side) elevation is adjacent to 1539 C Street, S.E. The manicured lawn is enclosed with a milled point fence and includes a mature tree. A concrete walkway extends from the front stoop to the sidewalk. The backyard is enclosed with a wooden privacy fence and includes a shed which fronts the alley south of the property.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1541_C_Street_SE_facade_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1541_C_Street_SE_rear_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074**
File: **1541_C_Street_SE_shed_looking_NW.JPG**
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
03/16/1914	3642	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0089

BASICS DATA

ID Number: **1074-0089** Year Built: **c. 2002** Data Source: **DC Real Property**

Number	Extended	Street	Quad Type of Address
328	A, B, & C	15th Street	SE Current

Name(s)	Type of Name
Apartment Building & Office, 328 A, B, & C 15th Street, S.E.	Common
Medical Support Services, Inc.	Current

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0089			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Not Historic** Quality:
Purpose: **Apartment/Office** Condition: **Excellent**

Function/Use	Start	Source	Stop	Source	Explain
Residential/Offices	c. 2002	DC Real Pr			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	c. 2002	DC Real Property			

Construction Event	Association	Associated Name

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached (1 side)**
Relate to Street: **Front Yard/Setback**
Massing: **Vertical Block**
Footprint: **Rectangular**

Number Stories: **3**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2010: Constructed c. 2002, this three-story, two-bay mixed use building is set on a solid concrete foundation. The concrete-block structure is faced with stretcher-bond brick along the façade (west elevation) and clad in vinyl siding on the secondary elevations. A shed roof of asphalt shingles caps the building and includes overhanging eaves. The façade features a large, common exterior chimney stack rising between the twin buildings. A two-sided canted bay extends the height of the building from the southwest corner and is capped by a pyramidal roof of asphalt shingles with overhanging eaves. Window openings hold 1/1, double-hung, vinyl-sash windows with 6/6 false muntins and header sills. Door openings have single-leaf, paneled wood doors set in square-edge wood surrounds. The third-story door has lights. Two window openings pierce the south (side) elevation. Fenestration of the east (rear) elevation was not visible from the public right-of-way.

Site Notes:

September 2010: This twin, mixed-used building is located east of 15th Street, S.E. and has a setback of approximately forty feet from the sidewalk. The north (side) elevation is adjacent to 326 15th Street, S.E. A milled point metal fence encloses the level, grassy front yard. A mature tree grows from the north side of the lawn, next to the terminus of the concrete driveway. Metal stairs provide access to the upper stories. A brick alley extends south of the building.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 328_15th_Street_SE_facade_looking_E.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 328_15th_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 328_15th_Street_SE_rear_looking_NW.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0088

BASICS DATA

ID Number: **1074-0088** Year Built: **c. 2002** Data Source: **DC Real Property**

Number	Extended	Street	Quad Type	Address
326	-326A	15th Street	SE	Current

Name(s)	Type of Name
Apartment Building, 326-326A 15th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0088			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Not Applicable** Quality:
Purpose: **Apartment Building** Condition: **Excellent**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Multi-Family)	c. 2002	DC Real Pr			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	c. 2002	DC Real Property			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached (1 side)**
Relate to Street: **Front Yard/Setback**
Massing: **Vertical Block**
Footprint: **Rectangular**

Number Stories: **3**
Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2010: Constructed c. 2002, this three-story, two-bay mixed use building is set on a solid concrete foundation. The concrete-block structure is faced with stretcher-bond brick along the façade (west elevation) and clad in vinyl siding on the secondary elevations. A shed roof of asphalt shingles caps the building and includes overhanging eaves. The façade features a large, common exterior chimney stack rising between the twin buildings. A two-sided canted bay extends the height of the building from the northwest corner and is capped by a pyramidal roof of asphalt shingles with overhanging eaves. Window openings hold 1/1, double-hung, vinyl-sash windows with 6/6 false muntins and header sills. Door openings have single-leaf, paneled wood doors with lights. The third-story door opening is sheltered by a metal awning and includes a metal porch with metal balusters. The east (rear) elevation has two, paired window openings. The northeast corner features a three-story integrated porch supported by wood posts with square wood balusters. Single-leaf, paneled wood doors and paired window openings are sheltered by the porch.

Site Notes:

September 2010: This twin, mixed-used building is located east of 15th Street, S.E. and has a setback of approximately forty feet from the sidewalk. The south (side) elevation is adjacent to 328 15th Street, S.E. A milled point metal security fence encloses the front yard, which is covered with concrete. Metal stairs provide access to the second story. An alley is located north of the building. The backyard is enclosed by a wooden privacy fence.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 326_15th_Street_SE_facade_looking_SE.JPG
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 326_15th_Street_SE_rear_looking_SW.JPG
 Date:: Photog:
 Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0090

BASICS DATA

ID Number: **1074-0090** Year Built: **c. 2000** Data Source: **Site Visit/Map**

Number	Extended	Street	Quad	Type of Address
330		15th Street	SE	Current

Name(s)	Type of Name
Commercial & Office, 330 15th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0090			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Not Historic** Quality:
Purpose: **Commercial Building w/ Offices** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Commercial & Office	c. 2000	Site Visit/			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	c. 2000	Site Visit/Map			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Freestanding**
Relate to Street: **Alley Building**
Massing: **Vertical Block**
Footprint: **Rectangular**

Number Stories: **3**

Bays Wide:

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2010: Constructed c. 2000, this three-story building has a rectangular form. Set on a solid parged foundation, this structure is clad in German vinyl siding. A gable roof of asphalt shingles with overhanging eaves caps the building. Fenestration consists of single and paired openings with 1/1, double-hung, vinyl-sash windows with 6/6 false muntins. A single-leaf, paneled metal door is located on the first story of the north elevation.

Site Notes:

September 2010: This building is located in the interior of Block 1074. The lot is enclosed with a wooden privacy fence. A concrete driveway is located along the eastern edge of the property.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074\

File: 330_15th_Street_SE_looking_NW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074\

File: 330_15th_Street_SE_looking_SW.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0091

BASICS DATA

ID Number: **1074-0091** Year Built: **c. 2002** Data Source: **DC Real Property**

Number	Extended	Street	Quad Type	Address
332	-332A	15th Street	SE	Current

Name(s)	Type of Name
Apartment & Commercial, 332-332A 15th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0091			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Not Historic** Quality:
Purpose: **Commercial/Dwelling** Condition: **Excellent**

Function/Use	Start	Source	Stop	Source	Explain
Commercial & Residential Multi	c. 2002	DC Real Pr			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	c. 2002	DC Real Property			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached (1 side)**
Relate to Street: **Front Yard/Setback**
Massing: **Vertical Block**
Footprint: **Rectangular**

Number Stories: **3**
Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2010: Constructed c. 2002, this three-story, two-bay mixed use building is set on a solid concrete foundation. The concrete-block structure is faced with stretcher-bond brick along the façade (west elevation) and clad in vinyl siding on the secondary elevations. A shed roof of asphalt shingles caps the building and includes overhanging eaves. The façade features a large, common exterior chimney stack rising between the twin buildings. A two-sided canted bay extends the height of the building from the northwest corner and is capped by a pyramidal roof of asphalt shingles with overhanging eaves. Window openings hold 1/1, double-hung, vinyl-sash windows with 6/6 false muntins and header sills. Door openings have single-leaf, wood-frame glass doors. The first-story door opening is set in the canted bay. The third-story door opening provides access to a metal porch with metal balusters. The east (rear) elevation has paired window openings. The northeast corner features a three-story integrated porch supported by wood posts with square wood balusters. Single-leaf, paneled wood doors and paired window openings are sheltered by the porch. A second-story wood deck extends off the integral porch, providing ground-level access to the second-story.

Site Notes:

September 2010: This twin, mixed-used building is located east of 15th Street, S.E. and has a setback of approximately forty feet from the sidewalk. The south (side) elevation is adjacent to 334 15th Street, S.E. A milled point metal fence encloses the front yard, has mature trees and a concrete walkway. Metal stairs provide access to the second story. A narrow brick alley is located north of the building. The backyard is partially enclosed by a wooden privacy fence and includes a brick and concrete parking lot.

NOTABLE FEATURES DATA

Component _____ Feature _____

EXTERIOR MATERIALS DATA

Roof Component _____ Material _____ Color _____ Treatment _____ Source _____

Wall Component _____ Material _____ Color _____ Treatment _____ Source _____

Structure Component _____ Material _____ Feature _____ Source _____

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location _____ Aperture Shape _____ Type _____ Lights _____ Material _____

Door Location _____ Aperture Shape _____ Type _____ Panels _____ Material _____

Notable Interior Plan(s) _____

Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s) _____

Contributing:

Survey(s)
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation
Permit Research
Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074\
File: 332-
332A_15th_Street_SE_facade_looking_E.jpg
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
II\Database\Pictures\Square 1074\
File: 332-
332A_15th_Street_SE_facade_looking_SE.JPG
G
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

Resource All Data Report

ID Number: 1074-0092

BASICS DATA

ID Number: **1074-0092** Year Built: **c. 2002** Data Source: **DC Real Property**

Number	Extended	Street	Quad Type of Address
334	-334A	15th Street	SE Current

Name(s)	Type of Name
Apartment Building, 334-334A 15th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0092			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Not Historic** Quality:
Purpose: **Apartment Building** Condition: **Excellent**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Multi-Family)	c. 2002	DC Real Pr			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	c. 2002	DC Real Property			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached (1 side)**
Relate to Street: **Face on Setback Line**
Massing: **Vertical Block**
Footprint: **Rectangular**

Number Stories: **3**
Bays Wide: **2**

Height:
Width:

Depth/Length:
SqFt:

Volume:
Lot Width

Lot Depth/Length:
Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type	Contributing Status
------------------	---------------------

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2010: Constructed c. 2002, this three-story, two-bay mixed use building is set on a solid concrete foundation. The concrete-block structure is faced with stretcher-bond brick along the façade (west elevation) and clad in vinyl siding on the secondary elevations. A shed roof of asphalt shingles caps the building and includes overhanging eaves. The façade features a large, common exterior chimney stack rising between the twin buildings. A two-sided canted bay extends the height of the building from the southwest corner and is capped by a pyramidal roof of asphalt shingles with overhanging eaves. Window openings hold 1/1, double-hung, vinyl-sash windows with 6/6 false muntins and header sills. Single-leaf door openings hold paneled wood doors and wood-frame doors with multiple lights. The first-story door opening is located in the canted bay. The east (rear) elevation has paired window openings. The southeast corner features a three-story integrated porch supported by wood posts with square wood balusters. Single-leaf, paneled wood doors and paired window openings are sheltered by the porch. A second-story wood deck with square wood balusters extends east from the integral porch. The deck is accessed via wood steps.

Site Notes:

September 2010: This twin, mixed-used building is located east of 15th Street, S.E. and has a setback of approximately forty feet from the sidewalk. The north (side) elevation is adjacent to 332 15th Street, S.E. A milled point metal security fence encloses the front yard, which has a concrete driveway. Metal stairs provide access to the second story. An alley is located north of the building. The backyard is enclosed by a wooden privacy fence.

NOTABLE FEATURES DATA

Component _____ Feature _____

EXTERIOR MATERIALS DATA

Roof Component _____ Material _____ Color _____ Treatment _____ Source _____

Wall Component _____ Material _____ Color _____ Treatment _____ Source _____

Structure Component _____ Material _____ Feature _____ Source _____

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location _____ Aperture Shape _____ Type _____ Lights _____ Material _____

Door Location _____ Aperture Shape _____ Type _____ Panels _____ Material _____

Notable Interior Plan(s) _____

Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s) _____

Contributing:

Survey(s) _____

Level(s) of Investigation _____

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 334_15th_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 334_15th_Street_SE_rear_looking_W.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0086

BASICS DATA

ID Number: **1074-0086** Year Built: **1892** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
336		15th Street	SE	Current

Name(s)	Type of Name
Single Dwelling, 336 15th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0086			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1892	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Rear Addition	post 1960	Site Visit/Map			
Orig Construction	1892	Permit			600 Permit

Construction Event	Association	Associated Name
Orig Construction	Builder	Baines, George W.
Orig Construction	Owner	Baines, Hannah, Mrs.

Construction Notes:

Originally one of three rowhouses constructed from the same permit (#0655). Currently two are extant.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Attached**
Relate to Street: **Front Yard/Setback**
Massing: **Vertical Box/flat front**
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **28**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type	Contributing Status
------------------	---------------------

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival
Italianate**

Exterior & Architectural Notes:

September 2010: Constructed in 1892, this two-story, two-bay single-family rowhouse exhibits stylistic influences of the Classical Revival and Italianate styles. Built by George W. Baines, this dwelling was one of three constructed from the same permit (#0655); only two are extant. Set on a solid brick foundation, this brick structure is faced with pressed brick. A sloped roof caps the dwelling and is fronted by a corbeled brick table and ovolo-molded metal cornice across the façade (west elevation).

The façade has two door openings, neither of which are subordinate. At the time of the 1928 Sanborn Fire Insurance Company map, the rowhouse north (non extant) was documented as a dwelling. This changed however by 1960, when it was documented as a store. It is possible that the buildings were connected, explaining the presence of two front doors. Another explanation is that this rowhouse was constructed as a duplex. The northern opening holds a single-leaf, paneled wood door with single-light transom. The southern opening has a single-leaf, multi-light wood door, also with a single-light transom. Both openings have narrow, square-edge wood surrounds and are capped by three-course, rowlock brick segmental arches. Second story fenestration consists of two, 1/1, double-hung, vinyl-sash windows with concrete sills and soldier/rowlock brick segmental arches. A two-course brick sill string extends across the openings. The north (side) elevation has been parged. This exposed section of the elevation was originally adjacent to 334 15th Street, S.E. before it was taken down to construct the current building with the same address. Fenestration of the east (rear) elevation consist of 1/1, double-hung, vinyl-sash windows with concrete sills and two-course, rowlock brick segmental arches.

A two-story ell is located on the rear of the dwelling. The ell has been parged and is capped by a shed roof. No openings were visible from the public right-of-way.

A two-story, one-bay addition is located on the rear of the ell. Constructed post 1960, this addition is parged and capped by a shed roof. No openings were visible from the public right-of-way.

Site Notes:

September 2010: Located east of 15th Street, S.E., this rowhouse has a setback of approximately fifteen feet from the sidewalk. The south (side) elevation is adjacent to 338 15th Street, S.E. while the north (side) elevation is partially attached to 334 15th Street, S.E. Landscaped with immature trees, shrubs, and plantings, the front yard is enclosed with a hairpin metal fence. A concrete walkway extends from the two front doors onto the sidewalk.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s) _____
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s) _____
Contributing:	
Survey(s) _____	Level(s) of Investigation _____
Capitol Hill Southeast Phase II (2010)	Permit Research
	Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 336_15th_Street_SE_facade_looking_NEx.jpg
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 336_15th_Street_SE_facade_looking_SE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 336_15th_Street_SE_rear_looking_W.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
09/15/1892	0655	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0085

BASICS DATA

ID Number: **1074-0085** Year Built: **1892** Data Source: **Permit**

Number Extended Street Quad Type of Address

338 **15th Street** **SE Current**

Name(s) Type of Name

Single Dwelling, 338 15th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1074/0085 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1892** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1892** **Permit** **600 Permit**

Construction Event Association Associated Name

Orig Construction **Builder** **Baines, George W.**

Orig Construction **Owner** **Baines, Hannah, Mrs.**

Construction Notes:

Originally one of three rowhouses constructed from the same permit (#0655). Currently two are extant.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Front Yard/Setback**

Massing: **Vertical Box/flat front**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **13**

Depth/Length: **28**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Italianate

Exterior & Architectural Notes:

September 2010: Constructed in 1892, this two-story, two-bay single-family rowhouse exhibits stylistic influences of the Classical Revival and Italianate styles. Built by George W. Baines, this dwelling was one of three constructed from the same permit (#0655); only two are extant. Set on a solid brick foundation, this brick structure is faced with pressed brick. A sloped roof caps the dwelling and is fronted by a corbeled brick table and ovolo-molded metal cornice across the façade (west elevation). An interior chimney with a parged stack pierces the roof. Located in the southern bay, the main entry contains a single-leaf, paneled wood door with semi-circular light. A single-light transom is located above. Window openings hold 1/1, double-hung, vinyl-sash windows with concrete sills. All façade openings have soldier/rowlock brick segmental arches. A second-story brick sill string completes the façade. The second story of the south (side) elevation have five-course, American-bond brickwork. Fenestration of the east (rear) elevation of the main block was not visible from the public right-of-way.

A two-story, one-bay ell is located on the rear of the dwelling. Adorned with a heavy molded metal cornice, the ell has 1/1, double-hung, vinyl-sash windows with concrete sills and two-course, rowlock brick segmental arches.

Site Notes:

September 2010: This rowhouse is located east of 15th Street, S.E. and has a setback from the sidewalk of approximately fifteen feet. The north (side) elevation is adjacent to 336 15th Street, S.E. while only the first story of the south (side) elevation is adjacent to 340 15th Street, S.E. The level front yard is enclosed with a milled point metal fence and has mature shrubs and plantings. A concrete paver walkway extends from the main entry out to the sidewalk. The backyard is enclosed with a wooden privacy fence.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Pannels Material

Notable Interior Plan(s) Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:
Contributing:

Designation Event(s) _____

Survey(s) _____
Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation _____
**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 338_15th_Street_SE_facade_looking_E.jpg
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 338_15th_Street_SE_facade_looking_NE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
I\Database\Pictures\Square 1074\
File: 338_15th_Street_SE_rear_looking_SW.jpg
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
09/15/1892	0655	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1074-0040

BASICS DATA

ID Number: **1074-0040** Year Built: **1894** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1500		D Street	SE	Current
340		15th Street	SE	Addition
342		15th Street	SE	Alternate

Name(s)	Type of Name
Single Dwelling, 1500 D Street, S.E.	Common
Neighbors United Activity Center	Current

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1074/0040			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Multi-Family)	1894	Permit			Original
Dwelling & Store		Sanborn M			Historic
Residential (Multifamily/Misc)		Site Visit/			Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1894	Permit			2300 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Didden, C.A.
Orig Construction	Builder	Volland, Charles
Orig Construction	Owner	Nesline, George

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Corner Attached**
 Relate to Street: **Front Yard/Setback**
 Massing: **Vertical Block**
 Footprint: **Rectangular (w/ additions)**

Cross Reference Notes:

Number Stories: **2**

Bays Wide:

Height:

Outbuilding Type

Contributing Status

Width: **18**

Depth/Length: **54**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway:

STYLE/EXTERIOR DATA

Architectural Style(s)

Italianate

Exterior & Architectural Notes:

September 2010: This building is composed of a main block and a small rear addition. The main block has addresses of 1500 D Street, S.E. and 342 15th Street, S.E. The small rear addition has an address of 340 15th Street, S.E. Although the building has three separate addresses, they are all linked to the same property lot, and as such, are presented as one building. The main block will be discussed first, followed by the rear addition.

Constructed in 1894, this two-story, semi-detached, single-family dwelling was designed by Charles Volland for George Nesline following the design of architect C.A. Didden. Set on a solid brick and concrete foundation, this brick structure is faced in seven-course, American-bond brick. Of note is the half-hipped roof, a scarce roof type in the area. Covered with asphalt shingles, the roof has prominent overhanging eaves and a molded metal cornice. An interior brick chimney pierces the western slope of the roof while an exterior brick chimney with corbeled cap pierces the eave on the north elevation. Window openings contain 1/1, double-hung, vinyl-sash windows with concrete sills and two-course, rowlock brick segmental arches.

The main entry (1500 15th Street), is located in a canted bay in the southwest corner of the building. A single-leaf, metal-frame glass door with a single-light transom is set in a narrow, square-edge wood surround. A metal awning shelters the opening, wrapping around the corner from the projecting storefront window bays. The bays, added c. 1970, are clad in Hardieplank siding and capped by standing-seam metal shed roofs. Fenestration consists of tripartite fixed windows.

The entry for 342 15th Street, S.E. is located in the second bay on the west elevation. This opening holds a single-leaf, paneled wood door set in a narrow, square-edge wood surround with a single-light transom. 342 15th Street, S.E. reads architecturally as a two-story, two-bay dwelling, though it is set under the same hipped roof as 1500 D Street, S.E.

The second story of the north elevation has a single-leaf, multi-light wood door and a glass block window. The door provides access to a rooftop deck located above 340 15th Street, S.E.

Located on the north end of the main block, 340 15th Street, S.E. is one story in height and four-bays wide. Based on its form and materials, as well as Sanborn Fire Insurance Company maps, this addition appears to have been constructed c. 1990. Set on a solid foundation, this appendage is clad in Hardieplank siding. A rooftop deck adorns the top of the structure. With square balusters, the patio extends between 338 and 342 D Street, S.E. The facade (west elevation) of this block has a single-leaf, multi-light wood door located in the third bay. Window openings hold 1/1, double-hung, vinyl-sash windows with 6/6 false muntins. All openings have vinyl-clad surrounds. The east (rear) elevation of 340 15th Street, S.E. was not visible from the public right-of-way.

Site Notes:

September 2010: This semi-detached building is located on a large corner lot northeast of the intersections of D Street, S.E. and 15th Street, S.E. The east elevation is adjacent to 1502 D Street, S.E. Level, the lot is enclosed with a milled point metal fence and features extensive landscaping of mature trees, shrubs, and foundation plantings. A majority of the lot fronting 15th Street, S.E. has been covered with concrete and benches installed. Curved concrete steps proceed up to the main entry, located in the southwest corner of the building. The northern end of the property has been divided into a small brick courtyard for 340 15th Street, S.E. Enclosed with a milled point metal fence, this division has mature shrubs.

NOTABLE FEATURES DATA

Component _____ Feature _____

EXTERIOR MATERIALS DATA

Roof Component _____ Material _____ Color _____ Treatment _____ Source _____

Wall Component _____ Material _____ Color _____ Treatment _____ Source _____

Structure Component _____ Material _____ Feature _____ Source _____

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location _____ Aperture Shape _____ Type _____ Lights _____ Material _____

Door Location _____ Aperture Shape _____ Type _____ Panels _____ Material _____

Notable Interior Plan(s) _____

Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** _____ Historic District(s) _____

Subdivision: _____

Ward/ANC: _____

Zoning: _____ Designation Event(s) _____

Contributing: _____

Survey(s) _____

Level(s) of Investigation _____

Capitol Hill Southeast Phase II (2010)

**Permit Research
Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Image File Not Found

Path: **X:\SD Databases\SE Phase II\Database\Pictures\Square 1074**

File: **1500_D_Street_SE_facade_looking_NE.JPG**

Date:: _____ Photog: _____

Code:: _____ R: _____ Fr: _____

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 1500_D_Street_SE_facade_looking_SE.JPG
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 1500_D_Street_SE_rear_looking_NE.JPG
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 340_15th_Street_SE_facade_looking_NE.JPG
 Date:: Photog:
 Code:: R: Fr:

Caption:

Image File Not Found

Path: X:\SD Databases\SE Phase
 I\Database\Pictures\Square 1074\
 File: 340_15th_Street_SE_facade_looking_SE.JPG
 Date:: Photog:
 Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code

Criteria

DATA PROCESSING EVENTS DATA
