

# Resource All Data Report

**ID Number: 1077-0098**

## BASICS DATA

ID Number: **1077-0098** Year Built: **1915** Data Source: **Permit**

Number Extended Street Quad Type of Address

**700** **15th Street** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 700 15th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0098** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1915** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1915** **Permit** **2500**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Norway, F.A.**

**Orig Construction** **Builder** **Norway, F.A.**

**Orig Construction** **Owner** **Norway, F.A.**

Construction Notes:

**One of eight rowhouses constructed from the same permit (#0098) and one of three consecutive rowhouses constructed along 15th Street, S.E.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 3)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular (irregular)**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

February 2008: Designed and constructed in 1915 by F.A. Norway, this two-story, two-bay, Colonial Revival-style single-family rowhouse is one of eight similar rowhouses constructed from the same permit (#0098). This dwelling is constructed of brick and is set on a solid concrete foundation. The dwelling is faced with Flemish-bond brick. The roofing type and material were not visible from the public right-of-way, but a false mansard covered with fish-scale slate shingles encircles the building. The mansard is pierced by shed-roofed dormers on the façade (west elevation) and north (side) elevation. Each dormer is fenestrated with an eight-light wood window (possibly fixed), which is flanked by wooden vents. Overhanging eaves with exposed rafter ends finish the roof. The southern bay of the first story holds a single-leaf paneled wood door with metal security door. A three-light wood sidelight is sited north of the door. A two-light wood transom and a soldier brick flat arch span the opening. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins. These openings have concrete sills and soldier brick flat arches. A one-story, two-bay porch spans the façade and is set on a brick pier foundation with decorative concrete block infill. The roof of the porch has molded, overhanging eaves and is supported by metal filigree posts which are set on brick piers. Metal balusters and curved poured concrete steps with metal hand rails in the southern end bay complete the porch. The canted northwest corner of the dwelling shares the same material treatment and fenestration as the façade. The foundation is pierced by a one-light vinyl window (possibly awning) without a sill. The north (side) elevation is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins and have concrete sills and soldier brick flat arches. Additionally, the foundation is pierced by a one-light vinyl window (possibly awning), which has a soldier brick flat arch.

A two-story, full-width block (possibly original) is located on the rear (east) elevation of the dwelling and is noted on the 1928 Sanborn map. The wood-frame addition is clad with German vinyl siding and is set on a solid, raised brick foundation, which serves as an integrated garage. The north elevation of the foundation is pierced by a roll-up paneled door with lights. A shed roof caps the addition. Visible fenestration consists of paired 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins. All windows have vinyl-clad surrounds. The rear (east) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

February 2008: This end-unit rowhouse is located on the east side of 15th Street, S.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 702 15th Street, S.E. The dwelling is located on a raised, flat, concrete-paved front yard, which features a rolling, grassy side yard planted with immature shrubs, plants, and mature trees. A concrete patio leads from the primary entrance and terminates with steps leading down to the brick sidewalk. These steps also provide access to a concrete walkway through the side yard. A brick retaining wall lines the front and sides of the property and runs parallel to the sidewalk. A metal picket fence with brick piers encloses the front and side yards. A paved driveway (possibly an alley previously) extends off of Potomac Avenue, S.E. to provide access to a below-grade garage located in the rear of the dwelling. An alley sits at the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Slate</b>		<b>Fishscale Pattern</b>	
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Flemish Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Dormer</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>8 Lite</b>	<b>Wood</b>

<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>
Notable Interior Plan(s)			Notable Interior Feature(s)	

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill Southeast Phase I (2009/2010)</b>	<b>Permit Research</b>
	<b>Volunteer Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**  
File: **700\_15STSE front.JPG**

Date:: Photog:  
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**  
File: **700\_15STSE corner view.JPG**

Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\

File: 700\_15STSE n side.JPG

Date:: Photog:

Code:: R: Fr:



---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

---

07/07/1915	0098	Build	
------------	------	-------	--

---

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

---

# Resource All Data Report

**ID Number: 1077-0097**

## BASICS DATA

ID Number: **1077-0097** Year Built: **1915** Data Source: **Permit**

Number Extended Street Quad Type of Address

**702** **15th Street** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 702 15th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0097** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1915** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1915** **Permit** **2500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Norway, F.A.**

**Orig Construction** **Builder** **Norway, F.A.**

**Orig Construction** **Owner** **Norway, F.A.**

Construction Notes:

**One of eight rowhouses constructed from the same permit (#0098) and one of three consecutive rowhouses constructed along 15th Street, S.E.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 3)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

**February 2008:** Designed and constructed in 1915 by F.A. Norway, this two-story, two-bay, Colonial Revival-style single-family rowhouse is one of eight similar rowhouses constructed from the same permit (#0098). This dwelling is constructed of brick and is set on a solid concrete foundation. The façade (west elevation) is faced with Flemish-bond brick. The roofing type and material were not visible from the public right-of-way, but a false mansard covered with fish-scale slate shingles spans the façade. The mansard is pierced by a shed-roofed dormer fenestrated with an eight-light wood window (possibly fixed), which is flanked by wooden vents. Overhanging eaves with exposed rafter ends finish the roof. The northern bay of the first story holds a single-leaf paneled wood door with lights and a storm door. A rectangular one-light wood transom and a soldier brick flat arch span the opening. The façade is fenestrated with a 1/1, double-hung, vinyl-sash window on the second story of the northern bay and Chicago-type windows in the southern bay. These openings have concrete sills and soldier brick flat arches. A one-story, two-bay porch spans the façade and is set on a brick pier foundation. The roof of the porch has molded, overhanging eaves and is supported by metal filigree posts which are set on brick piers. Metal balusters and poured concrete steps with metal hand rails in the northern end bay complete the porch. Below the porch, a single-leaf door and storm door pierce the foundation. A window opening pierces the foundation in the southern end bay. Concrete steps lead from the main concrete walkway to this below-grade door. The rear (east elevation) was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the east side of 15th Street, S.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 700 15th Street, S.E. and 704 15th Street, S.E. The dwelling is sited on a raised, flat, concrete- and brick- paved front yard planted with an immature tree. A concrete walkway leads from the primary entrance and terminates with steps leading down to the brick sidewalk. A concrete curb lines the front of the property and runs parallel to the sidewalk. A metal picket fence encloses the front yard. An alley sits at the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Slate</b>		<b>Fishscale Pattern</b>	
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Flemish Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Basemt Windows</b>	<b>Rectangular</b>	<b>Awning</b>	<b>1</b>	<b>Vinyl</b>
<b>Dormer</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>8 Lite</b>	<b>Wood</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>		<b>Vinyl</b>
<b>Facade</b>	<b>Tripartite</b>			<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Basement</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**  
File: **702\_15STSE.JPG**

Date::

Photog:

Code::

R:

Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

**07/07/1915**

**0098 Build**

Permit Notes:

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code

Criteria





# Resource All Data Report

**ID Number: 1077-0096**

## BASICS DATA

ID Number: **1077-0096** Year Built: **1915** Data Source: **Permit**

Number Extended Street Quad Type of Address

**704** **15th Street** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 704 15th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0096** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1915** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1915** **Permit** **2500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Norway, F.A.**

**Orig Construction** **Builder** **Norway, F.A.**

**Orig Construction** **Owner** **Norway, F.A.**

Construction Notes:

**One of eight rowhouses constructed from the same permit (#0098) and one of three consecutive rowhouses constructed along 15th Street, S.E.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 3)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Colonial Revival

Exterior & Architectural Notes:

**February 2008:** Designed and constructed in 1915 by F.A. Norway, this two-story, two-bay, Colonial Revival-style single-family rowhouse is one of eight similar rowhouses constructed from the same permit (#0098). This dwelling is constructed of brick and is set on a solid concrete foundation. The façade (west elevation) is faced with Flemish-bond brick. The roofing type and material were not visible from the public right-of-way, but a false mansard covered with fish-scale slate shingles spans the façade. The mansard is pierced by a shed-roofed dormer fenestrated with an eight-light wood window (possibly fixed), which is flanked by wooden vents. Overhanging eaves with exposed rafter ends finish the roof. The northern bay of the first story holds a single-leaf door with a metal security door. A rectangular one-light wood transom and a soldier brick flat arch span the opening. The façade is fenestrated with a 1/1, double-hung, vinyl-sash window on the second story of the northern bay and paired 1/1, double-hung, vinyl-sash windows in the southern bay. These openings have concrete sills and soldier brick flat arches. A one-story, two-bay porch spans the façade and is set on a brick pier foundation that has been partially infilled with decorative concrete blocks. The roof of the porch has molded, overhanging eaves and is supported by metal filigree posts which are set on brick piers. Metal balusters and poured concrete steps with metal hand rails in the northern end bay complete the porch. The south (side) elevation has no fenestration. It is faced with five-course American-bond brick that has been partially parged. The rear (east elevation) was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This end-unit rowhouse is located on the east side of 15th Street, S.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 702 15th Street, S.E. The dwelling is sited on a raised, flat, dirt-covered front yard with minimal plantings. A concrete walkway leads from the primary entrance and terminates with steps leading down to the brick sidewalk. A concrete curb lines the front of the property and runs parallel to the sidewalk. A metal bow and picket fence encloses the front yard. The south (side) elevation abuts a vacant, grassy lot. An alley sits at the rear of the property.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Slate</b>		<b>Fishscale Pattern</b>	
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Flemish Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Dormer</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>8 Lite</b>	<b>Wood</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1 Double</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**  
File: **704\_15STSE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**  
File: **704\_15STSE so side.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>07/07/1915</b>	<b>0098</b>	<b>Build</b>	

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

---

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 1077-0085**

## BASICS DATA

ID Number: **1077-0085** Year Built: **1932** Data Source: **Permit**

Number Extended Street Quad Type of Address

**708** **15th Street** **SE** **Current**

Name(s) Type of Name

**Dwelling/Store, 708 15th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0085** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Commercial** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Commercial** **1932** **Permit** **Original**

**Residential (Single-Family)** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Addition (Top)** **c. 1995** **Site**

**Visit/Maps**

**Addition (Rear)** **c. 1940** **Site**

**Visit/Maps**

**Orig Construction** **1932** **Permit** **6000 Permit**

Construction Event Association Associated Name

**Colbert, E.N.** **Owner** **McInerney, Martin**

**Orig Construction** **Architect** **Scholl, O.R.**

**Orig Construction** **Builder** **McInerney, Martin**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached (1 side)**  
Relate to Street: **Face on Setback Line**  
Massing: **Vertical Box/front porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **3**

Height:

Outbuilding Type

Contributing Status

Width: **26**

Depth/Length: **68**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** Constructed in 1932 by Martin McInerney from the design of O.R. Scholl, this one-story, three-bay store was built from permit #151990 and has been substantially altered with the addition of a ca. 1995 second story. The building now functions as a single-family dwelling. This building is constructed of five-course, American-bond brick and is set on a solid brick foundation. The façade (west elevation) is faced with stretcher-bond brick that has been painted. The north elevation has been partially parged. The building was originally capped by a sloping roof. The central bay of the first story holds a single-leaf door. Identical one-story rectangular bays, possibly original, project from the façade and flank the main entrance. The bays are pierced by triple one-light metal windows (possibly fixed). A one-story pent roof, covered with standing-seam metal, spans the facade and shelters the primary entrance and projecting bays. A one-story, full-width addition is located on the rear (east) elevation and was constructed ca. 1940. The addition is constructed of five-course, American-bond brick and is set on a solid brick foundation. A sloping roof caps the addition. The rear elevation is fenestrated with a single-leaf door with metal security door, which is accessed by poured concrete steps. Additional fenestration consists of louvered wood windows with a rowlock brick sill. A second story, full-width addition was constructed ca. 1995 and set on the roof of the original one-story store. The addition is constructed of concrete blocks. The facade (west elevation) is faced with stretcher-bond brick. A sloping roof, flanked by concrete block retaining walls, caps the addition and is complemented along the facade by a plain metal cornice. The second story of the facade is fenestrated with tripartite windows composed of a central one-light fixed metal window and flanking one-light metal casement windows. All windows have rowlock brick sills.

Site Notes:

**February 2008:** This rowhouse is located on the east side of 15th Street, S.E. and is set back approximately fifteen feet from the brick sidewalk. The south (side) elevation of the dwelling is adjacent to 710 15th Street, S.E. and a vacant grassy lot is located to the north. The dwelling is sited on a flat, grassy lot which features immature shrubs and trees and foundation plantings. A stone walkway leads from the primary entrance to the brick sidewalk. A metal fence encloses the front yard and an alley is located at the rear of the property.

## NOTABLE FEATURES DATA

Component Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Flat</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Brick</b>			

**Walls**                      **Brick**

Materials Notes:

--

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Tripartite</b>		<b>3 Lite</b>	<b>Metal</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

--

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill Southeast Phase I (2009/2010)</b>	<b>Permit Research</b>
	<b>Volunteer Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path:    **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**  
File:    **708\_15STSE n side looking ESE.JPG**

Date::                      Photog:  
Code::                                      R:                      Fr:



Caption:

Path:    **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**  
File:    **708\_15STSE n side looking WSW.JPG**

Date::                      Photog:  
Code::                                      R:                      Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 708\_15STSE n side rear addition.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 708\_15STSE rear.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 708\_15STSE.JPG

Date:: Photog:

Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/05/1932	151990	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA



Study Unit

---

Code	Criteria
------	----------

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 1077-0084**

## BASICS DATA

ID Number: **1077-0084** Year Built: **1912** Data Source: **Permit**

Number Extended Street Quad Type of Address

**710** **15th Street** **SE** **Current**

Name(s) Type of Name

**Single Dwelling, 710 15th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0084** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1912** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1912** **Permit** **2500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Weller, Michael A.**

**Orig Construction** **Builder** **Weller, Michael A.**

**Orig Construction** **Owner** **Weller, Michael A.**

Construction Notes:

**One of two single dwellings constructed from the same permit (#0832).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular (w/ hex rear bay)**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **20**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Craftsman

Exterior & Architectural Notes:

February 2008: Designed and constructed in 1912 by Michael A. Weller, this two-story, three-bay Colonial Revival-style single-family rowhouse form with Craftsman-style influences is one of two similar buildings constructed from the same permit (#0832). This dwelling is constructed of brick and is set on a solid foundation. The façade (west elevation) is faced with Flemish-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a false mansard covered with asphalt shingles spans the façade between two brick firewalls with corbeled brick end brackets. The mansard is pierced by a shed-roofed dormer with overhanging molded eaves. The dormer is fenestrated with paired, six-light, wood-frame windows (possibly fixed), and flush wood panels. Overhanging eaves with exposed rafter ends finish the roof. The southern bay of the first story holds a single-leaf door with metal security door. Single-light wood sidelights flank the door, and a one-light wood transom and a concrete lintel span the opening. The door also has a concrete-lug sill. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows. These openings have concrete-lug sills and lintels. A one-story, two-bay porch spans the façade and is set on a brick pier foundation with wood lattice infill. The roof of the porch has molded, overhanging eaves with exposed rafter ends and is supported by wood Tuscan columns. Ornate wood balusters and poured concrete steps with brick wing walls in the southern end bay complete the porch. The rear (east) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

February 2008: This rowhouse form is located on the east side of 15th Street, S.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 708 15th Street, S.E. and 712 15th Street, S.E. The dwelling is sited on a flat, dirt-covered front yard with immature shrubs and trees and foundation plantings. A concrete walkway leads from the primary entrance to the brick sidewalk. A metal fence encloses the front yard and an alley is located at the rear of the property.

## NOTABLE FEATURES DATA

Component Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False) Not Visible	Asphalt Not Visible		Shingled Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Flemish Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Dormer	Rectangular	Unknown	6	Wood
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**

File: **710\_15STSE.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

<b>08/17/1912</b>	<b>0832</b>	<b>Build</b>	
-------------------	-------------	--------------	--

Permit Notes:

--

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0083**

## BASICS DATA

ID Number: **1077-0083** Year Built: **1912** Data Source: **Permit**

Number Extended Street Quad Type of Address

**712** **15th Street** **SE** **Current**

Name(s) Type of Name

**Single Dwelling, 712 15th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0083** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1912** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1912** **Permit** **2500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Weller, Michael A.**

**Orig Construction** **Builder** **Weller, Michael A.**

**Orig Construction** **Owner** **Weller, Michael A.**

Construction Notes:

**One of two single dwellings constructed from the same permit (#0832).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **20**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Craftsman

Exterior & Architectural Notes:

February 2008: Designed and constructed in 1912 by Michael A. Weller, this two-story, three-bay Colonial Revival-style single-family rowhouse form with Craftsman-style influences is one of two similar buildings constructed from the same permit (#0832). This dwelling is constructed of brick and is set on a solid foundation. The façade (west elevation) is faced with Flemish-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a false mansard covered with slate shingles spans the façade between two brick firewalls with corbeled brick end brackets. The mansard is pierced by a shed-roofed dormer with overhanging molded eaves. The dormer is fenestrated with paired, six-light, wood-frame windows (possibly fixed), and flush wood panels. Overhanging eaves with exposed rafter ends finish the roof. The southern bay of the first story holds a single-leaf wood-frame glass door. Single-light wood sidelights and a one-light wood transom highlight the opening, and a concrete lintel spans the opening. The door also has a concrete-lug sill. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows. These openings have concrete-lug sills and lintels. A one-story, two-bay porch spans the façade and is set on a brick pier foundation. The roof of the porch has molded, overhanging eaves with exposed rafter ends and is supported by wood Tuscan columns. Small wood balusters and poured concrete steps with brick wing walls in the southern end bay complete the porch. The rear (east) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

February 2008: This rowhouse form is located on the east side of 15th Street, S.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 710 15th Street, S.E. and 714 15th Street, S.E. The dwelling is sited on a flat, dirt-covered front yard with immature shrubs, plants, and foundation plantings. A concrete walkway leads from the primary entrance to the brick sidewalk. A low wood planting wall lines the front of the property and runs parallel to the sidewalk. An alley is located at the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Asphalt		Shingled	
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Flemish Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Dormer	Rectangular	Unknown	6	Wood
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Full Glass	Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**

File: **712\_15STSE.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

<b>08/17/1912</b>	<b>0083</b>	<b>Build</b>	
-------------------	-------------	--------------	--

Permit Notes:

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0094**

## BASICS DATA

ID Number: **1077-0094** Year Built: **1915** Data Source: **Permit**

Number Extended Street Quad Type of Address

**714** **15th Street** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 714 15th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0094** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1915** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1915** **Permit** **2333 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Larnok (or Lamar)**

**Orig Construction** **Builder** **Boss, William A.**

**Orig Construction** **Owner** **Boss, William A.**

Construction Notes:

**One of six rowhouses constructed from the same permit (#4364).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 6)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **19**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

**February 2008:** Designed by Larnok (or Lamar) and constructed by William A. Boss in 1915, this two-story, three-bay Colonial Revival-style single-family rowhouse is one of six similar rowhouses constructed from the same permit (#4364). This dwelling is constructed of brick and is set on a solid concrete foundation. The façade (west elevation) is faced with five-course American-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a false mansard covered with shingles of an unknown material spans the façade between two brick firewalls with corbeled brick end brackets. The mansard is pierced by two pedimented gabled dormers fenestrated with eight-light wood windows (possibly fixed). Overhanging eaves with a molded cornice and dentils finish the roof. The southern bay of the first story holds a single-leaf door and storm door. A blind transom and concrete-lug sill and lintel highlight the opening. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows. These openings have concrete-lug sills and lintels. A deck spans the façade and is set on a brick pier foundation with wood lattice infill. The original roof has been removed. Wood balusters and poured concrete steps with wood hand rails in the southern end bay complete the deck. The rear (east) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the east side of 15th Street, S.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 712 15th Street, S.E. and 716 15th Street, S.E. The dwelling is sited on a raised flat, grassy front yard with a mature tree and plants. A concrete walkway leads from the primary entrance to the brick sidewalk. A wood retaining wall lines the front of the property and runs parallel to the sidewalk. An alley is located at the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Unknown</b>		<b>Shingled</b>	
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Dormer</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>8 Lite</b>	<b>Wood</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Friday, August 30, 2013

DC HPO Survey - SouthEast Phase 1

ID\_Number: 1077-0094 Page 2

Subdivision:  
Ward/ANC:  
Zoning:  
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 714\_15STSE.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/29/1915	4364	Build	

Permit Notes:

--

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0093**

## BASICS DATA

ID Number: **1077-0093** Year Built: **1915** Data Source: **Permit**

Number Extended Street Quad Type of Address

**716** **15th Street** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 716 15th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0093** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1915** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1915** **Permit** **2333 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Larnok (or Lamar)**

**Orig Construction** **Builder** **Boss, William A.**

**Orig Construction** **Owner** **Boss, William A.**

Construction Notes:

**One of six rowhouses constructed from the same permit (#4364).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 6)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **19**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

**February 2008:** Designed by Larnok (or Lamar) and constructed by William A. Boss in 1915, this two-story, three-bay Colonial Revival-style single-family rowhouse is one of six similar rowhouses constructed from the same permit (#4364). This dwelling is constructed of brick and is set on a solid concrete foundation. The façade (west elevation) is faced with five-course American-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a false mansard covered with shingles of an unknown material spans the façade between two brick firewalls with corbeled brick end brackets. The mansard is pierced by two pedimented gabled dormers fenestrated with eight-light wood windows (possibly fixed). Overhanging eaves with a molded cornice and dentils finish the roof. The southern bay of the first story holds a single-leaf paneled wood door with lights and a metal storm door. A wood entablature with concrete-lug sill and concrete-lug lintel highlight the opening. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows. These openings have concrete-lug sills and lintels. A one-story, two-bay porch spans the façade and is set on a brick pier foundation. The roof of the porch has overhanging eaves and is supported by wood Tuscan columns. Small wood balusters and poured concrete steps in the southern end bay complete the porch. The rear (east) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the east side of 15th Street, S.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 714 15th Street, S.E. and 718 15th Street, S.E. The dwelling is sited on a raised flat, grassy front yard with a mature tree, plants, and foundation plantings. A concrete walkway leads from the primary entrance to the brick sidewalk. A brick retaining wall lines the front of the property and runs parallel to the sidewalk. An alley is located at the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Unknown</b>		<b>Shingled</b>	
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Dormer</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>8 Lite</b>	<b>Wood</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>4-Panel</b>	<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill Southeast Phase I (2009/2010)**

Level(s) of Investigation

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**

File: **716\_15STSE.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

<b>04/29/1915</b>	<b>4364</b>	<b>Build</b>	
-------------------	-------------	--------------	--

Permit Notes:

--

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0092**

## BASICS DATA

ID Number: **1077-0092** Year Built: **1915** Data Source: **Permit**

Number Extended Street Quad Type of Address

**718** **15th Street** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 718 15th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0092** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1915** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1915** **Permit** **2333 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Larnok (or Lamar)**

**Orig Construction** **Builder** **Boss, William A.**

**Orig Construction** **Owner** **Boss, William A.**

Construction Notes:

**One of six rowhouses constructed from the same permit (#4364).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 6)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **19**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Colonial Revival

Exterior & Architectural Notes:

**February 2008:** Designed by Larnok (or Lamar) and constructed by William A. Boss in 1915, this two-story, three-bay Colonial Revival-style single-family rowhouse is one of six similar rowhouses constructed from the same permit (#4364). This dwelling is constructed of brick and is set on a solid concrete foundation. The façade (west elevation) is faced with five-course American-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a false mansard covered with shingles of an unknown material spans the façade between two brick firewalls with corbeled brick end brackets. The mansard is pierced by two pedimented gabled dormers fenestrated with eight-light wood windows (possibly fixed). Overhanging eaves with a molded cornice and dentils finish the roof. The southern bay of the first story holds a single-leaf paneled wood door with lights. A blind transom with concrete-lug sill, as well as a concrete-lug lintel highlight the opening. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows. These openings have concrete-lug sills and lintels. A one-story, one-bay porch spans the façade and is set on a brick pier foundation with decorative concrete block infill. The roof of the porch has overhanging eaves and dentils and is supported by brick posts. Metal balusters and poured concrete steps with metal hand rails in the southern end bay complete the porch. The rear (east) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the east side of 15th Street, S.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 716 15th Street, S.E. and 720 15th Street, S.E. A flat, plant-filled yard with a mature tree and foundation plantings fronts the dwelling. A concrete walkway leads from the primary entrance to the brick sidewalk. An alley is located at the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Unknown</b>		<b>Shingled</b>	
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Dormer</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>8 Lite</b>	<b>Wood</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>4-Panel</b>	<b>Unkown w/Lights</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Friday, August 30, 2013

DC HPO Survey - SouthEast Phase 1

ID\_Number: 1077-0092 Page 2

Subdivision:  
Ward/ANC:  
Zoning:  
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)**

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 718\_15STSE.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
04/29/1915	4364	Build	

Permit Notes:

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA



# Resource All Data Report

**ID Number: 1077-0091**

## BASICS DATA

ID Number: **1077-0091** Year Built: **1915** Data Source: **Permit**

Number Extended Street Quad Type of Address

**720** **15th Street** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 720 15th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0091** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1915** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1915** **Permit** **2333 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Larnok (or Lamar)**

**Orig Construction** **Builder** **Boss, William A.**

**Orig Construction** **Owner** **Boss, William A.**

Construction Notes:

**One of six rowhouses constructed from the same permit (#4364).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 6)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **19**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Colonial Revival

Exterior & Architectural Notes:

**February 2008:** Designed by Larnok (or Lamar) and constructed by William A. Boss in 1915, this two-story, three-bay Colonial Revival-style single-family rowhouse is one of six similar rowhouses constructed from the same permit (#4364). This dwelling is constructed of brick and is set on a solid concrete foundation. The façade (west elevation) is faced with beaded weatherboard. The roofing type and material were not visible from the public right-of-way, but a false mansard covered with shingles of an unknown material spans the façade between two brick firewalls with corbeled brick end brackets. The mansard is pierced by two pedimented gabled dormers fenestrated with eight-light wood windows (possibly fixed). Overhanging eaves with a plain wood cornice finish the roof. The southern bay of the first story holds a single-leaf door and storm door. The façade is fenestrated with 1/1, double-hung, wood-sash windows. These openings have concrete-lug sills and are sheltered by individual vinyl awnings. An original one-story, one-bay porch spans the façade and is set on a brick pier foundation. The porch has been enclosed ca. 1970 with brick and jalousie windows. The roof of the porch has overhanging eaves and a vinyl awning. Poured concrete steps with metal hand rails in the southern end bay complete the porch. The rear (east) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the east side of 15th Street, S.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 718 15th Street, S.E. and 722 15th Street, S.E. A raised flat, grassy yard with a mature shrubs fronts the dwelling. A concrete walkway leads from the primary entrance to the brick sidewalk. An alley is located at the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Unknown</b>		<b>Shingled</b>	
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>weatherboards</b>			
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Dormer</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>8 Lite</b>	<b>Wood</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:  
Zoning:  
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 720\_15STSE.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

04/29/1915	4364	Build	
------------	------	-------	--

Permit Notes:

--

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0090**

## BASICS DATA

ID Number: **1077-0090** Year Built: **1915** Data Source: **Permit**

Number Extended Street Quad Type of Address

**722** **15th Street** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 722 15th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0090** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1915** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1915** **Permit** **2333 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Larnok (or Lamar)**

**Orig Construction** **Builder** **Boss, William A.**

**Orig Construction** **Owner** **Boss, William A.**

Construction Notes:

**One of six rowhouses constructed from the same permit (#4364).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 6)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **19**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

**February 2008:** Designed by Larnok (or Lamar) and constructed by William A. Boss in 1915, this two-story, three-bay Colonial Revival-style single-family rowhouse is one of six similar rowhouses constructed from the same permit (#4364). This dwelling is constructed of brick and is set on a solid concrete foundation. The façade (west elevation) is faced with five-course American-bond brick. The roofing type and material were not visible from the public right-of-way, but a false mansard covered with shingles of an unknown material spans the façade between two brick firewalls with corbeled brick end brackets. The mansard is pierced by two pedimented gabled dormers fenestrated with eight-light wood windows (possibly fixed). Overhanging eaves with a plain wood cornice finish the roof. The southern bay of the first story holds a single-leaf paneled wood door and a storm door. A rectangular one-light transom with concrete-lug sill, as well as a concrete-lug lintel, highlights the opening. The façade is fenestrated with 1/1, double-hung, wood-sash windows. These openings have concrete-lug sills and lintels. A one-story, one-bay porch spans the façade and is set on a brick pier foundation with decorative concrete block infill. The roof of the porch has overhanging eaves and is supported by metal filigree posts. Metal balusters and poured concrete steps with metal hand rails in the southern end bay complete the porch. The rear (east) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the east side of 15th Street, S.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 720 15th Street, S.E. and 724 15th Street, S.E. The dwelling is sited on a flat, grassy yard with mature shrubs and foundation plantings. A concrete walkway leads from the primary entrance to the brick sidewalk. A concrete retaining wall lines the front of the property and runs parallel to the sidewalk. An alley is located at the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b> <b>Not Visible</b>	<b>Unknown</b> <b>Not Visible</b>		<b>Shingled</b> <b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b> <b>Walls</b>	<b>Concrete</b> <b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Dormer</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>8 Lite</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Wood</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Friday, August 30, 2013

DC HPO Survey - SouthEast Phase 1

ID\_Number: 1077-0090 Page 2

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\

File: 722\_15STSE.JPG

Date:: Photog:

Code::

R:

Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

04/29/1915	4364	Build	
------------	------	-------	--

Permit Notes:

--

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0089**

## BASICS DATA

ID Number: **1077-0089** Year Built: **1915** Data Source: **Permit**

Number Extended Street Quad Type of Address

**724** **15th Street** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 724 15th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0089** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1915** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1915** **Permit** **2333 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Larnok (or Lamar)**

**Orig Construction** **Builder** **Boss, William A.**

**Orig Construction** **Owner** **Boss, William A.**

Construction Notes:

**One of six rowhouses constructed from the same permit (#4364).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 6)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **19**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

**February 2008:** Designed by Larnok (or Lamar) and constructed by William A. Boss in 1915, this two-story, three-bay Colonial Revival-style single-family rowhouse is one of six similar rowhouses constructed from the same permit (#4364). This dwelling is constructed of brick and is set on a solid concrete foundation. The façade (west elevation) is faced with five-course American-bond brick. The roofing type and material were not visible from the public right-of-way, but a false mansard covered with shingles of an unknown material spans the façade between two brick firewalls with corbeled brick end brackets. The mansard is pierced by two pedimented gabled dormers fenestrated with eight-light wood windows (possibly fixed). Overhanging eaves with a molded cornice and dentils finish the roof. The southern bay of the first story holds a single-leaf door and a metal security door. A rectangular one-light transom with concrete-lug sill, as well as a concrete-lug lintel, highlights the opening. The façade is fenestrated with 1/1, double-hung, wood-sash windows. These openings have concrete-lug sills and lintels. A one-story, one-bay porch spans the façade and is set on a brick pier foundation with decorative concrete block infill. The roof of the porch has overhanging eaves and is supported by brick posts set on brick piers. Wood balusters and poured concrete steps with wood hand rails and brick wing walls in the southern end bay complete the porch. The rear (east) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the east side of 15th Street, S.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 722 15th Street, S.E. and 726 15th Street, S.E. The dwelling is sited on a flat, raised grassy yard. A concrete walkway leads from the primary entrance to the brick sidewalk. A concrete retaining wall lines the front of the property and runs parallel to the sidewalk, and a metal fence with brick piers encloses the yard. An alley is located at the rear of the property.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Unknown</b>		<b>Shingled</b>	
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Dormer</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>8 Lite</b>	<b>Wood</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Friday, August 30, 2013

DC HPO Survey - SouthEast Phase 1

ID\_Number: 1077-0089 Page 2



Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill Southeast Phase I (2009/2010)**

Level(s) of Investigation

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**

File: **724\_15STSE.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>04/29/1915</b>	<b>4364</b>	<b>Build</b>	

Permit Notes:

--

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0116**

## BASICS DATA

ID Number: **1077-0116** Year Built: **1916** Data Source: **Permit**

Number Extended Street Quad Type of Address

**726** **15th Street** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 726 15th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0116** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1916** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1916** **Permit** **2500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howser, W. Edgar**

**Orig Construction** **Builder** **Howenstein, H.R.**

**Orig Construction** **Owner** **Howenstein, H.R.**

Construction Notes:

**One of three buildings constructed from the same permit (#1390).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 3)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **19**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

**February 2008:** Designed by W.E. Howser and constructed by H.R. Howenstein in 1916, this two-story, three-bay Colonial Revival-style single-family rowhouse is one of three similar rowhouses constructed from the same permit (#1390). This dwelling is constructed of brick and is set on a solid concrete foundation. The façade (west elevation) is faced with five-course American-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a false mansard covered with fish-scale slate shingles spans the façade between two brick firewalls with corbeled brick end brackets. The mansard is pierced by two pedimented gabled dormers fenestrated with ten-light wood windows (possibly fixed). Overhanging eaves with a molded cornice finish the roof. The southern bay of the first story holds a single-leaf door with three lights and a storm door. A rectangular one-light transom with concrete-lug sill, as well as a concrete-lug lintel, highlights the opening. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows. These openings have concrete-lug sills and lintels. A one-story, one-bay porch spans the façade and is set on a brick pier foundation. The roof of the porch has molded overhanging eaves and is supported by metal filigree posts. Metal balusters and poured concrete steps with metal hand rails and brick wing walls in the southern end bay complete the porch. Concrete steps in the central bay descend from the front yard to offer access to an opening in the foundation which was not visible from the public right-of-way. The rear (east) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the east side of 15th Street, S.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 724 15th Street, S.E. and 728 15th Street, S.E. The dwelling is sited on a flat, grassy yard with mature shrubs and foundation plantings. A concrete walkway leads from the primary entrance to the brick sidewalk. A metal fence encloses the yard and an alley is located at the rear of the property.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Slate</b>		<b>Fishscale Pattern</b>	
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Dormer</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>10 Lite</b>	<b>Wood</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unkown w/Lights</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill Southeast Phase I (2009/2010)**

Level(s) of Investigation

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**

File: **726\_15STSE.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>09/19/1916</b>	<b>1390</b>	<b>Build</b>	

Permit Notes:

--

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code Criteria

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0115**

## BASICS DATA

ID Number: **1077-0115** Year Built: **1916** Data Source: **Permit**

Number Extended Street Quad Type of Address

**728** **15th Street** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 728 15th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0115** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1916** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1916** **Permit** **2500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howser, W. Edgar**

**Orig Construction** **Builder** **Howenstein, H.R.**

**Orig Construction** **Owner** **Howenstein, H.R.**

Construction Notes:

**One of three buildings constructed from the same permit (#1390).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 3)**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Front Porch**

Footprint: **L-Shaped**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **19**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

### Colonial Revival

Exterior & Architectural Notes:

**February 2008:** Designed by W.E. Howser and constructed by H.R. Howenstein in 1916, this two-story, three-bay Colonial Revival-style single-family rowhouse is one of three similar rowhouses constructed from the same permit (#1390). This dwelling is constructed of brick and is set on a solid concrete foundation. The façade (west elevation) is faced with five-course American-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a false mansard covered with fish-scale slate shingles spans the façade between two brick firewalls with corbeled brick end brackets. The mansard is pierced by two pedimented gabled dormers fenestrated with ten-light wood windows (possibly fixed). Overhanging eaves with a molded cornice and dentils finish the roof. The northern bay of the first story holds a single-leaf door and a storm door. A rectangular one-light wood transom with concrete-lug sill highlights the opening. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows. These openings have concrete-lug sills and lintels. A one-story, one-bay porch spans the façade and is set on a brick pier foundation. The roof of the porch has molded overhanging eaves and is supported by metal filigree posts. Turned metal balusters and poured concrete steps with metal hand rails in the northern end bay complete the porch. Concrete steps in the central bay descend from the front yard to offer access to an opening in the foundation which was not visible from the public right-of-way. The rear (east) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the east side of 15th Street, S.E. and is set back approximately fifteen feet from the brick sidewalk. The dwelling is adjacent to 726 15th Street, S.E. and 730 15th Street, S.E. The dwelling is sited on a flat, grassy yard with mature shrubs. A concrete walkway leads from the primary entrance to the brick sidewalk. A metal chain-link fence encloses the yard and an alley is located at the rear of the property.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Slate</b>		<b>Fishscale Pattern</b>	
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Dormer</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>10 Lite</b>	<b>Wood</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

**Capitol Hill Southeast Phase I (2009/2010)**

Level(s) of Investigation

**Permit Research**

**Volunteer Reconnaissance Survey**

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**

File: **728\_15STSE.JPG**

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

<b>09/19/1916</b>	<b>1390</b>	<b>Build</b>	
-------------------	-------------	--------------	--

Permit Notes:

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0114**

## BASICS DATA

ID Number: **1077-0114** Year Built: **1916** Data Source: **Permit**

Number Extended Street Quad Type of Address

**730** **15th Street** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 730 15th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0114** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Fair**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1916** **Permit** **Historic**

**Residential (Multi-Family)** **Site Visit/** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1916** **Permit** **2500 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Howser, W. Edgar**

**Orig Construction** **Builder** **Howenstein, H.R.**

**Orig Construction** **Owner** **Howenstein, H.R.**

Construction Notes:

**One of three buildings constructed from the same permit (#1390).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 3)**  
Relate to Street: **Face on Line**  
Massing: **Row Building/Canted Bay**  
Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **19**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

**February 2008:** Designed by W.E. Howser and constructed by H.R. Howenstein in 1916, this two-story, three-bay Colonial Revival-style single-family rowhouse is one of three similar rowhouses constructed from the same permit (#1390). The building has been altered to serve as a duplex. This building is constructed of brick and is set on a solid concrete foundation. The façade (west elevation) is faced with five-course American-bond brick that has been painted. The building has a sloping roof, and a false mansard covered with fish-scale slate shingles spans the façade between two brick firewalls with corbeled brick end brackets. The mansard is pierced by two pedimented dormers fenestrated with ten-light wood windows (possibly fixed). A molded cornice finishes the roof. A one-story bay projects from the façade and has a canted south elevation. The bay is fenestrated with single and triple one-light vinyl windows (possibly casement). The recessed half-cant southern end bay features two single-leaf paneled wood doors with one-light transoms. A one-story mansard roof, covered with wood shingles, spans the facade and shelters the primary entrance and projecting bay. The side (south) elevation is faced with five-course American-bond brick, and the rear (east) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the east side of 15th Street, S.E. The entire lot is paved with concrete and merges with the public concrete and brick sidewalk fronting the property. The dwelling is adjacent to 728 15th Street, S.E. and 732 15th Street, S.E.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Mansard (False)</b>	<b>Slate</b>		<b>Fishscale Pattern</b>	
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>American Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>1 Flr Windows</b>	<b>Rectangular</b>	<b>Unknown</b>	<b>1</b>	<b>Vinyl</b>
<b>2 Flr Windows</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
<b>Dormer</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>10 Lite</b>	<b>Wood</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>First Floor</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unknown</b>
<b>First Floor</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unknown</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill Southeast Phase I (2009/2010)</b>	<b>Permit Research</b> <b>Volunteer Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**  
File: **730\_15STSE.JPG**  
Date:: Photog:  
Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
<b>09/19/1916</b>	<b>1390</b>	<b>Build</b>	

Permit Notes:

--

---

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

Study Unit

--

Code

Criteria

--

---

**DATA PROCESSING EVENTS DATA**

# Resource All Data Report

**ID Number: 1077-0808**

## BASICS DATA

ID Number: **1077-0808** Year Built: **1926** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
--------	----------	--------	------	-----------------

<b>732</b>		<b>15th Street</b>	<b>SE</b>	<b>Current</b>
------------	--	--------------------	-----------	----------------

Name(s)	Type of Name
---------	--------------

<b>Store, 732 15th Street, S.E.</b>	<b>Common</b>
<b>The Laundromat</b>	<b>Current</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1077/0808</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Store** Condition: **Fair**

Function/Use	Start	Source	Stop	Source	Explain
<b>Commercial</b>	<b>1926</b>	<b>Permit</b>			<b>Historic</b>
<b>Vacant</b>		<b>Site Visit</b>			<b>Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1926</b>	<b>Permit</b>			<b>4700 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Spencer, Warren</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Spencer, Warren</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Sanitary Grocery Company, Inc.</b>

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached (1 side)**  
Relate to Street: **Face on Line**  
Massing: **Horizontal Block (irregular)**  
Footprint: **Rectangular**

Number Stories: **1**  
Bays Wide: **2**  
Height: **20**  
Width: **50**  
Depth/Length: **50**

SqFt:  
Volume:  
Lot Width  
Lot Depth/Length:  
Lot SqFt:  
Acreage:  
Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Italianate**  
**Colonial Revival**

Exterior & Architectural Notes:

**February 2008:** Designed and constructed in 1926 by Warren Spencer, this one-story, two-bay store was built from permit #6674. Influenced by the Italianate and Colonial Revival styles, the building, constructed of five-course American-bond brick, is set on a solid concrete foundation. The façade (west elevation) is faced with stretcher-bond brick that has been painted. The material of the shed roof was not visible from the public right-of-way, but a pedimented stepped gable parapet wall complements the roof on the façade. The parapet is edged with concrete coping. A decorative concrete diamond is inlaid below the gable of the parapet. The plain brick frieze is edged with rowlock bricks and a signboard is centrally located within the frieze. The southernmost bay holds a single-leaf, metal-frame glass door with a metal security door. A six-light, full-height storefront window is located to the north of the entry and is protected by metal security bars. An ogee-molded cornice with a plain frieze and blind transom span the openings on the façade. The rear (west) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This building is located on the east side of 15th Street, S.E. The entire lot is paved with concrete and merges with the public concrete and brick sidewalk fronting the property. The dwelling is adjacent to 730 15th Street, S.E. and an asphalt-paved parking lot is located to the south.

## NOTABLE FEATURES DATA

Component Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Shed</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Brick</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>6</b>	<b>Metal</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Full Glass</b>	<b>Metal</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill Southeast Phase I (2009/2010)</b>	<b>Permit Research</b>
	<b>Volunteer Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 732\_15STSE.JPG

Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 732\_15STSE s side.JPG

Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

02/19/1926	6674	Build	
------------	------	-------	--

Permit Notes:

--

## BIBLIOGRAPHIC DATA

---

## SIGNIFICANCE DATA

---

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

---

# Resource All Data Report

**ID Number: 1077-0809**

## BASICS DATA

ID Number: **1077-0809** Year Built: **c. 1951** Data Source: **Permit Index**

Number Extended Street Quad Type of Address

**1500** **Pennsylvania Avenue** **SE** **Current**

Name(s) Type of Name

**Commercial Building, 1500 Pennsylvania Avenue, S.E.** **Common**  
**Esso Gas Station** **Historic**  
**Domino's Pizza** **Current**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0809** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Gas Station** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Gas Station/Auto Sales** **c. 1951** **Permit** **Historic**  
**Restaurant/Carry-out** **Site Visit/** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **c. 1951** **Permit**

Construction Event Association Associated Name

**Orig Construction** **Owner** **Esso Standard Oil**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA



Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Detached**  
Relate to Street: **Commercial Lot**  
Massing: **Horizontal Box**  
Footprint: **Rectangular (irregular)**

Number Stories: **1**  
Bays Wide: **4**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Streamline Moderne**

Exterior & Architectural Notes:

**February 2008:** Based on its form, materials, and historic newspaper research, this commercial building was constructed ca. 1935. Set on a solid concrete foundation, this one-story, four-bay building replaced a gas station constructed in 1926 that was destroyed by a fire in 1935. The rectangular form, the horizontality, minimal ornamentation, curved façade, and streamlines of the building reflect the influence of the Moderne style in the second quarter of the twentieth century. As documented by the 1960 Sanborn Insurance map, this building was constructed for use as a gas station. It has since been rehabilitated for use as a commercial building/restaurant. The building sits on a solid concrete foundation and is constructed of concrete blocks covered with stucco. The materials of the flat roof were not visible from the public right-of-way, but a plain band covered with stucco encircles the façade, serving as a cornice. Metal ventilators pierce the roof and an interior brick chimney with a plain cap is located in the northwest corner. A signboard located on the façade partially extends above the roofline. The main entry to the building was originally located in the westernmost bay of the façade and provided access to the service counter. A replacement single-leaf metal-frame glass door with a one-light transom now serves as a secondary entry to the building. The entry is framed by large replacement storefront windows that curve around the edge of the façade to the northwest (side) elevation. The three vehicular service bays located east of the former main entry have been enclosed and used as entries and display windows. The bays hold single-leaf metal-frame glass doors with paired one-light storefront windows. A three-light transom spans each of the bays. Each bay is set in a segmentally-arched stucco surround with a keystone. A one-story, one-bay projecting bay is located on the northwest (side) elevation and shares the same material treatment as the façade. A single-leaf flush metal door is located on the northwest (side) elevation. The southeast (side) and rear (northeast) elevations of the building were not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This building is located on the northeast corner of Pennsylvania Avenue, S.E. and 15th Street, S.E.. It is set back approximately 60 feet from the public concrete and brick sidewalks that front the property. The building is surrounded by an asphalt-paved parking lot on the south and west sides. A small grassy area is located to the north of the building and contains minimal plantings and trees.

## NOTABLE FEATURES DATA

Component Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Flat</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Stucco</b>			
Structure Component	Material	Feature		Source

Foundation Concrete  
Walls Concrete Block

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Fixed</b>	<b>1</b>	<b>Metal</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>First Floor</b>	<b>Rectangular</b>	<b>Single</b>	<b>Full Glass</b>	<b>Metal</b>

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill Southeast Phase I (2009/2010)</b>	<b>Permit Research</b> <b>Volunteer Reconnaissance Survey</b>

### PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1500\_PENN\_AVSE.JPG  
Date:: Photog:  
Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

--

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

---

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 1077-0829**

## BASICS DATA

ID Number: **1077-0829** Year Built: **c. 1979** Data Source: **DC Real Property Database**

Number Extended Street Quad Type of Address

**1504** **Pennsylvania Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1504 Pennsylvania Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0829** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **c. 1979** **DC Real Pr** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **c. 1979** **DC Real Property Database**

Construction Event Association Associated Name

Construction Notes:

**One of nine rowhouses constructed at the same time.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 9)**

Relate to Street: **Face on Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **3**

Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☒

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** This three-story, three-bay concrete-block rowhouse was constructed in 1979. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The material of the roof was not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf paneled door with a metal security door. A rowlock brick sill and a splayed concrete lintel with keystone highlight the opening. The central bay of the first story holds a wood garage door (likely flip-up) with multiple lights. A splayed concrete lintel with keystone and projecting concrete elements spans the opening. A semi-circular breezeway with a rowlock brick arch is located in the northwestern end bay. This opening holds a metal security door and provides access to the buildings at the rear of the property (1504 rear, 1506 rear, and 1510 rear Pennsylvania Avenue, S.E.). The façade is fenestrated with 1/1, double-hung, vinyl-sash windows in wood surrounds. These openings are highlighted by splayed concrete lintels with keystones and projecting concrete elements, as well as rowlock brick sills. The northwest (side) elevation is faced with stucco. The rear (northeast) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This end-unit rowhouse is located on the northeast side of Pennsylvania Avenue, S.E. Concrete walkways leading from the main entrance and breezeway as well as a concrete driveway, bordered by small grassy areas for planting, dominate the small front yard. The walkways and driveway merge with the public concrete sidewalk fronting the property. The dwelling is adjacent to 1506 Pennsylvania Avenue, S.E., and an asphalt-paved parking lot is located to the northwest. A small yard is located at the rear of the property and is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbi-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unknown</b>
<b>Vehicular Door</b>	<b>Rectangular</b>			<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Friday, August 30, 2013

DC HPO Survey - SouthEast Phase 1

ID\_Number: 1077-0829 Page 2

Survey Name:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\

File: 1504\_PENN\_AVSE.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0816**

## BASICS DATA

ID Number: **1077-0816** Year Built: **c. 1979** Data Source: **DC Real Property Database**

Number	Extended	Street	Quad	Type of Address
<b>1504</b>	<b>Rear</b>	<b>Pennsylvania Avenue</b>	<b>SE</b>	<b>Current</b>
<b>1501</b>		<b>Freedom Way</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Multiple Dwelling, 1504 Rear Pennsylvania Avenue, S.E.</b>	<b>Common</b>
<b>Multiple Dwelling, 1501 Freedom Way, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1077/0816</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Not Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Multi-Family)</b>	<b>c. 1979</b>	<b>DC Real Pr</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>c. 1979</b>	<b>DC Real Property Database</b>			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

**One of six rowhouses constructed at the same time. Staggered to fit lot on alley.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row End (1 of 6)**  
Relate to Street: **Face on Line**  
Massing: **Row Building/Flat Front**  
Footprint: **Rectangular**

Number Stories: **3**  
Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** This three-story, three-bay multiple-family concrete-block dwelling was constructed ca. 1979. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf paneled door with metal security door. A rowlock brick sill and a splayed concrete lintel with keystone highlight the opening. All other openings on the façade hold 6/6, double-hung, vinyl-sash windows ornamented with splayed concrete lintels and rowlock brick sills. The northwest (side) elevation was not surveyed or photographed by the volunteer surveyor. The rear (northwest) elevation is covered with stucco and fronts Freedom Way, S.E., formerly an alley. This elevation has four bays. The northwestern and southern central bays of the first story hold single-leaf wood-frame glass doors and metal security doors. Rowlock brick sills highlight the openings. The other openings on the first story hold 6/6, double-hung, vinyl-sash windows with rowlock brick sills. The remainder of the elevation is fenestrated with paired 6/6, double-hung, vinyl-sash windows with rowlock brick sills.

Site Notes:

**February 2008:** This multiple dwelling is located behind 1504 Pennsylvania Avenue, S.E. and is adjacent to 1506 (rear) Pennsylvania Avenue, S.E./ 1503 Freedom Way, S.E. A small, grassy yard fronts the property, and a grassy lot is located to the northwest of the building. A paved driveway and alley are located at the rear of the building.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

Materials Notes:



## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>6/6</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unknown</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill Southeast Phase I (2009/2010)</b>	<b>Permit Research</b>
	<b>Volunteer Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**  
File: **1501\_FREEDOM\_WAYSE front view\_formerly  
1501 PaAvSE rear.JPG**  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**  
File: **1501-11\_FREEDOM\_AVSE rear view.JPG**  
Date:: Photog:  
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1501\_FREEDOM\_WAYSE rear view.JPG  
Date:: Photog:  
Code:: R: Fr:



---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

---

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

---

# Resource All Data Report

**ID Number: 1077-0824**

## BASICS DATA

ID Number: **1077-0824** Year Built: **c. 1979** Data Source: **DC Real Property Database**

Number Extended Street Quad Type of Address

**1506** **Pennsylvania Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1506 Pennsylvania Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0824** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **c. 1979** **DC Real Pr** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **c. 1979** **DC Real Property Database**

Construction Event Association Associated Name

Construction Notes:

**One of nine rowhouses constructed at the same time.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 9)**

Relate to Street: **Face on Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **3**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☒

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** This three-story, two-bay concrete-block rowhouse was constructed ca. 1979. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf paneled door with a metal security door. A rowlock brick sill and a splayed concrete lintel with keystone highlight the opening. The northwest end bay of the first story holds an aluminum roll-up paneled garage door with lights. A splayed concrete lintel with keystone spans the opening. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows in wood surrounds. These openings are highlighted by splayed concrete lintels with keystones and projecting concrete elements, as well as rowlock brick sills. The rear (northeast) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the northeast side of Pennsylvania Avenue, S.E. The lot is paved with concrete and brick and merges with the public concrete sidewalk fronting the property. The dwelling is adjacent to 1504 Pennsylvania Avenue, S.E. and 1508 Pennsylvania Avenue, S.E. A small yard is located at the rear of the property and is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Concrete Block			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
First Floor	Rectangular	Single	Paneled	Unknown
Vehicular Door	Rectangular		Paneled	Unknown w/Lights
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	Capitol Hill	Historic District(s)
Subdivision:		
Ward/ANC:		
Zoning:		Designation Event(s)
Contributing:		

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\

File: 1506\_PENN\_AVSE.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0830**

## BASICS DATA

ID Number: **1077-0830** Year Built: **c. 1979** Data Source: **DC Real Property Database**

Number Extended Street Quad Type of Address

**1508** **Pennsylvania Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1508 Pennsylvania Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0830** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **c. 1979** **DC Real Pr** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **c. 1979** **DC Real Property Database**

Construction Event Association Associated Name

Construction Notes:

**One of nine rowhouses constructed at the same time.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 9)**  
Relate to Street: **Face on Line**  
Massing: **Row Building/Flat Front**  
Footprint: **Rectangular**

Number Stories: **3**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☒

Cross Reference Notes:

Outbuilding Type Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** This three-story, two-bay concrete-block rowhouse was constructed ca.1979. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf paneled door with a metal security door. A rowlock brick sill and a splayed concrete lintel with keystone highlight the opening. The northwest end bay of the first story holds a wood garage door (likely flip-up) with multiple lights. A splayed concrete lintel with keystone spans the opening. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows in wood surrounds. These openings are highlighted by splayed concrete lintels with keystones and projecting concrete elements, as well as rowlock brick sills. The rear (northeast) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the northeast side of Pennsylvania Avenue, S.E. A concrete walkway leading from the main entrance and a concrete driveway dominate the small front yard. These concrete areas are bordered by small grassy planting areas encircled by scalloped brick planting walls. The walkway and driveway merge with the public concrete sidewalk fronting the property. The dwelling is adjacent to 1506 Pennsylvania Avenue, S.E., and 1510 Pennsylvania Avenue, S.E. A small yard is located at the rear of the property and is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unknown</b>
<b>Vehicular Door</b>	<b>Rectangular</b>			<b>Wood/Glass</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	<b>Capitol Hill</b>	Historic District(s)
Subdivision:		
Ward/ANC:		
Zoning:		Designation Event(s)
Contributing:		

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\

File: 1508\_PENN\_AVSE.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA



# Resource All Data Report

**ID Number: 1077-0818**

## BASICS DATA

ID Number: **1077-0818** Year Built: **c. 1979** Data Source: **DC Real Property Database**

Number Extended Street Quad Type of Address

**1510** **Pennsylvania Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1510 Pennsylvania Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0818** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **c. 1979** **DC Real Pr** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **c. 1979** **DC Real Property Database**

Construction Event Association Associated Name

Construction Notes:

**One of nine rowhouses constructed at the same time.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 9)**

Relate to Street: **Face on Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **3**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☒

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** This three-story, two-bay concrete-block rowhouse was constructed ca. 1979. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf leaded glass wood door with a storm door. A rowlock brick sill and a splayed concrete lintel with keystone highlight the opening. The northwest end bay of the first story previously held a garage door but has been infilled with stone. Two 1/1, double-hung vinyl sliding-sash windows sit at clerestory level. A splayed concrete lintel with keystone spans the opening. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows in wood surrounds. These openings are highlighted by splayed concrete lintels with keystones and rowlock brick sills. The rear (northeast) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the northeast side of Pennsylvania Avenue, S.E. A small, raised brick yard fronts the property. An inset brick walkway leads from the front entrance to the public concrete sidewalk. A concrete driveway leads from the garage opening to the street. The dwelling is adjacent to 1508 Pennsylvania Avenue, S.E., and 1512 Pennsylvania Avenue, S.E. A small yard is located at the rear of the property and is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>1 Flr Windows</b>	<b>Rectangular</b>	<b>Sliding</b>	<b>1</b>	<b>Unknown</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Unknown</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1510\_PENN\_AVSE.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0822**

## BASICS DATA

ID Number: **1077-0822** Year Built: **c. 1979** Data Source: **DC Real Property Database**

Number Extended Street Quad Type of Address

**1512** **Pennsylvania Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1512 Pennsylvania Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0822** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **c. 1979** **DC Real Pr** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **c. 1979** **DC Real Property Database**

Construction Event Association Associated Name

Construction Notes:

**One of nine rowhouses constructed at the same time.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 9)**

Relate to Street: **Face on Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **3**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☒

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** This three-story, two-bay concrete-block rowhouse was constructed ca. 1979. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a painted corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf wood door with inset leaded-glass oval and a storm door. A rowlock brick sill and a splayed concrete lintel with keystone highlight the opening. The northwest end bay of the first story holds a wood garage door (likely flip-up) with multiple lights. A splayed concrete lintel with keystone spans the opening. The façade is fenestrated with 1/1, double-hung windows in wood surrounds. These openings are highlighted by splayed concrete lintels with keystones and rowlock brick sills, as well as inoperable paneled shutters. The rear (northeast) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the northeast side of Pennsylvania Avenue, S.E. A small, raised, flat brick and dirt-filled yard fronts the property. An inset brick walkway leads from the front entrance to the public concrete sidewalk. A low brick retaining wall encircles the raised yard and a concrete driveway leads from the garage opening to the street. The dwelling is adjacent to 1510 Pennsylvania Avenue, S.E., and 1514 Pennsylvania Avenue, S.E. A small yard is located at the rear of the property and is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Unknown</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Wood/Glass</b>
<b>Vehicular Door</b>	<b>Rectangular</b>			<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1512\_PENN\_AVSE.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0836**

## BASICS DATA

ID Number: **1077-0836** Year Built: **c. 1979** Data Source: **DC Real Property Database**

Number Extended Street Quad Type of Address

**1514** **Pennsylvania Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1514 Pennsylvania Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0836** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **c. 1979** **DC Real Pr** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **c. 1979** **DC Real Property Database**

Construction Event Association Associated Name

Construction Notes:

**One of nine rowhouses constructed at the same time.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 9)**  
Relate to Street: **Face on Line**  
Massing: **Row Building/Flat Front**  
Footprint: **Rectangular**

Number Stories: **3**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☒

Cross Reference Notes:

Outbuilding Type Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** This three-story, two-bay concrete-block rowhouse was constructed ca. 1979. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf paneled door with a metal security door. A rowlock brick sill and a splayed concrete lintel with keystone highlight the opening. The northwest end bay of the first story holds a wood garage door (likely flip-up) with multiple lights. A splayed concrete lintel with keystone spans the opening. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows in wood surrounds. These openings are highlighted by splayed concrete lintels with keystones and rowlock brick sills. The rear (northeast) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the northeast side of Pennsylvania Avenue, S.E. A concrete walkway leading from the main entrance and a concrete driveway dominate the small front yard. These concrete areas are bordered by small grassy planting areas encircled by scalloped brick planting walls. The walkway and driveway merge with the public concrete sidewalk fronting the property. The dwelling is adjacent to 1512 Pennsylvania Avenue, S.E., and 1516 Pennsylvania Avenue, S.E. A small yard is located at the rear of the property and is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unknown</b>
<b>Vehicular Door</b>	<b>Rectangular</b>			<b>Wood/Glass</b>

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	<b>Capitol Hill</b>	Historic District(s)
Subdivision:		
Ward/ANC:		
Zoning:		Designation Event(s)
Contributing:		



Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\

File: 1514\_PENN\_AVSE.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0826**

## BASICS DATA

ID Number: **1077-0826** Year Built: **c. 1979** Data Source: **DC Real Property Database**

Number	Extended	Street	Quad	Type of Address
<b>1516</b>		<b>Pennsylvania Avenue</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 1516 Pennsylvania Avenue, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1077/0826</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Not Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>c. 1979</b>	<b>DC Real Pr</b>			

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>c. 1979</b>	<b>DC Real Property Database</b>			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 9)**  
Relate to Street: **Face on Line**  
Massing: **Row Building/Flat Front**  
Footprint: **Rectangular**

Number Stories: **3**  
Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☒

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** This three-story, two-bay concrete-block rowhouse was constructed ca. 1979. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick that has been painted. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf paneled door with inset half-circle light and a metal security door. A rowlock brick sill and a splayed concrete lintel with keystone highlight the opening. The northwest end bay of the first story holds a wood garage door (likely inoperable) with two 1/1, double-hung, vinyl sliding-sash windows. A splayed concrete lintel with keystone spans the opening. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows in wood surrounds. These openings are highlighted by splayed concrete lintels with keystones and rowlock brick sills. The rear (northeast) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the northeast side of Pennsylvania Avenue, S.E. A concrete driveway dominates the small front yard and sits beside a small raised brick yard. The driveway merges with the public concrete sidewalk fronting the property. The dwelling is adjacent to 1514 Pennsylvania Avenue, S.E., and 1518 Pennsylvania Avenue, S.E. A small yard is located at the rear of the property and is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>1 Flr Windows</b>	<b>Rectangular</b>	<b>Sliding</b>	<b>1</b>	<b>Vinyl</b>
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unkown w/Lights</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood:	<b>Capitol Hill</b>	Historic District(s)
Subdivision:		
Ward/ANC:		
Zoning:		Designation Event(s)
Contributing:		

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\

File: 1516\_PENN\_AVSE.JPG

Date:: Photog:

Code:: R: Fr:



## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0834**

## BASICS DATA

ID Number: **1077-0834** Year Built: **c. 1979** Data Source: **DC Real Property Database**

Number Extended Street Quad Type of Address

**1518** **Pennsylvania Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1518 Pennsylvania Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0834** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **c. 1979** **DC Real Pr** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **c. 1979**

Construction Event Association Associated Name

Construction Notes:

**One of nine rowhouses constructed at the same time.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 9)**

Relate to Street: **Face on Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **3**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☒

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

## Exterior &amp; Architectural Notes:

**February 2008:** This three-story, two-bay concrete-block rowhouse was constructed ca. 1979. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf paneled door with a metal security door. A rowlock brick sill and a splayed concrete lintel with keystone highlight the opening. The northwest end bay of the first story holds a wood garage door (likely flip-up) with multiple lights. A splayed concrete lintel with keystone spans the opening. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows in wood surrounds. These openings are highlighted by splayed concrete lintels with keystones and rowlock brick sills. The rear (northeast) elevation was not surveyed or photographed by the volunteer surveyor.

## Site Notes:

**February 2008:** This rowhouse is located on the northeast side of Pennsylvania Avenue, S.E. A concrete driveway and concrete walkway dominate the small front yard. These are bordered by small grassy areas for planting. The driveway and walkway merge with the public concrete sidewalk fronting the property. The dwelling is adjacent to 1516 Pennsylvania Avenue, S.E., and 1520 Pennsylvania Avenue, S.E. A small yard is located at the rear of the property and is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

## Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unknown</b>
<b>Vehicular Door</b>	<b>Rectangular</b>			<b>Wood/Glass</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

## Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill Southeast Phase I (2009/2010)**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**

File: **1518\_PENN\_AVSE.JPG**

Date:: Photog:

Code:: R: Fr:



### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0838**

## BASICS DATA

ID Number: **1077-0838** Year Built: **c. 1979** Data Source: **DC Real Property Database**

Number	Extended	Street	Quad	Type of Address
<b>1520</b>		<b>Pennsylvania Avenue</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 1520 Pennsylvania Avenue, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1077/0838</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Not Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>c. 1979</b>	<b>DC Real Pr</b>			

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>c. 1979</b>	<b>DC Real Property Database</b>			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

**One of nine rowhouses constructed at the same time.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 9)**  
Relate to Street: **Face on Line**  
Massing: **Row Building/Flat Front**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **3**  
Bays Wide: **3**

Height:	Outbuilding Type	Contributing Status
---------	------------------	---------------------

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☒

Outbuilding Notes:



## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** This three-story, three-bay concrete-block rowhouse was constructed ca. 1979. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The material of the flat roof was not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf paneled door with a metal security door. A rowlock brick sill and a splayed concrete lintel with keystone and projecting concrete elements highlight the opening. The central bay of the first story holds a wood garage door (likely flip-up) with multiple lights. A splayed concrete lintel with keystone and projecting concrete elements spans the opening. A semi-circular breezeway with a rowlock brick arch is located in the northwestern end bay. This opening holds a metal security door and provides access to the buildings at the rear of the property (1512 rear, 1514 rear, and 1518 rear Pennsylvania Avenue, S.E.). The façade is fenestrated with 1/1, double-hung, vinyl-sash windows in wood surrounds. These openings are highlighted by splayed concrete lintels with keystones and rowlock brick sills. The rear (northeast) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the northeast side of Pennsylvania Avenue, S.E. Concrete walkways leading from the main entrance and breezeway as well as a concrete driveway, bordered by a small dirt-filled area for planting, dominate the small front yard. The walkways and driveway merge with the public concrete sidewalk fronting the property. The dwelling is adjacent to 1518 Pennsylvania Avenue, S.E. and 1522 Pennsylvania Avenue, S.E. A small yard is located at the rear of the property and is enclosed by a wood privacy fence.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		Stretcher Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Concrete Block			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single	Paneled	Unknown
Vehicular Door	Rectangular			Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Historic District(s)

Subdivision:

Ward/ANCO:

WPAU/ANC.

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\

File: 1520\_PENN\_AVSE.JPG

Date:: Photog:

Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

## PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

## BIBLIOGRAPHIC DATA

## SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

## DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0839**

## BASICS DATA

ID Number: **1077-0839** Year Built: **c. 1980** Data Source: **Site Visit/Map**

Number Extended Street Quad Type of Address

**1522** **Pennsylvania Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1522 Pennsylvania Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0839** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **c. 1980** **Site Visit/** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **c. 1980** **Site Visit/Maps**

Construction Event Association Associated Name

Construction Notes:

**One of five rowhouses constructed at the same time.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 5)**

Relate to Street: **Face on Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **3**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Friday, August 30, 2013

DC HPO Survey - SouthEast Phase 1

ID\_Number: 1077-0839 Page 1

## Exterior &amp; Architectural Notes:

**February 2008:** This three-story, two-bay single-family concrete-block dwelling was constructed ca. 1980. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf paneled door with inset half-circle light and a metal security door. A rowlock brick sill and a splayed concrete lintel with keystone and projecting concrete elements highlight the opening. All other openings on the façade hold 1/1, double-hung, vinyl-sash windows ornamented with splayed concrete lintels with keystones and rowlock brick sills. The rear (northeast) elevation was not surveyed or photographed by the volunteer surveyor.

## Site Notes:

**February 2008:** This rowhouse is located on the northeast side of Pennsylvania Avenue, S.E. A small, grassy yard fronts the dwelling. A concrete walkway leads from the front entrance to the public sidewalk fronting the property. The dwelling is adjacent to 1520 Pennsylvania Avenue, S.E. and 1524 Pennsylvania Avenue, S.E. An alley and concrete driveway are located at the rear of the property.

**NOTABLE FEATURES DATA**

---

Component	Feature
-----------	---------

---

**EXTERIOR MATERIALS DATA**

---

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

## Materials Notes:

--

**WINDOW/DOOR/INTERIOR DATA**

---

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unkown w/Lights</b>

Notable Interior Plan(s)

---

Notable Interior Feature(s)

---

## Interior Notes:

--

**PLAN/SURVEY/DESIGNATION DATA**

---

Neighborhood: **Capitol Hill**Historic District(s)

---

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

---

Contributing:

Survey(s)

---

Level(s) of Investigation

---

**Capitol Hill Southeast Phase I (2009/2010)****Permit Research**

**PHOTOS - DIGITIZED**

---

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1522\_PENN\_AVSE.JPG

Date:: Photog:

Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

Code Criteria

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 1077-0825**

## BASICS DATA

ID Number: **1077-0825** Year Built: **c. 1980** Data Source: **Site Visit/Map**

Number Extended Street Quad Type of Address

**1524** **Pennsylvania Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1524 Pennsylvania Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0825** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **c. 1980** **Site Visit/** **Historic**  
**Office** **DC Real Pr** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **c. 1980** **Site**  
**Visit/Maps**

Construction Event Association Associated Name

Construction Notes:

**One of five rowhouses constructed at the same time.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 5)**

Relate to Street: **Face on Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **3**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** This three-story, two-bay concrete-block rowhouse was constructed ca. 1980. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. It has been converted to serve as an office space for the Metropolitan Police Department Labor Committee, a division of the Fraternal Order of Police. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf paneled door with multiple lights. A rowlock brick sill and a splayed concrete lintel with keystone and projecting concrete elements highlight the opening. All other openings on the façade hold 1/1, double-hung, vinyl-sash windows ornamented with splayed concrete lintels with keystones and rowlock brick sills. The rear (northeast) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the northeast side of Pennsylvania Avenue, S.E. A small, grassy yard with foundation plantings fronts the dwelling. A concrete walkway leads from the front entrance to the public sidewalk fronting the property. The dwelling is adjacent to 1522 Pennsylvania Avenue, S.E. and 1526 Pennsylvania Avenue, S.E. An alley and concrete driveway are located at the rear of the property.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unkown w/Lights</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill Southeast Phase I (2009/2010)**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**

File: **1524\_PENN\_AVSE.JPG**

Date:: Photog:

Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA



# Resource All Data Report

**ID Number: 1077-0832**

## BASICS DATA

ID Number: **1077-0832** Year Built: **c. 1980** Data Source: **Site Visit/Map**

Number Extended Street Quad Type of Address

**1526** **Pennsylvania Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1526 Pennsylvania Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0832** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **c. 1980** **Site Visit/** **Historic**  
**Office** **DC Real Pr** **Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **c. 1980** **Site**  
**Visit/Maps**

Construction Event Association Associated Name

Construction Notes:

**One of five rowhouses constructed at the same time.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 5)**

Relate to Street: **Face on Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **3**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** This three-story, two-bay concrete-block rowhouse was constructed ca. 1980. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. It has been converted to serve as office space for the organization Jobs for Homeless People (JHP), Inc. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf paneled door with a metal security door. A rowlock brick sill and a splayed concrete lintel with keystone and projecting concrete elements highlight the opening. All other openings on the façade hold 6/6, double-hung windows ornamented with splayed concrete lintels with keystones and rowlock brick sills. The rear (northeast) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

**February 2008:** This rowhouse is located on the northeast side of Pennsylvania Avenue, S.E. A small, grassy yard fronts the dwelling. A concrete walkway leads from the front entrance to the public sidewalk fronting the property. The dwelling is adjacent to 1524 Pennsylvania Avenue, S.E. and 1528 Pennsylvania Avenue, S.E. An alley and concrete driveway are located at the rear of the property.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>6/6</b>	<b>Unknown</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unknown</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill Southeast Phase I (2009/2010)**

Level(s) of Investigation  
**Permit Research**  
**Volunteer Reconnaissance Survey**

### PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**

File: **1526\_PENN\_AVESE v2.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**

File: **1526\_PENN\_AVSE v1.JPG**

Date:: Photog:

Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

--

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

--

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------



# Resource All Data Report

**ID Number: 1077-0827**

## BASICS DATA

ID Number: **1077-0827** Year Built: **c. 1980** Data Source: **Site Visit/Map**

Number Extended Street Quad Type of Address

**1528** **Pennsylvania Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1528 Pennsylvania Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0827** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **c. 1980** **Site Visit/** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **c. 1980** **Site Visit/Maps**

Construction Event Association Associated Name

Construction Notes:

**One of five rowhouses constructed at the same time.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 5)**

Relate to Street: **Face on Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **3**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Friday, August 30, 2013

DC HPO Survey - SouthEast Phase 1

ID\_Number: 1077-0827 Page 1

## Exterior &amp; Architectural Notes:

**February 2008:** This three-story, two-bay concrete-block rowhouse was constructed ca. 1980. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf paneled door with a leaded-glass window. A rowlock brick sill and a splayed concrete lintel with keystone and projecting concrete elements highlight the opening. All other openings on the façade hold 6/6, double-hung, vinyl-sash windows ornamented with splayed concrete lintels with keystones and rowlock brick sills. The rear (northeast) elevation was not surveyed or photographed by the volunteer surveyor.

## Site Notes:

**February 2008:** This rowhouse is located on the northeast side of Pennsylvania Avenue, S.E. A small, grassy yard fronts the dwelling. A concrete walkway leads from the front entrance to the public sidewalk fronting the property. The dwelling is adjacent to 1526 Pennsylvania Avenue, S.E. and 1530 Pennsylvania Avenue, S.E. An alley and concrete driveway are located at the rear of the property.

**NOTABLE FEATURES DATA**

---

Component	Feature
-----------	---------

---

**EXTERIOR MATERIALS DATA**

---

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

## Materials Notes:

--

**WINDOW/DOOR/INTERIOR DATA**

---

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unknown w/Lights</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

---

## Interior Notes:

--

**PLAN/SURVEY/DESIGNATION DATA**

---

Neighborhood: **Capitol Hill**Historic District(s)

---

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

---

Contributing:

Survey(s)

Level(s) of Investigation

---

**Capitol Hill Southeast Phase I (2009/2010)****Permit Research**

**PHOTOS - DIGITIZED**

---

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1528\_PENN\_AVSE.JPG

Date:: Photog:

Code:: R: Fr:

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

---

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

---

Permit Notes:

---

**BIBLIOGRAPHIC DATA**

---

---

**SIGNIFICANCE DATA**

---

Study Unit

Code	Criteria
------	----------

---

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 1077-0833**

## BASICS DATA

ID Number: **1077-0833** Year Built: **c. 1980** Data Source: **Site Visit/Map**

Number Extended Street Quad Type of Address

**1530** **Pennsylvania Avenue** **SE** **Current**

Name(s) Type of Name

**Rowhouse, 1530 Pennsylvania Avenue, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1077/0833** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Not Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **c. 1980** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **c. 1980** **Site Visit/Maps**

Construction Event Association Associated Name

Construction Notes:

**One of five rowhouses constructed at the same time.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 5)**

Relate to Street: **Face on Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **3**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Friday, August 30, 2013

DC HPO Survey - SouthEast Phase 1

ID\_Number: 1077-0833 Page 1



## Exterior &amp; Architectural Notes:

**February 2008:** This three-story, two-bay concrete-block rowhouse was constructed ca. 1980. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf paneled door with metal security door. A rowlock brick sill and a splayed concrete lintel with keystone and projecting concrete elements highlight the opening. All other openings on the façade hold 1/1, double-hung, vinyl-sash windows ornamented with splayed concrete lintels with keystones and rowlock brick sills. The southeast (side) elevation is faced with stucco and the rear (northeast) elevation was not surveyed or photographed by the volunteer surveyor.

## Site Notes:

**February 2008:** This end-unit rowhouse is located on the northeast side of Pennsylvania Avenue, S.E. A small, grassy yard fronts the dwelling. A concrete walkway leads from the front entrance to the public sidewalk fronting the property. The dwelling is adjacent to 1528 Pennsylvania Avenue, S.E., and an asphalt-paved parking lot is located to the southeast. An alley and concrete driveway are located at the rear of the property.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

## Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panel(s)	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unknown</b>

Notable Interior Plan(s)

Notable Interior Feature(s)

## Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase I (2009/2010)****Permit Research**

**PHOTOS - DIGITIZED**

---

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1530\_PENN\_AVSE.JPG

Date:: Photog:

Code:: R: Fr:

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

---

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

Code	Criteria
------	----------

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 1077-0820**

## BASICS DATA

ID Number: **1077-0820** Year Built: **c. 1979** Data Source: **DC Real Property Database**

Number	Extended	Street	Quad	Type of Address
<b>1506</b>	<b>Rear</b>	<b>Pennsylvania Avenue</b>	<b>SE</b>	<b>Current</b>
<b>1503</b>		<b>Freedom Way</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Multiple Dwelling, 1506 Rear Pennsylvania Avenue, S.E.</b>	<b>Common</b>
<b>Multiple Dwelling, 1503 Freedom Way, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1077/0820</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Not Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Multi-Family)</b>	<b>c. 1979</b>	<b>DC Real Pr</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>c. 1979</b>	<b>DC Real Property Database</b>			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

**One of six rowhouses constructed at the same time. Staggered to fit lot on alley.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Row (1 of 6)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Row Building/Flat Front**  
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **3**  
 Bays Wide: **3**

Height:

Outbuilding Type

Contributing Status

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** This three-story, three-bay multiple-family concrete-block dwelling was constructed ca. 1979. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf paneled door with inset half-circle light and metal security door. A rowlock brick sill and a splayed concrete lintel with keystone highlight the opening. All other openings on the façade hold 1/1, double-hung, vinyl-sash windows ornamented with splayed concrete lintels and rowlock brick sills. The rear (northwest) elevation is covered with stucco and the foundation and part of the first story were obscured by the rear fence. The rear elevation fronts Freedom Way, S.E., formerly an alley. This elevation has four bays. The northwestern and southern central bays of the first story hold single-leaf doors with multiple lights and metal security doors. The elevation is fenestrated with 1/1, double-hung, vinyl-sash windows with rowlock brick sills.

Site Notes:

**February 2008:** This multiple dwelling is located behind 1506 Pennsylvania Avenue, S.E. and is adjacent to 1504 (rear) Pennsylvania Avenue, S.E./1501 Freedom Way, S.E. and 1510 (rear) Pennsylvania Avenue, S.E./1505 Freedom Way, S.E. A small, grassy yard fronts the property and a paved driveway, alley, and small yard enclosed by a wood privacy fence are located at the rear of the building.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unkown w/Lights</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill Southeast Phase I (2009/2010)</b>	<b>Permit Research</b>
	<b>Volunteer Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1503&1505\_FREEDOM\_WAYSE front  
view.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1503\_FREEDOM\_WAYSE rear view.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\

File: 1501-11\_FREEDOM\_AVSE rear view.JPG

Date:: Photog:

Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

---

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

Code Criteria

### DATA PROCESSING EVENTS DATA

---

# Resource All Data Report

**ID Number: 1077-0823**

## BASICS DATA

ID Number: **1077-0823** Year Built: **c. 1979** Data Source: **DC Real Property Database**

Number	Extended	Street	Quad	Type of Address
<b>1510</b>	<b>Rear</b>	<b>Pennsylvania Avenue</b>	<b>SE</b>	<b>Current</b>
<b>1505</b>		<b>Freedom Way</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Multiple Dwelling, 1510 Rear Pennsylvania Avenue, S.E.</b>	<b>Common</b>
<b>Multiple Dwelling, 1505 Freedom Way, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1077/0823</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Not Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Multi-Family)</b>	<b>c. 1979</b>	<b>DC Real Pr</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>c. 1979</b>	<b>DC Real Property Database</b>			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

**One of six rowhouses constructed at the same time. Staggered to fit lot on alley.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 6)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Flat Front**  
Footprint: **Rectangular**

Number Stories: **3**  
Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** This three-story, three-bay multiple-family concrete-block dwelling was constructed ca. 1979. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The northwestern end bay of the first story holds a single-leaf paneled door with inset half-circle light and metal security door. A rowlock brick sill and a splayed concrete lintel with keystone highlight the opening. All other openings on the façade hold 1/1, double-hung, vinyl-sash windows ornamented with splayed concrete lintels and rowlock brick sills. The rear (northwest) elevation is covered with stucco and the foundation and part of the first story were obscured by the rear fence. The rear elevation fronts Freedom Way, S.E., formerly an alley. This elevation has two bays. The northwestern bay of the first story holds a single-leaf door with multiple lights and a metal security door. The elevation is fenestrated with 1/1, double-hung, vinyl-sash windows with rowlock brick sills.

Site Notes:

**February 2008:** This rowhouse is located behind 1510 Pennsylvania Avenue, S.E. and is adjacent to 1506 (rear) Pennsylvania Avenue, S.E./ 1503 Freedom Way, S.E. and 1512 (rear) Pennsylvania Avenue, S.E./ 1507 Freedom Way, S.E. A small, grassy yard fronts the property and a paved driveway, alley, and small yard enclosed by a wood privacy fence are located at the rear of the building.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

Materials Notes:



## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>		<b>Unknown</b>
Notable Interior Plan(s)			Notable Interior Feature(s)	

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill Southeast Phase I (2009/2010)</b>	<b>Permit Research</b>
	<b>Volunteer Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1503&1505\_FREEDOM\_WAYSE front  
view.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1503-11\_FREEDOM\_AVSE front view.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1501-11\_FREEDOM\_AVSE rear view.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1505\_FREEDOM\_WAYSE rear view.JPG

Date:: Photog:  
Code:: R: Fr:

#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

#### MISCELLANEOUS NOTES DATA

Notes:

#### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

#### BIBLIOGRAPHIC DATA

#### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

#### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0817**

## BASICS DATA

ID Number: **1077-0817** Year Built: **c. 1979** Data Source: **DC Real Property Database**

Number	Extended	Street	Quad	Type of Address
<b>1512</b>	<b>Rear</b>	<b>Pennsylvania Avenue</b>	<b>SE</b>	<b>Current</b>
<b>1507</b>		<b>Freedom Way</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Multiple Dwelling, 1512 Rear Pennsylvania Avenue, S.E.</b>	<b>Common</b>
<b>Multiple Dwelling, 1507 Freedom Way, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1077/0817</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Not Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Multi-Family)</b>	<b>c. 1979</b>	<b>DC Real Pr</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>c. 1979</b>	<b>DC Real Property Database</b>			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

**One of six rowhouses constructed at the same time. Staggered to fit lot on alley.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 6)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Flat Front**  
Footprint: **Rectangular**

Number Stories: **3**  
Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** This three-story, three-bay multiple-family concrete-block dwelling was constructed ca. 1979. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The southeastern end bay of the first story holds a single-leaf paneled door with a metal security door. A rowlock brick sill and a splayed concrete lintel with keystone highlight the opening. All other openings on the façade hold 1/1, double-hung, vinyl-sash windows ornamented with splayed concrete lintels and rowlock brick sills. The rear (northwest) elevation is covered with stucco and the foundation and part of the first story were obscured by the rear fence. The rear elevation fronts Freedom Way, S.E., formerly an alley. This elevation has four bays. The northwestern and southern central bays of the first story hold single-leaf wood doors with multiple lights and metal security doors. The elevation is fenestrated with 1/1, double-hung, vinyl-sash windows with rowlock brick sills.

Site Notes:

**February 2008:** This rowhouse is located behind 1512 Pennsylvania Avenue, S.E. and is adjacent to 1510 (rear) Pennsylvania Avenue, S.E./ 1505 Freedom Way, S.E. and 1514 (rear) Pennsylvania Avenue, S.E./ 1509 Freedom Way, S.E. A small, grassy yard fronts the property and a paved driveway, alley, and small yard enclosed by a wood privacy fence are located at the rear of the building.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unknown</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill Southeast Phase I (2009/2010)</b>	<b>Permit Research</b>
	<b>Volunteer Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1507\_FreedomWaySE front view.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1507\_FREEDOM\_WAYSE rear view.JPG  
Date:: Photog:  
Code:: R: Fr:

## PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

## MISCELLANEOUS NOTES DATA

Notes:

--

### PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

---

Permit Notes:

--

### BIBLIOGRAPHIC DATA

---

### SIGNIFICANCE DATA

---

Study Unit \_\_\_\_\_

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

---

# Resource All Data Report

**ID Number: 1077-0837**

## BASICS DATA

ID Number: **1077-0837** Year Built: **c. 1979** Data Source: **DC Real Property Database**

Number	Extended	Street	Quad	Type of Address
<b>1514</b>	<b>Rear</b>	<b>Pennsylvania Avenue</b>	<b>SE</b>	<b>Current</b>
<b>1509</b>		<b>Freedom Way</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Multiple Dwelling, 1514 Rear Pennsylvania Avenue, S.E.</b>	<b>Common</b>
<b>Multiple Dwelling, 1509 Freedom Way, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1077/0837</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Not Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Multi-Family)</b>	<b>c. 1979</b>	<b>DC Real Pr</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>c. 1979</b>	<b>DC Real Property Database</b>			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

**One of six similar rowhouses constructed at the same time. Staggered to fit lot on alley.**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 6)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Flat Front**  
Footprint: **Rectangular**

Number Stories: **3**  
Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** This three-story, three-bay multiple-family concrete-block dwelling was constructed ca. 1979. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The northwestern end bay of the first story holds a single-leaf paneled door with a metal security door. A rowlock brick sill and a splayed concrete lintel with keystone highlight the opening. All other openings on the façade hold 1/1, double-hung, vinyl-sash windows ornamented with splayed concrete lintels and rowlock brick sills. The rear (northwest) elevation is covered with stucco and the foundation and part of the first story were obscured by the rear fence. The rear elevation fronts Freedom Way, S.E., formerly an alley. This elevation has two bays. The northwestern bay of the first story holds a single-leaf paneled door and a metal security door. The elevation is fenestrated with 1/1, double-hung, vinyl-sash windows with rowlock brick sills.

Site Notes:

**February 2008:** This rowhouse is located behind 1514 Pennsylvania Avenue, S.E. and is adjacent to 1512 (rear) Pennsylvania Avenue, S.E./ 1507 Freedom Way, S.E. and 1516 (rear) Pennsylvania Avenue, S.E./ 1511 Freedom Way, S.E. A small, grassy yard fronts the property and a paved driveway, alley, and small yard enclosed by a wood privacy fence are located at the rear of the building.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA



Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>Paneled</b>	<b>Unknown</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill Southeast Phase I (2009/2010)</b>	<b>Permit Research</b>
	<b>Volunteer Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**  
File: **1507-11\_FreedomWaySE front view.JPG**  
Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: **C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\**  
File: **1509\_FreedomWaySE 1st floor front view.JPG**  
Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1509\_FreedomWaySE 2nd & 3rd floors.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1509\_FREEDOM\_WAYSE rear view.JPG

Date:: Photog:  
Code:: R: Fr:

---

#### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

---

#### MISCELLANEOUS NOTES DATA

Notes:

---

#### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

---

Permit Notes:

---

#### BIBLIOGRAPHIC DATA

---

#### SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

---

---

#### DATA PROCESSING EVENTS DATA

# Resource All Data Report

**ID Number: 1077-0821**

## BASICS DATA

ID Number: **1077-0821** Year Built: **c. 1979** Data Source: **DC Real Property Database**

Number	Extended	Street	Quad	Type of Address
1516	Rear	Pennsylvania Avenue	SE	Current
1511		Freedom Way	SE	Current
1518	Rear	Pennsylvania Avenue	SE	Alternate

Name(s)	Type of Name
Multiple Dwelling, 1516 Rear Pennsylvania Avenue, S.E.	Common
Multiple Dwelling, 1511 Freedom Way, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1077/0821			Square/Lot	Current

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Not Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Multi-Family) Office	c. 1979	DC Real Pr Site Visit			Historic/Current Current

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	c. 1979	DC Real Property Database			

Construction Event	Association	Associated Name
--------------------	-------------	-----------------

Construction Notes:

One of six similar rowhouses constructed at the same time. Staggered to fit lot on alley.

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Row End (1 of 6)**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Row Building/Flat Front**  
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **3**

Bays Wide: **3**

Height:

Outbuilding Type

Contributing Status

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Outbuilding Notes:

## STYLE/EXTERIOR DATA

Architectural Style(s)

Exterior & Architectural Notes:

**February 2008:** This three-story, three-bay multiple-family concrete-block dwelling was constructed ca. 1979. It is a modern interpretation of an Italianate-style rowhouse and sits on a solid concrete foundation. The façade (southeast elevation) is faced with stretcher-bond brick. The roofing type and material were not visible from the public right-of-way, but a corbeled brick cornice with brick dentils below spans the façade. The northwestern end bay of the first story holds a single-leaf paneled door with lights and a metal security door. A concrete sill and a splayed concrete lintel with keystone highlight the opening. All other openings on the façade hold 6/6, double-hung, vinyl-sash windows ornamented with splayed concrete lintels and rowlock brick sills. The rear (northwest) elevation is covered with stucco and the foundation and part of the first story were obscured by the rear fence. The rear elevation fronts Freedom Way, S.E., formerly an alley. This elevation has two bays. The northwestern bay of the first story holds a single-leaf door and a metal security door. The elevation is fenestrated with 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins and rowlock brick sills. A wood porch spans the rear elevation on the second story. The porch is supported by square wood posts and has turned wood balusters.

Site Notes:

**February 2008:** This rowhouse is located behind 1516 and 1518 Pennsylvania Avenue, S.E. and is adjacent to 1514 (rear) Pennsylvania Avenue, S.E./ 1509 Freedom Way, S.E. A small, grassy yard fronts the property and a paved driveway, alley, and small yard enclosed by a wood privacy fence are located at the rear of the building.

## NOTABLE FEATURES DATA

Component

Feature

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
<b>Not Visible</b>	<b>Not Visible</b>		<b>Not Visible</b>	
Wall Component	Material	Color	Treatment	Source
<b>Facade</b>	<b>Brick</b>		<b>Stretcher Bond</b>	
Structure Component	Material	Feature		Source
<b>Foundation</b>	<b>Concrete</b>			
<b>Walls</b>	<b>Concrete Block</b>			

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
<b>Facade</b>	<b>Rectangular</b>	<b>Dbl-Hung</b>	<b>1/1</b>	<b>Vinyl</b>
Door Location	Aperture Shape	Type	Panels	Material
<b>Main Door</b>	<b>Rectangular</b>	<b>Single</b>	<b>2-Panel</b>	<b>Unkown w/Lights</b>
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

## PLAN/SURVEY/DESIGNATION DATA

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill Southeast Phase I (2009/2010)</b>	<b>Permit Research</b>
	<b>Volunteer Reconnaissance Survey</b>

## PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1511\_FreedomWaySE 1st floor.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1511\_FreedomWaySE 2nd & 3rd floors.JPG

Date:: Photog:  
Code:: R: Fr:

Caption:

## Undisplayable Image Format

Path: C:\Users\CHRS\Documents\CHRS  
Databases\SE Phase I - D to G  
St\Database\Pictures\Square 1077\  
File: 1511\_FREEDOM\_WAYSE rear view\_formerly  
1518 PaAvSE REAR.JPG

Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

---

### MISCELLANEOUS NOTES DATA

Notes:

---

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

---

Permit Notes:

---

### BIBLIOGRAPHIC DATA

---

### SIGNIFICANCE DATA

Study Unit \_\_\_\_\_

Code	Criteria
------	----------

---

---

### DATA PROCESSING EVENTS DATA

---

