

Resource All Data Report

ID Number: 1079-0024

BASICS DATA

ID Number: **1079-0024** Year Built: **1937** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1000		15th Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1000 15th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1079/0024			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1937	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1937	Permit			4000 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Novak, Sam
Orig Construction	Builder	Brightwood Construction
Orig Construction	Owner	Brightwood Construction

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row End (1 of 3)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Block**
Footprint: **Rectangular**

Number Stories: **2**
Bays Wide: **2**
Height:
Width: **18**
Depth/Length: **32**

SqFt:
Volume:
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type	Contributing Status
------------------	---------------------

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Eclectic)

Exterior & Architectural Notes:

September 2009: Constructed in 1937 by Brightwood Construction Company, this two-story, three-bay Colonial Revival-style rowhouse is an end unit of three similar rowhouses constructed from the same permit (#207102). This masonry structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A belt course of soldier bricks extends above the second-story openings. The roof type and material were not visible from the public right-of-way due to a brick parapet wall. The parapet wall features a false mansard roof of slate shingles set along the façade (west elevation). The roof is set between stepped a stepped parapet wall which extends along the façade and north (side) elevation. The façade is fenestrated with single-leaf wood door located in the southern bay of the first story. Window openings hold paired one-light, vinyl-sash sliding windows with rowlock brick sills. The first story is sheltered by a full-width porch. The porch is set on a brick pier foundation with decorative concrete block infill. The shed roof is supported by brick pillars with twisted metal balusters. A metal awning has been affixed to the front of the porch. A second metal awning shelters the second-story window opening. The north (side) elevation has one-light basement windows in addition to 1/1, double-hung, vinyl-sash windows. The openings feature rowlock brick sills and soldier brick flat arches. The east (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located on a corner lot southeast of the intersection of 15th Street, S.E. and K Street, S.E. This residence has a setback of approximately thirty feet from the concrete sidewalk along 15th Street, S.E. The south (side) elevation is attached to 1002 15th Street, S.E. The raised, grassy yard has mature trees and shrubs, as well as a concrete walkway extending from the primary entry to the sidewalk. The backyard is enclosed by a chain-link fence.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Concrete Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Sliding	1-light Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zone:

Designation Event(s)

Zoning:
Contributing:

Designation Event(s)

Survey(s)
Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation
**Permit Research
Volunteer Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:



Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\
File: 1000_15STSE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\
File: 1000_15STSEa.JPG
Date:: Photog:
Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\
File: 1000_15STSE-NWcorner.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/2/1937	207102	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1079-0023

BASICS DATA

ID Number: **1079-0023** Year Built: **1937** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1002		15th Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1002 15th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1079/0023			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1937	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1937	Permit			4000 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Novak, Sam
Orig Construction	Builder	Brightwood Construction
Orig Construction	Owner	Brightwood Construction

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 3)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Block**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**
Height:
Width: **18**
Depth/Length: **32**

Outbuilding Type	Contributing Status
------------------	---------------------

SqFt:
Volume:
Lot Width:

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Eclectic)

Exterior & Architectural Notes:

September 2009: Constructed in 1937 by Brightwood Construction Company, this two-story, three-bay Colonial Revival-style rowhouse is one of three similar rowhouses constructed from the same permit (#207102). This concrete-block structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A belt course of soldier bricks extends above the second-story opening. The roof type and material were not visible from the public right-of-way due to a brick parapet wall. The parapet wall has six-course, American-bond brick coursing and is crenelated. The façade is fenestrated with single-leaf, paneled wood door located in the northern bay. Paired window openings hold 1/1, double-hung, vinyl-sash windows with rowlock brick sills. The first story is sheltered by a full-width porch. The porch is set on a brick pier foundation with decorative concrete block infill. The shed roof of asphalt shingles is supported by brick pillars with metal balusters. The east (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located east of 15th Street, S.E. and has a setback of approximately thirty feet from the concrete sidewalk. The raised, grassy yard has mature trees and shrubs, as well as a concrete walkway extending from the primary entry to the sidewalk. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Concrete Block			

Materials Notes:

[Empty text box for materials notes]

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision: _____

Ward/ANC: _____

Zoning: _____ Designation Event(s)

Contributing: _____

Survey(s) _____ Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:



Path: C:\Users\CHRS\Documents\CHRS
 Databases\SE Phase I - D to G
 St\Database\Pictures\Square 1079\
 File: 1002_15STSE.JPG
 Date:: Photog:
 Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/2/1937	207102	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1079-0022

BASICS DATA

ID Number: **1079-0022** Year Built: **1937** Data Source: **Permit**

Number Extended Street Quad Type of Address

1004 **15th Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1004 15th Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1079/0022 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1937** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1937** **Permit** **4000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Novak, Sam**

Orig Construction **Builder** **Brightwood Construction**

Orig Construction **Owner** **Brightwood Construction**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 3)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **32**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Eclectic)

Exterior & Architectural Notes:

September 2009: Constructed in 1937 by Brightwood Construction Company, this two-story, three-bay Colonial Revival-style rowhouse is an end unit of three similar rowhouses constructed from the same permit (#207102). This concrete-block structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A belt course of soldier bricks extends above the second-story openings. The roof type and material were not visible from the public right-of-way due to a false mansard set between a stepped parapet wall. The façade is fenestrated with single-leaf wood door with lights located in the northern bay. Paired window openings hold 1/1, double-hung, vinyl-sash windows with rowlock brick sills. The first story is sheltered by a full-width porch. The porch has a shed roof supported by brick pillars with metal balusters. The east (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located east of 15th Street, S.E. and has a setback of approximately thirty feet from the concrete sidewalk. The north (side) elevation is attached to 1002 15th Street, S.E. The raised, grassy yard has mature trees and shrubs, as well as a concrete walkway extending from the primary entry to the sidewalk. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Concrete Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Ward/ANC:

Zoning: Designation Event(s)

Contributing:

Survey(s) Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:



Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\

File: 1004_15STSE.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
10/2/1937	207102	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1079-0044

BASICS DATA

ID Number: **1079-0044** Year Built: **c. 1949** Data Source: **DC Real Property Database**

Number	Extended	Street	Quad	Type of Address
1006		15th Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1006 15th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1079/0044			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	c. 1949	DC Real Pr			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	c. 1949	DC Real Property Database			

Construction Event	Association	Associated Name
Orig Construction	Architect	Unknown
Orig Construction	Builder	Unknown
Orig Construction	Owner	Unknown

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row End (1 of 3)**
 Relate to Street: **Face on Setback Line**
 Massing: **Block**
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
 Bays Wide: **2**

Height:	Outbuilding Type	Contributing Status
---------	------------------	---------------------

Width:
 Depth/Length:

SqFt:
 Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Colonial)

Exterior & Architectural Notes:

February 2009: Constructed c. 1949, this two-story, two-bay rowhouse shows influences from the Colonial Revival and Classical Revival styles. The house is an end unit of three similar rowhouses constructed along 15th Street, S.E. This masonry structure is set on a solid foundation; both faced with six-course, American-bond brick. The roof type and material were not visible from the public right-of-way. A shallow boxed cornice and plain frieze highlight the façade (west elevation). The façade has a single-leaf entry (door materials not visible) with a metal storm door located in the southern bay of the first story. A one-story, one-bay porch shelters the opening. The porch has a metal awning supported by metal filigree posts. The northern bay contains a three-sided, canted bay window with diamond-light muntins on both the first and second stories. These openings have a rowlock brick sill, fluted pilasters, and an ogee-molded denticulated cornice with a keystone. The second story has a narrow, 1/1, double-hung, vinyl-sash window located in the southernmost bay. The opening is set in an elaborate denticulated surround composed of a rinceau-molded sill and denticulated cornice with keystone. The north (side) elevation has multiple window openings (not surveyed by volunteer surveyor). The east (rear) elevation was not surveyed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located east of 15th Street, S.E. and has a setback of approximately thirty feet from the concrete sidewalk. The south (side) elevation is attached to 1008 15th Street, S.E. The raised, grassy yard has been landscaped with immature plantings, mature shrubs, and a brick retaining wall with milled-point fence. A brick walkway extends from the primary entry to the sidewalk. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature	Source	
Foundation	Unknown			
Walls	Unknown			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	DbI-Hung	1/1	Vinyl
Facade	Rectangular	Casement	diamond	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown
Notable Interior Plan(s)			Notable Interior Feature(s)	

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill Southeast Phase I (2009/2010)	Permit Research Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS Databases\SE Phase I - D to G St\Database\Pictures\Square 1079**
 File: **1006-10_15STSE.JPG**
 Date:: Photog:
 Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS Databases\SE Phase I - D to G St\Database\Pictures\Square 1079**
 File: **1006_15STSE.JPG**
 Date:: Photog:
 Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1079-0043

BASICS DATA

ID Number: **1079-0043** Year Built: **c. 1949** Data Source: **DC Real Property Database**

Number	Extended	Street	Quad	Type of Address
1008		15th Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1008 15th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1079/0043			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	c. 1949	DC Real Pr			

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	c. 1949	DC Real Property Database			

Construction Event	Association	Associated Name
Orig Construction	Architect	Unknown
Orig Construction	Builder	Unknown
Orig Construction	Owner	Unknown

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row (1 of 3)**
 Relate to Street: **Face on Setback Line**
 Massing: **Block**
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
 Bays Wide: **2**

	Contributing Status
Height:	Outbuilding Type

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Colonial)

Exterior & Architectural Notes:

February 2009: Constructed c. 1949, this two-story, two-bay rowhouse shows influences from the Colonial Revival and Classical Revival styles. The house is one of three similar rowhouses constructed along 15th Street, S.E. This masonry structure is set on a solid foundation; both faced with six-course, American-bond brick. The roof type and material were not visible from the public right-of-way. A shallow boxed cornice and plain frieze highlight the façade (west elevation). The façade has a single-leaf entry (material not visible) with a metal storm door located in the southern bay of the first story. A one-story, one-bay porch shelters the opening. The porch has a metal awning supported by metal posts. The northern bay contains paired one-light, vinyl-sash sliding windows on both the first and second stories. These openings have a rowlock brick sill, fluted pilasters, and an ogee-molded denticulated cornice with keystone. The second story has a narrow, 1/1, double-hung, vinyl-sash window in the southernmost bay. The opening is set in an elaborate denticulated surround composed of a rinceau-molded sill and denticulated cornice with keystone. The east (rear) elevation was not surveyed or photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located east of 15th Street, S.E. and has a setback of approximately thirty feet from the concrete sidewalk. The north (side) elevation is attached to 1006 15th Street, S.E. and the south (side) elevation to 1010 15th Street, S.E. The raised, grassy yard has been landscaped with immature plantings and a brick retaining wall with milled-point fence. A brick walkway extends from the primary entry to the sidewalk. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component	Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible				

Not Visible

Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	

Structure Component	Material	Feature	Source
Foundation	Unknown		
Walls	Unknown		

Foundation **Unknown**

Walls **Unknown**

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Facade	Rectangular	Sliding	1-light Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown
Notable Interior Plan(s)		Notable Interior Feature(s)		

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill Southeast Phase I (2009/2010)	Permit Research Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:



Path: C:\Users\CHRS\Documents\CHRS Databases\SE Phase I - D to G St\Database\Pictures\Square 1079\
 File: 1008_15STSE.JPG
 Date:: Photog:
 Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS Databases\SE Phase I - D to G St\Database\Pictures\Square 1079\
 File: 1006-10_15STSE.JPG
 Date:: Photog:
 Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1079-0042

BASICS DATA

ID Number: **1079-0042** Year Built: **c. 1949** Data Source: **DC Real Property Database**

Number	Extended	Street	Quad	Type of Address
1010		15th Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1010 15th Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1079/0042			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	c. 1949	DC Real Pr			

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	c. 1949	DC Real Property Database			

Construction Event	Association	Associated Name
Orig Construction	Architect	Unknown
Orig Construction	Builder	Unknown
Orig Construction	Owner	Unknown

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
 Streetscape: **Intact**
 Relate to Othr Bldgs: **Row End (1 of 3)**
 Relate to Street: **Face on Setback Line**
 Massing: **Block**
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
 Bays Wide: **2**

Height: Outbuilding Type Contributing Status

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Colonial)

Exterior & Architectural Notes:

February 2009: Constructed c. 1949, this two-story, two-bay rowhouse shows influences from the Colonial Revival and Classical Revival styles. The house is an end unit of three similar rowhouses constructed along 15th Street, S.E. This masonry structure is set on a solid foundation; both faced with six-course, American-bond brick. The roof type and material were not visible from the public right-of-way. A shallow boxed cornice and plain frieze highlight the façade (west elevation). The façade has a single-leaf, paneled wood door located in the northern bay of the first story. The entry has an elaborate surround composed of fluted pilasters, an ogee-molded denticulated cornice with keystone, and a plain frieze. The southern bay contains paired 1/1, double-hung, vinyl-sash windows. The northernmost bay of the second story holds paired one-light vinyl sliding windows. The window openings in the northern bays have rowlock brick sills, fluted pilasters, and an ogee-molded denticulated cornice with keystone. The southernmost bay of the second story holds a narrow, 1/1, double-hung, vinyl-sash window set in an elaborate denticulated surround composed of a rinceau-molded sill and denticulated cornice with keystone. The south (side) elevation is pierced by a 1/1, double-hung, vinyl-sash window and a paired, one-light, vinyl-sash sliding window; both with header brick sills. The second story has tripartite windows with rowlock brick sills. The east (rear) elevation was not surveyed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located east of 15th Street, S.E. and has a setback of approximately thirty feet from the concrete sidewalk. The north (side) elevation is attached to 1006 15th Street, S.E. The south (side) elevation fronts a paved alley. The raised, grassy yard has been landscaped with immature trees and a milled-point fence. A concrete walkway extends from the primary entry to the sidewalk. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component	Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Unknown			
Walls	Unknown			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Sliding	1-light Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s) _____

Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s) _____

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s) _____

Contributing:

Survey(s) _____

Level(s) of Investigation _____

Capitol Hill Southeast Phase I (2009/2010)

**Permit Research
Volunteer Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:



Path: C:\Users\CHRS\Documents\CHRS Databases\SE Phase I - D to G St\Database\Pictures\Square 1079\

File: 1010_15STSE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS Databases\SE Phase I - D to G St\Database\Pictures\Square 1079\

File: 1010_15STSE_SEcorner.JPG

Date:: Photog:

Code:: R: Fr:

Caption:



Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\

File: 1006-10_15STSE.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1079-0028

BASICS DATA

ID Number: **1079-0028** Year Built: **1949** Data Source: **Permit**

Number Extended Street Quad Type of Address

1503 **K Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1503 K Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1079/0028 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1949** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1949** **Permit** **5357 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Miller, Joseph**

Orig Construction **Builder** **Libby, Bernard**

Orig Construction **Owner** **Libby, Bernard**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 14)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2009: Constructed in 1949 by owner/builder Bernard Libby, this two-story, two-bay rowhouse is an end unit of fourteen similar rowhouses designed by architect Joseph Miller. These rowhouses are illustrations of the Modern Movement and were constructed from the same permit (#322179). This hollow block structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A sloping roof caps the building and has overhanging boxed eaves. Fenestration of the façade consists of a single-leaf, paneled wood door located in the western bay. The eastern bay of both stories hold a tripartite window composed of a single-light fixed window flanked by one-light vinyl casements. The westernmost bay of the second story holds a 1/1, double-hung, vinyl-sash window. All of the window openings have rowlock brick sills. The west (side) elevation has no fenestration. The south (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located south of K Street, S.E. and set back from the concrete sidewalk approximately twenty feet. The east (side) elevation is attached to 1505 K Street, S.E. The small front yard is enclosed by a milled-point metal fence. A concrete walkway extends from the primary entry to the sidewalk. The grassy side yard has chain-link fencing while the backyard is enclosed by a wooden privacy fence. Mature trees and shrubs dot the property, which extends south to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Hollow Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	DbI-Hung	1/1	Vinyl
Facade	Rectangular	Casement	1	Vinyl
Facade	Rectangular	Fixed	1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research
Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\

File: 1503&05_KSTSE.JPG

Date:: Photog:

Code:: R: Fr:




Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\

File: 1503_KSTSE-Wside.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\

File: 1503-29_KSTSE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

[Empty text box for notes]

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
8/31/1949	322179	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1079-0029

BASICS DATA

ID Number: **1079-0029** Year Built: **1949** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1505		K Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1505 K Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1079/0029			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1949	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1949	Permit			5357 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Miller, Joseph
Orig Construction	Builder	Libby, Bernard
Orig Construction	Owner	Libby, Bernard

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 14)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Block**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**

Height:	Outbuilding Type	Contributing Status
---------	------------------	---------------------

Width:
Depth/Length:
SqFt:

Volume:
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2009: Constructed in 1949 by owner/builder Bernard Libby, this two-story, two-bay rowhouse is one of fourteen similar rowhouses designed by architect Joseph Miller. These rowhouses are illustrations of the Modern Movement and were constructed from the same permit (#322179). This hollow block structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A sloping roof caps the building and has overhanging boxed eaves. Fenestration of the façade consists of a single-leaf, paneled wood door and tripartite windows composed of a single-light fixed window flanked by one-light vinyl casements with rowlock brick sills. The south (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located south of K Street, S.E. and set back from the concrete sidewalk approximately twenty feet. The west (side) elevation is attached to 1503 K Street, S.E. and the east (side) elevation to 1507 K Street, S.E. The grassy front yard is enclosed by a milled-point metal fence and includes immature shrubs. A concrete walkway extends from the primary entry to the sidewalk. The property extends south to a paved alley. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Hollow Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Casement	1	Vinyl
Facade	Rectangular	Fixed	1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)
Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation
**Permit Research
Volunteer Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079**

File: **1505 K SE.JPG**

Date:: Photog:
Code:: R: Fr:

Caption:



Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079**

File: **1503-29_KSTSE.JPG**

Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
8/31/1949	322179	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

Resource All Data Report

ID Number: 1079-0030

BASICS DATA

ID Number: **1079-0030** Year Built: **1949** Data Source: **Permit**

Number Extended Street Quad Type of Address

1507 **K Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1507 K Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1079/0030 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1949** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1949** **Permit** **5357 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Miller, Joseph**

Orig Construction **Builder** **Libby, Bernard**

Orig Construction **Owner** **Libby, Bernard**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 14)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2009: Constructed in 1949 by owner/builder Bernard Libby, this two-story, two-bay rowhouse is one of fourteen similar rowhouses designed by architect Joseph Miller. These rowhouses are illustrations of the Modern Movement and were constructed from the same permit (#322179). This hollow block structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A sloping roof caps the building and has overhanging boxed eaves. Fenestration of the façade consists of a single-leaf, paneled wood door and tripartite windows composed of a single-light fixed window flanked by one-light vinyl casements with rowlock brick sills. Metal awnings shelter the door and window openings. The south (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located south of K Street, S.E. and set back from the concrete sidewalk approximately twenty feet. The west (side) elevation is attached to 1505 K Street, S.E. and the east (side) elevation to 1509 K Street, S.E. The grassy front yard is enclosed by a milled-point metal fence and has a concrete walkway extending from the primary entry to the sidewalk. The property extends south to a paved alley. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Hollow Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Casement	1	Vinyl
Facade	Rectangular	Fixed	1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\

File: 1507_KSTSE.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\

File: 1503-29_KSTSE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
8/31/1949	322179	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

Resource All Data Report

ID Number: 1079-0031

BASICS DATA

ID Number: **1079-0031** Year Built: **1949** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1509		K Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1509 K Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1079/0031			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1949	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1949	Permit			5357 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Miller, Joseph
Orig Construction	Builder	Libby, Bernard
Orig Construction	Owner	Libby, Bernard

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 14)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Block**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**

Height:	Outbuilding Type	Contributing Status
---------	------------------	---------------------

Width:
Depth/Length:
SqFt:

Volume:
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

The base map for the square indicates there is an outbuilding on the property. However, this building was neither photographed nor surveyed by the volunteer surveyor.

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2009: Constructed in 1949 by owner/builder Bernard Libby, this two-story, two-bay rowhouse is one of fourteen similar rowhouses designed by architect Joseph Miller. These rowhouses are illustrations of the Modern Movement and were constructed from the same permit (#322179). This hollow block structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A sloping roof caps the building and has overhanging boxed eaves. Fenestration of the façade consists of a single-leaf, paneled wood door and single and paired 1/1, double-hung, vinyl-sash windows with rowlock brick sills. The entry and second-story openings are sheltered by metal awnings. The south (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located south of K Street, S.E. and set back from the concrete sidewalk approximately twenty feet. The west (side) elevation is attached to 1507 K Street, S.E. and the east (side) elevation to 1511 K Street, S.E. The grassy front yard is enclosed by a milled-point metal fence. Landscaping includes planting beds, immature shrubs and trees, foundation plantings, and a concrete walkway extending from the primary entry to the sidewalk. The property extends south to a paved alley. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Hollow Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	DbI-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Ward/ANC:

Zoning: Designation Event(s)

Contributing:

Survey(s) Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\
File: 1509_KSTSE.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\
File: 1503-29_KSTSE.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
8/31/1949	322179	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1079-0032

BASICS DATA

ID Number: **1079-0032** Year Built: **1949** Data Source: **Permit**

Number Extended Street Quad Type of Address

1511 **K Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1511 K Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1079/0032 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1949** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1949** **Permit** **5357 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Miller, Joseph**

Orig Construction **Builder** **Libby, Bernard**

Orig Construction **Owner** **Libby, Bernard**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 14)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Block**
Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2009: Constructed in 1949 by owner/builder Bernard Libby, this two-story, two-bay rowhouse is one of fourteen similar rowhouses designed by architect Joseph Miller. These rowhouses are illustrations of the Modern Movement and were constructed from the same permit (#322179). This hollow block structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A sloping roof caps the building and has overhanging boxed eaves. Fenestration of the façade consists of a single-leaf, paneled wood door and paired one-light vinyl sliding windows with rowlock brick sills. The first-story window is protected by metal security bars. The south (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located south of K Street, S.E. and set back from the concrete sidewalk approximately twenty feet. The west (side) elevation is attached to 1509 K Street, S.E. and the east (side) elevation to 1513 K Street, S.E. The grassy front yard is enclosed by a milled-point metal fence and includes a concrete walkway extending from the primary entry to the sidewalk. The property extends south to a paved alley. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Hollow Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Sliding	1-light Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\
File: 1511_KSTSE.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\
File: 1503-29_KSTSE.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
8/31/1949	322179	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1079-0033

BASICS DATA

ID Number: **1079-0033** Year Built: **1949** Data Source: **Permit**

Number Extended Street Quad Type of Address

1513 **K Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1513 K Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1079/0033 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1949** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1949** **Permit** **5357 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Miller, Joseph**

Orig Construction **Builder** **Libby, Bernard**

Orig Construction **Owner** **Libby, Bernard**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 14)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2009: Constructed in 1949 by owner/builder Bernard Libby, this two-story, two-bay rowhouse is one of fourteen similar rowhouses designed by architect Joseph Miller. These rowhouses are illustrations of the Modern Movement and were constructed from the same permit (#322179). This hollow block structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A sloping roof caps the building and has overhanging boxed eaves. Fenestration of the façade consists of a replacement single-leaf, paneled metal door with a semicircular light, a single vinyl-sash casement window in the second story, and tripartite windows composed of a single-light fixed window flanked by one-light vinyl casements with rowlock brick sills. A metal awning shelters the entry. The south (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located south of K Street, S.E. and set back from the concrete sidewalk approximately twenty feet. The west (side) elevation is attached to 1513 K Street, S.E. and the east (side) elevation to 1517 K Street, S.E. The front yard is enclosed by a chain-link fence, has an immature tree, and a concrete walkway extending from the primary entry to the sidewalk. The property extends south to a paved alley. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Hollow Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Casement	1	Vinyl
Facade	Rectangular	Casement	1	Vinyl
Facade	Rectangular	Fixed	1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributor:	

Contributing

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research
Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\

File: 1513_KSTSE.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\

File: 1503-29_KSTSE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
8/31/1949	322179	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

Resource All Data Report

ID Number: 1079-0035

BASICS DATA

ID Number: **1079-0035** Year Built: **1949** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1517		K Street		SE

Name(s)	Type of Name
Rowhouse, 1517 K Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1079/0035			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1949	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1949	Permit			5357 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Miller, Joseph
Orig Construction	Builder	Libbey, J. Edward
Orig Construction	Owner	Libby, Bernard

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 14)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Block**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**

Height:	Width:	Depth/Length:	SqFt:	Volume:	Lot Width:	Lot Depth/Length:	Lot SqFt:	Acreage:	Has Driveway:
									<input type="checkbox"/>

Outbuilding Type _____ Contributing Status _____

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2009: Constructed in 1949 by owner/builder Bernard Libby, this two-story, two-bay rowhouse is one of fourteen similar rowhouses designed by architect Joseph Miller. These rowhouses are illustrations of the Modern Movement and were constructed from the same permit (#322179). This hollow block structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A sloping roof caps the building and has overhanging boxed eaves. Fenestration of the façade consists of a single-leaf door (materials not visible), tripartite windows composed of a single-light fixed window flanked by one-light vinyl casements, and a narrow 1/1, double-hung, vinyl-sash window. All window openings have rowlock brick sills. First-story openings are protected by metal security bars. The south (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located south of K Street, S.E. and set back from the concrete sidewalk approximately twenty feet. The west (side) elevation is attached to 1515 K Street, S.E. and the east (side) elevation to 1519 K Street, S.E. The front yard features a prominent brick and concrete tile wall along the sidewalk. A brick walkway extends from the primary entry to the sidewalk. The property extends south to a paved alley. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Hollow Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	DbI-Hung	1/1	Vinyl
Facade	Rectangular	Casement	1	Vinyl
Facade	Rectangular	Fixed	1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributor:

Contributing

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research
Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\
File: 1517_KSTSE.JPG

Date:: Photog:

Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\
File: 1503-29_KSTSE.JPG

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
08/31/1949	322179	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

Resource All Data Report

ID Number: 1079-0034

BASICS DATA

ID Number:	1079-0034	Year Built:	1949	Data Source:	
Number	Extended	Street	Quad Type of Address		
1515		K Street	SE	Current	
Name(s)	Type of Name				
Rowhouse, 1515 K Street, S.E.	Common				
TaxCode1	TaxCode2	TaxCode3	Type	Explain	
1079/0034			Square/Lot	Current	

STATUS/PURPOSE/USE DATA

Resource Type:	Building	Status Current:	Extant		
Desig. Status:	Historic	Quality:			
Purpose:	Rowhouse	Condition:	Good		
Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1949	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1949	Permit			5357 Permit
Construction Event	Association		Associated Name		
Orig Construction	Architect		Miller, Joseph		
Orig Construction	Builder		Libby, Bernard		
Orig Construction	Owner		Libby, Bernard		

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 14)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Block**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**

Height: _____
Width: _____
Depth/Length: _____

SqFt: _____
Volume: _____
Lot Width: _____

Lot Depth/Length: _____
Lot SqFt: _____
Acreage: _____

Has Driveway:

Outbuilding Type: _____
Contributing Status: _____

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2009: Constructed in 1949 by owner/builder Bernard Libby, this two-story, two-bay rowhouse is one of fourteen similar rowhouses designed by architect Joseph Miller. These rowhouses are illustrations of the Modern Movement and were constructed from the same permit (#322179). This hollow block structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A sloping roof caps the building and has overhanging boxed eaves. Fenestration of the façade consists of a replacement single-leaf, paneled metal door with a semicircular light, a single vinyl-sash casement window in the second story, and tripartite windows composed of a single-light fixed window flanked by one-light vinyl casements with rowlock brick sills. A metal awning shelters the entry. The south (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located south of K Street, S.E. and set back from the concrete sidewalk approximately twenty feet. The west (side) elevation is attached to 1513 K Street, S.E. and the east (side) elevation to 1517 K Street, S.E. The front yard is enclosed by a chain-link fence, has an immature tree, and a concrete walkway extending from the primary entry to the sidewalk. The property extends south to a paved alley. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Hollow Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
2 Flr Windows	Rectangular	Casement	1	Vinyl
Facade	Rectangular	Casement	1	Vinyl
Facade	Rectangular	Fixed	1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributor:

Contributing:

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research
Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\
File: 1515_KSTSE.JPG

Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\
File: 1503-29_KSTSE.JPG

Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

[Empty text box for notes]

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
8/31/1949	322179	Build	

Permit Notes:

[Empty text box for permit notes]

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

Resource All Data Report

ID Number: 1079-0036

BASICS DATA

ID Number: **1079-0036** Year Built: **1949** Data Source: **Permit**

Number Extended Street Quad Type of Address

1519 **K Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1519 K Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1079/0036 **Square/Lot** **Old**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1949** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1949** **Permit** **5357 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Miller, Joseph**

Orig Construction **Builder** **Libby, Bernard**

Orig Construction **Owner** **Libby, Bernard**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 14)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Block**

Footprint: **Rectangular**

Number Stories:

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2009: Constructed in 1949 by owner/builder Bernard Libby, this two-story, two-bay rowhouse is one of fourteen similar rowhouses designed by architect Joseph Miller. These rowhouses are illustrations of the Modern Movement and were constructed from the same permit (#322179). This hollow block structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A sloping roof caps the building and has overhanging boxed eaves. Fenestration of the façade consists of a single-leaf, flush wood door with a light and tripartite windows composed of a single-light fixed window flanked by one-light vinyl casements with rowlock brick sills. The south (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located south of K Street, S.E. and set back from the concrete sidewalk approximately twenty feet. The west (side) elevation is attached to 1517 K Street, S.E. and the east (side) elevation to 1521 K Street, S.E. The grassy front yard has an mature tree and a concrete walkway extending from the primary entry to the sidewalk. The property extends south to a paved alley. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Hollow Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Casement	1	Vinyl
Facade	Rectangular	Fixed	1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Ward/ANC:

Zoning: Designation Event(s)

Contributing:

Survey(s) Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\
File: 1519_KSTSE.JPG
Date:: Photog:
Code:: R: Fr:



Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\
File: 1503-29_KSTSE.JPG
Date:: Photog:
Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
8/31/1949	322179	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1079-0037

BASICS DATA

ID Number: **1079-0037** Year Built: **1949** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1521		K Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1521 K Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1079/0037			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1949	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1949	Permit			5357 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Miller, Joseph
Orig Construction	Builder	Libby, Bernard
Orig Construction	Owner	Libby, Bernard

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 14)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Block**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**

Height:	Outbuilding Type	Contributing Status
---------	------------------	---------------------

Width:
Depth/Length:
SqFt:

Volume:
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:
An outbuilding is noted on the base map of the square, however, the building was neither surveyed or photographed by the volunteer surveyor.

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2009: This rowhouse is located south of K Street, S.E. and set back from the concrete sidewalk approximately twenty feet. **September 2009:** Constructed in 1949 by owner/builder Bernard Libby, this two-story, two-bay rowhouse is one of fourteen similar rowhouses designed by architect Joseph Miller. These rowhouses are illustrations of the Modern Movement and were constructed from the same permit (#322179). This hollow block structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A sloping roof caps the building and has overhanging boxed eaves. Fenestration of the façade consists of a single-leaf, paneled wood door with one light and paired one-light vinyl sliding windows with rowlock brick sills. The entry is sheltered by a metal awning. The south (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located south of K Street, S.E. and set back from the concrete sidewalk approximately twenty feet. The west (side) elevation is attached to 1519 K Street, S.E. and the east (side) elevation to 1523 K Street, S.E. The grassy front yard has been landscaped with a concrete retaining wall and immature shrubs and plantings. A concrete walkway extends from the primary entry to the sidewalk. The property extends south to a paved alley. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Hollow Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Sliding	1-light Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s) _____

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation _____

**Permit Research
Volunteer Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079**

File: **1521_KSTSE.JPG**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079**

File: **1503-29_KSTSE.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
8/31/1949	322179	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria
------	----------

Resource All Data Report

ID Number: 1079-0038

BASICS DATA

ID Number: **1079-0038** Year Built: **1949** Data Source: **Permit**

Number Extended Street Quad Type of Address

1523 **K Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1523 K Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1079/0038 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1949** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1949** **Permit** **5357 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Miller, Joseph**

Orig Construction **Builder** **Libby, Bernard**

Orig Construction **Owner** **Libby, Bernard**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 14)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2009: Constructed in 1949 by owner/builder Bernard Libby, this two-story, two-bay rowhouse is one of fourteen similar rowhouses designed by architect Joseph Miller. These rowhouses are illustrations of the Modern Movement and were constructed from the same permit (#322179). This hollow block structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A sloping roof caps the building and has overhanging boxed eaves. Fenestration of the façade consists of a replacement single-leaf, paneled metal door with a semicircular light, paired one-light vinyl sliding windows, and a narrow 1/1, double-hung, vinyl-sash window in the second story. All window openings have rowlock brick sills. The entry is sheltered by a one-story, one-bay porch. The shed roof of the porch appears to be covered with asphalt shingles and is supported by turned wood posts. The south (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located south of K Street, S.E. and set back from the concrete sidewalk approximately twenty feet. The west (side) elevation is attached to 1521 K Street, S.E. and the east (side) elevation to 1525 K Street, S.E. The raised front yard is enclosed by chain-link fence and landscaped with immature shrubs and plantings. A brick walkway extends from the primary entry to the sidewalk. The property extends south to a paved alley. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Hollow Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	DbI-Hung	1/1	Vinyl
Facade	Rectangular	Sliding	1-light Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)
Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation
**Permit Research
Volunteer Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079**

File: **1503-29_KSTSE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079**

File: **1523_KSTSE.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
8/31/1949	322179	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

Resource All Data Report

ID Number: 1079-0039

BASICS DATA

ID Number: **1079-0039** Year Built: **1949** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1525		K Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1525 K Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1079/0039			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1949	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1949	Permit			5357 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Miller, Joseph
Orig Construction	Builder	Libby, Bernard
Orig Construction	Owner	Libby, Bernard

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 14)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Block**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**

Height:	Outbuilding Type	Contributing Status
---------	------------------	---------------------

Width:
Depth/Length:
SqFt:

Volume:
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2009: Constructed in 1949 by owner/builder Bernard Libby, this two-story, two-bay rowhouse is one of fourteen similar rowhouses designed by architect Joseph Miller. These rowhouses are illustrations of the Modern Movement and were constructed from the same permit (#322179). This hollow block structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A sloping roof caps the building and has overhanging boxed eaves. Fenestration of the façade consists of a replacement single-leaf, paneled metal door with a semicircular light and paired 1/1, double-hung, vinyl-sash windows with rowlock brick sills and inoperable louvered shutters. The entry has a Colonial Revival-style surround that includes an ogee-molded broken pediment with urn, pilasters, and a plain frieze. The south (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located south of K Street, S.E. and set back from the concrete sidewalk approximately twenty feet. The west (side) elevation is attached to 1523 K Street, S.E. and the east (side) elevation to 1527 K Street, S.E. The grassy front yard is enclosed by a chain-link fence and landscaped with immature shrubs and foundation plantings. A concrete walkway extends from the primary entry to the sidewalk. The property extends south to a paved alley. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Hollow Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	DbI-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	

Survey(s)
Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation
**Permit Research
Volunteer Reconnaissance Survey**

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079**

File: **1525_KTSE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079**

File: **1503-29_KTSE.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
8/31/1949	322179	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

Resource All Data Report

ID Number: 1079-0040

BASICS DATA

ID Number: **1079-0040** Year Built: **1949** Data Source: **Permit**

Number Extended Street Quad Type of Address

1527 **K Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1527 K Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1079/0040 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1949** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1949** **Permit** **5357 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Miller, Joseph**

Orig Construction **Builder** **Libby, Bernard**

Orig Construction **Owner** **Libby, Bernard**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 14)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2009: Constructed in 1949 by owner/builder Bernard Libby, this two-story, two-bay rowhouse is one of fourteen similar rowhouses designed by architect Joseph Miller. These rowhouses are illustrations of the Modern Movement and were constructed from the same permit (#322179). This hollow block structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A sloping roof caps the building and has overhanging boxed eaves. Fenestration of the façade consists of a single-leaf, paneled wood door and tripartite windows composed of a single-light fixed window flanked by one-light metal casements with rowlock brick sills. The entry is sheltered by a metal awning. The south (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located south of K Street, S.E. and set back from the concrete sidewalk approximately twenty feet. The west (side) elevation is attached to 1525 K Street, S.E. and the east (side) elevation to 1529 K Street, S.E. The grassy front yard has mature trees and a concrete walkway extending from the primary entry to the sidewalk. The property extends south to a paved alley. The backyard was not photographed by the volunteer surveyor.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Hollow Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Casement	1	Metal
Facade	Rectangular	Fixed	1	Metal
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\

File: 1527_KSTSE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\

File: 1503-29_KSTSE.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

8/31/1949 322179 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1079-0041

BASICS DATA

ID Number: **1079-0041** Year Built: **1949** Data Source: **Permit**

Number Extended Street Quad Type of Address

1529 **K Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1529 K Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1079/0041 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1949** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1949** **Permit** **5357 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Miller, Joseph**

Orig Construction **Builder** **Libby, Bernard**

Orig Construction **Owner** **Libby, Bernard**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 14)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Modern

Exterior & Architectural Notes:

September 2009: Constructed in 1949 by owner/builder Bernard Libby, this two-story, two-bay rowhouse is one of fourteen similar rowhouses designed by architect Joseph Miller. These rowhouses are illustrations of the Modern Movement and were constructed from the same permit (#322179). This hollow block structure is set on a solid brick foundation; both are faced with six-course, American-bond brick. A sloping roof caps the building and has overhanging boxed eaves. Fenestration of the façade consists of a replacement single-leaf, paneled metal door with a semicircular light, tripartite windows composed of a single-light fixed window flanked by one-light vinyl casements, and paired one-light vinyl sliding windows. All window openings have rowlock brick sills and openings on the second story are edged with inoperable shutters on the outermost bays. The main entry has a Colonial Revival-style surround that includes pilasters, and an ogee-molded, denticulated cornice. The south (rear) elevation was not photographed by the volunteer surveyor.

Site Notes:

September 2009: This rowhouse is located south of K Street, S.E. and set back from the concrete sidewalk approximately twenty feet. The west (side) elevation is attached to 1527 K Street, S.E. and the east (side) elevation to 1531 K Street, S.E. The raised front yard has a brick retaining wall and is enclosed by a milled-point metal fence. A concrete walkway extends from the primary entry to the sidewalk. The property extends south to a paved alley. The backyard is enclosed by a wooden privacy fence.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Sloped	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Hollow Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Rectangular	Casement	1	Vinyl
Facade	Rectangular	Fixed	1	Vinyl
Facade	Rectangular	Sliding	1-light Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research
Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\
File: 1529_KSTSE-rear.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\
File: 1529_KSTSE.JPG
Date:: Photog:
Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\
File: 1503-29_KSTSE.JPG
Date:: Photog:
Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
8/31/1949	322179	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1079-0806

BASICS DATA

ID Number: **1079-0806** Year Built: **1942** Data Source: **Permit**

Number Extended Street Quad Type of Address

1531 **K Street** **SE Current**

Name(s) Type of Name

Rowhouse, 1531 K Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1079/0806 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1942** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1942** **Permit** **3500 Permit**

Construction Event Association Associated Name

Huntt, George R. **Architect** **Huntt, George R.**

Orig Construction **Builder** **Queens Chapel, Inc.**

Orig Construction **Owner** **Queens Chapel, Inc.**

Construction Notes:

This rowhouse was originally one of 8 smiliar rowhouses. Only five are currently extant.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row**

Relate to Street: **Front Yard w/ Setback**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **15**

Depth/Length: **29**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

September 2009: This two-story, two-bay Colonial Revival-style rowhouse was constructed in 1942 for owner/builder Queens Chapel, Inc. The dwelling is one of eight similar rowhouses designed by architect George R. Huntt under the same permit (#254800). Only five of these buildings are currently extant. Set on a solid brick foundation, this concrete-block structure is faced with six-course, American-bond brick. The roof form and materials were not visible from the public right-of-way due to a parapet wall. The brick parapet with concrete coping mirrors the parapet found next door on 1533 K Street, S.E. An exterior chimney is located on the south (rear) elevation. The façade (north elevation) has a single-leaf wood door located in the eastern bay. A stepped brick wall accompanies the walkway to the door opening. All window openings hold 1/1, double-hung, vinyl-sash windows. The openings feature rowlock brick sills and two-course, rowlock brick segmental arches. The south (rear) elevation has a single-leaf door accessed via poured concrete stairs with metal railing. The door is flanked by a narrow 1/1, double-hung, vinyl-sash window. Additional fenestration consists of single and paired openings with 1/1, double-hung, vinyl-sash windows. A two-light window pierces the basement. All of the window openings have rowlock brick sills and two-course, rowlock brick segmental arches.

Site Notes:

September 2009: This rowhouse is located south of K Street, S.E. and has a setback from the concrete sidewalk of approximately twenty feet. The west (side) elevation is attached to 1529 K Street, S.E. and the east (side) elevation to 1533 K Street, S.E. The small front yard slopes to the north and has been enclosed by a chain-link fence. Landscaping includes immature shrubs and a mature tree. A concrete walkway extends from the primary entry to the sidewalk. The property extends south to a paved alley. The level, grassy backyard is enclosed by a chain-link fence and includes a concrete parking pad.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Flat	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Concrete Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Segmental-Arched	DbI-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Arched (Segmental)	Single		Wood

Notable Interior Plan(s) _____ Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill** _____ Historic District(s) _____

Subdivision:

Ward/ANC:

value/AVC.

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\

File: 1531_KSTSE.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079\

File: 1531_KSTSE-rear.JPG

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

[Empty text box for notes]

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
8/11/1942	254800	Build	

Permit Notes:

[Empty text box for permit notes]

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1079-0807

BASICS DATA

ID Number: **1079-0807** Year Built: **1942** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
1533		K Street	SE	Current

Name(s)	Type of Name
Rowhouse, 1533 K Street, S.E.	Common

TaxCode1	TaxCode2	TaxCode3	Type	Explain
1079/0807			Square/Lot	Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**
Desig. Status: **Historic** Quality:
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
Residential (Single-Family)	1942	Permit			Historic/Current

CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
Orig Construction	1942	Permit			3500 Permit

Construction Event	Association	Associated Name
Orig Construction	Architect	Huntt, George R.
Orig Construction	Builder	Queens Chapel, Inc.
Orig Construction	Owner	Queens Chapel, Inc.

Construction Notes:

This rowhouse was originally one of 8 smiliar rowhouses. Only five are currently extant.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 5)**
Relate to Street: **Front Yard w/ Setback**
Massing: **Block**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**
Bays Wide: **2**
Height:
Width: **15**
Depth/Length: **29**

Outbuilding Type	Contributing Status
------------------	---------------------

SqFt:
Volume:
Lot Width:

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

September 2009: This two-story, two-bay Colonial Revival-style rowhouse was constructed in 1942 for owner/builder Queens Chapel, Inc. The dwelling is one of eight similar rowhouses designed by architect George R. Huntt under the same permit (#254800). Only five of these buildings are currently extant. Set on a solid brick foundation, this concrete-block structure is faced with six-course, American-bond brick. The roof form and materials were not visible from the public right-of-way due to a parapet wall. The brick parapet with concrete coping mirrors the parapet found next door on 1531 K Street, S.E. An exterior-rear chimney is shared with 1535 K Street, S.E. The façade (north elevation) has a single-leaf wood door located in the western bay. A stepped brick wall accompanies the walkway to the door opening. All window openings hold 1/1, double-hung, vinyl-sash windows with false diamond-light or 6/6 muntins. The openings feature rowlock brick sills and metal awnings. Additional fenestration consists of a one-light basement window with rowlock brick sill and two-course, rowlock brick segmental arch. The south (rear) elevation has a single-leaf French door accessed via metal stairs. The door is flanked by a narrow 1/1, double-hung, vinyl-sash window with false 4/4 muntins. Additional fenestration consists of single and paired openings with 1/1, double-hung, vinyl-sash windows and false diamond-light or 6/6 muntins. A six-light window pierces the basement. All of the window openings have rowlock brick sills and two-course, rowlock brick segmental arches. Two openings include metal awnings.

Site Notes:

September 2009: This rowhouse is located south of K Street, S.E. and has a setback from the concrete sidewalk of approximately twenty feet. The west (side) elevation is attached to 1531 K Street, S.E. and the east (side) elevation to 1535 K Street, S.E. The small front yard slopes to the north and has been enclosed by a milled-point metal fence. Landscaping includes immature shrubs and plantings. A brick walkway extends from the primary entry to the sidewalk. The property extends south to a paved alley. The level, grassy backyard is enclosed by a chain-link fence and includes a concrete parking pad.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Flat	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Concrete Block			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Facade	Segmental-Arched	Dbl-Hung	diamond	Vinyl
Facade	Segmental-Arched	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Arched (Segmental)	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079**

File: **1533_KSTSE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1079**

File: **1533_KSTSE-rear.JPG**

Date:: Photog:

Code:: R: Fr:

PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

[Empty text box for miscellaneous notes]

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
8/11/1942	254800	Build	

Permit Notes:

[Empty text box for permit notes]

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code Criteria _____

DATA PROCESSING EVENTS DATA _____

