

# Resource All Data Report

# ID Number: 1111-0082

## BASICS DATA

ID Number: **1111-0082** Year Built: **1924** Data Source: **Permit**

Number	Extended	Street	Quad Type	Address
<b>110</b>		<b>18th Street</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 110 18th Street, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0082</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1924</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1924</b>	<b>Permit</b>			<b>6000 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Santmyers, George T.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Columbia Construction Company</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Columbia Construction Company</b>

Construction Notes:

**One of five rowhouses constructed from the same permit (#4539).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row End (1 of 5)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**  
Bays Wide: **2**  
Height: **18**  
Width: **30**  
Depth/Length: **30**

Outbuilding Type	Contributing Status
<b>Garage</b>	<b>Contributing</b>

Volume:  
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

**July 2010: A one-story, one-bay garage, constructed c. 1924, is located east of the dwelling. The wood-frame garage is clad with pressed metal siding and is capped by a front-gabled roof. Corrugated metal covers the roof, which is accented by overhanging eaves. A single-leaf, paneled door pierces the**

south elevation. The primary opening is located on the east elevation.

## STYLE/EXTERIOR DATA

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1924 by Columbia Construction Company, this two-story, two-bay Classical Revival-style single-family rowhouse is one of five rowhouses constructed from the same permit (#4539). Set on a solid concrete foundation, this brick dwelling is faced with five-course, American-bond brick. A soldier brick stringcourse spans the façade (west elevation) and is located above the second story openings. A sloping roof caps the dwelling. A molded metal cornice accents the façade and is finished with dentils. An exterior-rear pebble-dashed chimney rises from the east elevation and has a plain cap. The southernmost bay of the façade holds a single-leaf, paneled wood door with lights, which is topped by a single-light wood transom. Additional façade openings hold single and paired 6/1, double-hung, wood-sash windows. A rowlock brick sill completes each opening. A one-story, full-width porch spans the façade and is set on a brick pier foundation with wood lattice infill. The flat roof of the porch, featuring overhanging eaves, is supported by brick posts set upon brick pedestals. Metal balusters encircle the porch, which is accessed via steps in the southernmost end bay. The pebble-dashed north (side) elevation is pierced by 6/1, double-hung, wood-sash windows and paired six-light wood awning windows.

A two-story enclosed porch, which has been pebble-dashed, is located on the rear (east) elevation of the dwelling and is original. A sloping roof caps the enclosed porch. The first story of the porch is noted on the 1928 Sanborn map as being originally open. Visible fenestration consists of 6/1, double-hung, wood-sash windows and a single-leaf door.

Site Notes:

July 2010: This two-story, single-family rowhouse is located on the east side of 18th Street, S.E. and is set back approximately fifteen feet from the concrete sidewalk. The south (side) elevation of the dwelling is adjacent to 112 18th Street, S.E. and an alley runs parallel to the north (side) elevation of the dwelling. The raised, grassy front yard is bounded by a low, stone retaining wall. A concrete walkway provides access to the property from the public sidewalk. The rear yard is enclosed by a wood fence. An alley is located east of the dwelling.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

---

Neighborhood: **Capitol Hill**

Historic District(s)

---

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

---

Contributing:

Survey(s)

---

Level(s) of Investigation

---

**Capitol Hill Southeast Phase II (2010)**

**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **110\_18th\_Street\_SE\_facade\_looking\_E.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **110\_18th\_Street\_SE\_facade\_looking\_SE.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **110\_18th\_Street\_SE\_garage\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **110\_18th\_Street\_SE\_garage\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

## Image File Not Found

Path: X:\SD Databases\SE Phase  
 I\Database\Pictures\Square 1111\  
 File: 110\_18th\_Street\_SE\_rear\_looking\_SW.JPG  
 Date:: Photog:  
 Code:: R: Fr:

Caption:

## Image File Not Found

Path: X:\SD Databases\SE Phase  
 I\Database\Pictures\Square 1111\  
 File: 110\_18th\_Street\_SE\_side\_looking\_SE.JPG  
 Date:: Photog:  
 Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
11/06/1924	4539	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit \_\_\_\_\_

Code	Criteria
------	----------

### DATA PROCESSING EVENTS DATA

# Resource All Data Report

# ID Number: 1111-0081

## BASICS DATA

ID Number: **1111-0081** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**112** **18th Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 112 18th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0081** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **6000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Santmyers, George T.**

**Orig Construction** **Builder** **Columbia Construction Company**

**Orig Construction** **Owner** **Columbia Construction Company**

Construction Notes:

**One of five rowhouses constructed from the same permit (#4539).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 5)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1924 by Columbia Construction Company, this two-story, two-bay Classical Revival-style single-family rowhouse is one of five rowhouses constructed from the same permit (#4539). Set on a solid concrete foundation, this brick dwelling is faced with five-course, American-bond brick. A soldier brick stringcourse spans the façade (west elevation) and is located above the second story openings. A sloping roof caps the dwelling. A molded metal cornice accents the façade and is finished with dentils. An exterior-rear brick chimney rises from the east elevation and has a plain cap. The southernmost bay of the façade holds a single-leaf, paneled wood door, which is topped by a single-light wood transom. Additional façade openings hold single and paired 1/1, double-hung, vinyl-sash windows. A rowlock brick sill completes each opening and a soldier brick flat arch tops the first story openings. A one-story, full-width porch spans the façade and is set on a brick pier foundation. The flat roof of the porch, featuring overhanging eaves, is supported by brick posts set upon brick pedestals. Square wood balusters encircle the porch, which is accessed via steps in the southernmost end bay. The rear (east) elevation is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows and sliding, vinyl-frame glass doors with multi-lights. All openings are surmounted by a three-course, rowlock brick segmental arch and the windows feature rowlock brick sills.

Site Notes:

July 2010: This two-story, single-family dwelling is located on the east side of 18th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 110 and 114 18th Street, S.E. The raised, grassy front yard is marked by foundation plantings and is bounded by a low, stone retaining wall. Poured concrete steps approach the brick walkway from the public sidewalk. The rear yard is enclosed by a wood fence. An alley is located east of the dwelling.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Designation Level(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research  
Reconnaissance Survey

**PHOTOS - DIGITIZED**

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 112\_18th\_Street\_SE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 112\_18th\_Street\_SE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 112\_18th\_Street\_SE\_rear\_looking\_W.JPG  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
11/06/1924	4539	Build	

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---



# Resource All Data Report

# ID Number: 1111-0080

## BASICS DATA

ID Number: **1111-0080** Year Built: **1924** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>114</b>		<b>18th Street</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 114 18th Street, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0080</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1924</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1924</b>	<b>Permit</b>			<b>6000 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Santmyers, George T.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Columbia Construction Company</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Columbia Construction Company</b>

Construction Notes:

**One of five rowhouses constructed from the same permit (#4539).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 5)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**  
Bays Wide: **2**  
Height:   
Width: **18**  
Depth/Length: **30**  
SqFt:

Outbuilding Type	Contributing Status
------------------	---------------------

Volume:  
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1924 by Columbia Construction Company, this two-story, two-bay Classical Revival-style single-family rowhouse is one of five rowhouses constructed from the same permit (#4539). Set on a solid concrete foundation, this brick dwelling is faced with five-course, American-bond brick. A soldier brick stringcourse spans the façade (west elevation) and is located above the second story openings. A sloping roof caps the dwelling. A molded metal cornice accents the façade and is finished with dentils. An exterior-rear brick chimney rises from the east elevation and has a plain cap. The southernmost bay of the façade holds a single-leaf, paneled wood door with lights, which is topped by a single-light wood transom. Additional façade openings hold single and paired 6/1, double-hung, wood-sash windows. A rowlock brick sill completes each opening and a soldier brick flat arch tops the first story openings. A one-story, full-width porch spans the façade and is set on a brick pier foundation with decorative concrete block infill. The flat roof of the porch, featuring overhanging eaves, is supported by brick posts set upon brick pedestals. Square wood balusters encircle the porch, which is accessed via steps in the southernmost end bay.

A two-story enclosed porch is located on the rear (east) elevation and is original. The wood-frame enclosed porch is clad with vinyl siding and is capped by a sloping roof. Visible fenestration consists of a single-leaf, paneled metal door with lights, topped by a single-light transom, and 6/1, double-hung, wood-sash windows.

Site Notes:

July 2010: This two-story, single-family rowhouse is located on the east side of 18th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 112 and 116 18th Street, S.E. The raised, grassy front yard is marked by mature shrubs and is bounded by a low, stone retaining wall. A concrete walkway provides access to the property from the public sidewalk. A metal chain-link fence encloses the rear yard of the property. An alley is located east of the dwelling.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:  
Zoning:  
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research  
Reconnaissance Survey

### PHOTOS - DIGITIZED

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 114\_18th\_Street\_SE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 114\_18th\_Street\_SE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 114\_18th\_Street\_SE\_rear\_looking\_W.JPG  
Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
11/06/1924	4539	Build	

Permit Notes:

--

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0079

## BASICS DATA

ID Number: **1111-0079** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**116** **18th Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 116 18th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0079** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **6000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Santmyers, George T.**

**Orig Construction** **Builder** **Columbia Construction Company**

**Orig Construction** **Owner** **Columbia Construction Company**

Construction Notes:

**One of five rowhouses constructed from the same permit (#4539).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 5)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

**Garage**

Contributing Status

**Non-Contributing**

Outbuilding Notes:

**July 2010: A one-story, one-bay garage, constructed c. 1970, is located east of the dwelling. The wood-frame garage is clad with vinyl siding and is capped by a front-gabled roof. Asphalt shingles cover the roof, which is accented by overhanging eaves. A roll-up paneled metal door pierces the east elevation.**

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1924 by Columbia Construction Company, this two-story, two-bay Classical Revival-style single-family rowhouse is one of five rowhouses constructed from the same permit (#4539). Set on a solid concrete foundation, this brick dwelling is faced with five-course, American-bond brick. A soldier brick stringcourse spans the façade (west elevation) and is located above the second story openings. A sloping roof caps the dwelling. A molded metal cornice accents the façade and is finished with dentils. An exterior-rear brick chimney rises from the east elevation and has a plain cap. The southernmost bay of the façade holds a single-leaf, paneled wood door with lights, which is topped by a single-light wood transom. Additional façade openings hold single and paired 1/1, double-hung, vinyl-sash windows with false 6/6 vinyl muntins. A rowlock brick sill completes each opening and a soldier brick flat arch tops the first story openings. A one-story, full-width porch spans the façade and is set on a brick pier foundation. The flat roof of the porch, featuring overhanging eaves, is supported by brick posts set upon brick pedestals. Metal balusters encircle the porch, which is accessed via steps in the southernmost end bay.

A two-story enclosed porch is located on the rear (east) elevation and is original. The wood-frame enclosed porch is clad with vinyl siding and is capped by a sloping roof. Visible fenestration consists of a single-leaf door and 1/1, double-hung, vinyl-sash windows.

Site Notes:

July 2010: This two-story, single-family rowhouse is located on the east side of 18th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 114 and 118 18th Street, S.E. The raised front yard is marked by mature shrubs and foundation plantings and is bounded by a low, stone retaining wall, which is topped by a metal chain-link fence. A concrete walkway leads from the public sidewalk and provides access to the property. Wood fencing encloses the rear yard. An alley is located east of the dwelling.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

---

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

---

Survey(s)

Level(s) of Investigation

---

**Capitol Hill Southeast Phase II (2010)**

**Permit Research  
Reconnaissance Survey**

---

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **116\_18th\_Street\_SE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **116\_18th\_Street\_SE\_facade\_looking\_SE.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **116\_18th\_Street\_SE\_garage\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **116\_18th\_Street\_SE\_rear\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

---

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code          Roll          Frame(s)          Date          Photographer          Caption

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
11/06/1924	4539	Build	

---

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code          Criteria \_\_\_\_\_

**DATA PROCESSING EVENTS DATA**

---



# Resource All Data Report

# ID Number: 1111-0078

## BASICS DATA

ID Number: **1111-0078** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**118** **18th Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 118 18th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0078** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **6000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Santmyers, George T.**

**Orig Construction** **Builder** **Columbia Construction Company**

**Orig Construction** **Owner** **Columbia Construction Company**

Construction Notes:

**One of five rowhouses constructed from the same permit (#4539).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 5)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1924 by Columbia Construction Company, this two-story, two-bay Classical Revival-style single-family rowhouse is one of five rowhouses constructed from the same permit (#4539). Set on a solid concrete foundation, this brick dwelling is faced with five-course, American-bond brick. A soldier brick stringcourse spans the façade (west elevation) and is located above the second story openings. A sloping roof caps the dwelling. A molded metal cornice accents the façade and is finished with dentils. An exterior-rear brick chimney rises from the east elevation and has a plain cap. The southernmost bay of the façade holds a single-leaf door, which is topped by a single-light wood transom. Additional façade openings hold single and paired 1/1, double-hung, vinyl-sash windows. A rowlock brick sill completes each opening and a soldier brick flat arch tops the first story openings. A one-story, full-width porch spans the façade and is set on a brick pier foundation. The flat roof of the porch, featuring overhanging eaves, is supported by brick posts set upon brick pedestals. Square wood balusters encircle the porch, which is accessed via brick steps in the southernmost end bay.

A two-story enclosed porch, set on a brick pier foundation, is located on the rear (east) elevation and is original. The wood-frame enclosed porch is clad with vinyl siding and is capped by a sloping roof. Visible fenestration consists of a single-leaf, multi-light door and 1/1, double-hung, vinyl-sash windows.

Site Notes:

July 2010: This two-story, single-family rowhouse is located on the east side of 18th Street, S.E. and is set back approximately ten feet from the concrete sidewalk. The dwelling is adjacent to 116 and 120 18th Street, S.E. The raised, grassy front yard is marked by mature shrubs and is bounded by a low, stone retaining wall. A brick walkway, with steps, leads from the public sidewalk to the property. The rear yard is paved with concrete and is partially enclosed by wood fencing. An alley is located east of the dwelling.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:  
Zoning:  
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research  
Reconnaissance Survey

### PHOTOS - DIGITIZED

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 118\_18th\_Street\_SE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 118\_18th\_Street\_SE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 118\_18th\_Street\_SE\_rear\_looking\_W.JPG  
Date:: Photog:  
Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

--

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
11/06/1924	4539	Build	

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0083

## BASICS DATA

ID Number: **1111-0083**      Year Built: **1924**      Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>1801</b>		<b>A Street</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 1801 A Street, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0083</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building**      Status Current: **Extant**  
Desig. Status: **Historic**      Quality:  
Purpose: **Rowhouse**      Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1924</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1924</b>	<b>Permit</b>			<b>4285 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Santmyers, George T.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Poretsky, H.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Poretsky, Silver &amp; Rosen</b>

Construction Notes:

**One of seven rowhouses constructed from the same permit (#1319).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 7)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**  
Bays Wide: **2**  
Height:      **18**  
Width:      **30**  
Depth/Length:  
SqFt:

Outbuilding Type	Contributing Status
------------------	---------------------

Volume:  
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1924, this single-family rowhouse was one of seven built by H. Poretsky from the same permit (#1319). The two-story, two-bay, Classical Revival-style dwelling is set on a solid concrete foundation. The masonry structure has a five-course, American-bond brick veneer. A soldier brick lintel course extends above the basement and second story openings. Furthermore, a rowlock brick sill string enhances the second-story window openings. The sloped roof is obscured from view by a prominent ogee-molded metal cornice with dentils. An exterior-rear brick chimney with a plain cap pierces the roofline. Fenestration of the façade (north elevation) consists of a single-leaf, paneled metal door with semi-circular light located in the eastern bay of the first story. Topped by a single-light transom, the door is set in a narrow, square-edge wood surround. West of the door opening is a large, single-light landscape window. The second story has a 1/1, double-hung, wood-sash window and a two-light, vinyl-sash sliding window. All façade window openings have rowlock brick sills. A one-story porch spans the façade. Set on a brick pier foundation, this porch has a non-original shed roof supported by battered brick posts set on brick piers. A metal railing completes the porch. Fenestration of the west (side) elevation consists of 1/1, double-hung, vinyl-sash windows and one example of a two-light, vinyl-sash sliding window. Basement window openings were not visible from the public right-of-way. All openings have rowlock brick sills. The south (rear) elevation has a two-story, full-width rear porch. Set on a concrete pier foundation, this porch has been enclosed with German vinyl siding. A shed roof covers the appendage. Fenestration consists of paired 1/1, double-hung, vinyl-sash windows with false 6/6 muntins. A double-leaf, metal-frame glass door is located in the eastern bay of the first story and accessed via wooden steps.

Site Notes:

July 2010: Located on a corner lot southeast of the intersection of A Street, S.E. and 18th Street, S.E., this single-family rowhouse has a setback of approximately twenty feet from the concrete sidewalk. The east (side) elevation is adjacent to 1803 A Street, S.E. The level, raised front yard is enclosed with a metal chain-link fence. Mature trees and shrubs dot the lot. A concrete walkway links the front porch via steps to a sidewalk below. The level, grassy backyard is elevated. A concrete-block retaining wall extends aside the concrete sidewalk of 18th Street, S.E. The backyard does not have a fence.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**  
Subdivision:  
Ward/ANC:  
Zoning:  
Contributing:  
  
Survey(s)  
**Capitol Hill Southeast Phase II (2010)**

Historic District(s)  
  
Designation Event(s)  
  
Level(s) of Investigation  
**Permit Research**  
**Reconnaissance Survey**

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**  
File: **1801\_A\_Street\_SE\_facade\_looking\_SE.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**  
File: **1801\_A\_Street\_SE\_facade\_looking\_SW.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**  
File: **1801\_A\_Street\_SE\_rear\_looking\_NE.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
08/05/1924	1319	Build	

Permit Notes:

---

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

Study Unit

---

Code

Criteria

---

---

**DATA PROCESSING EVENTS DATA**



# Resource All Data Report

# ID Number: 1111-0084

## BASICS DATA

ID Number: **1111-0084** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1803** **A Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 1803 A Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0084** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4285 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Santmyers, George T.**

**Orig Construction** **Builder** **Poretsky, H.**

**Orig Construction** **Owner** **Poretsky, Silver & Rosen**

Construction Notes:

**One of seven rowhouses constructed from the same permit (#1319).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 7)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1924, this single-family rowhouse was one of seven built by H. Poretsky from the same permit (#1319). The two-story, two-bay, Classical Revival-style dwelling is set on a solid concrete foundation. The masonry structure has a five-course, American-bond brick veneer. A rowlock brick sill string and a soldier brick lintel course enhance the second-story window openings. The sloped roof has metal coping along the façade and an ogee-molded metal architrave with dentils set between the firewalls. An exterior-rear brick chimney with a plain cap pierces the roofline. Fenestration of the façade (north elevation) consists of a single-leaf, paneled wood door with semi-circular light located in the eastern bay of the first story. Topped by a single-light transom, the opening has a narrow, square-edge wood surround. Additional fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows with false 6/1 muntins. All façade window openings have rowlock brick sills. A one-story porch spans the width of the façade. Set on a brick pier foundation with decorative concrete-block infill, the porch features a flat roof with ogee-molded metal cornice. Corbeled brick posts set on brick piers support the roof. Metal railing completes the porch. The south (rear) elevation has a two-story porch set on a concrete pier foundation. The porch has been clad in aluminum siding and is capped by a shed roof. Paired, 1/1, double-hung, vinyl-sash windows with vinyl-clad surrounds pierce the rear of the porch. A single-leaf, paneled wood door and 1/1, double-hung, vinyl-sash window are located off a wooden porch.

Site Notes:

July 2010: Located south of A Street, S.E., this single-family rowhouse has a setback of approximately twenty feet from the concrete sidewalk. The west (side) elevation is adjacent to 1801 A Street, S.E. and the east (side) elevation to 1805 A Street, S.E. The elevated front yard slopes north and is enclosed with a metal chain-link fence. Immature shrubs line the front porch, while mulch covers much of the yard. Concrete steps with metal railing lead from the front porch to the sidewalk below. The backyard is enclosed with a metal chain-link fence.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:  
Contributing:

Designation Event(s) \_\_\_\_\_

Survey(s)  
**Capitol Hill Southeast Phase II (2010)**

Level(s) of Investigation  
**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\  
File: 1803\_A\_Street\_SE\_facade\_looking\_SE.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\  
File: 1803\_A\_Street\_SE\_facade\_looking\_SW.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\  
File: 1803\_A\_Street\_SE\_rear\_looking\_NE.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
08/05/1924	1319	Build	

Permit Notes:

--

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0085

## BASICS DATA

ID Number: **1111-0085** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1805** **A Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 1805 A Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0085** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4285 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Santmyers, George T.**

**Orig Construction** **Builder** **Poretsky, H.**

**Orig Construction** **Owner** **Poretsky, Silver & Rosen**

Construction Notes:

**One of seven rowhouses constructed from the same permit (#1319).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 7)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1924, this single-family rowhouse was one of seven built by H. Poretsky from the same permit (#1319). The two-story, two-bay, Classical Revival-style dwelling is set on a solid concrete foundation. The masonry structure has a five-course, American-bond brick veneer. A rowlock brick sill string and a soldier brick lintel course enhance the second-story window openings. The sloped roof has a ogee-molded metal cornice. Highlighting the façade is a molded metal architrave with dentils set between firewalls. An exterior-rear brick chimney with a plain cap pierces the roofline. The main entry, located in the eastern bay of the first story, holds a single-leaf, paneled wood door with single-light transom. Window openings have single and paired 6/1, double-hung, wood-sash windows with rowlock brick sills. The façade features a one-story, full-width porch set on a brick pier foundation. A flat roof with ogee-molded cornice is supported by corbeled brick posts set on brick piers. The south (rear) elevation has a two-story porch set on a concrete pier foundation. The porch has been clad in aluminum siding and is capped by a shed roof. Two-light, vinyl-sash vinyl sliding windows fenestrate the rear of the porch. A single-leaf, paneled wood door with semi-circular light is located in the eastern bay of the first story.

Site Notes:

July 2010: Located south of A Street, S.E., this single-family rowhouse has a setback of approximately twenty feet from the concrete sidewalk. The west (side) elevation is adjacent to 1803 A Street, S.E. and the east (side) elevation to 1807 A Street, S.E. The elevated front yard slopes north and is enclosed with a metal chain-link fence. Mature trees dominate the front yard. Concrete steps with metal railing lead from the front porch to the sidewalk below. Overgrown with mature trees, the backyard extends south to an alley. A metal chain-link fence encloses the rear of the property.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

**PHOTOS - DIGITIZED**

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\

File: 1805\_A\_Street\_facade\_looking\_S.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\

File: 1805\_A\_Street\_facade\_looking\_SW.JPG

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\

File: 1805\_A\_Street\_rear\_looking\_N.JPG

Date:: Photog:

Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

[Empty text box]

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
08/05/1924	1319	Build	

Permit Notes:

[Empty text box]

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

---

Code            Criteria

---

**DATA PROCESSING EVENTS DATA**

---



# Resource All Data Report

# ID Number: 1111-0086

## BASICS DATA

ID Number: **1111-0086** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1807** **A Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 1807 A Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0086** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4285 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Santmyers, George T.**

**Orig Construction** **Builder** **Poretsky, H.**

**Orig Construction** **Owner** **Poretsky, Silver & Rosen**

Construction Notes:

**One of seven rowhouses constructed from the same permit (#1319).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 7)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

**Garage**

Contributing Status

**Contributing**

Outbuilding Notes:

**July 2010: This one-story, one-bay garage, based on its form and materials, appears to have been constructed c. 1924. The brick structure is capped by a shed roof. The façade (north elevation) has a wide, double-leaf plywood door with metal strap hinges.**

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1924, this single-family rowhouse was one of seven built by H. Poretsky from the same permit (#1319). The two-story, two-bay, Classical Revival-style dwelling is set on a solid concrete foundation. The masonry structure has a five-course, American-bond brick veneer. A rowlock brick sill string and a soldier brick lintel course enhance the second-story window openings. The sloped roof has a ogee-molded metal cornice. Highlighting the façade is a molded metal architrave with dentils set between firewalls. An exterior-rear brick chimney with a plain cap pierces the roofline. The main entry, located in the eastern bay of the first story, holds a single-leaf, paneled wood door with a large rectangular light. A single-light transom is located above. The western bay of the first story holds a tripartite vinyl-sash window with sliding sash. The second story has a single and paired opening with 1/1, double-hung, vinyl sash. The façade features a one-story, full-width porch set on a brick pier foundation. A flat roof with ogee-molded cornice is supported by corbeled brick posts set on brick piers. The south (rear) elevation has a two-story porch that has been enclosed with aluminum siding and 1/1, double-hung, vinyl-sash windows. A shed roof caps the porch. Additional details were not visible from the public right-of-way due to foliage.

Site Notes:

July 2010: Located south of A Street, S.E., this single-family rowhouse has a setback of approximately twenty feet from the concrete sidewalk. The west (side) elevation is adjacent to 1805 A Street, S.E. and the east (side) elevation to 1809 A Street, S.E. The elevated front yard slopes north and is enclosed by a wooden picket fence. Vines cover most of the front yard. Brick steps lead from the front porch to the sidewalk below. Overgrown with mature trees, the backyard extends south to an alley. A garage fronts the alley.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zone:

Designation Event(s)

Zoning:  
Contributing:

Designation Event(s)

Survey(s)  
**Capitol Hill Southeast Phase II (2010)**

Level(s) of Investigation  
**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1807\_A\_Street\_SE\_facade\_looking\_S.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1807\_A\_Street\_SE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1807\_A\_Street\_SE\_garage\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1807\_A\_Street\_SE\_rear\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
08/05/1924	1319	Build	

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code	Criteria
------	----------

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0087

## BASICS DATA

ID Number: **1111-0087** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1809** **A Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 1809 A Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0087** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4285 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Santmyers, George T.**

**Orig Construction** **Builder** **Poretsky, H.**

**Orig Construction** **Owner** **Poretsky, Silver & Rosen**

Construction Notes:

**One of seven rowhouses constructed from the same permit (#1319).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 7)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type

**Garage**

Contributing Status

**Contributing**

Outbuilding Notes:

**July 2010: This one-story, one-bay garage, based on its form and materials, appears to have been constructed c. 1924. The five-course, American-bond brick structure is capped by a shed roof with metal coping. The west (side) elevation has a door opening with a two-course, rowlock brick segmental arch**

(no door). The south elevation fronts the concrete alley and features a large opening with a cantilevered southeast corner. It is possible that this opening has been altered to adjust for easier vehicular entry. The opening has been enclosed with metal sheeting on the south elevation and a wood-frame door with multiple panels that were originally filled with glass (now enclosed with plywood).

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1924, this single-family rowhouse was one of seven built by H. Poretsky from the same permit (#1319). The two-story, two-bay, Classical Revival-style dwelling is set on a solid concrete foundation. The masonry structure has a five-course, American-bond brick veneer. A rowlock brick sill string and a soldier brick lintel course enhance the second-story window openings. The sloped roof has a ogee-molded metal cornice. Highlighting the façade is a molded metal architrave with dentils set between firewalls. An exterior-rear brick chimney with a parged cap pierces the roofline. The main entry, located in the eastern bay of the first story, holds a single-leaf, paneled wood door with three lights. A single-light transom is located above. Single and paired window openings hold 1/1, double-hung, vinyl sash. The façade features a one-story, full-width porch set on a brick pier foundation. A flat roof with ogee-molded cornice is supported by corbeled brick posts set on brick piers. The south (rear) elevation has a two-story porch set on a concrete block pier foundation. Vinyl siding now encloses the porch, which is capped by a shed roof. Fenestration consists of paired 1/1, double-hung, vinyl-sash windows with vinyl-clad surrounds.

A one-story addition has been constructed on the rear of the enclosed two-story porch. Based on its materials, it appears that this addition dates to c. 1990. Clad in vinyl siding and capped by a shed roof of asphalt shingles, the addition contains a single-leaf wood door with diamond light.

Site Notes:

July 2010: Located south of A Street, S.E., this single-family rowhouse has a setback of approximately twenty feet from the concrete sidewalk. The west (side) elevation is adjacent to 1807 A Street, S.E. and the east (side) elevation to 1811 A Street, S.E. The landscaped front yard slopes north and is enclosed by a metal chain-link fence. Mature shrubs and a tree dot the front yard. Concrete steps lead from the front porch to the sidewalk below. The backyard is enclosed with a metal security fence and includes a garage fronting the alley at the rear of the property.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panel(s)	Material
---------------	----------------	------	----------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

---

Neighborhood: <b>Capitol Hill</b>	Historic District(s) _____
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s) _____
Contributing:	
Survey(s) _____	Level(s) of Investigation _____
<b>Capitol Hill Southeast Phase II (2010)</b>	<b>Permit Research</b>
	<b>Reconnaissance Survey</b>

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1809\_A\_Street\_SE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1809\_A\_Street\_SE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1809\_A\_Street\_SE\_garage\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

## Image File Not Found

Path: X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\  
File: 1809\_A\_Street\_SE\_rear\_looking\_N.JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

---

Notes:

### PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
08/05/1924	1319	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

---

### SIGNIFICANCE DATA

---

Study Unit

---

Code Criteria

---

### DATA PROCESSING EVENTS DATA

---



# Resource All Data Report

# ID Number: 1111-0088

## BASICS DATA

ID Number: **1111-0088** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1811** **A Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 1811 A Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0088** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4285 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Santmyers, George T.**

**Orig Construction** **Builder** **Poretsky, H.**

**Orig Construction** **Owner** **Poretsky, Silver & Rosen**

Construction Notes:

**One of seven rowhouses constructed from the same permit (#1319).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 7)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

**Garage**

Contributing Status

**Contributing**

Outbuilding Notes:

**July 2010: This one-story, one-bay garage, based on Sanborn Fire Insurance Company maps, its rock-faced exterior, and condition, this garage can be assigned a construction date of c. 1965. Set on a concrete slab, this rock-faced concrete structure is capped by a flat roof with metal coping. A stepped**

parapet along the façade (south elevation) embellishes this simple building. A wide opening is located on the façade, however, only one of the leafs is intact. Constructed of plywood covered with vertical pressed metal, the door has metal strap hinges. A single-leaf door opening (no door) is located on the east (side) elevation. The east elevations has no openings. The north elevation was not visible from the public right-of-way.

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1924, this single-family rowhouse was one of seven built by H. Poretzky from the same permit (#1319). The two-story, two-bay, Classical Revival-style dwelling is set on a solid concrete foundation. The masonry structure has a five-course, American-bond brick veneer. A rowlock brick sill string and a soldier brick lintel course enhance the second-story window openings. The sloped roof has a ogee-molded metal cornice. Highlighting the façade is a molded metal architrave with dentils set between firewalls. An exterior-rear brick chimney with a parged cap pierces the roofline. The main entry, located in the eastern bay of the first story, holds a single-leaf, paneled wood door with lights. A single-light transom is located above. A tripartite window composed of fixed and sliding vinyl sash is located in the western bay of the first story. The second story has a single and paired opening with 1/1, double-hung, vinyl-sash windows. All openings have rowlock brick sills and soldier brick jack arches. The façade features a one-story, full-width porch set on a brick pier foundation. A flat roof with molded cornice is supported by corbeled brick posts set on brick piers.

The south (rear) elevation has a two-story, full-width original porch that has been enclosed. This enclosed porch has been integrated into a c. 2000 rear addition, also clad in vinyl siding. A shed roof caps the addition while 1/1, double-hung, vinyl-sash windows with false 6/6 muntins pierce the walls. The second story is cantilevered out from the first story forming a full-width rear porch supported by wood posts.

Site Notes:

July 2010: Located south of A Street, S.E., this single-family rowhouse has a setback of approximately twenty feet from the concrete sidewalk. The west (side) elevation is adjacent to 1819 A Street, S.E. and the east (side) elevation to 1813 A Street, S.E. The landscaped front yard slopes north and is enclosed by a metal chain-link fence. Mature shrubs and foundation plantings compliment the manicured lawn. A brick walkway extends off the front porch to the sidewalk. The backyard extends south to a concrete alley. Most of the backyard is occupied by a garage, which fronts the alley.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

---

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill Southeast Phase II (2010)</b>	<b>Permit Research</b> <b>Reconnaissance Survey</b>

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1811\_A\_Street\_SE\_facade\_looking\_SE.JPG**

Date::                      Photog:

Code::                                      R:              Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1811\_A\_Street\_SE\_facade\_looking\_SW.JPG**

Date::                      Photog:

Code::                                      R:              Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1811\_A\_Street\_SE\_garage\_looking\_NE.JPG**

Date::                      Photog:

Code::                                      R:              Fr:

Caption:

## Image File Not Found

Path: X:\SD Databases\SE Phase  
 I\Database\Pictures\Square 1111\  
 File: 1811\_A\_Street\_SE\_garage\_looking\_NW.JPG  
 Date:: Photog:  
 Code:: R: Fr:

Caption:

## Image File Not Found

Path: X:\SD Databases\SE Phase  
 I\Database\Pictures\Square 1111\  
 File: 1811\_A\_Street\_SE\_rear\_looking\_NE.JPG  
 Date:: Photog:  
 Code:: R: Fr:

Caption:

## Image File Not Found

Path: X:\SD Databases\SE Phase  
 I\Database\Pictures\Square 1111\  
 File: 1811\_A\_Street\_SE\_rear\_looking\_NW.JPG  
 Date:: Photog:  
 Code:: R: Fr:

### PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

### MISCELLANEOUS NOTES DATA

Notes:

### PERMIT DATA

Permit Issue Date	Number	Type	Remarks
08/05/1924	1319	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

### SIGNIFICANCE DATA

Study Unit

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0089

## BASICS DATA

ID Number: **1111-0089** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1813** **A Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 1813 A Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0089** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1924** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1924** **Permit** **4285 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Santmyers, George T.**

**Orig Construction** **Builder** **Poretsky, H.**

**Orig Construction** **Owner** **Poretsky, Silver & Rosen**

Construction Notes:

**One of seven rowhouses constructed from the same permit (#1319).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 7)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1924, this single-family rowhouse was one of seven built by H. Poretsky from the same permit (#1319). The two-story, two-bay, Classical Revival-style dwelling is set on a solid concrete foundation. The masonry structure has a five-course, American-bond brick veneer. A rowlock brick sill string and a soldier brick lintel course enhance the second-story window openings. The sloped roof has a ogee-molded metal cornice. Highlighting the façade is a molded metal architrave with dentils set between firewalls. An exterior-rear brick chimney with a corbeled cap pierces the roofline. The main entry, located in the eastern bay of the first story, holds a single-leaf, paneled wood door with semi-circular light and single-light transom. Window openings hold single and paired 1/1, double-hung, vinyl sash. All openings have rowlock brick sills and soldier brick jack arches. The façade features a one-story, full-width porch set on a brick pier foundation with brick infill. A flat roof with molded metal cornice is supported by corbeled brick posts set on brick piers. The south (rear) elevation has a two-story porch that has been enclosed with German vinyl siding. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows with vinyl-clad surrounds. A single-leaf, paneled metal door with nine lights is located in the eastern bay of the first story.

Site Notes:

July 2010: Located south of A Street, S.E., this single-family rowhouse has a setback of approximately twenty feet from the concrete sidewalk. The west (side) elevation is adjacent to 1811 A Street, S.E. and the east (side) elevation to 1815 A Street, S.E. Sloping northward, the manicured lawn has immature foundation plantings and is partially enclosed by a metal chain-link fence. Concrete steps lead from the front porch to the sidewalk below, which is lined by a stone retaining wall. The backyard extends south to an alley and is enclosed by a wooden privacy fence. A wooden deck has been constructed on the rear of the dwelling.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Designation Level(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research  
Reconnaissance Survey

**PHOTOS - DIGITIZED**

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1813\_A\_Street\_SE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1813\_A\_Street\_SE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1813\_A\_Street\_SE\_rear\_looking\_N.JPG  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
08/05/1924	1319	Build	



Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0013

## BASICS DATA

ID Number: **1111-0013**      Year Built: **1925**      Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>1815</b>		<b>A Street</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Apartment Building, 1815 A Street, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0013</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building**      Status Current: **Extant**  
Desig. Status: **Historic**      Quality:  
Purpose: **Residential**      Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential</b>	<b>1925</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1925</b>	<b>Permit</b>			<b>35000 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Santmyers, George T.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Poretsky, H.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Poretsky, Silver &amp; Rosen</b>

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached (1 side)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Block**  
Footprint: **U-Shaped (irregular)**

Cross Reference Notes:

Number Stories: **2**  
Bays Wide: **5**  
Height:  
Width: **46**  
Depth/Length: **42**

Outbuilding Type	Contributing Status
------------------	---------------------

SqFt:  
Volume:  
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**  
**Colonial Revival**

Exterior & Architectural Notes:

July 2010: This apartment building was constructed in 1925 by H. Poretsky at a cost of \$35,000. With fourteen units, this building has a modified rectangular form. Wet on a solid concrete foundation, this brick structure has six-course, American-bond brickwork. A molded concrete sill course spans the first story of the façade. A flat roof is obscured by a brick parapet wall with decorative brick panels. Delineating the main block and the parapet wall is a molded stringcourse with basket weave brick topped by a metal architrave. With inspiration of both the Classical Revival and Colonial Revival styles, this two-story-on-raised-basement building is five-bays wide. Symmetrically fenestrated, the main entry is centrally located and composed of a single-leaf, wood-frame glass door. The wide paneled wood frame includes a single-light transom. A concrete surround with molded entablature completes the opening. Flanking the door opening are small, 1/1, double-hung, vinyl-sash windows with concrete lug sills and soldier brick jack arches. The outerbays of the first story hold tripartite 1/1, double-hung, vinyl-sash windows with blank pilasters. These wide outerbays have a round arched surround composed of soldier brick jack arches with rounded concrete panels with molded urns and ribbons. Second story fenestration closely mirrors that of the first story. The central bay holds a 1/1, double-hung, vinyl-sash windows with concrete sill. Small, 1/1, double-hung, vinyl-sash windows with concrete sills flank the central bay. Outerbays hold tripartite 1/1, double-hung, vinyl-sash windows with blank pilasters and concrete sills. Festooned concrete panels highlight the area between the first- and second-story openings. Window openings on the secondary elevations contain single and paired 1/1, double-hung, vinyl-sash windows with rowlock brick sills.

Site Notes:

July 2010: This apartment building is located south of A Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The slightly elevated manicured lawn slopes north and includes immature foundation plantings and shrubs. Mulched planting beds flank a wide concrete walkway and steps leading from the main entry to the sidewalk. Semi-detached, the west (side) elevation is adjacent to 1813 A Street, S.E. A concrete alley fronts the east (side) elevation. The alley extends to front the rear of the building.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

---

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

---

Survey(s)

Level(s) of Investigation

---

**Capitol Hill Southeast Phase II (2010)**

**Permit Research**

**Reconnaissance Survey**

---

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\**

File: **1815\_A\_Street\_SE\_facade\_looking\_S.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\**

File: **1815\_A\_Street\_SE\_facade\_looking\_SE.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\**

File: **1815\_A\_Street\_SE\_facade\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\**

File: **1815\_A\_Street\_SE\_rear\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

---

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code          Roll          Frame(s)          Date          Photographer          Caption

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
10/23/1925	3825	Build	

---

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code          Criteria \_\_\_\_\_

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0103

## BASICS DATA

ID Number: **1111-0103** Year Built: **1937** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1820 Independence Avenue SE Current**

Name(s) Type of Name

**Multiple Dwelling, 1820 Independence Avenue, S.E. Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0103 Square/Lot Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential 1937 Permit Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction 1937 Permit 10000 Permit**

Construction Event Association Associated Name

**Orig Construction Architect Holsople, T.**

**Orig Construction Builder Saunders, R.B.**

**Orig Construction Owner Saunders, R.B.**

Construction Notes:

**One of three buildings constructed from the same permit (#202144).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached (1 side)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Flat Front**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **34**

Depth/Length: **40**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

July 2010: This two-story, three-bay apartment building was constructed in 1937 by R.B. Saunders. Saunders constructed a total of three similar apartment buildings on Independence Avenue, S.E. under the same permit (#202144). Set on a solid brick and concrete foundation, this concrete structure has six-course, American-bond brickwork. The sloped roof is hidden by a false mansard roof of asphalt shingles and a stepped brick parapet found on the west (side) elevation. Front-gabled pediments in the outerbays of the façade interrupt brickwork designed to mimic dentils across the façade. A metal gutter system has been attached to the façade. A brick chimney rises from the interior of the building. The main entry, centrally located on the façade, is located in a projecting bay with quoins and a hipped metal roof. A single-leaf, paneled metal door with two-lights is set in a narrow, square-edge wood surround. Window openings contain 1/1, double-hung, vinyl-sash windows with concrete sills. The outerbays are paired. Fenestration of the west (side) elevation consists of 1/1, double-hung, vinyl-sash windows with false muntins and rowlock brick sills. The north (rear) elevation has a two-story, full-width porch that has been enclosed with German vinyl siding. The porch, set on a solid concrete foundation, is pierced with 1/1, double-hung, vinyl-sash windows and single-leaf, paneled metal doors. The second-story door has a semi-circular light and is accessed via a wood stair.

Site Notes:

July 2010: This apartment building turned condo is located north of Independence Avenue, S.E. With a setback of approximately twenty feet from the concrete sidewalk, this building is adjacent to 1826 Independence Avenue, S.E. A concrete alley extends along the west (side) elevation of the building to also form the northern boundary of the property. The small, grassy front yard is raised and lined by a stone retaining wall. A concrete walkway links the sidewalk with the front porch. The level, grassy backyard is enclosed with a metal chain-link fence. A concrete walkway extends from the rear entry north to the alley.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source

Wall Component	Material	Color	Treatment	Source

Structure Component	Material	Feature	Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material

Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:  
Zoning:  
Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research  
Reconnaissance Survey

### PHOTOS - DIGITIZED

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1820\_Independence\_Avenue\_SE\_facade\_loo  
king\_N.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1820\_Independence\_Avenue\_SE\_facade\_loo  
king\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1820\_Independence\_Avenue\_SE\_rear\_loo  
king\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

---

Notes:

### PERMIT DATA

---



Permit Issue Date	Number	Type	Remarks
05/05/1937	202144	Build	

Permit Notes:

---

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

Study Unit

---

Code

Criteria

---

---

**DATA PROCESSING EVENTS DATA**

# Resource All Data Report

# ID Number: 1111-0102

## BASICS DATA

ID Number: **1111-0102** Year Built: **1937** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>1826</b>		<b>Independence Avenue</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Multiple Dwelling, 1826 Independence Avenue, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0102</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Multi-Family)</b>	<b>1937</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1937</b>	<b>Permit</b>			<b>10000 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Holsople, T.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Saunders, R.B.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Saunders, R.B.</b>

Construction Notes:

**One of three buildings constructed from the same permit (#202144).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Flat Front**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**  
Bays Wide: **3**  
Height:  
Width: **34**  
Depth/Length: **40**  
SqFt:

Outbuilding Type	Contributing Status
------------------	---------------------

Volume:  
Lot Width  
Lot Depth/Length:  
Lot SqFt:  
Acreage:  
Has Driveway:

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1937 by R.B. Saunders, this four-unit apartment building is one of three apartment buildings constructed under the same permit (#202144). Set on a solid concrete and brick foundation, this concrete structure has six-course, American-bond brickwork. While a sloped roof covers the building, the façade is dominated by false mansard with a front-gabled pediment. The pediment has a metal cornice with short returns and features a circular molded concrete panel with rowlock brick surround and concrete impost. The main entry, located in the projecting middle bay, contains a paneled metal door with rectangular light. The projecting bay features quoins and is capped by a front-gabled roof with a closed pediment of weatherboard siding. Single and paired window openings hold 1/1, double-hung, vinyl-sash windows with concrete sills. The north (rear) elevation has a two-story, full-width porch that has been enclosed with German vinyl siding. Capped by a shed roof, the porch now includes single and paired 1/1, double-hung, vinyl-sash windows with vinyl-clad surrounds. Single-leaf, paneled doors are located on both stories. Metal stairs with a metal awning provide access to the second-story door opening.

Site Notes:

July 2010: This apartment building is located north of Independence Avenue, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The west (side) elevation is adjacent to 1820 Independence Avenue, S.E. and the east (side) elevation to 1830 Independence Avenue, S.E. The raised grassy front yard has a stone retaining wall aside the sidewalk. A wide concrete walkway and steps with metal railing proceed from the front stoop to the sidewalk. A large concrete parking pad occupies the backyard.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributor:

Contributing:

Survey(s)

Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1826\_Independence\_Avenue\_SE\_facade\_loo  
king\_N.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1826\_Independence\_Avenue\_SE\_facade\_loo  
king\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1826\_Independence\_Avenue\_SE\_rear\_loo  
king\_S.JPG  
Date:: Photog:  
Code:: R: Fr:

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
05/05/1937	202144	Build	

---

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0101

## BASICS DATA

ID Number: **1111-0101** Year Built: **1937** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1830 Independence Avenue SE Current**

Name(s) Type of Name

**Multiple Dwelling, 1830 Independence Avenue, S.E. Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0101 Square/Lot Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family) 1937 Permit Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction 1937 Permit 10000 Permit**

Construction Event Association Associated Name

**Orig Construction Architect Holsople, T.**

**Orig Construction Builder Saunders, R.B.**

**Orig Construction Owner Saunders, R.B.**

Construction Notes:

**One of three buildings constructed from the same permit (#202144).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **34**

Depth/Length: **40**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

July 2010: This two-story, three-bay apartment building was constructed in 1937 by R.B. Saunders. Saunders constructed a total of three similar apartment buildings on Independence Avenue, S.E. under the same permit (#202144). Set on a solid brick and concrete foundation, this concrete structure has six-course, American-bond brickwork. The sloped roof is hidden by a false mansard roof of slate shingles. Front-gabled pediments extend up from the façade, interrupting a corbeled brick cornice designed to mimic dentils. Metal gutter downpipes have been attached to the façade. A brick chimney with a corbeled cap rises from the interior-rear of the building. Two, approximately two-feet tall louvered ventilators are located on the roof. A one-story projecting bay centrally located on the façade holds the main entry. This projecting bay has a brick veneer with quoins. A hipped metal roof with a thin overhanging eaves and wide fascia board caps the projecting bay. Set in a slightly recessed opening, the main entry holds a single-leaf, paneled wood door with two lights and a thin ogee-molded lintel. Window openings contain 1/1, double-hung, vinyl-sash windows with concrete sills. The outerbays are paired. The north (rear) elevation has a two-story, full-width porch that has been enclosed with vinyl siding. The porch, set on a solid concrete foundation, is pierced with 1/1, double-hung, vinyl-sash windows and single-leaf, flush metal doors. A second-story integral porch is accessed via a metal stair. Centrally located on the rear of the dwelling, the integral porch holds two opposing single-leaf door openings.

Site Notes:

July 2010: This apartment building is located north of Independence Avenue, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The west (side) elevation is attached to 1826 Independence Avenue, S.E. and the east (side) elevation to 1832-1834 Independence Avenue, S.E. The slightly raised front yard has immature foundation shrubs lining the foundation. A concrete walkway with steps and metal railing extends from the front stoop to the concrete sidewalk. The rear of the property extends north to an alley. Metal chain-link fences extend down the sides of the backyard, which has been mostly covered with concrete to make parking spaces.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase II (2010)**

**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1830\_Independence\_Avenue\_SE\_facade\_loo  
king\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1830\_Independence\_Avenue\_SE\_facade\_loo  
king\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1830\_Independence\_Avenue\_SE\_rear\_loo  
king\_S.JPG**

Date:: Photog:

Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

[Empty text box for notes]



**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
05/05/1937	202144	Build	

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code            Criteria \_\_\_\_\_

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0030

## BASICS DATA

ID Number: **1111-0030** Year Built: **1952** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1832 -1834 Independence Avenue SE Current**

Name(s) Type of Name

**Duplex, 1832-1834 Independence Avenue, S.E. Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0030 Square/Lot Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family) 1952 Permit Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction 1952 Permit**

Construction Event Association Associated Name

**Schavach, G.E. Owner Schavach, G.E.**

Construction Notes:

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Flat Front**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **3**

Height:

Outbuilding Type

Contributing Status

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway:

## STYLE/EXTERIOR DATA

**Modern**

Exterior & Architectural Notes:

**July 2010:** Constructed in 1952 by owner G.E. Schavach, this two-story, three-bay apartment building has two units. Set on a solid concrete foundation, this masonry structure has six-course, American-bond brickwork. A sloped roof covers the dwelling, having metal coping and an exterior-rear brick chimney with a plain cap. The façade (south elevation) features a slightly projecting western half, which contains the two main entries. These entries hold single-leaf, paneled metal doors with lights set in narrow, square-edge wood surrounds. A common concrete stoop provides access. Above these two door openings is a centrally placed 1/1, double-hung, vinyl-sash windows with rowlock brick sill. The eastern half of the façade features paired openings on each story. These openings have 1/1, double-hung, vinyl-sash windows with rowlock or header brick sills. The north (rear) elevation has 1/1, double-hung, vinyl-sash windows and single-leaf, paneled metal doors with lights. The second-story door opening is accessed via a metal stair.

Site Notes:

**July 2010:** Located north of Independence Avenue, S.E., this multi-family apartment building has a setback of approximately twenty feet from the concrete sidewalk. The west (side) elevation is adjacent to 1830 Independence Avenue, S.E. and the east (side) elevation to 1836 Independence Avenue, S.E. The raised, grassy front yard is contained by a coursed stone retaining wall aside the sidewalk. A concrete walkway extends from the front stoop to the sidewalk. The backyard has been covered with poured concrete to form a driveway. An alley is located north of the property.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill** Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase II (2010)**

**Permit Research**

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
 I\Database\Pictures\Square 1111\  
 File: 1832-  
 1834\_Independence\_Avenue\_SE\_facade\_loo  
 ki  
 ng\_N.JPG  
 Date:: Photog:  
 Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
 I\Database\Pictures\Square 1111\  
 File: 1832-  
 1834\_Independence\_Avenue\_SE\_facade\_loo  
 ki  
 ng\_NE.JPG  
 Date:: Photog:  
 Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
 I\Database\Pictures\Square 1111\  
 File: 1832-  
 1834\_Independence\_Avenue\_SE\_rear\_loo  
 king\_S.JPG  
 Date:: Photog:  
 Code:: R: Fr:

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
04/03/1952	A-29448	Build	

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

**ID Number: 1111-0044**

## BASICS DATA

ID Number: **1111-0044** Year Built: **1935** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>1836</b>		<b>Independence Avenue</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Multiple Dwelling, 1836 Independence Avenue, S.E.</b>	<b>Common</b>
<b>Armory Place Condominium</b>	<b>Current</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0044</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Residential** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Multi-Family)</b>	<b>1935</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1935</b>	<b>Permit</b>			<b>8000 Permit</b>

Construction Event	Association	Associated Name
<b>Morgan, Joseph P.</b>	<b>Owner</b>	<b>Morgan, Joseph P.</b>
<b>Orig Construction</b>	<b>Architect</b>	<b>Johannes, Dana B.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Davis &amp; Platt</b>

Construction Notes:

**One of three buildings constructed from the same permit (#183658).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Attached**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Block**  
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**  
 Bays Wide: **3**  
 Height: **33**  
 Width: **40**  
 Depth/Length: **40**

Outbuilding Type \_\_\_\_\_ Contributing Status \_\_\_\_\_

SqFt:  
 Volume:  
 Lot Width  
 Lot Depth/Length:  
 Lot SqFt:  
 Acreage:  
 Has Driveway:

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

**July 2010: Constructed in 1935, this two-story, three-bay apartment building is one of three similar buildings built under the same permit (#183658) by Davis + Platt, Inc. Now known as Armory Place Condominium, this four-unit building combines multiple styles yet maintains a Colonial Revival influence. Set on a solid brick foundation, this masonry structure has a six-course, American-bond brick veneer. The sloped roof features a brick parapet wall set above a soldier brick string with metal coping. An exterior-rear brick chimney with a plain cap completes the roofline. The façade (south elevation) features a centrally located main entry. The single-leaf, paneled metal door with lights is set in a molded wood surround with three-light sidelights. Above the door opening, an oculus window with rowlock brick surround pierces the second story. Brick pilasters flank these central openings and extend into the parapet, lending the façade depth. The outerbays of the first story hold three-sided canted bays with 1/1, double-hung, vinyl-sash windows. Half-hipped roofs of asphalt shingles cap the bays, which share a brick veneer. Below the concrete sill course, each canted bay has a large blank panel. Fenestration of the outermost bays of the second story consists of 1/1, double-hung, vinyl-sash windows with concrete sills and soldier brick jack arches. The north (rear) elevation has a two-story, full-width original porch that has been subsequently enclosed with vinyl siding. Although the porch has been enclosed, the original brick supports remain exposed. Fenestration consists of paired, 1/1, double-hung, vinyl-sash windows and four, single-leaf, paneled metal doors with nine lights. A wood deck with stairs provides access to the second-story door openings.**

Site Notes:

**July 2010: This apartment building is located north of Independence Avenue, S.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The building is sited closed to the street than the building it is adjacent with to the west (1832-1834 Independence Avenue, S.E.) and even with the apartment building to the east 1840 Independence Avenue, S.E. The level, grassy front yard has been landscaped with immature shrubs and a coursed stone retaining wall aside the sidewalk. A concrete walkway extends from the front stoop to the sidewalk. The backyard extends north to an alley and has been enclosed with a wooden privacy fence.**

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

---

Window Location      Aperture Shape      Type      Lights      Material

---

Door Location      Aperture Shape      Type      Panels      Material

---

Notable Interior Plan(s)

---

Notable Interior Feature(s)

---

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

---

Neighborhood:      **Capitol Hill**

Historic District(s)

---

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

---

Contributing:

Survey(s)

---

Level(s) of Investigation

---

**Capitol Hill Southeast Phase II (2010)**

**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path:      **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File:      **1836\_Independence\_Avenue\_SE\_facade\_lookin  
g\_NE.JPG**

Date::      Photog:

Code::      R:      Fr:

---

Caption:

**Image File Not Found**

Path:      **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File:      **1836\_Independence\_Avenue\_SE\_facade\_lookin  
g\_NW.JPG**

Date::      Photog:

Code::      R:      Fr:

---



Caption:

## Image File Not Found

Path: X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\  
File: 1836\_Independence\_Avenue\_SE\_rear\_looking\_S  
.JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

---

Notes:

### PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
08/20/1935	183658	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

---

### SIGNIFICANCE DATA

---

Study Unit \_\_\_\_\_

Code Criteria \_\_\_\_\_

### DATA PROCESSING EVENTS DATA

---

# Resource All Data Report

**ID Number: 1111-0042**

## BASICS DATA

ID Number: **1111-0042** Year Built: **1935** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1840 Independence Avenue SE Current**

Name(s) Type of Name

**Multiple Dwelling, 1840 Independence Avenue, Common**

**S.E.**

**Armory Place Condominium Current**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0042 Square/Lot Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family) 1935 Permit Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction 1935 Permit 8000 Permit**

Construction Event Association Associated Name

**Orig Construction Architect Johannes, Dana B.**

**Orig Construction Builder Davis & Platt**

**Orig Construction Owner Morgan, Joseph P.**

Construction Notes:

**One of three buildings constructed from the same permit (#183658).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
 Streetscape: **Intact**  
 Relate to Othr Bldgs: **Attached**  
 Relate to Street: **Face on Setback Line**  
 Massing: **Block**  
 Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**  
 Bays Wide: **3**  
 Height: **33**  
 Width: **40**  
 Depth/Length: **40**

Outbuilding Type \_\_\_\_\_ Contributing Status \_\_\_\_\_

SqFt:  
 Volume:  
 Lot Width  
 Lot Depth/Length:  
 Lot SqFt:  
 Acreage:  
 Has Driveway:

Outbuilding Notes:

### STYLE/EXTERIOR DATA

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

**July 2010: Constructed in 1935, this two-story, three-bay apartment building is one of three similar buildings built under the same permit (#183658) by Davis + Platt, Inc. Now known as Armory Place Condominium, this four-unit building combines multiple styles yet maintains a Colonial Revival influence. Set on a solid brick foundation, this masonry structure has a six-course, American-bond brick veneer. The sloped roof features a brick parapet wall set above a soldier brick string with metal coping. An exterior-rear brick chimney with a plain cap completes the roofline. The façade (south elevation) features a centrally located, rounded headed main entry. A single-leaf, paneled metal door is set in a molded wood surround with a blank sidelight beneath a blank semi-circular transom and a soldier brick arch. Above the door opening, a small, 1/1, double-hung, vinyl-sash window with concrete sill and soldier brick jack arch pierces the second story. Brick pilasters flank these central openings and extend into the parapet. An ogee-molded pediment adorns this feature. The outerbays of the first story hold three-sided canted bays with 1/1, double-hung, vinyl-sash windows. Half-hipped roofs of slate shingles cap the bays, which share a brick veneer. Below the concrete sill course, each canted bay has a large blank panel. Fenestration of the outermost bays of the second story consists of 1/1, double-hung, vinyl-sash windows with concrete sills and soldier brick jack arches. The north (rear) elevation has a two-story, full-width original porch that has been subsequently enclosed with vertical board and ribbons of 1/1, double-hung, vinyl-sash windows. Original brick supports remain exposed. Additional details were not visible from the public right-of-way.**

Site Notes:

**July 2010: This apartment building is located north of Independence Avenue, S.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The building is adjacent to 1836 and 1844 Independence Avenue, S.E. The raised front yard has a manicured lawn and immature trees and shrubs. A coursed stone retaining wall is located next to the sidewalk. Extending between the concrete front stoop and the sidewalk is a concrete walkway. The rear of the property is enclosed with a wooden privacy fence and includes immature trees.**

### NOTABLE FEATURES DATA

Component	Feature
-----------	---------

### EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

---

Window Location      Aperture Shape      Type      Lights      Material

---

Door Location      Aperture Shape      Type      Panels      Material

---

Notable Interior Plan(s) \_\_\_\_\_

Notable Interior Feature(s) \_\_\_\_\_

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

---

Neighborhood:      **Capitol Hill**

Historic District(s) \_\_\_\_\_

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s) \_\_\_\_\_

Contributing:

Survey(s) \_\_\_\_\_

Level(s) of Investigation \_\_\_\_\_

**Capitol Hill Southeast Phase II (2010)**

**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path:      **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File:      **1840\_Independence\_Avenue\_SE\_facade\_loo  
king\_NE.JPG**

Date::      Photog:

Code::      R:      Fr:

---

Caption:

**Image File Not Found**

Path:      **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File:      **1840\_Independence\_Avenue\_SE\_facade\_loo  
king\_NW.JPG**

Date::      Photog:

Code::      R:      Fr:

---

Caption:

## Image File Not Found

Path: X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\  
File: 1840\_Independence\_Avenue\_SE\_rear\_looking  
\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

---

Notes:

### PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
08/20/1935	183658	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

---

### SIGNIFICANCE DATA

---

Study Unit \_\_\_\_\_

Code            Criteria \_\_\_\_\_

### DATA PROCESSING EVENTS DATA

---

# Resource All Data Report

# ID Number: 1111-0040

## BASICS DATA

ID Number: **1111-0040** Year Built: **1935** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1844 Independence Avenue SE Current**

Name(s) Type of Name

**Multiple Dwelling, 1844 Independence Avenue, S.E. Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0040 Square/Lot Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family) 1935 Permit Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction 1935 Permit 8000 Permit**

Construction Event Association Associated Name

**Orig Construction Architect Johannes, Dana B.**

**Orig Construction Builder Davis & Platt**

**Orig Construction Owner Morgan, Joseph P.**

Construction Notes:

**One of three buildings constructed from the same permit (#183658).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached (1 side)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **33**

Depth/Length: **40**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1935, this two-story, three-bay apartment building is one of three similar buildings built under the same permit (#183658) by Davis + Platt, Inc. This four-unit building combines multiple styles yet maintains a Colonial Revival influence. Set on a solid brick foundation, this masonry structure has a six-course, American-bond brick veneer. The sloped roof features a brick parapet wall set above a soldier brick string with metal coping. An exterior-rear brick chimney with a corbeled cap completes the roofline. The façade (south elevation) has a centrally located, double-leaf, multi-light wood door set in a molded wood surround. Above the door opening, a four-light oculus window with rowlock brick surround pierces the second story. Brick pilasters flank these central openings and extend into the parapet, balancing the protruding bay windows located in the outerbays of the first story. The three-sided brick canted bays have 1/1, double-hung, vinyl-sash windows with half-hipped roofs of slate shingles. Below the concrete sill course, each canted bay has a large parged panel. Fenestration of the outermost bays of the second story consists of 1/1, double-hung, vinyl-sash windows with concrete sills and soldier brick jack arches. Window openings on the east (side) elevation hold 1/1, double-hung, vinyl-sash windows with concrete sills. Twin brick pilasters give the side elevation vertical emphasis with three architectural bays. The north (rear) elevation has a two-story, full-width original porch that has been subsequently enclosed with vinyl siding. Although the porch has been enclosed, the original brick supports remain exposed. Fenestration consists of 1/1, double-hung, vinyl-sash windows and two, single-leaf paneled doors. Wood steps provide access to the first-story door openings.

Site Notes:

July 2010: Located on a corner lot northwest of the intersection of Independence Avenue, S.E. and 19th Street, S.E., this apartment building has a setback from the concrete sidewalk of approximately fifteen feet. The west (side) elevation is adjacent to 1840 Independence Avenue, S.E. The slightly raised, grassy front and side yards feature a coursed stone retaining wall aside the sidewalks. Mature trees dot the property. The backyard is enclosed with a metal security fence.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase II (2010)**

**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1844\_Independence\_Avenue\_SE\_facade\_loo  
king\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1844\_Independence\_Avenue\_SE\_facade\_loo  
king\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1844\_Independence\_Avenue\_SE\_rear\_loo  
king\_SW.JPG**

Date:: Photog:

Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

[Empty text box for notes]



**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
08/20/1935	183658	Build	

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code            Criteria \_\_\_\_\_

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0077

## BASICS DATA

ID Number: **1111-0077**      Year Built: **1924**      Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>120</b>		<b>18th Street</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 120 18th Street, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0077</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building**      Status Current: **Extant**  
Desig. Status: **Historic**      Quality:  
Purpose: **Rowhouse**      Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1924</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1924</b>	<b>Permit</b>			<b>4125 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Stewart, N.A.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Burch, G.E.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Burch, G.E.</b>

Construction Notes:

**One of four rowhouses constructed from the same permit (#4083).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 4)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**  
Bays Wide: **3**  
Height:      **16**  
Width:      **26**  
Depth/Length:      **26**  
SqFt:  
Volume:  
Lot Width

Outbuilding Type	Contributing Status
------------------	---------------------

Lot Depth/Length:  
Lot SqFt:  
Acreage:  
Has Driveway:

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1924 by G.E. Burch, this two-story, two-bay single-family rowhouse is one of four constructed under the same permit (#4083). This Classical Revival-style dwelling is set on a solid brick foundation. The brick structure has five-course, American-bond brickwork and is capped by a shed roof. A slate shingle pent roof extends between brick firewalls along the façade (west elevation). Exposed bracket ends highlight the pent roof. An interior-rear brick chimney with a plain cap rises from the east elevation of the main block. Located in the southern bay, the main entry holds a single-leaf, paneled wood door with a single-light transom. Window openings, both single and paired, have 1/1, double-hung, vinyl sash with concrete sills. Soldier brick courses extend above the first- and second-story openings. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation with decorative concrete block infill, this porch has a flat roof with a molded metal cornice and overhanging eaves. Brick posts support the roof while metal balusters extend between. An original two-story, full-width rear porch has been enclosed. The first story is clad in Bricktex and the second story in aluminum siding. A shed roof caps the porch. Fenestration consists of 1/1, double-hung, vinyl-sash windows with vinyl-clad surrounds and single-leaf, paneled metal doors with lights. The brick pier foundation has also been enclosed and a single-leaf, wood-frame glass door installed. Concrete steps lead down to this opening.

The second-story deck has been constructed on the rear of the dwelling. This wood-frame porch has a shed roof of corrugated metal supported by wood posts. Square balusters complete the porch.

Site Notes:

July 2010: This single-family rowhouse is located on the east side of 18th Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The north (side) elevation is adjacent to 118 18th Street, S.E. and the south (side) elevation to 122 18th Street, S.E. The raised grassy front yard has a stone retaining wall and is enclosed with a metal chain-link fence. A concrete walkway extends off the front porch down to the sidewalk. The backyard, partially covered by a concrete patio, extends east to an alley. A metal chain-link fence encloses the rear of the lot.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase II (2010)**

**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **120\_18th\_Street\_SE\_facade\_looking\_E.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **120\_18th\_Street\_SE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **120\_18th\_Street\_SE\_rear\_looking\_W.JPG**

Date:: Photog:

Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code \_\_\_\_\_

Criteria \_\_\_\_\_

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0076

## BASICS DATA

ID Number: **1111-0076** Year Built: **1924** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>122</b>		<b>18th Street</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 122 18th Street, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0076</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1924</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1924</b>	<b>Permit</b>			<b>4125 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Stewart, N.A.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Burch, G.E.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Burch, G.E.</b>

Construction Notes:

**One of four rowhouses constructed from the same permit (#4083).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 4)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**  
Bays Wide: **2**  
Height:   
Width: **16**  
Depth/Length: **26**  
SqFt:  
Volume:  
Lot Width

Outbuilding Type	Contributing Status
------------------	---------------------

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1924 by G.E. Burch, this two-story, two-bay single-family rowhouse is one of four constructed under the same permit (#4083). This Classical Revival-style dwelling is set on a solid brick foundation. The brick structure has five-course, American-bond brickwork and is capped by a shed roof. An asphalt shingle pent roof extends between brick firewalls along the façade (west elevation). Exposed bracket ends highlight the pent roof. An interior-rear brick chimney with a plain cap rises from the east elevation of the main block. Located in the southern bay, the main entry holds a single-leaf flush wood door with three lights and a single-light wood transom. Window openings, both single and paired, have 1/1, double-hung, vinyl sash with concrete sills. Soldier brick courses extend above the first- and second-story openings. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation with brick infill, this porch has a flat roof with a molded metal cornice and overhanging eaves. Brick posts support the roof, visually enhanced with a brick balustrade. The east (rear) elevation is fenestrated with 1/1, double-hung, vinyl-sash windows with rowlock brick sills and single-leaf, paneled wood doors with lights located on the first and second stories. An original, two-story, full-height porch shelters the rear of the dwelling. Capped by shed roof, the porch has square wood posts and square wood balusters. Metal awnings have been attached to both stories.

Site Notes:

July 2010: This single-family rowhouse is located on the east side of 18th Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The north (side) elevation is adjacent to 120 18th Street, S.E. and the south (side) elevation to 124 18th Street, S.E. The raised grassy front yard has a stone retaining wall and metal chain-link fencing down the sides. A concrete walkway with metal railing extends off the front porch down to the sidewalk. The backyard has brick steps coming off the back porch. A metal chain-link fence encloses the rear of the property. An alley is located east of the property.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:  
Contributing:

Designation Event(s) \_\_\_\_\_

Survey(s)  
**Capitol Hill Southeast Phase II (2010)**

Level(s) of Investigation  
**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**  
File: **122\_18th\_Street\_SE\_facade\_looking\_E.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**  
File: **122\_18th\_Street\_SE\_facade\_looking\_SE.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**  
File: **122\_18th\_Street\_SE\_rear\_looking\_WNW.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
10/23/1924	4083	Build	



Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0075

## BASICS DATA

ID Number: **1111-0075** Year Built: **1924** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>124</b>		<b>18th Street</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 124 18th Street, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0075</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1924</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1924</b>	<b>Permit</b>			<b>4125 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Stewart, N.A.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Burch, G.E.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Burch, G.E.</b>

Construction Notes:

**One of four rowhouses constructed from the same permit (#4083).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 4)**  
Relate to Street: **Face on Line w/ Projection**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**  
Bays Wide: **2**  
Height:   
Width: **16**  
Depth/Length: **26**  
SqFt:  
Volume:  
Lot Width

Outbuilding Type	Contributing Status
------------------	---------------------

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1924 by G.E. Burch, this two-story, two-bay single-family rowhouse is one of four constructed under the same permit (#4083). This Classical Revival-style dwelling is set on a solid brick foundation. The brick structure has five-course, American-bond brickwork and is capped by a shed roof. A slate shingle pent roof extends between brick firewalls along the façade (west elevation). Exposed bracket ends highlight the pent roof. An interior-rear brick chimney with a plain cap rises from the east elevation of the main block. Located in the southern bay, the main entry holds a single-leaf, paneled wood door with a semi-circular light. A single-light, wood-sash transom and a narrow, square-edge wood surround frame the door. Window openings, both single and paired, have 1/1, double-hung, vinyl sash with concrete sills. Solider brick courses extend above the first- and second-story openings. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation with honeycomb brick infill, this porch has a flat roof with a molded metal cornice and overhanging eaves. Brick posts support the roof while metal railing extends between.

The east (rear) elevation originally had a two-story, full-width porch. This has been removed and a two-story, full-width addition constructed. Extending east farther than the original porch's footprint, this large addition appears to have been constructed c. 2000. Set on a solid concrete block foundation, this addition is clad in German vinyl siding with a shed roof. An overhanging eave extends across the east elevation. Fenestration is composed of 1/1, double-hung, vinyl-sash windows and a single-leaf, paneled metal door with nine lights.

Site Notes:

July 2010: This single-family rowhouse is located on the east side of 18th Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The north (side) elevation is adjacent to 122 18th Street, S.E. and the south (side) elevation to 126 18th Street, S.E. The raised grassy front yard has a stone retaining wall and mature shrubs. A concrete walkway extends off the front porch down to the sidewalk. The backyard has a wooden privacy fence and a wood deck constructed off the rear addition. A concrete alley is located east of the property.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase II (2010)**

**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **124\_18th\_Street\_SE\_facade\_looking\_E.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **124\_18th\_Street\_SE\_facade\_looking\_SE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **124\_18th\_Street\_SE\_rear\_looking\_W.JPG**

Date:: Photog:

Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0074

## BASICS DATA

ID Number: **1111-0074** Year Built: **1924** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>126</b>		<b>18th Street</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 126 18th Street, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0074</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1924</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1924</b>	<b>Permit</b>			<b>4125 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Stewart, N.A.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Burch, G.E.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Burch, G.E.</b>

Construction Notes:

**One of four rowhouses constructed from the same permit (#4083).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 4)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**  
Bays Wide: **2**  
Height:   
Width: **16**  
Depth/Length: **26**  
SqFt:

Outbuilding Type	Contributing Status
------------------	---------------------

Volume:  
Lot Width:  
Lot Depth/Length:  
Lot SqFt:  
Acreage:  
Has Driveway:

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1924 by G.E. Burch, this two-story, two-bay single-family rowhouse is one of four constructed under the same permit (#4083). This Classical Revival-style dwelling is set on a solid brick foundation. The brick structure has five-course, American-bond brickwork and is capped by a shed roof. A slate shingle pent roof extends between brick firewalls along the façade (west elevation). Exposed bracket ends highlight the pent roof. An interior-rear brick chimney with a plain cap rises from the east elevation of the main block. Located in the southern bay, the main entry holds a single-leaf, paneled wood door with a single-light transom set in a narrow, square-edge wood surround. A metal storm door with filigree design has been installed in front of the main door. Window openings, both single and paired, have 1/1, double-hung, vinyl sash with concrete sills. Solider brick courses extend above the first- and second-story openings. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation with decorative concrete block infill, this porch has a flat roof with a molded metal cornice and overhanging eaves. Brick posts support the roof while a hipped metal railing extends between.

The original two-story, full-width rear porch has been removed and vinyl siding installed on the second story. Fenestration consists of 1/1, double-hung, vinyl-sash windows and a single-leaf door opening with a single-light transom set beneath a two-course, rowlock brick segmental arch. Additional details were not visible from the public right-of-way.

Site Notes:

July 2010: This single-family rowhouse is located on the east side of 18th Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The north (side) elevation is adjacent to 124 18th Street, S.E. and the south (side) elevation to 128 18th Street, S.E. The raised grassy front yard has a stone retaining wall landscaping consisting of mature shrubs, immature trees, and planting beds. A concrete walkway with metal railing extends off the front porch down to the sidewalk. Extending east to an alley, the backyard is enclosed with a metal security fence. A mature tree provides shade to a wood deck constructed on the rear of the house.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase II (2010)**

**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **126\_18th\_Street\_SE\_facade\_looking\_E.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **126\_18th\_Street\_SE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **126\_18th\_Street\_SE\_rear\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------



Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0803

## BASICS DATA

ID Number: **1111-0803** Year Built: **1940** Data Source: **Permit**

Number Extended Street Quad Type of Address

**128** **18th Street** **SE Current**

Name(s) Type of Name

**Multiple Dwelling, 128 18th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0803** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multi-Family)** **1940** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1940** **Permit** **7000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Santmyers, George T.**

**Orig Construction** **Builder** **Davis & Platt**

**Orig Construction** **Owner** **Steuart Bros. Inc.**

Construction Notes:

**One of two buildings constructed from the same permit (#230478).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached**

Relate to Street: **Face on Setback Line**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

July 2010: This two-story, three-bay, Colonial Revival-style apartment building was constructed in 1940 by Davis + Platt, Inc. The wide building is much larger than the adjacent building (132 Independence Avenue, S.E.), which was constructed under the same permit (#230478). Set on a raised solid concrete foundation, this concrete-block structure has six-course, American-bond brick. A false mansard with slate shingles highlights the façade (west elevation), however, a sloped roof caps the building. An exterior brick chimney with corbeled cap rises from the northeast corner. Centrally located on the façade, the main entry holds a single-leaf, metal-frame glass door set in a Colonial Revival-style surround. The surround has wide pilasters, entablature, and an ogee-molded pediment. Flanking the door opening are paired, 1/1, double-hung, vinyl-sash windows with rowlock brick sills and soldier brick jack arches. The second story has a central window opening flanked by paired window openings. Openings have 1/1, double-hung, vinyl-sash windows with rowlock brick sills. A raised stretcher course accompanies the sills while a soldier brick course tops the second-story openings. Additional fenestration consists of paired, six-light, wood-sash awning basement windows with rowlock brick sills. The east (rear) elevation has a large, two-story, full-width porch. Set on a brick pier foundation, this wood-frame structure has concrete floors. A shed roof caps the porch, which is enclosed with vertical board and ribbons of 1/1, double-hung, vinyl-sash windows set in narrow, square-edge wood surrounds. An integral porch on the first story provides access to opposing units via single-leaf, paneled wood doors. Metal stairs with brick cladding and metal handrail provide access to the first-story porch. Directly above, a second-story integral porch has a closed balustrade and single-leaf flush wood doors.

Site Notes:

July 2010: This apartment building is located east of 18th Street, S.E. and has a setback from the concrete sidewalk of approximately fifteen feet. The north (side) elevation is attached to 126 18th Street, S.E. and the south (side) elevation to 132 18th Street, S.E. The raised, level grassy front yard is enclosed with a metal chain-link fence and milled point metal fence. A brick walkway extends from the brick stoop down to the sidewalk. The level, grassy backyard is enclosed with metal chain-link fencing and includes concrete walkways.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase II (2010)**

**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **128\_18th\_Street\_SE\_facade\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **128\_18th\_Street\_SE\_facade\_looking\_SE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **128\_18th\_Street\_SE\_rear\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0802

## BASICS DATA

ID Number: **1111-0802** Year Built: **1940** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>132</b>		<b>18th Street</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Multiple Dwelling, 132 18th Street, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0802</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Multi-Family)</b>	<b>1940</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1940</b>	<b>Permit</b>			<b>7000 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Santmyers, George T.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Davis &amp; Platt</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Steuart Bros. Inc.</b>

Construction Notes:

**One of two buildings constructed from the same permit (#230478).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Attached (1 side)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Flat Front**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2**  
Bays Wide: **2**

Height:	Width:	Depth/Length:	SqFt:	Volume:	Lot Width:	Lot Depth/Length:	Lot SqFt:	Acreage:	Has Driveway:
									<input type="checkbox"/>

Outbuilding Type \_\_\_\_\_ Contributing Status \_\_\_\_\_

Height:  
Width:  
Depth/Length:  
SqFt:  
Volume:  
Lot Width:  
Lot Depth/Length:  
Lot SqFt:  
Acreage:  
Has Driveway:

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

July 2010: This two-story, two-bay, Colonial Revival-style apartment building was constructed in 1940 by Davis + Platt, Inc. This building is much smaller than the adjacent building (128 Independence Avenue, S.E.), which was constructed under the same permit (#230478). Set on a raised solid concrete foundation, this concrete-block structure has six-course, American-bond brick. A false mansard with slate shingles extends between firewalls, with a sloped roof covering a majority of the building. An exterior brick chimney with corbeled cap rises from southeast of the building. The façade (west elevation) has a main entry located in the northern bay. This single-leaf, metal-frame glass door is set in a Colonial Revival-style surround composed of wide pilasters and a hipped pediment with sunburst tympanum. The southern bay of the first story holds paired, 1/1, double-hung, vinyl-sash windows with a rowlock brick sill and soldier brick jack arch. The second story features a narrow, six-light, wood-sash casement with rowlock brick sill located in the northern bay. The southern bay holds paired, 1/1, double-hung, vinyl-sash windows with a rowlock brick sill and soldier brick jack arch. A raised stretcher brick string accompanies the second-story sill of the southern bay while a soldier brick string extends above, just below the cornice. Additional fenestration consists of paired, two-light, vinyl-sash sliding windows with rowlock brick sills. This small opening pierces the basement. Fenestration of the south (side) elevation consists of 1/1, double-hung, vinyl-sash windows with rowlock brick sills. A single-leaf flush wood door is located in a below-grade opening. A two-story, full-width porch is located on the east (rear) elevation. Set on a raised, six-course, American-bond brick foundation, this wood-frame porch has concrete floors. The south (side) elevation has six-course, American-bond brickwork with paired and tripled 1/1, double-hung, vinyl-sash windows with rowlock brick sills. The east (rear) elevation is clad in vertical board and includes paired and ribbons of 1/1, double-hung, vinyl-sash windows. A six-light, wood-frame awning window with a rowlock brick sill pierces the raised foundation. A single-leaf, flush wood door provides access to the first story. This opening is reached via cast concrete steps with metal railing. The second story features a narrow integral porch with access via metal stairs.

Site Notes:

July 2010: Located on a corner lot northeast of the intersection of 18th Street, S.E. and Independence Avenue, S.E., this apartment building has a setback of approximately fifteen feet from the concrete sidewalk. The north (side) elevation is attached to 128 18th Street, S.E. The grassy yard is enclosed with a metal chain-link fence and includes immature trees in the front yard and a large, mature tree in the side yard along Independence Avenue, S.E. The level, grassy backyard has a concrete patio and is enclosed with metal chain-link fencing.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

---

Neighborhood: <b>Capitol Hill</b>	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
<b>Capitol Hill Southeast Phase II (2010)</b>	<b>Permit Research</b> <b>Reconnaissance Survey</b>

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 132\_18th\_Street\_SE\_facade\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 132\_18th\_Street\_SE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 132\_18th\_Street\_SE\_side\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

---



Caption:

## Image File Not Found

Path: X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\  
File: 132\_18th\_Street\_SE\_rear\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

---

Notes:

### PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
03/16/1940	230478	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

---

### SIGNIFICANCE DATA

---

Study Unit

---

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

---

# Resource All Data Report

# ID Number: 1111-0093

## BASICS DATA

ID Number: **1111-0093** Year Built: **1935** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>1810</b>		<b>Independence Avenue</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 1810 Independence Avenue, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0093</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1935</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1935</b>	<b>Permit</b>			<b>4000 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Cadle, John R.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Cadle, John R.</b>
<b>Stuart, G.T.</b>	<b>Owner</b>	<b>Stuart, G.T.</b>

Construction Notes:

**One of four rowhouses constructed from the same permit (#181306).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row End (1 of 4)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type	Contributing Status
------------------	---------------------

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1935 by John R. Cadle, this two-story, three-bay, single-family rowhouse was one of four constructed under the same permit (#181306). The Classical Revival-style dwelling is set on a solid concrete foundation faced with six-course, American-bond brickwork. The brick structure also has six-course, American-bond brickwork. Of note is the channeled southwest corner. A sloped roof caps the structure, but is obscured from view by an asphalt shingle pent roof with a deep overhanging eave and scrolled rafter ends. The pent roof is set between brick firewalls embellished with corbeled caps that slope to the north. The main entry, located in the western bay of the façade (south elevation) holds a single-leaf, paneled wood door with single-light transom. East of the door opening are two, 1/1, double-hung, vinyl-sash windows with concrete sills. A soldier brick string course extends above the first-story openings. A one-story, one-bay porch is located on the façade. Set on a brick pier foundation, this porch has a flat roof with an ogee-molded gutter. Brick posts support the roof and include square balusters. Second-story fenestration consists of tripled 1/1, double-hung, vinyl-sash windows with concrete sills. A soldier string extends above the second story openings. Additional fenestration consists of a two-light, vinyl-sash sliding window which pierces the raised basement. The west (side) elevation has no openings. The north (rear) elevation has single and paired window openings with 1/1, double-hung, vinyl sash. All openings include rowlock brick sills. A single-leaf, paneled wood door with two lights and single-light transom is located on the first story. A single-leaf, multi-light wood door is located on the second story. A single-leaf, paneled wood door is located in a below-grade door opening, located beneath the rear porch. The porch, which is two-stories tall and one-bay wide, has brick supports and concrete floors. Square wood balusters complete the porch.

Site Notes:

July 2010: This single-family rowhouse is located north of Independence Avenue, S.E. and has a setback from the concrete sidewalk of approximately fifteen feet. The east (side) elevation is attached to 1812 Independence Avenue, S.E. The raised, grassy front yard has a coursed stone retaining wall and immature shrubs. Wood steps from the front porch link with concrete steps to provide access from the sidewalk to the dwelling. A large, grassy side yard is enclosed with metal chain-link fence. The rear of the property extends north and is enclosed with a metal security fence. A concrete walkway extends off the rear deck to the alley behind.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase II (2010)**

**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1810\_Independence\_Avenue\_SE\_facade\_lookin  
g\_N.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1810\_Independence\_Avenue\_SE\_facade\_lookin  
g\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1810\_Independence\_Avenue\_SE\_rear\_looking\_  
S.JPG**

Date:: Photog:

Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
06/11/1935	181306	Build	

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code            Criteria \_\_\_\_\_

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0092

## BASICS DATA

ID Number: **1111-0092** Year Built: **1935** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>1812</b>		<b>Independence Avenue</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 1812 Independence Avenue, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0092</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1935</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1935</b>	<b>Permit</b>			<b>4000 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Cadle, John R.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Cadle, John R.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Stuart, G.T.</b>

Construction Notes:

**One of four rowhouses constructed from the same permit (#181306).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 4)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:



Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type	Contributing Status
<b>Garage</b>	<b>Contributing</b>

Outbuilding Notes:

**July 2010: DC Property Quest states that this one-story, four-bay garage is associated with 1812 Independence Avenue, S.E. This garage was originally constructed as two separate garages between 1928 and 1960. The building is faced with five-course American-bond brick and is capped by a sloped roof.**

Three paneled metal roll-up garage doors and one single-leaf flush metal door pierce the north elevation of the building.

## STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival

Exterior & Architectural Notes:

July 2010: Constructed in 1935 by John R. Cadle, this two-story, three-bay, single-family rowhouse was one of four constructed under the same permit (#181306). The Classical Revival-style dwelling is set on a solid concrete foundation faced with six-course, American-bond brickwork. The brick structure also has six-course, American-bond brickwork. A sloped roof caps the structure, but is obscured from view by an asphalt shingle pent roof with a deep overhanging eave and scrolled rafter ends. The metal gutter has become separated from much of the roof. The pent roof is set between brick firewalls embellished with corbeled caps.

The first story has a 1/1, double-hung, vinyl-sash windows with concrete sill located in the eastern bay of the first story. The second story holds a triple window of 1/1, double-hung, vinyl sash, also with a concrete sill. The basement is pierced by a short, 1/1, double-hung, vinyl-sash window with concrete sill. A solder brick string course is passes just above each opening.

The original one-story, one-bay front porch has been altered. Set on a brick pier foundation, the foundation has been infilled with decorative concrete block. Aluminum siding now encloses the porch in conjunction with jalousie windows and a single-leaf, metal-frame storm door. The original corbeled brick supports and flat roof with overhanging eaves remain.

The north (rear) elevation is pierced by single and paired 1/1, double-hung, vinyl-sash windows with concrete sills. A one-story, one-bay original porch is located on the rear of the dwelling. However, details were not visible from the public right-of-way due to an addition.

The north (rear) elevation has a one-story porch addition, which based on its form and materials, appears to have been constructed c. 1980. The wood-frame structure is an extension of the original rear porch. With its shed roof of asphalt shingles, the porch is supported by wood posts with plank balusters. Lattice encloses much of the porch.

Site Notes:

July 2010: This single-family rowhouse is located north of Independence Avenue, S.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The rowhouse is adjacent to 1810 and 1814 Independence Avenue, S.E. The raised front yard has a course stone retaining wall and immature shrubs. Concrete steps lead from the enclosed front porch down to the sidewalk below. The rear of the property extends north to an alley and in enclosed with a metal chain-link fence. Concrete and brick covers most of the backyard. A detached multi-bay garage associated with this apartment building is located to the south in the interior of the block.

## NOTABLE FEATURES DATA

Component	Feature
-----------	---------

## EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

## WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s) \_\_\_\_\_

Notable Interior Feature(s) \_\_\_\_\_

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

---

Neighborhood: **Capitol Hill**

Historic District(s) \_\_\_\_\_

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s) \_\_\_\_\_

Contributing:

Survey(s) \_\_\_\_\_

Level(s) of Investigation \_\_\_\_\_

**Capitol Hill Southeast Phase II (2010)**

**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1812\_Independence\_Avenue\_SE\_facade\_loo  
king\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1812\_Independence\_Avenue\_SE\_facade\_loo  
king\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1812\_Independence\_Avenue\_SE\_rear\_loo  
king\_SW.JPG**

Date:: Photog:

Code:: R: Fr:

---



Caption:

## Image File Not Found

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1812\_Independence\_Avenue\_SE\_garage\_loo  
king\_SE.JPG

Date:: Photog:  
Code:: R: Fr:

---

Caption:

## Image File Not Found

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1812\_Independence\_Avenue\_SE\_garage\_loo  
king\_SW.JPG

Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

---

Notes:

### PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
06/11/1935	1812	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

---

### SIGNIFICANCE DATA

---

Study Unit

---

Code	Criteria
------	----------

---

### DATA PROCESSING EVENTS DATA

---

# Resource All Data Report

# ID Number: 1111-0091

## BASICS DATA

ID Number: **1111-0091** Year Built: **1935** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>1814</b>		<b>Independence Avenue</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 1814 Independence Avenue, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0091</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1935</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1935</b>	<b>Permit</b>			<b>4000 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Cadle, John R.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Cadle, John R.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Stuart, G.T.</b>

Construction Notes:

**One of four rowhouses constructed from the same permit (#181306).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 4)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type	Contributing Status
------------------	---------------------

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1935 by John R. Cadle, this two-story, three-bay, single-family rowhouse was one of four constructed under the same permit (#181306). The Classical Revival-style dwelling is set on a solid concrete foundation faced with six-course, American-bond brickwork. The brick structure also has six-course, American-bond brickwork. A sloped roof caps the structure, but is obscured from view by an asphalt shingle pent roof with a deep overhanging eave and scrolled rafter ends. The pent roof is set between brick firewalls embellished with corbeled caps that slope to the north. The main entry, located in the western bay of the façade (south elevation) holds a single-leaf, paneled wood door with semi-circular light. East of the door opening are two, 1/1, double-hung, vinyl-sash windows with concrete sills. A soldier brick string course extends above the first-story openings. A one-story, one-bay porch is located on the façade. Set on a brick pier foundation with decorative concrete block infill, this porch has a flat roof with overhanging eaves. Brick posts support the roof and include metal railing between. Tripled 1/1, double-hung, vinyl-sash windows with a concrete sill pierce the middle of the second story. A soldier brick string course extends above the opening. Additional fenestration consists of a 1/1, double-hung, vinyl-sash basement window, also with a concrete sill and accompanied by a soldier brick string above. The north (rear) elevation is pierced with single and paired openings of 1/1, double-hung, vinyl-sash windows with rowlock brick sills. A one-story, one-bay original porch is set on a brick pier foundation augmented with brick infill. A single-leaf door opening now occupies the north side of the porch's foundation. Aluminum siding encloses the porch and is pierced with a two-light, vinyl-sash sliding window and a single-leaf, paneled wood door. A metal awning extends off the shed roof of standing-seam metal to shelter the rear of the porch.

Site Notes:

July 2010: This single-family rowhouse is located north of Independence Avenue, S.E. and has a setback of approximately fifteen feet from the concrete sidewalk. The rowhouse is adjacent to 1812 and 1816 Independence Avenue, S.E. The raised front yard has a brick retaining wall with milled point fence. Crushed stone covers the yard, supplemented with immature shrubs. Brick steps extend off the front porch down to a concrete walkway to the sidewalk. The rear of the property extends north and is enclosed with metal chain-link fence. A concrete parking pad and gravel cover most of the backyard. The portion of the backyard nearest the dwelling has been dugout to allow for below-grade door openings.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

---

Neighborhood: **Capitol Hill** Historic District(s) \_\_\_\_\_  
Subdivision: \_\_\_\_\_  
Ward/ANC: \_\_\_\_\_  
Zoning: \_\_\_\_\_ Designation Event(s) \_\_\_\_\_  
Contributing: \_\_\_\_\_  
  
Survey(s) \_\_\_\_\_ Level(s) of Investigation \_\_\_\_\_  
**Capitol Hill Southeast Phase II (2010)** **Permit Research**  
**Reconnaissance Survey**

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1814\_Independence\_Avenue\_SE\_facade\_loo  
king\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1814\_Independence\_Avenue\_SE\_facade\_loo  
king\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1814\_Independence\_Avenue\_SE\_rear\_loo  
king\_S.JPG  
Date:: Photog:  
Code:: R: Fr:

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
06/11/1935	181306	Build	

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code            Criteria \_\_\_\_\_

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0090

## BASICS DATA

ID Number: **1111-0090**      Year Built: **1935**      Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>1816</b>		<b>Independence Avenue</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 1816 Independence Avenue, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0090</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building**      Status Current: **Extant**  
Desig. Status: **Historic**      Quality:  
Purpose: **Rowhouse**      Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1935</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1935</b>	<b>Permit</b>			<b>4000</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Cadle, John R.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Cadle, John R.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Stuart, G.T.</b>

Construction Notes:

**One of four rowhouses constructed from the same permit (#181306).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row End (1 of 4)**  
Relate to Street: **Face on Setback Line**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **18**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type	Contributing Status
------------------	---------------------

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1935 by John R. Cadle, this two-story, three-bay, single-family rowhouse was one of four constructed under the same permit (#181306). The Classical Revival-style dwelling is set on a solid concrete foundation faced with six-course, American-bond brickwork. The brick structure also has six-course, American-bond brickwork. A sloped roof caps the structure, but is obscured from view by an slate shingle pent roof with a deep overhanging eave and scrolled rafter ends. The pent roof is set between brick firewalls embellished with corbeled caps stepped to the north. The main entry, located in the western bay of the façade (south elevation) holds a single-leaf, paneled wood door with lights. East of the door opening are two, 1/1, double-hung, vinyl-sash windows with concrete sills. A soldier brick string course extends above the first-story openings. A one-story, one-bay porch is located on the façade. Set on a brick pier foundation with decorative concrete block infill, this porch has a flat roof with overhanging eaves. Brick posts support the roof and include metal railing between. Metal awnings have been attached to the porch. Tripled 1/1, double-hung, vinyl-sash windows with a concrete sill pierce the middle of the second story. A soldier brick string course extends above the opening. Additional fenestration consists of a 1/1, double-hung, vinyl-sash basement window, also with a concrete sill and accompanied by a soldier brick string above. The east (side) elevation has been parged and has no openings. The north (rear) elevation is pierced with single and paired openings of 1/1, double-hung, vinyl-sash windows with rowlock brick sills. An one-story, one-bay porch has been enclosed with aluminum siding. A shed roof of asphalt sheets caps the porch. Paired metal jalousie windows and a single-leaf, metal-frame jalousie door pierce the porch. The original brick supports remain exposed.

Site Notes:

July 2010: This single-family rowhouse is located north of Independence Avenue, S.E. and is set back from the concrete sidewalk approximately fifteen feet. The west (side) elevation is attached to 1814 Independence Avenue, S.E. while the east (side) elevation fronts a concrete alley. The raised front yard has a brick retaining wall with milled point fence. Mature shrubs and vegetation have overgrown the yard. Concrete steps extend off the front porch down to the sidewalk. The backyard is enclosed with a metal security fence. Concrete covers most of the backyard, which backs to an alley.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

---

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

---

Survey(s)

---

Level(s) of Investigation

---

**Capitol Hill Southeast Phase II (2010)**

**Permit Research  
Reconnaissance Survey**

---

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1816\_Independence\_Avenue\_SE\_facade\_loo  
king\_N.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1816\_Independence\_Avenue\_SE\_facade\_loo  
king\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1816\_Independence\_Avenue\_SE\_facade\_loo  
king\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

---



Caption:

## Image File Not Found

Path: X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\  
File: 1816\_Independence\_Avenue\_SE\_rear\_looking  
\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

---

Notes:

### PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
06/11/1935	181306	Build	

Permit Notes:

### BIBLIOGRAPHIC DATA

---

### SIGNIFICANCE DATA

---

Study Unit

Code Criteria

### DATA PROCESSING EVENTS DATA

---

# Resource All Data Report

# ID Number: 1111-0056

## BASICS DATA

ID Number: **1111-0056** Year Built: **1923** Data Source: **Permit**

Number Extended Street Quad Type of Address

**105** **19th Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 105 19th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0056** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1923** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1923** **Permit** **3800 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Miller, W. C. & A. N.**

**Orig Construction** **Builder** **Miller, W. C. & A. N.**

**Orig Construction** **Owner** **Miller, W. C. & A. N.**

Construction Notes:

**One of five rowhouses constructed from the same permit (#8420).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row End (1 of 5)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Flat Front**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **14**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1923 by owner, architect, and builder W.C. Miller and A.N. Miller, this two-story, two-bay single-family rowhouse was one of five similar dwellings constructed under the same permit (#8420). The Colonial Revival-style rowhouse is set on a solid concrete foundation. The brick structure has five-course, American-bond brickwork and is capped by a shed roof. A pedimented brick parapet is set above a soldier brick string course. An interior-side brick chimney with corbeled cap is located on the east side of the dwelling. The façade (east elevation) has a single-leaf, paneled wood door with semi-circular light located in the southern bay. A pedimented door hood with scrolled brackets shelters the opening. Window openings contain 1/1, double-hung, vinyl-sash windows with concrete sills. All first-story openings have soldier brick jack arches. A rowlock brick string course extends above the second-story openings. The north (side) elevation is clad in vinyl siding and pierced with 1/1, double-hung, vinyl-sash windows set in vinyl-clad surrounds. Fenestration of the west (rear) elevation consists of 1/1, double-hung, vinyl-sash windows and a single-leaf door (not visible).

Site Notes:

July 2010: This single-family rowhouse is located west of 19th Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The south (side) elevation is attached to 107 19th Street, S.E. while the north (side) elevation fronts a concrete alley. The front yard slopes east and has been hardscaped with gravel and a stone retaining wall. A concrete walkway extends from the main entry to the sidewalk. The backyard extends west to an alley and is enclosed with a wooden privacy fence. The fence is set on a concrete retaining wall.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

**PHOTOS - DIGITIZED**

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 105\_19th\_Street\_SE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 105\_19th\_Street\_SE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 105\_19th\_Street\_SE\_rear\_looking\_ESE.JPG  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

[Empty text box]

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
03/29/1923	8420	Build	

Permit Notes:

[Empty text box]

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

---

Code            Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0059

## BASICS DATA

ID Number: **1111-0059** Year Built: **1923** Data Source: **Permit**

Number Extended Street Quad Type of Address

**107** **19th Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 107 19th Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0059** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1923** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1923** **Permit** **3800 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Miller, W. C. & A. N.**

**Orig Construction** **Builder** **Miller, W. C. & A. N.**

**Orig Construction** **Owner** **Miller, W. C. & A. N.**

Construction Notes:

**One of five rowhouses constructed from the same permit (#8420).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 5)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Flat Front**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **14**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1923 by owner, architect, and builder W.C. Miller and A.N. Miller, this two-story, two-bay single-family rowhouse was one of five similar dwellings constructed under the same permit (#8420). The Colonial Revival-style rowhouse is set on a solid concrete foundation. The brick structure has five-course, American-bond brickwork and is capped by a shed roof. A brick parapet is set above a soldier brick string course and capped with metal coping. Two interior brick chimneys pierce the roof. The façade (east elevation) has a single-leaf, paneled metal door with large light located in the southern bay. A pedimented door hood with scrolled brackets shelters the opening. Window openings contain 1/1, double-hung, vinyl-sash windows with concrete sills. All first-story openings have soldier brick jack arches. A rowlock brick string course extends above the second-story openings. The west (rear) elevation has 1/1, double-hung, vinyl-sash windows and single-leaf doors on the first and second stories. A second-story wood deck has a metal awning roof supported by metal filigree posts set on the wooden balustrade. Metal poles set on the ground provide support.

Site Notes:

July 2010: This single-family rowhouse is located west of 19th Street, S.E. and has a setback from the concrete sidewalk of approximately twenty feet. The north (side) elevation is adjacent to 105 19th Street, S.E. and the south (side) elevation to 109 19th Street, S.E. The grassy front yard slopes east and includes a stone retaining wall aside the sidewalk. Stone steps with metal railing link the main entry to the sidewalk below. The backyard, enclosed with wooden privacy fence and a metal gate, has been covered with concrete.

**NOTABLE FEATURES DATA**

Component \_\_\_\_\_ Feature \_\_\_\_\_

**EXTERIOR MATERIALS DATA**

Roof Component \_\_\_\_\_ Material \_\_\_\_\_ Color \_\_\_\_\_ Treatment \_\_\_\_\_ Source \_\_\_\_\_

Wall Component \_\_\_\_\_ Material \_\_\_\_\_ Color \_\_\_\_\_ Treatment \_\_\_\_\_ Source \_\_\_\_\_

Structure Component \_\_\_\_\_ Material \_\_\_\_\_ Feature \_\_\_\_\_ Source \_\_\_\_\_

Materials Notes:

\_\_\_\_\_

**WINDOW/DOOR/INTERIOR DATA**

Window Location \_\_\_\_\_ Aperture Shape \_\_\_\_\_ Type \_\_\_\_\_ Lights \_\_\_\_\_ Material \_\_\_\_\_

Door Location \_\_\_\_\_ Aperture Shape \_\_\_\_\_ Type \_\_\_\_\_ Panels \_\_\_\_\_ Material \_\_\_\_\_

Notable Interior Plan(s) \_\_\_\_\_

Notable Interior Feature(s) \_\_\_\_\_

Interior Notes:

\_\_\_\_\_

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s) \_\_\_\_\_

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s) \_\_\_\_\_

Contributing:

Survey(s)  
**Capitol Hill Southeast Phase II (2010)**

Level(s) of Investigation  
**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**  
File: **107\_19th\_Street\_SE\_facade\_looking\_NW.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**  
File: **107\_19th\_Street\_SE\_facade\_looking\_SW.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**  
File: **107\_19th\_Street\_SE\_rear\_looking\_E.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
<b>03/29/1923</b>	<b>8420</b>	<b>Build</b>	

---

Permit Notes:



**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

---

Code            Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0058

## BASICS DATA

ID Number: **1111-0058** Year Built: **1923** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>109</b>		<b>19th Street</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 109 19th Street, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0058</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1923</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1923</b>	<b>Permit</b>			<b>3800 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Miller, W. C. &amp; A. N.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Miller, W. C. &amp; A. N.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Miller, W. C. &amp; A. N.</b>

Construction Notes:

**One of five rowhouses constructed from the same permit (#8420).**


## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 5)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Flat Front**  
Footprint: **Rectangular**

Cross Reference Notes:



Number Stories: **2**  
Bays Wide: **2**  
Height:  
Width: **14**  
Depth/Length: **30**

Outbuilding Type	Contributing Status
<b>Garage</b>	<b>Contributing</b>

SqFt:  
Volume:  
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

**July 2010: This two-story, one-bay garage, based on its form and materials, appears to have been constructed c. 1923. Set on a concrete slab, this brick structure has five-course, American-bond brickwork. A shed roof with metal coping caps the garage. The façade (west elevation) has a tall, double-leaf**

plywood door with a massive concrete lintel. A single-light wood-sash awning window with rowlock brick sill pierces the second story.

### STYLE/EXTERIOR DATA

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1923 by owner, architect, and builder W.C. Miller and A.N. Miller, this two-story, two-bay single-family rowhouse was one of five similar dwellings constructed under the same permit (#8420). The Colonial Revival-style rowhouse is set on a solid concrete foundation. The brick structure has five-course, American-bond brickwork and is capped by a shed roof. A pedimented brick parapet is set above a soldier brick string course. An interior-side brick chimney with corbeled cap pierces the roof. The façade (east elevation) has a single-leaf, paneled wood door with semi-circular light located in the southern bay. A pedimented door hood with scrolled brackets shelters the opening. Window openings contain 1/1, double-hung, vinyl-sash windows with concrete sills. All first-story openings have soldier brick jack arches. A rowlock brick string course extends above the second-story openings. The west (rear) elevation has paired 1/1, double-hung, vinyl-sash windows located on the second story. A projecting one-story, one-bay door surround appears to be located on the rear of the dwelling. This feature has a front-gabled roof, has thin overhanging eaves, and is constructed of wood. Additional details were not visible from the public right-of-way.

Site Notes:

July 2010: This single-family rowhouse is located west of 19th Street, S.E. and has a setback from the concrete sidewalk of approximately twenty feet. The north (side) elevation is adjacent to 107 19th Street, S.E. and the south (side) elevation to 111 19th Street, S.E. The front yard slopes east to a stone retaining wall aside the sidewalk. Immature plantings and mature shrubs dot the slope. A concrete walkway extends from the main entry down steps to the sidewalk. The backyard, enclosed with wooden privacy fence, extends west to a large garage. The garage fronts an alley.

### NOTABLE FEATURES DATA

Component Feature

### EXTERIOR MATERIALS DATA

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

### WINDOW/DOOR/INTERIOR DATA

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

### PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:  
Ward/ANC:  
Zoning:  
Contributing:

Designation Event(s)

---

Survey(s)

---

Level(s) of Investigation

---

**Capitol Hill Southeast Phase II (2010)**

**Permit Research  
Reconnaissance Survey**

---

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 109\_19th\_Street\_SE\_facade\_looking\_NW.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 109\_19th\_Street\_SE\_facade\_looking\_SW.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 109\_19th\_Street\_SE\_garage\_looking\_SE.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 109\_19th\_Street\_SE\_rear\_looking\_NE.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

## Image File Not Found

Path: X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\  
File: 109\_19th\_Street\_SE\_rear\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

### PHOTOS - B/W OR NON-DIGITIZED

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

### MISCELLANEOUS NOTES DATA

---

Notes:

### PERMIT DATA

---

Permit Issue Date	Number	Type	Remarks
03/29/1923	8420	Build	

---

Permit Notes:

### BIBLIOGRAPHIC DATA

---

### SIGNIFICANCE DATA

---

Study Unit

---

Code Criteria

---

### DATA PROCESSING EVENTS DATA

---

# Resource All Data Report

# ID Number: 1111-0057

## BASICS DATA

ID Number: **1111-0057** Year Built: **1923** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>111</b>		<b>19th Street</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 111 19th Street, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0057</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1923</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1923</b>	<b>Permit</b>			<b>3800 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Miller, W. C. &amp; A. N.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Miller, W. C. &amp; A. N.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Miller, W. C. &amp; A. N.</b>

Construction Notes:

**One of five rowhouses constructed from the same permit (#8420).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 5)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Flat Front**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**  
Bays Wide: **2**  
Height:  
Width: **14**  
Depth/Length: **30**

Outbuilding Type	Contributing Status
<b>Shed</b>	<b>Non-Contributing</b>

SqFt:  
Volume:  
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

**July 2010: This one-story, one-bay prefabricated shed, based on its form and materials, appears to have been constructed c. 2000. Set on the concrete driveway, the shed is clad in plastic siding and capped by a front-gabled roof of the same material.**

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1923 by owner, architect, and builder W.C. Miller and A.N. Miller, this two-story, two-bay single-family rowhouse was one of five similar dwellings constructed under the same permit (#8420). The Colonial Revival-style rowhouse is set on a solid concrete foundation. The brick structure has five-course, American-bond brickwork and is capped by a shed roof. A pedimented brick parapet is set above a soldier brick string course. An interior-side brick chimney with corbeled cap pierces the roof. The façade (east elevation) has a single-leaf, paneled wood door with semi-circular light located in the southern bay. A pedimented door hood with scrolled brackets shelters the opening. Window openings contain 1/1, double-hung, vinyl-sash windows with concrete sills. All first-story openings have soldier brick jack arches. A rowlock brick string course extends above the second-story openings. The west (rear) elevation has 1/1, double-hung, vinyl-sash windows with rowlock brick sills and two-course, rowlock brick segmental arches. A single-leaf, paneled wood door is located in the central bay of the first story.

Site Notes:

July 2010: This single-family rowhouse is located west of 19th Street, S.E. and has a setback from the concrete sidewalk of approximately twenty feet. The north (side) elevation is adjacent to 109 19th Street, S.E. and the south (side) elevation to 113 19th Street, S.E. The front yard has been terraced with concrete pavers and landscaped with immature plantings and shrubs. A concrete walkway extends from the main entry down steps to the sidewalk. The backyard, enclosed with wooden privacy fence and metal gate, has been mostly covered with concrete. A shed is located in the backyard.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panel(s)	Material
---------------	----------------	------	----------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill Southeast Phase II (2010)**

Level(s) of Investigation  
**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**  
File: **111\_19th\_Street\_SE\_facade\_looking\_NW.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**  
File: **111\_19th\_Street\_SE\_facade\_looking\_SW.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**  
File: **111\_19th\_Street\_SE\_rear\_looking\_E.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
<b>03/29/1923</b>	<b>8420</b>	<b>Build</b>	

---

Permit Notes:



**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

---

Code            Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0060

## BASICS DATA

ID Number: **1111-0060** Year Built: **1923** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>113</b>		<b>19th Street</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 113 19th Street, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0060</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1923</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1923</b>	<b>Permit</b>			<b>3800 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Miller, W. C. &amp; A. N.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Miller, W. C. &amp; A. N.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Miller, W. C. &amp; A. N.</b>

Construction Notes:

**One of five rowhouses constructed from the same permit (#8420).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row End (1 of 5)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Flat Front**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**  
Bays Wide: **2**  
Height:  
Width: **14**  
Depth/Length: **30**  
SqFt:

Outbuilding Type	Contributing Status
------------------	---------------------

Volume:  
Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1923 by owner, architect, and builder W.C. Miller and A.N. Miller, this two-story, two-bay single-family rowhouse was one of five similar dwellings constructed under the same permit (#8420). The Colonial Revival-style rowhouse is set on a solid concrete foundation. The brick structure has five-course, American-bond brickwork. The second-story of the façade (east elevation) has been clad in German vinyl siding. Capped by a sloping roof, the roofline features a pedimented parapet across the façade and an interior-side parged chimney along the south elevation. The façade has a single-leaf, paneled metal door with semi-circular light located in the southern bay. A pedimented door hood with scrolled brackets shelters the opening. Window openings contain 1/1, double-hung, vinyl-sash windows with concrete sills. All first-story openings have soldier brick jack arches. A rowlock brick string course extends above the second-story openings. The south (side) elevation has no fenestration. A two-story, full-width addition is located on the west (rear) elevation. Based on its materials, this addition dates to c. 2000. Clad in German vinyl siding, the addition is capped by a shed roof. Fenestration of the west (rear) elevation consists of 1/1, double-hung, vinyl-sash windows and a single-leaf, paneled metal door with lights. The south (side) elevation has two-light, vinyl-sash sliding windows.

Site Notes:

July 2010: This single-family rowhouse is located west of 19th Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The north (side) elevation is attached to 111 19th Street, S.E. The grassy front yard slopes east down to the sidewalk. A concrete walkway extends from the main entry to the sidewalk below. A narrow grassy alley is located south of the dwelling. The backyard is enclosed with metal fencing and includes a concrete and grass ribbon driveway. Mature trees line the southern side of the backyard.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

**PHOTOS - DIGITIZED**

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 113\_19th\_Street\_SE\_facade\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 113\_19th\_Street\_SE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 113\_19th\_Street\_SE\_rear\_looking\_E.JPG  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

[Empty text box]

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
03/29/1923	8420	Build	

Permit Notes:

[Empty text box]

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

---

Code            Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0096

## BASICS DATA

ID Number: **1111-0096** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1819** **A Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 1819 A Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0096** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1925** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Santmyers, George T.**

**Orig Construction** **Builder** **Poretsky, H.**

**Orig Construction** **Owner** **Poretsky, Silver & Rosen**

Construction Notes:

**One of five rowhouses constructed from the same permit (#3653).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 5)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1925 by H. Poretsky, this two-story, two-bay Classical Revival-style, single-family rowhouse is one of five constructed under the same permit (#3653); this dwelling may have originally been constructed as a duplex. Set on a solid concrete foundation, this brick structure has six-course, American-bond brickwork. A sloped roof caps the dwelling, though is obscured by a brick parapet with molded metal cornice stretching across the façade (north elevation). Three concrete panels with garland and swag ornamentation embellish the parapet. Brick firewalls with metal coping extend down the sides of the rowhouse. A one-story, two-bay porch with a concrete deck is located on the façade. Set on a brick pier foundation, the porch has a flat roof with overhanging eaves. Brick posts with corbeled capitals support the roof. Metal railing completes the porch. A single-leaf, paneled door with semi-circular light is located in the eastern bay. A blank transom is located above. The west bay holds paired, 1/1, double-hung, vinyl-sash windows with a rowlock brick sill. The second story has three window openings with 1/1, double-hung, vinyl sash and rowlock brick sills. Whereas the first-story openings have soldier brick jack arches, the second-story openings have a soldier brick string course directly above. Additional fenestration consists of a two-light, vinyl-sash sliding basement window located beneath the porch. The west (side) elevation has 1/1, double-hung, vinyl-sash windows in the first- and second-story openings. Single and paired vinyl-sash sliding windows occupy the basement openings. All openings have rowlock brick sills and two-course, rowlock brick segmental arches. The south (rear) elevation has a c. 1990 two-story, full-width addition. Set on the brick foundation of an original rear porch, the addition is clad in vinyl siding and capped by a shed roof. Fenestration consists of tripartite vinyl-sash on the rear and 1/1, double-hung, vinyl sash on the side elevations. A single-leaf, paneled metal door with semi-circular light is located on the rear of the addition.

Site Notes:

July 2010: This single-family rowhouse is located south of A Street, S.E. and has a setback from the concrete sidewalk of approximately twenty feet. The east (side) elevation is adjacent to 1821 A Street, S.E. while a concrete alley fronts the west (side) elevation. A stone retaining wall aside the sidewalk and a concrete retaining wall aside the alley contain the raised, grassy front yard. Concrete steps with metal railing extend off the front porch to a walkway down to the sidewalk. The deep backyard extends south to the alley. A wooden privacy fence encloses the backyard.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**  
Subdivision:  
Ward/ANC:  
Zoning:  
Contributing:  
  
Survey(s)  
**Capitol Hill Southeast Phase II (2010)**

Historic District(s)  
  
Designation Event(s)  
  
Level(s) of Investigation  
**Permit Research**  
**Reconnaissance Survey**

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**  
File: **1819\_A\_Street\_SE\_facade\_looking\_SE.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**  
File: **1819\_A\_Street\_SE\_facade\_looking\_SW.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**  
File: **1819\_A\_Street\_SE\_rear\_looking\_N.JPG**  
Date:: Photog:  
Code:: R: Fr:

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---



Permit Issue Date	Number	Type	Remarks
10/19/1925	3653	Build	

Permit Notes:

---

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

Study Unit

---

Code

Criteria

---

---

**DATA PROCESSING EVENTS DATA**

# Resource All Data Report

# ID Number: 1111-0097

## BASICS DATA

ID Number: **1111-0097** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1821** **A Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 1821 A Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0097** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1925** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Santmyers, George T.**

**Orig Construction** **Builder** **Poretsky, H.**

**Orig Construction** **Owner** **Poretsky, Silver & Rosen**

Construction Notes:

**One of five rowhouses constructed from the same permit (#3653).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 5)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type

**Garage**

Contributing Status

**Non-Contributing**

Outbuilding Notes:

**July 2010: This one-story, one-bay garage, based on its form and materials, appears to have been constructed c. 1970. The metal-frame structure is clad in pressed metal and capped by a front-gabled roof of corrugated metal. Corner boards complete the structure. Overhanging eaves complete the roofline. The**

façade (south elevation) has a roll-up metal garage door.

**STYLE/EXTERIOR DATA**

Architectural Style(s)

Colonial Revival

Exterior & Architectural Notes:

July 2010: Constructed in 1925 by H. Poretsky, this two-story, two-bay Classical Revival-style single-family rowhouse is one of five constructed under the same permit (#3653). Set on a solid concrete foundation, this brick structure has six-course, American-bond brickwork. A sloped roof caps the dwelling, however, it is obscured by a pent roof of terra cotta tiles. Set between brick firewalls with molded caps, the pent roof features scrolled rafter tails. An exterior brick chimney with plain cap rises from the rear of the rowhouse. A one-story porch with a concrete deck is located on the façade. Set on a brick pier foundation, the porch has a flat roof with overhanging eaves (deteriorated). Brick posts with corbeled capitals support the roof. Metal railing completes the porch. A single-leaf, paneled wood door with nine lights is located in the eastern bay. Set in a narrow, square-edge wood surround, the door has a single-light wood transom. The west bay holds paired, 6/1, double-hung, wood-sash windows with a rowlock brick sill. The second story has a single and paired window openings with 6/1, double-hung, wood sash and rowlock brick sills. Whereas the first-story openings have soldier brick jack arches, the second-story openings have a soldier brick string course directly above. The south (rear) elevation has a two-story, full-width screened porch capped by a shed roof. The balustrades have been enclosed with aluminum siding.

Site Notes:

July 2010: This single-family rowhouse is located south of A Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The west (side) elevation is adjacent to 1819 A Street, S.E. and the east (side) elevation to 1823 A Street, S.E. A coursed stone retaining wall contains the raised, grassy front lawn with mature shrubs and foundation plantings. Brick steps with metal railing extend off the front porch down a brick walkway to the sidewalk. The backyard is enclosed with a wooden privacy fence and includes a garage that fronts the concrete alley.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s) Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: Capitol Hill Historic District(s)

Subdivision:  
Ward/ANC:  
Zoning:  
Contributing:

Designation Event(s)

---

Survey(s)

---

Level(s) of Investigation

---

**Capitol Hill Southeast Phase II (2010)**

**Permit Research  
Reconnaissance Survey**

---

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1821\_A\_Street\_SE\_facade\_looking\_S.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1821\_A\_Street\_SE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1821\_A\_Street\_SE\_garage\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1821\_A\_Street\_SE\_rear\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code          Roll          Frame(s)          Date          Photographer          Caption

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
10/19/1925	3653	Build	

---

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code	Criteria
------	----------

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0098

## BASICS DATA

ID Number: **1111-0098** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1823** **A Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 1823 A Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0098** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1925** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Santmyers, George T.**

**Orig Construction** **Builder** **Poretsky, H.**

**Orig Construction** **Owner** **Poretsky, Silver & Rosen**

Construction Notes:

**One of five rowhouses constructed from the same permit (#3653).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 5)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1925 by H. Poretsky, this two-story, two-bay Classical Revival-style single-family rowhouse is one of five constructed under the same permit (#3653). Set on a solid concrete foundation, this brick structure has six-course, American-bond brickwork. A sloped roof caps the dwelling, however, it is obscured by a pent roof of terra cotta tiles. Set between brick firewalls with molded caps, the pent roof features scrolled rafter tails. An exterior brick chimney with plain cap rises from the rear of the rowhouse. A one-story porch with a concrete deck is located on the façade. Set on a brick pier foundation, the porch has a flat roof with overhanging eaves and molded metal cornice. Brick posts with corbeled capitals support the roof. Delicate metal railing completes the porch. A single-leaf, paneled wood door with semi-circular light is located in the eastern bay. Set in a narrow, square-edge wood surround, the door has a single-light wood transom. The west bay has been altered to accommodate a three-sided bay window with single-light casements. The second story has a single and paired window openings with 1/1, double-hung, vinyl sash and rowlock brick sills. Whereas the first-story openings have soldier brick jack arches, the second-story openings have a soldier brick string course directly above.

The foundation of the front porch has been partially infilled. It could not be seen from the public right-of-way if a below-grade door opening is located beneath the porch.

The south (rear) elevation has a two-story, full-width porch. This original feature has been enclosed with German vinyl siding. A shed roof caps the porch. Fenestration consists of tripartite sliding vinyl windows and a single-leaf, paneled metal door with semi-circular light. Additional details were not visible from the public right-of-way.

Site Notes:

July 2010: This single-family rowhouse is located south of A Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The west (side) elevation is adjacent to 1821 A Street, S.E. and the east (side) elevation to 1825 A Street, S.E. A coursed stone retaining wall contains the raised, grassy front yard landscaped with immature plantings. Concrete steps with metal railing extend off the front porch down a concrete walkway to the sidewalk. Concrete steps extend from the walkway underneath the porch. The backyard extends south to an alley and is enclosed with a tall plastic security fence.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

---

Neighborhood: **Capitol Hill** Historic District(s) \_\_\_\_\_  
Subdivision: \_\_\_\_\_  
Ward/ANC: \_\_\_\_\_  
Zoning: Designation Event(s) \_\_\_\_\_  
Contributing: \_\_\_\_\_  
Survey(s) Level(s) of Investigation \_\_\_\_\_  
**Capitol Hill Southeast Phase II (2010)** **Permit Research**  
**Reconnaissance Survey**

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1823\_A\_Street\_SE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1823\_A\_Street\_SE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1823\_A\_Street\_SE\_rear\_looking\_N.JPG  
Date:: Photog:  
Code:: R: Fr:

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:



**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
10/19/1925	3653	Build	

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code            Criteria \_\_\_\_\_

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0099

## BASICS DATA

ID Number: **1111-0099** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1825** **A Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 1825 A Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0099** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1925** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Santmyers, George T.**

**Orig Construction** **Builder** **Poretsky, H.**

**Orig Construction** **Owner** **Poretsky, Silver & Rosen**

Construction Notes:

**One of five rowhouses constructed from the same permit (#3653).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 5)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1925 by H. Poretzky, this two-story, two-bay Classical Revival-style single-family rowhouse is one of five constructed under the same permit (#3653). Set on a solid concrete foundation, this brick structure has six-course, American-bond brickwork. A sloped roof caps the dwelling, however, it is obscured by a pent roof of terra cotta tiles. Set between brick firewalls with molded caps, the pent roof features scrolled rafter tails. An exterior brick chimney with plain cap rises from the rear of the rowhouse. A one-story porch with a concrete deck is located on the façade. Set on a brick pier foundation with brick infill, the porch has a flat roof with overhanging eaves and molded metal cornice. Brick posts with corbeled capitals support the roof. Metal railing completes the porch. A single-leaf, wood door with twelve lights is located in the eastern bay. Set in a narrow, square-edge wood surround, the door has a single-light wood transom. The west bay holds paired, 1/1, double-hung, vinyl-sash windows with a rowlock brick sill. The second story has a single and paired window openings with 1/1, double-hung, vinyl sash and rowlock brick sills. Whereas the first-story openings have soldier brick jack arches, the second-story openings have a soldier brick string course directly above. The south (rear) elevation is fenestrated with single and paired 1/1, double-hung, vinyl-sash windows with rowlock brick sills. A single-leaf, paneled wood door with single-light transom is located in the third bay and served by a metal stoop. Two-light, vinyl-sash sliding basement windows complete fenestration of the rear of the dwelling.

Site Notes:

July 2010: This single-family rowhouse is located south of A Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The west (side) elevation is adjacent to 1823 A Street, S.E. and the east (side) elevation to 1827 A Street, S.E. A rough-faced stone retaining wall contains the raised, grassy front yard with mature shrubs. Concrete steps with metal railing extend off the front porch down a concrete walkway to the sidewalk. The backyard extends south to an alley and includes mature shrubs and a tree. A concrete walkway extends from the rear entry to the alley. Plastic privacy fencing extends down the sides of the backyard while a metal chain-link fence forms the southern boundary of the property.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

---

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

---

Survey(s)

---

Level(s) of Investigation

---

**Capitol Hill Southeast Phase II (2010)**

**Permit Research**

**Reconnaissance Survey**

---

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\**

File: **1825\_A\_Street\_SE\_facade\_looking\_S.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\**

File: **1825\_A\_Street\_SE\_facade\_looking\_SE.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\**

File: **1825\_A\_Street\_SE\_facade\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
II\Database\Pictures\Square 1111\**

File: **1825\_A\_Street\_SE\_rear\_looking\_N.JPG**

Date:: Photog:

Code:: R: Fr:

---

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code          Roll          Frame(s)          Date          Photographer          Caption

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
10/19/1925	3653	Build	

---

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code          Criteria \_\_\_\_\_

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0100

## BASICS DATA

ID Number: **1111-0100** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1827** **A Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 1827 A Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0100** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1925** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Santmyers, George T.**

**Orig Construction** **Builder** **Poretsky, H.**

**Orig Construction** **Owner** **Poretsky, Silver & Rosen**

Construction Notes:

**One of five rowhouses constructed from the same permit (#3653).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 5)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2 plus basement**

Bays Wide: **2**

Height:

Width:

Depth/Length:

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Classical Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1925 by H. Poretsky, this two-story, two-bay Classical Revival-style single-family rowhouse is one of five constructed under the same permit (#3653); this dwelling may have originally been constructed as a duplex. Set on a solid concrete foundation, this brick structure has six-course, American-bond brickwork. A sloped roof caps the dwelling, though is obscured by a brick parapet with molded metal cornice stretching across the façade (north elevation). Three concrete panels with garland and swag ornamentation embellish the parapet. Brick firewalls with metal coping extend down the sides of the rowhouse. An exterior brick chimney with plain cap rises from the rear of the rowhouse. A one-story porch with a concrete deck is located on the façade. Set on a brick pier foundation with lattice infill, the porch has a shed roof with overhanging eaves and molded metal cornice. Brick posts with corbeled capitals support the roof. Metal railing completes the porch. A single-leaf, paneled wood door with oval light is located in the western bay. Set in a narrow, square-edge wood surround, the door has a single-light wood transom. The east bay holds paired, 1/1, double-hung, vinyl-sash windows with a rowlock brick sill. The second story has a three openings with 1/1, double-hung, vinyl sash and rowlock brick sills. Whereas the first-story openings have soldier brick jack arches, the second-story openings have a soldier brick string course directly above. Fenestration of the east (side) elevation consists of 1/1 double-hung and two-light sliding vinyl-sash windows. All openings have rowlock brick sills and two-course, rowlock brick segmental arches. The southern bays of the first and second stories are paired. The south (rear) elevation has a two-story, full-width addition constructed c. 1990. The addition has a stretcher-bond brick veneer and a shed roof extending off the main block. Fenestration consists of single and paired 1/1, double-hung, vinyl-sash windows with rowlock brick sills. A single-leaf, paneled wood door with single-light transom is located in the third bay and served by a metal stoop. Two-light, vinyl-sash sliding basement windows complete fenestration of the addition.

Site Notes:

July 2010: This single-family rowhouse is located south of A Street, S.E. and has a setback of approximately twenty feet from the concrete sidewalk. The west (side) elevation is adjacent to 1825 A Street, S.E. while the east (side) elevation fronts a concrete alley. A stone retaining wall contains the raised, grassy front yard. Concrete steps with metal railing extend off the front porch down a concrete walkway to the sidewalk. Enclosed with a plastic privacy fence set on a concrete retaining wall, the backyard extends south to an alley.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

---

Neighborhood: **Capitol Hill** Historic District(s) \_\_\_\_\_  
Subdivision: \_\_\_\_\_  
Ward/ANC: \_\_\_\_\_  
Zoning: \_\_\_\_\_ Designation Event(s) \_\_\_\_\_  
Contributing: \_\_\_\_\_  
  
Survey(s) \_\_\_\_\_ Level(s) of Investigation \_\_\_\_\_  
**Capitol Hill Southeast Phase II (2010)** **Permit Research**  
**Reconnaissance Survey**

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1827\_A\_Street\_SE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1827\_A\_Street\_SE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1827\_A\_Street\_SE\_rear\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---



Permit Issue Date	Number	Type	Remarks
10/19/1925	3653	Build	

Permit Notes:

---

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

Study Unit

---

Code

Criteria

---

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0050

## BASICS DATA

ID Number: **1111-0050** Year Built: **1922** Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>1835</b>		<b>A Street</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 1835 A Street, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0050</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**  
Desig. Status: **Historic** Quality:  
Purpose: **Rowhouse** Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1922</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1922</b>	<b>Permit</b>			<b>5000 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Miller, W. C. &amp; A. N.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Miller, W. C. &amp; A. N.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Miller, W. C. &amp; A. N.</b>

Construction Notes:

**One of six rowhouses constructed from the same permit (#4729).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row End (1 of 6)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **19**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type	Contributing Status
------------------	---------------------

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1922 by owner, architect, builder W.C. Miller and A.N. Miller, this two-story, three-bay, single-family rowhouse was one of six similar buildings constructed under the same permit (#4729). Set on a solid concrete foundation, this brick structure has five-course, American-bond brick coursing. A brick parapet across the façade (north elevation) and east (side) elevation obscures the sloped roof. The segmental parapet with flared ends has a soldier brick string course, molded metal coping, and a decorative brick bull's eye panel. An interior brick chimney pierces the roof. A one-story, one-bay porch with concrete deck is located on the façade. Set on a brick pier foundation with decorative concrete brick infill, this porch has a low-pitched shed roof with overhanging eaves. Thick metal filigree posts support the porch, linked by metal balusters. The main entry, located in the eastern bay of the first story, holds a single-leaf, paneled wood door with large light. Window openings on the façade have 1/1, double-hung, vinyl sash with concrete sills. First-story openings have soldier brick jack arches. A rowlock brick belt extends above the second-story openings. The east (side) elevation has 1/1, double-hung, vinyl-sash windows with rowlock brick sills and two-course, rowlock brick segmental arches. Fenestration of the south (rear) elevation of the main block consists of 1/1, double-hung, vinyl-sash windows with rowlock brick sills and two-course, rowlock brick segmental arches. A one-story, one-bay original porch occupies the rear of the dwelling. This porch has been either altered or rebuilt so that it now has a stretcher-bond brick veneer. A shed roof with raking wood boards caps the porch. Due to the raised basement, the porch is supported by metal poles. A single-leaf, paneled wood door painted pink is located in a recessed opening along the west (side) elevation. Steps covered in Astroturf provide access to the opening.

Site Notes:

July 2010: This single-family rowhouse is located south of A Street, S.E. and has a setback from the concrete sidewalk of approximately thirty feet. The east (side) elevation is adjacent to 1837 A Street, S.E. The west (side) elevation fronts a concrete alley. The grassy front yard slopes north and is contained by a stone retaining wall to the north and west. Mature shrubs dot the front yard, which has a concrete walkway extending from the front porch to the sidewalk below. Planting beds have been attached to the front and side of the porch. A concrete alley forms the southern boundary of the property. The elevated backyard has mature trees and a metal chain-link fence set on a concrete retaining wall.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

---

Designation Event(s)

---

Survey(s)

---

**Capitol Hill Southeast Phase II (2010)**

Level(s) of Investigation

---

**Permit Research  
Reconnaissance Survey**

---

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase**

**I\Database\Pictures\Square 1111\**

File: **1835\_A\_Street\_SE\_facade\_looking\_SE.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase**

**I\Database\Pictures\Square 1111\**

File: **1835\_A\_Street\_SE\_facade\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase**

**I\Database\Pictures\Square 1111\**

File: **1835\_A\_Street\_SE\_rear\_looking\_NE.JPG**

Date:: Photog:

Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase**

**I\Database\Pictures\Square 1111\**

File: **1835\_A\_Street\_SE\_side\_addition\_looking\_E.J  
PG**

Date:: Photog:

Code:: R: Fr:

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
11/13/1922	4729	Build	

---

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code	Criteria
------	----------

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0051

## BASICS DATA

ID Number: **1111-0051**      Year Built: **1922**      Data Source: **Permit**

Number	Extended	Street	Quad	Type of Address
<b>1837</b>		<b>A Street</b>	<b>SE</b>	<b>Current</b>

Name(s)	Type of Name
<b>Rowhouse, 1837 A Street, S.E.</b>	<b>Common</b>

TaxCode1	TaxCode2	TaxCode3	Type	Explain
<b>1111/0051</b>			<b>Square/Lot</b>	<b>Current</b>

## STATUS/PURPOSE/USE DATA

Resource Type: **Building**      Status Current: **Extant**  
Desig. Status: **Historic**      Quality:  
Purpose: **Rowhouse**      Condition: **Good**

Function/Use	Start	Source	Stop	Source	Explain
<b>Residential (Single-Family)</b>	<b>1922</b>	<b>Permit</b>			<b>Historic/Current</b>

## CONSTRUCTION DATA

Construction Event	Start	Source	Stop	Source	Cost Source
<b>Orig Construction</b>	<b>1922</b>	<b>Permit</b>			<b>5000 Permit</b>

Construction Event	Association	Associated Name
<b>Orig Construction</b>	<b>Architect</b>	<b>Miller, W. C. &amp; A. N.</b>
<b>Orig Construction</b>	<b>Builder</b>	<b>Miller, W. C. &amp; A. N.</b>
<b>Orig Construction</b>	<b>Owner</b>	<b>Miller, W. C. &amp; A. N.</b>

Construction Notes:

**One of six rowhouses constructed from the same permit (#4729).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 6)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**  
Bays Wide: **3**  
Height:      **19**  
Width:      **31**  
Depth/Length:      **31**

Outbuilding Type	Contributing Status
------------------	---------------------

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1922 by owner, architect, builder W.C. Miller and A.N. Miller, this two-story, three-bay, single-family rowhouse was one of six similar buildings constructed under the same permit (#4729). Set on a solid concrete foundation, this brick structure has five-course, American-bond brick coursing. A brick parapet across the façade (north elevation) has a soldier brick string topped by a modified basket weave string and molded metal coping. An interior brick chimney pierces the roof. A one-story, one-bay porch with concrete deck is located on the façade. Set on a brick pier foundation, this porch has a low-pitched shed roof with overhanging eaves. Thick metal filigree posts support the porch, linked by metal balusters. The main entry, located in the western bay of the first story, holds a single-leaf, paneled wood door. Window openings on the façade have 1/1, double-hung, vinyl sash with concrete sills. First-story openings have soldier brick jack arches. A rowlock brick belt extends above the second-story openings. The south (rear) elevation has an original, two-story, full-width porch. Capped by a shed roof with exposed rafter ends, the porch has been enclosed with asbestos shingles. Fenestration consists of 1/1, double-hung, vinyl-sash windows and two-light, sliding-vinyl-sash windows. A single-leaf door opening (door not visible) is sheltered by a metal storm door.

Site Notes:

July 2010: This single-family rowhouse is located south of A Street, S.E. and has a setback from the concrete sidewalk of approximately thirty feet. The building is adjacent to 1835 and 1839 A Street, S.E. Covered with ivy, the front yard slopes severely to the north and terminates at a stone retaining wall. A brick walkway extends off the concrete steps of the front porch to the sidewalk below. A concrete alley forms the southern boundary of the property. The elevated backyard has mature trees and a metal chain-link fence.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)  
**Capitol Hill Southeast Phase II (2010)**

Level(s) of Investigation  
**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1837\_A\_Street\_SE\_facade\_looking\_S.JPG  
Date:: Photog:  
Code:: R: Fr:**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1837\_A\_Street\_SE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:**

---

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1837\_A\_Street\_SE\_rear\_looking\_N.JPG  
Date:: Photog:  
Code:: R: Fr:**

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
11/13/1922	4729	Build	

---

Permit Notes:



**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

---

Code            Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0052

## BASICS DATA

ID Number: **1111-0052** Year Built: **1922** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1839** **A Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 1839 A Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0052** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1922** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1922** **Permit** **5000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Miller, W. C. & A. N.**

**Orig Construction** **Builder** **Miller, W. C. & A. N.**

**Orig Construction** **Owner** **Miller, W. C. & A. N.**

Construction Notes:

**One of six rowhouses constructed from the same permit (#4729).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 6)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **19**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1922 by owner, architect, builder W.C. Miller and A.N. Miller, this two-story, three-bay, single-family rowhouse was one of six similar buildings constructed under the same permit (#4729). Set on a solid concrete foundation, this brick structure has five-course, American-bond brick coursing. A brick parapet across the façade (north elevation) has a soldier brick string topped by a modified basket weave string and molded metal coping. An interior brick chimney pierces the roof. A one-story, one-bay porch with a concrete deck is located on the façade. Set on a brick pier foundation, this porch has a low-pitched shed roof with overhanging eaves. Metal filigree posts support the porch, linked by metal balusters. The main entry, located in the western bay of the first story, holds a single-leaf, paneled wood door with four lights. Window openings on the façade have 1/1, double-hung, vinyl sash with concrete sills. First-story openings have soldier brick jack arches. A rowlock brick belt extends above the second-story openings. The south (rear) elevation has two, 1/1, double-hung, vinyl-sash windows located on the second story. Rowlock brick sills and two-course, rowlock brick segmental arches complete the openings. The first story has a full-width enclosed porch. Based on its form and materials, this porch dates to c. 1975 and replaced an earlier porch. The porch is clad in aluminum siding and pierced by 1/1, double-hung, vinyl-sash windows with false 6/6 muntins and a large picture light.

Site Notes:

July 2010: This single-family rowhouse is located south of A Street, S.E. and has a setback from the concrete sidewalk of approximately thirty feet. The building is adjacent to 1837 and 1841 A Street, S.E. The grassy front yard slopes severely to the north, terminating at a stone retaining wall. Mature shrubs and immature trees dominate the landscape. A brick walkway extends off the front porch to the sidewalk below. A concrete alley forms the southern boundary of the property. The elevated backyard has mature trees and a metal chain-link fence.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Designation Level(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase II (2010)

Permit Research  
Reconnaissance Survey

**PHOTOS - DIGITIZED**

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1839\_A\_Street\_SE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1839\_A\_Street\_SE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1839\_A\_Street\_SE\_rear\_looking\_NE.JPG  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
11/13/1922	4729	Build	

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

---

Code            Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0053

## BASICS DATA

ID Number: **1111-0053** Year Built: **1922** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1841** **A Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 1841 A Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0053** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1922** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1922** **Permit** **5000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Miller, W. C. & A. N.**

**Orig Construction** **Builder** **Miller, W. C. & A. N.**

**Orig Construction** **Owner** **Miller, W. C. & A. N.**

Construction Notes:

**One of six rowhouses constructed from the same permit (#4729).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 6)**

Relate to Street: **Front Yard w/ Setback**

Massing: **Row Building/Front Porch**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **3**

Height:

Width: **19**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1922 by owner, architect, builder W.C. Miller and A.N. Miller, this two-story, three-bay, single-family rowhouse was one of six similar buildings constructed under the same permit (#4729). Set on a solid concrete foundation, this brick structure has five-course, American-bond brick coursing. A brick parapet across the façade (north elevation) has a soldier brick string topped by a modified basket weave string and molded metal coping. An interior brick chimney pierces the roof. A one-story, one-bay porch is located on the façade. Set on a brick pier foundation with decorative concrete block infill, this porch has a low-pitched shed roof with overhanging eaves (deteriorated). Metal filigree posts support the porch, linked by metal balusters. The main entry, located in the western bay of the first story, holds a single-leaf door (not visible). Window openings on the façade have 1/1, double-hung, vinyl sash with concrete sills. First-story openings have soldier brick jack arches. A rowlock brick belt extends above the second-story openings. The south (rear) elevation has 1/1, double-hung, vinyl-sash windows with rowlock brick sills and two-course, rowlock brick segmental arches. The south (rear) elevation has 1/1, double-hung, vinyl-sash windows with rowlock brick sills and two-course, rowlock brick segmental arches. Further details were not visible from the public right-of-way.

Site Notes:

July 2010: This single-family rowhouse is located south of A Street, S.E. and has a setback from the concrete sidewalk of approximately thirty feet. The building is adjacent to 1839 and 1843 A Street, S.E. The grassy front yard slopes severely to the north, terminating at a stone retaining wall. Concrete steps extend off the front porch to a brick walkway with brick steps leading down to the sidewalk. A concrete alley forms the southern boundary of the property. The elevated backyard has mature trees and a metal chain-link fence.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

**PHOTOS - DIGITIZED**

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1841\_A\_Street\_SE\_facade\_looking\_S.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1841\_A\_Street\_SE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

---

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1841\_A\_Street\_SE\_rear\_looking\_N.JPG  
Date:: Photog:  
Code:: R: Fr:

---

**PHOTOS - B/W OR NON-DIGITIZED**

---

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

---

**MISCELLANEOUS NOTES DATA**

---

Notes:

**PERMIT DATA**

---

Permit Issue Date	Number	Type	Remarks
11/13/1922	4729	Build	

---

Permit Notes:



**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

---

Code            Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0054

## BASICS DATA

ID Number: **1111-0054** Year Built: **1922** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1843** **A Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 1843 A Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0054** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Multifamily/Misc)** **1922** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1922** **Permit** **5000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Miller, W. C. & A. N.**

**Orig Construction** **Builder** **Miller, W. C. & A. N.**

**Orig Construction** **Owner** **Miller, W. C. & A. N.**

Construction Notes:

**One of six rowhouses constructed from the same permit (#4729).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row (1 of 6)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Front Porch**  
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **19**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1922 by owner, architect, builder W.C. Miller and A.N. Miller, this two-story, three-bay, single-family rowhouse was one of six similar buildings constructed under the same permit (#4729). Set on a solid concrete foundation, this brick structure has five-course, American-bond brick coursing. A brick parapet across the façade (north elevation) has molded metal coping. An interior brick chimney pierces the roof. A one-story, one-bay porch is located on the façade. Set on a brick pier foundation with decorative concrete block infill, this porch has a low-pitched shed roof with overhanging eaves. Metal filigree posts support the porch, linked by metal balusters. The main entry, located in the western bay of the first story, holds a single-leaf flush wood door. Window openings on the façade have 1/1, double-hung, vinyl sash with concrete sills. First-story openings have soldier brick jack arches. A rowlock brick belt extends above the second-story openings. The south (rear) elevation has 1/1, double-hung, vinyl-sash windows with rowlock brick sills and two-course, rowlock brick segmental arches. A one-story, one-bay shed-roofed porch is located in the western bay. This porch shelters a door opening. Additional details were not visible from the public right-of-way due to change in elevation.

Site Notes:

July 2010: This single-family rowhouse is located south of A Street, S.E. and has a setback from the concrete sidewalk of approximately thirty feet. The building is adjacent to 1841 and 1845 A Street, S.E. The grassy front yard slopes severely to the north, terminating at a stone retaining wall. Concrete steps with metal railing link the front porch with the sidewalk below. A concrete alley forms the southern boundary of the property. The backyard is elevated from the alley and was not visible from the public right-of-way.

**NOTABLE FEATURES DATA**

Component Feature

**EXTERIOR MATERIALS DATA**

Roof Component Material Color Treatment Source

Wall Component Material Color Treatment Source

Structure Component Material Feature Source

Materials Notes:

**WINDOW/DOOR/INTERIOR DATA**

Window Location Aperture Shape Type Lights Material

Door Location Aperture Shape Type Panels Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Capitol Hill Southeast Phase II (2010)

Level(s) of Investigation

Permit Research  
Reconnaissance Survey

**PHOTOS - DIGITIZED**

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1843\_A\_Street\_SE\_facade\_looking\_SE.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1843\_A\_Street\_SE\_facade\_looking\_SW.JPG  
Date:: Photog:  
Code:: R: Fr:

Caption:

**Image File Not Found**

Path: X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\  
File: 1843\_A\_Street\_SE\_rear\_looking\_NW.JPG  
Date:: Photog:  
Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption

**MISCELLANEOUS NOTES DATA**

Notes:

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
11/13/1922	4729	Build	

Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit

---

Code            Criteria

---

**DATA PROCESSING EVENTS DATA**

---

# Resource All Data Report

# ID Number: 1111-0055

## BASICS DATA

ID Number: **1111-0055** Year Built: **1922** Data Source: **Permit**

Number Extended Street Quad Type of Address

**1845** **A Street** **SE Current**

Name(s) Type of Name

**Rowhouse, 1845 A Street, S.E.** **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

**1111/0055** **Square/Lot** **Current**

## STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

**Residential (Single-Family)** **1922** **Permit** **Historic/Current**

## CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

**Orig Construction** **1922** **Permit** **5000 Permit**

Construction Event Association Associated Name

**Orig Construction** **Architect** **Miller, W. C. & A. N.**

**Orig Construction** **Builder** **Miller, W. C. & A. N.**

**Orig Construction** **Owner** **Miller, W. C. & A. N.**

Construction Notes:

**One of six rowhouses constructed from the same permit (#4729).**

## PEOPLE/EVENTS DATA

Racial Segregation Status:

## SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**  
Streetscape: **Intact**  
Relate to Othr Bldgs: **Row End (1 of 6)**  
Relate to Street: **Front Yard w/ Setback**  
Massing: **Row Building/Front Porch**  
Footprint: **L-Shaped**

Cross Reference Notes:

Number Stories: **2 plus basement**

Bays Wide: **3**

Height:

Width: **19**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway:

Outbuilding Type

Contributing Status

Outbuilding Notes:

**STYLE/EXTERIOR DATA**

Architectural Style(s)

**Colonial Revival**

Exterior & Architectural Notes:

July 2010: Constructed in 1922 by owner, architect, builder W.C. Miller and A.N. Miller, this two-story, three-bay, single-family rowhouse was one of six similar buildings constructed under the same permit (#4729). Set on a solid concrete foundation, this brick structure has five-course, American-bond brick coursing. A brick parapet across the façade (north elevation) and east (side) elevation obscures the sloped roof. The segmental parapet with flared ends has a soldier brick string course, molded metal coping, and a decorative brick bull's eye panel. An interior brick chimney pierces the roof. A one-story, one-bay porch is located on the façade. Set on a brick pier foundation with lattice infill, this porch has a low-pitched shed roof with overhanging eaves. Brick columns with square balusters set between support the porch roof. The main entry, located in the western bay of the first story, holds a single-leaf, paneled wood door with large oval light. Window openings on the façade have 1/1, double-hung, vinyl sash with concrete sills. First-story openings have soldier brick jack arches. A rowlock brick belt extends above the second-story openings. A single-leaf, paneled wood door with semi-circular light is located in a below-grade opening in the eastern bay. Fenestration of the east (side) elevation consists of 1/1, double-hung, vinyl-sash windows with concrete sills. First-story openings have soldier brick jack arches. A rowlock brick belt extends above the second-story openings. Additional fenestration consists of a basement window (sash not visible). The south (rear) elevation has a two-story original porch set on a solid parged foundation. Not quite spanning the width of the elevation, the porch is capped by a shed roof, and has enclosed with German vinyl siding and paired 1/1, double-hung, vinyl-sash windows. A single-leaf, paneled metal door with light is located in the westernmost bay of the rear of the porch.

Site Notes:

July 2010: Located high above the intersection of A Street, S.E. and 19th Street, S.E., this single-family rowhouse has a setback of approximately thirty feet from the concrete sidewalk along A Street, S.E. The dwelling is about twenty feet from the concrete sidewalk aside 19th Street, S.E. With stone retaining walls running aside the sidewalks, the grassy property slopes severely to the east. Brick steps with metal railing link the front porch with the sidewalk below. A concrete alley forms the southern boundary of the property.

**NOTABLE FEATURES DATA**

Component	Feature
-----------	---------

**EXTERIOR MATERIALS DATA**

Roof Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Wall Component	Material	Color	Treatment	Source
----------------	----------	-------	-----------	--------

Structure Component	Material	Feature	Source
---------------------	----------	---------	--------

Materials Notes:

[Empty text box for materials notes]

**WINDOW/DOOR/INTERIOR DATA**

Window Location	Aperture Shape	Type	Lights	Material
-----------------	----------------	------	--------	----------

Door Location	Aperture Shape	Type	Panels	Material
---------------	----------------	------	--------	----------

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

[Empty text box for interior notes]

**PLAN/SURVEY/DESIGNATION DATA**

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

**Capitol Hill Southeast Phase II (2010)**

**Permit Research  
Reconnaissance Survey**

**PHOTOS - DIGITIZED**

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1845\_A\_Street\_facade\_looking\_S.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1845\_A\_Street\_facade\_looking\_SW.JPG**

Date:: Photog:

Code:: R: Fr:

Caption:

**Image File Not Found**

Path: **X:\SD Databases\SE Phase  
I\Database\Pictures\Square 1111\**

File: **1845\_A\_Street\_rear\_looking\_NW.JPG**

Date:: Photog:

Code:: R: Fr:

**PHOTOS - B/W OR NON-DIGITIZED**

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

**MISCELLANEOUS NOTES DATA**

Notes:

**PERMIT DATA**

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------



Permit Notes:

**BIBLIOGRAPHIC DATA**

---

**SIGNIFICANCE DATA**

---

Study Unit \_\_\_\_\_

Code

Criteria

---

**DATA PROCESSING EVENTS DATA**

---

