

Resource All Data Report

ID Number: 1114SE-0016

BASICS DATA

ID Number: **1114SE-0016** Year Built: **1926** Data Source: **Permit**

Number Extended Street Quad Type of Address

1801 Potomac Avenue SE Current

Name(s) Type of Name

Rowhouse, 1801 Potomac Avenue, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114SE/00 Square/Lot Current
16

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1926 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1926 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row Corner (1 of 13)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1926, this two-story, two-bay rowhouse is one of thirteen similar residences designed by architect George T. Santmyers. These buildings were constructed by owner/builder T.A. Jameson from the same permit (#5555) and reflect the stylistic influences of the Colonial Revival as well as the Craftsman style, both of which were popular in the second quarter of the twentieth-century. This end-unit rowhouse is set on a solid concrete foundation and constructed of brick. The façade (northwest elevation) and southwest (side) elevation are faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the basement openings as well as the first- and second-story openings. The materials of the flat roof were not visible from the public right-of-way due to a false mansard roof with flared eaves. The roof is covered with hexagonal slate shingles and includes overhanging eaves, a boxed cornice with scrolled brackets, and two dormers along the façade. The dormers are covered with shed roofs with narrow, exposed rafter tails. Clad in slate shingles, the dormers are fenestrated with ten-light wood-sash windows. The façade (northwest elevation) has a single-leaf, paneled wood door with a single-light transom in the eastern bay of the first story. Window openings on the dwelling contain 1/1, double-hung, vinyl-sash windows with false 6/1 muntins and concrete sills. The western bay of the first story is paired while the second story has triple window openings. A one-story, full-width porch shelters the first story of the façade. The porch is set on a solid brick foundation pierced by paired one-light, vinyl sliding windows. The porch has a flat roof with overhanging eaves and modillions supported by wood posts. The porch is edged with square balusters. The southwest (side) elevation features a two-story projecting bay. Fenestration consists of two-light, vinyl-sash sliding basement windows, a six-light awning window, and 1/1, double-hung, vinyl-sash windows with false 6/1 muntins. All of the openings have concrete sills. The southeast (rear) elevation has a two-story wing which, based on its form and documentation on the 1928 Sanborn Insurance Company map, may have originally been a sleeping porch. This wing has been clad in vinyl siding and is capped by a shed roof. The rear elevation has a paneled, roll-up garage door with lights providing access to the lower level. Additional fenestration consists of double-leaf, metal-frame glass doors, paired one-light sliding vinyl windows, and a six-light casement window. A single-leaf door is located on the southwest (side) elevation. The first-story entries are accessed via a wooden porch which wraps around the side and rear elevations.

Site Notes:

February 2009: This dwelling is located south of Potomac Avenue, S.E. and has a setback from the concrete sidewalk of approximately twenty feet. The level, grassy lot has mature shrubs and is enclosed by a chain-link fence. South of the property is E Street, S.E., accessed via a concrete parking pad. To the west is a large open area with mature trees. The dwelling is attached on the east (side) elevation to 1803 Potomac Avenue, S.E.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Hexagonal Shape	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	6/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	6/1 Triple	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G**

File: **St\Database\Pictures\Square 1114SE\
1801PotomacAvenueSE, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G**

File: **St\Database\Pictures\Square 1114SE\
1801PotomacAvenueSE, looking east.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/28/1926	5555	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114SE-0017

BASICS DATA

ID Number: **1114SE-0017** Year Built: **1926** Data Source: **Permit**

Number Extended Street Quad Type of Address

1803 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1803 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114SE/00 **Square/Lot** **Current**
17

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1926** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1926** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 13)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1926, this two-story, two-bay rowhouse is one of thirteen similar residences designed by architect George T. Santmyers. These buildings were constructed by owner/builder T.A. Jameson from the same permit (#5555) and reflect the stylistic influences of the Colonial Revival as well as the Craftsman style, both of which were popular in the second quarter of the twentieth-century. This dwelling is set on a solid concrete foundation and constructed of brick. The façade (northwest elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings. The materials of the flat roof were not visible from the public right-of-way due to a false mansard roof with flared eaves. Extending between stepped brick firewalls, the roof is covered with hexagonal slate shingles and includes overhanging eaves with exposed rafter ends and a dormer. Clad in shingles, the shed-roof dormer has narrow exposed rafter ends and is fenestrated with paired, ten-light wood-sash windows. The western bay of the façade holds a single-leaf, paneled door with single-light transom. The dwelling is fenestrated with 1/1, double-hung, vinyl-sash windows with concrete sills. The eastern bay of the first story is paired while the second story has tripled window openings. A one-story, full-width porch shelters the first story of the façade. The porch is set on a brick pier foundation with lattice infill. The porch has a flat roof with overhanging eaves, modillions, and a molded cornice all supported by wood posts. The porch is edged with square balusters. The southeast (rear) elevation has a two-story wing which, based on its form and documentation on the 1928 Sanborn Insurance Company map, may have originally been a sleeping porch. However, the rear elevation was not photographed by the volunteer surveyor. This wing has been clad in vinyl siding and is capped by a shed roof. The rear elevation has a double-leaf wood garage door which provides access to the lower level. Additional fenestration consists of a single-leaf wood door on the first story accessed via wood steps and 1/1, double-hung, vinyl-sash windows.

Site Notes:

February 2009: This rowhouse is located south of Potomac Avenue, S.E. and is set back from the concrete sidewalk approximately twenty feet. The southwest (side) elevation is attached to 1801 Potomac Avenue, S.E. and the northeast (side) elevation is attached to 1805 Potomac Avenue, S.E. The level, grassy front yard has immature plantings and a chain-link fence separating the property to the west. A concrete walkway extends from the primary entry to the sidewalk. The rear of the property is enclosed by a chain-link fence and has a concrete parking pad that extends to meet E Street, S.E.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Hexagonal Shape	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1 Triple	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1114SE

File: **1803PotomacAvenueSE, looking south.jpg**

Date::

Photog:

Code::

R:

Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

12/28/1926

5555 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Saturday, July 20, 2013

DC HPO Survey - SouthEast Phase 1

ID_Number: 1114SE-0017 Page 3

Resource All Data Report

ID Number: 1114SE-0018

BASICS DATA

ID Number: **1114SE-0018** Year Built: **1926** Data Source: **Permit**

Number Extended Street Quad Type of Address

1805 Potomac Avenue SE

Name(s) Type of Name

Rowhouse, 1805 Potomac Avenue, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114SE/00 Square/Lot Current
18

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1926 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1926 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 13)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1926, this two-story, two-bay rowhouse is one of thirteen similar residences designed by architect George T. Santmyers. These buildings were constructed by owner/builder T.A. Jameson from the same permit (#5555) and reflect the stylistic influences of the Colonial Revival as well as the Craftsman style, both of which were popular in the second quarter of the twentieth-century. This dwelling is set on a solid concrete foundation and constructed of brick. The façade (northwest elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings. The materials of the flat roof were not visible from the public right-of-way due to a false mansard roof with flared eaves. Extending between stepped brick firewalls, the roof is covered with hexagonal shingles and includes overhanging eaves with exposed rafter ends and a dormer. Clad in shingles, the shed-roof dormer has narrow exposed rafter ends and is fenestrated with paired, ten-light wood-sash windows. The western bay of the façade holds a single-leaf, paneled wood door with nine lights and a single-light transom. The dwelling is fenestrated with 1/1, double-hung, vinyl-sash windows with false 6/6 muntins and concrete sills. The eastern bay of the first story is paired while the second story has a triple window opening. A one-story, full-width porch shelters the first story of the façade. The porch is set on a brick pier foundation with lattice infill. The porch has a flat roof with overhanging eaves, modillions, and a molded cornice supported by wood posts. The porch is edged with square balusters. Poured concrete steps with a metal railing provide access to the porch. The southeast (rear) elevation has a two-story wing which, based on its form and documentation on the 1928 Sanborn Insurance Company map, may have originally been a sleeping porch. However, the rear elevation was not photographed by the volunteer surveyor. Based on Google street view imagery, this wing has been clad in vinyl siding and is capped by a shed roof with an interior brick chimney. The rear elevation has a paneled metal garage door which provides access to the lower level. Additional fenestration consists of a single-leaf wood door with three lights accessed via wood steps and 1/1, double-hung, vinyl-sash windows.

Site Notes:

February 2009: This rowhouse is located south of Potomac Avenue, S.E. and is set back from the concrete sidewalk approximately twenty feet. The southwest (side) elevation is attached to 1803 Potomac Avenue, S.E. and the northeast (side) elevation is attached to 1807 Potomac Avenue, S.E. The level, grassy front yard has a concrete walkway extending from the primary entry to the sidewalk. The rear of the property is enclosed by a chain-link fence and has a concrete parking pad that extends to meet E Street, S.E.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Hexagonal Shape	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1 Triple	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1114SE

File: **1805PotomacAvenueSE, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

12/28/1926	5555	Build	
-------------------	-------------	--------------	--

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

Resource All Data Report

ID Number: 1114SE-0019

BASICS DATA

ID Number: **1114SE-0019** Year Built: **1926** Data Source: **Permit**

Number Extended Street Quad Type of Address

1807 Potomac Avenue SE Current

Name(s) Type of Name

Rowhouse, 1807 Potomac Avenue, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114SE/00 Square/Lot Current
19

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1926 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1926 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 13)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1926, this two-story, two-bay rowhouse is one of thirteen similar residences designed by architect George T. Santmyers. These buildings were constructed by owner/builder T.A. Jameson from the same permit (#5555) and reflect the stylistic influences of the Colonial Revival as well as the Craftsman style, both of which were popular in the second quarter of the twentieth-century. This dwelling is set on a solid concrete foundation and constructed of brick. The façade (northwest elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings. The materials of the flat roof were not visible from the public right-of-way due to a false mansard roof with flared eaves. Extending between stepped brick firewalls, the roof is covered with asphalt shingles and includes overhanging eaves with exposed rafter ends and a dormer. Clad in shingles, the shed-roof dormer has narrow exposed rafter ends and is fenestrated with paired, ten-light wood-sash windows. The western bay of the façade holds a single-leaf, paneled wood door and a single-light transom. The dwelling is fenestrated with 6/1, double-hung, wood-sash windows with concrete sills. The eastern bay of the first story is paired while the second story has a triple window opening. A one-story, full-width porch shelters the first story of the façade. The porch is set on a brick pier foundation with lattice infill. The porch has a flat roof with overhanging eaves and modillions and is supported by wood posts. The porch is edged with square balusters. Poured concrete steps provide access to the porch. The southeast (rear) elevation has a two-story wing which, based on its form and documentation on the 1928 Sanborn Insurance Company map, may have originally been a sleeping porch. However, the rear elevation was not photographed by the volunteer surveyor. Based on Google street view imagery, this wing has been clad in vinyl siding and is capped by a shed roof with an interior brick chimney. The rear elevation has a single-leaf wood door with three lights accessed via wood steps and 1/1, double-hung, vinyl-sash windows.

Site Notes:

February 2009: This rowhouse is located south of Potomac Avenue, S.E. and is set back from the concrete sidewalk approximately twenty feet. The southwest (side) elevation is attached to 1805 Potomac Avenue, S.E. and the northeast (side) elevation is attached to 1809 Potomac Avenue, S.E. The level, grassy front yard has a concrete walkway extending from the primary entry to the sidewalk. The rear of the property is enclosed by a wood privacy fence and has a concrete parking pad that extends to meet E Street, S.E.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Asphalt		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	6/1 Double	Wood
2 Flr Windows	Rectangular	Dbl-Hung	6/1 Triple	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1114SE

File: **1807PotomacAvenueSE, looking south.jpg**

Date::

Photog:

Code::

R:

Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

12/28/1926

5555 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Saturday, July 20, 2013

DC HPO Survey - SouthEast Phase 1

ID_Number: 1114SE-0019 Page 3

Resource All Data Report

ID Number: 1114SE-0020

BASICS DATA

ID Number: **1114SE-0020** Year Built: **1926** Data Source: **Permit**

Number Extended Street Quad Type of Address

1809 Potomac Avenue SE Current

Name(s) Type of Name

Rowhouse, 1809 Potomac Avenue, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114SE/00 Square/Lot Current
20

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1926 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1926 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 13)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1926, this two-story, two-bay rowhouse is one of thirteen similar residences designed by architect George T. Santmyers. These buildings were constructed by owner/builder T.A. Jameson from the same permit (#5555) and reflect the stylistic influences of the Colonial Revival as well as the Craftsman style, both of which were popular in the second quarter of the twentieth-century. This dwelling is set on a solid concrete foundation and constructed of brick. The façade (northwest elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings. The materials of the flat roof were not visible from the public right-of-way due to a false mansard roof. Extending between stepped brick firewalls, the roof is covered with hexagonal shingles and includes overhanging eaves with exposed rafter ends and a dormer. Clad in shingles, the shed-roof dormer has narrow exposed rafter ends and is fenestrated with paired, ten-light wood-sash windows. The western bay of the façade holds a single-leaf, paneled wood door and a single-light transom. The dwelling is fenestrated with 6/1, double-hung, wood-sash windows with concrete sills. The eastern bay of the first story is paired while the second story has a triple window opening. A one-story, full-width porch shelters the first story of the façade. The porch is set on a brick pier foundation with lattice infill. The porch has a flat roof with overhanging eaves and molded cornice and is supported by wood posts. The porch is edged with square balusters. Poured concrete steps with a metal railing provide access to the porch. The southeast (rear) elevation has a two-story wing which, based on its form and documentation on the 1928 Sanborn Insurance Company map, may have originally been a sleeping porch. However, the rear elevation was not photographed by the volunteer surveyor. Based on Google street view imagery, this wing has been clad in vinyl siding and is capped by a shed roof with an interior brick chimney. The rear elevation has a roll-up garage door providing access to the lower level. Additional fenestration consists of a double-leaf, metal-frame glass door and 1/1, double-hung, vinyl-sash windows. A wooden porch has been constructed on the first story.

Site Notes:

February 2009: This rowhouse is located south of Potomac Avenue, S.E. and is set back from the concrete sidewalk approximately twenty feet. The southwest (side) elevation is attached to 1807 Potomac Avenue, S.E. and the northeast (side) elevation is attached to 1811 Potomac Avenue, S.E. The level, grassy front yard has a concrete walkway extending from the primary entry to the sidewalk. The rear of the property is enclosed by a chain-link fence and has a concrete parking pad that extends to meet E Street, S.E.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Hexagonal Shape	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	6/1 Double	Wood
2 Flr Windows	Rectangular	Dbl-Hung	6/1 Triple	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1114SE

File: **1809PotomacAvenueSE, looking south.jpg**

Date::

Photog:

Code::

R:

Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

12/28/1926

5555 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Saturday, July 20, 2013

DC HPO Survey - SouthEast Phase 1

ID_Number: 1114SE-0020 Page 3

Resource All Data Report

ID Number: 1114SE-0021

BASICS DATA

ID Number: **1114SE-0021** Year Built: **1926** Data Source: **Permit**

Number Extended Street Quad Type of Address

1811 Potomac Avenue SE Current

Name(s) Type of Name

Rowhouse, 1811 Potomac Avenue, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114SE/00 Square/Lot Current
21

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1926 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1926 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 13)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories:

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1926, this two-story, two-bay rowhouse is one of thirteen similar residences designed by architect George T. Santmyers. These buildings were constructed by owner/builder T.A. Jameson from the same permit (#5555) and reflect the stylistic influences of the Colonial Revival as well as the Craftsman style, both of which were popular in the second quarter of the twentieth-century. This dwelling is set on a solid concrete foundation and constructed of brick. The façade (northwest elevation) has been clad in Permastone. The materials of the flat roof were not visible from the public right-of-way due to a false mansard roof. Extending between stepped brick firewalls, the roof is covered with hexagonal shingles and includes overhanging eaves with a boxed cornice supported by scrolled brackets. Two shed-roof dormers pierce the roof. Clad in shingles and fenestrated with single-light windows, the dormers have narrow overhanging eaves and rafter ends. The western bay of the façade holds a single-leaf wood door and a single-light transom. The eastern bay of the first story holds a paired opening that now contains a single-light picture window with a flat arch of Permastone with a faux keystone. The second story is fenestrated with a triple window of 1/1, double-hung, vinyl-sash with concrete sill and Permastone flat arch. A one-story, full-width porch shelters the first story of the façade. The porch is set on a brick pier foundation with lattice infill. The porch has a flat roof with overhanging eaves and a molded cornice. The porch posts that support the roof have been covered with Permastone. The porch is edged with square wood balusters. The raised foundation of the porch has been clad in Permastone. Poured concrete steps with a metal railing provide access to the porch. The southeast (rear) elevation has a two-story wing which, based on its form and documentation on the 1928 Sanborn Insurance Company map, may have originally been a sleeping porch. This wing has been clad in Permastone and is capped by a shed roof with an interior brick chimney. The rear elevation has 1/1, double-hung, vinyl-sash windows with metal awnings above the first-story openings. A first-story deck has been constructed on the rear of the dwelling.

Site Notes:

February 2009: This rowhouse is located south of Potomac Avenue, S.E. and is set back from the concrete sidewalk approximately twenty feet. The southwest (side) elevation is attached to 1809 Potomac Avenue, S.E. and the northeast (side) elevation is attached to 1813 Potomac Avenue, S.E. The level, grassy front yard has a concrete walkway extending from the primary entry to the sidewalk. The rear of the property is enclosed by a chain-link fence and has a concrete parking pad that extends to meet E Street, S.E. Half of the backyard has been landscaped with a raised planting bed with immature trees and shrubs.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Hexagonal Shape	
Wall Component	Material	Color	Treatment	Source
Facade	Permastone		Refaced*	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Fixed	1-light	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1 Triple	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1114SE

File: **1811PotomacAvenueSE, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

12/28/1926	5555	Build	
-------------------	-------------	--------------	--

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

Resource All Data Report

ID Number: 1114SE-0022

BASICS DATA

ID Number: **1114SE-0022** Year Built: **1926** Data Source: **Permit**

Number Extended Street Quad Type of Address

1813 Potomac Avenue SE Current

Name(s) Type of Name

Rowhouse, 1813 Potomac Avenue, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114SE/00 Square/Lot Current
22

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1926 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1926 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 13)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Garage

Contributing Status

Contributing

Outbuilding Notes:

February 2009: This one-story, one-bay garage is located in the rear of the property. The garage is documented on the 1928 and 1960 Sanborn Insurance Company maps. As such, in conjunction with its form and materials, this garage can be

assigned a construction date of c. 1926. This wood-frame structure has been clad in wood siding and is capped by a front-gabled roof. The roof has partially collapsed. The façade (southeast elevation) has a vehicular opening.

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1926, this two-story, two-bay rowhouse is one of thirteen similar residences designed by architect George T. Santmyers. These buildings were constructed by owner/builder T.A. Jameson from the same permit (#5555) and reflect the stylistic influences of the Colonial Revival as well as the Craftsman style, both of which were popular in the second quarter of the twentieth-century. This dwelling is set on a solid concrete foundation and constructed of brick. The façade (northwest elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings. The materials of the flat roof were not visible from the public right-of-way due to a false mansard roof. Extending between stepped brick firewalls, the roof is covered with asphalt shingles and includes overhanging eaves, scrolled brackets, and two dormers. Clad in shingles, the shed-roof dormers have narrow exposed rafter ends and are fenestrated with ten-light wood-sash windows. The western bay of the façade holds a single-leaf metal door with an oval light and a single-light transom. The dwelling is fenestrated with 6/1, double-hung, wood-sash windows with concrete sills. The eastern bay of the first story is paired while the second story has a triple window opening sheltered by a metal awning. A one-story, full-width porch shelters the first story of the façade. The porch is set on a brick pier foundation with lattice infill. The porch has a flat roof with overhanging eaves and molded cornice and is supported by wood posts. The porch is edged with narrow square balusters. Poured concrete steps with a metal railing provide access to the porch. The southeast (rear) elevation has a two-story wing which, based on its form and documentation on the 1928 Sanborn Insurance Company map, may have originally been a sleeping porch. This wing has been clad in vinyl siding and is capped by a shed roof with an interior brick chimney. Fenestration consists of a single-leaf, metal-frame door with lights and 1/1, double-hung, vinyl-sash windows.

Site Notes:

February 2009: This rowhouse is located south of Potomac Avenue, S.E. and is set back from the concrete sidewalk approximately twenty feet. The southwest (side) elevation is attached to 1811 Potomac Avenue, S.E. and the northeast (side) elevation is attached to 1815 Potomac Avenue, S.E. The level, grassy front yard has a concrete walkway extending from the primary entry to the sidewalk. The rear of the property is enclosed by a chain-link fence and extends to meet E Street, S.E. A garage is located in the backyard.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Asphalt		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	6/1 Double	Wood
2 Flr Windows	Rectangular	Dbl-Hung	6/1 Triple	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G**

File: **St\Database\Pictures\Square 1114SE\
1813PotomacAvenueSE, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G**

File: **St\Database\Pictures\Square 1114SE\
1813PotomacAvenueSErear, looking
northwest.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/28/1926	5555	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114SE-0023

BASICS DATA

ID Number: **1114SE-0023** Year Built: **1926** Data Source: **Permit**

Number Extended Street Quad Type of Address

1815 Potomac Avenue SE

Name(s) Type of Name

Rowhouse, 1815 Potomac Avenue, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114SE/00 Square/Lot Current
23

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1926 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1926 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 13)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Garage

Contributing Status

Contributing

Outbuilding Notes:

February 2009: This one-story, one-bay garage is located in the rear of the property. The garage is documented on the 1928 and 1960 Sanborn Insurance Company maps. As such, in conjunction with its form and materials, this garage can be

assigned a construction date of c. 1926. This wood-frame structure has been clad in wood siding and is capped by a front-gabled roof. The façade (southeast elevation) has a double-leaf wood door.

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1926, this two-story, two-bay rowhouse is one of thirteen similar residences designed by architect George T. Santmyers. These buildings were constructed by owner/builder T.A. Jameson from the same permit (#5555) and reflect the stylistic influences of the Colonial Revival as well as the Craftsman style, both of which were popular in the second quarter of the twentieth-century. This dwelling is set on a solid concrete foundation and constructed of brick. The façade (northwest elevation) has been clad in German vinyl siding. The materials of the flat roof were not visible from the public right-of-way due to a false mansard roof. Extending between stepped brick firewalls, the roof is covered with asphalt shingles and includes overhanging eaves, scrolled brackets, and two dormers. Clad in shingles, the shed-roof dormers have narrow rafter ends and are fenestrated with ten-light wood-sash windows. The western bay of the façade holds a single-leaf door with a single-light transom. The dwelling is fenestrated with 6/1, double-hung, wood-sash windows with vinyl-clad surrounds. The eastern bay of the first story is paired while the second story has a triple window with inoperable paneled vinyl shutters. A one-story, full-width porch shelters the first story of the façade. The porch is set on a brick pier foundation with lattice infill. The porch has a flat roof with overhanging eaves and molded cornice and is supported by wood posts. The porch is edged with square balusters. Poured concrete steps with a metal railing provide access to the porch. The southeast (rear) elevation has a two-story wing which, based on its form and documentation on the 1928 Sanborn Insurance Company map, may have originally been a sleeping porch. This wing has been clad in vinyl siding and is capped by a shed roof with an interior brick chimney. Fenestration consists of a single-leaf, metal-frame door with lights and 1/1, double-hung, vinyl-sash windows.

Site Notes:

February 2009: This rowhouse is located south of Potomac Avenue, S.E. and is set back from the concrete sidewalk approximately twenty feet. The southwest (side) elevation is attached to 1813 Potomac Avenue, S.E. and the northeast (side) elevation is attached to 1817 Potomac Avenue, S.E. The level, grassy front yard has a concrete walkway extending from the primary entry to the sidewalk. A mature shrub dots the yard. The rear of the property extends to meet E Street, S.E. and includes a garage.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Asphalt		Shingled	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	6/1 Double	Wood
2 Flr Windows	Rectangular	Dbl-Hung	6/1 Triple	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G**

File: **St\Database\Pictures\Square 1114SE\
1815PotomacAvenueSE, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G**

File: **St\Database\Pictures\Square 1114SE\
1815PotomacAvenueSErear, looking
northwest.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/28/1926	5555	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114SE-0024

BASICS DATA

ID Number: **1114SE-0024** Year Built: **1926** Data Source: **Permit**

Number Extended Street Quad Type of Address

1817 Potomac Avenue SE Current

Name(s) Type of Name

Rowhouse, 1817 Potomac Avenue, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114SE/00 Square/Lot Current
24

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1926 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1926 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 13)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Garage

Contributing Status

Non-Contributing

Outbuilding Notes:

February 2009: This one-story, one-bay garage is located in the rear of the property. Although a garage is documented on the 1928 and 1960 Sanborn Insurance Company maps in this location, its form and materials suggest that garage was

constructed c. 2005. The garage is clad in German vinyl siding and capped by a front-gabled roof of asphalt shingles. The façade (southeast elevation) has a vehicular opening.

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1926, this two-story, two-bay rowhouse is one of thirteen similar residences designed by architect George T. Santmyers. These buildings were constructed by owner/builder T.A. Jameson from the same permit (#5555) and reflect the stylistic influences of the Colonial Revival as well as the Craftsman style, both of which were popular in the second quarter of the twentieth-century. This dwelling is set on a solid concrete foundation and constructed of brick. The façade (northwest elevation) has been clad in Permastone. The materials of the flat roof were not visible from the public right-of-way due to a false mansard roof. Extending between stepped brick firewalls, the roof is covered with hexagonal shingles and includes overhanging eaves, scrolled brackets, and a dormer. Clad in shingles, the shed-roof dormer has narrow exposed rafter ends and has paired, ten-light wood-sash windows. The western bay of the façade holds a single-leaf, paneled metal door with a single-light transom. The dwelling is fenestrated with 1/1, double-hung, vinyl-sash windows with concrete sills. Openings on the first story are paired, while the second story holds triple window openings. A one-story, full-width porch shelters the first story of the façade. The porch is set on a brick pier foundation with lattice infill. The porch has a flat roof with overhanging eaves and is supported by wood posts. The porch is edged with narrow square balusters. Poured concrete steps with a metal railing provide access to the porch. The southeast (rear) elevation has a two-story wing which, based on its form and documentation on the 1928 Sanborn Insurance Company map, may have originally been a sleeping porch. This wing has been clad in vinyl siding and is capped by a shed roof with an interior brick chimney. Fenestration consists of paired 1/1, double-hung, vinyl-sash windows.

Site Notes:

February 2009: This rowhouse is located south of Potomac Avenue, S.E. and is set back from the concrete sidewalk approximately twenty feet. The southwest (side) elevation is attached to 1815 Potomac Avenue, S.E. and the northeast (side) elevation is attached to 1819 Potomac Avenue, S.E. The level, grassy front yard has a concrete walkway extending from the primary entry to the sidewalk. Mature shrubs line the front porch. The rear of the property extends to meet E Street, S.E. and includes a garage.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Hexagonal Shape	
Wall Component	Material	Color	Treatment	Source
Facade	Permastone		Refaced*	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1 Triple	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1114SE

File: **1817PotomacAvenueSE, looking south.jpg**

Date::

Photog:

Code::

R:

Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1114SE

File: **1817PotomacAvenueSErear, looking northwest.jpg**

Date::

Photog:

Code::

R:

Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/28/1926	5555	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114SE-0025

BASICS DATA

ID Number: **1114SE-0025** Year Built: **1926** Data Source: **Permit**

Number Extended Street Quad Type of Address

1819 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1819 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114SE/00 **Square/Lot** **Current**
25

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1926** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1926** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 13)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Garage

Contributing Status

Contributing

Outbuilding Notes:

February 2009: This one-story, one-bay garage is located in the rear of the property. The garage is documented on the 1928 and 1960 Sanborn Insurance Company maps. As such, in conjunction with its form and materials, this garage can be

assigned a construction date of c. 1926. This wood-frame structure has been clad in wood siding and is capped by a front-gabled roof. The façade (southeast elevation) has a double-leaf, paneled wood door.

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1926, this two-story, two-bay rowhouse is one of thirteen similar residences designed by architect George T. Santmyers. These buildings were constructed by owner/builder T.A. Jameson from the same permit (#5555) and reflect the stylistic influences of the Colonial Revival as well as the Craftsman style, both of which were popular in the second quarter of the twentieth-century. This dwelling is set on a solid concrete foundation and constructed of brick. The façade (northwest elevation) has five-course, American-bond brick coursing. The materials of the flat roof were not visible from the public right-of-way due to a false mansard roof. Extending between stepped brick firewalls, the roof is covered with hexagonal shingles and includes overhanging eaves with exposed ends and a dormer. Clad in shingles, the shed-roof dormer has narrow exposed rafter ends and has paired, ten-light wood-sash windows. The western bay of the façade holds a single-leaf wood door with a single-light transom. The dwelling is fenestrated by 6/1, double-hung, wood-sash windows with concrete sills. The eastern bay of the first story is paired while the second story has a triple window opening. A one-story, full-width porch shelters the first story of the façade. The porch is set on a brick pier foundation with lattice infill. The porch has a flat roof with overhanging eaves and is supported by wood posts. The porch is edged with square balusters. The porch was being repaired and rebuilt at the time of the volunteer survey. Poured concrete steps with a metal railing provide access to the porch. The southeast (rear) elevation has a two-story wing which, based on its form and documentation on the 1928 Sanborn Insurance Company map, may have originally been a sleeping porch. This wing has been clad in vinyl siding and is capped by a shed roof with an interior brick chimney. Fenestration consists of paired 1/1, double-hung, vinyl-sash windows.

Site Notes:

February 2009: This rowhouse is located south of Potomac Avenue, S.E. and is set back from the concrete sidewalk approximately twenty feet. The southwest (side) elevation is attached to 1817 Potomac Avenue, S.E. and the northeast (side) elevation is attached to 1821 Potomac Avenue, S.E. The level, grassy front yard has a concrete walkway extending from the primary entry to the sidewalk. Immature potted shrubs line the porch. The rear of the property extends to meet E Street, S.E. and includes a garage. A wooden privacy fence extends along the eastern boundary of the backyard.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Hexagonal Shape	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	6/1 Double	Wood
2 Flr Windows	Rectangular	Dbl-Hung	6/1 Triple	Wood
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G**

File: **St\Database\Pictures\Square 1114SE\
1819PotomacAvenueSE, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G**

File: **St\Database\Pictures\Square 1114SE\
1819PotomacAvenueSErear, looking
northwest.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/28/1926	5555	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114SE-0026

BASICS DATA

ID Number: **1114SE-0026** Year Built: **1926** Data Source: **Permit**

Number Extended Street Quad Type of Address

1821 Potomac Avenue SE Current

Name(s) Type of Name

Rowhouse, 1821 Potomac Avenue, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114SE/00 Square/Lot Current
26

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1926 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1926 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 13)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1926, this two-story, two-bay rowhouse is one of thirteen similar residences designed by architect George T. Santmyers. These buildings were constructed by owner/builder T.A. Jameson from the same permit (#5555) and reflect the stylistic influences of the Colonial Revival as well as the Craftsman style, both of which were popular in the second quarter of the twentieth-century. This dwelling is set on a solid concrete foundation and constructed of brick. The façade (northwest elevation) has five-course, American-bond brick coursing. The materials of the flat roof were not visible from the public right-of-way due to a false mansard roof. Extending between stepped brick firewalls, the roof is covered with hexagonal shingles and includes overhanging eaves with exposed ends and a dormer. Clad in shingles, the shed-roof dormer has narrow exposed rafter ends and has paired, single-light windows. The western bay of the façade holds a single-leaf metal door with oval light. The dwelling is fenestrated by 1/1, double-hung, vinyl-sash windows with concrete sills. The eastern bay of the first story is paired while the second story has a triple window opening. A one-story, full-width porch shelters the first story of the façade. The porch is set on a brick pier foundation with lattice infill. The porch has a flat roof with overhanging eaves and molded cornice and is supported by tapered wood columns with square balusters. Poured concrete steps with a metal railing provide access to the porch. The southeast (rear) elevation has a two-story wing which, based on its form and documentation on the 1928 Sanborn Insurance Company map, may have originally been a sleeping porch. The rear elevation was not photographed by the volunteer surveyor.

Site Notes:

February 2009: This rowhouse is located south of Potomac Avenue, S.E. and is set back from the concrete sidewalk approximately twenty feet. The southwest (side) elevation is attached to 1819 Potomac Avenue, S.E. and the northeast (side) elevation is attached to 1823 Potomac Avenue, S.E. The level, grassy front yard has a concrete walkway extending from the primary entry to the sidewalk. The rear of the property is enclosed with a wooden privacy fence and includes a concrete driveway with access from 19th Street, S.E.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard	Slate		Hexagonal Shape	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1 Triple	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\SE Phase I - D to G

File: **StDatabase\Pictures\Square 1114SE**

1821PotomacAvenueSE, looking south.jpg

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

12/28/1926	5555	Build	
-------------------	-------------	--------------	--

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114SE-0027

BASICS DATA

ID Number: **1114SE-0027** Year Built: **1926** Data Source: **Permit**

Number Extended Street Quad Type of Address

1823 Potomac Avenue SE Current

Name(s) Type of Name

Rowhouse, 1823 Potomac Avenue, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114SE/00 Square/Lot Current
27

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1926 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Addition (Rear) c. 2005 Observation

Orig Construction 1926 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**
Streetscape: **Intact**
Relate to Othr Bldgs: **Row (1 of 13)**
Relate to Street: **Face on Setback Line**
Massing: **Block**
Footprint: **Rectangular**

Cross Reference Notes:

Number Stories: **2**

Bays Wide: **2**

Height:

Outbuilding Type

Contributing Status

Width: **17**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Outbuilding Notes:

Lot SqFt:

Acreage:

Has Driveway: ☐

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1926, this two-story, two-bay rowhouse is one of thirteen similar residences designed by architect George T. Santmyers. These buildings were constructed by owner/builder T.A. Jameson from the same permit (#5555) and reflect the stylistic influences of the Colonial Revival as well as the Craftsman style, both of which were popular in the second quarter of the twentieth-century. This dwelling is set on a solid concrete foundation and constructed of brick. The façade (northwest elevation) has five-course, American-bond brick coursing. The materials of the flat roof were not visible from the public right-of-way due to a false mansard roof. Extending between stepped brick firewalls, the roof is covered with asphalt shingles and includes overhanging eaves with exposed ends and a dormer. Clad in shingles, the shed-roof dormer has narrow exposed rafter ends and has paired, ten-light, wood-sash windows. The western bay of the façade holds a single-leaf door. The dwelling is fenestrated by 1/1, double-hung, vinyl-sash windows with concrete sills. The eastern bay of the first story is paired while the second story has a triple window with a metal awning. A one-story, full-width porch shelters the first story of the façade. The porch is set on a brick pier foundation with lattice infill. The porch has a flat roof with overhanging eaves and molded cornice and is supported by tapered wood posts. The porch is edged with square balusters. Poured concrete steps with a metal railing provide access to the porch. A metal awning has been attached to the front of the porch. The southeast (rear) elevation has a two-story wing which, based on its form and documentation on the 1928 Sanborn Insurance Company map, may have originally been a sleeping porch. Fenestration consists of paired, 1/1, double-hung, vinyl-sash windows on the second story.

A one-story, full-width addition has been constructed on the rear of the dwelling. Based on its form and materials, this addition dates to c. 2000. Clad in vinyl siding and capped by a shed roof, this addition is fenestrated with a single-leaf, metal door with lights and 1/1, double-hung, vinyl-sash windows. All of the southeast (rear) elevation openings have metal awnings.

Site Notes:

February 2009: This rowhouse is located south of Potomac Avenue, S.E. and is set back from the concrete sidewalk approximately twenty feet. The southwest (side) elevation is attached to 1821 Potomac Avenue, S.E. and the northeast (side) elevation is attached to 1825 Potomac Avenue, S.E. The level, grassy front yard has a concrete walkway extending from the primary entry to the sidewalk. The rear of the property is enclosed with a wooden privacy fence and includes a concrete driveway with access from 19th Street, S.E.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Asphalt		Shingled	
Wall Component	Material	Color	Treatment	Source

Facade	Brick	American Bond
Structure Component	Material	Feature
Foundation	Concrete	
Walls	Brick	

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1 Triple	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown

Notable Interior Plan(s) _____ Notable Interior Feature(s) _____

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill	Historic District(s)
Subdivision:	
Ward/ANC:	
Zoning:	Designation Event(s)
Contributing:	
Survey(s)	Level(s) of Investigation
Capitol Hill Southeast Phase I (2009/2010)	Permit Research
	Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114SE**
 File: **1823PotomacAvenueSE, looking south.jpg**
 Date:: Photog:
 Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/28/1926	5555	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114SE-0028

BASICS DATA

ID Number: **1114SE-0028** Year Built: **1926** Data Source: **Permit**

Number Extended Street Quad Type of Address

1825 Potomac Avenue SE Current

Name(s) Type of Name

Rowhouse, 1825 Potomac Avenue, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114SE/00 Square/Lot Current
28

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1926 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1926 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row Corner (1 of 13)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **17**

Depth/Length: **31**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1926, this two-story, two-bay rowhouse is one of thirteen similar residences designed by architect George T. Santmyers. These buildings were constructed by owner/builder T.A. Jameson from the same permit (#5555) and reflect the stylistic influences of the Colonial Revival as well as the Craftsman style, both of which were popular in the second quarter of the twentieth-century. This end-unit is set on a solid concrete foundation and constructed of brick. The façade (northwest elevation) has five-course, American-bond brick coursing. The materials of the flat roof were not visible from the public right-of-way due to a false mansard roof extending along the façade (northwest elevation) and northeast (side) elevation. The roof is covered with hexagonal slate shingles and includes wide overhanging eaves, a boxed cornice with scrolled brackets, and two dormers. Clad in shingles, the shed-roof dormers have narrow rafter ends and ten-light, wood-sash windows. The western bay of the façade holds a single-leaf wood door and single-light transom. The dwelling is fenestrated by 1/1, double-hung, vinyl-sash windows with concrete sills. The eastern bay of the first story is paired while the second story has a triple window opening. A one-story, full-width porch shelters the first story of the façade. The porch is set on a brick pier foundation with decorative concrete block infill. The porch has a flat roof with overhanging eaves, modillions, and a molded cornice. The roof is supported by metal filigree posts set on brick piers with metal balusters. Poured concrete steps with a metal railing provide access to the porch. The northeast (side) elevation features a two-story projecting bay. The bay has the same materials as the main block, including the false mansard roof. Fenestration of the side elevation consists of two-light, vinyl-sash basement windows (single and paired), 1/1, double-hung, vinyl-sash windows (single and paired), and a single-light, vinyl-sash awning window. The southeast (rear) elevation has a two-story wing which, based on its form and documentation on the 1928 Sanborn Insurance Company map, may have originally been a sleeping porch. This wing has been clad in vinyl siding and is capped by a shed roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows and two-light, vinyl-sash sliding windows. A single-leaf wood door with a transom is located on the rear of the wing. This first-story opening is accessed via a wooden deck set on wood piers.

Site Notes:

February 2009: This end-unit rowhouse is located on a large triangular-shaped lot southwest of the intersection of Potomac Avenue, S.E. and 19th Street, S.E. The dwelling has a setback of approximately twenty feet from the concrete sidewalk. Flanked by a brick retaining wall, the sidewalk also extends down 19th Street, S.E. The level, grassy lot is marked by mature trees and shrubs. A concrete walkway extends from the primary entry to the Potomac Avenue, S.E. sidewalk. The property is enclosed by chain-link fence. A concrete driveway in the backyard provides access to 19th Street, S.E.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Mansard (False)	Slate		Hexagonal Shape	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1 Triple	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G**

File: **St\Database\Pictures\Square 1114SE\
1825PotomacAvenueSE, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G**

File: **St\Database\Pictures\Square 1114SE\
1825PotomacAvenueSE, looking
southwest.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
12/28/1926	5555	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0058

BASICS DATA

ID Number: **1114-0058** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1801 D Street SE Current

Name(s) Type of Name

Rowhouse, 1801 D Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0058 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1925 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1925 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

This rowhouse is one of eleven dwellings constructed from the same permit, nine of which are rowhouses.

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 9)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type Contributing Status

Garage Non-Contributing

Outbuilding Notes:

February 2009: This one-story garage is located next to the dwelling. Based on its materials, this rudimentary building was constructed c. 1990. The garage is clad in plywood and has a flat roof. Additional details were not provided by the volunteer surveyor.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Restrained)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay dwelling is one of eleven similar buildings designed by architect George T. Santmyers. All on the same permit (#11145), this building combines elements of the Classical Revival and Colonial Revival styles. This end-unit brick residence is set on a solid concrete foundation. Both the foundation and structure have five-course, American-bond brick coursing. A soldier-brick stringcourse extends above the first- and second-story openings, serving as a continuous lintel. The roof was not visible from the public right-of-way due to a brick parapet wall. The parapet has an ogee-molded cornice and extends across the façade (north elevation) from a brick firewall to the west (side) elevation. Concrete panels with garland and a molded architrave embellish the parapet wall. The façade (north elevation) holds a single-leaf, paneled wood door with a single-light transom in the eastern bay. The western bay holds replacement tripled one-light vinyl-sash casement windows. A one-story, full-width porch shelters the first-story openings. The porch is set on a brick pier foundation with decorative concrete-block infill. Tuscan columns support the flat porch roof. The roof has overhanging eaves and an ogee-molded cornice. The porch is edged with a narrow square-post balustrade. Wood stairs provide access to the north side of the porch, via D Street, S.E. A metal awning has been attached to the west (side) elevation of the porch. The second-story openings hold 1/1, double-hung, vinyl-sash windows with concrete lug sills. The west (side) elevation has a two-story projecting bay. The west (side) elevation of the dwelling was not surveyed by the volunteer surveyor. However, based on Google street view imagery, the elevation has a collection of six-light awning windows. The south (rear) elevation has a two-story, full-width wing. Based on its form and its documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch that has since been enclosed with vinyl siding. Based on the presence of a driveway leading to the west (side) elevation, a garage was likely integrated into the lower level of the building. The vehicular opening has been infilled, clad with vinyl siding, and is now pierced with a single-leaf paneled metal door. The first story has a tripartite window opening of vinyl sash. The second story has 1/1, double-hung, vinyl-sash windows. Additional details were not provided by the volunteer surveyor.

Site Notes:

February 2009: This dwelling is located on a corner lot southeast of the intersection of D Street, S.E. and 18th Street, S.E. The dwelling has a typical setback for Square 1114. The east (side) elevation is attached to 1803 D Street, S.E. The raised front yard with immature trees and shrubs has a stone retaining wall. A concrete walkway extends from the dwelling to the concrete sidewalk. A concrete driveway cutout is located along 18th Street, S.E. The sidewalk flanks the property along D and 18th Streets. The rear of the property is enclosed by a chain-link fence and includes a garage. A paved alley is located south of the property.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1801DSTSE, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1801DSTSE, looking east.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1801DSTSErear, looking east.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

Saturday, July 20, 2013

DC HPO Survey - SouthEast Phase 1

ID_Number: 1114-0058 Page 3

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
6/25/1925	11145	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0059

BASICS DATA

ID Number: **1114-0059** Year Built: **1925** Data Source:

Number Extended Street Quad Type of Address

1803 D Street SE

Name(s) Type of Name

Rowhouse, 1803 D Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0059 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1925 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1925 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 9)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 11 similar dwellings designed by architect George T. Santmyers from the same permit (#11145). This dwelling combines elements of the Colonial Revival and Craftsman styles, both of which were popular in the second quarter of the twentieth century. The dwelling is set on a solid concrete foundation and is constructed of brick. The façade (north elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way due to a pent roof. Set between brick firewalls, the pent roof has hexagonal slate shingles and a pronounced overhanging eave with narrow exposed rafter ends. The eastern bay of the first story holds a single-leaf, paneled wood door with a single-light transom. All of the window openings on the façade (north elevation) hold 1/1, double-hung, vinyl-sash windows and have concrete sills. The first story window opening is paired. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation with decorative concrete-block infill, this porch has a concrete deck. The flat roof of the porch has overhanging eaves, modillions, and a molded cornice. The south (rear) elevation has a two-story, full-width wing. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. The volunteer surveyor did not survey or photograph the rear elevation. However, based on photographs from another property, this appendage has been clad in vinyl siding and fenestrated with 1/1, double-hung, vinyl-sash windows. An interior-side brick chimney pierces the roof.

Site Notes:

February 2009: This single-family rowhouse is located on the south side of D Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1801 and 1805 D Street, S.E. A poured concrete walkway leads from the primary entrance of the dwelling and terminates at the sidewalk. The raised front yard with immature shrubs has a stone retaining wall along the sidewalk. The rear of the property extends south to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114\
File: 1803DSTSE, looking south.jpg

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
6/5/1925	11145	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0060

BASICS DATA

ID Number: **1114-0060** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1805 D Street SE Current

Name(s) Type of Name

Rowhouse, 1805 D Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0060 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1925 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1925 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 9)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 11 similar dwellings designed by architect George T. Santmyers from the same permit (#11145). This dwelling combines elements of the Colonial Revival and Craftsman styles, both of which were popular in the second quarter of the twentieth century. The dwelling is set on a solid concrete foundation and is constructed of brick. The façade (north elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way due to a pent roof. Set between brick firewalls, the pent roof has hexagonal slate shingles and a pronounced overhanging eave with narrow exposed rafter ends. The eastern bay of the first story holds a single-leaf, paneled metal door with oval light and a single-light transom. All of the window openings on the façade (north elevation) hold 1/1, double-hung, vinyl-sash windows and have concrete sills. The first story window opening is paired. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation, this porch has a concrete deck. Metal filigree posts with metal balusters support the flat roof, which includes overhanging eaves, modillions, and a molded cornice. The south (rear) elevation has a two-story, full-width wing. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. The volunteer surveyor did not survey or photograph the rear elevation. However, based on photographs from another property, this appendage has been clad in vinyl siding and fenestrated with 1/1, double-hung, vinyl-sash windows. An interior-side brick chimney pierces the roof.

Site Notes:

February 2009: This single-family rowhouse is located on the south side of D Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1803 and 1807 D Street, S.E. A poured concrete walkway leads from the primary entrance of the dwelling and terminates at the sidewalk. The raised front yard has a stone retaining wall along the sidewalk. The rear of the property extends south to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1805DSTSE, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
6/5/1925	11145	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0061

BASICS DATA

ID Number: **1114-0061** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1807 **D Street** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1807 D Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0061 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 9)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 11 similar dwellings designed by architect George T. Santmyers from the same permit (#11145). This dwelling combines elements of the Colonial Revival and Craftsman styles, both of which were popular in the second quarter of the twentieth century. The dwelling is set on a solid concrete foundation and is constructed of brick. The façade (north elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way due to a pent roof. Set between brick firewalls, the pent roof has hexagonal slate shingles and a pronounced overhanging eave with narrow exposed rafter ends. The eastern bay of the first story holds a single-leaf, paneled wood door and a single-light transom. All of the window openings on the façade (north elevation) hold 1/1, double-hung, vinyl-sash windows and have concrete sills. The first story window opening is paired. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation with brick infill, the flat roof of the porch is supported by brick pillars set on brick posts. The roof includes overhanging eaves, modillions, and a molded cornice. Metal balusters complete the porch. The south (rear) elevation has a two-story, full-width wing. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. The volunteer surveyor did not survey or photograph the rear elevation. However, based on photographs from another property, this appendage has been clad in vinyl siding and fenestrated with 1/1, double-hung, vinyl-sash windows. An interior-side brick chimney pierces the roof.

Site Notes:

February 2009: This single-family rowhouse is located on the south side of D Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1805 and 1809 D Street, S.E. A poured concrete walkway leads from the primary entrance of the dwelling to a stone patio and terminates at the sidewalk. The raised front yard has mature shrubs and a stone retaining wall along the sidewalk. The rear of the property extends south to a paved alley.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1807DSTSE, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

6/25/1925	11145	Build	
------------------	--------------	--------------	--

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0062

BASICS DATA

ID Number: **1114-0062** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1809 **D Street** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1809 D Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0062 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 9)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Restrained)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay dwelling is one of eleven similar buildings designed by architect George T. Santmyers. All on the same permit (#11145), this building combines elements of the Classical Revival and Colonial Revival styles. The dwelling is set on a solid concrete foundation and is constructed of brick. The façade (north elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way due to a brick parapet wall. The parapet, set between brick firewalls, has two parged panels with garland and a molded architrave. The eastern bay of the first story holds a single-leaf, paneled wood door with lights and a single-light transom. All of the window openings on the façade (north elevation) hold 1/1, double-hung, vinyl-sash windows and have concrete sills. The first story window opening is paired. A one-story, full-width porch shelters the first-story openings. The porch is set on a brick pier foundation with decorative concrete-block infill. The flat roof has overhanging eaves and is supported by brick pillars with metal balusters. The south (rear) elevation has a two-story, full-width wing. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. The volunteer surveyor did not survey or photograph the rear elevation. However, based on photographs from another property, this appendage has been clad in vinyl siding and fenestrated with 1/1, double-hung, vinyl-sash windows. An interior-side brick chimney pierces the roof.

Site Notes:

February 2009: This single-family rowhouse is located on the south side of D Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1805 and 1809 D Street, S.E. A brick walkway leads from the primary entrance of the dwelling to the concrete sidewalk. The raised front yard has been landscaped with mature shrubs and a stone retaining wall. The rear of the property extends south to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**
File: **1809DSTSE, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
6/25/1925	11145	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0063

BASICS DATA

ID Number: **1114-0063** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1811 D Street SE Current

Name(s) Type of Name

Rowhouse, 1811 D Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0063 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1925 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1925 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 9)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 11 similar dwellings designed by architect George T. Santmyers from the same permit (#11145). This dwelling combines elements of the Colonial Revival and Craftsman styles, both of which were popular in the second quarter of the twentieth century. The residence has a rectangular form. The dwelling is set on a solid concrete foundation and is constructed of brick. The façade (north elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way due to a pent roof. Set between brick firewalls, the pent roof has hexagonal slate shingles and a pronounced overhanging eave with narrow exposed rafter ends. The eastern bay of the first story holds a single-leaf, paneled metal door with two lights and a single-light transom. All of the window openings on the façade (north elevation) hold 1/1, double-hung, vinyl-sash windows and have concrete sills. The first story window opening is paired. A one-story, full-width porch shelters the first-story openings. The porch is set on a brick pier foundation with lattice infill. The flat roof has overhanging eaves, modillions, and a molded cornice. Brick pillars provide support to the roof while complimented by metal balusters. The south (rear) elevation has a two-story, full-width wing. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. The volunteer surveyor did not survey or photograph the rear elevation. However, based on photographs from another property, this appendage has been clad in vinyl siding and fenestrated with 1/1, double-hung, vinyl-sash windows. An interior-side brick chimney pierces the roof.

Site Notes:

February 2009: This single-family rowhouse is located on the south side of D Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1809 and 1813 D Street, S.E. A brick walkway leads from the primary entrance of the dwelling to the concrete sidewalk. The raised front yard has a mature shrub and tree. A stone retaining wall extends along the sidewalk. The backyard, enclosed by a chain-link fence, includes a concrete parking area. The rear of the property extends south to a paved alley.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1811DSTSE, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

6/5/1925	11145	Build	
-----------------	--------------	--------------	--

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0064

BASICS DATA

ID Number: **1114-0064** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1813 **D Street** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1813 D Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0064 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 9)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type Contributing Status

Garage **Contributing**

Outbuilding Notes:

February 2009: This one-story garage faces the paved rear alley. Based on its form and documentation on the 1928 Sanborn Insurance Company map, a c. 1925 date of construction can be assigned. Set on a concrete slab, this building has been clad in vinyl siding. A front-gabled roof of

corrugated metal caps the garage. The roof has overhanging eaves. The façade (south elevation), based on a photograph, includes a single-leaf wood door and a double-leaf wood door.

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 11 similar dwellings designed by architect George T. Santmyers from the same permit (#11145). This dwelling combines elements of the Colonial Revival and Craftsman styles, both of which were popular in the second quarter of the twentieth century. The residence has a rectangular form. The dwelling is set on a solid concrete foundation and is constructed of brick. The façade (north elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way due to a pent roof. Set between brick firewalls, the pent roof has hexagonal slate shingles and a pronounced overhanging eave with narrow exposed rafter ends. The eastern bay of the first story holds a single-leaf, paneled metal door with lights and a single-light transom. All of the window openings on the façade (north elevation) hold 1/1, double-hung, vinyl-sash windows and have concrete sills. The first story window opening is paired. A one-story, full-width porch shelters the first-story openings. The porch is set on a brick pier foundation with lattice infill. The flat roof has overhanging eaves and a narrow molded cornice. Brick pillars provide support to the roof while complimented by metal balusters. The deck of the porch has been covered with carpet. The south (rear) elevation has a two-story, full-width wing. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. The volunteer surveyor did not survey or photograph the rear elevation. However, based on photographs from another property, this appendage has been clad in vinyl siding and fenestrated with 1/1, double-hung, vinyl-sash windows. An interior-side brick chimney pierces the roof.

Site Notes:

February 2009: This single-family rowhouse is located on the south side of D Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1811 and 1815 D Street, S.E. A poured concrete walkway leads from the primary entrance of the dwelling to the concrete sidewalk. The raised front yard has been landscaped with planting beds and immature shrubs and plants. A stone retaining wall extends along the sidewalk. The rear of the property extends south to a paved alley. A garage faces the alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1813DSTSE, looking south.jpg**

Date::

Photog:

Code::

R:

Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1813DSTSE rear, looking northwest.jpg**

Date::

Photog:

Code::

R:

Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

6/5/1925	11145	Build	
-----------------	--------------	--------------	--

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0065

BASICS DATA

ID Number: **1114-0065** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1815 D Street SE

Name(s) Type of Name

Rowhouse, 1815 D Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0065 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1925 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1925 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row Corner (1 of 9)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type Contributing Status

Garage Contributing

Outbuilding Notes:

February 2009: This one-story, one-bay garage faces the rear alley. Based on its form and documentation on the 1928 Sanborn Insurance Company map, a c. 1925 date of construction can be assigned. The garage is clad in (what appears to be) wood siding and capped by a front-gabled roof

of corrugated metal. The façade (south elevation) includes a double-leaf metal door with a small pent in the upper gable end. The east (side) elevation includes a single-leaf wood door set in a square-edge wood surround.

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 11 similar dwellings designed by architect George T. Santmyers from the same permit (#11145). This dwelling combines elements of the Colonial Revival and Craftsman styles, both of which were popular in the second quarter of the twentieth century. The residence has a rectangular form. The dwelling is set on a solid concrete foundation and is constructed of brick. The façade (north elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way due to a pent roof. Set between brick firewalls, the pent roof has hexagonal slate shingles and a pronounced overhanging eave with narrow exposed rafter ends. The eastern bay of the first story holds a single-leaf, paneled wood door with twelve lights and a single-light transom. All of the window openings on the façade (north elevation) hold 1/1, double-hung, vinyl-sash windows with false 6/1 muntins. The window openings have concrete sills. The first story window opening is paired. A one-story, full-width porch shelters the first-story openings. The porch is set on a brick pier foundation with lattice infill. The flat roof has overhanging eaves, modillions, and a molded cornice. Brick pillars support the roof and are complimented by metal balusters. The south (rear) elevation has a two-story, full-width wing. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. This wing has been clad in vinyl siding and fenestrated with paired, 1/1, double-hung, vinyl-sash windows. A metal awning shelters a metal porch and stair providing access to a first-story door opening (not surveyed). An interior-side brick chimney pierces the roof.

Site Notes:

February 2009: This single-family rowhouse is located on the south side of D Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The dwelling is adjacent to 1813 and 1817 D Street, S.E. A brick walkway leads from the primary entrance of the dwelling to the concrete sidewalk. The raised front yard has a mature shrub and tree. A stone retaining wall extends along the sidewalk. The rear of the property is enclosed by a chain-link fence and extends south to a paved alley. A garage faces the alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	6/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	6/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1815DSTSE, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1815DSTSErear, looking northwest.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
6/5/1925	11145	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0066

BASICS DATA

ID Number: **1114-0066** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1817 **D Street** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1817 D Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0066 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 9)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Restrained)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of eleven similar buildings designed by architect George T. Santmyers. All on the same permit (#11145), this building combines elements of the Classical Revival and Colonial Revival styles. This building has a rectangular form and is set on a solid concrete foundation and is constructed of brick. The façade (north elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings on the façade (north elevation) and east (side) elevation, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way due to a brick parapet wall. The parapet wall features concrete panels with garland and a molded architrave. The western bay of the first story holds a single-leaf door and a single-light transom. All of the window openings on the façade (north elevation) hold 1/1, double-hung, vinyl-sash windows. All of the window openings have concrete sills. The first story window opening is paired. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation, this porch has a flat roof with overhanging eaves, modillions, and a molded cornice. Metal filigree posts support the roof. Metal balusters complete the porch. Additional fenestration of the façade includes a two-light, vinyl-sash sliding basement window. The east (side) elevation is fenestrated with two-light, vinyl-sash windows with concrete sills. The basement contains two window openings; the first-story has four, and the second story two. The south (rear) elevation has a two-story wing. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. This wing has been clad in vinyl siding and fenestrated with paired, 1/1, double-hung, vinyl-sash windows. A brick chimney extends from the east (side) elevation.

Site Notes:

February 2009: This single-family rowhouse is located on the south side of D Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The west (side) elevation is attached to 1815 D Street, S.E. A concrete walkway leads from the primary entrance of the dwelling to the concrete sidewalk. The raised front yard extends to the east of the dwelling, forming a large slopes side and backyard. A chain-link fence encloses the yard. A stone retaining wall extends along the sidewalk. The rear of the property extends south to a paved alley.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**
File: **1817DSTSE, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**
File: **1817DSTSE, looking southwest.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
6/5/1925	11145	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0069

BASICS DATA

ID Number: **1114-0069** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1819 D Street SE

Name(s) Type of Name

Twin Dwelling, 1819 D Street, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0069 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Multifamily/Misc) 1925 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1925 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached Twin (1 of 2)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Restrained)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay twin dwelling is one of eleven similar buildings designed by architect George T. Santmyers. All on the same permit (#11145), this building combines elements of the Classical Revival and Colonial Revival styles. The dwelling is set on a solid concrete foundation and is constructed of brick. The façade (north elevation) and west (side) elevation are faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way due to a brick parapet wall. The parapet wall features concrete panels with garland and a molded architrave. The eastern bay of the first story holds a single-leaf, paneled wood door and a single-light transom. The building's house number has been etched into the transom window. All of the window openings hold vinyl sash and have concrete sills. The western bay of the first story holds paired, single-light windows. The two second-story openings are evenly spaced and hold 1/1, double-hung windows. A one-story, full-width porch shelters the first-story openings. The porch is set on a brick pier foundation with decorative concrete block infill. The flat roof of the porch has overhanging eaves, modillions, and a molded cornice. Brick columns support the roof and are complimented by metal balusters. The west (side) elevation is pierced by two, paired, one-light, vinyl-sash sliding basement windows. The first story holds four, six-light, wood-sash awning windows. Paired, one-light, vinyl-sash sliding windows pierce the second story. The south (rear) elevation has a two-story wing. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. Set on a brick foundation, this wing has been clad in vinyl siding and fenestrated with paired, 1/1, double-hung, vinyl-sash windows. Additional details were not provided by the volunteer surveyor.

Site Notes:

February 2009: This single-family twin dwelling is located south of D Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The east (side) elevation is attached to 1821 D Street, S.E. A brick walkway leads from the primary entry to the sidewalk. The raised grassy yard slopes gently to the south as it extends west of the dwelling. The large lot is enclosed by a chain-link fence and features mature shrubs and trees and a stone retaining wall along the D Street, S.E. sidewalk. The rear of the property extends to the south and ends at a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Roman Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114\
File: 1819DSTSE, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114\
File: 1819DSTSE, looking southeast.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
6/5/1925	11145	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0070

BASICS DATA

ID Number: **1114-0070** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1821 **D Street** **SE** **Current**

Name(s) Type of Name

Twin Dwelling, 1821 D Street, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0070 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Residential** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Attached Twin (1 of 2)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Restrained)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay twin dwelling is one of eleven similar buildings designed by architect George T. Santmyers. All on the same permit (#11145), this building combines elements of the Classical Revival and Colonial Revival styles. This twin dwelling has a rectangular form and is set on a solid concrete foundation and is constructed of brick. The façade (north elevation) and east (side) elevation are faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way due to a brick parapet wall. The parapet wall features concrete panels with garland and a molded architrave. The western bay of the first story holds a single-leaf, paneled wood door and a single-light transom. All of the window openings hold vinyl sash and have concrete sills. The eastern bay of the first story holds a tripartite window of single-light sash. The two second-story openings are evenly spaced and hold 1/1, double-hung windows. A one-story, full-width porch shelters the first-story openings. The porch is set on a brick pier foundation with decorative concrete block infill. The flat roof of the porch has overhanging eaves, modillions, and a molded cornice. Brick columns support the roof and are complimented by metal balusters. The east (side) elevation has a single-leaf wood door providing access to the lower level. The first story holds two paired, one-light, vinyl-sash sliding windows. The second story contains two of the paired, one-light, vinyl-sash sliding windows. A one-story, one-bay garage is attached to the lower level of the east elevation. Based on its form and materials, as well as its documentation on the 1928 Sanborn Insurance Company map, the garage is an original feature. The garage is clad in brick and capped by a roof (materials and form not visible) with overhanging eaves. Fenestration consists of paired, one-light, vinyl-sash sliding windows set in segmental openings. The openings have rowlock brick sills and two-course, rowlock brick segmental arches. The south (rear) elevation has a two-story wing. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. This wing has been clad in vinyl siding and fenestrated with paired, 1/1, double-hung, vinyl-sash windows. The second story extends south beyond the first story. Additional details were not provided by the volunteer surveyor.

Site Notes:

February 2009: This single-family twin dwelling is located south of D Street, S.E. and is set back approximately twenty feet from the concrete sidewalk. The west (side) elevation is attached to 1819 D Street, S.E. A brick walkway leads from the primary entry to the sidewalk. This large, triangular-shaped raised yard has a stone retaining wall along D Street, S.E. and includes mature trees and shrubs. A paved alley extends to the southeast of the property and provides access to D Street, S.E. east of the property. A concrete parking area is located off of the alley.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1821DSTSE, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1821DSTSE, looking southwest.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

6/5/1925	11145	Build	
-----------------	--------------	--------------	--

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0057

BASICS DATA

ID Number: **1114-0057** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1800 Potomac Avenue SE Current

Name(s) Type of Name

Rowhouse, 1800 Potomac Avenue, S.E. Common

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0057 Square/Lot Current

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) 1925 Permit Historic/Current

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction 1925 Permit 5000 Permit

Construction Event Association Associated Name

Orig Construction Architect Santmyers, George T.

Orig Construction Builder Jameson, Thomas A.

Orig Construction Owner Jameson, Thomas A.

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Restrained)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building is a restrained interpretation of the Classical Revival and Colonial Revival styles. Eleven dwellings designed by Santmyers (#11145) were constructed by Jameson just prior to these dwellings on the same square. Those buildings had the same style, form, materials, and dimensions as this row of 26 residences. The dwelling is set on a solid concrete foundation and is constructed of brick. The façade (southeast elevation) and southwest (side) elevation are faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the basement level and first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way due to a brick parapet wall. The parapet wall features concrete panels with garland and a molded architrave. The eastern bay of the first story holds a single-leaf door and single-light transom. All of the window openings hold vinyl sash and have concrete sills. The façade is fenestrated with 1/1, double-hung windows with false 6/1 muntins. The first-story window opening is paired. A one-story, full-width porch shelters the first-story openings. The porch is set on a brick pier foundation with lattice infill. The flat roof of the porch has overhanging eaves, modillions, and a molded cornice. Tuscan columns support the roof and are complimented by square wood balusters. The southwest (side) elevation has a single-leaf metal door set providing access to the lower level. Additional lower-level fenestration consists of paired, paired, one-light sliding windows and a single-light window. The first story has paired, 1/1, double-hung, vinyl-sash windows with false 6/1 muntins and two, single-light, awning windows. The second story has paired and single, 1/1, double-hung, vinyl-sash windows with false 6/1 muntins. The northwest (rear) elevation has a two-story wing. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. Only the southwest (side) elevation was surveyed by the volunteer surveyor. The lower level has a roll-up garage door. The first and second stories have been clad in German vinyl siding. Fenestration consists of triple, 1/1, double-hung, vinyl-sash windows with false 6/1 muntins.

Site Notes:

February 2009: This end-unit rowhouse is located on a large, triangular-shaped corner lot northeast of the intersection of Potomac Avenue, S.E. and 18th Street, S.E. The dwelling has a setback of approximately twenty feet from Potomac Avenue, S.E. The northeast (side) elevation of the dwelling is attached to 1801 Potomac Avenue, S.E. Concrete sidewalks extend aside Potomac Avenue, S.E. and 18th Street, S.E. The raised yard features a stone retaining wall, mature trees and shrubs, as well as a chain-link fence enclosing the property. A poured concrete walkway extends from the primary entry to the Potomac Avenue, S.E. sidewalk. A driveway extends off of 18th Street, S.E. to the rear of the dwelling.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	6/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	6/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

--

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1800PotomacAvenueSE, looking north.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1800PotomacAvenueSE, looking east.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0056

BASICS DATA

ID Number: **1114-0056** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1802 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1802 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0056 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building reflects stylistic elements of both the Colonial Revival and Craftsman styles which were popular in the second-quarter of the twentieth century. Eleven buildings constructed by Jameson on the south side of the 1800 block of D Street, S.E. were also constructed under one permit (#11145) and are similar in design, materials, form, and dimensions. This rowhouse is set on a solid concrete foundation and is constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way. However, a pent roof highlights the façade. Stretching between brick firewalls, the pent roof has boxed eaves. The western bay of the first story holds a single-leaf wood door with lights. The eastern bay has a large, single-light window. Second-story fenestration consists of two, 1/1, double-hung, vinyl-sash windows with metal awnings. A one-story, full-width porch shelters the first-story openings. The porch's brick foundation has been altered with the installation of a single-leaf metal door on the façade. The flat roof of the porch has overhanging eaves and a molded cornice. Brick pillars set on brick posts with metal balusters support the roof. A metal awning has been installed along the front of the porch. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. Google street view imagery documents that this wing has been clad in vinyl siding and fenestrated with paired, 1/1, double-hung, vinyl-sash windows. An interior brick chimney pierces the shed roof.

Site Notes:

February 2009: This rowhouse is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1800 Potomac Avenue, S.E. and the northeast (side) elevation to 1804 Potomac Avenue, S.E. The level, grassy front yard has mature shrubs and is enclosed by chain-link fence. A concrete walkway extends from the main entry to the sidewalk. Additionally, the walkway extends to a below-grade door opening beneath the dwelling's front porch. The rear of the property extends northwest to a paved alley and is enclosed by a wooden privacy fence.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Brick			
Walls	Concrete			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Fixed	1	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1114

File: **1802PotomacAvenueSE, looking north.jpg**

Date::

Photog:

Code::

R:

Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

9/30/1925

3033 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Saturday, July 20, 2013

DC HPO Survey - SouthEast Phase 1

ID_Number: 1114-0056 Page 3

Resource All Data Report

ID Number: 1114-0055

BASICS DATA

ID Number: **1114-0055** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1804 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1804 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0055 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type Contributing Status

Garage **Contributing**

Outbuilding Notes:

February 2009: This one-story, two-bay garage fronts the paved alley at the northern end of the property. Based on its form and materials, as well as a garage documented on the 1928 Sanborn Insurance Company map on this spot, a construction date of c. 1925 can be assigned. The building has

been clad in metal siding. Fenestration consists of a single-leaf metal door and a roll-up metal door on the façade (northwest elevation).

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building reflects stylistic elements of both the Colonial Revival and Craftsman styles which were popular in the second-quarter of the twentieth century. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way. However, a pent roof highlights the façade. Stretching between brick firewalls, the pent roof is covered with hexagonal slate shingles and has narrow rafter ends. The western bay of the first story holds a single-leaf door. All of the façade window openings hold 1/1, double-hung, vinyl sash with concrete sills. The eastern bay of the first story is paired. A one-story, full-width porch shelters the first-story openings. The porch's brick pier foundation has been infilled with decorative concrete block. The flat roof of the porch has overhanging eaves, modillions, and a molded cornice. Brick pillars set on brick posts with metal balusters support the roof. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. Google street view imagery documents that this wing has been clad in vinyl siding and fenestrated with 1/1, double-hung, vinyl-sash windows and a single-leaf door with a transom. An interior brick chimney pierces the shed roof.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1802 Potomac Avenue, S.E. and the northeast (side) elevation to 1806 Potomac Avenue, S.E. The level, grassy front yard has mature shrubs and is enclosed by chain-link fencing. A concrete walkway extends from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley and includes a garage.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1114

File: **1804PotomacAvenueSE, looking north.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1114

File: **1804PotomacAvenueSErear, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

9/30/1925	3033	Build	
------------------	-------------	--------------	--

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0054

BASICS DATA

ID Number: **1114-0054** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1806 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1806 Potomac Avenue **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0054 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type Contributing Status

Garage **Contributing**

Outbuilding Notes:

February 2009: This one-story, one-bay garage fronts the alley at the north end of the property. Based on its form and materials, as well as a garage documented on the 1928 Sanborn Insurance Company map on this spot, a construction date of c. 1925 can be assigned. The garage has been parged

and a metal roll-up garage door installed on the façade (northwest elevation). A shed roof caps the garage.

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building reflects stylistic elements of both the Colonial Revival and Craftsman styles which were popular in the second-quarter of the twentieth century. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way. However, a pent roof highlights the façade. Stretching between brick firewalls, the pent roof is covered with hexagonal slate shingles and has narrow rafter ends. The western bay of the first story holds a single-leaf, paneled metal door with fanlight and three-light transom. All of the façade window openings hold 1/1, double-hung, vinyl sash with false 6/6 muntins and concrete sills. The eastern bay of the first story is paired. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation with honeycomb brickwork, the porch has a flat roof with overhanging eaves, modillions, and a molded cornice. Metal filigree posts with twisted metal balusters complete the porch. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. Google street view imagery documents that this wing has been clad in vinyl siding and fenestrated with 1/1, double-hung, vinyl-sash windows. An interior brick chimney pierces the shed roof.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1804 Potomac Avenue, S.E. and the northeast (side) elevation to 1808 Potomac Avenue, S.E. The level, grassy front yard has mature shrubs and is enclosed by chain-link fencing. A concrete walkway extends from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley and includes a garage.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1806PotomacAvenueSE, looking north.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1806PotomacAvenueSErear, looking south.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1806PotomacAvenueSErear, looking
southwest.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit _____

Code	Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0053

BASICS DATA

ID Number: **1114-0053** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1808 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1808 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0053 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building reflects stylistic elements of both the Colonial Revival and Craftsman styles which were popular in the second-quarter of the twentieth century. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) has five-course, American-bond brick coursing. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way. However, a pent roof highlights the façade. Stretching between brick firewalls, the pent roof is covered with hexagonal slate shingles and has narrow rafter ends. The western bay of the first story holds a single-leaf, paneled metal door with fanlight and transom. The eastern bay has a single-light, vinyl-sash fixed picture window with concrete sill. Two 1/1, double-hung, vinyl-sash windows with concrete lug sills pierce the second story. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation with honeycomb brickwork, the porch has a flat roof with overhanging eaves and a molded cornice. Brick columns with metal balusters complete the porch. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. Google street view imagery documents that this wing has been clad in vinyl siding and fenestrated with 1/1, double-hung, vinyl-sash windows. An interior brick chimney pierces the shed roof.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1806 Potomac Avenue, S.E. and the northeast (side) elevation to 1810 Potomac Avenue, S.E. The level, grassy front yard has mature trees and is enclosed by chain-link fencing. A concrete walkway extends from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Fixed	1	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
StDatabase\Pictures\Square 1114**

File: **1808PotomacAvenueSE, looking north.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0052

BASICS DATA

ID Number: **1114-0052** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1810 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1810 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0052 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Garage

Contributing Status

Contributing

Outbuilding Notes:

February 2009: This one-story, one-bay garage fronts the paved alley. Based on its form and materials, as well as a garage documented on the 1928 Sanborn Insurance Company map on this spot, a construction date of c. 1925 can be assigned. The garage is clad in metal sheets and capped by a

shed roof. The façade (northwest elevation) has a large, double-leaf wood door set in a square-edge wood surround.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Restrained)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building is a restrained interpretation of the Classical Revival and Colonial Revival styles. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) has five-course, American-bond brick coursing. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way due to a brick parapet wall. Concrete panels with garland and a molded architrave embellish the parapet wall. The western bay of the first story holds a single-leaf, paneled wood door with lights and a three-light transom. Window fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills. The first-story window opening is paired. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation with decorative concrete-block infill, the porch has a flat roof with overhanging eaves, modillions, and a molded cornice. Metal filigree supports set on brick posts support the roof. Metal balusters complete the porch. The northwest (rear) elevation has a two-story wing. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. The wing has been clad in aluminum siding and is capped by a shed roof. An interior brick chimney pierces the roof. Fenestration consists of 1/1, double-hung, vinyl-sash windows with false 6/1 muntins and a single-leaf door opening on the first story accessed via a metal porch. The porch is sheltered by a metal awning. A single-leaf door opening is located below-grade, beneath the metal porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1808 Potomac Avenue, S.E. and the northeast (side) elevation to 1812 Potomac Avenue, S.E. The level, grassy front yard is enclosed by metal fencing. A concrete walkway extends from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley and includes a garage.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Designation Event(s)

Contributing:

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1114

File: **1810PotomacAvenueSE, looking north.jpg**

Date::

Photog:

Code::

R:

Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1114

File: **1810PotomacAvenueSErear, looking southwest.jpg**

Date::

Photog:

Code::

R:

Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0051

BASICS DATA

ID Number: **1114-0051** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1812 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1812 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0051 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Restrained)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building is a restrained interpretation of the Classical Revival and Colonial Revival styles. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) has five-course, American-bond brick coursing. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way due to a brick parapet wall. Concrete panels with garland and a molded architrave embellish the parapet wall. The western bay of the first story holds a single-leaf door and transom. The eastern bay of the first story holds a single-light picture window with concrete sill. The second-story contains two, 1/1, double-hung, vinyl-sash windows with concrete sills and metal awnings. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation with decorative concrete-block infill, the porch has a flat roof with overhanging eaves, modillions, and a molded cornice. Brick pillars set on brick posts support the roof. A metal awning and metal balusters complete the porch. The northwest (rear) elevation has a two-story wing. The rear of the dwelling was not photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch. The rear includes a wood deck with wood stairs and metal awnings over the second-story window openings. Additional information was not supplied by the volunteer surveyor.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1810 Potomac Avenue, S.E. and the northeast (side) elevation to 1814 Potomac Avenue, S.E. The level, grassy front yard has mature trees and is enclosed by metal fencing. A concrete walkway extends from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
1 Flr Windows	Rectangular	Fixed	1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1812PotomacAvenueSE, looking north.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0050

BASICS DATA

ID Number: **1114-0050** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1814 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1814 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0050 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building reflects stylistic elements of both the Colonial Revival and Craftsman styles which were popular in the second-quarter of the twentieth century. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way. However, a pent roof highlights the façade. Stretching between brick firewalls, the pent roof is covered with hexagonal slate shingles and has narrow rafter ends. The western bay of the first story holds a single-leaf, paneled metal door and a three-light transom. All of the façade window openings hold 1/1, double-hung, vinyl sash and have concrete sills. The eastern bay of the first story is paired. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation with brick infill, the porch has a flat roof with overhanging eaves and a molded cornice. Brick pillars with twisted metal balusters complete the porch. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1812 Potomac Avenue, S.E. and the northeast (side) elevation to 1816 Potomac Avenue, S.E. The level, grassy front yard has mature trees and is enclosed by chain-link fencing. A concrete walkway extends from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1814PotomacAvenueSE, looking north.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0049

BASICS DATA

ID Number: **1114-0049** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1816 **Potomac Avenue** **SE**

Name(s) Type of Name

Rowhouse, 1816 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0049 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building reflects stylistic elements of both the Colonial Revival and Craftsman styles which were popular in the second-quarter of the twentieth century. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way. However, a pent roof highlights the façade. Stretching between brick firewalls, the pent roof is covered with hexagonal slate shingles and has narrow rafter ends. The western bay of the first story holds a single-leaf door and a three-light transom. All of the façade window openings hold 1/1, double-hung, vinyl sash and have concrete sills. The eastern bay of the first story is paired. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation with lattice infill, the porch has a flat roof with overhanging eaves and a molded cornice. The roof is supported by wood posts with square wood balusters. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1814 Potomac Avenue, S.E. and the northeast (side) elevation to 1818 Potomac Avenue, S.E. The level, grassy front yard has mature shrubs and trees and is enclosed by chain-link fencing. A concrete walkway extends from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1816PotomacAvenueSE, looking north.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0048

BASICS DATA

ID Number: **1114-0048** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1818 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1818 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0048 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building reflects stylistic elements of both the Colonial Revival and Craftsman styles which were popular in the second-quarter of the twentieth century. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way. However, a pent roof highlights the façade. Stretching between brick firewalls, the pent roof is covered with hexagonal slate shingles and has narrow rafter ends. The western bay of the first story holds a single-leaf door and a three-light transom. The eastern bay of the first story holds a single-light picture window with a concrete sill. The second story has two, 1/1, double-hung, vinyl-sash windows with concrete sills. A one-story, full-width porch shelters the first-story openings. The brick pier foundation of the porch has been infilled with brick and a single-light awning window. The porch has a flat roof with overhanging eaves, modillions, and a molded cornice and is supported by brick pillars with metal balusters. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1816 Potomac Avenue, S.E. and the northeast (side) elevation to 1820 Potomac Avenue, S.E. The level, grassy front yard is enclosed by chain-link fencing. A concrete walkway extends from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114\

File: 1818PotomacAvenueSE, looking north.jpg

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0047

BASICS DATA

ID Number: **1114-0047** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1820 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1820 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0047 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Restrained)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building is a restrained interpretation of the Classical Revival and Colonial Revival styles. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roof was not visible from the public right-of-way due to a brick parapet wall. Set between brick firewalls, the parapet has two concrete panels with garland and a molded architrave. The western bay of the first story holds a single-leaf, paneled metal door with two lights. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows with concrete sills. The first-story window opening is paired. Metal awnings have been shelter the two, second-story window openings. A one-story, full-width porch shelters the first-story openings. The brick pier foundation of the porch has been infilled with honeycomb brickwork. The porch has a flat roof with overhanging eaves and a molded cornice and is supported by metal filigree posts with metal balusters. A metal awning has been attached to the front of the porch. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this may have originally been a sleeping porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1818 Potomac Avenue, S.E. and the northeast (side) elevation to 1822 Potomac Avenue, S.E. The level, grassy front yard is enclosed by chain-link fencing. A concrete walkway extends from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Wall Component	Material	Color	Treatment	Source
Structure Component	Material	Feature		Source

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114\

File: 1820PotomacAvenueSE, looking north.jpg

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0046

BASICS DATA

ID Number: **1114-0046** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1822 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1822 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0046 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Restrained)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building is a restrained interpretation of the Classical Revival and Colonial Revival styles. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roof was not visible from the public right-of-way due to a brick parapet wall. Set between brick firewalls, the parapet has two concrete panels with garland and a molded architrave. The western bay of the first story holds a single-leaf, paneled wood door with lights and a three-light transom. The façade is fenestrated with 1/1, double-hung, vinyl-sash windows with concrete sills. The first-story window opening is paired. Metal awnings shelter the two, second-story window openings. A one-story, full-width porch shelters the first-story openings. The brick pier foundation of the porch has been infilled with lattice. The porch has a flat roof with overhanging eaves and a molded cornice and is supported by wood posts with square wood balusters. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this may have originally been a sleeping porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1820 Potomac Avenue, S.E. and the northeast (side) elevation to 1824 Potomac Avenue, S.E. The level, grassy front yard is enclosed by chain-link fencing and has mature shrubs. A concrete walkway extends from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114\

File: 1822PotomacAvenueSE, looking north.jpg

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0045

BASICS DATA

ID Number: **1114-0045** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1824 **Potomac Avenue** **SE**

Name(s) Type of Name

Rowhouse, 1824 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0045 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building reflects stylistic elements of both the Colonial Revival and Craftsman styles which were popular in the second-quarter of the twentieth century. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way. However, a pent roof highlights the façade. Stretching between brick firewalls, the pent roof is covered with hexagonal shingles and has narrow rafter ends. The western bay of the first story holds a single-leaf door and a three-light transom. Window fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills. The first-story window opening is paired while the second-story window openings have metal awnings. A one-story, full-width porch shelters the first-story openings. The brick pier foundation of the porch has been infilled with lattice. The porch has a flat roof with overhanging eaves, modillions, and a molded cornice. Tuscan columns and square wood balusters compliment the porch. A metal awning with wood supports has been attached to the front of the porch. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this was probably a sleeping porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1822 Potomac Avenue, S.E. and the northeast (side) elevation to 1826 Potomac Avenue, S.E. The level, grassy front yard has mature shrubs. A walkway extends from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown

Notable Interior Plan(s)	Notable Interior Feature(s)
--------------------------	-----------------------------

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114\

File: 1824PotomacAvenueSE, looking north.jpg

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0043

BASICS DATA

ID Number: **1114-0043** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1828 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1828 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0043 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

The square map notes the presence of an outbuilding on the property. However, this information was not verified by the volunteer surveyor.

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building reflects stylistic elements of both the Colonial Revival and Craftsman styles which were popular in the second-quarter of the twentieth century. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way. However, a pent roof highlights the façade. Stretching between brick firewalls, the pent roof is covered with hexagonal shingles and has narrow rafter ends. The western bay of the first story holds a single-leaf door. Window fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills. The first-story window opening is paired. The second-story window openings are sheltered by metal awnings. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation, the porch has a flat roof with overhanging eaves, modillions, and a molded cornice. Metal filigree posts set on brick piers support the roof. Metal balusters extend between the brick piers. A metal awning has been attached to the front of the porch. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this may have originally been a sleeping porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1826 Potomac Avenue, S.E. and the northeast (side) elevation to 1830 Potomac Avenue, S.E. The level, grassy front yard has mature plantings. A concrete walkway extends from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1828PotomacAvenueSE, looking north.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0042

BASICS DATA

ID Number: **1114-0042** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1830 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1830 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0042 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Restrained)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building is a restrained interpretation of the Classical Revival and Colonial Revival styles. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roof was not visible from the public right-of-way due to a brick parapet wall. Set between brick firewalls, the parapet has two concrete panels with garland and a molded architrave. The western bay of the first story holds a single-leaf door and a three-light transom. Window fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills. The first-story window opening is paired with false 6/6 muntins. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation with lattice infill, the porch has a flat roof with overhanging eaves, modillions, and a molded cornice. Tuscan columns support the roof. Square wood balusters extend between the columns. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this may have originally been a sleeping porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1828 Potomac Avenue, S.E. and the northeast (side) elevation to 1832 Potomac Avenue, S.E. The level, grassy front yard has a concrete walkway extending from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	6/6 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Historic District(s)

Subdivision:

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1114\

File: 1830PotomacAvenueSE, looking north.jpg

Date::

Photog:

Code::

R:

Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

--

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

--

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0041

BASICS DATA

ID Number: **1114-0041** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1832 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1832 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0041 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

The square map notes the presence of an outbuilding. However, this building was neither photographed nor surveyed by the volunteer surveyor.

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Restrained)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building is a restrained interpretation of the Classical Revival and Colonial Revival styles. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roof was not visible from the public right-of-way due to a brick parapet wall. Set between brick firewalls, the parapet has two concrete panels with garland and a molded architrave. The western bay of the first story holds a single-leaf paneled door and a three-light transom. Window fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills. The first-story window opening is paired. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation with decorative concrete-block infill, the porch has a flat roof with overhanging eaves, modillions, and a molded cornice. Metal filigree posts set on brick piers support the roof. Metal balusters extend between the piers. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this may have originally been a sleeping porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1830 Potomac Avenue, S.E. and the northeast (side) elevation to 1834 Potomac Avenue, S.E. The level, grassy front yard has a concrete walkway extending from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: Capitol Hill

Historic District(s)

Subdivision:

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114\

File: 1832PotomacAvenueSE, looking north.jpg

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0040

BASICS DATA

ID Number: **1114-0040** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1834 **Potomac Avenue** **SE**

Name(s) Type of Name

Rowhouse, 1834 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0040 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

The square map notes the presence of an outbuilding. However, this building was neither photographed nor surveyed by the volunteer surveyor.

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building reflects stylistic elements of both the Colonial Revival and Craftsman styles which were popular in the second-quarter of the twentieth century. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way. However, a pent roof highlights the façade. Stretching between brick firewalls, the pent roof is covered with hexagonal shingles and has narrow rafter ends. The western bay of the first story holds a single-leaf French door with three-light transom. Window fenestration consists of 1/1, double-hung, vinyl-sash windows with false 6/1 muntins. The openings have concrete sills. The first-story window opening is paired. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation with lattice infill, the porch has a flat roof with overhanging eaves, modillions, and a molded cornice. Brick posts support the roof. Metal balusters extend between the posts. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this may have originally been a sleeping porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1832 Potomac Avenue, S.E. and the northeast (side) elevation to 1836 Potomac Avenue, S.E. The level, grassy front yard has mature trees. A concrete walkway extends from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	6/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	6/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1834PotomacAvenueSE, looking north.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0039

BASICS DATA

ID Number: **1114-0039** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1836 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1836 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0039 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building reflects stylistic elements of both the Colonial Revival and Craftsman styles which were popular in the second-quarter of the twentieth century. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way. However, a pent roof highlights the façade. Stretching between brick firewalls, the pent roof is covered with hexagonal shingles and has narrow rafter ends. The western bay of the first story holds a single-leaf wood door with twelve lights. A three-light transom is above. Window fenestration consists of 1/1, double-hung, vinyl-sash windows with false 6/1 muntins and concrete sills. The first-story window opening is paired. A one-story, full-width porch shelters the first-story openings. Set on a brick pier foundation with lattice infill, the porch has a flat roof with overhanging eaves, modillions, and a molded cornice. Brick posts support the roof. Metal balusters extend between the posts. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this may have originally been a sleeping porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1834 Potomac Avenue, S.E. and the northeast (side) elevation to 1838 Potomac Avenue, S.E. The level, grassy front yard has immature plantings and shrubs. A concrete walkway extends from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	6/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	6/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114\

File: 1836PotomacAvenueSE, looking north.jpg

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0038

BASICS DATA

ID Number: **1114-0038** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1838 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1838 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0038 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building reflects stylistic elements of both the Colonial Revival and Craftsman styles which were popular in the second-quarter of the twentieth century. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way. However, a pent roof highlights the façade. Stretching between brick firewalls, the pent roof is covered with hexagonal shingles and has narrow rafter ends. The western bay of the first story holds a single-leaf door with a three-light transom. Window fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills. The first-story window opening is paired. A one-story, full-width porch shelters the first-story. Set on a brick pier foundation with lattice infill, the porch has a flat roof with overhanging eaves and modillions. Metal filigree posts set on brick piers support the roof. Metal balusters extend between the pier supports. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this may have originally been a sleeping porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1836 Potomac Avenue, S.E. and the northeast (side) elevation to 1840 Potomac Avenue, S.E. The level, grassy front yard has immature shrubs. A concrete walkway extends from the main entry to the sidewalk. The rear of the property extends northwest to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114\

File: 1838PotomacAvenueSE, looking north.jpg

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0037

BASICS DATA

ID Number: **1114-0037** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1840 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1840 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0037 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Restrained)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building is a restrained interpretation of the Classical Revival and Colonial Revival styles. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roof was not visible from the public right-of-way due to a brick parapet wall. Set between brick firewalls, the parapet has two concrete panels with garland and a molded architrave. The western bay of the first story holds a single-leaf, paneled metal door with fanlight. A three-light transom is above. Window fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills. The first-story window opening is paired. A one-story, full-width porch shelters the first-story. Set on a brick pier foundation, the porch has a flat roof with overhanging eaves, a few modillions, and a molded cornice. Brick posts provide support to the roof. Metal balusters extend between the posts. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this may have originally been a sleeping porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1838 Potomac Avenue, S.E. and the northeast (side) elevation to 1842 Potomac Avenue, S.E. The level, grassy front yard has mature shrubs. Brick steps extend off of the front porch to join a brick walkway leading to the sidewalk. The rear of the property extends northwest to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Metal

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1840PotomacAvenueSE, looking north.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0036

BASICS DATA

ID Number: **1114-0036** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1842 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1842 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0036 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Restrained)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building is a restrained interpretation of the Classical Revival and Colonial Revival styles. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roof was not visible from the public right-of-way due to a brick parapet wall. Set between brick firewalls, the parapet has two concrete panels with garland and a molded architrave. The western bay of the first story holds a single-leaf, paneled door with a three-light transom. Window fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills. The first-story window opening is paired. A one-story, full-width porch shelters the first-story. Set on a brick pier foundation with lattice infill, the porch has a flat roof with overhanging eaves, modillions, and a molded cornice. Metal filigree posts support the roof. Metal balusters extend between the posts. The northwest (rear) elevation has a two-story wing. The rear of the property was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this may have originally been a sleeping porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1840 Potomac Avenue, S.E. and the northeast (side) elevation to 1844 Potomac Avenue, S.E. The level, grassy front yard has mature trees and shrubs. A concrete walkway extends from the dwelling to the sidewalk. The rear of the property extends northwest to a paved alley.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Historic District(s)

Subdivision:

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: C:\Users\CHRS\Documents\CHRS

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1114\

File: 1842PotomacAvenueSE, looking north.jpg

Date::

Photog:

Code::

R:

Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

9/30/1925

3033 Build

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0035

BASICS DATA

ID Number: **1114-0035** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1844 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1844 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0035 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type Contributing Status
Garage **Non-Contributing**

Outbuilding Notes:

February 2009: This garage fronts the rear alley. The garage does not appear on the 1928 or the 1960 Sanborn Insurance Company map. Based on its form and materials, this garage appears to have a construction date of c. 1965. The brick structure has a rock-faced concrete-block veneer. The flat roof

has a prominent centered front-gable which extends the depth of the building. Asphalt shingles cover the roof. The façade (northwest elevation) contains a paneled, metal roll-up door set in a wide wood surround with wooden lintel. The upper gable end of the front gable has a single-light, wood-sash casement window set in a narrow, square-edge wood surround.

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building reflects stylistic elements of both the Colonial Revival and Craftsman styles which were popular in the second-quarter of the twentieth century. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way. However, a pent roof highlights the façade. Stretching between brick firewalls, the pent roof is covered with hexagonal slate shingles and has narrow rafter ends. The western bay of the first story holds a single-leaf, paneled door with a three-light transom. Window fenestration consists of 1/1, double-hung, vinyl-sash windows with concrete sills. The first-story window opening is paired. A one-story, full-width porch shelters the first-story. Set on a brick pier foundation with lattice infill, the porch has a flat roof with overhanging eaves, modillions, and a molded cornice. Tuscan columns support the roof. Square balusters extend between the columns. In addition, a wooden ramp has been constructed on half of the wooden stair providing access to the front porch. The northwest (rear) elevation has a two-story wing. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this may have originally been a sleeping porch. It is now clad in German vinyl siding and fenestrated with 1/1, double-hung, vinyl-sash windows and single-light casement windows. A single-leaf door with nine lights is located in the western bay of the first story. A brick chimney pierces the shed roof.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1842 Potomac Avenue, S.E. and the northeast (side) elevation to 1846 Potomac Avenue, S.E. The level, grassy front yard has been landscaped with immature plantings and shrubs. A concrete walkway extends from the dwelling to the sidewalk. The rear of the property is enclosed by a wood fence and extends northwest to a paved alley. A garage fronts the rear alley.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1844PotomacAvenueSE, looking north.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1844PotomacAvenueSErear,looking
southeast.jpg**

Date:: Photog:

Code:: R: Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1844PotomacAvenueSErear,looking
southwest.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

9/30/1925	3033	Build	
-----------	------	-------	--

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code	Criteria
------	----------

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0034

BASICS DATA

ID Number: **1114-0034** Year Built: **1924** Data Source: **Permit**

Number Extended Street Quad Type of Address

1846 **Potomac Avenue** **SE**

Name(s) Type of Name

Rowhouse, 1846 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0034 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building reflects stylistic elements of both the Colonial Revival and Craftsman styles which were popular in the second-quarter of the twentieth century. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way. However, a pent roof highlights the façade. Stretching between brick firewalls, the pent roof is covered with hexagonal shingles and has narrow rafter ends. The western bay of the first story holds a single-leaf, paneled wood door with four lights and a three-light transom. Window fenestration consists of 1/1, double-hung, vinyl-sash windows with false 6/1 muntins and concrete sills. The first-story window opening is paired. A one-story, full-width porch shelters the first-story. Set on a brick pier foundation, the porch has a flat roof with overhanging eaves, modillions, and a molded cornice. Wood post supports with square wood balusters complete the porch. The northwest (rear) elevation has a two-story wing which was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this may have originally been a sleeping porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1844 Potomac Avenue, S.E. and the northeast (side) elevation to 1848 Potomac Avenue, S.E. The level, grassy front yard has mature trees and shrubs. A concrete walkway extends from the dwelling to the sidewalk. The rear of the property is enclosed by a wood fence and extends northwest to D Street, S.E.

NOTABLE FEATURES DATA

Component

Feature

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	6/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	6/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1846PotomacAvenueSE, looking north.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0033

BASICS DATA

ID Number: **1114-0033** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1848 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1848 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0033 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

Residential (Single-Family) **1925** **Permit** **Historic/Current**

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Colonial Revival (Craftsman)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building reflects stylistic elements of both the Colonial Revival and Craftsman styles which were popular in the second-quarter of the twentieth century. This rowhouse is set on a solid concrete foundation and constructed of brick. The façade (southeast elevation) is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way. However, a pent roof highlights the façade. Stretching between brick firewalls, the pent roof is covered with hexagonal shingles and has narrow rafter ends. The western bay of the first story holds a single-leaf door. The transom has been enclosed with wood. Window fenestration consists of 1/1, double-hung, vinyl-sash windows concrete sills. The first-story window opening is paired. A one-story, full-width porch shelters the first-story. Set on a brick pier foundation with honeycomb brickwork infill, the porch has a flat roof with overhanging eaves and modillions. Brick piers with metal balusters complete the porch. The northwest (rear) elevation has a two-story wing which was not surveyed or photographed by the volunteer surveyor. Based on its form and documentation on the 1928 Sanborn Insurance Company map, this may have originally been a sleeping porch.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a set back of approximately twenty feet from the concrete sidewalk. The southwest (side) elevation of the dwelling is attached to 1846 Potomac Avenue, S.E. and the northeast (side) elevation to 1850 Potomac Avenue, S.E. The level, grassy front yard has mature trees and shrubs. A concrete walkway extends from the dwelling to the sidewalk. The rear of the property is enclosed by a wood fence and extends northwest to D Street, S.E.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Dbl-Hung	1/1 Double	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	1/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Unknown

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Level(s) of Investigation

Capitol Hill Southeast Phase I (2009/2010)

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS
Databases\SE Phase I - D to G
St\Database\Pictures\Square 1114**

File: **1848PotomacAvenueSE, looking north.jpg**

Date:: Photog:

Code:: R: Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
9/30/1925	3033	Build	

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code Criteria

DATA PROCESSING EVENTS DATA

Resource All Data Report

ID Number: 1114-0032

BASICS DATA

ID Number: **1114-0032** Year Built: **1925** Data Source: **Permit**

Number Extended Street Quad Type of Address

1850 **Potomac Avenue** **SE** **Current**

Name(s) Type of Name

Rowhouse, 1850 Potomac Avenue, S.E. **Common**

TaxCode1 TaxCode2 TaxCode3 Type Explain

1114/0032 **Square/Lot** **Current**

STATUS/PURPOSE/USE DATA

Resource Type: **Building** Status Current: **Extant**

Desig. Status: **Historic** Quality:

Purpose: **Rowhouse** Condition: **Good**

Function/Use Start Source Stop Source Explain

CONSTRUCTION DATA

Construction Event Start Source Stop Source Cost Source

Orig Construction **1925** **Permit** **5000 Permit**

Construction Event Association Associated Name

Orig Construction **Architect** **Santmyers, George T.**

Orig Construction **Builder** **Jameson, Thomas A.**

Orig Construction **Owner** **Jameson, Thomas A.**

Construction Notes:

PEOPLE/EVENTS DATA

Racial Segregation Status:

SETTING/SHAPE/SIZE DATA

Surroundings: **Urban**

Streetscape: **Intact**

Relate to Othr Bldgs: **Row End (1 of 26)**

Relate to Street: **Face on Setback Line**

Massing: **Block**

Footprint: **Rectangular**

Number Stories: **2**

Bays Wide: **2**

Height:

Width: **16**

Depth/Length: **30**

SqFt:

Volume:

Lot Width

Lot Depth/Length:

Lot SqFt:

Acreage:

Has Driveway: ☐

Cross Reference Notes:

Outbuilding Type

Contributing Status

Outbuilding Notes:

STYLE/EXTERIOR DATA

Architectural Style(s)

Classical Revival (Restrained)

Exterior & Architectural Notes:

February 2009: Constructed in 1925 by owner/builder T. A. Jameson, this two-story, two-bay rowhouse is one of 26 similar rowhouses designed by architect George T. Santmyers as part of the same permit (#3033). This building is a restrained interpretation of the Classical Revival and Colonial Revival styles. This rowhouse is set on a solid concrete foundation and constructed of brick. The building is faced with five-course, American-bond brick. A stringcourse of soldier bricks extends above the first- and second-story openings, serving as a continuous lintel. The roofing type and material were not visible from the public right-of-way due to a brick parapet wall. Parged panels with garland and a molded cornice complete the parapet wall. An exterior-side brick chimney extends from the northeast (side) elevation. The façade (southeast elevation) has a single-leaf wood door with lights in the western bay. This entry is accessed via wood steps with a wooden pergola. The eastern bay of the first story holds a ribbon of three, single-light, vinyl-sash casement windows. The second story of the façade has two, 1/1, double-hung, vinyl-sash windows with false 6/1 muntins. The northeast (side) elevation has a double-leaf, metal-frame glass door accessed via landscaping stones. Additional fenestration consists of single-light, vinyl-sash casements and 1/1, double-hung, vinyl-sash windows. The northwest (rear) elevation has a two-story wing which, based on its form and documentation on the 1928 Sanborn Insurance Company map, may have originally been a sleeping porch. This rear wing has been stuccoed and is covered by a shed roof. Fenestration consists of a double-leaf, metal-frame glass door and 1/1, double-hung, vinyl-sash windows with false 6/6 muntins.

Site Notes:

February 2009: This dwelling is located on the north side of Potomac Avenue, S.E. and has a setback of approximately twenty feet from the street. The southwest (side) elevation of this end-unit is attached to 1848 Potomac Avenue, S.E. The large triangular-shaped lot is located northwest of the intersection of Potomac Avenue, S.E. and 19th Street, S.E. and southwest of the intersection of D Street, S.E. and 19th Street S.E. The level, grassy lot has mature trees and shrubs. The side yard has been landscaped with retaining walls and immature plantings. A concrete sidewalk extends along Potomac Avenue, S.E., 19th Street, S.E., and D Street, S.E. The property is enclosed by a wooden fence. A concrete driveway is located in the backyard with access to D Street, S.E.

NOTABLE FEATURES DATA

Component	Feature
-----------	---------

EXTERIOR MATERIALS DATA

Roof Component	Material	Color	Treatment	Source
Not Visible	Not Visible		Not Visible	
Wall Component	Material	Color	Treatment	Source
Facade	Brick		American Bond	
Structure Component	Material	Feature		Source
Foundation	Concrete			
Walls	Brick			

Materials Notes:

WINDOW/DOOR/INTERIOR DATA

Window Location	Aperture Shape	Type	Lights	Material
1 Flr Windows	Rectangular	Casement	multi	Vinyl
2 Flr Windows	Rectangular	Dbl-Hung	6/1	Vinyl
Door Location	Aperture Shape	Type	Panels	Material
Main Door	Rectangular	Single		Wood

Notable Interior Plan(s)

Notable Interior Feature(s)

Interior Notes:

PLAN/SURVEY/DESIGNATION DATA

Neighborhood: **Capitol Hill**

Subdivision:

Ward/ANC:

Zoning:

Contributing:

Historic District(s)

Designation Event(s)

Survey(s)

Capitol Hill Southeast Phase I (2009/2010)

Level(s) of Investigation

Permit Research

Volunteer Reconnaissance Survey

PHOTOS - DIGITIZED

Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1114

File: **1850PotomacAvenueSE, looking north.jpg**

Date::

Photog:

Code::

R:

Fr:



Caption:

Path: **C:\Users\CHRS\Documents\CHRS**

Databases\SE Phase I - D to G

St\Database\Pictures\Square 1114

File: **1850PotomacAvenueSE, looking west.jpg**

Date::

Photog:

Code::

R:

Fr:



PHOTOS - B/W OR NON-DIGITIZED

Photo Code	Roll	Frame(s)	Date	Photographer	Caption
------------	------	----------	------	--------------	---------

MISCELLANEOUS NOTES DATA

Notes:

PERMIT DATA

Permit Issue Date	Number	Type	Remarks
-------------------	--------	------	---------

9/30/1925	3033	Build	
------------------	-------------	--------------	--

Permit Notes:

BIBLIOGRAPHIC DATA

SIGNIFICANCE DATA

Study Unit

Code

Criteria

DATA PROCESSING EVENTS DATA
